

**VEHICLE APPLICATIONS**  
**APLICACIONES POR VEHÍCULOS**  
**APPLICATIONS POUR VÉHICULES**



**GLOSSARY BODY DESIGN / GLOSARIO TIPOS DE CARROCERÍA / GLOSSARIE TYPES DE CARROSSERIE**




**Hatchback.**  
Berlina 3 y 5p.  
Fastback.



**Truck / Lorry.**  
Camión.  
Camion.



**Saloon / Sedan.**  
Sedán.  
A trois volumes.



**Flatbed / Chassis.**  
Caja / Chasis.  
Camion plate-forme / Châssis.



**Station Wagon / SW.**  
Familiar.  
Break.



**Minibus / Bus / Coach.**  
Microbus / Autobús.  
Autobus / Autocar.



**MPV.**  
Monovolumen.  
Monospace.



**Box / Van.**  
Furgoneta / Furgón.  
Camionnette.



**Closed Off-Road / 4WD / SUV.**  
Todo terreno cerrada / 4x4 / SUV.  
Tout terrain à crosserie fermée.



**Open Off-Road / Pick-up truck.**  
Todo terreno abierta / Pick-up.  
Tout terrain à crosserie ouverte.



**Convertible / Roadster.**  
Descapotable / Cabrio.  
Décapotable.



**Tractor.**  
Tractor.  
Tracteur.



**Coupe / Sportback.**  
Cupé.  
Coupé.



**Motorcycle.**  
Motocicleta.  
Moto.



## INDEX OF MAKERS / ÍNDICE DE FABRICANTES / INDEX DES CONSTRUCTEURS

	PAG.		PAG.		PAG.
ABARTH	68	HONDA	134-138	PEUGEOT	191-200
ALFA ROMEO	67-71	HYUNDAI	138-142	PLYMOUTH	200
ALPINA	71	INFINITI	142-143	PORSCHE	200
ALPINE	71	INNOCENTI	143	PROTON	201
AUDI	71-85	ISUZU	143	PUCH	201
AUSTIN	85-86	JAGUAR	143	RELIANT	201
AUTOBIANCHI	86	JEEP	143-144	RENAULT	201-215
BMW	86-96	KIA	144-147	ROLLS-ROYCE	215
CADILLAC	96	LADA	147-149	ROVER	215-218
CHEVROLET	96-98	LAMBORGHINI	149	SAAB	218
CHRYSLER	98-99	LANCIA	149-152	SEAT	219-225
CITROËN	99-108	LANDROVER	152	SKODA	225-229
DACIA	109-109	LEXUS	152	SMART	229-230
DAEWOO	109-111	LINCOLN	153	SSANGYONG	230
DAIHATSU	111	LOTUS	153	SUBARU	231
DODGE	111-112	MAZDA	153-156	SUZUKI	232-234
FERRARI	112	MERCEDES-BENZ	156-165	TALBOT	234
FIAT	12-120	MG	165	TOYOTA	234-240
FORD	120-133	MINI	165-166	TRIUMPH	240
FORD AUSTRALIA	133	MITSUBISHI	167-170	VAUXHALL	240-247
FORD USA	133	MORRIS	170	VOLKSWAGEN	247-263
FSO	133	NISSAN	171-176	VOLVO	264-270
HOLDEN	134	OPEL	176-191		

## SYMBOLS / SÍMBOLOS / SYMBOLES



Vehicle applications.  
Aplicaciones por vehículos.  
Applications pour véhicules.



Engine.  
Motor.  
Moteur.



Year.  
Año.  
Année.



Kilowatts / Horse power.  
Kilovatios / Caballos de vapor.  
Kilowatts / Chevaux-vapeur.



Information.  
Información.  
Information.



Cross references.  
Cruce de referencias.  
Tableau des équivalences.

## EXAMPLES / EJEMPLOS / EXEMPLES



### ALFA ROMEO

145 (930) 1.4 i.e.	1994-96
AR 33501	66 90
Ignition Coil AR 33501	80217
145 (930) 1.4 i.e. 16V T.S.	1996-01
AR 33503/AR 38501	76 103
Ignition Coil ->02.1999	80227
Ignition Coil 02.1999-12.2000	80313
145 (930) 1.6 16V T.S.	1997-00
AR 32102	82 112
Ignition Coil	80313

### MAKER / FABRICANTE / CONSTRUCTEUR

MODEL / MODELO / MODELE	Date / Fecha / Date
ENGINE / MOTOR / MOTEUR	KW HP
Family / Familia / Famille	Info REF. FAE

## INFORMATION / INFORMACIÓN / INFORMATION

### GBR

This catalogue considers vehicles with:

- Left Hand Drive (L.H.D.)
- Manual Gear, 5 speed
- Without Air Conditioning
- Without Check Control
- Without Cruise Control
- Without ABS

As the standard vehicle (generic).

Vehicles with different features (criteria) are treated in a specific way in the information column.

### ESP

En este catálogo se han considerado los vehículos con:

- Conducción a la izquierda (L.H.D.)
- Cambio Manual, 5 velocidades
- Sin Aire Acondicionado
- Sin Check Control
- Sin Cruise Control
- Sin ABS

Como el vehículo standard (genérico).

El resto de vehículos con otras características (criterios) se tratan de forma específica en la columna de información.

### FRA

Dans ce catalogue sont considérés les véhicules avec:

- Conduction à gauche (L.H.D.)
- Avec boîte de vitesses manuelle, 5 vitesses
- Sans Air Conditionné/Climatisation
- Sans Tableau de Contrôle
- Sans Vitesse de Croisière
- Sans Antiblocage (ABS)

Comme le véhicule standard (générique).

Le reste des véhicules avec d'autres caractéristiques (critères) sont abordés d'une façon spécifique dans la colonne d'information.



ABARTH		
<b>500 (312) 1.4</b>	2008->	
312 A3.000	132	180
Ignition Coil ->12.2012	<b>80267</b>	
<b>500 (312) 1.4</b>	2008->	
312 A1.000	139	190
Ignition Coil	<b>80233</b>	
Ignition Coil ->12.2012	<b>80267</b>	
<b>500 (312) 1.4</b>	2008->	
312 A1.000	99	135
Ignition Coil	<b>80233</b>	
Ignition Coil Euro 5	<b>80267</b>	
<b>500 (312) 1.4</b>	2008->	
312 A3.000/312 A1.000	118	160
Ignition Coil ->02.2016; Euro 5	<b>80267</b>	
<b>500 (312) 1.4</b>	2010->	
312 A3.000	103	140
Ignition Coil	<b>80233</b>	
Ignition Coil Euro 5	<b>80267</b>	
<b>500 C (312) 1.4</b>	2009->	
312 A3.000	103	140
Ignition Coil Euro 5	<b>80267</b>	
<b>500 C (312) 1.4</b>	2011->	
312 A1.000	118	160
Ignition Coil	<b>80233</b>	
<b>500 C (312) 1.4</b>	2009->	
312 A3.000	132	180
Ignition Coil	<b>80233</b>	
Ignition Coil 03.2012->; Euro 5	<b>80267</b>	
<b>500C / 595C (312) 1.4</b>	2011->	
312 A1.000	99	135
Ignition Coil Euro 5	<b>80267</b>	
<b>Punto / Grande Punto (199) 1.4</b>	2007-10	
199 A8.000	114	155
Ignition Coil	<b>80267</b>	
<b>Punto / Grande Punto (199) 1.4</b>	2007-12	
199 A8.000/955 A8.000	132	180
Ignition Coil 199 A8.000; ->12.2010	<b>80267</b>	

ALFA ROMEO		
<b>145 (930) 1.4 i.e.</b>	1994-96	
AR 33501	66	90
Ignition Coil AR 33501	<b>80217</b>	
<b>145 (930) 1.4 i.e. 16V T.S.</b>	1996-01	
AR 33503/AR 38501	76	103
Ignition Coil ->02.1999	<b>80227</b>	
Ignition Coil 02.1999-12.2000	<b>80313</b>	
<b>145 (930) 1.6 16V T.S.</b>	1997-00	
AR 32102	82	112
Ignition Coil	<b>80313</b>	
<b>145 (930) 1.6 i.e.</b>	1994-96	
AR 33201	76	103
Ignition Coil	<b>80279</b>	
Ignition Leads ->11.1994	<b>85400</b>	
Ignition Leads 11.1994->	<b>85401</b>	
<b>145 (930) 1.6 i.e. 16V T.S.</b>	1996-01	
AR 67601/AR 38201	88	120
Ignition Coil ->02.1999	<b>80227</b>	
Ignition Coil 02.1999-12.2000	<b>80313</b>	
<b>145 (930) 1.7 i.e. 16V</b>	1994-96	
AR 33401	95	129
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>85725</b>	
<b>145 (930) 1.8 i.e. 16V</b>	1998-01	
AR 32201	106	144
Ignition Coil	<b>80227</b>	
Ignition Coil 05.1998-12.2000	<b>80313</b>	
Ignition Leads	<b>85725</b>	
<b>145 (930) 1.8 i.e. 16V T.S.</b>	1996-98	
AR 38401/AR 67199/AR 67106	103	140
Ignition Coil	<b>80227</b>	
<b>145 (930) 2.0 16V Quadrifoglio</b>	1998-01	
AR 32301	114	155
Ignition Coil	<b>80227</b>	
Ignition Coil 05.1998-12.2000	<b>80313</b>	
<b>145 (930) 2.0 16V T.S.</b>	1995-01	
AR 67204	110	150
Ignition Coil	<b>80227</b>	

ALFA ROMEO Cont.		
<b>146 (930) 1.4 i.e.</b>	1994-96	
AR 33501	66	90
Ignition Coil AR 33501	<b>80217</b>	
<b>146 (930) 1.4 i.e. 16V T.S.</b>	1996-01	
AR 33503/AR 38501	76	103
Ignition Coil ->02.1999	<b>80227</b>	
Ignition Coil 02.1999-12.2000	<b>80313</b>	
<b>146 (930) 1.6 16V T.S.</b>	1997-00	
AR 32102	82	112
Ignition Coil	<b>80313</b>	
<b>146 (930) 1.6 i.e.</b>	1994-96	
AR 33201	76	103
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>85401</b>	
<b>146 (930) 1.6 i.e. 16V T.S.</b>	1996-01	
AR 67601/AR 38201	88	120
Ignition Coil ->02.1999	<b>80227</b>	
Ignition Coil 02.1999-12.2000	<b>80313</b>	
<b>146 (930) 1.7 i.e. 16V</b>	1994-96	
AR 33401	95	129
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>85725</b>	
<b>146 (930) 1.8 i.e. 16V T.S.</b>	1996-01	
AR 38401/AR 67106	103	140
Ignition Coil	<b>80227</b>	
<b>146 (930) 1.8 i.e. 16V T.S.</b>	1998-01	
AR 32201	106	144
Ignition Coil	<b>80227</b>	
Ignition Coil 05.1998-12.2000	<b>80313</b>	
Ignition Leads AR 32201	<b>85725</b>	
<b>146 (930) 2.0 16V Quadrifoglio</b>	1998-01	
AR 32301	114	155
Ignition Coil	<b>80227</b>	
Ignition Coil 05.1998-12.2000	<b>80313</b>	
<b>146 (930) 2.0 16V T.S.</b>	1995-01	
AR 67204	110	150
Ignition Coil	<b>80227</b>	
<b>147 (937) 1.6 16V T.SPARK</b>	2001-10	
AR 32104	88	120
Ignition Coil	<b>80229</b>	
<b>147 (937) 1.6 16V T.SPARK ECO</b>	2001-10	
AR 37203	77	105
Ignition Coil	<b>80229</b>	
<b>147 (937) 2.0 16V T.SPARK</b>	2001-10	
AR 32310	110	150
Ignition Coil	<b>80229</b>	
<b>155 (167) 1.6 16V T.S.</b>	1996-97	
AR 67601	88	120
Ignition Coil	<b>80227</b>	
<b>155 (167) 1.7 T.S.</b>	1993-96	
AR 67105	85	115
Ignition Coil	<b>80279</b>	
<b>155 (167) 1.7 T.S.</b>	1993-96	
AR 67103	83	113
Ignition Coil	<b>80279</b>	
<b>155 (167) 1.7 T.S. 16V</b>	1996-97	
AR 67106	103	140
Ignition Coil	<b>80227</b>	
<b>155 (167) 1.8 T.S.</b>	1992-97	
AR 67402	77	105
Ignition Coil	<b>80279</b>	
<b>155 (167) 1.8 T.S.</b>	1992-93	
AR 67101	95	129
Ignition Coil	<b>80279</b>	
<b>155 (167) 1.8 T.S. Sport</b>	1992-96	
AR 67101/AR 67102	93	127
Ignition Coil	<b>80279</b>	
<b>155 (167) 2.0 16V Turbo Q4</b>	1992-97	
AR 67203	137	186
Ignition Coil AR 67203	<b>80217</b>	
<b>155 (167) 2.0 16V Turbo Q4</b>	1992-97	
AR 67203	140	190
Ignition Coil AR 67203	<b>80217</b>	
<b>155 (167) 2.0 T.S.</b>	1992-95	
AR 67201/AR 67202	104	141
Ignition Coil	<b>80279</b>	
<b>155 (167) 2.0 T.S.</b>	1992-93	
AR 67201/AR 67202	106	144
Ignition Coil	<b>80279</b>	

**ALFA ROMEO Cont.**

<b>155 (167) 2.0 T.S. 16V</b>	<b>1995-97</b>
AR 67299/AR 67204	110 150
Ignition Coil	<b>80227</b>
<b>156 (932) 1.6 16V T.SPARK</b>	<b>1997-05</b>
AR 32102	82 112
Ignition Coil ->09.2000	<b>80313</b>
<b>156 (932) 1.6 16V T.SPARK</b>	<b>1997-05</b>
AR 32102/AR 32103/AR 32104/AR 67601	88 120
Ignition Coil AR67601; 10.1997-05.1999; With regul.cat.(3way)	<b>80227</b>
Ignition Coil AR 32104, AR 32103; 09.2000->	<b>80229</b>
Ignition Coil 04.1998-09.2000	<b>80313</b>
<b>156 (932) 1.8 16V T.SPARK</b>	<b>2000-05</b>
AR 32205	103 140
Ignition Coil ->12.2000	<b>80227</b>
Ignition Coil 01.2001->	<b>80229</b>
<b>156 (932) 1.8 16V T.SPARK</b>	<b>1997-00</b>
AR 32201	106 144
Ignition Coil	<b>80227</b>
Ignition Coil	<b>80229</b>
Ignition Coil 10.1997-09.2000	<b>80313</b>
<b>156 (932) 2.0 16V T.SPARK</b>	<b>2000-02</b>
AR 32310	110 150
Ignition Coil	<b>80229</b>
<b>156 (932) 2.0 16V T.SPARK</b>	<b>1997-02</b>
AR 32301/AR 32310	114 155
Ignition Coil	<b>80227</b>
Ignition Coil 10.1997-09.2000	<b>80313</b>
<b>156 (932) 2.0 JTS</b>	<b>2002-05</b>
937 A1.000	122 166
Ignition Coil	<b>80229</b>
<b>156 (932) 2.0 Twin Spark</b>	<b>1997-00</b>
AR 32303	118 160
Ignition Coil	<b>80313</b>
<b>156 Sportwagon (932) 1.6 16V T.SPARK</b>	<b>2000-05</b>
AR 32102	82 112
Ignition Coil 01.2002->	<b>80229</b>
Ignition Coil ->09.2000	<b>80313</b>
<b>156 Sportwagon (932) 1.6 16V T.SPARK.</b>	<b>2000-06</b>
AR 32102/AR 32103/AR 32104/AR 67601	88 120
Ignition Coil AR 67601	<b>80227</b>
Ignition Coil AR 32104, AR 32103	<b>80229</b>
Ignition Coil AR 67601, AR 32102	<b>80313</b>
<b>156 Sportwagon (932) 1.6 16V T.SPARK. (932.B4B00)</b>	<b>2000-05</b>
AR 32103	81 110
Ignition Coil 01.2002->	<b>80229</b>
<b>156 Sportwagon (932) 1.8 16V T.SPARK</b>	<b>2000-00</b>
AR 32201	106 144
Ignition Coil With regul.cat.(3way)	<b>80227</b>
Ignition Coil 06.2000-09.2000	<b>80229</b>
Ignition Coil	<b>80313</b>
<b>156 Sportwagon (932) 1.8 16V T.SPARK</b>	<b>2000-06</b>
AR 32205	103 140
Ignition Coil	<b>80229</b>
<b>156 Sportwagon (932) 2.0 16V T.SPARK</b>	<b>2000-02</b>
AR 32301/AR 32310	114 155
Ignition Coil With regul.cat.(3way)	<b>80227</b>
Ignition Coil 06.2000-09.2000	<b>80229</b>
Ignition Coil	<b>80313</b>
<b>156 Sportwagon (932) 2.0 16V T.SPARK</b>	<b>2000-02</b>
AR 32310	110 150
Ignition Coil	<b>80229</b>
<b>156 Sportwagon (932) 2.0 JTS</b>	<b>2002-06</b>
937 A1.000	122 166
Ignition Coil	<b>80229</b>
<b>159 (939) 1.8 MPI</b>	<b>2007-11</b>
939 A4.000	103 140
Ignition Coil	<b>80291</b>
<b>159 (939) 1.8 TBi</b>	<b>2009-11</b>
939 B1.000	147 200
Ignition Coil	<b>80291</b>
<b>159 (939) 1.9 JTDM 8V</b>	<b>2005-11</b>
939 A1.000	88 120
Ignition Coil	<b>80355</b>
<b>159 (939) 2.2 JTS</b>	<b>2005-11</b>
939 A5.000	136 185
Ignition Coil	<b>80269</b>
<b>159 (939) 3.2 JTS</b>	<b>2008-11</b>
939 A.000	191 260
Ignition Coil	<b>80355</b>

**ALFA ROMEO Cont.**

<b>159 Sportwagon (939) 1.8 MPI</b>	<b>2007-11</b>
939 A4.000	103 140
Ignition Coil	<b>80291</b>
<b>159 Sportwagon (939) 1.8 TBi</b>	<b>2009-11</b>
939 B1.000	147 200
Ignition Coil	<b>80291</b>
<b>159 Sportwagon (939) 2.2 JTS</b>	<b>2006-11</b>
939 A5.000	136 185
Ignition Coil	<b>80269</b>
<b>159 Sportwagon (939) 3.2 JTS</b>	<b>2008-11</b>
939 A.000	191 260
Ignition Coil	<b>80355</b>
<b>159 Sportwagon (939) 3.2 JTS Q4</b>	<b>2006-11</b>
939 A.000	191 260
Ignition Coil	<b>80355</b>
<b>164 (164) 2.0</b>	<b>1987-92</b>
AR 64103	105 143
Ignition Coil	<b>80279</b>
<b>164 (164) 2.0 T.S.</b>	<b>1987-90</b>
AR 06420	109 148
Ignition Coil	<b>80279</b>
<b>164 (164) 2.0 T.S.</b>	<b>1992-98</b>
AR 64103	106 144
Ignition Coil	<b>80279</b>
<b>164 (164) 2.0 Twin Spark</b>	<b>1987-90</b>
AR 06420	109 148
Ignition Coil	<b>80279</b>
<b>166 (936) 2.0 T.Spark</b>	<b>1998-00</b>
AR 34103	114 155
Ignition Coil	<b>80227</b>
Ignition Coil 10.1998-09.2000	<b>80313</b>
<b>166 (936) 2.0 T.Spark</b>	<b>2000-07</b>
AR 36301	110 150
Ignition Coil	<b>80229</b>
<b>33 (905) 1,2</b>	<b>1983-89</b>
AR 30585	50 68
Ignition Leads	<b>83750</b>
<b>33 (905) 1,3</b>	<b>1983-89</b>
AR 30586/AR 30502	55 75
Ignition Coil	<b>80217</b>
Ignition Leads	<b>83750</b>
<b>33 (905) 1,3</b>	<b>1984-89</b>
AR 30168/AR 30587	63 86
Ignition Coil	<b>80217</b>
<b>33 (905) 1,5</b>	<b>1983-86</b>
AR 30520	66 90
Ignition Leads	<b>83750</b>
<b>33 (905) 1,5</b>	<b>1986-89</b>
AR 30588	75 102
Ignition Leads	<b>83750</b>
<b>33 (905) 1.3</b>	<b>1983-89</b>
AR 30502	58 79
Ignition Coil	<b>80217</b>
Ignition Leads	<b>83750</b>
<b>33 (905) 1.5</b>	<b>1983-93</b>
AR 30182	70 95
Ignition Leads	<b>83750</b>
<b>33 (905) 1.5 4x4</b>	<b>1985-86</b>
AR 30520	66 90
Ignition Leads	<b>83750</b>
<b>33 (905) 1.5 4x4</b>	<b>1986-89</b>
AR 30588/AR 30146	77 105
Ignition Leads	<b>83750</b>
<b>33 (905) 1.5 4x4</b>	<b>1986-89</b>
AR 30588	75 102
Ignition Leads	<b>83750</b>
<b>33 (905) 1.7</b>	<b>1986-89</b>
AR 30550	87 118
Ignition Leads	<b>83750</b>
<b>33 (905) 1.7 i.e.</b>	<b>1988-89</b>
AR 30558	77 105
Ignition Leads	<b>85400</b>
<b>33 (905) 1.7 QV</b>	<b>1988-89</b>
AR 30550	84 114
Ignition Leads	<b>83750</b>
<b>33 (907A) 1.4 i.e.</b>	<b>1991-94</b>
AR 30755/AR 30753	65 88
Ignition Coil AR 30753,AR 30755	<b>80217</b>
Ignition Leads	<b>83020</b>



ALFA ROMEO Cont.	
<b>33 (907A) 1.4 i.e.</b>	1991-94
AR 30755/AR 30753	66 90
Ignition Coil AR 30753,AR 30755	<b>80217</b>
Ignition Leads	<b>83020</b>
<b>33 (907A) 1.5</b>	1990-93
AR 30734	77 105
Ignition Leads	<b>83020</b>
<b>33 (907A) 1.5 i.e</b>	1990-94
AR 30751	71 97
Ignition Leads AR 30751	<b>83020</b>
<b>33 (907A) 1.5 i.e.</b>	1990-91
AR 30750	74 101
Ignition Leads AR 30750	<b>83020</b>
Ignition Leads	<b>83750</b>
<b>33 (907A) 1.7 i.e.</b>	1990-94
AR 30736/AR 30737	79 107
Ignition Leads AR 30736	<b>83020</b>
Ignition Leads	<b>85400</b>
<b>33 (907A) 1.7 i.e.</b>	1992-94
AR 30737 A	77 105
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85400</b>
<b>33 Sportwagon (905A) 1.4</b>	1984-88
AR 30587	66 90
Ignition Coil	<b>80217</b>
<b>33 Sportwagon (905A) 1.5</b>	1984-86
AR 30520	66 90
Ignition Leads	<b>83750</b>
<b>33 Sportwagon (905A) 1.5</b>	1986-89
AR 30588	75 102
Ignition Leads	<b>83750</b>
<b>33 Sportwagon (905A) 1.5</b>	1986-89
AR 30588/AR 30508/AR 30146	77 105
Ignition Leads	<b>83750</b>
<b>33 Sportwagon (905A) 1.5 4x4</b>	1984-86
AR 30520	66 90
Ignition Leads	<b>83750</b>
<b>33 Sportwagon (905A) 1.5 4x4</b>	1986-89
AR 30588	75 102
Ignition Leads	<b>83750</b>
<b>33 Sportwagon (905A) 1.5 4x4</b>	1986-89
AR 30588/AR 30508/AR 30146	77 105
Ignition Leads	<b>83750</b>
<b>33 Sportwagon (905A) 1.7</b>	1988-89
AR 30550	87 118
Ignition Leads	<b>83750</b>
<b>33 Sportwagon (905A) 1.7 i.e.</b>	1988-89
AR 30558	77 105
Ignition Leads	<b>85400</b>
<b>33 Sportwagon (905A) 1.7 i.e. 4x4</b>	1988-89
AR 30558/AR 30737	77 105
Ignition Coil	<b>80279</b>
Ignition Leads	<b>83750</b>
<b>33 Sportwagon (907B) 1.4 i.e.</b>	1991-94
AR 30755/AR 30753	65 88
Ignition Coil	<b>80217</b>
<b>33 Sportwagon (907B) 1.4 i.e.</b>	1991-94
AR 30755	66 90
Ignition Coil	<b>80217</b>
<b>33 Sportwagon (907B) 1.7 i.e.</b>	1990-92
AR 30736/AR 30737	79 107
Ignition Leads AR 30736	<b>83020</b>
<b>33 Sportwagon (907B) 1.7 i.e.</b>	1992-94
AR 30737	77 105
Ignition Coil	<b>80279</b>
<b>33 Sportwagon (907B) 1.7 i.e. 4x4</b>	1990-92
AR 30736/AR 30737	79 107
Ignition Leads AR 30736	<b>83020</b>
<b>75 (162B) 1,8</b>	1989-92
AR 61201	90 122
Ignition Leads 01.1991->	<b>83020</b>
<b>75 (162B) 2.0 T.S KAT</b>	1985-92
AR 06224	109 148
Ignition Leads 01.1991->	<b>83020</b>
<b>75 (162B) 2.0 T.S.</b>	1987-92
AR 06166/AR 06224	107 146
Ignition Leads 01.1991->	<b>83020</b>

ALFA ROMEO Cont.	
<b>Alfasud (901) 1,2</b>	1980-84
AR 30102 S	44 60
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1,2</b>	1972-84
AR 30102	46 63
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1,3</b>	1978-80
AR 30180	50 68
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1.2 ti</b>	1973-84
AR 30104	50 68
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1.3 SC/ti Super</b>	1977-84
AR 30164	55 76
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1.3 Super</b>	1979-84
AR 30160	51 69
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1.3 ti</b>	1977-84
AR 30184	55 75
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1.3 ti</b>	1980-84
AR 30168	63 86
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1.5 ti</b>	1979-84
AR 30124	61 83
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1.5 ti</b>	1980-84
AR 30128	70 95
Ignition Leads	<b>83750</b>
<b>Alfasud (901) 1.5 ti Sprint</b>	1983-84
AR 30146	77 105
Ignition Leads	<b>83750</b>
<b>Alfasud Giardinetta (904) 1.2</b>	1978-81
AR 30102	46 63
Ignition Leads	<b>83750</b>
<b>Alfasud Giardinetta (904) 1.3</b>	1980-81
AR 30160	51 69
Ignition Leads	<b>83750</b>
<b>Alfasud Giardinetta (904) 1.3</b>	1978-79
AR 30180	48 65
Ignition Leads	<b>83750</b>
<b>Alfasud Sprint (902.A) 1,3</b>	1976-81
AR 30184	55 76
Ignition Leads	<b>83750</b>
<b>Alfasud Sprint (902.A) 1,5</b>	1978-81
AR 30124	61 83
Ignition Leads	<b>83750</b>
<b>Alfasud Sprint (902.A) 1,5</b>	1979-87
AR 30128	70 95
Ignition Leads	<b>83750</b>
<b>Alfasud Sprint (902.A) 1.4</b>	1978-80
AR 30164	55 76
Ignition Leads	<b>83750</b>
<b>Alfasud Sprint (902.A) 1.4</b>	1979-89
AR 30168	63 85
Ignition Leads	<b>83750</b>
<b>Alfasud Sprint (902.A) 1.5</b>	1983-88
AR 30146	77 105
Ignition Leads	<b>83750</b>
<b>Alfasud Sprint (902.A) 1.5 Veloce</b>	1980-89
AR 30146	75 102
Ignition Leads	<b>83750</b>
<b>Alfasud Sprint (902.A) 1.7</b>	1987-89
AR 30550	87 118
Ignition Leads	<b>83750</b>
<b>Alfasud Sprint (902.A) 1.7 i.e.</b>	1987-89
AR 30558	77 105
Ignition Leads	<b>83750</b>
<b>Alfetta (116) 1,6</b>	1975-84
AR 01600	79 107
Ignition Leads	<b>83020</b>
<b>Alfetta (116) 1,8</b>	1979-84
AR 01678	90 122
Ignition Leads	<b>83020</b>
<b>Alfetta (116) 1.8</b>	1979-84
AR 01608	89 121
Ignition Leads	<b>83020</b>





ALFA ROMEO Cont.	
<b>Alfetta Gt (116) 1.6</b>	<b>1976-82</b>
AR 01600	79 107
Ignition Leads	<b>83020</b>
<b>Alfetta Gt (116) 1.8</b>	<b>1974-76</b>
AR 01608 X	85 116
Ignition Leads	<b>83020</b>
<b>Alfetta Gt (116) 1.8</b>	<b>1974-76</b>
AR 01608	89 121
Ignition Leads	<b>83020</b>
<b>Brera 2.2 JTS</b>	<b>2006-10</b>
939 A5.000	136 185
Ignition Coil	<b>80269</b>
<b>Brera 3.2 JTS</b>	<b>2008-10</b>
939 A.000	191 260
Ignition Coil	<b>80355</b>
<b>Brera 3.2 JTS Q4</b>	<b>2006-10</b>
939 A.000	191 260
Ignition Coil	<b>80355</b>
<b>Giulietta (940) 1.4 TB</b>	<b>2010-&gt;</b>
940 A6.000	85 116
Ignition Coil	<b>80267</b>
<b>Giulietta (116) 1,3</b>	<b>1977-83</b>
AR 01644	66 90
Ignition Leads	<b>83020</b>
<b>Giulietta (116) 1,6</b>	<b>1977-85</b>
AR 01600	79 107
Ignition Leads	<b>83020</b>
<b>Giulietta (116) 1,8</b>	<b>1979-85</b>
AR 01678	90 122
Ignition Leads	<b>83020</b>
<b>Giulietta (940) 1.4 BiFuel</b>	<b>2011-&gt;</b>
198 A4.000	88 120
Ignition Coil	<b>80267</b>
<b>Giulietta (940) 1.4 TB</b>	<b>2014-&gt;</b>
940 C2.000/940 A2.000	110 150
Ignition Coil <940>; ->11.2014	<b>80267</b>
<b>Giulietta (940) 1.4 TB</b>	<b>2011-&gt;</b>
940 B1.000/940 B8.000	77 105
Ignition Coil 940 B1.000	<b>80267</b>
<b>Giulietta (940) 1.4 TB</b>	<b>2010-&gt;</b>
940 B7.000/198 A4.000	88 120
Ignition Coil 198 A4.000; 05.2010->	<b>80267</b>
<b>GT (937) 1.8 TS</b>	<b>2003-10</b>
AR 32205	103 140
Ignition Coil	<b>80229</b>
<b>GTV (916C) 1.8 16V</b>	<b>1998-05</b>
AR 32201	106 144
Ignition Coil ->12.2000	<b>80227</b>
Ignition Coil 01.2001->	<b>80229</b>
Ignition Coil ->12.2000	<b>80313</b>
<b>GTV (916C) 2.0 T.SPARK 16V</b>	<b>1995-05</b>
AR 16201/AR 32310	110 150
Ignition Coil	<b>80227</b>
Ignition Coil 08.2000->	<b>80229</b>
Ignition Coil ->04.1998	<b>80313</b>
<b>GTV (916C) 2.0 T.SPARK 16V</b>	<b>1998-00</b>
AR 32301	114 155
Ignition Coil	<b>80227</b>
Ignition Coil 08.2000->	<b>80229</b>
Ignition Coil ->07.2000	<b>80313</b>
<b>Mito (955) 1.4</b>	<b>2011-&gt;</b>
955 A9.000	51 69
Ignition Coil	<b>80340</b>
<b>Mito (955) 1.4</b>	<b>2011-&gt;</b>
955 A1.000	57 78
Ignition Coil	<b>80233</b>
<b>Mito (955) 1.4</b>	<b>2008-&gt;</b>
199 A6.000	70 95
Ignition Coil	<b>80233</b>
Ignition Coil	<b>80266</b>
<b>Mito (955) 1.4</b>	<b>2008-&gt;</b>
955 A1.000	58 78
Ignition Coil	<b>80233</b>
<b>Mito (955) 1.4</b>	<b>2008-&gt;</b>
198 A4.000	88 120
Ignition Coil 10.2008->	<b>80267</b>
<b>Mito (955) 1.4</b>	<b>2010-&gt;</b>
955 A6.000	77 105
Ignition Coil	<b>80266</b>

ALFA ROMEO Cont.	
<b>Mito (955) 1.4</b>	<b>2011-&gt;</b>
350 A1.000	57 78
Ignition Coil	<b>80233</b>
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Mito (955) 1.4 Bifuel</b>	<b>2011-&gt;</b>
198 A4.000	88 120
Ignition Coil	<b>80267</b>
<b>Mito (955) 1.4 TB</b>	<b>2008-&gt;</b>
199 A8.000	114 155
Ignition Coil	<b>80267</b>
<b>Spider (916) 3.0 V6 24V</b>	<b>1999-03</b>
AR 16102	162 220
Ignition Coil	<b>80355</b>
<b>Spider (916S) 1.8 16V</b>	<b>1998-05</b>
AR 32201	106 144
Ignition Coil ->12.2000	<b>80227</b>
Ignition Coil 01.2001->	<b>80229</b>
Ignition Coil ->07.2000	<b>80313</b>
<b>Spider (916S) 2.0 T.SPARK 16V</b>	<b>1995-05</b>
AR 16201/AR 32310	110 150
Ignition Coil With regul.cat.(3way)	<b>80227</b>
Ignition Coil 08.2000->	<b>80229</b>
Ignition Coil ->04.1998	<b>80313</b>
<b>Spider (916S) 2.0 T.SPARK 16V</b>	<b>1998-00</b>
AR 32301	114 155
Ignition Coil	<b>80227</b>
Ignition Coil 08.2000->	<b>80229</b>
Ignition Coil ->07.2000	<b>80313</b>
<b>Spider (939) 2.2 JTS</b>	<b>2006-10</b>
939 A5.000	136 185
Ignition Coil	<b>80269</b>
<b>Spider (939) 3.2 JTS</b>	<b>2008-10</b>
939 A.000	191 260
Ignition Coil	<b>80355</b>
<b>Spider (939) 3.2 JTS Q4</b>	<b>2006-10</b>
939 A.000	191 260
Ignition Coil	<b>80355</b>
ALPINA	
<b>B7 (E65) 4.4</b>	<b>2003-08</b>
N62B44A19	368 500
Ignition Coil	<b>80247</b>
<b>Roadster (Z8) 4.8 V8</b>	<b>2002-03</b>
	280 381
Ignition Coil	<b>80216</b>
ALPINE	
<b>A610 3.0 TURBO</b>	<b>1991-95</b>
Z7X 744	184 250
Ignition Coil	<b>80264</b>
<b>V6 2.5 TURBO</b>	<b>1985-90</b>
Z7U 734/Z7U 732/Z7U 730	136 185
Ignition Coil	<b>80264</b>
<b>V6 2.5 TURBO</b>	<b>1988-90</b>
Z7U 734/Z7U 732/Z7U 730	147 200
Ignition Coil	<b>80264</b>
AUDI	
<b>100 (44, 44Q, C3) 1.8</b>	<b>1986-88</b>
SH	65 88
Ignition Leads	<b>83960</b>
<b>100 (44, 44Q, C3) 1.8</b>	<b>1983-89</b>
JW /NP/DS	66 90
Ignition Leads	<b>83960</b>
<b>100 (44, 44Q, C3) 1.8 KAT</b>	<b>1985-90</b>
PH/4B	66 90
Ignition Leads	<b>83960</b>
<b>100 (44, 44Q, C3) 1.8 quattro</b>	<b>1986-90</b>
SH	65 88
Ignition Leads	<b>83960</b>
<b>100 (44, 44Q, C3) 1.8 quattro</b>	<b>1984-88</b>
JW /NP	66 90
Ignition Leads	<b>83960</b>



AUDI Cont.	
100 (44, 44Q, C3) 1.8 quattro KAT	1985-90
PH/4B	66 90
Ignition Leads	83960
100 (44, 44Q, C3) 1.9	1982-84
WH	74 100
Ignition Leads	83960
100 (44, 44Q, C3) 2.0	1986-87
SL	83 113
Ignition Leads M4	83950
Ignition Leads	83960
100 (44, 44Q, C3) 2.0	1984-87
KP	85 115
Ignition Leads M4	83950
Ignition Leads	83960
100 (44, 44Q, C3) 2.0 KAT	1988-90
RT	85 115
Ignition Leads M4	83950
100 (44, 44Q, C3) 2.2	1984-86
KZ	85 115
Ignition Leads	83950
100 (44, 44Q, C3) 2.2	1984-88
KU	101 137
Ignition Leads	83950
100 (44, 44Q, C3) 2.2 E quattro	1985-86
PX	88 120
Ignition Leads	83950
100 (44, 44Q, C3) 2.2 E Turbo quattro	1986-90
MC	121 165
Ignition Leads	83950
100 (44, 44Q, C3) 2.2 KAT	1989-90
KU/HX	101 137
Ignition Leads	83950
100 (44, 44Q, C3) 2.2 quattro	1984-88
KU	101 137
Ignition Leads	83950
100 (44, 44Q, C3) 2.2 quattro KAT	1989-90
KU/HX	101 137
Ignition Leads	83950
100 (44, 44Q, C3) 2.2 Turbo	1986-90
MC	121 165
Ignition Leads	83950
100 (44, 44Q, C3) 2.3 E	1986-90
NF	100 136
Ignition Leads	83950
100 (44, 44Q, C3) 2.3 E	1990-90
NF	98 133
Ignition Leads	83950
100 (44, 44Q, C3) 2.3 E quattro	1986-90
NF	100 136
Ignition Leads	83950
100 (44, 44Q, C3) 2.3 quattro	1990-90
NF	98 133
Ignition Leads	83950
100 (4A, C4) 2.0	1990-94
AAE	74 100
Ignition Coil	80200
Ignition Leads	83960
100 (4A, C4) 2.0 E	1990-94
ABK/AAD	85 115
Ignition Leads	83960
100 (4A, C4) 2.0 E 16V	1992-94
ACE	103 140
Ignition Leads	83960
100 (4A, C4) 2.0 E 16V quattro	1992-94
ACE	103 140
Ignition Leads	83960
100 (4A, C4) 2.0 E quattro	1990-92
AAD	85 115
Ignition Leads	83960
100 (4A, C4) 2.3 E	1990-94
AAR	98 134
Ignition Leads	83950
100 (4A, C4) 2.3 E quattro	1990-94
AAR	98 134
Ignition Leads	83950
100 (4A, C4) 2.6	1992-94
ABC	110 150
Ignition Leads	85878

AUDI Cont.	
100 (4A, C4) 2.6 quattro	1992-94
ABC	110 150
Ignition Leads	85878
100 (4A, C4) 2.8 E	1990-94
AAH	128 174
Ignition Leads	85878
100 (4A, C4) 2.8 E quattro	1990-94
AAH	128 174
Ignition Leads	85878
100 Avant (44, 44Q, C3) 1.8	1982-87
RS/DR	55 75
Ignition Leads	83960
100 Avant (44, 44Q, C3) 1.8	1986-90
SH	65 88
Ignition Leads	83960
100 Avant (44, 44Q, C3) 1.8	1983-89
JW /NP/DS	66 90
Ignition Leads	83960
100 Avant (44, 44Q, C3) 1.8 KAT	1985-90
PH/4B	66 90
Ignition Coil	80200
Ignition Leads	83960
100 Avant (44, 44Q, C3) 1.8 quattro	1986-90
SH	65 88
Ignition Leads	83960
100 Avant (44, 44Q, C3) 1.8 quattro	1984-88
JW /NP	66 90
Ignition Leads	83960
100 Avant (44, 44Q, C3) 1.8 quattro KAT	1985-90
PH/4B	66 90
Ignition Leads	83960
100 Avant (44, 44Q, C3) 1.9	1983-84
WH	74 100
Ignition Leads	83960
100 Avant (44, 44Q, C3) 2.0	1986-87
SL	83 113
Ignition Leads M4	83950
Ignition Leads	83960
100 Avant (44, 44Q, C3) 2.0 E	1985-87
KP	85 115
Ignition Leads M4	83950
Ignition Leads	83960
100 Avant (44, 44Q, C3) 2.0 E KAT	1988-90
RT	85 115
Ignition Leads M4	83950
Ignition Leads	83960
100 Avant (44, 44Q, C3) 2.2	1984-86
KZ	85 115
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.2	1984-88
KU	101 137
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.2 E quattro	1985-86
PX	88 120
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.2 KAT	1989-90
KU/HX	101 137
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.2 quattro	1984-88
KU	101 137
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.2 quattro KAT	1989-90
KU/HX	101 137
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.2 Turbo	1986-90
MC	121 165
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.2 Turbo quattro	1986-90
MC	121 165
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.3	1986-90
NF	100 136
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.3	1990-90
NF	98 133
Ignition Leads	83950
100 Avant (44, 44Q, C3) 2.3 E quattro	1986-90
NF	100 136
Ignition Leads	83950





AUDI Cont.	
100 Avant (4A, 44Q, C3) 2.3 quattro	1990-90
NF	98 133
Ignition Leads	<b>83950</b>
100 Avant (4A, C4) 2.0 E	1991-94
AAE	74 100
Ignition Coil	<b>80200</b>
100 Avant (4A, C4) 2.0 E	1991-94
ABK/AAD	85 115
Ignition Leads	<b>85690</b>
100 Avant (4A, C4) 2.0 E quattro	1990-92
AAD	85 115
Ignition Leads	<b>85690</b>
100 Avant (4A, C4) 2.3 E	1991-94
AAR	98 133
Ignition Leads	<b>83950</b>
100 Avant (4A, C4) 2.3 E quattro	1991-94
AAR	98 134
Ignition Leads	<b>83950</b>
100 Avant (4A, C4) 2.6	1992-94
ABC	110 150
Ignition Leads	<b>85878</b>
100 Avant (4A, C4) 2.6	1993-94
ACZ	102 139
Ignition Leads	<b>85878</b>
100 Avant (4A, C4) 2.6 quattro	1992-94
ABC	110 150
Ignition Leads	<b>85878</b>
100 Avant (4A, C4) 2.8 E	1991-94
AAH	128 174
Ignition Leads	<b>85878</b>
100 Avant (4A, C4) 2.8 E quattro	1991-94
AAH	128 174
Ignition Leads	<b>85878</b>
200 (4A, 44Q) 2.1 Turbo	1983-88
KG	134 182
Ignition Leads	<b>83950</b>
200 (4A, 44Q) 2.1 Turbo quattro	1983-86
KG	134 182
Ignition Leads	<b>83950</b>
200 (4A, 44Q) 2.2	1984-85
KU	101 137
Ignition Leads	<b>83950</b>
200 (4A, 44Q) 2.2 20V Turbo quattro	1989-90
3B	162 220
Ignition Leads	<b>83950</b>
200 (4A, 44Q) 2.2 Turbo	1985-91
MC	121 165
Ignition Leads	<b>83950</b>
200 (4A, 44Q) 2.2 Turbo	1988-90
2B	140 190
Ignition Leads	<b>83950</b>
200 (4A, 44Q) 2.2 Turbo	1988-90
1B	147 200
Ignition Leads	<b>83950</b>
200 (4A, 44Q) 2.2 Turbo quattro	1985-91
MC	121 165
Ignition Leads	<b>83950</b>
200 (4A, 44Q) 2.2 Turbo quattro	1988-90
1B	147 200
Ignition Leads	<b>83950</b>
200 Avant (4A, 44Q) 2.1 Turbo quattro	1983-88
JY/KG	134 182
Ignition Leads	<b>83950</b>
200 Avant (4A, 44Q) 2.2 20V Turbo quattro	1989-90
3B	162 220
Ignition Leads	<b>83950</b>
200 Avant (4A, 44Q) 2.2 Turbo	1985-91
MC	121 165
Ignition Leads	<b>83950</b>
200 Avant (4A, 44Q) 2.2 Turbo quattro	1983-90
MC	121 165
Ignition Leads	<b>83950</b>
200 Avant (4A, 44Q) 2.2 Turbo quattro	1988-91
1B	147 200
Ignition Leads	<b>83950</b>
200 Avant (4A, 44Q) 2.3	1986-91
NF	100 136
Ignition Leads	<b>83950</b>

AUDI Cont.	
50 (86) 1.1	1974-78
HB	37 50
Ignition Leads	<b>83660</b>
50 (86) 1.1	1974-77
HC	44 60
Ignition Leads	<b>83660</b>
50 (86) 1.3	1977-78
HH	44 60
Ignition Leads	<b>83660</b>
80 (80, 82, B1) 1.3	1972-78
ZA	40 55
Ignition Leads	<b>83660</b>
80 (80, 82, B1) 1.3	1972-78
ZF	44 60
Ignition Leads	<b>83660</b>
80 (80, 82, B1) 1.5	1972-75
ZB/YJ	55 75
Ignition Leads	<b>83660</b>
80 (80, 82, B1) 1.5	1972-76
ZC	63 85
Ignition Leads	<b>83660</b>
80 (80, 82, B1) 1.6	1975-78
YN	55 75
Ignition Leads	<b>83660</b>
80 (80, 82, B1) 1.6	1975-78
YP	63 85
Ignition Leads	<b>83660</b>
80 (80, 82, B1) 1.6 GT	1973-76
XX	74 100
Ignition Leads	<b>83660</b>
80 (80, 82, B1) 1.6 GTE	1976-78
YS	81 110
Ignition Leads	<b>83660</b>
80 (81, 85, B2) 1.3	1978-86
EP	44 60
Ignition Leads	<b>83960</b>
80 (81, 85, B2) 1.6	1986-86
SA	54 73
Ignition Leads	<b>83960</b>
80 (81, 85, B2) 1.6	1978-86
DT	55 75
Ignition Leads ->07.1984	<b>83660</b>
Ignition Leads	<b>83960</b>
80 (81, 85, B2) 1.6	1978-83
YP	63 85
Ignition Leads	<b>83660</b>
80 (81, 85, B2) 1.6	1978-86
WV/YN	55 75
Ignition Leads	<b>83660</b>
80 (81, 85, B2) 1.6 GLE	1978-82
YZ	81 110
Ignition Leads	<b>83660</b>
80 (81, 85, B2) 1.8	1983-86
DS/JV	66 90
Ignition Leads ->07.1984	<b>83660</b>
Ignition Leads	<b>83960</b>
80 (81, 85, B2) 1.8	1983-86
JN	68 93
Ignition Leads	<b>83960</b>
80 (81, 85, B2) 1.8 CC quattro	1984-86
NE/JV	66 90
Ignition Leads	<b>83960</b>
80 (81, 85, B2) 1.8 CC quattro	1985-86
JN	68 93
Ignition Leads	<b>83960</b>
80 (81, 85, B2) 1.8 GTE	1985-86
PV	81 110
Ignition Leads	<b>83960</b>
80 (81, 85, B2) 1.8 GTE quattro	1984-86
DZ	82 112
Ignition Leads	<b>83960</b>
80 (81, 85, B2) 1.8 GTE quattro	1985-86
PV	81 110
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.4	1986-88
SE	48 65
Ignition Leads	<b>83960</b>



AUDI Cont.	
80 (89, 89Q, 8A, B3) 1.6	1986-91
RN	55 75
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.6	1987-91
PP	51 70
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.6	1990-91
ABB	75 102
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.8	1986-90
RU	55 75
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.8	1986-88
SD	83 113
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.8 E	1986-91
DZ	82 112
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.8 E quattro	1986-91
DZ	82 112
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.8 quattro	1986-90
SD	83 113
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.8 S	1986-90
SF	65 88
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.8 S	1986-91
NE/PM/JN	66 90
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.8 S quattro	1986-90
SF	65 88
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 1.8 S quattro	1986-91
NE/PM/JN	66 90
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 2.0	1990-91
AAD	82 112
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 2.0 E	1988-90
3A	83 113
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 2.0 E 16V	1990-91
6A	101 137
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 2.0 E 16V quattro	1990-91
6A	101 137
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 2.0 E quattro	1988-90
3A	83 113
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 2.0 quattro	1990-91
AAD	85 115
Ignition Leads	<b>83960</b>
80 (89, 89Q, 8A, B3) 2.0 quattro	1988-90
3A	82 112
Ignition Leads	<b>83960</b>
80 (8C, B4) 1.6	1991-94
ABM	52 71
Ignition Coil	<b>80200</b>
Ignition Leads	<b>83960</b>
80 (8C, B4) 2.0	1991-94
ABT	66 90
Ignition Coil	<b>80200</b>
Ignition Leads M4	<b>83960</b>
Ignition Leads	<b>85680</b>
80 (8C, B4) 2.0 E	1991-94
ABK	85 115
Ignition Coil ->07.1993	<b>80200</b>
Ignition Leads M4	<b>83960</b>
Ignition Leads	<b>85680</b>
80 (8C, B4) 2.0 E quattro	1991-94
ABK	85 115
Ignition Coil ->Ch.8C-P-300000	<b>80200</b>
Ignition Leads M4; With ignition distributor	<b>83960</b>
Ignition Leads	<b>85680</b>

AUDI Cont.	
80 (8C, B4) 2.3 E	1991-94
NG	98 133
Ignition Coil	<b>80200</b>
Ignition Leads M4; With ignition distributor	<b>83950</b>
Ignition Leads	<b>85680</b>
80 (8C, B4) 2.3 E quattro	1991-94
NG	98 133
Ignition Leads M4; With ignition distributor	<b>83950</b>
Ignition Leads	<b>85680</b>
80 (8C, B4) 2.6	1992-94
ABC	110 150
Ignition Leads	<b>85878</b>
80 (8C, B4) 2.6 quattro	1992-94
ABC	110 150
Ignition Leads	<b>85878</b>
80 (8C, B4) 2.8	1991-94
AAH	128 174
Ignition Leads	<b>85878</b>
80 (8C, B4) 2.8 quattro	1991-94
AAH	128 174
Ignition Leads	<b>85878</b>
80 Avant (8C, B4) 2.0	1992-96
ABT	66 90
Ignition Coil	<b>80200</b>
Ignition Leads M4; With ignition distributor	<b>83960</b>
Ignition Leads	<b>85680</b>
80 Avant (8C, B4) 2.0 E	1992-96
ABK	85 115
Ignition Coil 3 term.; ->07.1993	<b>80200</b>
Ignition Coil 6 term.	<b>80219</b>
Ignition Leads M4	<b>83960</b>
Ignition Leads	<b>85680</b>
80 Avant (8C, B4) 2.3 E	1992-96
NG	98 133
Ignition Leads M4	<b>83950</b>
Ignition Leads	<b>85680</b>
80 Avant (8C, B4) 2.3 E quattro	1991-94
NG	98 133
Ignition Leads M4	<b>83950</b>
Ignition Leads	<b>85680</b>
80 Avant (8C, B4) 2.6	1992-96
ABC	110 150
Ignition Leads	<b>85878</b>
80 Avant (8C, B4) 2.6 quattro	1992-95
ABC	110 150
Ignition Leads	<b>85878</b>
80 Avant (8C, B4) 2.8	1991-96
AAH	128 174
Ignition Leads	<b>85878</b>
80 Avant (8C, B4) 2.8 quattro	1992-95
AAH	128 174
Ignition Leads	<b>85878</b>
90 (81, 85, B2) 2.0	1984-87
JS/HP	85 115
Ignition Leads	<b>83950</b>
90 (81, 85, B2) 2.0	1986-87
SK	83 113
Ignition Leads	<b>83950</b>
90 (81, 85, B2) 2.2	1985-87
KX	85 115
Ignition Leads	<b>83950</b>
90 (81, 85, B2) 2.2	1984-87
KV/HY	100 136
Ignition Leads	<b>83950</b>
90 (81, 85, B2) 2.2 E quattro	1984-87
KV	100 136
Ignition Leads	<b>83950</b>
90 (81, 85, B2) 2.2 E quattro	1985-87
JT	88 120
Ignition Leads	<b>83950</b>
90 (89, 89Q, 8A, B3) 2.0	1988-91
PS	85 115
Ignition Leads	<b>83950</b>
90 (89, 89Q, 8A, B3) 2.0 20 V	1989-91
NM	118 160
Ignition Leads	<b>85680</b>
90 (89, 89Q, 8A, B3) 2.0 20 V quattro	1988-91
NM	118 160
Ignition Leads	<b>85680</b>



AUDI Cont.	
90 (89, 89Q, 8A, B3) 2.2 E	1987-91
KV	100 136
Ignition Leads	83950
90 (89, 89Q, 8A, B3) 2.2 E quattro	1987-91
KV	100 136
Ignition Leads	83950
90 (89, 89Q, 8A, B3) 2.3 E	1987-91
NG	100 136
Ignition Leads	83950
90 (89, 89Q, 8A, B3) 2.3 E	1987-91
NG	98 133
Ignition Leads	83950
90 (89, 89Q, 8A, B3) 2.3 E 20V	1990-91
7A	123 167
Ignition Leads	85680
90 (89, 89Q, 8A, B3) 2.3 E 20V	1988-91
7A	125 170
Ignition Leads	85680
90 (89, 89Q, 8A, B3) 2.3 E 20V quattro	1988-91
7A	125 170
Ignition Leads	85680
90 (89, 89Q, 8A, B3) 2.3 E 20V quattro	1990-91
7A	123 167
Ignition Leads	85680
90 (89, 89Q, 8A, B3) 2.3 E quattro	1987-91
NG	100 136
Ignition Leads	83950
90 (89, 89Q, 8A, B3) 2.3 E quattro	1987-91
NG	98 133
Ignition Leads	83950
A1 (8X1, 8XF) 1.2 TFSI	2010->
CBZA	63 86
Ignition Coil	80218
Ignition Leads	85871
A1 (8X1, 8XF) 1.4 TFSI	2012->
CPTA	103 140
Ignition Coil 02.2013-04.2015	80249
A1 (8X1, 8XF) 1.4 TFSI	2010->
CNVA/CAXA	90 122
Ignition Coil	80201
A1 (8X1, 8XF) 1.4 TFSI	2011->
CTHG/CTJA/CAVG	136 185
Ignition Coil	80201
A1 (8X1, 8XK) 1.0 TFSI	2015->
CHZB	70 95
Ignition Coil	80249
A1 (8X1, 8XK) 1.0 TFSI	2016->
CHZE	60 82
Ignition Coil	80249
A1 (8X1, 8XK) 1.4 TFSI	2014->
CZDB/CZCA	92 125
Ignition Coil ->06.2015	80249
A1 (8X1, 8XK) 1.4 TFSI	2014->
CZEA	110 150
Ignition Coil ->06.2015	80249
A1 Sportback (8XA, 8XF) 1.0 TFSI	2015->
CHZB	70 95
Ignition Coil	80249
A1 Sportback (8XA, 8XF) 1.0 TFSI	2016->
CHZE	60 82
Ignition Coil	80249
A1 Sportback (8XA, 8XF) 1.4 TFSI	2014->
CZCA	92 125
Ignition Coil ->06.2015	80249
A1 Sportback (8XA, 8XF) 1.4 TFSI	2014->
CZEA	110 150
Ignition Coil ->06.2015	80249
A1 Sportback (8XA, 8XK) 1.2 TFSI	2012->
CBZA	63 86
Ignition Coil ->04.2015	80218
Ignition Leads	85871
A1 Sportback (8XA, 8XK) 1.4 TFSI	2011->
CNVA/CAXA	90 122
Ignition Coil 05.2012-04.2015	80201
A1 Sportback (8XA, 8XK) 1.4 TFSI	2012->
CPTA	103 140
Ignition Coil 02.2013-04.2015	80249

AUDI Cont.	
A1 Sportback (8XA, 8XK) 1.4 TFSI	2011->
CTHG/CTJA/CAVG	136 185
Ignition Coil ->04.2015	80201
A2 (8Z0) 1.4	2000-05
BBY/AUA	55 75
Ignition Coil 11.2001->	80201
Ignition Coil	80218
Ignition Leads AUA	85696
A2 (8Z0) 1.6 FSI	2002-05
BAD	81 110
Ignition Coil	80201
A3 (8L1) 1.6	2000-03
AVU/BFQ	75 102
Ignition Coil	80218
Ignition Leads BFQ	85874
Ignition Leads	85879
A3 (8L1) 1.6	1996-03
AKL/APF/AEH	74 101
Ignition Coil	80218
Ignition Leads AEH/AKL/APF	85875
A3 (8L1) 1.8	1996-03
AGN/APG	92 125
Ignition Coil	80218
Ignition Leads ->08.2000; ->Ch.8L-V-140000	85061
Ignition Leads AGN; 09.2000->	85065
A3 (8L1) 1.8 T	1998-03
AJQ/APP/ARY/AUQ	132 180
Ignition Coil ARY; 09.2000->	80202
Ignition Coil APP/AJQ/AUQ	80239
A3 (8L1) 1.8 T	1996-03
ARZ/AQA/AGU/AUM	110 150
Ignition Coil AGU/AUM; 05.2001->	80202
Ignition Coil AQA, ARZ	80239
Ignition Coil AGU; ->04.2001	80252
A3 (8L1) 1.8 T quattro	1998-03
AJQ/ARY	132 180
Ignition Coil ARY; 09.2000->	80202
Ignition Coil AJQ; ->08.2000	80239
A3 (8L1) 1.8 T quattro	1996-03
ARX/AQA/AGU	110 150
Ignition Coil With regul.cat.(3way)	80202
Ignition Coil ARX,AGU,AQA	80239
Ignition Coil ->07.1998	80252
A3 (8L1) S3 quattro	1999-02
AMK/APY/AUL	154 210
Ignition Coil With regul.cat.(3way)	80202
Ignition Coil APY,AMK,AUL	80239
A3 (8L1) S3 quattro	2001-03
BAM	165 224
Ignition Coil With regul.cat.(3way)	80202
A3 (8P1) 1.2 TSI	2010-12
CBZB	77 105
Ignition Coil	80218
Ignition Leads	85871
A3 (8P1) 1.4 TFSI	2007-12
CMSA/CAXC	92 125
Ignition Coil	80201
A3 (8P1) 1.6	2003-12
BGU/BSF/BSE	75 102
Ignition Coil BGU	80218
Ignition Leads	85875
Ignition Leads	85879
A3 (8P1) 1.6 FSI	2003-07
BLF/BLP/BAG	85 115
Ignition Coil BLP/BAG; ->12.2004; Direct Injection	80201
A3 (8P1) 1.8 TFSI	2006-12
BZB/CDA/BYT	118 160
Ignition Coil	80240
A3 (8P1) 1.8 TFSI quattro	2008-12
CDA	118 160
Ignition Coil	80240
A3 (8P1) 2.0 FSI	2003-08
BLX/BLY/BMB/BLR/AXW/BVZ/BVY	110 150
Ignition Coil	80240
A3 (8P1) 2.0 TFSI	2004-12
BWA/AXX/CCZA/CAWB	147 200
Ignition Coil AXX	80240



AUDI Cont.	
<b>A3 (8P1) 2.0 TFSI quattro</b>	2004-12
BWA/AXX/CCZA/CCTA	147 200
Ignition Coil AXX	<b>80240</b>
<b>A3 (8P1) 3.2 V6 quattro</b>	2003-09
BDB/BMJ/BUB	184 250
Ignition Coil	<b>80327</b>
<b>A3 (8P1) S3 quattro</b>	2006-12
BHZ/CDLA	195 265
Ignition Coil	<b>80240</b>
<b>A3 (8P1) S3 quattro</b>	2007-12
BZC/CDLC	188 256
Ignition Coil	<b>80240</b>
<b>A3 (8V1) 1.2 TFSI</b>	2014->
CYVB	81 110
Ignition Coil	<b>80249</b>
<b>A3 (8V1) 1.2 TFSI</b>	2013->
CJZA	77 105
Ignition Coil ->05.2015	<b>80249</b>
<b>A3 (8V1) 1.4 TFSI</b>	2014->
CXSB/CZCA	92 125
Ignition Coil ->06.2015	<b>80249</b>
<b>A3 (8V1) 1.4 TFSI</b>	2014->
CZEA	110 150
Ignition Coil ->06.2015	<b>80249</b>
<b>A3 (8V1) 1.4 TFSI</b>	2012->
CMBA/CXSA	90 122
Ignition Coil	<b>80249</b>
<b>A3 (8V1) 1.4 TFSI</b>	2013->
CPTA	103 140
Ignition Coil	<b>80249</b>
<b>A3 (8V1) 1.8 TFSI</b>	2012->
CJSA	132 180
Ignition Coil	<b>80238</b>
<b>A3 (8V1) 1.8 TFSI quattro</b>	2012->
CJSB	132 180
Ignition Coil	<b>80238</b>
<b>A3 (8V1) S3 quattro</b>	2013->
CJXB	206 280
Ignition Coil	<b>80238</b>
<b>A3 (8V1) S3 quattro</b>	2012->
CJXC	221 300
Ignition Coil	<b>80238</b>
<b>A3 (8V1, 8VK) 1.0 TFSI</b>	2016->
CHZD	85 115
Ignition Coil	<b>80249</b>
<b>A3 Cabriolet (8P7) 1.2 TFSI</b>	2010-13
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>A3 Cabriolet (8P7) 1.4 TFSI</b>	2011-13
CAXC	92 125
Ignition Coil	<b>80201</b>
<b>A3 Cabriolet (8P7) 1.6</b>	2008-10
BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
Ignition Leads	<b>85879</b>
<b>A3 Cabriolet (8P7) 1.8 TFSI</b>	2008-13
BZB/CDA	118 160
Ignition Coil	<b>80240</b>
<b>A3 Cabriolet (8P7) 2.0 TFSI</b>	2008-13
CCZA/CAWB	147 200
Ignition Coil	<b>80240</b>
<b>A3 Cabriolet (8V7) 1.4 TFSI</b>	2013->
CPTA	103 140
Ignition Coil ->05.2014	<b>80249</b>
<b>A3 Cabriolet (8V7) 1.4 TFSI</b>	2014->
CXSB/CZCA	92 125
Ignition Coil ->06.2015	<b>80249</b>
<b>A3 Cabriolet (8V7) 1.4 TFSI</b>	2014->
CZEA	110 150
Ignition Coil ->06.2015	<b>80249</b>
<b>A3 Cabriolet (8V7) 1.8 TFSI</b>	2013->
CJSA	132 180
Ignition Coil	<b>80238</b>
<b>A3 Cabriolet (8V7) 1.8 TFSI quattro</b>	2014->
CJSB	132 180
Ignition Coil	<b>80238</b>

AUDI Cont.	
<b>A3 Cabriolet (8V7, 8VE) 1.4 TFSI</b>	2016->
CZCC	85 115
Ignition Coil ->07.2016	<b>80249</b>
<b>A3 Limousine (8VS) 1.2 TFSI</b>	2014->
CYVB	81 110
Ignition Coil	<b>80249</b>
<b>A3 Limousine (8VS) 1.2 TFSI</b>	2013->
CJZA	77 105
Ignition Coil ->05.2015	<b>80249</b>
<b>A3 Limousine (8VS) 1.4 TFSI</b>	2014->
CZEA	110 150
Ignition Coil	<b>80249</b>
<b>A3 Limousine (8VS) 1.4 TFSI</b>	2013->
CMBA/CXSA	90 122
Ignition Coil CXSA	<b>80249</b>
<b>A3 Limousine (8VS) 1.4 TFSI</b>	2013->
CXSB/CZCA	92 125
Ignition Coil CXSB; ->05.2015	<b>80249</b>
<b>A3 Limousine (8VS) 1.4 TFSI</b>	2013->
CPTA	103 140
Ignition Coil 09.2013->	<b>80249</b>
<b>A3 Limousine (8VS) 1.8 TFSI</b>	2013->
CJSB/CJSA	132 180
Ignition Coil	<b>80238</b>
<b>A3 Limousine (8VS) 1.8 TFSI quattro</b>	2013->
CJSB	132 180
Ignition Coil	<b>80238</b>
<b>A3 Limousine (8VS, 8VM) 1.0 TFSI</b>	2016->
CHZD	85 115
Ignition Coil	<b>80249</b>
<b>A3 Sportback (8PA) 1.2 TSI</b>	2010-13
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>A3 Sportback (8PA) 1.4 TFSI</b>	2007-13
CMSA/CAXC	92 125
Ignition Coil	<b>80201</b>
<b>A3 Sportback (8PA) 1.6</b>	2004-13
BGU/BSF/BSE	75 102
Ignition Coil BGU	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>A3 Sportback (8PA) 1.6 FSI</b>	2004-07
BLF/BLP	85 115
Ignition Coil	<b>80201</b>
<b>A3 Sportback (8PA) 1.8 TFSI</b>	2006-13
BZB/CDA/AYT	118 160
Ignition Coil	<b>80240</b>
<b>A3 Sportback (8PA) 1.8 TFSI quattro</b>	2008-13
CDA	118 160
Ignition Coil	<b>80240</b>
<b>A3 Sportback (8PA) 2.0 FSI</b>	2004-08
BLX/BLY/BMB/BLR/AXW/BVZ/BVY	110 150
Ignition Coil	<b>80240</b>
<b>A3 Sportback (8PA) 2.0 TFSI</b>	2004-13
BWA/BPY/AXX/CCZA/CBFA/CAWB	147 200
Ignition Coil BPY,AXX	<b>80240</b>
<b>A3 Sportback (8PA) 2.0 TFSI quattro</b>	2004-13
BWA/BPY/AXX/CCZA	147 200
Ignition Coil AXX	<b>80240</b>
<b>A3 Sportback (8PA) 3.2 V6 quattro</b>	2004-09
BMJ/BUB	184 250
Ignition Coil	<b>80327</b>
<b>A3 Sportback (8PA) S3 quattro</b>	2008-13
BHZ/CDLA	195 265
Ignition Coil	<b>80240</b>
<b>A3 Sportback (8PA) S3 quattro</b>	2008-13
CDLC	188 256
Ignition Coil	<b>80240</b>
<b>A3 Sportback (8VA) 1.2 TFSI</b>	2014->
CYVB	81 110
Ignition Coil	<b>80249</b>
<b>A3 Sportback (8VA) 1.2 TFSI</b>	2013->
CJZA	77 105
Ignition Coil ->05.2015	<b>80249</b>
<b>A3 Sportback (8VA) 1.4 TFSI</b>	2014->
CXSB/CZCA	92 125
Ignition Coil CZCA; ->06.2015	<b>80249</b>



AUDI Cont.	
<b>A3 Sportback (8VA) 1.4 TFSI</b>	2014->
CZEA	110 150
Ignition Coil ->06.2015	<b>80249</b>
<b>A3 Sportback (8VA) 1.4 TFSI</b>	2012->
CMBA/CXSA	90 122
Ignition Coil	<b>80249</b>
<b>A3 Sportback (8VA) 1.4 TFSI</b>	2013->
CPTA	103 140
Ignition Coil	<b>80249</b>
<b>A3 Sportback (8VA) 1.4 TFSI g-tron</b>	2013->
CPWA	81 110
Ignition Coil ->06.2015	<b>80249</b>
<b>A3 Sportback (8VA) 1.8 TFSI</b>	2012->
CJSB/CJSA	132 180
Ignition Coil	<b>80238</b>
<b>A3 Sportback (8VA) 1.8 TFSI quattro</b>	2013->
CJSB	132 180
Ignition Coil	<b>80238</b>
<b>A3 Sportback (8VA) S3 quattro</b>	2012->
CJXC	221 300
Ignition Coil	<b>80238</b>
<b>A3 Sportback (8VA, 8VF) 1.0 TFSI</b>	2016->
CHZD	85 115
Ignition Coil	<b>80249</b>
<b>A3 Sportback (8VA, 8VF) 1.4 TFSI e-tron</b>	2014->
CUKB/CXUA	110 150
Ignition Coil CUKB; ->06.2015	<b>80249</b>
<b>A4 (8D2, B5) 1.6</b>	2000-00
ALZ	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>A4 (8D2, B5) 1.6</b>	1994-00
AHL/ADP/ARM/ANA	74 100
Ignition Coil	<b>80218</b>
Ignition Leads ADP	<b>85870</b>
Ignition Leads ADP/AHL	<b>85875</b>
<b>A4 (8D2, B5) 1.8</b>	1995-00
AFY	85 115
Ignition Leads	<b>85682</b>
<b>A4 (8D2, B5) 1.8</b>	1994-00
AVV/ADR/APT/ARG	92 125
Ignition Leads	<b>85682</b>
<b>A4 (8D2, B5) 1.8 quattro</b>	1995-00
AFY	85 115
Ignition Leads	<b>85682</b>
<b>A4 (8D2, B5) 1.8 quattro</b>	1995-00
ADR/APT/ARG	92 125
Ignition Leads	<b>85682</b>
<b>A4 (8D2, B5) 1.8 T</b>	1997-00
AJL	132 180
Ignition Coil AJL	<b>80252</b>
<b>A4 (8D2, B5) 1.8 T</b>	1995-00
ARK/AEB/ANB/APU/AWT	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil ->12.1998	<b>80252</b>
<b>A4 (8D2, B5) 1.8 T quattro</b>	1997-00
AJL	132 180
Ignition Coil AJL	<b>80252</b>
<b>A4 (8D2, B5) 1.8 T quattro</b>	1995-00
ARK/AEB/ANB/APU/AWT	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil ->12.1998	<b>80252</b>
<b>A4 (8D2, B5) 2.4</b>	1997-00
AMM/APZ/AJG	120 163
Ignition Leads AMM	<b>85062</b>
Ignition Leads APZ	<b>85878</b>
<b>A4 (8D2, B5) 2.4</b>	1997-00
AML/ARJ/ALF/AGA/APS	121 165
Ignition Leads AGA/ALF/APS/ARJ	<b>85062</b>
Ignition Leads AML	<b>85878</b>
<b>A4 (8D2, B5) 2.4 quattro</b>	1997-00
APZ	120 163
Ignition Leads ->06.2000	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A4 (8D2, B5) 2.4 quattro</b>	1997-00
AML/ARJ/ALF/AGA/APS	121 165
Ignition Leads AGA	<b>85062</b>
Ignition Leads ARJ	<b>85878</b>

AUDI Cont.	
<b>A4 (8D2, B5) 2.6</b>	1995-00
ABC	110 150
Ignition Leads 07.1997->	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A4 (8D2, B5) 2.6 quattro</b>	1995-00
ABC	110 150
Ignition Leads ABC	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A4 (8D2, B5) 2.8</b>	1995-97
AAH	128 174
Ignition Leads	<b>85878</b>
<b>A4 (8D2, B5) 2.8</b>	1996-00
APR/ACK/ALG/AHA/AQD/AMX	142 193
Ignition Leads AMX	<b>85062</b>
Ignition Leads ACK	<b>85878</b>
<b>A4 (8D2, B5) 2.8 quattro</b>	1995-97
AAH	128 174
Ignition Leads	<b>85878</b>
<b>A4 (8D2, B5) 2.8 quattro</b>	1996-01
APR/ACK/ALG/AHA/AQD/AMX	142 193
Ignition Leads AMX	<b>85062</b>
Ignition Leads APR	<b>85878</b>
<b>A4 (8D2, B5) S4 quattro</b>	1997-01
AGB/AZB	195 265
Ignition Coil AZB,AGB	<b>80252</b>
<b>A4 (8E2, B6) 1.6</b>	2000-04
ALZ	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
Ignition Leads	<b>85879</b>
<b>A4 (8E2, B6) 1.8 T</b>	2000-02
AVJ	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 (8E2, B6) 1.8 T</b>	2002-04
BFB	120 163
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 (8E2, B6) 1.8 T</b>	2002-04
BEX	140 190
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 (8E2, B6) 1.8 T quattro</b>	2000-02
AVJ	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 (8E2, B6) 1.8 T quattro</b>	2002-04
BFB	120 163
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 (8E2, B6) 1.8 T quattro</b>	2002-04
BEX	140 190
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 (8E2, B6) 2.0 FSI</b>	2002-04
AWA	110 150
Ignition Coil ->Ch.8E..4..400 000; ->05.2004	<b>80240</b>
Ignition Coil AWA	<b>80248</b>
<b>A4 (8E2, B6) 2.4</b>	2001-04
BDV	125 170
Ignition Leads	<b>85062</b>
<b>A4 (8E2, B6) 2.4</b>	2001-04
AMM	120 163
Ignition Leads	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A4 (8EC, B7) 1.6</b>	2004-08
ALZ	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>A4 (8EC, B7) 1.8 T</b>	2004-08
BFB	120 163
Ignition Coil	<b>80202</b>
<b>A4 (8EC, B7) 1.8 T quattro</b>	2004-08
BFB	120 163
Ignition Coil	<b>80202</b>
<b>A4 (8EC, B7) 2.0</b>	2004-08
ALT	96 130
Ignition Coil	<b>80202</b>
<b>A4 (8EC, B7) 2.0 TFSI</b>	2004-08
BPG/BWT/BGB/BWE	147 200
Ignition Coil BPG,BGB	<b>80240</b>
<b>A4 (8EC, B7) 2.0 TFSI</b>	2005-08
BUL	162 220
Ignition Coil	<b>80240</b>





AUDI Cont.	
<b>A4 (8EC, B7) 2.0 TFSI</b>	<b>2006-08</b>
BPJ/BYK	125 170
Ignition Coil	<b>80240</b>
<b>A4 (8EC, B7) 2.0 TFSI quattro</b>	<b>2004-08</b>
BPG/BWT/BGB/BWE	147 200
Ignition Coil BGB,BWE,BWT	<b>80240</b>
<b>A4 (8EC, B7) 2.0 TFSI quattro</b>	<b>2005-08</b>
BUL	162 220
Ignition Coil	<b>80240</b>
<b>A4 (8EC, B7) 3.2 FSI</b>	<b>2005-08</b>
AUK	188 255
Ignition Coil	<b>80248</b>
<b>A4 (8EC, B7) 3.2 FSI quattro</b>	<b>2005-08</b>
AUK/BKH	188 255
Ignition Coil	<b>80248</b>
<b>A4 (8K2, B8) 1.8 TFSI</b>	<b>2011-15</b>
CJEB	125 170
Ignition Coil	<b>80238</b>
<b>A4 (8K2, B8) 1.8 TFSI</b>	<b>2007-12</b>
CDHB/CABB	118 160
Ignition Coil	<b>80240</b>
<b>A4 (8K2, B8) 1.8 TFSI</b>	<b>2008-15</b>
CABA/CDHA	88 120
Ignition Coil	<b>80240</b>
<b>A4 (8K2, B8) 1.8 TFSI quattro</b>	<b>2011-15</b>
CJEB	125 170
Ignition Coil	<b>80238</b>
<b>A4 (8K2, B8) 1.8 TFSI quattro</b>	<b>2008-12</b>
CDHB	118 160
Ignition Coil	<b>80240</b>
<b>A4 (8K2, B8) 2.0 TFSI</b>	<b>2008-15</b>
CDNB/CFKA/CAEA	132 180
Ignition Coil	<b>80240</b>
<b>A4 (8K2, B8) 2.0 TFSI</b>	<b>2008-13</b>
CAEB/CDNC	155 211
Ignition Coil	<b>80240</b>
<b>A4 (8K2, B8) 2.0 TFSI</b>	<b>2013-15</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A4 (8K2, B8) 2.0 TFSI flexible fuel</b>	<b>2009-15</b>
CFKA	132 180
Ignition Coil	<b>80240</b>
<b>A4 (8K2, B8) 2.0 TFSI flexible fuel quattro</b>	<b>2009-15</b>
CFKA	132 180
Ignition Coil	<b>80240</b>
<b>A4 (8K2, B8) 2.0 TFSI quattro</b>	<b>2008-15</b>
CAEB/CPMA/CDNC	155 211
Ignition Coil	<b>80240</b>
<b>A4 (8K2, B8) 2.0 TFSI quattro</b>	<b>2013-15</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A4 (8K2, B8) 3.0 TFSI quattro</b>	<b>2012-&gt;</b>
CRED/CMUA	200 272
Ignition Coil	<b>80248</b>
<b>A4 (8K2, B8) 3.2 FSI</b>	<b>2008-12</b>
CALA	195 265
Ignition Coil	<b>80248</b>
<b>A4 (8K2, B8) 3.2 FSI quattro</b>	<b>2007-12</b>
CALA	195 265
Ignition Coil	<b>80248</b>
<b>A4 (8K2, B8) S4 quattro</b>	<b>2008-15</b>
CGWC/CTUB/CAKA/CCBA/CGXC/CREC	245 333
Ignition Coil	<b>80240</b>
Ignition Coil CAKA	<b>80248</b>
<b>A4 (8W2, B9) 1.4 TFSI</b>	<b>2015-&gt;</b>
CVNA	110 150
Ignition Coil	<b>80249</b>
<b>A4 4WD (8KH, B8) 2.0 TFSI quattro</b>	<b>2009-16</b>
CPMA/CDNC	155 211
Ignition Coil	<b>80240</b>
<b>A4 4WD (8KH, B8) 2.0 TFSI quattro</b>	<b>2013-16</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A4 Avant (8D5, B5) 1.6</b>	<b>2000-01</b>
ALZ	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>

AUDI Cont.	
<b>A4 Avant (8D5, B5) 1.6</b>	<b>1994-01</b>
AHL/ADP/ARM/ANA	74 100
Ignition Coil	<b>80218</b>
Ignition Leads ADP	<b>85870</b>
Ignition Leads ADP/AHL	<b>85875</b>
<b>A4 Avant (8D5, B5) 1.8</b>	<b>1995-01</b>
AFY	85 115
Ignition Leads	<b>85682</b>
<b>A4 Avant (8D5, B5) 1.8</b>	<b>1996-01</b>
AVV/ADR/APT/ARG	92 125
Ignition Leads	<b>85682</b>
<b>A4 Avant (8D5, B5) 1.8 quattro</b>	<b>1995-01</b>
AFY	85 115
Ignition Leads	<b>85682</b>
<b>A4 Avant (8D5, B5) 1.8 quattro</b>	<b>1996-01</b>
ADR/APT/ARG	92 125
Ignition Leads	<b>85682</b>
<b>A4 Avant (8D5, B5) 1.8 T</b>	<b>1997-01</b>
AJL	132 180
Ignition Coil AJL	<b>80252</b>
<b>A4 Avant (8D5, B5) 1.8 T</b>	<b>1996-01</b>
ARK/AEB/ANB/APU/AWT	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil AEB,ARK,ANB,AWT,APU	<b>80252</b>
<b>A4 Avant (8D5, B5) 1.8 T quattro</b>	<b>1997-01</b>
AJL	132 180
Ignition Coil AJL	<b>80252</b>
<b>A4 Avant (8D5, B5) 1.8 T quattro</b>	<b>1996-01</b>
ARK/AEB/ANB/APU/AWT	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil AWT,ANB,AEB,ARK,APU	<b>80252</b>
<b>A4 Avant (8D5, B5) 2.4</b>	<b>1997-01</b>
AMM/APZ/AJG	120 163
Ignition Leads AMM	<b>85062</b>
Ignition Leads APZ	<b>85878</b>
<b>A4 Avant (8D5, B5) 2.4</b>	<b>1997-01</b>
AML/ARJ/ALF/AGA/APS	121 165
Ignition Leads ARJ	<b>85062</b>
Ignition Leads ALF	<b>85878</b>
<b>A4 Avant (8D5, B5) 2.4 quattro</b>	<b>1997-01</b>
APZ	120 163
Ignition Leads ->06.2000	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A4 Avant (8D5, B5) 2.4 quattro</b>	<b>1997-01</b>
AML/ARJ/ALF/AGA/APS	121 165
Ignition Leads APS	<b>85062</b>
Ignition Leads AGA	<b>85878</b>
<b>A4 Avant (8D5, B5) 2.6</b>	<b>1996-01</b>
ABC	110 150
Ignition Leads ABC	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A4 Avant (8D5, B5) 2.6 quattro</b>	<b>1996-01</b>
ABC	110 150
Ignition Leads ABC	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A4 Avant (8D5, B5) 2.8</b>	<b>1996-96</b>
AAH	128 174
Ignition Leads	<b>85878</b>
<b>A4 Avant (8D5, B5) 2.8</b>	<b>1996-01</b>
APR/ACK/ALG/AHA/AQD/AMX	142 193
Ignition Leads AQD	<b>85062</b>
Ignition Leads ACK	<b>85878</b>
<b>A4 Avant (8D5, B5) 2.8 quattro</b>	<b>1996-96</b>
AAH	128 174
Ignition Leads	<b>85878</b>
<b>A4 Avant (8D5, B5) 2.8 quattro</b>	<b>1996-01</b>
APR/ACK/ALG/AHA/AQD/AMX	142 193
Ignition Leads ACK	<b>85062</b>
Ignition Leads AMX	<b>85878</b>
<b>A4 Avant (8D5, B5) RS4 quattro</b>	<b>2000-01</b>
AZR/ASJ	280 380
Ignition Coil 11.2000->	<b>80252</b>
<b>A4 Avant (8D5, B5) S4 quattro</b>	<b>1997-01</b>
AGB/AZB	195 265
Ignition Coil AGB,AZB	<b>80252</b>



AUDI Cont.	
<b>A4 Avant (8E5, B6) 1.6</b>	<b>2001-04</b>
ALZ	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
Ignition Leads	<b>85879</b>
<b>A4 Avant (8E5, B6) 1.8 T</b>	<b>2001-02</b>
AVJ	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 Avant (8E5, B6) 1.8 T</b>	<b>2002-04</b>
BFB	120 163
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 Avant (8E5, B6) 1.8 T</b>	<b>2002-04</b>
BEX	140 190
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 Avant (8E5, B6) 1.8 T quattro</b>	<b>2001-02</b>
AVJ	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 Avant (8E5, B6) 1.8 T quattro</b>	<b>2002-04</b>
BFB	120 163
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 Avant (8E5, B6) 1.8 T quattro</b>	<b>2002-04</b>
BEX	140 190
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 Avant (8E5, B6) 2.0 FSI</b>	<b>2002-04</b>
AWA	110 150
Ignition Coil ->Ch.8E..4..400 000; ->05.2004	<b>80240</b>
Ignition Coil AWA	<b>80248</b>
<b>A4 Avant (8E5, B6) 2.4</b>	<b>2001-04</b>
BDV	125 170
Ignition Leads	<b>85062</b>
<b>A4 Avant (8E5, B6) 2.4</b>	<b>2001-04</b>
AMM	120 163
Ignition Leads	<b>85062</b>
<b>A4 Avant (8ED, B7) 1.6</b>	<b>2004-08</b>
ALZ	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>A4 Avant (8ED, B7) 1.8 T</b>	<b>2004-08</b>
BFB	120 163
Ignition Coil	<b>80202</b>
<b>A4 Avant (8ED, B7) 1.8 T quattro</b>	<b>2004-08</b>
BFB	120 163
Ignition Coil	<b>80202</b>
<b>A4 Avant (8ED, B7) 2.0</b>	<b>2004-08</b>
ALT	96 130
Ignition Coil	<b>80202</b>
<b>A4 Avant (8ED, B7) 2.0 TFSI</b>	<b>2004-08</b>
BGB/BWE	147 200
Ignition Coil BGB	<b>80240</b>
<b>A4 Avant (8ED, B7) 2.0 TFSI</b>	<b>2005-08</b>
BUL	162 220
Ignition Coil	<b>80240</b>
<b>A4 Avant (8ED, B7) 2.0 TFSI</b>	<b>2006-08</b>
BPJ/BYK	125 170
Ignition Coil	<b>80240</b>
<b>A4 Avant (8ED, B7) 2.0 TFSI quattro</b>	<b>2004-08</b>
BWT/BGB/BWE	147 200
Ignition Coil BWE,BGB	<b>80240</b>
<b>A4 Avant (8ED, B7) 2.0 TFSI quattro</b>	<b>2005-08</b>
BUL	162 220
Ignition Coil	<b>80240</b>
<b>A4 Avant (8ED, B7) 3.2 FSI</b>	<b>2005-08</b>
AUK	188 255
Ignition Coil	<b>80248</b>
<b>A4 Avant (8ED, B7) 3.2 FSI quattro</b>	<b>2005-08</b>
AUK	188 255
Ignition Coil	<b>80248</b>
<b>A4 Avant (8ED, B7) RS4 quattro</b>	<b>2005-08</b>
BNS	309 420
Ignition Coil	<b>80240</b>
<b>A4 Avant (8K5, B8) 1.8 TFSI</b>	<b>2011-15</b>
CJEB	125 170
Ignition Coil	<b>80238</b>
<b>A4 Avant (8K5, B8) 1.8 TFSI</b>	<b>2007-12</b>
CDHB/CABB	118 160
Ignition Coil	<b>80240</b>
<b>A4 Avant (8K5, B8) 1.8 TFSI</b>	<b>2008-15</b>
CDHA	88 120
Ignition Coil	<b>80240</b>

AUDI Cont.	
<b>A4 Avant (8K5, B8) 1.8 TFSI quattro</b>	<b>2011-15</b>
CJEB	125 170
Ignition Coil	<b>80238</b>
<b>A4 Avant (8K5, B8) 1.8 TFSI quattro</b>	<b>2008-12</b>
CDHB	118 160
Ignition Coil	<b>80240</b>
<b>A4 Avant (8K5, B8) 2.0 TFSI</b>	<b>2008-13</b>
CAEB/CDNC	155 211
Ignition Coil	<b>80240</b>
<b>A4 Avant (8K5, B8) 2.0 TFSI</b>	<b>2008-15</b>
CDNB/CFKA/CAEA	132 180
Ignition Coil	<b>80240</b>
<b>A4 Avant (8K5, B8) 2.0 TFSI</b>	<b>2013-15</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A4 Avant (8K5, B8) 2.0 TFSI flexible fuel</b>	<b>2009-15</b>
CFKA	132 180
Ignition Coil	<b>80240</b>
<b>A4 Avant (8K5, B8) 2.0 TFSI flexible fuel quattro</b>	<b>2009-15</b>
CFKA	132 180
Ignition Coil	<b>80240</b>
<b>A4 Avant (8K5, B8) 2.0 TFSI quattro</b>	<b>2008-15</b>
CAEB/CDNC	155 211
Ignition Coil	<b>80240</b>
<b>A4 Avant (8K5, B8) 2.0 TFSI quattro</b>	<b>2013-15</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A4 Avant (8K5, B8) 3.0 TFSI quattro</b>	<b>2012-&gt;</b>
CRED/CMUA	200 272
Ignition Coil	<b>80248</b>
<b>A4 Avant (8K5, B8) 3.2 FSI</b>	<b>2008-12</b>
CALA	195 265
Ignition Coil	<b>80248</b>
<b>A4 Avant (8K5, B8) 3.2 FSI quattro</b>	<b>2008-12</b>
CALA	195 265
Ignition Coil	<b>80248</b>
<b>A4 Avant (8K5, B8) S4 quattro</b>	<b>2008-15</b>
CGWC/CTUB/CAKA/CCBA/CGXC/CREC	245 333
Ignition Coil	<b>80248</b>
<b>A4 Avant (8W5, B9) 1.4 TFSI</b>	<b>2016-&gt;</b>
CVNA	110 150
Ignition Coil	<b>80249</b>
<b>A4 Cabriolet (8H7, B6, 8HE, B7) 1.8 T</b>	<b>2002-09</b>
BFB	120 163
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>A4 Cabriolet (8H7, B6, 8HE, B7) 1.8 T quattro</b>	<b>2003-09</b>
BFB	120 163
Ignition Coil Intake manifold injection	<b>80202</b>
<b>A4 Cabriolet (8H7, B6, 8HE, B7) 2.0 TFSI 16V</b>	<b>2006-09</b>
BWT/BWE	147 200
Ignition Coil	<b>80240</b>
<b>A4 Cabriolet (8H7, B6, 8HE, B7) 2.4</b>	<b>2002-05</b>
BDV	125 170
Ignition Leads	<b>85062</b>
<b>A4 Cabriolet (8H7, B6, 8HE, B7) 2.4</b>	<b>2002-05</b>
AMM	120 163
Ignition Leads	<b>85062</b>
<b>A4 Cabriolet (8H7, B6, 8HE, B7) 3.2 FSI</b>	<b>2006-09</b>
AUK	188 255
Ignition Coil	<b>80248</b>
<b>A4 Cabriolet (8H7, B6, 8HE, B7) 3.2 FSI quattro</b>	<b>2006-09</b>
AUK	188 255
Ignition Coil	<b>80248</b>
<b>A4 Cabriolet (8H7, B6, 8HE, B7) RS4 quattro</b>	<b>2006-09</b>
BNS	309 420
Ignition Coil	<b>80240</b>
<b>A5 (8T3) 1.8 TFSI</b>	<b>2007-17</b>
CABD/CJEB	125 170
Ignition Coil CJEB; 08.2011->	<b>80238</b>
Ignition Coil	<b>80240</b>
<b>A5 (8T3) 1.8 TFSI</b>	<b>2009-11</b>
CDHB	118 160
Ignition Coil	<b>80240</b>
<b>A5 (8T3) 2.0 TFSI</b>	<b>2008-12</b>
CDNB	132 180
Ignition Coil	<b>80240</b>
<b>A5 (8T3) 2.0 TFSI</b>	<b>2008-13</b>
CDNC	155 211
Ignition Coil	<b>80240</b>



AUDI Cont.	
<b>A5 (8T3) 2.0 TFSI</b>	<b>2013-16</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A5 (8T3) 2.0 TFSI quattro</b>	<b>2008-17</b>
CAEB/CDNC	155 211
Ignition Coil	<b>80240</b>
<b>A5 (8T3) 2.0 TFSI quattro</b>	<b>2013-16</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A5 (8T3) 3.0 TFSI quattro</b>	<b>2011-&gt;</b>
CMUA	200 272
Ignition Coil	<b>80248</b>
<b>A5 (8T3) 3.2 FSI</b>	<b>2007-12</b>
CALA	195 265
Ignition Coil	<b>80248</b>
<b>A5 (8T3) 3.2 FSI quattro</b>	<b>2007-12</b>
CALA	195 265
Ignition Coil	<b>80248</b>
<b>A5 (8T3) S5 quattro</b>	<b>2011-&gt;</b>
CGWC/CTDA/CTUB/CAKA/CGXC/CREC	245 333
Ignition Coil	<b>80248</b>
<b>A5 (8T3) S5 quattro</b>	<b>2007-12</b>
CAUA	260 354
Ignition Coil	<b>80248</b>
<b>A5 Cabriolet (8F7) 1.8 TFSI</b>	<b>2011-16</b>
CABD/CJEB	125 170
Ignition Coil CJEB; ->05.2015	<b>80238</b>
<b>A5 Cabriolet (8F7) 1.8 TFSI</b>	<b>2009-12</b>
CDHB	118 160
Ignition Coil	<b>80240</b>
<b>A5 Cabriolet (8F7) 2.0 TFSI</b>	<b>2009-12</b>
CDNB/CAEA	132 180
Ignition Coil	<b>80240</b>
<b>A5 Cabriolet (8F7) 2.0 TFSI</b>	<b>2009-14</b>
CAEB/CDNC	155 211
Ignition Coil	<b>80240</b>
<b>A5 Cabriolet (8F7) 2.0 TFSI</b>	<b>2013-16</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A5 Cabriolet (8F7) 2.0 TFSI quattro</b>	<b>2009-17</b>
CAEB/CPMA/CDNC	155 211
Ignition Coil	<b>80240</b>
<b>A5 Cabriolet (8F7) 2.0 TFSI quattro</b>	<b>2013-16</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A5 Cabriolet (8F7) 3.0 TFSI quattro</b>	<b>2011-&gt;</b>
CMUA	200 272
Ignition Coil	<b>80248</b>
<b>A5 Cabriolet (8F7) 3.2 FSI</b>	<b>2009-12</b>
CALA	195 265
Ignition Coil	<b>80248</b>
<b>A5 Cabriolet (8F7) 3.2 FSI quattro</b>	<b>2009-12</b>
CALA	195 265
Ignition Coil	<b>80248</b>
<b>A5 Cabriolet (8F7) S5 quattro</b>	<b>2009-17</b>
CGWC/CTDA/CTUB/CAKA/CGBA/CGXC/CREC	245 333
Ignition Coil	<b>80248</b>
<b>A5 Sportback (8TA) 1.8 TFSI</b>	<b>2014-17</b>
CJED	106 144
Ignition Coil	<b>80238</b>
<b>A5 Sportback (8Ta) 1.8 TFSI</b>	<b>2011-17</b>
CJEB	125 170
Ignition Coil	<b>80238</b>
<b>A5 Sportback (8Ta) 1.8 TFSI</b>	<b>2009-11</b>
CDHB	118 160
Ignition Coil	<b>80240</b>
<b>A5 Sportback (8Ta) 2.0 TFSI</b>	<b>2009-14</b>
CDNB	132 180
Ignition Coil	<b>80240</b>
<b>A5 Sportback (8Ta) 2.0 TFSI</b>	<b>2009-13</b>
CDNC	155 211
Ignition Coil	<b>80240</b>
<b>A5 Sportback (8Ta) 2.0 TFSI</b>	<b>2013-16</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A5 Sportback (8Ta) 2.0 TFSI quattro</b>	<b>2009-17</b>
CAEB/CDNC	155 211
Ignition Coil	<b>80240</b>

AUDI Cont.	
<b>A5 Sportback (8Ta) 2.0 TFSI quattro</b>	<b>2013-16</b>
CNCD	165 224
Ignition Coil	<b>80238</b>
<b>A5 Sportback (8Ta) 3.0 TFSI quattro</b>	<b>2011-&gt;</b>
CMUA	200 272
Ignition Coil	<b>80248</b>
<b>A5 Sportback (8Ta) 3.2 FSI quattro</b>	<b>2009-12</b>
CALA	195 265
Ignition Coil	<b>80248</b>
<b>A5 Sportback (8Ta) S5 quattro</b>	<b>2010-17</b>
CGWC/CTDA/CTUB/CAKA/CGXC/CREC	245 333
Ignition Coil	<b>80248</b>
<b>A6 (4A, C4) 1.8</b>	<b>1995-97</b>
ADR	92 125
Ignition Leads	<b>85682</b>
<b>A6 (4A, C4) 1.8 quattro</b>	<b>1995-97</b>
ADR	92 125
Ignition Leads	<b>85682</b>
<b>A6 (4A, C4) 2.0</b>	<b>1994-97</b>
AAE	74 101
Ignition Leads	<b>85690</b>
<b>A6 (4A, C4) 2.0</b>	<b>1994-97</b>
ABK	85 115
Ignition Leads	<b>85690</b>
<b>A6 (4A, C4) 2.6</b>	<b>1994-97</b>
ABC	110 150
Ignition Leads	<b>85878</b>
<b>A6 (4A, C4) 2.6</b>	<b>1994-97</b>
ACZ	102 139
Ignition Leads	<b>85878</b>
<b>A6 (4A, C4) 2.6 quattro</b>	<b>1994-97</b>
ABC	110 150
Ignition Leads	<b>85878</b>
<b>A6 (4A, C4) 2.8</b>	<b>1994-97</b>
AEJ/AAH/AFC	128 174
Ignition Leads	<b>85878</b>
<b>A6 (4A, C4) 2.8</b>	<b>1995-97</b>
ACK	142 193
Ignition Leads <4B2, C5>; 04.1997->	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A6 (4A, C4) 2.8 quattro</b>	<b>1994-97</b>
AEJ/AAH	128 174
Ignition Leads	<b>85878</b>
<b>A6 (4A, C4) 2.8 quattro</b>	<b>1995-97</b>
ACK	142 193
Ignition Leads ACK	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A6 (4A, C4) S6 Plus quattro</b>	<b>1996-97</b>
AHK	240 326
Ignition Coil AHK	<b>80252</b>
<b>A6 (4B2, C5) 1.8</b>	<b>1997-05</b>
AFY	85 116
Ignition Leads	<b>85682</b>
<b>A6 (4B2, C5) 1.8</b>	<b>1997-05</b>
ANQ/ARH/AJP/AQE	92 125
Ignition Coil AQE,ARH,ANQ,AJP	<b>80239</b>
<b>A6 (4B2, C5) 1.8 T</b>	<b>1997-05</b>
AJL	132 180
Ignition Coil AJL	<b>80252</b>
<b>A6 (4B2, C5) 1.8 T</b>	<b>1997-05</b>
ARK/AEB/ANB/APU/AWT/AWL	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil ->01.1999	<b>80252</b>
<b>A6 (4B2, C5) 1.8 T quattro</b>	<b>1997-05</b>
AJL	132 180
Ignition Coil AJL	<b>80252</b>
<b>A6 (4B2, C5) 1.8 T quattro</b>	<b>1997-05</b>
ARK/AEB/ANB/APU/AWT	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil ->01.1999	<b>80252</b>
<b>A6 (4B2, C5) 2.0</b>	<b>2001-05</b>
ALT	96 130
Ignition Coil	<b>80202</b>
<b>A6 (4B2, C5) 2.4</b>	<b>1998-05</b>
ARN/ASM/ALW	100 136
Ignition Leads	<b>85062</b>
Ignition Leads	<b>85878</b>



AUDI Cont.		
<b>A6 (4B2, C5) 2.4</b>		<b>1997-05</b>
APC		115 156
Ignition Leads		<b>85062</b>
Ignition Leads		<b>85878</b>
<b>A6 (4B2, C5) 2.4</b>		<b>2001-05</b>
BDV		125 170
Ignition Leads		<b>85062</b>
<b>A6 (4B2, C5) 2.4</b>		<b>1997-05</b>
AMM/APZ/AJG		120 163
Ignition Leads		<b>85062</b>
Ignition Leads		<b>85878</b>
<b>A6 (4B2, C5) 2.4</b>		<b>1997-05</b>
AML/ARJ/ALF/AGA/APS		121 165
Ignition Leads		<b>85062</b>
<b>A6 (4B2, C5) 2.4 quattro</b>		<b>2001-05</b>
BDV		125 170
Ignition Leads		<b>85062</b>
<b>A6 (4B2, C5) 2.4 quattro</b>		<b>1997-05</b>
APZ/AJG		120 163
Ignition Leads		<b>85062</b>
Ignition Leads		<b>85878</b>
<b>A6 (4B2, C5) 2.4 quattro</b>		<b>1998-99</b>
APC		115 156
Ignition Leads		<b>85062</b>
<b>A6 (4B2, C5) 2.4 quattro</b>		<b>1997-05</b>
AML/ARJ/ALF/AGA/APS		121 165
Ignition Leads		<b>85062</b>
Ignition Leads		<b>85878</b>
<b>A6 (4B2, C5) 2.7 T</b>		<b>1999-05</b>
AJK		169 230
Ignition Coil ->08.2000		<b>80252</b>
<b>A6 (4B2, C5) 2.7 T quattro</b>		<b>2001-05</b>
BES/ARE		184 250
Ignition Coil BES; 07.2002-05.2004		<b>80202</b>
Ignition Coil ARE; ->06.2002		<b>80252</b>
<b>A6 (4B2, C5) 2.7 T quattro</b>		<b>1997-05</b>
AJK/AZA		169 230
Ignition Coil AJK; 02.1999-08.2000		<b>80252</b>
<b>A6 (4B2, C5) 2.8</b>		<b>1997-00</b>
AGE		132 180
Ignition Leads		<b>85062</b>
<b>A6 (4B2, C5) 2.8</b>		<b>1999-05</b>
BBG/ATX		140 190
Ignition Leads		<b>85062</b>
<b>A6 (4B2, C5) 2.8</b>		<b>1997-05</b>
APR/ACK/ALG/AHA/AQD/AMX		142 193
Ignition Leads		<b>85062</b>
<b>A6 (4B2, C5) 2.8 quattro</b>		<b>1999-01</b>
ATX		140 190
Ignition Leads		<b>85062</b>
<b>A6 (4B2, C5) 2.8 quattro</b>		<b>1997-05</b>
APR/ACK/ALG/AHA/AQD/AMX		142 193
Ignition Leads		<b>85062</b>
<b>A6 (4B2, C5) 3.7</b>		<b>1999-05</b>
AQG		191 260
Ignition Coil AQG		<b>80239</b>
<b>A6 (4B2, C5) 3.7 quattro</b>		<b>1999-05</b>
AQG		191 260
Ignition Coil AQG		<b>80239</b>
<b>A6 (4B2, C5) 4.2 quattro</b>		<b>1998-05</b>
AWN/ARS/ASG		220 299
Ignition Coil ARS,ASG,AWN		<b>80239</b>
<b>A6 (4B2, C5) RS6 quattro</b>		<b>2002-05</b>
BCY		331 450
Ignition Coil		<b>80239</b>
<b>A6 (4B2, C5) S6 quattro</b>		<b>1999-05</b>
AQJ/ANK		250 340
Ignition Coil		<b>80239</b>
<b>A6 (4F2, C6) 2.0 TFSI</b>		<b>2005-11</b>
BPJ/BYK		125 170
Ignition Coil BYK,BPJ		<b>80240</b>
<b>A6 (4F2, C6) 2.4</b>		<b>2004-08</b>
BDW		130 177
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 2.4 quattro</b>		<b>2005-08</b>
BDW		130 177
Ignition Coil		<b>80248</b>

AUDI Cont.		
<b>A6 (4F2, C6) 2.8 FSI</b>		<b>2006-08</b>
BDX		154 210
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 2.8 FSI</b>		<b>2008-11</b>
CCDA		140 190
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 2.8 FSI</b>		<b>2008-11</b>
CCEA		162 220
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 2.8 FSI quattro</b>		<b>2007-08</b>
BDX		154 210
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 2.8 FSI quattro</b>		<b>2008-11</b>
CCDA		140 190
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 2.8 FSI quattro</b>		<b>2008-11</b>
CCEA		162 220
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 3.0 TFSI quattro</b>		<b>2008-11</b>
CCAA		220 299
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 3.0 TFSI quattro</b>		<b>2008-11</b>
CAJA		213 290
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 3.2 FSI</b>		<b>2009-11</b>
CALA		195 265
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 3.2 FSI</b>		<b>2004-09</b>
AUK/BKH		188 255
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 3.2 FSI quattro</b>		<b>2004-08</b>
AUK/BKH		188 255
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) 4.2 FSI quattro</b>		<b>2006-11</b>
BVJ		257 350
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) RS6 quattro</b>		<b>2008-10</b>
BUH		426 580
Ignition Coil		<b>80248</b>
<b>A6 (4F2, C6) S6 quattro</b>		<b>2006-11</b>
BXA		320 435
Ignition Coil		<b>80248</b>
<b>A6 (4G2, C7, 4Gc) 2.0 TFSI</b>		<b>2011-&gt;</b>
CDNB		132 180
Ignition Coil		<b>80240</b>
<b>A6 (4G2, C7, 4Gc) 2.8 FSI</b>		<b>2011-&gt;</b>
CHVA		150 204
Ignition Coil		<b>80248</b>
<b>A6 (4G2, C7, 4Gc) 2.8 FSI quattro</b>		<b>2011-&gt;</b>
CHVA		150 204
Ignition Coil		<b>80248</b>
<b>A6 (4G2, C7, 4Gc) 3.0 TFSI quattro</b>		<b>2014-&gt;</b>
CREC		245 333
Ignition Coil		<b>80248</b>
<b>A6 (4G2, C7, 4Gc) 3.0 TFSI quattro</b>		<b>2011-&gt;</b>
CGWD/CGXB/CTUA		228 310
Ignition Coil		<b>80248</b>
<b>A6 (4G2, C7, 4Gc) 3.0 TFSI quattro</b>		<b>2010-12</b>
CGWB		220 300
Ignition Coil		<b>80248</b>
<b>A6 4WD (4FH, C6) 3.0 TFSI quattro</b>		<b>2008-11</b>
CAJA		213 290
Ignition Coil		<b>80248</b>
<b>A6 4WD (4FH, C6) 3.2 FSI quattro</b>		<b>2006-08</b>
AUK		188 255
Ignition Coil		<b>80248</b>
<b>A6 4WD (4FH, C6) 4.2 FSI quattro</b>		<b>2006-10</b>
BVJ		257 350
Ignition Coil		<b>80248</b>
<b>A6 4WD (4GH, 4GJ) 3.0 TFSI quattro</b>		<b>2012-&gt;</b>
CGWD		228 310
Ignition Coil		<b>80248</b>
<b>A6 Allroad (4GH, 4GJ) 3.0 TFSI quattro</b>		<b>2014-&gt;</b>
CREC		245 333
Ignition Coil		<b>80248</b>
<b>A6 Avant (4A, C4) 1.8</b>		<b>1995-97</b>
ADR		92 125
Ignition Leads		<b>85682</b>





AUDI Cont.	
<b>A6 Avant (4A, C4) 1.8 quattro</b>	<b>1995-97</b>
ADR	92 125
Ignition Leads	<b>85682</b>
<b>A6 Avant (4A, C4) 2.0</b>	<b>1994-97</b>
AAE	74 100
Ignition Leads	<b>85690</b>
<b>A6 Avant (4A, C4) 2.0</b>	<b>1994-97</b>
ABK	85 115
Ignition Leads	<b>85690</b>
<b>A6 Avant (4A, C4) 2.6</b>	<b>1994-97</b>
ABC	110 150
Ignition Leads	<b>85878</b>
<b>A6 Avant (4A, C4) 2.6</b>	<b>1994-97</b>
ACZ	102 139
Ignition Leads	<b>85878</b>
<b>A6 Avant (4A, C4) 2.6 quattro</b>	<b>1994-97</b>
ABC	110 150
Ignition Leads	<b>85878</b>
<b>A6 Avant (4A, C4) 2.8</b>	<b>1994-97</b>
AEJ/AAH	128 174
Ignition Leads	<b>85878</b>
<b>A6 Avant (4A, C4) 2.8</b>	<b>1995-97</b>
ACK	142 193
Ignition Leads ACK	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A6 Avant (4A, C4) 2.8 quattro</b>	<b>1994-97</b>
AEJ/AAH	128 174
Ignition Leads	<b>85878</b>
<b>A6 Avant (4A, C4) 2.8 quattro</b>	<b>1995-97</b>
ACK	142 193
Ignition Leads ACK	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A6 Avant (4A, C4) S6 Plus quattro</b>	<b>1996-97</b>
AHK	240 326
Ignition Coil AHK	<b>80252</b>
<b>A6 Avant (4B5, C5) 1.8</b>	<b>1998-05</b>
AFY	85 116
Ignition Leads	<b>85682</b>
<b>A6 Avant (4B5, C5) 1.8</b>	<b>1997-05</b>
ARH/AJP/AQE	92 125
Ignition Coil AQE,ARH,AJP	<b>80239</b>
<b>A6 Avant (4B5, C5) 1.8 T</b>	<b>1999-05</b>
AJL	132 180
Ignition Coil AJL	<b>80252</b>
<b>A6 Avant (4B5, C5) 1.8 T</b>	<b>1997-05</b>
ARK/AEB/ANB/APU/AWT	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil AEB,APU,ANB,ARK,AWT	<b>80252</b>
<b>A6 Avant (4B5, C5) 1.8 T quattro</b>	<b>1997-05</b>
AJL	132 180
Ignition Coil AJL	<b>80252</b>
<b>A6 Avant (4B5, C5) 1.8 T quattro</b>	<b>1997-05</b>
ARK/AEB/ANB/APU/AWT	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil APU,ANB,AWT,AEB,ARK	<b>80252</b>
<b>A6 Avant (4B5, C5) 2.0</b>	<b>2001-05</b>
ALT	96 130
Ignition Coil	<b>80202</b>
Ignition Leads	<b>85062</b>
<b>A6 Avant (4B5, C5) 2.4</b>	<b>1998-05</b>
ARN/ASM/ALW	100 136
Ignition Leads	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A6 Avant (4B5, C5) 2.4</b>	<b>1997-05</b>
APC	115 156
Ignition Leads ->04.2001	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A6 Avant (4B5, C5) 2.4</b>	<b>2001-05</b>
BDV	125 170
Ignition Leads	<b>85062</b>
<b>A6 Avant (4B5, C5) 2.4</b>	<b>1997-05</b>
AMM/APZ/AJG	120 163
Ignition Leads	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A6 Avant (4B5, C5) 2.4</b>	<b>1997-05</b>
AML/ARJ/ALF/AGA/APS	121 165
Ignition Leads ->04.2001	<b>85062</b>

AUDI Cont.	
<b>A6 Avant (4B5, C5) 2.4 quattro</b>	<b>2001-05</b>
BDV	125 170
Ignition Leads	<b>85062</b>
<b>A6 Avant (4B5, C5) 2.4 quattro</b>	<b>1997-05</b>
APZ/AJG	120 163
Ignition Leads ->05.2001	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A6 Avant (4B5, C5) 2.4 quattro</b>	<b>1998-01</b>
APC	115 156
Ignition Leads	<b>85062</b>
<b>A6 Avant (4B5, C5) 2.4 quattro</b>	<b>1997-05</b>
AML/ARJ/ALF/AGA/APS	121 165
Ignition Leads ->05.2001	<b>85062</b>
Ignition Leads	<b>85878</b>
<b>A6 Avant (4B5, C5) 2.7 T</b>	<b>1999-05</b>
AJK	169 230
Ignition Coil AJK	<b>80252</b>
<b>A6 Avant (4B5, C5) 2.7 T quattro</b>	<b>2001-05</b>
BES/ARE	184 250
Ignition Coil BES; 07.2002->	<b>80202</b>
Ignition Coil ARE; ->06.2002	<b>80252</b>
<b>A6 Avant (4B5, C5) 2.7 T quattro</b>	<b>1997-05</b>
AJK/AZA	169 230
Ignition Coil 02.1999-05.2001	<b>80252</b>
<b>A6 Avant (4B5, C5) 2.8</b>	<b>1997-00</b>
AGE	132 180
Ignition Leads	<b>85062</b>
<b>A6 Avant (4B5, C5) 2.8</b>	<b>1999-05</b>
ATX	140 190
Ignition Leads ->04.2001	<b>85062</b>
<b>A6 Avant (4B5, C5) 2.8</b>	<b>1997-05</b>
APR/ACK/ALG/AHA/AQD/AMX	142 193
Ignition Leads 02.1998-04.2001	<b>85062</b>
<b>A6 Avant (4B5, C5) 2.8 quattro</b>	<b>1997-05</b>
APR/ACK/ALG/AHA/AQD/AMX	142 193
Ignition Leads	<b>85062</b>
<b>A6 Avant (4B5, C5) 3.7</b>	<b>1999-05</b>
AQG	191 260
Ignition Coil AQG	<b>80239</b>
<b>A6 Avant (4B5, C5) 3.7 quattro</b>	<b>1999-05</b>
AQG	191 260
Ignition Coil AQG	<b>80239</b>
<b>A6 Avant (4B5, C5) 4.2 quattro</b>	<b>1998-05</b>
AWN/ARS/ASG	220 299
Ignition Coil	<b>80239</b>
<b>A6 Avant (4B5, C5) RS6 plus quattro</b>	<b>2004-05</b>
BRV	353 480
Ignition Coil	<b>80239</b>
<b>A6 Avant (4B5, C5) RS6 quattro</b>	<b>2002-05</b>
BCY	331 450
Ignition Coil	<b>80239</b>
<b>A6 Avant (4B5, C5) S6 quattro</b>	<b>1999-05</b>
AQJ/ANK	250 340
Ignition Coil	<b>80239</b>
<b>A6 Avant (4F5, C6) 2.0 TFSI</b>	<b>2005-11</b>
BPJ	125 170
Ignition Coil BPJ	<b>80240</b>
<b>A6 Avant (4F5, C6) 2.4</b>	<b>2005-08</b>
BDW	130 177
Ignition Coil	<b>80240</b>
Ignition Coil Ch.4F-5-000 001-4F-6-050 000	<b>80248</b>
<b>A6 Avant (4F5, C6) 2.4 quattro</b>	<b>2005-08</b>
BDW	130 177
Ignition Coil	<b>80240</b>
Ignition Coil ->Ch.4F-6-050 000	<b>80248</b>
<b>A6 Avant (4F5, C6) 2.8 FSI</b>	<b>2006-08</b>
BDX	154 210
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) 2.8 FSI</b>	<b>2008-11</b>
CCDA	140 190
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) 2.8 FSI</b>	<b>2008-11</b>
CCEA	162 220
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) 2.8 FSI quattro</b>	<b>2007-08</b>
BDX	154 210
Ignition Coil	<b>80248</b>





AUDI Cont.	
<b>A6 Avant (4F5, C6) 2.8 FSI quattro</b>	<b>2008-11</b>
CCDA	140 190
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) 2.8 FSI quattro</b>	<b>2008-11</b>
CCEA	162 220
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) 3.0 TFSI quattro</b>	<b>2008-11</b>
CCAA	220 299
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) 3.0 TFSI quattro</b>	<b>2008-11</b>
CAJA	213 290
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) 3.2 FSI</b>	<b>2005-08</b>
AUK	188 255
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) 3.2 FSI quattro</b>	<b>2005-08</b>
AUK	188 255
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) 4.2 FSI quattro</b>	<b>2006-11</b>
BVJ	257 350
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) RS6 quattro</b>	<b>2008-10</b>
BUH	426 580
Ignition Coil	<b>80248</b>
<b>A6 Avant (4F5, C6) S6 quattro</b>	<b>2006-11</b>
BXA	320 435
Ignition Coil	<b>80248</b>
<b>A6 Avant (4G5, C7, 4GD) 2.8 FSI</b>	<b>2011-&gt;</b>
CHVA	150 204
Ignition Coil	<b>80248</b>
<b>A6 Avant (4G5, C7, 4GD) 2.8 FSI quattro</b>	<b>2011-&gt;</b>
CHVA	150 204
Ignition Coil	<b>80248</b>
<b>A6 Avant (4G5, C7, 4GD) 3.0 TFSI quattro</b>	<b>2011-12</b>
CGWB	220 300
Ignition Coil	<b>80248</b>
<b>A6 Avant (4G5, C7, 4GD) 3.0 TFSI quattro</b>	<b>2014-&gt;</b>
CREC	245 333
Ignition Coil	<b>80248</b>
<b>A6 Avant (4G5, C7, 4GD) 3.0 TFSI quattro</b>	<b>2011-&gt;</b>
CGWD	228 310
Ignition Coil	<b>80248</b>
<b>A7 Sportback (4GA, 4GF) 2.8 FSI</b>	<b>2011-&gt;</b>
CHVA	150 204
Ignition Coil	<b>80248</b>
<b>A7 Sportback (4GA, 4GF) 2.8 FSI quattro</b>	<b>2010-&gt;</b>
CHVA/CNYA	150 204
Ignition Coil	<b>80248</b>
<b>A7 Sportback (4GA, 4GF) 3.0 TFSI quattro</b>	<b>2014-&gt;</b>
CREC	245 333
Ignition Coil	<b>80248</b>
<b>A7 Sportback (4GA, 4GF) 3.0 TFSI quattro</b>	<b>2010-&gt;</b>
CGWB/CHMA	220 300
Ignition Coil	<b>80248</b>
<b>A7 Sportback (4GA, 4GF) 3.0 TFSI quattro</b>	<b>2011-&gt;</b>
CTTA/CGWD/CGXB/CTUA	228 310
Ignition Coil	<b>80248</b>
<b>A8 (4D2, 4D8) 2.8</b>	<b>1994-96</b>
AAH	128 174
Ignition Leads	<b>85878</b>
<b>A8 (4D2, 4D8) 2.8</b>	<b>1996-02</b>
APR/ACK/ALG/AQD/AMX	142 193
Ignition Leads	<b>85062</b>
<b>A8 (4D2, 4D8) 2.8</b>	<b>1995-96</b>
AEJ	120 163
Ignition Leads	<b>85878</b>
<b>A8 (4D2, 4D8) 2.8 quattro</b>	<b>1994-96</b>
AAH	128 174
Ignition Leads	<b>85878</b>
<b>A8 (4D2, 4D8) 2.8 quattro</b>	<b>1995-96</b>
AEJ	120 163
Ignition Leads	<b>85878</b>
<b>A8 (4D2, 4D8) 3.7</b>	<b>1998-02</b>
AKC/AQG	191 260
Ignition Coil AKC,AQG	<b>80239</b>
<b>A8 (4D2, 4D8) 3.7</b>	<b>1995-98</b>
AEW	169 230
Ignition Coil	<b>80252</b>

AUDI Cont.	
<b>A8 (4D2, 4D8) 3.7 quattro</b>	<b>1998-02</b>
AKC/AQG	191 260
Ignition Coil	<b>80239</b>
<b>A8 (4D2, 4D8) 3.7 quattro</b>	<b>1995-98</b>
AKJ/AEW	169 230
Ignition Coil	<b>80252</b>
<b>A8 (4D2, 4D8) 4.2 quattro</b>	<b>1998-02</b>
AUW/AQF/AUX	228 310
Ignition Coil	<b>80239</b>
<b>A8 (4D2, 4D8) 4.2 quattro</b>	<b>1999-00</b>
ARU	175 238
Ignition Coil	<b>80239</b>
<b>A8 (4D2, 4D8) 4.2 quattro</b>	<b>1994-98</b>
AKG/ABZ	220 299
Ignition Coil Ch.4D-T-000 221->	<b>80252</b>
<b>A8 (4D2, 4D8) 4.2 quattro</b>	<b>1994-96</b>
AEM	180 245
Ignition Coil Ch.4D-T-000 221->	<b>80252</b>
<b>A8 (4D2, 4D8) S 8 quattro</b>	<b>1999-02</b>
AQH/AVP	265 360
Ignition Coil	<b>80239</b>
<b>A8 (4D2, 4D8) S 8 quattro</b>	<b>1996-99</b>
AHC/AKH	250 340
Ignition Coil AKH,AHC	<b>80252</b>
<b>A8 (4E) 2.8 FSI</b>	<b>2007-10</b>
BDX	154 210
Ignition Coil	<b>80248</b>
<b>A8 (4E) 3.2 FSI</b>	<b>2005-10</b>
BPK	191 260
Ignition Coil	<b>80248</b>
<b>A8 (4E) 3.2 FSI quattro</b>	<b>2005-10</b>
BPK	191 260
Ignition Coil	<b>80248</b>
<b>A8 (4E) 4.2 FSI quattro</b>	<b>2006-10</b>
BVJ	257 350
Ignition Coil	<b>80248</b>
<b>A8 (4E) S8 quattro</b>	<b>2006-10</b>
BSM	331 450
Ignition Coil	<b>80248</b>
<b>A8 (4H) 2.5 TFSI</b>	<b>2012-&gt;</b>
CPAA/CVBA	150 204
Ignition Coil	<b>80248</b>
<b>A8 (4H) 3.0 TFSI quattro</b>	<b>2011-&gt;</b>
CGWD/CREA	228 310
Ignition Coil	<b>80248</b>
<b>A8 (4H) 3.0 TFSI quattro</b>	<b>2010-&gt;</b>
CGWA/CREG/CGXA	213 290
Ignition Coil	<b>80248</b>
<b>A8 (4H) 3.0 TFSI quattro</b>	<b>2010-&gt;</b>
CTDA/CMDA/CTUB/CGXC/CREC	245 333
Ignition Coil	<b>80248</b>
<b>A8 (4H) 4.2 FSI quattro</b>	<b>2009-&gt;</b>
CDRA	273 371
Ignition Coil	<b>80248</b>
<b>Allroad (4BH, C5) 2.7 T quattro</b>	<b>2000-05</b>
BES/ARE	184 250
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil BES,ARE	<b>80252</b>
<b>Cabriolet (8G7, B4) 1.8</b>	<b>1997-00</b>
ADR	92 125
Ignition Leads	<b>85682</b>
<b>Cabriolet (8G7, B4) 2.0 E</b>	<b>1993-98</b>
ABK	85 115
Ignition Coil ->Ch.8G-P-015000	<b>80200</b>
Ignition Leads M4	<b>83960</b>
<b>Cabriolet (8G7, B4) 2.3 E</b>	<b>1991-94</b>
NG	98 133
Ignition Leads	<b>83950</b>
<b>Cabriolet (8G7, B4) 2.6</b>	<b>1995-00</b>
ACZ	102 139
Ignition Leads	<b>85878</b>
<b>Cabriolet (8G7, B4) 2.6</b>	<b>1993-00</b>
ABC	110 150
Ignition Leads	<b>85878</b>
<b>Cabriolet (8G7, B4) 2.8</b>	<b>1992-00</b>
AAH	128 174
Ignition Leads	<b>85878</b>



AUDI Cont.	
Coupe (81, 85) 1.6	1980-81
YN	55 75
Ignition Leads	<b>83660</b>
Coupe (81, 85) 1.8	1981-83
DD	55 75
Ignition Leads	<b>83660</b>
Coupe (81, 85) 1.8 GT	1986-88
SF	65 88
Ignition Leads	<b>83960</b>
Coupe (81, 85) 1.8 GT	1982-88
DS/JV	66 90
Ignition Leads ->07.1984	<b>83660</b>
Ignition Leads	<b>83960</b>
Coupe (81, 85) 1.8 GT	1986-87
PV	79 107
Ignition Leads	<b>83960</b>
Coupe (81, 85) 1.8 GT	1986-88
DZ	82 112
Ignition Leads	<b>83960</b>
Coupe (81, 85) 1.8 GT	1985-88
JN	68 93
Ignition Leads	<b>83960</b>
Coupe (81, 85) 1.8 GT quattro	1984-88
DZ	82 112
Ignition Leads	<b>83960</b>
Coupe (81, 85) 2.0	1986-88
SK	83 113
Ignition Leads M4	<b>83950</b>
Ignition Leads	<b>83960</b>
Coupe (81, 85) 2.0	1983-86
JS/HP	85 115
Ignition Leads M4	<b>83950</b>
Ignition Leads	<b>83960</b>
Coupe (81, 85) 2.2 GT	1981-87
KX	85 115
Ignition Leads	<b>83950</b>
Coupe (81, 85) 2.2 GT	1984-88
KV/HY	100 136
Ignition Leads	<b>83950</b>
Coupe (81, 85) 2.2 quattro	1984-88
KV	100 136
Ignition Leads	<b>83950</b>
Coupe (81, 85) 2.2 quattro	1985-88
JT	88 120
Ignition Leads	<b>83950</b>
Coupe (81, 85) 2.3	1987-88
NG	100 136
Ignition Leads	<b>83950</b>
Ignition Leads NG	<b>85680</b>
Coupe (81, 85) 2.3 quattro	1987-88
NG	100 136
Ignition Leads	<b>83950</b>
Ignition Leads NG	<b>85680</b>
Coupe (89, 8B) 2.0	1989-96
ABK/AAD	85 115
Ignition Coil ->Ch.8B-P-015000	<b>80200</b>
Ignition Leads M4; With ignition distributor	<b>83960</b>
Coupe (89, 8B) 2.0	1990-90
3A	82 112
Ignition Leads	<b>83960</b>
Coupe (89, 8B) 2.0	1989-90
3A	83 113
Ignition Leads M4	<b>83960</b>
Coupe (89, 8B) 2.0 20 V	1989-91
NM	118 160
Ignition Leads	<b>85680</b>
Coupe (89, 8B) 2.2 quattro	1988-91
KV	100 136
Ignition Leads	<b>83950</b>
Coupe (89, 8B) 2.3	1988-94
NG	100 136
Ignition Leads	<b>83950</b>
Ignition Leads	<b>85680</b>
Coupe (89, 8B) 2.3	1990-96
NG	98 133
Ignition Leads NG (KAT)	<b>85680</b>
Coupe (89, 8B) 2.3 20V	1990-91
7A	123 167
Ignition Leads	<b>85680</b>

AUDI Cont.	
Coupe (89, 8B) 2.3 20V	1989-91
7A	125 170
Ignition Leads	<b>85680</b>
Coupe (89, 8B) 2.3 20V quattro	1988-91
7A	125 170
Ignition Leads	<b>85680</b>
Coupe (89, 8B) 2.3 20V quattro	1990-96
7A	123 167
Ignition Leads	<b>85680</b>
Coupe (89, 8B) 2.3 quattro	1988-92
NG	100 136
Ignition Leads NG (KAT)	<b>85680</b>
Coupe (89, 8B) 2.3 quattro	1990-96
NG	98 134
Ignition Leads	<b>83950</b>
Ignition Leads NG (KAT)	<b>85680</b>
Coupe (89, 8B) 2.6	1992-96
ABC	110 150
Ignition Leads	<b>85878</b>
Coupe (89, 8B) 2.6 quattro	1992-96
ABC	110 150
Ignition Leads	<b>85878</b>
Coupe (89, 8B) 2.8	1991-96
AAH	128 174
Ignition Leads	<b>85878</b>
Coupe (89, 8B) 2.8 quattro	1991-96
AAH	128 174
Ignition Leads	<b>85878</b>
Q2 (GA) 1.0 TFSI	2016->
CHZJ	85 115
Ignition Coil	<b>80249</b>
Q2 (GA) 1.4 TFSI	2016->
CZEA	110 150
Ignition Coil	<b>80249</b>
Q3 (8U) 1.4 TFSI	2013->
CZEA/CHPB/CZDA	110 150
Ignition Coil	<b>80249</b>
Q3 (8U) 1.4 TFSI	2016->
CZDB	92 125
Ignition Coil	<b>80249</b>
Q5 (8R) 2.0 TFSI quattro	2008->
CAEB/CPMA/CDNC	155 211
Ignition Coil	<b>80240</b>
Q5 (8R) 2.0 TFSI quattro	2009->
CDNB/CNCB	132 180
Ignition Coil	<b>80240</b>
Q5 (8R) 2.0 TFSI quattro	2012->
CNCD	165 224
Ignition Coil	<b>80238</b>
Q5 (8R) 3.0 TFSI quattro	2012->
CTVA/CTUC	200 272
Ignition Coil	<b>80248</b>
Q5 (8R) 3.2 FSI quattro	2008->
CALB	199 270
Ignition Coil	<b>80240</b>
Ignition Coil	<b>80248</b>
Q5 (8R) SQ5 TFSI quattro	2013->
CTUD/CTXA	260 354
Ignition Coil	<b>80248</b>
Q7 (4L) 3.0 TFSI	2011->
CTWB/CJWE	206 280
Ignition Coil	<b>80248</b>
Q7 (4L) 3.0 TFSI	2010-15
CJWC/CJTC	200 272
Ignition Coil	<b>80248</b>
Q7 (4L) 3.0 TFSI	2010-15
CJTB/CTWA/CNA/CJWB	245 333
Ignition Coil	<b>80248</b>
Q7 (4L) 3.6 FSI	2006-10
BHK	206 280
Ignition Coil	<b>80327</b>
Q7 (4L) 4.2 FSI	2006-10
BAR	257 350
Ignition Coil	<b>80248</b>
Q7 (4M) 3.0 TFSI quattro	2015->
CREC	245 333
Ignition Coil	<b>80248</b>



AUDI Cont.		
<b>R8 (422, 423) 5.2 FSI quattro</b>	2014-15	
CTPB	419	570
Ignition Coil	<b>80248</b>	
<b>R8 4.2 FSI quattro</b>	2007-10	
BYH	309	420
Ignition Coil	<b>80248</b>	
<b>R8 4.2 FSI quattro</b>	2010-15	
CNDA	316	430
Ignition Coil	<b>80248</b>	
<b>R8 5.2 FSI quattro</b>	2012->	
CTPA	404	549
Ignition Coil	<b>80248</b>	
<b>R8 5.2 FSI quattro</b>	2009-15	
BUJ/CTYA	386	525
Ignition Coil	<b>80248</b>	
<b>R8 Spyder 4.2 FSI quattro</b>	2010-15	
CNDA	316	430
Ignition Coil	<b>80248</b>	
<b>R8 Spyder 5.2 FSI quattro</b>	2010-15	
BUJ/CTYA	386	525
Ignition Coil	<b>80248</b>	
<b>TT (8J3) 1.8 TFSI</b>	2008-14	
CDA A	118	160
Ignition Coil	<b>80240</b>	
<b>TT (8J3) 2.0 TFSI</b>	2006-10	
BWA/BPY/CCTA	147	200
Ignition Coil BWA	<b>80240</b>	
<b>TT (8J3) 2.0 TFSI</b>	2010-14	
CESA	155	211
Ignition Coil	<b>80240</b>	
<b>TT (8J3) 2.0 TFSI quattro</b>	2008-10	
BWA/CCZA	147	200
Ignition Coil	<b>80240</b>	
<b>TT (8J3) 2.0 TFSI quattro</b>	2010-14	
CETA/CESA	155	211
Ignition Coil	<b>80240</b>	
<b>TT (8J3) 2.0 TTS quattro</b>	2008-14	
CDLB	200	272
Ignition Coil	<b>80240</b>	
<b>TT (8J3) 2.0 TTS quattro</b>	2008-14	
CDMA/CDLA	195	265
Ignition Coil	<b>80240</b>	
<b>TT (8J3) 3.2 V6 quattro</b>	2006-10	
BUB	184	250
Ignition Coil	<b>80327</b>	
<b>TT (8N3) 1.8 T</b>	2002-06	
AUM	110	150
Ignition Coil Ch.8N-1-010001->; 01.2003->	<b>80202</b>	
Ignition Coil ->Ch.8N-1-010000	<b>80239</b>	
<b>TT (8N3) 1.8 T</b>	2005-06	
BVP	120	163
Ignition Coil	<b>80202</b>	
<b>TT (8N3) 1.8 T</b>	2005-06	
BVR	140	190
Ignition Coil	<b>80202</b>	
<b>TT (8N3) 1.8 T</b>	1998-06	
AJQ/APP/AUQ/ATC	132	180
Ignition Coil AUQ; With regul.cat.(3way)	<b>80202</b>	
Ignition Coil APP,AUQ	<b>80239</b>	
<b>TT (8N3) 1.8 T quattro</b>	2005-06	
BFV	176	240
Ignition Coil	<b>80202</b>	
<b>TT (8N3) 1.8 T quattro</b>	2005-06	
BVR	140	190
Ignition Coil	<b>80202</b>	
<b>TT (8N3) 1.8 T quattro</b>	1998-06	
AJQ/ARY/AUQ	132	180
Ignition Coil With regul.cat.(3way)	<b>80202</b>	
Ignition Coil ATC,AWP,ARY,AJQ	<b>80239</b>	
<b>TT (8N3) 1.8 T quattro</b>	1998-06	
BAM/APX	165	224
Ignition Coil BAM; Ch.8N-1-010001->; 01.2003->	<b>80202</b>	
Ignition Coil BAM; 09.2000->	<b>80239</b>	
Ignition Coil APX; Ch.8N-1-010001->; 09.2000-08.2001	<b>80239</b>	
<b>TT (8N3) 3.2 VR6 quattro</b>	2003-06	
BPF/BHE	184	250
Ignition Coil	<b>80327</b>	

AUDI Cont.		
<b>TT Roadster (8J9) 1.8 TFSI</b>	2008-14	
CDA A	118	160
Ignition Coil	<b>80240</b>	
<b>TT Roadster (8J9) 2.0 TFSI</b>	2007-10	
BWA/BPY/CCTA	147	200
Ignition Coil BWA	<b>80240</b>	
<b>TT Roadster (8J9) 2.0 TFSI</b>	2010-14	
CESA	155	211
Ignition Coil	<b>80240</b>	
<b>TT Roadster (8J9) 2.0 TFSI quattro</b>	2008-10	
CCZA	147	200
Ignition Coil	<b>80240</b>	
<b>TT Roadster (8J9) 2.0 TFSI quattro</b>	2010-14	
CETA/CESA	155	211
Ignition Coil	<b>80240</b>	
<b>TT Roadster (8J9) 2.0 TTS quattro</b>	2008-14	
CDLB	200	272
Ignition Coil	<b>80240</b>	
<b>TT Roadster (8J9) 2.0 TTS quattro</b>	2008-14	
CDMA/CDLA	195	265
Ignition Coil	<b>80240</b>	
<b>TT Roadster (8J9) 3.2 V6 quattro</b>	2007-10	
BUB	184	250
Ignition Coil	<b>80327</b>	
<b>TT Roadster (8N9) 1.8 T</b>	1999-06	
AJQ/APP/AUQ/ATC	132	180
Ignition Coil With regul.cat.(3way)	<b>80202</b>	
Ignition Coil	<b>80239</b>	
<b>TT Roadster (8N9) 1.8 T</b>	2001-06	
AUM	110	150
Ignition Coil With regul.cat.(3way)	<b>80202</b>	
<b>TT Roadster (8N9) 1.8 T</b>	2005-06	
BVR	140	190
Ignition Coil	<b>80202</b>	
<b>TT Roadster (8N9) 1.8 T</b>	2005-06	
BVP	120	163
Ignition Coil	<b>80202</b>	
<b>TT Roadster (8N9) 1.8 T quattro</b>	2000-06	
AJQ/ARY/AUQ	132	180
Ignition Coil 09.2000-05.2005	<b>80202</b>	
Ignition Coil AJQ	<b>80239</b>	
Ignition Coil AJQ; SAE	<b>80252</b>	
<b>TT Roadster (8N9) 1.8 T quattro</b>	1999-06	
BAM/APX	165	224
Ignition Coil With regul.cat.(3way)	<b>80202</b>	
<b>TT Roadster (8N9) 1.8 T quattro</b>	2005-06	
BVR	140	190
Ignition Coil	<b>80202</b>	
<b>TT Roadster (8N9) 3.2 VR6 quattro</b>	2003-06	
BPF/BHE	184	250
Ignition Coil	<b>80327</b>	

AUSTIN		
<b>Allegro Hatchback (Ado 67) 1.1</b>	1973-81	
10 H	33	45
Ignition Leads	<b>83850</b>	
<b>Allegro Hatchback (Ado 67) 1.3</b>	1973-82	
12 H	40	54
Ignition Leads	<b>83850</b>	
<b>Allegro Hatchback (Ado 67) 1.5 Super</b>	1973-82	
14 H	50	68
Ignition Leads	<b>83850</b>	
<b>Maestro (Xc) 1.3</b>	1983-85	
12 H999AA/12 HC32/12 H	46	63
Ignition Leads	<b>83850</b>	
<b>Maestro (Xc) 1.3 LS</b>	1983-90	
12 H	49	67
Ignition Leads ->12.1984	<b>83850</b>	
<b>Maestro (Xc) 1.6</b>	1983-84	
16 H956AK	59	80
Ignition Leads	<b>83850</b>	
<b>Maestro (Xc) 1.6 Mayfair HLS</b>	1983-90	
16 HC37	61	83
Ignition Leads ->12.1984	<b>83850</b>	
<b>Maestro (Xc) 1.6 MG</b>	1983-85	
16 HA03AL	72	98
Ignition Leads	<b>83850</b>	



<b>AUSTIN Cont.</b>		
<b>Maestro (Xc) 1.6 MG</b>	<b>1983-90</b>	
16 HA35AL	73 99	
Ignition Leads ->12.1984	<b>83850</b>	
<b>Maxi 1500</b>	<b>1969-80</b>	
14 H	50 68	
Ignition Leads	<b>83850</b>	
<b>Maxi 1750</b>	<b>1969-80</b>	
17 H	53 72	
Ignition Leads	<b>83850</b>	
<b>Maxi 1750 HL</b>	<b>1972-80</b>	
17 LA	66 90	
Ignition Leads	<b>83850</b>	
<b>Metro 1.0</b>	<b>1980-90</b>	
99 H	30 41	
Ignition Leads	<b>83850</b>	
<b>Metro 1.0</b>	<b>1980-90</b>	
99 H	33 45	
Ignition Leads	<b>83850</b>	
<b>Metro 1.0 Surf HLE</b>	<b>1980-90</b>	
99 HA65P	35 48	
Ignition Leads	<b>83850</b>	
<b>Metro 1.3</b>	<b>1980-90</b>	
12 HA83AA	51 69	
Ignition Leads	<b>83850</b>	
<b>Metro 1.3</b>	<b>1980-85</b>	
12 H996AA	52 71	
Ignition Leads	<b>83850</b>	
<b>Metro 1.3 L,HLE,S</b>	<b>1980-90</b>	
12 H	44 60	
Ignition Leads	<b>83850</b>	
<b>Metro 1.3 Surf</b>	<b>1985-90</b>	
12 HC21AA	44 60	
Ignition Leads	<b>83850</b>	
<b>Metro 1.3 Turbo</b>	<b>1983-90</b>	
12 HA85AA	66 90	
Ignition Leads	<b>83850</b>	
<b>Mini 1275 GT</b>	<b>1969-80</b>	
12 H	39 53	
Ignition Leads	<b>83850</b>	
<b>Mini 850</b>	<b>1967-79</b>	
BMC Serie A	25 34	
Ignition Leads	<b>83850</b>	

<b>AUTOBIANCHI</b>		
<b>Y10 1.0</b>	<b>1985-95</b>	
156A2.000	33 45	
Ignition Coil	<b>80265</b>	
<b>Y10 1.0</b>	<b>1985-95</b>	
156A.000	41 56	
Ignition Coil	<b>80265</b>	
<b>Y10 1.0 4WD</b>	<b>1986-95</b>	
156A3.000	37 50	
Ignition Coil	<b>80265</b>	
<b>Y10 1.0 KAT</b>	<b>1987-95</b>	
156A2.246	33 45	
Ignition Coil	<b>80265</b>	
<b>Y10 1.1</b>	<b>1989-95</b>	
156C.000	42 57	
Ignition Coil	<b>80265</b>	
<b>Y10 1.1 4WD</b>	<b>1989-95</b>	
156C.000	42 57	
Ignition Coil	<b>80265</b>	
<b>Y10 1.1 i.e. KAT</b>	<b>1990-95</b>	
156C.046	42 57	
Ignition Coil	<b>80265</b>	

<b>BMW</b>		
<b>1 (E81) 116 i</b>	<b>2007-11</b>	
N45 B16 A	85 115	
Ignition Coil	<b>80247</b>	
<b>1 (E81) 116 i</b>	<b>2007-11</b>	
N43 B16 AA/N43 B16 A	90 122	
Ignition Coil	<b>80281</b>	
<b>1 (E81) 116 i</b>	<b>2008-11</b>	
N43 B20 A	90 122	
Ignition Coil	<b>80281</b>	

<b>BMW Cont.</b>		
<b>1 (E81) 116 i</b>	<b>2007-11</b>	
N43 B16 AA/N43 B16 A	89 121	
Ignition Coil 09.2007->	<b>80281</b>	
<b>1 (E81) 118 i</b>	<b>2006-11</b>	
N43 B20 A	105 143	
Ignition Coil	<b>80281</b>	
<b>1 (E81) 120 i</b>	<b>2006-11</b>	
N43 B20 A	125 170	
Ignition Coil	<b>80281</b>	
<b>1 (E81) 120 i</b>	<b>2006-11</b>	
N46 B20 B/N46 B20 C	115 156	
Ignition Coil	<b>80247</b>	
<b>1 (E81) 120 i</b>	<b>2006-11</b>	
N43 B20 A	120 163	
Ignition Coil	<b>80281</b>	
<b>1 (E81) 130 i</b>	<b>2006-11</b>	
N52 B30 A/N52 B30 BF/N52 B30 B	195 265	
Ignition Coil N52 B30 A	<b>80247</b>	
<b>1 (E81) 130 i</b>	<b>2006-11</b>	
N52 B30 A/N52 B30 BF/N52 B30 B	190 258	
Ignition Coil	<b>80247</b>	
<b>1 (E87) 116 i</b>	<b>2003-11</b>	
N45 B16 A	85 115	
Ignition Coil	<b>80247</b>	
<b>1 (E87) 116 i</b>	<b>2007-11</b>	
N43 B16 A	90 122	
Ignition Coil	<b>80281</b>	
<b>1 (E87) 116 i</b>	<b>2009-11</b>	
N43 B20 A	90 122	
Ignition Coil	<b>80281</b>	
<b>1 (E87) 118 i</b>	<b>2004-07</b>	
N46 B20 B	95 129	
Ignition Coil N46 B20 B	<b>80247</b>	
Ignition Coil N43 B20 A	<b>80281</b>	
<b>1 (E87) 118 i</b>	<b>2006-11</b>	
N43 B20 A	105 143	
Ignition Coil N46 B20 B	<b>80247</b>	
Ignition Coil N43 B20 A	<b>80281</b>	
<b>1 (E87) 120 i</b>	<b>2003-11</b>	
N46 B20 B/N46 B20 CC/N46 B20 C/N46 B20 BD	110 150	
Ignition Coil N46 B20 B	<b>80247</b>	
Ignition Coil N43 B20 A	<b>80281</b>	
<b>1 (E87) 120 i</b>	<b>2003-11</b>	
N46 B20 B/N46 B20 CC/N46 B20 A/N46 B20 C/N46 B20 BD	115 156	
Ignition Coil N46B20C,N46B20B	<b>80247</b>	
<b>1 (E87) 120 i</b>	<b>2006-11</b>	
N43 B20 A	120 163	
Ignition Coil N46B20B,N46B20C	<b>80247</b>	
Ignition Coil N43 B20 A	<b>80281</b>	
<b>1 (E87) 120 i</b>	<b>2006-11</b>	
N43 B20 A	125 170	
Ignition Coil	<b>80247</b>	
Ignition Coil	<b>80281</b>	
<b>1 (E87) 130 i</b>	<b>2005-12</b>	
N52 B30 A/N52 B30 BF/N52 B30 B/N52 B30 AF	190 258	
Ignition Coil	<b>80247</b>	
<b>1 (E87) 130 i</b>	<b>2005-12</b>	
N52 B30 A/N52 B30 BF/N52 B30 B/N52 B30 AF	195 265	
Ignition Coil N52B30B,N52B30A; 04.2006->	<b>80247</b>	
<b>1 (F20) 114 i</b>	<b>2011-&gt;</b>	
N13 B16 A	75 102	
Ignition Coil	<b>80247</b>	
<b>1 (F20) 116 i</b>	<b>2010-&gt;</b>	
N13 B16 A	100 136	
Ignition Coil	<b>80247</b>	
<b>1 (F20) 118 i</b>	<b>2010-&gt;</b>	
N13 B16 A	125 170	
Ignition Coil	<b>80247</b>	
<b>1 (F21) 114 i</b>	<b>2011-&gt;</b>	
N13 B16 A	75 102	
Ignition Coil	<b>80247</b>	
<b>1 (F21) 116 i</b>	<b>2011-&gt;</b>	
N13 B16 A	100 136	
Ignition Coil	<b>80247</b>	
<b>1 (F21) 118 i</b>	<b>2012-&gt;</b>	
N13 B16 A	125 170	
Ignition Coil	<b>80247</b>	



BMW Cont.	
<b>1 Cabriolet (E88) 118 i</b>	<b>2008-13</b>
N43 B20 A	105 143
Ignition Coil	<b>80281</b>
<b>1 Cabriolet (E88) 120 i</b>	<b>2008-13</b>
N43 B20 A	125 170
Ignition Coil	<b>80281</b>
<b>1 Cabriolet (E88) 120 i</b>	<b>2008-13</b>
N43 B20 A	120 163
Ignition Coil	<b>80281</b>
<b>1 Cabriolet (E88) 120 i</b>	<b>2008-13</b>
N46 B20 B/N46 B20 E/N46 B20 C	115 156
Ignition Coil	<b>80247</b>
<b>1 Cabriolet (E88) 125 i</b>	<b>2008-13</b>
N52 B30 A	160 218
Ignition Coil	<b>80247</b>
<b>1 Cabriolet (E88) 135 i</b>	<b>2008-13</b>
N55 B30 A/N54 B30 A	225 306
Ignition Coil	<b>80247</b>
<b>1 Coupe (E82) 120 i</b>	<b>2007-13</b>
N43 B20 A	125 170
Ignition Coil	<b>80281</b>
<b>1 Coupe (E82) 125 i</b>	<b>2007-13</b>
N52 B30 A	160 218
Ignition Coil	<b>80247</b>
<b>1 Coupe (E82) 135 i</b>	<b>2007-13</b>
N55 B30 A/N54 B30 A	225 306
Ignition Coil	<b>80247</b>
<b>1 Coupe (E82) M</b>	<b>2011-12</b>
N54 B30 A	250 340
Ignition Coil	<b>80247</b>
<b>3 (E21) 315</b>	<b>1981-84</b>
M10 B16 (164VB)	55 75
Ignition Leads ->12.1983	<b>83820</b>
Ignition Leads 01.1984->	<b>85020</b>
<b>3 (E21) 318 i</b>	<b>1979-82</b>
M10 B18 (184VA)	77 105
Ignition Leads 09.1980->	<b>85020</b>
<b>3 (E21) 320/6</b>	<b>1977-82</b>
M20 B20 (206VA)	90 122
Ignition Leads	<b>85890</b>
<b>3 (E21) 323 i</b>	<b>1978-82</b>
M20 B23 (236EA)	105 143
Ignition Leads	<b>85890</b>
<b>3 (E30) 315</b>	<b>1982-91</b>
M10 B16	55 75
Ignition Leads	<b>85020</b>
<b>3 (E30) 316</b>	<b>1983-90</b>
M10 B18 (184VD)	66 90
Ignition Leads	<b>85020</b>
<b>3 (E30) 316</b>	<b>1982-87</b>
M10 B18 (184VC)	66 90
Ignition Leads	<b>85020</b>
<b>3 (E30) 316 i</b>	<b>1987-91</b>
M40 B16 (164E1)	73 100
Ignition Leads ->08.1988	<b>85020</b>
<b>3 (E30) 316 i</b>	<b>1987-88</b>
M10 B18 (184KA)	75 102
Ignition Leads	<b>85020</b>
<b>3 (E30) 318 i</b>	<b>1984-88</b>
M10 B18 (184KA)	75 102
Ignition Leads ->08.1987	<b>85020</b>
<b>3 (E30) 318 i</b>	<b>1982-87</b>
M10 B18 (184EA)	77 105
Ignition Leads	<b>85020</b>
<b>3 (E30) 318 is</b>	<b>1989-91</b>
M42 B18 (184S1)	100 136
Ignition Coil With regul.cat.(3way)	<b>80215</b>
Ignition Leads	<b>85940</b>
<b>3 (E30) 320 i</b>	<b>1985-91</b>
M20 B20 (206KA)	95 129
Ignition Leads	<b>85890</b>
<b>3 (E30) 320 i</b>	<b>1982-85</b>
M20 B20 (206EB)	92 125
Ignition Leads	<b>85890</b>
<b>3 (E30) 320 i</b>	<b>1985-90</b>
M20 B20 (206KA)	110 150
Ignition Leads	<b>85890</b>

BMW Cont.	
<b>3 (E30) 323 i</b>	<b>1982-83</b>
M20 B23 (236EC)	102 139
Ignition Leads	<b>85890</b>
<b>3 (E30) 323 i</b>	<b>1983-86</b>
M20 B23 (236EC)	110 150
Ignition Leads	<b>85890</b>
<b>3 (E36) 316 i</b>	<b>1993-98</b>
M43 B16 (164E2)	75 102
Ignition Leads 07.1994->	<b>85950</b>
<b>3 (E36) 316 i</b>	<b>1990-93</b>
M43 B16 (164E2)	75 102
Ignition Leads	<b>85950</b>
<b>3 (E36) 318 i</b>	<b>1993-98</b>
M43 B18 (184E2)	85 115
Ignition Leads 07.1994->	<b>85950</b>
Ignition Leads	<b>85955</b>
<b>3 (E36) 318 is</b>	<b>1995-98</b>
M44 B19 (194S1)	103 140
Ignition Leads	<b>85940</b>
Ignition Leads SAE	<b>85945</b>
<b>3 (E36) 318 is</b>	<b>1993-98</b>
M42 B18 (184S1)	103 140
Ignition Coil M 42 B 18; ->09.1993; With regul.cat.(3way)	<b>80215</b>
Ignition Leads ->12.1996	<b>85940</b>
Ignition Leads	<b>85945</b>
Ignition Leads 07.1994->	<b>85950</b>
<b>3 (E36) 320 i</b>	<b>1990-98</b>
M52 B20 (206S3)/M50 B20 (206S2)/M50 B20 (206S1)	110 150
Ignition Coil ->12.1995	<b>80215</b>
Ignition Coil M52 B(20 6 S3) Vanos; 09.1994->	<b>80216</b>
<b>3 (E36) 323 i 2.5</b>	<b>1995-98</b>
M52 B25 (256S3)	125 170
Ignition Coil M 52 B 25 (Vanos)	<b>80216</b>
<b>3 (E36) 325 i</b>	<b>1990-95</b>
M50 B25 (256S1)/M50 B25 (256S2)	141 192
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>3 (E36) 328 i</b>	<b>1995-98</b>
M52 B28 (286S1)	142 193
Ignition Coil M 52 B 28	<b>80216</b>
<b>3 (E36) M3 3.0</b>	<b>1994-95</b>
S50 B30 (306S1)	210 286
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>3 (E36) M3 3.2</b>	<b>1995-98</b>
S50 B32 (326S1)	236 321
Ignition Coil S 50 B 32	<b>80216</b>
<b>3 (E46) 316 i</b>	<b>1998-05</b>
M43 B19 (194E1)	77 105
Ignition Leads	<b>85955</b>
<b>3 (E46) 316 i</b>	<b>2000-05</b>
M43 B16 (164E3)	77 105
Ignition Leads	<b>85955</b>
<b>3 (E46) 316 i</b>	<b>2002-05</b>
N46 B18 A/N42 B18 A	85 115
Ignition Coil	<b>80247</b>
<b>3 (E46) 316 i</b>	<b>2002-05</b>
N45 B16 A/N40 B16 A	85 115
Ignition Coil N45 B16 A	<b>80247</b>
<b>3 (E46) 318 i</b>	<b>2001-05</b>
N46 B20 A/N42 B20 A	105 143
Ignition Coil	<b>80247</b>
<b>3 (E46) 318 i</b>	<b>1998-01</b>
M43 B19 (194E1)	87 118
Ignition Leads	<b>85955</b>
<b>3 (E46) 320 i</b>	<b>2000-05</b>
M54 B22 (226S1)	125 170
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>3 (E46) 320 i</b>	<b>1998-00</b>
M52 B20 (206S4)	110 150
Ignition Coil 04.1998->	<b>80216</b>
<b>3 (E46) 323 i</b>	<b>1998-00</b>
M52 B25 (256S4)	125 170
Ignition Coil M 52 B 25 (Vanos)	<b>80216</b>
<b>3 (E46) 325 i</b>	<b>2000-05</b>
M54 B25 (256S5)	141 192
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>





BMW Cont.		
<b>3 (E46) 325 xi</b>		<b>2000-05</b>
M54 B25 (256S5)	141 192	
Ignition Coil ->09.2002		<b>80216</b>
Ignition Coil 10.2002->		<b>80247</b>
<b>3 (E46) 328 i</b>		<b>1998-00</b>
M52 B28 (286S2)	142 193	
Ignition Coil M 52 B 28		<b>80216</b>
<b>3 (E46) 330 i</b>		<b>2000-05</b>
M54 B30 (306S3)	170 231	
Ignition Coil ->09.2002		<b>80216</b>
Ignition Coil 10.2002->		<b>80247</b>
<b>3 (E46) 330 xi</b>		<b>2000-05</b>
M54 B30 (306S3)	170 231	
Ignition Coil ->09.2002		<b>80216</b>
Ignition Coil 10.2002->		<b>80247</b>
<b>3 (E90) 316 i</b>		<b>2005-11</b>
N45 B16 A	85 116	
Ignition Coil		<b>80247</b>
<b>3 (E90) 316 i</b>		<b>2007-11</b>
N43 B16 A	90 122	
Ignition Coil		<b>80281</b>
<b>3 (E90) 318 i</b>		<b>2004-07</b>
N46 B20 B	95 129	
Ignition Coil		<b>80247</b>
<b>3 (E90) 318 i</b>		<b>2007-11</b>
N43 B20 A	105 143	
Ignition Coil		<b>80281</b>
<b>3 (E90) 320 i</b>		<b>2007-11</b>
N43 B20 A	120 163	
Ignition Coil		<b>80281</b>
<b>3 (E90) 320 i</b>		<b>2004-07</b>
N46 B20 B/N46 B20 A/N46 B20 C	110 150	
Ignition Coil		<b>80247</b>
<b>3 (E90) 320 i</b>		<b>2007-11</b>
N43 B20 A	125 170	
Ignition Coil		<b>80281</b>
<b>3 (E90) 320 i</b>		<b>2006-11</b>
N46 B20 B/N46 B20 CD/N46 B20 CC/N46 B20 E/N46 B20 C	115 156	
Ignition Coil N46 B20 B		<b>80281</b>
<b>3 (E90) 320 si</b>		<b>2005-06</b>
N45 B20 A	127 173	
Ignition Coil		<b>80247</b>
<b>3 (E90) 323 i</b>		<b>2006-11</b>
N52 B25 A	130 177	
Ignition Coil		<b>80247</b>
<b>3 (E90) 323 i</b>		<b>2008-11</b>
N52 B25 A	140 190	
Ignition Coil		<b>80247</b>
<b>3 (E90) 325 i</b>		<b>2007-11</b>
N53 B30 A	155 211	
Ignition Coil 09.2007->		<b>80281</b>
<b>3 (E90) 325 i</b>		<b>2005-11</b>
N52 B25 A	160 218	
Ignition Coil 05.2006->		<b>80247</b>
<b>3 (E90) 325 i</b>		<b>2007-11</b>
N53 B30 A	160 218	
Ignition Coil		<b>80281</b>
<b>3 (E90) 325 i xDrive</b>		<b>2008-11</b>
N53 B30 A	160 218	
Ignition Coil		<b>80281</b>
<b>3 (E90) 325 xi</b>		<b>2005-11</b>
N52 B25 A	160 218	
Ignition Coil 05.2006->		<b>80247</b>
<b>3 (E90) 325 xi</b>		<b>2007-08</b>
N53 B30 A	160 218	
Ignition Coil		<b>80281</b>
<b>3 (E90) 330 i</b>		<b>2007-11</b>
N52 B30 A/N52 B30 BF/N52 B30 B	200 272	
Ignition Coil		<b>80247</b>
<b>3 (E90) 330 i</b>		<b>2005-07</b>
N52 B30 A/N52 B30 BF/N52 B30 B	190 258	
Ignition Coil 05.2006->		<b>80247</b>
<b>3 (E90) 330 i</b>		<b>2007-11</b>
N53 B30 A	200 272	
Ignition Coil N53 B30 A		<b>80281</b>
<b>3 (E90) 330 i xDrive</b>		<b>2008-11</b>
N53 B30 A	200 272	
Ignition Coil		<b>80281</b>

BMW Cont.		
<b>3 (E90) 330 xi</b>		<b>2005-07</b>
N52 B30 A	190 258	
Ignition Coil 05.2006->		<b>80247</b>
<b>3 (E90) 330 xi</b>		<b>2007-11</b>
N53 B30 A	200 272	
Ignition Coil		<b>80281</b>
<b>3 (E90) 335 i</b>		<b>2006-11</b>
N55 B30 A/N54 B30 A	225 306	
Ignition Coil		<b>80247</b>
<b>3 (E90) 335 i</b>		<b>2006-11</b>
N55 B30 A/N54 B30 A	220 299	
Ignition Coil		<b>80247</b>
<b>3 (E90) 335 i xDrive</b>		<b>2008-11</b>
N55 B30 A/N54 B30 A	225 306	
Ignition Coil		<b>80247</b>
<b>3 (E90) 335 xi</b>		<b>2006-08</b>
N55 B30 A/N54 B30 A	225 306	
Ignition Coil		<b>80247</b>
<b>3 (F30, F35, F80) 316 i</b>		<b>2012-16</b>
N13 B16 A	100 136	
Ignition Coil		<b>80247</b>
<b>3 (F30, F35, F80) 320 i</b>		<b>2011-&gt;</b>
N20 B20 A/N20 B20 D	135 184	
Ignition Coil		<b>80247</b>
<b>3 (F30, F35, F80) 320 i</b>		<b>2012-16</b>
N13 B16 A	125 170	
Ignition Coil		<b>80247</b>
<b>3 Cabriolet (E30) 320 i</b>		<b>1986-93</b>
M20 B20 (206KA)	95 129	
Ignition Leads ->08.1988		<b>85890</b>
<b>3 Cabriolet (E36) 318 i</b>		<b>1994-99</b>
M43 B18 (184E2)	85 115	
Ignition Leads 07.1994->		<b>85950</b>
Ignition Leads		<b>85955</b>
<b>3 Cabriolet (E36) 320 i</b>		<b>1993-99</b>
M52 B20 (206S3)/M50 B20 (206S2)	110 150	
Ignition Coil ->12.1995		<b>80215</b>
Ignition Coil		<b>80216</b>
<b>3 Cabriolet (E36) 323 i</b>		<b>1995-99</b>
M52 B25 (256S3)	125 170	
Ignition Coil M 52 B 25 (Vanos)		<b>80216</b>
<b>3 Cabriolet (E36) 325 i</b>		<b>1993-95</b>
M50 B25 (256S2)	141 192	
Ignition Coil With regul.cat.(3way)		<b>80215</b>
<b>3 Cabriolet (E36) 328 i</b>		<b>1995-99</b>
M52 B28 (286S1)	142 193	
Ignition Coil M 52 B 28		<b>80216</b>
<b>3 Cabriolet (E36) M3 3.0</b>		<b>1994-95</b>
S50 B30 (306S1)	210 286	
Ignition Coil With regul.cat.(3way)		<b>80215</b>
<b>3 Cabriolet (E36) M3 3.2</b>		<b>1995-99</b>
S50 B32 (326S1)	236 321	
Ignition Coil S 50 B 32		<b>80216</b>
<b>3 Cabriolet (E46) 318 Ci</b>		<b>2001-07</b>
N46 B20 A/N42 B20 A	105 143	
Ignition Coil		<b>80247</b>
Ignition Leads		<b>85955</b>
<b>3 Cabriolet (E46) 318 Ci</b>		<b>2005-07</b>
N46 B20 B/N46 B20 A	110 150	
Ignition Coil N46 B20 B		<b>80247</b>
<b>3 Cabriolet (E46) 320 Ci</b>		<b>2000-07</b>
M54 B22 (226S1)	125 170	
Ignition Coil ->09.2002		<b>80216</b>
Ignition Coil 10.2002->		<b>80247</b>
<b>3 Cabriolet (E46) 320 Ci</b>		<b>2006-07</b>
M54 B22 (226S1)	120 163	
Ignition Coil		<b>80247</b>
<b>3 Cabriolet (E46) 323 Ci</b>		<b>2000-00</b>
M52 B25 (256S4)	125 170	
Ignition Coil M 52 B 25 (Vanos)		<b>80216</b>
<b>3 Cabriolet (E46) 325 Ci</b>		<b>2000-07</b>
M54 B25 (256S5)	141 192	
Ignition Coil ->09.2002		<b>80216</b>
Ignition Coil 10.2002		<b>80247</b>
<b>3 Cabriolet (E46) 330 Ci</b>		<b>2000-07</b>
M54 B30 (306S3)	170 231	
Ignition Coil ->09.2002		<b>80216</b>
Ignition Coil 10.2002->		<b>80247</b>



BMW Cont.	
<b>3 Cabriolet (E46) M3 3.2</b>	<b>2001-07</b>
S54 B32 (326S4)	252 343
Ignition Coil	<b>80247</b>
<b>3 Cabriolet (E93) 318 i</b>	<b>2010-13</b>
N43 B20 A	105 143
Ignition Coil	<b>80281</b>
<b>3 Cabriolet (E93) 320 i</b>	<b>2006-13</b>
N43 B20 A	125 170
Ignition Coil	<b>80281</b>
<b>3 Cabriolet (E93) 320 i</b>	<b>2007-13</b>
N46 B20 A	110 149
Ignition Coil	<b>80247</b>
<b>3 Cabriolet (E93) 320 i</b>	<b>2007-&gt;</b>
N46 B20 B/N43 B20 A	115 156
Ignition Coil 03.2007->	<b>80247</b>
Ignition Coil	<b>80281</b>
<b>3 Cabriolet (E93) 320 i</b>	<b>2006-13</b>
N43 B20 A	120 163
Ignition Coil 03.2007->	<b>80281</b>
<b>3 Cabriolet (E93) 323 i</b>	<b>2007-11</b>
N52 B25 A	130 177
Ignition Coil	<b>80247</b>
<b>3 Cabriolet (E93) 325 i</b>	<b>2007-13</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>3 Cabriolet (E93) 325 i</b>	<b>2007-13</b>
N52 B25 A	160 218
Ignition Coil	<b>80247</b>
<b>3 Cabriolet (E93) 325 i</b>	<b>2006-13</b>
N53 B30 A	155 211
Ignition Coil 03.2007-09.2013	<b>80281</b>
<b>3 Cabriolet (E93) 330 i</b>	<b>2007-13</b>
N53 B30 A	200 272
Ignition Coil N53 B30 A	<b>80281</b>
<b>3 Cabriolet (E93) 330 i</b>	<b>2007-13</b>
N52 B30 A/N52N B30 B	190 258
Ignition Coil N52B30A	<b>80247</b>
<b>3 Cabriolet (E93) 335 i</b>	<b>2006-13</b>
N54 B30 B/N55 B30 A/N54 B30 A	225 306
Ignition Coil	<b>80247</b>
<b>3 Compact (E36) 316 g</b>	<b>1994-00</b>
M43 B16 (164E2)	75 102
Ignition Leads	<b>85950</b>
<b>3 Compact (E36) 316 i</b>	<b>1998-00</b>
M43 B19 (194E1)	77 105
Ignition Leads	<b>85950</b>
Ignition Leads M43 B19 TU	<b>85955</b>
<b>3 Compact (E36) 316 i</b>	<b>1994-00</b>
M43 B16 (164E2)	75 102
Ignition Leads	<b>85950</b>
<b>3 Compact (E36) 318 ti</b>	<b>1994-95</b>
M42 B18 (184S1)	103 140
Ignition Leads	<b>85940</b>
Ignition Leads SAE	<b>85945</b>
<b>3 Compact (E36) 318 ti</b>	<b>1995-00</b>
M44 B19 (194S1)	103 140
Ignition Leads	<b>85940</b>
Ignition Leads SAE	<b>85945</b>
<b>3 Compact (E36) 323 ti</b>	<b>1997-00</b>
M52 B25 (256S3)	125 170
Ignition Coil M 52 B 25 (Vanos)	<b>80216</b>
<b>3 Compact (E46) 316 ti</b>	<b>2001-05</b>
N46 B18 A/N42 B18 A	85 115
Ignition Coil ->12.2004	<b>80247</b>
<b>3 Compact (E46) 316 ti</b>	<b>2002-05</b>
N45 B16 A/N40 B16 A	85 115
Ignition Coil ->12.2004	<b>80247</b>
<b>3 Compact (E46) 318 ti</b>	<b>2001-04</b>
N46 B20 A/N42 B20 A	105 143
Ignition Coil	<b>80247</b>
<b>3 Compact (E46) 325 ti</b>	<b>2001-05</b>
M54 B25 (256S5)	141 192
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 12.2002-12.2004	<b>80247</b>
<b>3 Coupe (E36) 316 i</b>	<b>1993-99</b>
M43 B16 (164E2)	75 102
Ignition Leads	<b>85950</b>

BMW Cont.	
<b>3 Coupe (E36) 318 is</b>	<b>1995-99</b>
M44 B19 (194S1)	103 140
Ignition Leads	<b>85940</b>
Ignition Leads SAE	<b>85945</b>
<b>3 Coupe (E36) 318 is</b>	<b>1992-95</b>
M42 B18 (184S1)	103 140
Ignition Coil M 42 B 18; ->09.1993; With regul.cat.(3way)	<b>80215</b>
Ignition Leads	<b>85940</b>
Ignition Leads 08.1993->	<b>85945</b>
<b>3 Coupe (E36) 320 i</b>	<b>1992-99</b>
M52 B20 (206S3)/M50 B20 (206S2)/M50 B20 (206S1)	110 150
Ignition Coil ->12.1995	<b>80215</b>
Ignition Coil M52 B(20 6 S3) Vanos; 09.1994-12.1998	<b>80216</b>
<b>3 Coupe (E36) 323 i</b>	<b>1995-99</b>
M52 B25 (256S3)	125 170
Ignition Coil M 52 B 25 (Vanos)	<b>80216</b>
<b>3 Coupe (E36) 325 i</b>	<b>1992-99</b>
M50 B25 (256S1)/M50 B25 (256S2)	141 192
Ignition Coil M 50 B 25 (Vanos); With regul.cat.(3way)	<b>80215</b>
<b>3 Coupe (E36) 328 i</b>	<b>1995-99</b>
M52 B28 (286S1)	142 193
Ignition Coil M 52 B 28	<b>80216</b>
<b>3 Coupe (E36) M3 3.0</b>	<b>1992-95</b>
S50 B30 (306S1)	210 286
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>3 Coupe (E36) M3 3.0</b>	<b>1995-95</b>
S50 B30 (306S1)	217 295
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>3 Coupe (E36) M3 3.2</b>	<b>1995-99</b>
S50 B32 (326S1)	236 321
Ignition Coil S 50 B 32	<b>80216</b>
<b>3 Coupe (E46) 316 Ci</b>	<b>2000-06</b>
M43 B16 (164E3)	77 105
Ignition Leads	<b>85955</b>
<b>3 Coupe (E46) 316 Ci</b>	<b>2002-06</b>
N45 B16 A	85 115
Ignition Coil	<b>80247</b>
<b>3 Coupe (E46) 318 Ci</b>	<b>1999-01</b>
M43 B19 (194E1)	87 118
Ignition Leads	<b>85955</b>
<b>3 Coupe (E46) 318 Ci</b>	<b>2000-06</b>
N46 B20 A/N42 B20 A/N46 B20 C	105 143
Ignition Coil N42 B20	<b>80247</b>
<b>3 Coupe (E46) 318 Ci</b>	<b>2005-06</b>
N46 B20 A	110 150
Ignition Coil	<b>80247</b>
<b>3 Coupe (E46) 320 Ci</b>	<b>1999-01</b>
M52 B20 (206S4)	110 150
Ignition Coil M 52 B (20 6 S4)	<b>80216</b>
<b>3 Coupe (E46) 320 Ci</b>	<b>2000-06</b>
M54 B22 (226S1)	125 170
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>3 Coupe (E46) 323 Ci</b>	<b>1999-00</b>
M52 B25 (256S4)	125 170
Ignition Coil M 52 B 25 (Vanos)	<b>80216</b>
<b>3 Coupe (E46) 325 Ci</b>	<b>2000-06</b>
M54 B25 (256S5)	141 192
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>3 Coupe (E46) 328 Ci</b>	<b>1999-00</b>
M52 B28 (286S2)	142 193
Ignition Coil M 52 B 28	<b>80216</b>
<b>3 Coupe (E46) 330 Ci</b>	<b>2000-06</b>
M54 B30 (306S3)	170 231
Ignition Coil ->09.2002	<b>80215</b>
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002-05.2006	<b>80247</b>
<b>3 Coupe (E46) 330 xi</b>	<b>2000-06</b>
M54 B30 (306S3)	170 231
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>3 Coupe (E46) M3 3.2</b>	<b>2000-06</b>
S54 B32 (326S4)	252 343
Ignition Coil	<b>80247</b>
<b>3 Coupe (E46) M3 CSL</b>	<b>2003-06</b>
S54 B32 (326S4)	265 360
Ignition Coil	<b>80247</b>



BMW Cont.	
<b>3 Coupe (E92) 316 i</b>	<b>2007-13</b>
N43 B16 A	90 122
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 318 i</b>	<b>2010-13</b>
N43 B20 A	105 143
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 320 i</b>	<b>2007-13</b>
N43 B20 A	125 170
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 320 i</b>	<b>2006-07</b>
N46 B20 A	110 150
Ignition Coil N46N B20 B	<b>80247</b>
<b>3 Coupe (E92) 320 i</b>	<b>2007-13</b>
N43 B20 A	120 163
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 320 i</b>	<b>2007-13</b>
N46 B20 B	115 156
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 323 i</b>	<b>2006-12</b>
N52 B25 A	130 177
Ignition Coil	<b>80247</b>
<b>3 Coupe (E92) 325 i</b>	<b>2005-13</b>
N52 B25 A	160 218
Ignition Coil	<b>80247</b>
<b>3 Coupe (E92) 325 i</b>	<b>2005-13</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 325 i</b>	<b>2005-13</b>
N53 B30 A	155 211
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 325 i xDrive</b>	<b>2008-13</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 325 xi</b>	<b>2006-13</b>
N52 B25 A	160 218
Ignition Coil	<b>80247</b>
<b>3 Coupe (E92) 325 xi</b>	<b>2007-13</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 330 i</b>	<b>2007-13</b>
N53 B30 A	200 272
Ignition Coil 09.2007-06.2013	<b>80281</b>
<b>3 Coupe (E92) 330 i</b>	<b>2006-10</b>
N52 B30 A/N52 B30 BF/N52 B30 B/N52 B30 AF	200 272
Ignition Coil N52 B30 A	<b>80247</b>
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 330 i</b>	<b>2006-13</b>
N52 B30 A	190 258
Ignition Coil	<b>80247</b>
<b>3 Coupe (E92) 330 i xDrive</b>	<b>2008-13</b>
N53 B30 A	200 272
Ignition Coil	<b>80281</b>
<b>3 Coupe (E92) 330 xi</b>	<b>2006-13</b>
N52 B30 A	200 272
Ignition Coil	<b>80247</b>
Ignition Coil 09.2007-08.2008	<b>80281</b>
<b>3 Coupe (E92) 330 xi</b>	<b>2006-13</b>
N52 B30 A	190 258
Ignition Coil	<b>80247</b>
<b>3 Coupe (E92) 335 i</b>	<b>2005-13</b>
N55 B30 A/N54 B30 A	225 306
Ignition Coil	<b>80247</b>
<b>3 Coupe (E92) 335 i xDrive</b>	<b>2008-13</b>
N55 B30 A/N54 B30 A	225 306
Ignition Coil	<b>80247</b>
<b>3 Coupe (E92) 335 xi</b>	<b>2007-10</b>
N55 B30 A/N54 B30 A	225 306
Ignition Coil ->08.2008	<b>80247</b>
<b>3 Touring (E30) 320 i</b>	<b>1988-91</b>
M20 B20 (206KA)	95 129
Ignition Leads ->08.1988	<b>85890</b>
<b>3 Touring (E36) 316 i</b>	<b>1996-99</b>
M43 B16 (164E2)	75 102
Ignition Leads	<b>85950</b>
<b>3 Touring (E36) 318 i</b>	<b>1995-99</b>
M43 B18 (184E2)	85 116
Ignition Leads	<b>85950</b>
Ignition Leads SAE	<b>85955</b>

BMW Cont.	
<b>3 Touring (E36) 320 i</b>	<b>1995-99</b>
M52 B20 (206S3)	110 150
Ignition Coil	<b>80216</b>
<b>3 Touring (E36) 323 i</b>	<b>1995-99</b>
M52 B25 (256S3)	125 170
Ignition Coil M 52 B 25 (Vanos)	<b>80216</b>
<b>3 Touring (E36) 328 i</b>	<b>1995-99</b>
M52 B28 (286S1)	142 193
Ignition Coil M 52 B 28	<b>80216</b>
<b>3 Touring (E46) 316 i</b>	<b>2002-05</b>
N46 B18 A/N42 B18 A	85 115
Ignition Coil	<b>80247</b>
<b>3 Touring (E46) 316 i</b>	<b>2002-05</b>
N45 B16 A	85 115
Ignition Coil	<b>80247</b>
<b>3 Touring (E46) 318 i</b>	<b>1999-01</b>
M43 B19 (194E1)	87 118
Ignition Leads	<b>85955</b>
<b>3 Touring (E46) 318 i</b>	<b>2001-05</b>
N46 B20 A/N42 B20 A	105 143
Ignition Coil	<b>80247</b>
<b>3 Touring (E46) 320 i</b>	<b>1999-00</b>
M52 B20 (206S4)	110 150
Ignition Coil M52 B20	<b>80216</b>
<b>3 Touring (E46) 320 i</b>	<b>2000-05</b>
M54 B22 (226S1)	125 170
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>3 Touring (E46) 325 i</b>	<b>2000-05</b>
M54 B25 (256S5)	141 192
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>3 Touring (E46) 325 xi</b>	<b>2000-05</b>
M54 B25 (256S5)	141 192
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>3 Touring (E46) 328 i</b>	<b>1999-00</b>
M52 B28 (286S2)	142 193
Ignition Coil M 52 B 28	<b>80216</b>
<b>3 Touring (E46) 330 i</b>	<b>2000-05</b>
M54 B30 (306S3)	170 231
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>3 Touring (E46) 330 xi</b>	<b>2000-05</b>
M54 B30 (306S3)	170 231
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>3 Touring (E91) 316 i</b>	<b>2008-12</b>
N43 B16 A	90 122
Ignition Coil	<b>80247</b>
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 318 i</b>	<b>2007-12</b>
N46 B20 B	100 136
Ignition Coil	<b>80247</b>
Ignition Coil N43 B20 A	<b>80281</b>
<b>3 Touring (E91) 318 i</b>	<b>2006-07</b>
N46 B20 B	95 129
Ignition Coil	<b>80247</b>
<b>3 Touring (E91) 318 i</b>	<b>2007-12</b>
N43 B20 A	105 143
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 320 i</b>	<b>2007-12</b>
N43 B20 A	120 163
Ignition Coil 09.2007->	<b>80281</b>
<b>3 Touring (E91) 320 i</b>	<b>2005-12</b>
N46 B20 B	110 150
Ignition Coil	<b>80247</b>
<b>3 Touring (E91) 320 i</b>	<b>2007-12</b>
N43 B20 A	125 170
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 323 i</b>	<b>2006-08</b>
N52 B25 A	140 190
Ignition Coil	<b>80247</b>
<b>3 Touring (E91) 325 i</b>	<b>2004-10</b>
N52 B25 A	160 218
Ignition Coil ->04.2006	<b>80247</b>



BMW Cont.	
<b>3 Touring (E91) 325 i</b>	<b>2007-12</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 325 i</b>	<b>2007-12</b>
N53 B30 A	155 211
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 325 i xDrive</b>	<b>2007-12</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 325 xi</b>	<b>2005-11</b>
N52 B25 A	160 218
Ignition Coil 05.2006->	<b>80247</b>
<b>3 Touring (E91) 325 xi</b>	<b>2007-12</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 330 i</b>	<b>2005-07</b>
N52 B30 A	190 258
Ignition Coil 05.2006->	<b>80247</b>
<b>3 Touring (E91) 330 i</b>	<b>2007-12</b>
N53 B30 A	200 272
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 330 i xDrive</b>	<b>2007-12</b>
N53 B30 A	200 272
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 330 xi</b>	<b>2005-07</b>
N52 B30 A	190 258
Ignition Coil 05.2006->	<b>80247</b>
<b>3 Touring (E91) 330 xi</b>	<b>2007-12</b>
N53 B30 A	200 272
Ignition Coil	<b>80281</b>
<b>3 Touring (E91) 335 i</b>	<b>2006-12</b>
N55 B30 A/N54 B30 A	225 306
Ignition Coil	<b>80247</b>
<b>3 Touring (E91) 335 i xDrive</b>	<b>2008-12</b>
N55 B30 A/N54 B30 A	225 306
Ignition Coil	<b>80247</b>
<b>3 Touring (E91) 335 xi</b>	<b>2006-08</b>
N55 B30 A/N54 B30 A	225 306
Ignition Coil	<b>80247</b>
<b>3 Touring (F31) 316 i</b>	<b>2012-16</b>
N13 B16 A	100 136
Ignition Coil	<b>80247</b>
<b>5 (E12) 518</b>	<b>1975-77</b>
M10 B20	80 109
Ignition Leads	<b>83820</b>
<b>5 (E12) 518</b>	<b>1974-81</b>
M10 B18 (184VB)	66 90
Ignition Leads	<b>83820</b>
<b>5 (E12) 520</b>	<b>1972-77</b>
M10 B20	85 115
Ignition Leads	<b>83820</b>
<b>5 (E12) 520 i</b>	<b>1972-75</b>
M10 B20	96 131
Ignition Leads	<b>83820</b>
<b>5 (E12) 520 i</b>	<b>1975-77</b>
M10 B20	92 125
Ignition Leads	<b>83820</b>
<b>5 (E12) 520/6</b>	<b>1977-81</b>
M20 B20 (206VA)	90 122
Ignition Leads	<b>85890</b>
<b>5 (E12) 525</b>	<b>1973-76</b>
M30 B25	107 146
Ignition Leads	<b>83820</b>
<b>5 (E12) 525</b>	<b>1976-81</b>
M30 B25 (256VA)	110 150
Ignition Leads	<b>83820</b>
<b>5 (E12) 528</b>	<b>1975-77</b>
M30 B28	121 165
Ignition Leads	<b>83820</b>
<b>5 (E12) 528</b>	<b>1975-77</b>
M30 B28	125 170
Ignition Leads	<b>83820</b>
<b>5 (E12) 528 i</b>	<b>1977-81</b>
M30 B28	130 177
Ignition Leads	<b>83820</b>
<b>5 (E12) 528 i</b>	<b>1977-81</b>
M30 B28	135 184
Ignition Leads	<b>83820</b>

BMW Cont.	
<b>5 (E12) M 3.4</b>	<b>1980-81</b>
M30 B35 (Motronic,9.3:1)	160 218
Ignition Leads	<b>83820</b>
<b>5 (E28) 520 i</b>	<b>1981-87</b>
M20 B20 (206EA)	92 125
Ignition Leads ->09.1982	<b>85890</b>
<b>5 (E28) 520 i</b>	<b>1985-87</b>
M20 B20 (206KA)	95 129
Ignition Leads	<b>85890</b>
<b>5 (E28) 525 i</b>	<b>1981-87</b>
M30 B25 (256EA)	110 150
Ignition Leads	<b>85890</b>
<b>5 (E28) 535 i, M 535 i</b>	<b>1985-87</b>
M30 B34 (346KA)	136 185
Ignition Leads	<b>85920</b>
Ignition Leads	<b>85930</b>
<b>5 (E28) 535 i, M 535 i</b>	<b>1985-87</b>
M30 B35 (Motronic)	141 192
Ignition Leads	<b>85920</b>
Ignition Leads	<b>85930</b>
<b>5 (E28) 535 i, M 535 i</b>	<b>1985-87</b>
M30 B34 (346EC)	160 218
Ignition Leads	<b>85920</b>
Ignition Leads	<b>85930</b>
<b>5 (E28) M 3.5</b>	<b>1985-87</b>
S38 B35 (356ED)	211 286
Ignition Leads	<b>85930</b>
<b>5 (E34) 518 i</b>	<b>1989-95</b>
M43 B18 (184E2)	85 115
Ignition Leads	<b>85955</b>
<b>5 (E34) 520 i 24V</b>	<b>1989-95</b>
M50 B20 (206S2)/M50 B20 (206S1)	110 150
Ignition Coil	<b>80215</b>
<b>5 (E34) 525 i</b>	<b>1988-91</b>
M20 B25 (256K1)	125 170
Ignition Leads ->08.1988	<b>85920</b>
<b>5 (E34) 525 i 24V</b>	<b>1989-95</b>
M50 B25 (256S2)	141 192
Ignition Coil M50 B25/M50 B25 TU	<b>80215</b>
<b>5 (E34) 525 iX 24V</b>	<b>1991-95</b>
M50 B25 (256S1)/M50 B25 (256S2)	141 192
Ignition Coil	<b>80215</b>
<b>5 (E34) 530 i</b>	<b>1988-91</b>
M30 B30 (306KA)	138 188
Ignition Leads ->10.1988	<b>85920</b>
Ignition Leads 11.1988-12.1990	<b>85930</b>
<b>5 (E34) 530 i V8</b>	<b>1992-95</b>
M60 B30 (308S1)	160 218
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>5 (E34) 535 i</b>	<b>1988-95</b>
M30 B34 (346KB)	155 211
Ignition Leads ->10.1988	<b>85920</b>
Ignition Leads 11.1988-04.1993	<b>85930</b>
<b>5 (E34) 540 i V8</b>	<b>1992-95</b>
M60 B40 (408S1)	210 286
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>5 (E34) M 3.8</b>	<b>1992-95</b>
S38 B38 (386S1)	250 340
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>5 (E39) 520 i</b>	<b>1999-03</b>
M52 B20 (206S3)	100 136
Ignition Coil	<b>80216</b>
<b>5 (E39) 520 i</b>	<b>2000-03</b>
M54 B22 (226S1)	125 170
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>5 (E39) 520 i</b>	<b>1996-00</b>
M52 B20 (206S3)	110 150
Ignition Coil	<b>80216</b>
<b>5 (E39) 523 i</b>	<b>1995-00</b>
M52 B25 (256S3)	125 170
Ignition Coil M 52 B 25 (Vanos)	<b>80216</b>
<b>5 (E39) 525 i</b>	<b>2000-03</b>
M54 B25 (256S5)	141 192
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>5 (E39) 528 i</b>	<b>1995-00</b>
M52 B28 (286S1)/M52 B28 (286S2)	142 193
Ignition Coil M 52 B 28	<b>80216</b>



BMW Cont.	
5 (E39) 530 i	2000-03
M54 B30 (306S3)	170 231
Ignition Coil ->09.2002	80216
Ignition Coil 10.2002->	80247
5 (E39) 535 i	1999-03
M62 B35 (358S2)	180 245
Ignition Coil M 62 B (35 8 S2)	80216
5 (E39) 535 i	1996-99
M62 B35 (358S1)/M62 B35 (358S2)	173 235
Ignition Coil M 62 B (35 8 S1)	80216
5 (E39) 540 i	1996-03
M62 B44 (448S2)/M62 B44 (448S1)	210 286
Ignition Coil M 62 B 44	80216
5 (E39) M 4.9	1998-03
S62 B50 (508S1)	294 400
Ignition Coil S 62 B 50,S 38 B 49	80216
5 (E60) 520 i	2003-10
M54 B22 (226S1)	125 170
Ignition Coil	80247
5 (E60) 520 i	2007-10
N43 B20 A	125 170
Ignition Coil	80281
5 (E60) 520 i	2006-10
N43 B20 A	120 163
Ignition Coil	80247
5 (E60) 520 i	2006-09
N46 B20 B	115 156
Ignition Coil	80247
5 (E60) 523 i	2005-10
N52 B25 A	130 177
Ignition Coil 05.2006->	80247
5 (E60) 523 i	2007-10
N52 B25 A/N52 B25 BE	140 190
Ignition Coil N52 B25 A	80281
5 (E60) 525 i	2003-10
M54 B25 (256S5)	141 192
Ignition Coil	80247
5 (E60) 525 i	2005-10
N52 B25 A	160 218
Ignition Coil 05.2006->	80247
5 (E60) 525 i	2007-10
N53 B30 A	160 218
Ignition Coil	80281
5 (E60) 525 i xDrive	2008-10
N53 B30 A	160 218
Ignition Coil	80281
5 (E60) 525 xi	2005-10
N52 B25 A	160 218
Ignition Coil 05.2006->	80247
5 (E60) 525 xi	2007-10
N53 B30 A	160 218
Ignition Coil	80281
5 (E60) 530 i	2007-10
N52 B30 A/N52 B30 BF/N52 B30 B	200 272
Ignition Coil	80247
5 (E60) 530 i	2001-05
M54 B30 (306S3)	170 231
Ignition Coil	80247
5 (E60) 530 i	2004-07
N52 B30 A/N52 B30 BF/N52 B30 B	190 258
Ignition Coil 05.2006->	80247
5 (E60) 530 i	2006-09
N53 B30 A	200 272
Ignition Coil N53 B30 A	80281
5 (E60) 530 i xDrive	2007-09
N53 B30 A	200 272
Ignition Coil N53 B30 A	80281
5 (E60) 530 xi	2004-07
N52 B30 A	190 258
Ignition Coil 05.2006->	80247
5 (E60) 530 xi	2005-07
N53 B30 A	200 272
Ignition Coil	80247
Ignition Coil N53 B30 A	80281
5 (E60) 540 i	2005-10
N62 B40 A	225 306
Ignition Coil	80247

BMW Cont.	
5 (E60) 540 i	2005-10
N54 B30 A	225 306
Ignition Coil 05.2006->	80247
5 (E60) 545 i	2003-10
N62 B44 A	245 333
Ignition Coil	80247
5 (E60) 550 i	2005-10
N62 B48 A/N62 B48 B	270 367
Ignition Coil N62 B48 B	80247
5 (F10, F18) 523 i	2009-11
N52 B25 AF/N52 B25 B/N52 B25 BF/N52 B25 A	150 204
Ignition Coil	80247
5 (F10, F18) 523 i	2009-11
N53 B30 A	150 204
Ignition Coil	80281
5 (F10, F18) 528 i	2009-11
N53 B30 A	190 258
Ignition Coil	80281
5 (F10, F18) 528 i xDrive	2010-16
N20 B20 A	180 245
Ignition Coil	80247
5 (F10, F18) 550 i	2009-13
N63 B44 A	300 408
Ignition Coil	80247
5 (F10, F18) 550 i	2012-16
N63 B44 B	330 449
Ignition Coil	80247
5 (F10, F18) 550 i xDrive	2010-13
N63 B44 A	300 408
Ignition Coil	80247
5 (F10, F18) 550 i xDrive	2013-16
N63 B44 B	330 449
Ignition Coil	80247
5 (F10, F18) M5	2014->
S63 B44 B	423 575
Ignition Coil ->11.2015	80247
5 (F10, F18) M5	2014->
S63 B44 B	441 600
Ignition Coil ->11.2015	80247
5 (F10, F18) M5	2010-16
S63 B44 B	412 560
Ignition Coil ->09.2011	80247
5 Gran Turismo (F07) 550 i	2009-12
N63 B44 A	300 408
Ignition Coil	80247
5 Gran Turismo (F07) 550 i	2012-16
N63 B44 B	330 449
Ignition Coil	80247
5 Gran Turismo (F07) 550 i xDrive	2009-12
N63 B44 A	300 408
Ignition Coil	80247
5 Gran Turismo (F07) 550 i xDrive	2011->
N63 B44 B	330 449
Ignition Coil	80247
5 Touring (E34) 518 i	1994-97
M43 B18 (184E2)	85 115
Ignition Leads	85955
5 Touring (E34) 520 i	1991-97
M50 B20 (206S2)/M50 B20 (206S1)	110 150
Ignition Coil ->12.1996	80215
5 Touring (E34) 525 i	1991-97
M50 B25 (256S1)/M50 B25 (256S2)	141 192
Ignition Coil With regul.cat.(3way)	80215
5 Touring (E34) 525 ix	1992-97
M50 B25 (256S1)/M50 B25 (256S2)	141 192
Ignition Coil With regul.cat.(3way)	80215
5 Touring (E34) 530 i V8	1992-97
M60 B30 (308S1)	160 218
Ignition Coil With regul.cat.(3way)	80215
5 Touring (E34) 540 i	1993-97
M60 B40 (408S1)	210 286
Ignition Coil With regul.cat.(3way)	80215
5 Touring (E34) M 3.8	1994-97
S38 B38 (386S1)	250 340
Ignition Coil With regul.cat.(3way)	80215
5 Touring (E39) 520 i	1999-04
M52 B20 (206S3)	100 136
Ignition Coil ->12.2001	80216





BMW Cont.	
<b>5 Touring (E39) 520 i</b>	<b>2000-04</b>
M54 B22 (226S1)	125 170
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>5 Touring (E39) 520 i</b>	<b>1997-00</b>
M52 B20 (206S3)	110 150
Ignition Coil	<b>80216</b>
<b>5 Touring (E39) 523 i</b>	<b>1997-00</b>
M52 B25 (256S3)	125 170
Ignition Coil M 52 B 25 (Vanos)	<b>80216</b>
<b>5 Touring (E39) 525 i</b>	<b>2000-04</b>
M54 B25 (256S5)	141 192
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>5 Touring (E39) 528 i</b>	<b>1997-00</b>
M52 B28 (286S1)/M52 B28 (286S2)	142 193
Ignition Coil M 52 B 28	<b>80216</b>
<b>5 Touring (E39) 530 i</b>	<b>2000-04</b>
M54 B30 (306S3)	170 231
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>5 Touring (E39) 540 i</b>	<b>1997-04</b>
M62 B44 (448S2)/M62 B44 (448S1)	210 286
Ignition Coil M 62 B 44	<b>80216</b>
<b>5 Touring (E61) 520 i</b>	<b>2007-10</b>
N43 B20 A	125 170
Ignition Coil	<b>80281</b>
<b>5 Touring (E61) 523 i</b>	<b>2005-10</b>
N52 B25 B/N52 B25 A/N52 B25 BE	130 177
Ignition Coil 05.2006->	<b>80247</b>
<b>5 Touring (E61) 523 i</b>	<b>2007-10</b>
N52 B25 A	140 190
Ignition Coil N52 B25 A	<b>80281</b>
<b>5 Touring (E61) 525 i</b>	<b>2004-10</b>
M54 B25 (256S5)	141 192
Ignition Coil	<b>80247</b>
<b>5 Touring (E61) 525 i</b>	<b>2005-10</b>
N52 B25 A	160 218
Ignition Coil 05.2006->	<b>80247</b>
<b>5 Touring (E61) 525 i</b>	<b>2007-10</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>5 Touring (E61) 525 i xDrive</b>	<b>2008-10</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>5 Touring (E61) 525 xi</b>	<b>2005-10</b>
N52 B25 A	160 218
Ignition Coil 05.2006->	<b>80247</b>
<b>5 Touring (E61) 525 xi</b>	<b>2007-10</b>
N53 B30 A	160 218
Ignition Coil	<b>80281</b>
<b>5 Touring (E61) 530 i</b>	<b>2007-10</b>
N52 B30 A	200 272
Ignition Coil	<b>80247</b>
<b>5 Touring (E61) 530 i</b>	<b>2005-10</b>
N52 B30 A	190 258
Ignition Coil 05.2006->	<b>80247</b>
<b>5 Touring (E61) 530 i</b>	<b>2007-10</b>
N53 B30 A	200 272
Ignition Coil	<b>80281</b>
<b>5 Touring (E61) 530 i xDrive</b>	<b>2008-10</b>
N53 B30 A	200 272
Ignition Coil	<b>80281</b>
<b>5 Touring (E61) 530 xi</b>	<b>2005-10</b>
N52 B30 A	190 258
Ignition Coil 05.2006->	<b>80247</b>
<b>5 Touring (E61) 530 xi</b>	<b>2007-10</b>
N52 B30 A	200 272
Ignition Coil	<b>80281</b>
<b>5 Touring (E61) 545 i</b>	<b>2004-10</b>
N62 B44 A	245 333
Ignition Coil ->06.2009	<b>80247</b>
<b>5 Touring (E61) 550 i</b>	<b>2005-10</b>
N62 B48 A/N62 B48 B	270 367
Ignition Coil 09.2005-06.2009	<b>80247</b>
<b>5 Touring (F11) 550 i</b>	<b>2010-13</b>
N63 B44 A	300 408
Ignition Coil ->03.2011	<b>80247</b>

BMW Cont.	
<b>5 Touring (F11) 550 i</b>	<b>2012-&gt;</b>
N63 B44 B	330 449
Ignition Coil	<b>80247</b>
<b>6 (E24) 628 CSi</b>	<b>1979-87</b>
M30 B28	135 184
Ignition Leads	<b>85930</b>
<b>6 (E24) 635 CSi</b>	<b>1978-88</b>
M30 B35 (Motronic,9.3:1)/M30 B35 (Motronic,10:1)/M30 B35 (L-	160 218
Ignition Leads	<b>85930</b>
<b>6 (E24) 635 CSi</b>	<b>1987-89</b>
M30 B34 (346KB)	155 211
Ignition Leads	<b>85930</b>
<b>6 (E24) 635 CSi</b>	<b>1977-89</b>
M30 B34 (346KA)	136 185
Ignition Leads	<b>85930</b>
<b>6 (E24) 635 CSi</b>	<b>1977-89</b>
M30 B35	141 192
Ignition Leads	<b>85930</b>
<b>6 (E63) 630 i</b>	<b>2007-10</b>
N52 B30 A/N52 B30 BF/N52 B30 B	200 272
Ignition Coil	<b>80247</b>
<b>6 (E63) 630 i</b>	<b>2004-10</b>
N52 B30 A	190 258
Ignition Coil 05.2006->	<b>80247</b>
<b>6 (E63) 630 i</b>	<b>2007-10</b>
N53 B30 A	200 272
Ignition Coil N52 B30 A	<b>80281</b>
<b>6 (E63) 645 Ci</b>	<b>2004-05</b>
N62 B44 A	245 333
Ignition Coil	<b>80247</b>
<b>6 (E63) 650 i</b>	<b>2005-10</b>
N62 B48 B	270 367
Ignition Coil	<b>80247</b>
<b>6 Cabriolet (E64) 630 i</b>	<b>2007-10</b>
N52 B30 A/N52 B30 BF/N52 B30 B	200 272
Ignition Coil	<b>80247</b>
<b>6 Cabriolet (E64) 630 i</b>	<b>2004-10</b>
N52 B30 A	190 258
Ignition Coil 05.2006->	<b>80247</b>
<b>6 Cabriolet (E64) 630 i</b>	<b>2007-10</b>
N53 B30 A	200 272
Ignition Coil	<b>80281</b>
<b>6 Cabriolet (E64) 645 Ci</b>	<b>2004-05</b>
N62 B44 A	245 333
Ignition Coil	<b>80247</b>
<b>6 Cabriolet (E64) 650 i</b>	<b>2005-10</b>
N62 B48 B	270 367
Ignition Coil 09.2005-06.2009	<b>80247</b>
<b>6 Cabriolet (F12) 650 i</b>	<b>2011-&gt;</b>
N63 B44 A/N63 B44 B	330 449
Ignition Coil N63B44B; ->07.2012	<b>80247</b>
<b>6 Cabriolet (F12) 650 i</b>	<b>2011-&gt;</b>
N63 B44 A	300 408
Ignition Coil	<b>80247</b>
<b>6 Cabriolet (F12) 650 i xDrive</b>	<b>2011-&gt;</b>
N63 B44 A	300 407
Ignition Coil ->06.2012	<b>80247</b>
<b>6 Cabriolet (F12) 650 i xDrive</b>	<b>2011-&gt;</b>
N63 B44 A/N63 B44 B	330 449
Ignition Coil N63 B44 B; ->07.2012	<b>80247</b>
<b>6 Cabriolet (F12) M6</b>	<b>2014-&gt;</b>
S63 B44 B	423 575
Ignition Coil ->11.2015	<b>80247</b>
<b>6 Cabriolet (F12) M6</b>	<b>2015-&gt;</b>
S63 B44 B	441 600
Ignition Coil ->11.2015	<b>80247</b>
<b>6 Cabriolet (F12) M6</b>	<b>2012-&gt;</b>
S63 B44 B	412 560
Ignition Coil ->03.2012	<b>80247</b>
<b>6 Coupe (F13) 650 i</b>	<b>2011-&gt;</b>
N63 B44 B	330 449
Ignition Coil ->07.2012	<b>80247</b>
<b>6 Coupe (F13) 650 i</b>	<b>2010-&gt;</b>
N63 B44 A	300 407
Ignition Coil	<b>80247</b>
<b>6 Coupe (F13) 650 i xDrive</b>	<b>2011-&gt;</b>
N63 B44 A	300 408
Ignition Coil ->06.2012	<b>80247</b>



BMW Cont.	
<b>6 Coupe (F13) 650 i xDrive</b>	2011->
N63 B44 B	330 449
Ignition Coil ->07.2012	<b>80247</b>
<b>6 Coupe (F13) M6</b>	2014->
S63 B44 B	423 575
Ignition Coil ->11.2015	<b>80247</b>
<b>6 Coupe (F13) M6</b>	2015->
S63 B44 B	441 600
Ignition Coil ->11.2015	<b>80247</b>
<b>6 Coupe (F13) M6</b>	2012->
S63 B44 B	412 560
Ignition Coil ->09.2012	<b>80247</b>
<b>6 Gran Coupe (F06) 650 i</b>	2011->
N63 B44 B	330 449
Ignition Coil	<b>80247</b>
<b>6 Gran Coupe (F06) 650 i xDrive</b>	2011->
N63 B44 B	330 449
Ignition Coil	<b>80247</b>
<b>6 Gran Coupe (F06) M6</b>	2014->
S63 B44 B	423 575
Ignition Coil ->11.2015	<b>80247</b>
<b>6 Gran Coupe (F06) M6</b>	2015->
S63 B44 B	441 600
Ignition Coil ->11.2015	<b>80247</b>
<b>6 Gran Coupe (F06) M6</b>	2012->
S63 B44 B	412 560
Ignition Coil	<b>80247</b>
<b>7 (E23) 728 i</b>	1978-86
M30 B28	135 184
Ignition Leads	<b>85930</b>
<b>7 (E23) 730</b>	1977-79
M30 B30	135 184
Ignition Leads	<b>85930</b>
<b>7 (E23) 733 i</b>	1977-86
M30 B32	145 197
Ignition Leads	<b>85930</b>
<b>7 (E23) 735 i</b>	1985-86
M30 B34 (346KA)	136 185
Ignition Leads	<b>85930</b>
<b>7 (E23) 735 i</b>	1979-86
M30 B35 (Motronic,9.3:1)/M30 B35 (Motronic,10:1)	160 218
Ignition Leads	<b>85930</b>
<b>7 (E23) 735 i</b>	1985-86
M30 B35 (Motronic)	141 192
Ignition Leads	<b>85930</b>
<b>7 (E23) 745 i</b>	1980-83
M30 B32 (326TA)	185 252
Ignition Leads	<b>85930</b>
<b>7 (E23) 745 i</b>	1983-86
M30 B35	185 252
Ignition Leads	<b>85930</b>
<b>7 (E32) 730 i,iL</b>	1986-94
M30 B30 (306EA)	145 197
Ignition Leads 02.1988->	<b>85920</b>
Ignition Leads ->01.1988	<b>85930</b>
<b>7 (E32) 730 i,iL</b>	1986-94
M30 B30 (306KA)	138 188
Ignition Leads 02.1988->	<b>85920</b>
Ignition Leads ->01.1988	<b>85930</b>
<b>7 (E32) 730 i,iL V8</b>	1992-94
M60 B30 (308S1)	160 218
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>7 (E32) 735 i,iL</b>	1986-92
M30 B34 (346KB)	155 211
Ignition Leads 02.1988->	<b>85920</b>
Ignition Leads ->01.1988	<b>85930</b>
<b>7 (E32) 735 i,iL</b>	1986-87
M30 B35 (Motronic,9.2:1)	162 220
Ignition Leads	<b>85930</b>
<b>7 (E32) 740 i,iL V8</b>	1992-94
M60 B40 (408S1)	210 286
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>7 (E38) 728 i,iL</b>	1995-01
M52 B28 (286S1)/M52 B28 (286S2)	142 193
Ignition Coil M 52 B 28	<b>80216</b>
<b>7 (E38) 730 i,iL</b>	1994-01
M60 B30 (308S1)	155 211
Ignition Coil With regul.cat.(3way)	<b>80215</b>

BMW Cont.	
<b>7 (E38) 730 i,iL</b>	1994-01
M60 B30 (308S1)	160 218
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>7 (E38) 735 i,iL</b>	1998-01
M62 B35 (358S2)	175 238
Ignition Coil	<b>80216</b>
<b>7 (E38) 735 i,iL</b>	1996-98
M62 B35 (358S1)	173 235
Ignition Coil M 62 B (35 8 S1)	<b>80216</b>
<b>7 (E38) 740 i,iL</b>	1994-01
M60 B40 (408S1)	210 286
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>7 (E38) 740 i,iL</b>	1996-01
M62 B44 (448S2)/M62 B44 (448S1)	210 286
Ignition Coil M 62 B 44	<b>80216</b>
<b>7 (E38) 750 i,iL</b>	1994-01
M73 B54 (54122)/M73 B54 (54121)	240 326
Ignition Coil	<b>80216</b>
<b>7 (E65, E66, E67) 730 i,Li</b>	2003-08
M54 B30 (306S3)	170 231
Ignition Coil	<b>80247</b>
<b>7 (E65, E66, E67) 730 i,Li</b>	2005-08
N52 B30 A	190 258
Ignition Coil 11.2007->	<b>80247</b>
<b>7 (E65, E66, E67) 735 i</b>	2005-09
N62 B40 A	225 306
Ignition Coil	<b>80247</b>
<b>7 (E65, E66, E67) 735 i,Li</b>	2001-05
N62 B36 A	200 272
Ignition Coil	<b>80247</b>
<b>7 (E65, E66, E67) 740 i,Li</b>	2005-08
N62 B40 A	225 306
Ignition Coil	<b>80247</b>
<b>7 (E65, E66, E67) 745 i,Li</b>	2001-08
N62 B44 A	245 333
Ignition Coil	<b>80247</b>
<b>7 (E65, E66, E67) 750 i,Li</b>	2005-08
N62 B48 B	270 367
Ignition Coil	<b>80247</b>
<b>7 (E65, E66, E67) 760 i,Li</b>	2003-08
N73 B60 A	327 445
Ignition Coil	<b>80247</b>
<b>7 (F01, F02, F03, F04) 730 i</b>	2008-15
N52 B30 A/N52 B30 BF	190 258
Ignition Coil ->05.2009	<b>80247</b>
<b>7 (F01, F02, F03, F04) 740 i</b>	2008-15
N54 B30 A	240 326
Ignition Coil ->06.2012	<b>80247</b>
<b>7 (F01, F02, F03, F04) 750 i</b>	2008-15
N63 B44 A	300 408
Ignition Coil ->06.2012	<b>80247</b>
<b>7 (F01, F02, F03, F04) 750 i</b>	2012-15
N63 B44 B	330 449
Ignition Coil	<b>80247</b>
<b>7 (F01, F02, F03, F04) 750 i xDrive</b>	2009-15
N63 B44 A/N63 B44 B	300 408
Ignition Coil N63 B44 A; ->06.2012	<b>80247</b>
<b>7 (F01, F02, F03, F04) 750 i xDrive</b>	2012-15
N63 B44 B	330 449
Ignition Coil	<b>80247</b>
<b>7 (F01, F02, F03, F04) 760 i</b>	2009-15
N74 B60 A	400 544
Ignition Coil	<b>80247</b>
<b>7 (F01, F02, F03, F04) ActiveHybrid</b>	2009-12
N63 B44 A	330 449
Ignition Coil	<b>80247</b>
<b>7 (F01, F02, F03, F04) ActiveHybrid</b>	2009-12
N63 B44 A	342 465
Ignition Coil	<b>80247</b>
<b>8 (E31) 840 Ci</b>	1996-99
M62 B44 (448S1)	210 286
Ignition Coil M 62 B 44	<b>80216</b>
<b>8 (E31) 840 i</b>	1993-96
M60 B40 (408S1)	210 286
Ignition Coil With regul.cat.(3way)	<b>80215</b>
<b>8 (E31) 850 Ci</b>	1994-99
M73 B54 (54121)	240 326
Ignition Coil	<b>80216</b>



BMW Cont.	
<b>X1 (E84) sDrive 18 i</b>	<b>2009-15</b>
N46 B20 B	100 136
Ignition Coil	<b>80247</b>
<b>X1 (E84) sDrive 18 i</b>	<b>2010-15</b>
N46 B20 B	110 150
Ignition Coil	<b>80247</b>
<b>X1 (E84) xDrive 25 i</b>	<b>2010-15</b>
N52 B30 A	160 218
Ignition Coil	<b>80247</b>
<b>X1 (E84) xDrive 28 i</b>	<b>2009-15</b>
N52 B30 A	190 258
Ignition Coil	<b>80247</b>
<b>X3 (E83) 2.0 i</b>	<b>2005-08</b>
N46 B20 B	110 150
Ignition Coil	<b>80247</b>
<b>X3 (E83) 2.5 i</b>	<b>2004-06</b>
M54 B25 (256S5)	141 192
Ignition Coil	<b>80247</b>
<b>X3 (E83) 2.5 si</b>	<b>2006-08</b>
N52 B25 A	160 218
Ignition Coil	<b>80247</b>
<b>X3 (E83) 3.0 i xDrive</b>	<b>2004-06</b>
M54 B30 (306S3)	170 231
Ignition Coil	<b>80247</b>
<b>X3 (E83) 3.0 si</b>	<b>2006-08</b>
N52 B30 A	200 272
Ignition Coil	<b>80247</b>
<b>X3 (E83) xDrive 20 i</b>	<b>2008-11</b>
N46 B20 B	110 150
Ignition Coil	<b>80247</b>
<b>X3 (E83) xDrive 25 i</b>	<b>2008-11</b>
N52 B25 A	160 218
Ignition Coil	<b>80247</b>
<b>X3 (E83) xDrive 30 i</b>	<b>2008-11</b>
N52 B30 A	200 272
Ignition Coil	<b>80247</b>
<b>X3 (F25) xDrive 20 i</b>	<b>2011-&gt;</b>
N20 B20 A	135 184
Ignition Coil	<b>80247</b>
<b>X3 (F25) xDrive 28 i</b>	<b>2011-&gt;</b>
N52 B30 A	190 258
Ignition Coil	<b>80247</b>
<b>X5 (E53) 3.0 i</b>	<b>2000-06</b>
M54 B30 (306S3)	163 222
Ignition Coil ->10.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>X5 (E53) 3.0 i</b>	<b>2000-06</b>
M54 B30 (306S3)	170 231
Ignition Coil ->10.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>X5 (E53) 4.4 i</b>	<b>2000-03</b>
M62 B44 (448S2)	210 286
Ignition Coil With regul.cat.(3way)	<b>80216</b>
<b>X5 (E53) 4.4 i</b>	<b>2003-06</b>
N62 B44/N62 B44 A	235 320
Ignition Coil N62 B44 A	<b>80247</b>
<b>X5 (E53) 4.6 is</b>	<b>2002-03</b>
M62 B46 (468S1)	255 347
Ignition Coil M67468S1	<b>80216</b>
<b>X5 (E53) 4.8 is</b>	<b>2004-06</b>
N62 B48 A	265 360
Ignition Coil	<b>80247</b>
<b>X5 (E70) 3.0 si</b>	<b>2006-08</b>
N52 B30 A/N52 B30 BF/N52 B30 B/N52 B30 AF	200 272
Ignition Coil	<b>80247</b>
<b>X5 (E70) 4.8 i xDrive</b>	<b>2007-08</b>
N62 B48 B	261 355
Ignition Coil	<b>80247</b>
<b>X5 (E70) M</b>	<b>2009-13</b>
S63 B44 A	408 555
Ignition Coil	<b>80247</b>
<b>X5 (E70) xDrive 30 i</b>	<b>2008-10</b>
N52 B30 A	200 272
Ignition Coil	<b>80247</b>
<b>X5 (E70) xDrive 48 i</b>	<b>2008-13</b>
N62 B48 B	261 355
Ignition Coil	<b>80247</b>

BMW Cont.	
<b>X5 (E70) xDrive 50 i</b>	<b>2010-13</b>
N63 B44 A	300 408
Ignition Coil	<b>80247</b>
<b>X5 (F15, F85) M</b>	<b>2014-&gt;</b>
S63 B44 B	423 575
Ignition Coil ->12.2015	<b>80247</b>
<b>X5 (F15, F85) xDrive 50 i</b>	<b>2013-&gt;</b>
N63 B44 B	330 449
Ignition Coil ->11.2013	<b>80247</b>
<b>X6 (E71, E72) ActiveHybrid</b>	<b>2010-&gt;</b>
N63 B44 A	300 408
Ignition Coil	<b>80247</b>
<b>X6 (E71, E72) ActiveHybrid</b>	<b>2009-11</b>
N63 B44 A	357 485
Ignition Coil	<b>80247</b>
<b>X6 (E71, E72) M</b>	<b>2008-14</b>
S63 B44 A	408 555
Ignition Coil	<b>80247</b>
<b>X6 (E71, E72) xDrive 35 i</b>	<b>2007-10</b>
N55 B30 A/N54 B30 A	225 306
Ignition Coil	<b>80247</b>
<b>X6 (E71, E72) xDrive 50 i</b>	<b>2007-14</b>
N63 B44 A	300 408
Ignition Coil	<b>80247</b>
<b>X6 (F16, F86) M</b>	<b>2014-&gt;</b>
S63 B44 B	423 575
Ignition Coil ->12.2015	<b>80247</b>
<b>X6 (F16, F86) xDrive 50 i</b>	<b>2014-&gt;</b>
N63 B44 B	330 450
Ignition Coil ->11.2015	<b>80247</b>
<b>Z3 (E36) 1.8</b>	<b>1995-98</b>
M43 B18 (184E2)	85 116
Ignition Leads	<b>85950</b>
Ignition Leads SAE	<b>85955</b>
<b>Z3 (E36) 1.9</b>	<b>1998-03</b>
M43 B19 (194E1)	87 118
Ignition Leads ->09.2002	<b>85950</b>
Ignition Leads M43 B19/ M43 194 E1	<b>85955</b>
<b>Z3 (E36) 1.9</b>	<b>1999-03</b>
M43 B19 (194E1)	85 116
Ignition Leads ->09.2002	<b>85950</b>
Ignition Leads SAE	<b>85955</b>
<b>Z3 (E36) 1.9</b>	<b>1995-99</b>
M44 B19 (194S1)	103 140
Ignition Leads	<b>85940</b>
Ignition Leads SAE	<b>85945</b>
<b>Z3 (E36) 2.0</b>	<b>1999-03</b>
M52 B20 (206S4)	110 150
Ignition Coil M 52 B (20 6 S4)	<b>80216</b>
<b>Z3 (E36) 2.2</b>	<b>2000-03</b>
M54 B22 (226S1)	125 170
Ignition Coil ->09.2002	<b>80216</b>
<b>Z3 (E36) 2.8</b>	<b>1997-00</b>
M52 B28 (286S1)	141 192
Ignition Coil M 52 B 28	<b>80216</b>
<b>Z3 (E36) 3.0</b>	<b>2000-03</b>
M54 B30 (306S3)	170 231
Ignition Coil M54306S3	<b>80216</b>
<b>Z3 (E36) M 3.2</b>	<b>2001-03</b>
S54 B32 (326S4)	239 325
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>Z3 (E36) M 3.2</b>	<b>1997-01</b>
S50 B32 (326S1)	236 321
Ignition Coil S 50 B 32	<b>80216</b>
<b>Z3 Coupe (E36) 2.8</b>	<b>1997-00</b>
M52 B28 (286S1)	141 192
Ignition Coil M 52 B 28	<b>80216</b>
<b>Z3 Coupe (E36) 3.0</b>	<b>2000-03</b>
M54 B30 (306S3)	170 231
Ignition Coil M54306S3	<b>80216</b>
<b>Z3 Coupe (E36) M</b>	<b>2001-03</b>
S54 B32 (326S4)	239 325
Ignition Coil ->09.2002	<b>80216</b>
Ignition Coil 10.2002->	<b>80247</b>
<b>Z3 Coupe (E36) M</b>	<b>1998-01</b>
S50 B32 (326S1)	236 321
Ignition Coil S 50 B 32	<b>80216</b>



<b>BMW Cont.</b>		
<b>Z4 (E85) 2.0 i</b>	<b>2005-09</b>	
N46 B20 B/N46 B20 A	110 150	
Ignition Coil	<b>80247</b>	
<b>Z4 (E85) 2.2 i</b>	<b>2003-05</b>	
M54 B22 (226S1)	125 170	
Ignition Coil	<b>80247</b>	
<b>Z4 (E85) 2.5 i</b>	<b>2003-05</b>	
M54 B25 (256S5)	141 192	
Ignition Coil	<b>80247</b>	
<b>Z4 (E85) 2.5 i</b>	<b>2005-09</b>	
N52 B25 A	130 177	
Ignition Coil ->05.2006	<b>80247</b>	
<b>Z4 (E85) 2.5 si</b>	<b>2005-09</b>	
N52 B25 A	160 218	
Ignition Coil 05.2006->	<b>80247</b>	
<b>Z4 (E85) 3.0 i</b>	<b>2003-05</b>	
M54 B30 (306S3)	170 231	
Ignition Coil	<b>80247</b>	
<b>Z4 (E85) 3.0 si</b>	<b>2006-08</b>	
N52 B30 A	195 265	
Ignition Coil 05.2006->	<b>80247</b>	
<b>Z4 (E85) M</b>	<b>2006-09</b>	
S54 B32 (326S4)	252 343	
Ignition Coil	<b>80247</b>	
<b>Z4 (E89) sDrive 23 i</b>	<b>2009-&gt;</b>	
N52 B25 A	150 204	
Ignition Coil	<b>80247</b>	
<b>Z4 (E89) sDrive 30 i</b>	<b>2009-&gt;</b>	
N52 B30 A	190 258	
Ignition Coil	<b>80247</b>	
<b>Z4 (E89) sDrive 35 i</b>	<b>2009-&gt;</b>	
N54 B30 A	225 306	
Ignition Coil	<b>80247</b>	
<b>Z4 (E89) sDrive 35 is</b>	<b>2010-&gt;</b>	
N54 B30 A	250 340	
Ignition Coil	<b>80247</b>	
<b>Z4 Coupe (E86) 3.0 si</b>	<b>2006-09</b>	
N52 B30 A	195 265	
Ignition Coil 05.2006->	<b>80247</b>	
<b>Z4 Coupe (E86) M</b>	<b>2006-09</b>	
S54 B32 (326S4)	252 343	
Ignition Coil	<b>80247</b>	
<b>Z8 (E52) 4.9</b>	<b>2000-03</b>	
S62 B50 (508S1)	294 400	
Ignition Coil S38 B49	<b>80216</b>	

<b>CADILLAC</b>		
<b>CTS 2.8</b>	<b>2005-07</b>	
LP1	158 215	
Ignition Coil	<b>80355</b>	
<b>CTS 3.6</b>	<b>2005-07</b>	
LY7	189 257	
Ignition Coil	<b>80355</b>	
<b>CTS 3.6</b>	<b>2008-&gt;</b>	
LLT	229 311	
Ignition Coil	<b>80355</b>	
<b>CTS 3.6 AWD</b>	<b>2008-&gt;</b>	
LLT	229 311	
Ignition Coil	<b>80355</b>	
<b>SRX 3.6</b>	<b>2004-08</b>	
LY7	190 258	
Ignition Coil	<b>80355</b>	
<b>SRX 3.6</b>	<b>2004-08</b>	
LY7	190 258	
Ignition Coil	<b>80355</b>	
<b>STS 3.6</b>	<b>2005-07</b>	
LY7	189 257	
Ignition Coil	<b>80355</b>	

<b>CHEVROLET</b>		
<b>Aveo Fastback (T250, T255) 1.2</b>	<b>2008-&gt;</b>	
LMU/B12D1	62 84	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83566</b>	

<b>CHEVROLET Cont.</b>		
<b>Aveo Fastback (T250, T255) 1.2 LPG</b>	<b>2008-&gt;</b>	
LMU/B12D1	62 84	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83566</b>	
<b>Aveo Fastback (T250, T255) 1.4</b>	<b>2008-&gt;</b>	
LDT/F14D4	74 101	
Ignition Coil ->12.2011	<b>80351</b>	
Ignition Coil ->05.2013	<b>80353</b>	
Ignition Leads	<b>83563</b>	
<b>Aveo Fastback (T300) 1.2</b>	<b>2011-&gt;</b>	
A 12 XEL	51 69	
Ignition Coil	<b>80322</b>	
Ignition Leads	<b>83567</b>	
<b>Aveo Fastback (T300) 1.2</b>	<b>2011-&gt;</b>	
A 12 XER	63 86	
Ignition Coil	<b>80322</b>	
Ignition Leads	<b>83567</b>	
<b>Aveo Fastback (T300) 1.2 LPG</b>	<b>2012-&gt;</b>	
A 12 XER	63 86	
Ignition Coil	<b>80322</b>	
<b>Aveo Fastback (T300) 1.4</b>	<b>2011-&gt;</b>	
A 14 XER	74 101	
Ignition Coil A14XER	<b>80322</b>	
<b>Aveo Fastback (T300) 1.4 Turbo</b>	<b>2013-&gt;</b>	
LUJ/LUV	103 140	
Ignition Coil LUJ	<b>80322</b>	
<b>Aveo Fastback (T300) 1.6</b>	<b>2011-&gt;</b>	
F16D4	85 116	
Ignition Coil F16D4	<b>80321</b>	
<b>Aveo Sedan (T250, T255) 1.2</b>	<b>2008-&gt;</b>	
LMU/B12D1	62 84	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83566</b>	
<b>Aveo Sedan (T250, T255) 1.2</b>	<b>2006-07</b>	
F12S3/B12S1/LY4	53 72	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83566</b>	
<b>Aveo Sedan (T250, T255) 1.2</b>	<b>2008-&gt;</b>	
LMU/B12D1	55 75	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83566</b>	
<b>Aveo Sedan (T250, T255) 1.2 LPG</b>	<b>2009-&gt;</b>	
LMU/B12D1	62 84	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83566</b>	
<b>Aveo Sedan (T250, T255) 1.4</b>	<b>2006-07</b>	
F14D3/L14	69 94	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83562</b>	
Ignition Leads F14D3	<b>83563</b>	
<b>Aveo Sedan (T250, T255) 1.4</b>	<b>2008-&gt;</b>	
F14D4	74 101	
Ignition Coil ->12.2011	<b>80351</b>	
Ignition Coil ->05.2013	<b>80353</b>	
<b>Aveo Sedan (T250, T255) 1.5</b>	<b>2005-&gt;</b>	
F15S3/LX6	62 84	
Ignition Coil	<b>80317</b>	
<b>Aveo Sedan (T300) 1.2</b>	<b>2011-&gt;</b>	
A 12 XER	63 86	
Ignition Coil	<b>80322</b>	
Ignition Leads	<b>83567</b>	
<b>Aveo Sedan (T300) 1.2</b>	<b>2011-&gt;</b>	
A 12 XEL	51 69	
Ignition Coil	<b>80322</b>	
Ignition Leads	<b>83567</b>	
<b>Aveo Sedan (T300) 1.2 LPG</b>	<b>2012-&gt;</b>	
A 12 XER	63 86	
Ignition Coil	<b>80322</b>	
<b>Aveo Sedan (T300) 1.4</b>	<b>2011-&gt;</b>	
A 14 XER	74 100	
Ignition Coil	<b>80322</b>	
<b>Aveo Sedan (T300) 1.6</b>	<b>2011-&gt;</b>	
F16D4	85 116	
Ignition Coil	<b>80321</b>	
<b>Captiva (C100, C140) 2.4</b>	<b>2006-&gt;</b>	
Z 24 SED	100 136	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>85561</b>	



CHEVROLET Cont.	
<b>Captiva (C100, C140) 2.4</b>	2011->
A 24 XE/LE5	123 167
Ignition Coil	<b>80329</b>
<b>Captiva (C100, C140) 2.4 4WD</b>	2006->
Z 24 SED	100 136
Ignition Coil	<b>80317</b>
Ignition Leads	<b>85561</b>
<b>Captiva (C100, C140) 2.4 4WD</b>	2011->
A 24 XE/LE5	123 167
Ignition Coil	<b>80329</b>
<b>Captiva (C100, C140) 2.4 LPG</b>	2007->
Z 24 SED	100 136
Ignition Coil	<b>80317</b>
Ignition Leads	<b>85561</b>
<b>Captiva (C100, C140) 2.4 LPG 4WD</b>	2007->
Z 24 SED	100 136
Ignition Coil	<b>80317</b>
Ignition Leads	<b>85561</b>
<b>Cruze (J300) 1.4</b>	2013->
A 14 XER/LDD	74 101
Ignition Coil	<b>80322</b>
<b>Cruze (J300) 1.6</b>	2009->
F16D4	83 113
Ignition Coil	<b>80317</b>
Ignition Coil ->12.2010	<b>80351</b>
Ignition Coil ->12.2013	<b>80353</b>
Ignition Leads	<b>83563</b>
<b>Cruze (J300) 1.6</b>	2012->
LDE	86 117
Ignition Coil ->12.2013	<b>80353</b>
<b>Cruze (J300) 1.6</b>	2012->
F16D4	89 121
Ignition Coil ->12.2013	<b>80351</b>
<b>Cruze (J300) 1.6</b>	2009->
LDE/F16D4	91 124
Ignition Coil 10.2010-12.2013	<b>80351</b>
Ignition Coil ->12.2013	<b>80353</b>
<b>Cruze (J300) 1.6</b>	2009->
LXV/F16D3/LXT	80 109
Ignition Coil	<b>80317</b>
Ignition Coil LXV; ->12.2013	<b>80353</b>
Ignition Leads ->12.2014	<b>83563</b>
<b>Cruze (J300) 1.8</b>	2009->
2H0/F18D4	104 141
Ignition Coil	<b>80351</b>
Ignition Coil	<b>80353</b>
Ignition Leads	<b>83563</b>
<b>Cruze (J300) 1.8</b>	2009->
LUW/LWE	103 140
Ignition Coil F18D4	<b>80351</b>
<b>Cruze (J300) 1.8 LPG</b>	2011->
2H0/F18D4	104 141
Ignition Coil	<b>80351</b>
Ignition Coil	<b>80353</b>
<b>Cruze Fastback (J305) 1.4</b>	2013->
A 14 XER/LDD	74 101
Ignition Coil	<b>80322</b>
<b>Cruze Fastback (J305) 1.4</b>	2012->
LUJ	103 140
Ignition Coil	<b>80322</b>
<b>Cruze Fastback (J305) 1.6</b>	2011->
F16D4	91 124
Ignition Coil 07.2011-12.2013	<b>80351</b>
Ignition Coil ->12.2013	<b>80353</b>
<b>Cruze Fastback (J305) 1.6</b>	2012->
F16D4	86 117
Ignition Coil ->12.2013	<b>80353</b>
<b>Cruze Fastback (J305) 1.6</b>	2012->
F16D4	89 121
Ignition Coil ->12.2013	<b>80351</b>
<b>Cruze Fastback (J305) 1.8</b>	2011->
F18D4	103 140
Ignition Coil	<b>80351</b>
<b>Cruze Fastback (J305) 1.8</b>	2011->
F18D4	104 141
Ignition Coil 07.2011->	<b>80351</b>
Ignition Coil	<b>80353</b>

CHEVROLET Cont.	
<b>Cruze Fastback (J305) 1.8 LPG</b>	2011->
F18D4	104 141
Ignition Coil 07.2011->	<b>80351</b>
Ignition Coil	<b>80353</b>
<b>Cruze Station Wagon (J308) 1.4</b>	2013->
A 14 XER/LDD	74 101
Ignition Coil	<b>80322</b>
<b>Cruze Station Wagon (J308) 1.4</b>	2012->
LUJ	103 140
Ignition Coil	<b>80322</b>
<b>Cruze Station Wagon (J308) 1.6</b>	2012->
LDE	91 124
Ignition Coil ->12.2013	<b>80351</b>
Ignition Coil ->12.2013	<b>80353</b>
<b>Cruze Station Wagon (J308) 1.6</b>	2012->
F16D4	89 121
Ignition Coil ->12.2013	<b>80351</b>
<b>Cruze Station Wagon (J308) 1.6</b>	2012->
LDE	86 117
Ignition Coil ->12.2013	<b>80353</b>
<b>Cruze Station Wagon (J308) 1.8</b>	2012->
2H0	104 141
Ignition Coil	<b>80351</b>
Ignition Coil	<b>80353</b>
<b>Epica (K11) 2.0</b>	2006->
X 20 D1	105 144
Ignition Coil	<b>80357</b>
<b>Epica (K11) 2.5</b>	2006->
LF4	115 156
Ignition Coil	<b>80357</b>
<b>Evanda 2.0</b>	2005->
X 20 SED	96 131
Ignition Coil	<b>80317</b>
<b>Kalos 1.2</b>	2005->
B12S1	53 72
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83566</b>
<b>Kalos 1.4</b>	2005->
F14S3	61 83
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83562</b>
Ignition Leads	<b>83563</b>
<b>Kalos 1.4 16V</b>	2005->
F14D3	69 94
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83563</b>
<b>Kalos Sedan 1.2</b>	2005->
F12S3	53 72
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83566</b>
<b>Kalos Sedan 1.4</b>	2005->
F14S3	61 83
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83562</b>
<b>Kalos Sedan 1.4 16V</b>	2005->
F14D3	69 94
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83563</b>
<b>Lacetti (J200) 1.4 16V</b>	2005->
F14D3	70 95
Ignition Leads	<b>83562</b>
Ignition Leads F14D3	<b>83564</b>
<b>Lacetti (J200) 1.6</b>	2005->
F16D3	80 109
Ignition Leads F16D3	<b>83564</b>
<b>Lacetti (J200) 1.8</b>	2005->
T18SED	90 122
Ignition Coil	<b>80317</b>
<b>Lacetti (J200) 1.8</b>	2005->
F18D3	89 121
Ignition Coil ->02.2006	<b>80317</b>
<b>Malibu (V300) 2.4</b>	2012->
LE9	123 167
Ignition Coil	<b>80329</b>
<b>Malibu (V300) 2.4</b>	2012->
LE9	125 170
Ignition Coil	<b>80329</b>





CHEVROLET Cont.		
<b>Matiz (M200, M250) 0.8</b>	2005->	
F8CV	38	52
Ignition Leads ->Ch.577030	<b>83561</b>	
Ignition Leads SAE; Ch.577031->	<b>83565</b>	
<b>Matiz (M200, M250) 0.8 LPG</b>	2005->	
F8CV	38	52
Ignition Leads	<b>83561</b>	
<b>Matiz (M200, M250) 1.0</b>	2005->	
B10S	47	64
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83566</b>	
<b>Matiz (M200, M250) 1.0</b>	2005->	
B10S1	49	67
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83566</b>	
<b>Matiz (M200, M250) 1.0 LPG</b>	2005->	
B10S1	49	67
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83566</b>	
<b>Niva 1.7 4x4</b>	2002->	
	59	80
Ignition Coil	<b>80358</b>	
<b>Nubira Kombi 1.6</b>	2005->	
F16D3	80	109
Ignition Leads	<b>83564</b>	
<b>Nubira Kombi 1.8</b>	2005->	
T18SED	90	122
Ignition Coil	<b>80317</b>	
<b>Nubira Sedan 1.6</b>	2005->	
F16D3	80	109
Ignition Leads	<b>83564</b>	
<b>Nubira Sedan 1.8</b>	2005->	
T18SED	90	122
Ignition Coil	<b>80317</b>	
<b>Orlando (J309) 1.4</b>	2012->	
LUJ	103	140
Ignition Coil	<b>80322</b>	
<b>Orlando (J309) 1.8</b>	2011->	
2H0/F18D4	104	141
Ignition Coil	<b>80351</b>	
Ignition Coil	<b>80353</b>	
<b>Orlando (J309) 1.8 LPG</b>	2011->	
2H0	104	141
Ignition Coil	<b>80351</b>	
Ignition Coil	<b>80353</b>	
<b>Spark (M300) 1.0</b>	2010->	
B10D1	50	68
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83567</b>	
<b>Spark (M300) 1.2</b>	2010->	
LMU/B12D1	60	82
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83567</b>	
<b>Spark 0.8</b>	2005->	
F8CV	37	50
Ignition Leads	<b>83561</b>	
<b>Spark 1.0 SX</b>	2005->	
LA2/B10S	46	63
Ignition Leads	<b>83566</b>	
<b>Tacuma 1.6</b>	2005->	
A16DMS	77	105
Ignition Coil	<b>80317</b>	
Ignition Coil	<b>80318</b>	
Ignition Leads	<b>83563</b>	
<b>Tacuma 1.6</b>	2005->	
A16DMS	79	107
Ignition Coil	<b>80317</b>	
Ignition Coil	<b>80318</b>	
Ignition Leads	<b>83563</b>	
<b>Tacuma 2.0</b>	2005->	
T20SED	89	121
Ignition Coil	<b>80317</b>	
<b>Tacuma 2.0</b>	2005->	
T20SED	90	122
Ignition Coil	<b>80317</b>	
<b>Trax 1.4</b>	2012->	
LUJ/LUV	103	140
Ignition Coil	<b>80322</b>	

CHEVROLET Cont.		
<b>Trax 1.4 AWD</b>	2012->	
LUJ	103	140
Ignition Coil	<b>80322</b>	
<b>Trax 1.6</b>	2012->	
LDE/F16D4	85	116
Ignition Coil	<b>80352</b>	
<b>Trax 1.8</b>	2013->	
2H0/F18D4	103	140
Ignition Coil	<b>80321</b>	
<b>Vectra 2.2</b>	2002-04	
Z 22 SE	108	147
Ignition Coil	<b>80269</b>	
<b>Vectra 2.2</b>	2005-06	
Z 22 YH	114	155
Ignition Coil	<b>80269</b>	
<b>Volt EV 150</b>	2011->	
LUU	111	151
Ignition Coil	<b>80322</b>	
<b>Zafira 2.2</b>	2005->	
Z 22 YH	110	150
Ignition Coil	<b>80269</b>	
CHRYSLER		
<b>Cirrus 2.0 LX</b>	1994-97	
ECB	96	131
Ignition Coil	<b>80295</b>	
Ignition Coil	<b>80296</b>	
<b>Cirrus 2.0 LX</b>	1997-00	
ECB	98	133
Ignition Coil	<b>80295</b>	
Ignition Coil	<b>80296</b>	
<b>Crossfire 3.2</b>	2003-08	
EGX	160	218
Ignition Coil	<b>80294</b>	
Ignition Leads	<b>85053</b>	
<b>Crossfire Roadster 3.2</b>	2004-08	
EGX	160	218
Ignition Coil	<b>80294</b>	
Ignition Leads	<b>85053</b>	
<b>Crossfire Roadster SRT-6</b>	2004-06	
EGZ	246	335
Ignition Coil	<b>80294</b>	
Ignition Leads	<b>85053</b>	
<b>Crossfire SRT-6</b>	2004-07	
EGZ	246	335
Ignition Coil	<b>80294</b>	
Ignition Leads	<b>85053</b>	
<b>Daytona Coupe 2.2 i Turbo</b>	1986-90	
EDR	130	177
Ignition Coil	<b>80362</b>	
<b>Daytona Coupe 2.5 i Turbo</b>	1989-92	
EDT	110	150
Ignition Coil	<b>80362</b>	
<b>Neon (PI) 1.8 16V</b>	1997-99	
EBD	85	116
Ignition Leads	<b>83981</b>	
<b>Neon (PI) 2.0 16V</b>	1994-99	
420H	98	133
Ignition Coil	<b>80295</b>	
Ignition Coil	<b>80296</b>	
Ignition Leads 420H	<b>83981</b>	
<b>Neon (PI) 2.0 16V</b>	1994-99	
ECC	107	145
Ignition Coil	<b>80296</b>	
Ignition Leads	<b>83981</b>	
Ignition Leads ECC	<b>83982</b>	
<b>Neon (PI) 2.0 16V</b>	1996-99	
420T	109	148
Ignition Coil	<b>80296</b>	
Ignition Leads	<b>83981</b>	
Ignition Leads 420T	<b>83982</b>	
<b>Neon II 1.6</b>	2001-06	
EJD	85	116
Ignition Coil	<b>80296</b>	
Ignition Leads EJD	<b>83985</b>	
<b>Neon II 1.8</b>	2000-01	
EBD	91	124
Ignition Leads	<b>83981</b>	



CHRYSLER Cont.		
<b>Neon II 2.0 16V</b>		<b>1999-06</b>
420H/ECB		98 133
Ignition Coil	01.2004->	<b>80296</b>
Ignition Leads	09.1999-12.2005	<b>83981</b>
Ignition Leads	420H	<b>83985</b>
<b>Neon II 2.0 16V</b>		<b>2002-06</b>
ECB		97 131
Ignition Coil		<b>80295</b>
Ignition Coil	01.2004->	<b>80296</b>
Ignition Leads	->12.2005	<b>83981</b>
<b>Neon II 2.0 16V R/T</b>		<b>2001-06</b>
ECH		110 150
Ignition Coil		<b>80295</b>
Ignition Coil	01.2004->	<b>80296</b>
Ignition Leads		<b>83981</b>
<b>PT Cruiser (PT) 1.6</b>		<b>2001-10</b>
EJD		85 116
Ignition Coil		<b>80349</b>
Ignition Leads	EJD	<b>83985</b>
<b>PT Cruiser (PT) 2.0</b>		<b>2000-10</b>
ECC		104 141
Ignition Coil		<b>80295</b>
Ignition Coil	01.2004->	<b>80296</b>
Ignition Leads	->12.2005	<b>83984</b>
<b>PT Cruiser (PT) 2.0</b>		<b>2004-10</b>
ECC		100 136
Ignition Coil		<b>80295</b>
Ignition Coil		<b>80296</b>
Ignition Leads	->12.2005	<b>83984</b>
<b>PT Cruiser (PT) 2.4</b>		<b>2000-10</b>
EDZ		110 150
Ignition Coil		<b>80295</b>
Ignition Coil	01.2004->	<b>80296</b>
Ignition Leads		<b>83984</b>
<b>PT Cruiser (PT) 2.4</b>		<b>2005-10</b>
EDZ		105 143
Ignition Coil		<b>80295</b>
Ignition Coil		<b>80296</b>
Ignition Leads	EDZ	<b>83984</b>
<b>PT Cruiser (PT) GT 2.4</b>		<b>2003-10</b>
EDV		164 223
Ignition Coil	01.2004->	<b>80296</b>
Ignition Leads		<b>83984</b>
<b>PT Cruiser Cabriolet 2.4</b>		<b>2004-08</b>
EDZ		105 143
Ignition Coil		<b>80295</b>
Ignition Coil		<b>80296</b>
Ignition Leads		<b>83984</b>
<b>PT Cruiser Cabriolet 2.4 GT</b>		<b>2004-08</b>
EDV		164 223
Ignition Coil		<b>80296</b>
Ignition Leads		<b>83984</b>
<b>Sebring (JR) 2.0</b>		<b>2001-07</b>
ECC		104 141
Ignition Coil		<b>80295</b>
<b>Sebring (JR) 2.4</b>		<b>2001-07</b>
EDZ		105 143
Ignition Coil	->12.2006	<b>80296</b>
Ignition Coil	->12.2005	<b>80346</b>
<b>Sebring (JR) 2.4</b>		<b>2001-07</b>
EDZ		112 152
Ignition Coil	->12.2006	<b>80296</b>
Ignition Coil	->12.2005	<b>80346</b>
Ignition Leads	EDZ	<b>83984</b>
<b>Sebring (JR) 2.4 Turbo</b>		<b>2001-07</b>
EDV		164 223
Ignition Coil	->12.2005	<b>80346</b>
<b>Sebring Cabriolet (JR) 2.0</b>		<b>2001-07</b>
ECC		104 141
Ignition Leads	ECC	<b>83984</b>
<b>Sebring Cabriolet (JR) 2.4</b>		<b>2001-07</b>
EDZ		112 152
Ignition Coil	->12.2006	<b>80296</b>
Ignition Coil	->12.2005	<b>80346</b>
Ignition Leads	EDZ	<b>83984</b>
<b>Sebring Cabriolet (JR) 2.4 Turbo</b>		<b>2001-07</b>
EDV		164 223
Ignition Coil	->12.2005	<b>80346</b>

CHRYSLER Cont.		
<b>Stratus (Ja) 2.0 16V</b>		<b>1995-01</b>
ECB		98 133
Ignition Coil		<b>80295</b>
Ignition Coil		<b>80296</b>
Ignition Leads		<b>83981</b>
<b>Stratus (Ja) 2.0 LE</b>		<b>1995-01</b>
C00		96 131
Ignition Coil		<b>80295</b>
Ignition Leads		<b>83981</b>
<b>Stratus (Ja) 2.4 16 V</b>		<b>1995-01</b>
EDZ		103 140
Ignition Leads		<b>83981</b>
Ignition Leads	EDZ	<b>83982</b>
<b>Stratus (Ja) 2.4 16V</b>		<b>1995-01</b>
EDZ		112 152
Ignition Coil		<b>80296</b>
Ignition Leads		<b>83981</b>
Ignition Leads	EDZ	<b>83982</b>
<b>Stratus Cabriolet (JX) 2.0 LE</b>		<b>1996-01</b>
420X		96 131
Ignition Coil		<b>80295</b>
Ignition Leads	->12.1999	<b>83981</b>
<b>Voyager I (AS) 3.3</b>		<b>1989-90</b>
EGA		112 152
Ignition Leads		<b>86020</b>
<b>Voyager II (ES) 2.5 i</b>		<b>1990-95</b>
K		74 101
Ignition Coil		<b>80362</b>
<b>Voyager II (ES) 3.3 i</b>		<b>1990-95</b>
EGA		110 150
Ignition Leads		<b>86020</b>
<b>Voyager II (ES) 3.3 i</b>		<b>1990-95</b>
EGA		120 163
Ignition Leads		<b>86020</b>
<b>Voyager II (ES) 3.3 i AWD</b>		<b>1990-95</b>
EGA		110 150
Ignition Leads		<b>86020</b>
<b>Voyager III (GS) 2.0 i</b>		<b>1995-01</b>
C00		98 133
Ignition Coil		<b>80295</b>
Ignition Leads		<b>83981</b>
<b>Voyager III (GS) 2.4 AWD</b>		<b>1997-01</b>
EDZ		111 151
Ignition Coil		<b>80295</b>
Ignition Leads		<b>83982</b>
<b>Voyager III (GS) 2.4 i</b>		<b>1995-01</b>
B00		111 151
Ignition Coil		<b>80295</b>
Ignition Coil	01.1997->	<b>80296</b>
Ignition Leads	->12.2000	<b>83981</b>
Ignition Leads		<b>83982</b>
<b>Voyager III (GS) 3.3 i</b>		<b>1995-01</b>
R00		116 158
Ignition Leads	01.2000->	<b>83986</b>
Ignition Leads		<b>86020</b>
<b>Voyager IV (RG, RS) 2.4</b>		<b>2000-08</b>
EDZ		108 147
Ignition Coil		<b>80295</b>
Ignition Coil	01.2004->	<b>80296</b>
Ignition Leads	->12.2002	<b>83981</b>
Ignition Leads	01.2003-12.2007	<b>83984</b>
<b>Voyager IV (RG, RS) 3.3</b>		<b>2000-08</b>
EGA/EGM		128 174
Ignition Leads		<b>83986</b>
<b>Voyager IV (RG, RS) 3.3 AWD</b>		<b>2000-08</b>
EGA		128 174
Ignition Leads		<b>83986</b>
<b>Voyager IV (RG, RS) 3.8</b>		<b>2000-08</b>
EGH		160 218
Ignition Leads		<b>83986</b>
<b>Voyager IV (RG, RS) 3.8 AWD</b>		<b>2000-08</b>
EGH		160 218
Ignition Leads		<b>83986</b>



CITROËN		1987-88
<b>AX (ZA-) 1.3 Sport</b>		70 95
M4A		
Ignition Coil		<b>80263</b>
Ignition Leads		<b>83650</b>
<b>AX (ZA-) 1.4 GTi</b>		<b>1991-92</b>
KFZ (TU3FJ2)		74 100
Ignition Coil		<b>80260</b>
Ignition Coil		<b>80272</b>
Ignition Leads		<b>85600</b>
<b>AX (ZA-) 1.4 GTi</b>		<b>1991-96</b>
KFY (TU3FJ2)		66 90
Ignition Coil		<b>80260</b>
Ignition Coil	07.1994->	<b>80272</b>
Ignition Leads		<b>85600</b>
<b>AX (ZA-) 1.4 GTi</b>		<b>1991-96</b>
KFZ (TU3FJ2)		69 94
Ignition Coil		<b>80260</b>
Ignition Coil	07.1994->	<b>80272</b>
Ignition Leads		<b>85600</b>
<b>AX (ZA-) 10</b>		<b>1986-92</b>
C1A		32 44
Ignition Coil	05.1991->	<b>80260</b>
Ignition Coil		<b>80263</b>
Ignition Leads		<b>83650</b>
<b>AX (ZA-) 10</b>		<b>1986-98</b>
CDY (TU9M)		33 45
Ignition Coil	06.1991-06.1993	<b>80260</b>
Ignition Coil	->12.1990	<b>80263</b>
Ignition Coil	07.1994->	<b>80272</b>
Ignition Leads	->05.1991	<b>83650</b>
Ignition Leads		<b>85600</b>
<b>AX (ZA-) 10</b>		<b>1987-98</b>
CDZ (TU9M)		37 50
Ignition Coil	06.1997->	<b>80226</b>
Ignition Coil	07.1994->	<b>80272</b>
Ignition Leads		<b>83650</b>
Ignition Leads	07.1992->; Without ignition distributor	<b>85600</b>
<b>AX (ZA-) 10 E</b>		<b>1986-88</b>
C3A		30 41
Ignition Coil		<b>80263</b>
Ignition Leads		<b>83650</b>
<b>AX (ZA-) 11</b>		<b>1986-94</b>
H1A/H1B		40 54
Ignition Coil	H1A; Org. 5284->; 05.1991-05.1992	<b>80260</b>
Ignition Coil	->04.1991	<b>80263</b>
Ignition Leads		<b>83650</b>
<b>AX (ZA-) 11</b>		<b>1986-97</b>
HDZ (TU1M)/H1B		44 60
Ignition Coil	05.1991-05.1992	<b>80260</b>
Ignition Coil	10.1989-04.1991	<b>80263</b>
Ignition Coil	07.1994->	<b>80272</b>
Ignition Leads	HDZ (TU1M); ->05.1993	<b>83650</b>
Ignition Leads		<b>85600</b>
<b>AX (ZA-) 11 4x4</b>		<b>1991-92</b>
H1A		40 54
Ignition Coil		<b>80260</b>
Ignition Coil		<b>80263</b>
Ignition Leads		<b>83650</b>
<b>AX (ZA-) 11 KAT</b>		<b>1988-89</b>
HAZ (TU1CP)		40 54
Ignition Coil		<b>80263</b>
Ignition Leads		<b>83650</b>
<b>AX (ZA-) 14</b>		<b>1986-88</b>
KAY (TU3CP)		44 60
Ignition Coil		<b>80263</b>
Ignition Leads		<b>83650</b>
<b>AX (ZA-) 14</b>		<b>1988-92</b>
K2B/K2A		62 85
Ignition Coil	06.1991->	<b>80260</b>
Ignition Coil	->06.1991	<b>80263</b>
Ignition Leads		<b>83650</b>
<b>AX (ZA-) 14</b>		<b>1988-89</b>
K1F		49 67
Ignition Coil		<b>80263</b>
Ignition Leads		<b>83650</b>

CITROËN Cont.		1987-97
<b>AX (ZA-) 14</b>		55 75
KDY (TU3FM)/KDZ (TU3M/Z)/KDX (TU3M/Z)/KDY (TU3M)		
Ignition Coil	05.1991-06.1994	<b>80260</b>
Ignition Coil	06.1988-04.1991	<b>80263</b>
Ignition Coil	07.1994-12.1996	<b>80272</b>
Ignition Leads	KDX (TU3M/Z); KDZ (TU3M/Z); KDY (TU3FM)	<b>83650</b>
Ignition Leads		<b>85600</b>
<b>AX (ZA-) 14 4x4</b>		<b>1991-96</b>
KDY (TU3FM)/KDZ (TU3M/Z)/KDX (TU3M/Z)/KDY (TU3M)		55 75
Ignition Coil	KDY; ->06.1993	<b>80260</b>
Ignition Coil		<b>80263</b>
Ignition Coil	KDX; 07.1994->	<b>80272</b>
Ignition Leads		<b>83650</b>
Ignition Leads	KDY/KDX; 12.1992->	<b>85600</b>
<b>Berlingo (B9) 1.6</b>		<b>2008-&gt;</b>
NFR (TU5JP4B)		66 90
Ignition Coil		<b>80235</b>
<b>Berlingo (B9) 1.6</b>		<b>2008-&gt;</b>
NFU (TU5JP4)		80 109
Ignition Coil	TU5JP4	<b>80235</b>
<b>Berlingo (B9) 1.6 VTI 120</b>		<b>2009-&gt;</b>
5FS (EP6C)		88 120
Ignition Coil		<b>80247</b>
<b>Berlingo (B9) 1.6 VTI 95</b>		<b>2010-&gt;</b>
5FK (EP6CB)		72 98
Ignition Coil		<b>80247</b>
<b>Berlingo (MF) 1.1 i</b>		<b>1996-08</b>
HDZ (TU1M)/HFX (TU1JP)		44 60
Ignition Coil	->05.1997	<b>80207</b>
Ignition Coil	SAE; 06.2000->	<b>80208</b>
Ignition Coil	06.1997-05.2000	<b>80226</b>
Ignition Leads		<b>85600</b>
<b>Berlingo (MF) 1.4 bivalent</b>		<b>2002-11</b>
KFW (TU3JP)		48 65
Ignition Coil		<b>80208</b>
<b>Berlingo (MF) 1.4 i</b>		<b>1996-08</b>
KFX (TU3JP)/KFW (TU3JP)		55 75
Ignition Coil		<b>80207</b>
Ignition Coil	With regul.cat.(3way)	<b>80208</b>
Ignition Coil	Hydraulic Brake	<b>80226</b>
Ignition Leads	->Vet. 07874	<b>85600</b>
<b>Berlingo (MF) 1.4 i bivalent</b>		<b>2003-08</b>
KFW (TU3JP)		55 75
Ignition Coil		<b>80208</b>
<b>Berlingo (MF) 1.6 16V</b>		<b>2000-11</b>
NFU (TU5JP4)		80 109
Ignition Coil	NFU (TU5JP4)	<b>80235</b>
<b>Berlingo (MF) 1.8 i</b>		<b>1997-02</b>
LFX (XU7JB)		66 90
Ignition Coil	LFX (XU7JB)	<b>80207</b>
Ignition Leads		<b>85010</b>
<b>Berlingo (MF) 1.8 i 4WD</b>		<b>1997-01</b>
LFX (XU7JB)		66 90
Ignition Coil	LFX (XU7JB)	<b>80207</b>
Ignition Leads		<b>85010</b>
<b>Berlingo Van (B9) 1.6</b>		<b>2008-&gt;</b>
NFR (TU5JP4B)		66 90
Ignition Coil		<b>80235</b>
<b>Berlingo Van (B9) 1.6</b>		<b>2008-&gt;</b>
NFU (TU5JP4)		80 109
Ignition Coil		<b>80235</b>
<b>Berlingo Van (B9) 1.6 VTI 120</b>		<b>2009-&gt;</b>
5FS (EP6C)		88 120
Ignition Coil		<b>80247</b>
<b>Berlingo Van (B9) 1.6 VTI 95</b>		<b>2010-&gt;</b>
5FK (EP6CB)		72 98
Ignition Coil		<b>80247</b>
<b>Berlingo Van (M) 1.1 i</b>		<b>1996-08</b>
HDZ (TU1M)/HFX (TU1JP)		44 60
Ignition Coil	->05.1997	<b>80207</b>
Ignition Coil	SAE; 06.2000->	<b>80208</b>
Ignition Coil	06.1997-05.2000	<b>80226</b>
Ignition Leads		<b>85600</b>
<b>Berlingo Van (M) 1.4 bivalent</b>		<b>2002-11</b>
KFW (TU3JP)		48 65
Ignition Coil		<b>80208</b>

**CITROËN Cont.**

<b>Berlingo Van (M) 1.4 i</b>	<b>1996-11</b>
KFX (TU3JP)/KFW (TU3JP)	55 75
Ignition Coil	<b>80207</b>
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
Ignition Leads	<b>85600</b>
<b>Berlingo Van (M) 1.4 i bivalent</b>	<b>2003-05</b>
KFW (TU3JP)	55 75
Ignition Coil	<b>80208</b>
<b>Berlingo Van (M) 1.6 16V</b>	<b>2000-08</b>
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>Berlingo Van (M) 1.8 i</b>	<b>1999-02</b>
LFX (XU7JB)	66 90
Ignition Coil LFX (XU7JB)	<b>80207</b>
Ignition Leads	<b>85010</b>
<b>BX (XB-) 1.8 D</b>	<b>1985-93</b>
161 (XUD7)	44 60
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 11</b>	<b>1988-92</b>
HDZ (TU1M)	40 55
Ignition Coil	<b>80263</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 11</b>	<b>1986-92</b>
H1A	42 57
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 14</b>	<b>1989-93</b>
KDZ (TU3M/Z)/KDY (TU3M)	55 75
Ignition Coil	<b>80263</b>
Ignition Leads Vet. 04206->	<b>83650</b>
Ignition Leads KDY (TU3M); 12.1992->	<b>85600</b>
<b>BX (XB-) 14</b>	<b>1989-89</b>
K1H (TU3A)	47 64
Ignition Coil	<b>80263</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 14 E</b>	<b>1982-88</b>
150A	45 61
Ignition Coil	<b>80263</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 14 E</b>	<b>1985-93</b>
150F	49 67
Ignition Coil	<b>80263</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 14 E</b>	<b>1983-89</b>
150C/K1G	52 71
Ignition Coil	<b>80263</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 14 E</b>	<b>1983-93</b>
150C	53 72
Ignition Coil	<b>80263</b>
Ignition Leads ->03.1988	<b>83380</b>
Ignition Leads Vet. 04193->	<b>83650</b>
<b>BX (XB-) 14 E</b>	<b>1985-89</b>
Ignition Leads Vet. 04206->	59 80
<b>BX (XB-) 15</b>	<b>1987-92</b>
B1E (XU51C)	59 80
Ignition Leads 05.1988->	<b>83320</b>
<b>BX (XB-) 16</b>	<b>1987-93</b>
B1E (XU51C)	53 72
Ignition Leads 05.1988->	<b>83320</b>
<b>BX (XB-) 16</b>	<b>1985-93</b>
171D	64 87
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83320</b>
<b>BX (XB-) 16</b>	<b>1982-88</b>
171B/171A/171C	66 90
Ignition Coil	<b>80207</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) 16</b>	<b>1982-92</b>
XU52C	68 92
Ignition Coil	<b>80207</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) 16</b>	<b>1986-93</b>
180Z	76 103
Ignition Coil	<b>80207</b>
Ignition Coil 12.1989->	<b>80263</b>

**CITROËN Cont.**

<b>BX (XB-) 16</b>	<b>1987-93</b>
B1A (XU51C/K)	58 79
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 16</b>	<b>1988-93</b>
BAZ (XU5CP)/BAY (XU5CP)	55 75
Ignition Coil	<b>80263</b>
<b>BX (XB-) 16 E</b>	<b>1989-93</b>
BDY (XU5M)/BDZ (XU5M)	65 88
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83320</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) 19</b>	<b>1986-89</b>
D2A (XU92C)	77 105
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 19</b>	<b>1986-89</b>
D2C (XU92C)	70 95
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) 19</b>	<b>1986-89</b>
159A	75 102
Ignition Coil	<b>80207</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 19 D</b>	<b>1983-93</b>
DJZ (XUD9Y)/D9A (XUD9)/162 (XUD9)	47 64
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 19 D</b>	<b>1987-93</b>
D9B (XUD9A/U)	51 69
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 19 E</b>	<b>1988-93</b>
DDZ (XU9M)	80 109
Ignition Coil	<b>80207</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) 19 E 4x4</b>	<b>1989-93</b>
D2F	80 109
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83320</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) 19 GTi</b>	<b>1988-93</b>
DKZ (XU9JA)	88 120
Ignition Coil DKZ (XU9JA)	<b>80207</b>
Ignition Coil Org. 4984->; 06.1990->	<b>80263</b>
Ignition Leads	<b>83320</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) 19 GTi</b>	<b>1986-93</b>
D6A (XU9J2)	90 122
Ignition Coil D6A (XU9J2)	<b>80207</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) 19 GTi 16V</b>	<b>1988-93</b>
DFW (XU9J4)	108 147
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX (XB-) 19 GTi 16V</b>	<b>1987-88</b>
D6C (XU9J4)	116 158
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) 19 GTi 4x4</b>	<b>1988-93</b>
DKZ (XU9JA)	88 120
Ignition Coil DKZ (XU9JA)	<b>80207</b>
Ignition Coil Org. 4984->; 06.1990->	<b>80263</b>
Ignition Leads	<b>83320</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX (XB-) TRD Turbo</b>	<b>1988-93</b>
AJZ (XUD7TE)/A8A (XUD7TE)	66 90
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 1.4</b>	<b>1987-92</b>
Ignition Coil	44 60
<b>BX Break (XB-) 1.4</b>	<b>80263</b>
150C	52 71
Ignition Coil	<b>80263</b>
<b>BX Break (XB-) 14</b>	<b>1989-89</b>
K1H (TU3A)	47 64
Ignition Coil	<b>80263</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 14</b>	<b>1986-93</b>
150C	53 72
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 14</b>	<b>1989-93</b>
KDY (TU3M)	55 75
Ignition Coil	<b>80263</b>
Ignition Leads Vet. 04206->	<b>83650</b>
Ignition Leads 12.1992->	<b>85600</b>



CITROËN Cont.	
<b>BX Break (XB-) 15</b>	1987-92
B1E (XU51C)	59 80
Ignition Leads	<b>83320</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 16</b>	1985-88
171B/171A/171C	66 90
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX Break (XB-) 16</b>	1988-94
B1E (XU51C)	53 72
Ignition Leads	<b>83320</b>
Ignition Leads	<b>83380</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 16</b>	1985-94
171D	64 87
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83320</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX Break (XB-) 16</b>	1986-94
180Z	76 103
Ignition Coil	<b>80207</b>
Ignition Coil 12.1989->	<b>80263</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX Break (XB-) 16</b>	1989-94
BDY (XU5M)/BDZ (XU5M)	65 88
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83320</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 16</b>	1988-94
BAZ (XU5CP)/BAY (XU5CP)	55 75
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 18 D</b>	1985-93
161A (XUD7)	44 60
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 19</b>	1986-94
D2A (XU92C)	75 102
Ignition Coil	<b>80207</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 19</b>	1988-94
DKZ (XU9JA)	88 120
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83320</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX Break (XB-) 19</b>	1988-94
DDZ (XU9M)	80 109
Ignition Coil	<b>80207</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 19</b>	1987-89
D2C (XU92C)	70 95
Ignition Leads	<b>83380</b>
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 19 4x4</b>	1990-91
DDZ (XU9M)	80 109
Ignition Coil	<b>80207</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX Break (XB-) 19 D</b>	1983-94
DJZ (XUD9Y)/D9A (XUD9)/162 (XUD9)	47 64
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 19 D</b>	1987-94
D9B (XUD9A/U)	51 69
Ignition Leads Vet. 04206->	<b>83650</b>
<b>BX Break (XB-) 19 KAT</b>	1986-94
DFZ (XU9J1)	75 102
Ignition Coil DFZ (XU9J1)	<b>80207</b>
Ignition Coil Org. 4984->; 06.1990->	<b>80263</b>
Ignition Leads ->Vet. 04740	<b>83380</b>
<b>BX Break (XB-) TRD Turbo</b>	1988-94
AJZ (XUD7TE)/A8A (XUD7TE)	66 90
Ignition Leads Vet. 04206->	<b>83650</b>
<b>C1 (PM, PN) 1.0</b>	2005->
1KR-FE	50 68
Ignition Coil	<b>80282</b>
<b>C1 II 1.0 VTi 68</b>	2014->
1KR-FE	51 69
Ignition Coil	<b>80282</b>
<b>C1 II 1.2 VTi 82</b>	2014->
HMT (EB2D)	60 82
Ignition Coil	<b>80273</b>

CITROËN Cont.	
<b>C15 (VD-) 1.0</b>	1984-97
XV8/TU9	33 45
Ignition Coil	<b>80263</b>
Ignition Leads 07.1986->	<b>83650</b>
<b>C15 (VD-) 1.1</b>	1984-96
109K/E1A	35 48
Ignition Coil	<b>80263</b>
Ignition Leads 07.1986->	<b>83650</b>
<b>C15 (VD-) 1.1 i</b>	1988-96
HDZ (TU1M)	44 60
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>
Ignition Leads 12.1992->	<b>85600</b>
<b>C15 (VD-) 1.3</b>	1987-88
G1A	47 64
Ignition Leads	<b>83650</b>
<b>C15 (VD-) 1.4</b>	1987-96
K1H (TU3A)	49 67
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>
<b>C15 (VD-) 1.4 E</b>	1987-96
150D (XY7)	44 60
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>
<b>C15 (VD-) 1.4 E</b>	1987-96
K3A	40 55
Ignition Leads	<b>83650</b>
<b>C15 (VD-) 1.4 i</b>	1991-96
KDY (TU3FM)/KDY (TU3M)	55 75
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>
<b>C15 Break 1.1</b>	1988-92
HDZ (TU1M)	40 54
Ignition Coil 06.1989->	<b>80263</b>
Ignition Leads 06.1989->	<b>83650</b>
<b>C15 Break 1.1</b>	1988-96
HDZ (TU1M)	44 60
Ignition Coil	<b>80263</b>
Ignition Leads 06.1989-12.1992	<b>83650</b>
<b>C15 Break 1.4</b>	1991-96
KDY (TU3M)	55 75
Ignition Coil	<b>80263</b>
<b>C2 (JM) 1.1</b>	2003->
HFX (TU1JP)	44 60
Ignition Coil	<b>80208</b>
<b>C2 (JM) 1.4</b>	2003->
KFV (TU3JP)	54 73
Ignition Coil	<b>80208</b>
<b>C2 (JM) 1.4 16V</b>	2006->
KFU (ET3J4)	65 90
Ignition Coil	<b>80236</b>
<b>C2 (JM) 1.6</b>	2003->
NFU (TU5JP4)	80 109
Ignition Coil SAE; Euro 4	<b>80208</b>
Ignition Coil SAE	<b>80235</b>
<b>C2 (JM) 1.6 VTS</b>	2005->
NFS (TU5JP4S)	90 122
Ignition Coil NFS (TU5JP4S)	<b>80235</b>
<b>C25 Bus (280, 290) 1.8 E</b>	1987-94
169 (XM7T)	51 69
Ignition Leads	<b>85190</b>
<b>C25 Bus (280, 290) 2.0</b>	1991-94
170C (XN1T)	62 84
Ignition Leads	<b>85190</b>
<b>C25 Bus (280, 290) 2.0 E</b>	1981-94
170B (XN1T)/170A (XN1T)	58 79
Ignition Leads 01.1985->	<b>85190</b>
<b>C25 Chassis (280, 290) 2.0</b>	1987-94
170C (XN1T)	62 84
Ignition Leads	<b>85190</b>
<b>C25 Van (280, 290) 2.0</b>	1991-94
170C (XN1T)	62 84
Ignition Leads	<b>85190</b>
<b>C25 Van (280, 290) 2.0 E</b>	1981-94
170B (XN1T)/170A (XN1T)	58 79
Ignition Leads 01.1985->	<b>85190</b>





CITROËN Cont.	
<b>C3 I (FC) 1.1 i</b>	2002->
HFX (TU1A)/HFX (TU1JP)	44 60
Ignition Coil	<b>80208</b>
Ignition Leads	<b>85600</b>
<b>C3 I (FC) 1.4 16V</b>	2003->
KFU (ET3J4)	65 88
Ignition Coil	<b>80236</b>
<b>C3 I (FC) 1.4 i</b>	2002->
KFV (TU3JP)/KFV (TU3A)	54 73
Ignition Coil	<b>80208</b>
<b>C3 I (FC) 1.4 i Bivalent</b>	2002->
KFV (TU3JP)	54 73
Ignition Coil	<b>80208</b>
Ignition Leads	<b>85600</b>
<b>C3 I (FC) 1.6 16V</b>	2002->
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
Ignition Leads	<b>85600</b>
<b>C3 II 1.0 VTI 68</b>	2012->
ZMZ (EBO)	50 68
Ignition Coil	<b>80273</b>
<b>C3 II 1.2 THP 110</b>	2014->
HNZ (EB2DT)	81 110
Ignition Coil	<b>80273</b>
<b>C3 II 1.2 VTI 82</b>	2012->
HMZ (EB2F)	60 82
Ignition Coil	<b>80273</b>
<b>C3 II 1.4 LPG</b>	2013->
8FN (EP3)	70 95
Ignition Coil -->12.2016	<b>80247</b>
<b>C3 II 1.4 VTI 95</b>	2009->
8FP (EP3)	70 95
Ignition Coil	<b>80247</b>
<b>C3 II 1.6 VTI 120</b>	2009->
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>C3 Picasso 1.4 VTI 95</b>	2009->
8FS (EP3)/8FN (EP3)/8FP (EP3)	70 95
Ignition Coil	<b>80247</b>
<b>C3 Picasso 1.4 VTI 95 LPG</b>	2012->
8FN (EP3)	70 95
Ignition Coil	<b>80247</b>
<b>C3 Picasso 1.6 VTI 120</b>	2009->
5FS (EP6C)/5FW (EP6)	88 120
Ignition Coil	<b>80247</b>
<b>C3 Pluriel (HB) 1.4</b>	2003->
KFV (TU3JP)	54 73
Ignition Coil	<b>80208</b>
<b>C3 Pluriel (HB) 1.6</b>	2003->
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
Ignition Leads	<b>85600</b>
<b>C4 Berline 1.6 16V</b>	2006->
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>C4 Berline 2.0 16V</b>	2006->
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>C4 Cactus 1.2 VTI 75</b>	2014->
HMU (EB2D)	55 75
Ignition Coil	<b>80273</b>
<b>C4 Cactus 1.2 VTI 82</b>	2014->
HMZ (EB2F)	60 82
Ignition Coil	<b>80273</b>
<b>C4 Coupe (LA) 1.4 16V</b>	2004-11
KFU (ET3J4)	65 88
Ignition Coil	<b>80236</b>
<b>C4 Coupe (LA) 1.6 16V</b>	2004-11
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
<b>C4 Coupe (LA) 1.6 THP 150</b>	2008-11
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>C4 Coupe (LA) 1.6 VTI 120</b>	2008-11
5FW (EP6)	88 120
Ignition Coil	<b>80247</b>
<b>C4 Coupe (LA) 2.0 16V</b>	2004-07
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>

CITROËN Cont.	
<b>C4 Coupe (LA) 2.0 16V</b>	2004-10
RFK (EW10J4S)	130 177
Ignition Coil	<b>80277</b>
<b>C4 Grand Picasso I (UA) 1.6 16V</b>	2008->
5FT (EP6DT)	103 140
Ignition Coil	<b>80247</b>
<b>C4 Grand Picasso I (UA) 1.6 16V</b>	2008->
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>C4 Grand Picasso I (UA) 1.6 THP 155</b>	2010->
5FV (EP6CDT)	115 156
Ignition Coil	<b>80247</b>
<b>C4 Grand Picasso I (UA) 1.6 VTI 120</b>	2008->
5FW (EP6)	88 120
Ignition Coil	<b>80247</b>
<b>C4 Grand Picasso I (UA) 1.8 i 16V</b>	2006->
6FY (EW7A)	92 125
Ignition Coil	<b>80278</b>
<b>C4 Grand Picasso I (UA) 2.0 i 16V</b>	2006->
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>C4 Grand Picasso II 1.6 VTI 120</b>	2013->
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>C4 I (LC) 1.4 16V</b>	2004-11
KFU (ET3J4)	65 88
Ignition Coil	<b>80236</b>
<b>C4 I (LC) 1.6 16V</b>	2004-11
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
<b>C4 I (LC) 1.6 16V Bio-Flex</b>	2007-08
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>C4 I (LC) 1.6 THP 140</b>	2008-11
5FT (EP6DT)	103 140
Ignition Coil	<b>80247</b>
<b>C4 I (LC) 1.6 THP 150</b>	2008-11
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>C4 I (LC) 1.6 VTI 120</b>	2008-11
5FW (EP6)	88 120
Ignition Coil	<b>80247</b>
<b>C4 I (LC) 2.0 16V</b>	2004-07
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>C4 I (LC) 2.0 16V</b>	2004-11
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>C4 I (LC) 2.0 16V</b>	2004->
RFK (EW10J4S)	130 177
Ignition Coil	<b>80277</b>
<b>C4 II (B7) 1.4 VTI 95</b>	2009->
8FP (EP3)	70 95
Ignition Coil	<b>80247</b>
<b>C4 II (B7) 1.6 THP 155</b>	2009->
5FV (EP6CDT)	115 156
Ignition Coil	<b>80247</b>
<b>C4 II (B7) 1.6 VTI 120</b>	2009->
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>C4 II (B7) 1.6 VTI 120 LPG</b>	2011->
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>C4 Picasso I (UD) 1.6 16V</b>	2008-13
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>C4 Picasso I (UD) 1.6 THP 140</b>	2008-13
5FT (EP6DT)	103 140
Ignition Coil	<b>80247</b>
<b>C4 Picasso I (UD) 1.6 THP 155</b>	2010-13
5FV (EP6CDT)	115 156
Ignition Coil	<b>80247</b>
<b>C4 Picasso I (UD) 1.6 VTI 120</b>	2008-13
5FW (EP6)	88 120
Ignition Coil	<b>80247</b>
<b>C4 Picasso I (UD) 1.8 i 16V</b>	2007-11
6FY (EW7A)	92 125
Ignition Coil	<b>80278</b>



CITROËN Cont.	
<b>C4 Picasso I (UD) 2.0 i 16V</b>	<b>2007-13</b>
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>C4 Picasso II 1.6 VTi 120</b>	<b>2013-&gt;</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>C5 I (DC) 1.8 16V</b>	<b>2001-04</b>
6FZ (EW7J4)	85 115
Ignition Coil	<b>80275</b>
<b>C5 I (DC) 2.0 16V</b>	<b>2001-04</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>C5 I (DC) 2.0 16V HPI</b>	<b>2001-04</b>
RLZ (EW10D)	103 140
Ignition Coil	<b>80275</b>
<b>C5 I (DC) 3.0 V6</b>	<b>2001-04</b>
XFX (ES9J4S)	152 207
Ignition Coil	<b>80309</b>
<b>C5 I Break (DE) 1.8 16V</b>	<b>2001-04</b>
6FZ (EW7J4)	85 115
Ignition Coil	<b>80275</b>
<b>C5 I Break (DE) 2.0 16V</b>	<b>2001-04</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>C5 I Break (DE) 3.0 Carlsson</b>	<b>2003-04</b>
	173 235
Ignition Coil	<b>80309</b>
<b>C5 I Break (DE) 3.0 V6</b>	<b>2001-04</b>
XFX (ES9J4S)	152 207
Ignition Coil	<b>80309</b>
<b>C5 II (RC) 1.8 16V</b>	<b>2004-&gt;</b>
6FZ (EW7J4)	85 116
Ignition Coil	<b>80275</b>
<b>C5 II (RC) 1.8 16V</b>	<b>2005-&gt;</b>
6FY (EW7A)	92 125
Ignition Coil	<b>80278</b>
<b>C5 II (RC) 2.0 16V</b>	<b>2004-&gt;</b>
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>C5 II (RC) 3.0 V6</b>	<b>2004-&gt;</b>
XFU (ES9A)/XFX (ES9J4S)	152 207
Ignition Coil	<b>80309</b>
<b>C5 II Break (RE) 1.8 16V</b>	<b>2004-&gt;</b>
6FZ (EW7J4)	85 116
Ignition Coil	<b>80275</b>
<b>C5 II Break (RE) 1.8 16V</b>	<b>2005-&gt;</b>
6FY (EW7A)	92 125
Ignition Coil	<b>80278</b>
<b>C5 II Break (RE) 2.0 16V</b>	<b>2004-&gt;</b>
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>C5 II Break (RE) 3.0 V6</b>	<b>2004-&gt;</b>
XFU (ES9A)	152 207
Ignition Coil	<b>80309</b>
<b>C5 III (RD) 1.6 THP 155</b>	<b>2009-&gt;</b>
5FV (EP6CDT)	115 156
Ignition Coil	<b>80247</b>
<b>C5 III (RD) 1.6 VTi 120</b>	<b>2010-&gt;</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>C5 III (RD) 1.8 16V</b>	<b>2008-&gt;</b>
6FY (EW7A)	92 125
Ignition Coil	<b>80278</b>
<b>C5 III (RD) 2.0 16V</b>	<b>2008-&gt;</b>
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>C5 III (RD) 3.0 V6</b>	<b>2008-&gt;</b>
XFU (ES9A)	155 211
Ignition Coil	<b>80309</b>
<b>C5 III Break (TD) 1.6 THP 155</b>	<b>2009-&gt;</b>
5FV (EP6CDT)	115 156
Ignition Coil	<b>80247</b>
<b>C5 III Break (TD) 1.6 VTi 120</b>	<b>2010-&gt;</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>C5 III Break (TD) 1.8 16V</b>	<b>2008-&gt;</b>
6FY (EW7A)	92 125
Ignition Coil	<b>80278</b>

CITROËN Cont.	
<b>C5 III Break (TD) 2.0 16V</b>	<b>2008-&gt;</b>
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>C5 III Break (TD) 3.0 V6</b>	<b>2008-&gt;</b>
XFU (ES9A)	155 211
Ignition Coil	<b>80309</b>
<b>C6 (TD) 3.0 V6</b>	<b>2005-&gt;</b>
XFV (ES9A)/XFX (ES9J4S)	155 211
Ignition Coil	<b>80309</b>
<b>C8 (EA, EB) 2.0</b>	<b>2002-&gt;</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>C8 (EA, EB) 2.0 16V</b>	<b>2005-&gt;</b>
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>C8 (EA, EB) 2.2</b>	<b>2002-&gt;</b>
3FZ (EW12J4)	116 158
Ignition Coil	<b>80277</b>
<b>C8 (EA, EB) 3.0 V6</b>	<b>2002-&gt;</b>
XFX (ES9J4S)	150 204
Ignition Coil	<b>80309</b>
<b>C-Crosser (EP) 2.0</b>	<b>2010-&gt;</b>
4B11	108 147
Ignition Coil	<b>80338</b>
<b>C-Crosser (EP) 2.0 4WD</b>	<b>2010-&gt;</b>
4B11	108 147
Ignition Coil	<b>80338</b>
<b>C-Crosser (EP) 2.4 16V</b>	<b>2008-&gt;</b>
SFZ (4B12-MMC)	125 170
Ignition Coil	<b>80338</b>
<b>C-Crosser Enterprise 2.4 16V</b>	<b>2009-&gt;</b>
4B12	125 170
Ignition Coil	<b>80338</b>
<b>C-Elysee 1.2 VTi 72</b>	<b>2012-&gt;</b>
HMY (EB2M)	53 72
Ignition Coil	<b>80273</b>
<b>C-Elysee 1.6 VTi 115</b>	<b>2012-&gt;</b>
NFP (EC5)	85 115
Ignition Coil	<b>80271</b>
<b>DS3 1.2 THP 110</b>	<b>2014-15</b>
HNZ (EB2DT)	81 110
Ignition Coil	<b>80273</b>
<b>DS3 1.2 VTi 82</b>	<b>2013-15</b>
HMZ (EB2F)	60 82
Ignition Coil	<b>80273</b>
<b>DS3 1.4 VTi 95</b>	<b>2010-15</b>
8FP (EP3)	70 95
Ignition Coil	<b>80247</b>
<b>DS3 1.4 VTi 95 LPG</b>	<b>2012-&gt;</b>
8FN (EP3)	70 95
Ignition Coil	<b>80247</b>
<b>DS3 1.4 VTi 98</b>	<b>2009-&gt;</b>
8FR (EP3)	72 98
Ignition Coil	<b>80247</b>
<b>DS3 1.6 THP 155</b>	<b>2010-15</b>
5FV (EP6CDT)/5FR (EP6DT)	115 156
Ignition Coil	<b>80247</b>
<b>DS3 1.6 VTi 120</b>	<b>2010-15</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>DS3 Cabriolet 1.2 THP 110</b>	<b>2014-15</b>
HNZ (EB2DT)	81 110
Ignition Coil	<b>80273</b>
<b>DS3 Cabriolet 1.2 VTi 82</b>	<b>2013-15</b>
HMZ (EB2F)	60 82
Ignition Coil	<b>80273</b>
<b>DS3 Cabriolet 1.6 VTi 120</b>	<b>2013-&gt;</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>DS4 1.6 VTi 120</b>	<b>2011-&gt;</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>Dyane 4</b>	<b>1968-75</b>
A79/1 (AYA2)	17 23
Ignition Leads	<b>83300</b>
<b>Dyane 4</b>	<b>1967-68</b>
A79/0 (AYA)	13 18
Ignition Leads	<b>83300</b>

**CITROËN Cont.**

<b>Dyane 6</b>	<b>1972-80</b>
M28/1 (AK2)	24 33
Ignition Leads	<b>83300</b>
<b>Dyane 6</b>	<b>1968-84</b>
M28 (AM2)	21 29
Ignition Leads	<b>83300</b>
<b>Evasion (22, U6) 1.8</b>	<b>1997-02</b>
LFZ (XU7JP)	73 99
Ignition Coil	<b>80207</b>
Ignition Coil	->12.1997; With regul.cat.(3way)
Ignition Leads	<b>85010</b>
<b>Evasion (22, U6) 2.0</b>	<b>1994-02</b>
RFU (XU10J2/C)	89 121
Ignition Coil RFU (XU10J2/C)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Evasion (22, U6) 2.0 16V</b>	<b>1998-00</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80274</b>
<b>Evasion (22, U6) 2.0 16V</b>	<b>2000-02</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>Evasion (22, U6) 2.0 Turbo C.T.</b>	<b>1994-02</b>
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Jumper Bus (230P) 2.0</b>	<b>1994-02</b>
RFW (XU10J2U)	80 109
Ignition Coil RFW (XU10J2U)	<b>80207</b>
Ignition Leads	<b>85010</b>
<b>Jumper Bus (230P) 2.0 4x4</b>	<b>1996-02</b>
RFW (XU10J2U)	80 109
Ignition Coil RFW (XU10J2U)	<b>80207</b>
Ignition Leads	<b>85010</b>
<b>Jumper Bus (244, Z) 2.0</b>	<b>2002-&gt;</b>
XU10J2	81 110
Ignition Coil XU10J2	<b>80207</b>
<b>Jumper Bus (244, Z) 2.0 bivalent</b>	<b>2003-&gt;</b>
XU10J2	81 110
Ignition Coil	<b>80207</b>
<b>Jumper Chassis (230) 2.0</b>	<b>1994-02</b>
RFW (XU10J2U)	80 109
Ignition Coil RFW (XU10J2U)	<b>80207</b>
Ignition Leads	<b>85010</b>
<b>Jumper Van (230L) 2.0</b>	<b>1994-02</b>
RFW (XU10J2U)	80 109
Ignition Coil RFW (XU10J2U)	<b>80207</b>
Ignition Leads	<b>85010</b>
<b>Jumper Van (244) 2.0</b>	<b>2002-&gt;</b>
XU10J2	81 110
Ignition Coil XU10J2	<b>80207</b>
<b>Jumper Van (244) 2.0 bivalent</b>	<b>2003-&gt;</b>
XU10J2	81 110
Ignition Coil	<b>80207</b>
<b>Jumpy (U6U) 1.6</b>	<b>1995-00</b>
220 A2.000/1580 SPI	58 79
Ignition Coil	<b>80279</b>
<b>Jumpy (U6U) 2.0</b>	<b>2000-06</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>Jumpy (U6U) 2.0 i 16V</b>	<b>2000-06</b>
RFN (EW10J4)	102 138
Ignition Coil	<b>80275</b>
<b>Jumpy 2.0 i</b>	<b>2007-&gt;</b>
RFH (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>JUMPY Chassis (BU, BV, BW, BX) 2.0</b>	<b>2003-06</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>JUMPY Van (BS, BT, BY, BZ) 1.6 i</b>	<b>1995-00</b>
220 A2.000/1580 SPI	58 79
Ignition Coil	<b>80279</b>
<b>JUMPY Van (BS, BT, BY, BZ) 2.0 i 16V</b>	<b>2000-06</b>
RFN (EW10J4)	102 138
Ignition Coil	<b>80275</b>
<b>Jumpy Van 2.0 i</b>	<b>2007-&gt;</b>
RFH (EW10A)	103 140
Ignition Coil	<b>80278</b>

**CITROËN Cont.**

<b>LNA 0.6</b>	<b>1976-79</b>
R06 627	24 33
Ignition Leads	<b>83300</b>
<b>LNA 0.6</b>	<b>1978-86</b>
V06 644/V06 630	26 35
Ignition Leads	<b>83300</b>
<b>Saxo (S0, S1) 1.0 X</b>	<b>1998-03</b>
CDZ (TU9M)	37 50
Ignition Coil	<b>80207</b>
Ignition Coil	06.2000-12.2002
Ignition Coil	->05.2000
Ignition Leads	<b>85600</b>
<b>Saxo (S0, S1) 1.0 X</b>	<b>1996-98</b>
CDZ (TU9M)	33 45
Ignition Coil	->05.1997
Ignition Coil	06.1997->
Ignition Leads	<b>85600</b>
<b>Saxo (S0, S1) 1.1 X,SX</b>	<b>1996-03</b>
HDZ (TU1M)/HFX (TU1JP)	44 60
Ignition Coil HDZ (TU1M); ->05.1997	<b>80207</b>
Ignition Coil	06.2000-12.2002
Ignition Coil	06.1997-05.2000
Ignition Leads	<b>85600</b>
<b>Saxo (S0, S1) 1.1 X,SX</b>	<b>1996-03</b>
HDZ (TU1M)	40 54
Ignition Coil	->05.1997
Ignition Coil	06.2000-12.2002
Ignition Coil	06.1997-05.2000
Ignition Leads	<b>85600</b>
<b>Saxo (S0, S1) 1.4 VTS</b>	<b>1996-03</b>
KFX (TU3JP)/KFW (TU3JP)	55 75
Ignition Coil	<b>80207</b>
Ignition Coil	With regul.cat.(3way)
Ignition Coil	Hydraulic Brake
Ignition Leads	<b>85600</b>
<b>Saxo (S0, S1) 1.6</b>	<b>1996-03</b>
NFZ (TU5JP)	66 90
Ignition Coil	Automatic transmission
Ignition Coil	06.1998->; Manual gear
Ignition Leads	<b>85600</b>
<b>Saxo (S0, S1) 1.6</b>	<b>2001-04</b>
NFT (TU5JP)	74 101
Ignition Coil	<b>80208</b>
<b>Saxo (S0, S1) 1.6</b>	<b>1996-04</b>
NFX (TU5JP4)	88 120
Ignition Coil	<b>80310</b>
<b>Saxo (S0, S1) 1.6 VTL,VTR</b>	<b>1996-03</b>
NFZ (TU5JP)	65 88
Ignition Coil	NFZ (TU5JP)
Ignition Coil	With regul.cat.(3way)
Ignition Coil	Hydraulic Brake
Ignition Leads	<b>85600</b>
<b>Saxo (S0, S1) 1.6 VTS</b>	<b>2000-03</b>
NFT (TU5JP)	72 98
Ignition Coil	M4
Ignition Coil	SAE; Euro 4
<b>Saxo (S0, S1) 1.6 VTS</b>	<b>1996-03</b>
NFX (TU5JP4)	87 118
Ignition Coil	<b>80310</b>
Ignition Leads	<b>85600</b>
<b>Visa 0.6</b>	<b>1982-91</b>
V06/665	24 33
Ignition Leads	<b>83300</b>
<b>Xantia (X1) 1.6 i</b>	<b>1993-98</b>
BFZ (XU5JP)	65 88
Ignition Coil	BFZ (XU5JP)
Ignition Leads	<b>85010</b>
<b>Xantia (X1) 1.8 i</b>	<b>1993-98</b>
LFZ (XU7JP)	74 101
Ignition Coil	LFZ (XU7JP)
Ignition Leads	<b>85010</b>
<b>Xantia (X1) 1.8 i</b>	<b>1997-98</b>
LFX (XU7JB)	66 90
Ignition Coil	LFX (XU7JB)
Ignition Leads	<b>80207</b>
<b>Xantia (X1) 1.8 i 16V</b>	<b>1995-98</b>
LFY (XU7JP4)	81 110
Ignition Coil	03.1997-12.1997; With regul.cat.(3way)
Ignition Coil	Vet. 07609->



CITROËN Cont.	
<b>Xantia (X1) 2.0 i</b>	1993-98
RFX (XU10J2C)	89 121
Ignition Coil RFX (XU10J2C)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Xantia (X1) 2.0 i 16V</b>	1993-98
RFY (XU10J4/Z)	112 152
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Xantia (X1) 2.0 i 16V</b>	1994-98
RFT (XU10J4/Z)	110 150
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Xantia (X1) 2.0 i 16V</b>	1995-98
RFV (XU10J4R)	97 132
Ignition Coil	<b>80207</b>
Ignition Coil SAE	<b>80237</b>
Ignition Coil Vet. 07609->	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>Xantia (X1) 2.0 Turbo</b>	1995-98
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Xantia (X2) 1.6 i SX</b>	1998-01
BFZ (XU5JP)	65 88
Ignition Coil	<b>80207</b>
<b>Xantia (X2) 1.8 i</b>	1998-03
LFX (XU7JB)	66 90
Ignition Coil LFX (XU7JB)	<b>80207</b>
Ignition Leads	<b>85010</b>
<b>Xantia (X2) 1.8 i 16V</b>	1998-03
LFY (XU7JP4)	81 110
Ignition Coil	<b>80274</b>
<b>Xantia (X2) 2.0 i</b>	1998-03
RFX (XU10J2C)	89 121
Ignition Coil RFX (XU10J2C)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Xantia (X2) 2.0 i 16V</b>	1998-03
RFV (XU10J4R)	97 132
Ignition Coil	<b>80274</b>
<b>Xantia (X2) 2.0 Turbo</b>	1998-03
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Xantia (X2) 3.0 V6</b>	1998-03
XFZ (ES9J4)	140 190
Ignition Coil	<b>80374</b>
<b>Xantia Break (X1) 1.8 i</b>	1995-98
LFZ (XU7JP)	74 101
Ignition Coil LFZ (XU7JP)	<b>80207</b>
<b>Xantia Break (X1) 1.8 i</b>	1997-98
LFX (XU7JB)	66 90
Ignition Coil LFX (XU7JB)	<b>80207</b>
<b>Xantia Break (X1) 1.8 i 16V</b>	1995-98
LFY (XU7JP4)	81 110
Ignition Coil 03.1997->; With regul.cat.(3way)	<b>80237</b>
Ignition Coil Vet. 07609->	<b>80274</b>
<b>Xantia Break (X1) 2.0 i</b>	1995-98
RFX (XU10J2C)	89 121
Ignition Coil RFX (XU10J2C)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Xantia Break (X1) 2.0 i 16V</b>	1995-98
RFV (XU10J4R)	97 132
Ignition Coil ->02.1997	<b>80207</b>
Ignition Coil SAE	<b>80237</b>
Ignition Coil Vet. 07609->	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>Xantia Break (X1) 2.0 Turbo</b>	1995-98
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Xantia Break (X2) 1.8 i</b>	1998-03
LFX (XU7JB)	66 90
Ignition Coil LFX (XU7JB)	<b>80207</b>
<b>Xantia Break (X2) 1.8 i 16V</b>	1998-03
LFY (XU7JP4)	81 110
Ignition Coil	<b>80274</b>

CITROËN Cont.	
<b>Xantia Break (X2) 2.0 i</b>	1998-03
RFX (XU10J2C)	89 121
Ignition Coil RFX (XU10J2C)	<b>80207</b>
Ignition Coil SAE; ->05.2002	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>Xantia Break (X2) 2.0 i 16V</b>	1998-03
RFV (XU10J4R)	97 132
Ignition Coil	<b>80274</b>
<b>Xantia Break (X2) 2.0 Turbo</b>	1998-03
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>Xantia Break (X2) 3.0 V6</b>	1998-03
XFZ (ES9J4)	140 190
Ignition Coil	<b>80374</b>
<b>XM (Y3) 2.0</b>	1989-94
R6A	94 130
Ignition Coil 05.1990->	<b>80207</b>
Ignition Coil	<b>80260</b>
<b>XM (Y3) 2.0 i</b>	1989-94
RDZ (XU10MZ)	79 107
Ignition Coil	<b>80207</b>
Ignition Coil ->06.1990	<b>80260</b>
Ignition Leads Vet. 04957->	<b>83330</b>
<b>XM (Y3) 2.0 i</b>	1989-94
RFZ (XU10J2)	89 121
Ignition Coil RFZ (XU10J2)	<b>80207</b>
Ignition Coil	<b>80260</b>
Ignition Leads Vet. 04936->	<b>83330</b>
<b>XM (Y3) 2.0 i Turbo</b>	1992-94
RGY (XU10J2TE/Z)	104 141
Ignition Coil RGY (XU10J2TE/Z)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>XM (Y4) 2.0 i 16V</b>	1994-00
RFV (XU10J4R)	97 132
Ignition Coil	<b>80207</b>
Ignition Coil SAE	<b>80237</b>
Ignition Coil SAE; 09.1997->	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>XM (Y4) 2.0 Turbo</b>	1994-00
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>XM (Y4) 3.0 V6</b>	1997-00
XFZ (ES9J4)	140 190
Ignition Coil	<b>80374</b>
<b>XM Break (Y3) 2.0</b>	1989-94
R6A	94 130
Ignition Coil 05.1990->	<b>80207</b>
Ignition Coil	<b>80260</b>
<b>XM Break (Y3) 2.0 i</b>	1991-94
RFZ (XU10J2)	89 121
Ignition Coil RFZ (XU10J2)	<b>80207</b>
Ignition Coil	<b>80260</b>
Ignition Leads	<b>83330</b>
<b>XM Break (Y3) 2.0 i</b>	1991-94
RDZ (XU10MZ)/XU102C	79 107
Ignition Coil	<b>80207</b>
Ignition Coil	<b>80260</b>
<b>XM Break (Y3) 2.0 Turbo</b>	1992-94
RGY (XU10J2TE/Z)	104 141
Ignition Coil RGY (XU10J2TE/Z)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>XM Break (Y4) 2.0 i 16V</b>	1994-00
RFV (XU10J4R)	97 132
Ignition Coil	<b>80207</b>
Ignition Coil SAE	<b>80237</b>
Ignition Coil SAE; 09.1997->	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>XM Break (Y4) 2.0 Turbo</b>	1994-00
RGX (XU10J2TE)/RGY (XU10J2TE/Z)	108 147
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>XM Break (Y4) 3.0 V6</b>	1997-00
XFZ (ES9J4)	140 190
Ignition Coil	<b>80374</b>

**CITROËN Cont.**

<b>Xsara (N1) 1.4 i</b>	<b>1997-05</b>
KFX (TU3JP)/KFW (TU3JP)	55 75
Ignition Coil	<b>80207</b>
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
Ignition Leads ->Vet. 07874	<b>85600</b>
<b>Xsara (N1) 1.6 16V</b>	<b>2000-05</b>
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
<b>Xsara (N1) 1.6 i</b>	<b>1997-00</b>
NFZ (TU5JP)	65 88
Ignition Coil NFZ (TU5JP)	<b>80207</b>
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
Ignition Leads ->Vet. 07874	<b>85600</b>
<b>Xsara (N1) 1.8 i</b>	<b>1997-00</b>
LFZ (XU7JB)	66 90
Ignition Coil LFX (XU7JB)	<b>80207</b>
Ignition Leads	<b>85010</b>
<b>Xsara (N1) 1.8 i 16V</b>	<b>1997-00</b>
LFY (XU7JP4)	81 110
Ignition Coil ->12.1997; With regul.cat.(3way)	<b>80237</b>
Ignition Coil SAE	<b>80274</b>
<b>Xsara (N1) 1.8 i Aut.</b>	<b>1997-00</b>
LFZ (XU7JP)	74 101
Ignition Coil LFZ (XU7JP)	<b>80207</b>
Ignition Coil ->12.1997; With regul.cat.(3way)	<b>80237</b>
Ignition Leads	<b>85010</b>
<b>Xsara (N1) 2.0 16V</b>	<b>1998-00</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>Xsara (N1) 2.0 16V</b>	<b>2000-05</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>Xsara Break (N2) 1.4 i</b>	<b>1997-05</b>
KFX (TU3JP)/KFW (TU3JP)	55 75
Ignition Coil	<b>80207</b>
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
<b>Xsara Break (N2) 1.6 16V</b>	<b>2000-05</b>
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
<b>Xsara Break (N2) 1.6 i</b>	<b>1997-00</b>
NFZ (TU5JP)	65 88
Ignition Coil NFZ (TU5JP)	<b>80207</b>
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
Ignition Leads	<b>85600</b>
<b>Xsara Break (N2) 1.8 i</b>	<b>1997-00</b>
LFZ (XU7JB)	66 90
Ignition Coil LFX (XU7JB)	<b>80207</b>
<b>Xsara Break (N2) 1.8 i 16V</b>	<b>1997-00</b>
LFY (XU7JP4)	81 110
Ignition Coil ->12.1997; With regul.cat.(3way)	<b>80237</b>
Ignition Coil SAE	<b>80274</b>
<b>Xsara Break (N2) 1.8 i Aut.</b>	<b>1997-00</b>
LFZ (XU7JP)	74 101
Ignition Coil	<b>80207</b>
Ignition Coil ->12.1997; With regul.cat.(3way)	<b>80237</b>
<b>Xsara Break (N2) 2.0 16V</b>	<b>1998-00</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>Xsara Break (N2) 2.0 16V</b>	<b>2000-05</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>Xsara Coupe (N0) 1.4 i</b>	<b>1998-05</b>
KFX (TU3JP)/KFW (TU3JP)	55 75
Ignition Coil	<b>80207</b>
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
<b>Xsara Coupe (N0) 1.6 16V</b>	<b>2000-05</b>
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>

**CITROËN Cont.**

<b>Xsara Coupe (N0) 1.6 i</b>	<b>1998-00</b>
NFZ (TU5JP)	65 88
Ignition Coil NFZ (TU5JP)	<b>80207</b>
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
<b>Xsara Coupe (N0) 1.8 i</b>	<b>1998-00</b>
LFZ (XU7JP)	74 101
Ignition Coil LFZ (XU7JP)	<b>80207</b>
<b>Xsara Coupe (N0) 1.8 i</b>	<b>1998-00</b>
LFZ (XU7JP)	74 101
Ignition Coil LFZ (XU7JP)	<b>80207</b>
<b>Xsara Coupe (N0) 1.8 i 16V</b>	<b>1998-00</b>
LFY (XU7JP4)	81 110
Ignition Coil	<b>80274</b>
<b>Xsara Coupe (N0) 2.0 16V</b>	<b>2000-05</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>Xsara Picasso (N68) 1.6</b>	<b>1999-&gt;</b>
NFZ (TU5JP)	65 88
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
<b>Xsara Picasso (N68) 1.6</b>	<b>1999-&gt;</b>
NFV (TU5JP)	70 95
Ignition Coil 01.2000->	<b>80208</b>
Ignition Coil 01.2000->; Euro 4	<b>80226</b>
<b>Xsara Picasso (N68) 1.6 16V</b>	<b>2005-&gt;</b>
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>Xsara Picasso (N68) 1.6 Chrono</b>	<b>2001-04</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80207</b>
<b>Xsara Picasso (N68) 1.8 16V</b>	<b>2000-&gt;</b>
6FZ (EW7J4)	85 115
Ignition Coil	<b>80275</b>
<b>Xsara Picasso (N68) 2.0 16V</b>	<b>2003-&gt;</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>ZX (N2) 1,1</b>	<b>1991-93</b>
H1A/H1B	40 54
Ignition Coil	<b>80260</b>
Ignition Leads	<b>83650</b>
<b>ZX (N2) 1.1</b>	<b>1991-97</b>
HDZ (TU1M)	44 60
Ignition Coil ->03.1994	<b>80260</b>
Ignition Coil 04.1994->	<b>80272</b>
Ignition Leads HDZ (TU1M)	<b>83650</b>
Ignition Leads	<b>85600</b>
<b>ZX (N2) 1.4</b>	<b>1991-97</b>
KDZ (TU3M/Z)	55 75
Ignition Coil	<b>80260</b>
Ignition Leads KDZ (TU3M/Z)	<b>83650</b>
Ignition Leads	<b>85600</b>
<b>ZX (N2) 1.4 i</b>	<b>1991-97</b>
KDZ (TU3M/Z)/KFX (TU3JP)/KDX (TU3M/Z)	55 75
Ignition Coil KFX (TU3JP); 05.1996->	<b>80207</b>
Ignition Coil KDX, KDZ; ->07.1992	<b>80260</b>
Ignition Coil KDX; 08.1992-04.1996	<b>80272</b>
Ignition Leads ->Vet. 06366	<b>83650</b>
Ignition Leads Vet. 06367->	<b>85600</b>
<b>ZX (N2) 1.6</b>	<b>1994-97</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80207</b>
<b>ZX (N2) 1.6 i</b>	<b>1991-97</b>
BFZ (XU5JP)/BDY (XU5M)	65 88
Ignition Coil	<b>80207</b>
Ignition Leads Vet. 06367->	<b>85010</b>
<b>ZX (N2) 1.8 i</b>	<b>1992-97</b>
LFZ (XU7JP)	74 101
Ignition Coil LFZ (XU7JP)	<b>80207</b>
Ignition Leads Vet. 06367->	<b>85010</b>
<b>ZX (N2) 1.8 i 16V</b>	<b>1996-97</b>
LFY (XU7JP4)	81 110
Ignition Coil	<b>80237</b>
Ignition Coil SAE; Vet. 07609->	<b>80274</b>
Ignition Leads Vet. 06367->	<b>85010</b>
<b>ZX (N2) 1.9</b>	<b>1991-97</b>
D6E (XU9JA)	93 126
Ignition Coil	<b>80207</b>





<b>CITROËN Cont.</b>		
<b>ZX (N2) 1.9 i</b>		<b>1991-97</b>
DKZ (XU9JA)	88	120
Ignition Coil DKZ (XU9JA)		<b>80207</b>
Ignition Coil		<b>80260</b>
<b>ZX (N2) 2.0</b>		<b>1996-97</b>
RFS (XU10J4RS)	122	166
Ignition Coil		<b>80207</b>
<b>ZX (N2) 2.0</b>		<b>1994-97</b>
RFX (XU10J2C)	90	122
Ignition Coil		<b>80207</b>
<b>ZX (N2) 2.0 i</b>		<b>1992-97</b>
RFX (XU10J2C)	89	121
Ignition Coil RFX (XU10J2C)		<b>80207</b>
Ignition Leads Vet. 06367->		<b>83330</b>
<b>ZX (N2) 2.0 i 16V</b>		<b>1992-94</b>
RFT (XU10J4Z)/RFY (XU10J4Z)	112	152
Ignition Coil		<b>80207</b>
Ignition Leads		<b>83330</b>
<b>ZX (N2) 2.0 i 16V</b>		<b>1994-97</b>
RFT (XU10J4Z)	110	150
Ignition Coil		<b>80207</b>
Ignition Leads		<b>83330</b>
<b>ZX (N2) 2.0 i 16V</b>		<b>1996-97</b>
RFS (XU10J4RS)	120	163
Ignition Coil		<b>80207</b>
<b>ZX Break (N2) 1.4 i</b>		<b>1993-97</b>
KFX (TU3JP)/KDX (TU3M/Z)/KDY (TU3M)	55	75
Ignition Coil 05.1996->		<b>80207</b>
Ignition Coil		<b>80260</b>
Ignition Coil KDX; ->08.1996		<b>80272</b>
Ignition Leads KDX (TU3M/Z)		<b>83650</b>
Ignition Leads		<b>85600</b>
<b>ZX Break (N2) 1.6 i</b>		<b>1993-97</b>
BFZ (XU5JP)/BDY (XU5M)	65	88
Ignition Coil		<b>80207</b>
Ignition Leads ->Vet. 06366		<b>83650</b>
Ignition Leads Vet. 06367->		<b>85600</b>
<b>ZX Break (N2) 1.8 i</b>		<b>1993-97</b>
LFZ (XU7JP)	74	101
Ignition Coil		<b>80207</b>
Ignition Coil 03.1997->; With regul.cat.(3way)		<b>80237</b>
Ignition Leads ->Vet. 06366		<b>83650</b>
Ignition Leads Vet. 06367->		<b>85600</b>
<b>ZX Break (N2) 1.8 i 16V</b>		<b>1996-98</b>
LFY (XU7JP4)	81	110
Ignition Coil 03.1997->; With regul.cat.(3way)		<b>80237</b>
Ignition Coil SAE; Vet. 07609->		<b>80274</b>
Ignition Leads ->Vet. 06366		<b>83650</b>
Ignition Leads Vet. 06367->		<b>85600</b>

<b>DACIA</b>		
<b>Dokker 1.6 16V</b>		<b>2012-&gt;</b>
	61	83
Ignition Coil		<b>80222</b>
Ignition Leads ->03.2015		<b>85994</b>
<b>Dokker 1.6 LPG</b>		<b>2013-&gt;</b>
	61	83
Ignition Coil		<b>80222</b>
Ignition Leads ->03.2015		<b>85994</b>
<b>Dokker Express 1.6 16V</b>		<b>2012-&gt;</b>
	61	83
Ignition Coil		<b>80222</b>
Ignition Leads ->03.2015		<b>85994</b>
<b>Dokker Express 1.6 LPG</b>		<b>2013-&gt;</b>
K7M 812/K7M 828	61	83
Ignition Coil		<b>80222</b>
Ignition Leads ->03.2015		<b>85994</b>
<b>Duster 1.6 16V</b>		<b>2010-&gt;</b>
K4M 696/K4M 690	77	105
Ignition Coil		<b>80203</b>
<b>Duster 1.6 16V 4x4</b>		<b>2010-&gt;</b>
K4M 606	77	105
Ignition Coil		<b>80203</b>
<b>Duster 1.6 16V Hi-Flex</b>		<b>2010-&gt;</b>
K4M 696	77	105
Ignition Coil		<b>80203</b>

<b>DACIA Cont.</b>		
<b>Duster 1.6 16V LPG</b>		<b>2011-&gt;</b>
K4M 696	77	105
Ignition Coil		<b>80203</b>
<b>Duster Van 1.6 16V 4x4</b>		<b>2011-&gt;</b>
K4M 606	77	105
Ignition Coil		<b>80203</b>
<b>Duster Van 1.6 16V Hi-Flex</b>		<b>2011-&gt;</b>
K4M 696	77	105
Ignition Coil		<b>80203</b>
<b>Lodgy 1.6</b>		<b>2012-&gt;</b>
K7MA8	61	83
Ignition Coil		<b>80222</b>
Ignition Leads ->03.2015		<b>85994</b>
<b>Lodgy 1.6 LPG</b>		<b>2013-&gt;</b>
	61	83
Ignition Coil		<b>80222</b>
Ignition Leads ->03.2015		<b>85994</b>
<b>Logan (LS) 1,4</b>		<b>2004-&gt;</b>
K7J 710	55	75
Ignition Coil		<b>80222</b>
Ignition Leads		<b>85994</b>
<b>Logan (LS) 1,6</b>		<b>2004-&gt;</b>
K7M 710	64	87
Ignition Coil		<b>80222</b>
Ignition Leads		<b>85994</b>
<b>Logan (LS) 1.2 16V</b>		<b>2006-&gt;</b>
D4F 732	55	75
Ignition Coil		<b>80225</b>
Ignition Coil		<b>80287</b>
Ignition Leads		<b>85988</b>
<b>Logan (LS) 1.2 16V LPG</b>		<b>2006-&gt;</b>
	55	75
Ignition Coil		<b>80287</b>
<b>Logan (LS) 1.4 MPI LPG</b>		<b>2006-&gt;</b>
K7J 714/K7J 710	55	75
Ignition Coil		<b>80222</b>
Ignition Leads		<b>85994</b>
<b>Logan (LS) 1.6 16V</b>		<b>2006-&gt;</b>
K4M 696/K4M 690	77	105
Ignition Coil		<b>80203</b>
<b>Logan (LS) 1.6 16V Flexifuel</b>		<b>2010-&gt;</b>
K4M 696	77	105
Ignition Coil		<b>80203</b>
<b>Logan (LS) 1.6 Bifuel</b>		<b>2010-&gt;</b>
K7M 718	62	84
Ignition Coil		<b>80222</b>
Ignition Leads 11.2010-03.2015		<b>85994</b>
<b>Logan (LS) 1.6 MPI 85</b>		<b>2010-&gt;</b>
K7M 800	62	84
Ignition Coil		<b>80222</b>
Ignition Leads 11.2010-03.2015		<b>85994</b>
<b>Logan Express (FS) 1.4</b>		<b>2009-&gt;</b>
K7J 710	55	75
Ignition Coil		<b>80222</b>
Ignition Leads		<b>85994</b>
<b>Logan Express (FS) 1.6</b>		<b>2009-&gt;</b>
K7M 710	64	87
Ignition Coil		<b>80222</b>
Ignition Leads		<b>85994</b>
<b>Logan Express (FS) 1.6 MPI 85</b>		<b>2010-&gt;</b>
K7M 800	62	84
Ignition Coil		<b>80222</b>
Ignition Leads 11.2010-03.2015		<b>85994</b>
<b>Logan II 1,2</b>		<b>2015-&gt;</b>
	54	73
Ignition Coil		<b>80287</b>
<b>Logan II 1.2</b>		<b>2012-&gt;</b>
	55	75
Ignition Coil		<b>80225</b>
Ignition Coil		<b>80287</b>
Ignition Leads		<b>85988</b>
<b>Logan II 1.2 LPG</b>		<b>2012-&gt;</b>
D4F 734	55	75
Ignition Coil		<b>80225</b>
Ignition Coil		<b>80287</b>
<b>Logan Mcv (KS) 1.4</b>		<b>2007-&gt;</b>
K7J 710	55	75
Ignition Coil		<b>80222</b>
Ignition Leads		<b>85994</b>



DACIA Cont.	
<b>Logan Mcv (KS) 1.6</b>	2007->
K7M 710	64 87
Ignition Coil	80222
Ignition Leads	85994
<b>Logan Mcv (KS) 1.6 16V</b>	2007->
K4M 696/K4M 690	77 105
Ignition Coil	80203
<b>Logan Mcv (KS) 1.6 16V Hi-Flex</b>	2009->
K4M 690	77 105
Ignition Coil	80203
<b>Logan Mcv (KS) 1.6 Bifuel</b>	2008->
K7M 710	64 87
Ignition Coil	80222
Ignition Leads	85994
<b>Logan Mcv (KS) 1.6 MPI 85</b>	2010->
K7M 800	62 84
Ignition Coil	80222
Ignition Leads 11.2010-03.2015	85994
<b>Logan Mcv II 1,2</b>	2015->
D4F 732	54 73
Ignition Coil	80287
Ignition Leads Engine 15622->	85988
<b>Logan Mcv II 1,2</b>	2013->
D4F 732	55 75
Ignition Coil	80287
Ignition Leads Engine 15622->	85988
<b>Logan Mcv II 1.2 LPG</b>	2013->
D4F 734	55 75
Ignition Coil	80287
Ignition Leads Engine 15622->	85988
<b>Logan Pick-Up (US) 1.4</b>	2009->
K7J 710	55 75
Ignition Coil	80222
Ignition Leads	85994
<b>Logan Pick-Up (US) 1.6</b>	2008->
K7M 710	64 87
Ignition Coil	80222
Ignition Leads	85994
<b>Logan Pick-Up (US) 1.6 Bifuel</b>	2010->
K7M 800	62 84
Ignition Coil	80222
Ignition Leads 11.2010-03.2015	85994
<b>Logan Pick-Up (US) 1.6 MPI 85</b>	2010->
K7M 800	62 84
Ignition Coil	80222
Ignition Leads 11.2010-03.2015	85994
<b>Nova 1.6</b>	1996-03
	53 72
Ignition Coil	80279
<b>Sandero 1.2 16V</b>	2008->
D4F 732	55 75
Ignition Coil	80225
Ignition Coil	80287
Ignition Leads	85988
<b>Sandero 1.2 16V LPG</b>	2008->
D4F 732	55 75
Ignition Coil	80225
Ignition Coil	80287
Ignition Leads	85988
<b>Sandero 1.4</b>	2008->
K7J 710	55 75
Ignition Coil	80222
Ignition Leads	85994
<b>Sandero 1.4 MPI LPG</b>	2009->
K7J 714	53 72
Ignition Coil	80222
Ignition Leads ->03.2015	85994
<b>Sandero 1.6</b>	2008->
K7M 710	64 87
Ignition Coil	80222
Ignition Leads	85994
<b>Sandero 1.6 16V</b>	2011->
K4M 690	77 105
Ignition Coil	80203
<b>Sandero 1.6 MPI 85</b>	2010->
K7M 800	62 84
Ignition Coil	80222
Ignition Leads 11.2010-03.2015	85994

DACIA Cont.	
<b>Sandero II 1,2</b>	2015->
D4F 732	54 73
Ignition Coil	80287
<b>Sandero II 1,6</b>	2012->
K7M 812	61 83
Ignition Leads ->03.2015	85994
<b>Sandero II 1.2</b>	2012->
D4F 732	55 75
Ignition Coil	80225
Ignition Coil	80287
Ignition Leads	85988
<b>Sandero II 1.2 LPG</b>	2012->
	55 75
Ignition Coil	80225
Ignition Coil D4F 734	80287
Ignition Leads	85988
<b>Solenza 1.4</b>	2003->
E7J 262	55 75
Ignition Coil	80222
Ignition Leads	85994

DAEWOO	
<b>Aranos 2.0</b>	1995-97
C20LE	77 105
Ignition Leads	85960
<b>Cielo 1.5</b>	1994-98
V15L	66 90
Ignition Coil	80356
<b>Espero (KLEJ) 1.5 16V</b>	1993-94
A15MF	65 88
Ignition Leads	85960
Ignition Leads	85970
<b>Espero (KLEJ) 1.5 16V</b>	1995-99
A15MF	66 90
Ignition Coil	80356
Ignition Leads	85970
<b>Espero (KLEJ) 1.8</b>	1995-99
C18LE	66 90
Ignition Coil	80356
Ignition Leads	85960
<b>Espero (KLEJ) 1.8</b>	1995-99
C18LE	70 95
Ignition Coil	80356
Ignition Leads	85960
<b>Espero (KLEJ) 2.0</b>	1991-93
C20LZ	74 101
Ignition Leads	85960
<b>Espero (KLEJ) 2.0</b>	1993-94
C20LE	81 110
Ignition Leads	85960
<b>Espero (KLEJ) 2.0</b>	1995-99
C20LE	77 105
Ignition Coil	80356
Ignition Leads	85960
<b>Evanda (KLAL) 2.0</b>	2002->
L88/X 20 SED	96 131
Ignition Coil	80317
<b>Kalos (KLAS) 1.2</b>	2003->
F12S3/B12S1	53 72
Ignition Coil	80317
Ignition Leads	83566
<b>Kalos (KLAS) 1.4</b>	2002->
F14S3	61 83
Ignition Coil	80317
Ignition Leads	83562
<b>Kalos (KLAS) 1.4 16V</b>	2003->
F14D3	69 94
Ignition Coil	80317
Ignition Leads	83563
<b>Kalos Sedan (KLAS) 1.4</b>	2002-04
F14S3	61 83
Ignition Coil	80317
Ignition Leads	83562
<b>Kalos Sedan (KLAS) 1.4</b>	2003-04
F14D3	69 94
Ignition Coil	80317
Ignition Leads	83562
<b>Kalos Sedan (KLAS) 1.4</b>	2003-04
F14D3	69 94
Ignition Coil	80317
Ignition Leads	83562
Ignition Leads SAE	83563



DAEWOO Cont.	
<b>Korando (KJ) 2.3</b>	1999->
M 161.970	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Korando (KJ) 3.2 4x4</b>	1999->
M 104.995	156 212
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Korando Cabrio (KJ) 2.0 16V</b>	1999->
M 161.950	94 128
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Korando Cabrio (KJ) 2.3</b>	1999->
M 161.970	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Lacetti Fastback (KLAN) 1.4</b>	2004->
F14D3	70 95
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83563</b>
<b>Lacetti Fastback (KLAN) 1.6</b>	2004->
F16D3	80 109
Ignition Leads	<b>83564</b>
<b>Lacetti Fastback (KLAN) 1.8</b>	2004->
T18SED	90 122
Ignition Coil	<b>80317</b>
<b>Lanos (KLAT) 1.4</b>	1997->
A14SMS	55 75
Ignition Coil	<b>80317</b>
Ignition Coil	<b>80318</b>
Ignition Leads	<b>83562</b>
<b>Lanos (KLAT) 1.5</b>	1997-99
A15DMS	73 99
Ignition Coil	<b>80317</b>
<b>Lanos (KLAT) 1.5</b>	1997->
A15SMS	63 86
Ignition Coil Ch.590906->	<b>80317</b>
Ignition Coil	<b>80318</b>
Ignition Leads	<b>83562</b>
<b>Lanos (KLAT) 1.6 16V</b>	1997->
A16DMS	78 106
Ignition Coil	<b>80318</b>
Ignition Leads	<b>83563</b>
<b>Lanos Sedan (KLAT) 1.4</b>	1997->
A13SMS/A14SMS	55 75
Ignition Coil	<b>80317</b>
Ignition Coil	<b>80318</b>
Ignition Leads	<b>83562</b>
<b>Lanos Sedan (KLAT) 1.5</b>	1997->
A15SMS	63 86
Ignition Coil	<b>80317</b>
Ignition Coil	<b>80318</b>
Ignition Leads	<b>83562</b>
<b>Lanos Sedan (KLAT) 1.6 16V</b>	1997->
A16DMS	78 106
Ignition Coil	<b>80318</b>
Ignition Leads	<b>83563</b>
<b>Leganza (KLAV) 2.0 16V</b>	1997-02
X 20 SED	98 133
Ignition Coil	<b>80318</b>
<b>Matiz (KLYA) 0.8</b>	1998->
F8CV	38 52
Ignition Coil	<b>80319</b>
Ignition Leads	<b>83561</b>
<b>Matiz (KLYA) 1.0</b>	2003-04
B10S	46 63
Ignition Leads	<b>83566</b>
<b>Matiz (KLYA) 1.0</b>	2003->
B10S	47 64
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83566</b>
<b>Musso (FJ) 2.3</b>	1999->
M 111.970	103 140
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Musso (FJ) 3.2 4x4</b>	1999->
M 104.992	162 220
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Nexia (KLETN) 1.5</b>	1995-97
G15MF	52 71
Ignition Coil	<b>80356</b>
Ignition Leads	<b>83560</b>

DAEWOO Cont.	
<b>Nexia (KLETN) 1.5</b>	1995-97
G15MF	55 75
Ignition Coil	<b>80356</b>
Ignition Leads	<b>83560</b>
Ignition Leads G15MF	<b>85960</b>
<b>Nexia (KLETN) 1.5</b>	1996-97
G15MF	44 60
Ignition Coil	<b>80356</b>
Ignition Leads	<b>83560</b>
<b>Nexia (KLETN) 1.5 16V</b>	1995-97
A15MF	66 90
Ignition Coil	<b>80356</b>
Ignition Leads	<b>85970</b>
<b>Nexia Sedan (KLETN) 1.5</b>	1995-97
G15MF	52 71
Ignition Coil	<b>80356</b>
Ignition Leads	<b>83560</b>
Ignition Leads G15MF	<b>85960</b>
<b>Nexia Sedan (KLETN) 1.5</b>	1996-97
G15MF	44 60
Ignition Coil	<b>80374</b>
Ignition Leads	<b>83560</b>
<b>Nexia Sedan (KLETN) 1.5 16V</b>	1995-97
A15MF	66 90
Ignition Coil	<b>80356</b>
Ignition Leads	<b>85970</b>
<b>Nexia Sedan 1.5</b>	2008->
Y15L	59 80
Ignition Coil	<b>80356</b>
<b>Nexia Sedan 1.6</b>	2008->
F16D3	80 109
Ignition Coil	<b>80356</b>
<b>Nubira (KLAJ) 1.6 16V</b>	1997->
A16DMS	78 106
Ignition Coil	<b>80317</b>
Ignition Coil	<b>80318</b>
Ignition Leads	<b>83563</b>
<b>Nubira (KLAJ) 2.0 16V</b>	1997->
X 20 SED/Z20L	98 133
Ignition Coil	<b>80318</b>
<b>Nubira Sedan (KLAJ) 1.6 16V</b>	2000->
A16DMS	76 103
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83563</b>
<b>Nubira Sedan (KLAJ) 1.6 16V</b>	1997->
A16DMS	78 106
Ignition Coil	<b>80317</b>
Ignition Coil	<b>80318</b>
Ignition Leads	<b>83563</b>
<b>Nubira Sedan (KLAJ) 2.0 16V</b>	2000->
T20SED	93 126
Ignition Coil	<b>80317</b>
<b>Nubira Sedan (KLAJ) 2.0 16V</b>	1997->
X 20 SED	98 133
Ignition Coil Ch.642921->	<b>80317</b>
Ignition Coil	<b>80318</b>
<b>Nubira Sedan (KLAN) 1.6</b>	2003->
F16D3	80 109
Ignition Leads	<b>83564</b>
<b>Nubira Sedan (KLAN) 1.8</b>	2003->
T18SED	90 122
Ignition Coil	<b>80317</b>
<b>Nubira Wagon (KLAJ) 1.6 16V</b>	2000->
A16DMS	76 103
Ignition Coil	<b>80317</b>
Ignition Leads	<b>83563</b>
<b>Nubira Wagon (KLAJ) 1.6 16V</b>	1997->
A16DMS	78 106
Ignition Coil	<b>80317</b>
Ignition Coil	<b>80318</b>
Ignition Leads	<b>83563</b>
<b>Nubira Wagon (KLAJ) 2.0 16V</b>	2000->
T20SED	93 126
Ignition Coil	<b>80317</b>



DAEWOO Cont.		
<b>Nubira Wagon (KLAJ) 2.0 16V</b>	1997->	
X 20 SED	98 133	
Ignition Coil Ch.642921->	<b>80317</b>	
Ignition Coil	<b>80318</b>	
<b>Nubira Wagon (KLAN) 1.6</b>	2003->	
F16D3	80 109	
Ignition Leads	<b>83564</b>	
<b>Nubira Wagon (KLAN) 1.8</b>	2003->	
T18SED	90 122	
Ignition Coil	<b>80317</b>	
<b>Rexton (GAB) 3.2 V6</b>	2002->	
M 162.992	162 220	
Ignition Coil With regul.cat.(3way)	<b>80211</b>	
<b>Tacuma (KLAU) 1.6</b>	2000->	
A16DMS	77 105	
Ignition Leads	<b>83563</b>	
<b>Tacuma (KLAU) 1.8</b>	2000->	
F18S2	74 101	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83562</b>	
<b>Tacuma (KLAU) 1.8</b>	2000->	
A18DMS	72 98	
Ignition Coil	<b>80317</b>	
<b>Tacuma (KLAU) 1.8</b>	2000->	
F18D2	67 91	
Ignition Coil	<b>80317</b>	
Ignition Leads	<b>83562</b>	
<b>Tacuma (KLAU) 2.0</b>	2000->	
T20SED	94 128	
Ignition Coil	<b>80317</b>	
<b>Tacuma (KLAU) 2.0</b>	2001->	
X 20 SED	89 121	
Ignition Coil	<b>80317</b>	
<b>Tico (KLY3) 0.8</b>	1996-00	
F8CV	38 52	
Ignition Leads	<b>83561</b>	
<b>Tico (KLY3) 0.8</b>	1995-00	
F8C	35 48	
Ignition Coil	<b>80319</b>	
Ignition Leads	<b>83561</b>	

DAIHATSU		
<b>Charade 1.33 16V</b>	2011->	
1NR-FE	73 99	
Ignition Coil	<b>80367</b>	
<b>Charade IV (G200, G202) 1.0</b>	1994-96	
CB 22	38 52	
Ignition Leads	<b>85350</b>	
<b>Charade IV (G200, G202) 1.3 i 16V</b>	1993-00	
HCE/HC	62 84	
Ignition Leads	<b>85350</b>	
<b>Charade IV (G200, G202) 1.6 GTi</b>	1993-99	
HD-E	77 105	
Ignition Leads	<b>85350</b>	
<b>Charmant (A) 1,3</b>	1981-87	
4K	48 65	
Ignition Leads 4K	<b>83210</b>	
<b>Copen 1.3</b>	2006-12	
K3-VE	64 87	
Ignition Coil	<b>80366</b>	
<b>Cuore VIII 1.0</b>	2007->	
1KR-FE	51 70	
Ignition Coil	<b>80282</b>	
<b>Materia (M4) 1.3</b>	2006->	
K3-VE	67 91	
Ignition Coil	<b>80366</b>	
<b>Materia (M4) 1.5</b>	2006->	
3SZ-VE	76 103	
Ignition Coil	<b>80366</b>	
<b>Materia (M4) 1.5 ECO 4WD</b>	2006->	
3SZ-VE	76 103	
Ignition Coil	<b>80366</b>	
<b>Sirion (M1) 1.3 Sport</b>	2000-05	
K3-VE2	75 102	
Ignition Coil	<b>80366</b>	
<b>Sirion (M3) 1.0</b>	2005->	
1KR-FE	51 70	
Ignition Coil	<b>80282</b>	

DAIHATSU Cont.		
<b>Sirion (M3) 1.3</b>	2005->	
K3-VE	64 87	
Ignition Coil	<b>80366</b>	
<b>Sirion (M3) 1.3</b>	2008->	
K3-VE	67 91	
Ignition Coil	<b>80366</b>	
<b>Sirion (M3) 1.3 4WD</b>	2005->	
K3-VE	64 87	
Ignition Coil	<b>80366</b>	
<b>Sirion (M3) 1.3 4WD</b>	2008->	
K3-VE	67 91	
Ignition Coil	<b>80366</b>	
<b>Sirion (M3) 1.5</b>	2008->	
3SZ-VE	76 103	
Ignition Coil	<b>80366</b>	
<b>Terios (J2) 1.3 VVT-i 4x4</b>	2005->	
K3-VE	63 86	
Ignition Coil	<b>80366</b>	
<b>Terios (J2) 1.5 4x4</b>	2006->	
3SZ-VE	77 105	
Ignition Coil	<b>80366</b>	

DODGE		
<b>Caravan (RG) 2.4</b>	2000-07	
EDZ	111 151	
Ignition Coil	<b>80295</b>	
Ignition Coil	<b>80296</b>	
Ignition Leads 09.2002-08.2007	<b>83984</b>	
<b>Caravan (RG) 3.3</b>	2000-07	
EGA	128 174	
Ignition Leads	<b>86020</b>	
<b>Caravan (RG) 3.3 AWD</b>	2000-07	
EGA	128 174	
Ignition Leads	<b>86020</b>	
<b>Caravan 2.0 i</b>	1995-01	
	98 133	
Ignition Coil 01.1997->	<b>80296</b>	
Ignition Leads	<b>83981</b>	
<b>Caravan 2.4 i</b>	1995-01	
EDZ	111 151	
Ignition Coil	<b>80295</b>	
Ignition Coil 01.1997->	<b>80296</b>	
Ignition Leads ->08.2000	<b>83981</b>	
<b>Dakota 3.7</b>	2003->	
EKG	157 213	
Ignition Coil	<b>80345</b>	
<b>Dakota 3.7 AWD</b>	2003->	
EKG	157 213	
Ignition Coil	<b>80345</b>	
<b>Dakota 4.7</b>	2003->	
EVA	172 234	
Ignition Coil	<b>80345</b>	
<b>Dakota 4.7 AWD</b>	2004->	
EVC	190 258	
Ignition Coil	<b>80345</b>	
<b>Dakota 4.7 AWD</b>	2000-03	
EVA	172 234	
Ignition Coil	<b>80345</b>	
<b>Dakota 4.7 AWD</b>	2003->	
EVA	172 234	
Ignition Coil	<b>80345</b>	
<b>Durango 3.7</b>	2003-10	
EKG	157 213	
Ignition Coil	<b>80345</b>	
<b>Durango 4.7 AWD</b>	2003-09	
EVA	172 234	
Ignition Coil	<b>80345</b>	
<b>Neon 2.0 16V</b>	1994-99	
ECC	107 145	
Ignition Coil	<b>80295</b>	
Ignition Leads	<b>83981</b>	
<b>Neon 2.0 16V</b>	1994-99	
ECB	98 133	
Ignition Coil	<b>80295</b>	
Ignition Coil 01.1997->	<b>80296</b>	
Ignition Leads 06.1994->	<b>83981</b>	



<b>DODGE Cont.</b>	
<b>Neon 2.0 16V</b>	<b>1996-99</b>
ECC	109 148
Ignition Coil	<b>80295</b>
Ignition Leads	<b>83981</b>
<b>Neon 2.0 16V</b>	<b>1996-99</b>
ECC	112 152
Ignition Coil	<b>80295</b>
<b>Neon II 2.0 16V</b>	<b>1999-&gt;</b>
ECB	98 133
Ignition Coil	<b>80295</b>
Ignition Coil	<b>80296</b>
Ignition Leads 09.1999-12.2005	<b>83981</b>
<b>Neon II 2.0 16V</b>	<b>1999-&gt;</b>
ECH	112 152
Ignition Coil	<b>80295</b>
Ignition Coil	<b>80296</b>
Ignition Leads 09.2000-08.2005	<b>83981</b>
<b>Ram 1500 Pick-Up (BE, BR) 3.7</b>	<b>2001-08</b>
EKG	157 213
Ignition Coil	<b>80345</b>
<b>Ram 1500 Pick-Up (D1, DC, DH, DM, DR) 4.7</b>	<b>2001-08</b>
EVA	172 234
Ignition Coil	<b>80345</b>
<b>Ram 1500 Pick-Up (D1, DC, DH, DM, DR) 4.7 4X4</b>	<b>2001-08</b>
EVA	172 234
Ignition Coil	<b>80345</b>
<b>Stratus 2.0 16V</b>	<b>1995-01</b>
ECB	98 133
Ignition Coil 01.1997->	<b>80296</b>
<b>Stratus 2.4 16 V</b>	<b>1995-01</b>
EDZ	103 140
Ignition Coil	<b>80295</b>
Ignition Coil	<b>80296</b>
<b>Stratus 2.4 16V</b>	<b>1995-01</b>
EDZ	112 152
Ignition Coil	<b>80295</b>
Ignition Coil	<b>80296</b>

<b>FERRARI</b>	
<b>348 Spider 3.4</b>	<b>1993-95</b>
V834	235 320
Ignition Coil F 119 F 000; ->04.1994	<b>80279</b>
<b>348 TB/GTB 3.4</b>	<b>1990-94</b>
F 119 F 000	221 300
Ignition Coil	<b>80279</b>
<b>348 TB/GTB 3.4</b>	<b>1993-94</b>
F 119 D 040	235 320
Ignition Coil	<b>80279</b>
<b>348 TS/GTS 3.4</b>	<b>1990-93</b>
F 119 F 000	221 300
Ignition Coil	<b>80279</b>
<b>348 TS/GTS 3.4</b>	<b>1993-95</b>
F 119 D 040	235 320
Ignition Coil	<b>80279</b>
<b>F355 Berlinetta 3.5</b>	<b>1994-99</b>
F 129B/40	280 380
Ignition Coil	<b>80279</b>
<b>F355 GTS 3.5 Spider</b>	<b>1995-00</b>
F 129B/40	280 380
Ignition Coil	<b>80279</b>
<b>Mondial 3.4 T</b>	<b>1989-93</b>
F 119 D	221 300
Ignition Coil	<b>80279</b>
<b>Mondial Cabriolet 3.4 T</b>	<b>1989-93</b>
F 119 D	221 300
Ignition Coil	<b>80279</b>

<b>FIAT</b>	
<b>124 1600</b>	<b>1973-75</b>
132 AC.000/124 A9.000	70 95
Ignition Leads	<b>83060</b>
<b>124 Coupe 1800 Sport</b>	<b>1973-76</b>
	87 118
Ignition Leads	<b>83060</b>
<b>124 Spider 1600 Sport</b>	<b>1969-74</b>
125 B.000	80 108
Ignition Leads	<b>83060</b>

<b>FIAT Cont.</b>	
<b>132 1.6</b>	<b>1977-81</b>
132 C6.000	66 90
Ignition Leads 132 C6.000	<b>83100</b>
<b>500 (312) 0.9</b>	<b>2013-&gt;</b>
312 A4.000/312 A6.000	44 60
Ignition Coil	<b>80233</b>
<b>500 (312) 0.9</b>	<b>2013-&gt;</b>
312 A5.000	59 80
Ignition Coil	<b>80233</b>
<b>500 (312) 0.9</b>	<b>2012-&gt;</b>
312 A4.000	48 65
Ignition Coil	<b>80233</b>
<b>500 (312) 1.2</b>	<b>2007-&gt;</b>
169 A4.000	51 69
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>500 (312) 1.2 LPG</b>	<b>2010-&gt;</b>
169 A4.000	51 69
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>500 (312) 1.4</b>	<b>2007-&gt;</b>
169 A3.000	74 100
Ignition Coil	<b>80233</b>
<b>500 C (312) 0.9</b>	<b>2012-&gt;</b>
312 A4.000	48 65
Ignition Coil	<b>80233</b>
<b>500 C (312) 1.2</b>	<b>2009-&gt;</b>
169 A4.000	51 69
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>500 C (312) 1.4</b>	<b>2009-&gt;</b>
169 A3.000	74 100
Ignition Coil	<b>80233</b>
<b>500L (199_) 1.4</b>	<b>2013-&gt;</b>
940 B7.000	88 120
Ignition Coil 01.2014-11.2014	<b>80267</b>
<b>500L (199_) 1.4 LPG</b>	<b>2014-&gt;</b>
940 B7.000	88 120
Ignition Coil ->11.2014	<b>80267</b>
<b>500L 1.4</b>	<b>2012-&gt;</b>
843 A1.000	70 95
Ignition Coil	<b>80233</b>
<b>Argenta (132A) 2000 i.e.</b>	<b>1981-86</b>
132 C3.000	90 122
Ignition Leads 132 C3.000	<b>83100</b>
<b>Barchetta (183) 1.8 16V</b>	<b>1995-05</b>
183 A1.000/188 A6.000	96 130
Ignition Coil 06.1998->	<b>80228</b>
<b>Brava (182) 1,4</b>	<b>1995-01</b>
182 A5.000	55 75
Ignition Coil	<b>80279</b>
Ignition Leads	<b>86040</b>
<b>Brava (182) 1.2 16V 80</b>	<b>1998-02</b>
182 B2.000	60 82
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85648</b>
<b>Brava (182) 1.2 16V 80</b>	<b>2000-01</b>
188 A5.000	59 80
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85648</b>
<b>Brava (182) 1.4 12 V</b>	<b>1995-98</b>
182 A3.000	59 80
Ignition Coil	<b>80279</b>
Ignition Leads	<b>86040</b>
<b>Brava (182) 1.6 16V</b>	<b>1995-01</b>
182 A6.000	66 90
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Brava (182) 1.6 16V</b>	<b>1996-01</b>
182 A4.000	76 103
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Brava (182) 1.8 GT 16V</b>	<b>1995-01</b>
182 A2.000	83 113
Ignition Coil 07.1999->	<b>80228</b>
<b>Bravo I (182) 1,4</b>	<b>1995-01</b>
182 A5.000	55 75
Ignition Coil	<b>80279</b>
Ignition Leads	<b>86040</b>





FIAT Cont.	
<b>Bravo I (182) 1,4</b>	<b>1995-01</b>
182 A3.000	59 80
Ignition Coil	<b>80279</b>
Ignition Leads	<b>86040</b>
<b>Bravo I (182) 1.2 16V 80</b>	<b>1998-00</b>
182 B2.000	60 82
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85648</b>
<b>Bravo I (182) 1.2 16V 80</b>	<b>2000-01</b>
188 A5.000	59 80
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85648</b>
<b>Bravo I (182) 1.6 16V</b>	<b>1995-01</b>
182 A6.000	66 90
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Bravo I (182) 1.6 16V</b>	<b>1996-01</b>
182 A4.000	76 103
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Bravo I (182) 1.8 GT</b>	<b>1995-01</b>
182 A2.000	83 113
Ignition Coil 08.1999->	<b>80228</b>
Ignition Leads	<b>86050</b>
<b>Bravo I (182) 2.0 HGT 20V</b>	<b>1998-01</b>
182 B7.000	113 154
Ignition Coil	<b>80312</b>
<b>Bravo II (198) 1.4</b>	<b>2007-&gt;</b>
192 B2.000	66 90
Ignition Coil	<b>80233</b>
<b>Bravo II (198) 1.4 16V</b>	<b>2008-&gt;</b>
198 A7.000	103 140
Ignition Coil OE N° 46 777 288	<b>80233</b>
<b>Bravo II (198) 1.4 LPG</b>	<b>2008-14</b>
192 B2.000	66 90
Ignition Coil	<b>80233</b>
<b>Bravo II (198) 1.4 T-Jet</b>	<b>2007-&gt;</b>
198 A4.000	88 120
Ignition Coil	<b>80233</b>
Ignition Coil 03.2010-12.2014	<b>80267</b>
<b>Bravo II (198) 1.4 T-Jet</b>	<b>2007-&gt;</b>
198 A1.000	110 150
Ignition Coil	<b>80233</b>
Ignition Coil 03.2010-12.2014	<b>80267</b>
<b>Cinquecento (170) 0,7</b>	<b>1991-96</b>
170 A.000	23 31
Ignition Coil 170 A.000	<b>80217</b>
Ignition Leads	<b>85290</b>
<b>Cinquecento (170) 0,9</b>	<b>1991-93</b>
170 A1.000	30 41
Ignition Coil 170 A1.000	<b>80217</b>
Ignition Leads	<b>85250</b>
<b>Cinquecento (170) 0.7 i</b>	<b>1994-98</b>
170 A.046	22 30
Ignition Coil 170 A.046	<b>80217</b>
<b>Cinquecento (170) 0.9 i.e.</b>	<b>1991-93</b>
170 A1.046	30 41
Ignition Coil 170 A1.046	<b>80217</b>
Ignition Leads	<b>85250</b>
<b>Cinquecento (170) 0.9 i.e. S</b>	<b>1991-99</b>
1170 A1.000/1170 A1.046	29 40
Ignition Coil	<b>80217</b>
Ignition Leads	<b>85250</b>
<b>Cinquecento (170) 1.1 Sporting</b>	<b>1994-98</b>
176 B2.000	40 54
Ignition Coil 176 B2.000	<b>80217</b>
Ignition Leads	<b>85280</b>
Ignition Leads	<b>85625</b>
<b>Coupe (Fa/175) 1.8 16V</b>	<b>1996-00</b>
183 A1.000	96 131
Ignition Coil 05.1998->	<b>80228</b>
<b>Coupe (Fa/175) 2.0 16V</b>	<b>1993-96</b>
836 A3.000	102 139
Ignition Leads	<b>85610</b>
<b>Coupe (Fa/175) 2.0 16V Turbo</b>	<b>1993-96</b>
175 A1.000	140 190
Ignition Coil 175 A1.000	<b>80217</b>
Ignition Leads	<b>85620</b>

FIAT Cont.	
<b>Coupe (Fa/175) 2.0 20V</b>	<b>1998-00</b>
182 B3.000	113 154
Ignition Coil	<b>80312</b>
<b>Croma (154) 1600</b>	<b>1985-90</b>
154 A.048	61 83
Ignition Leads	<b>83390</b>
<b>Croma (154) 2000 16V</b>	<b>1992-96</b>
154 E1.000	101 137
Ignition Coil	<b>80279</b>
<b>Croma (154) 2000 CHT</b>	<b>1991-92</b>
154 C5.000/154 A1.000	74 100
Ignition Leads	<b>83390</b>
<b>Croma (154) 2000 CHT</b>	<b>1985-89</b>
154 A1.000	66 90
Ignition Leads	<b>83390</b>
<b>Croma (154) 2000 i.e.</b>	<b>1986-90</b>
834 B.048	83 113
Ignition Leads	<b>83390</b>
<b>Croma (154) 2000 i.e.</b>	<b>1987-92</b>
834 B.000/154 C3.000	88 120
Ignition Leads	<b>83390</b>
<b>Croma (154) 2000 i.e.</b>	<b>1987-96</b>
154 C3.046/834 B.146	85 116
Ignition Leads	<b>83390</b>
<b>Croma (154) 2000 i.e. Turbo</b>	<b>1985-90</b>
154 A2.000	114 155
Ignition Leads	<b>83390</b>
<b>Croma (154) 2000 i.e. Turbo</b>	<b>1987-96</b>
154 C4.046/834 C.146	110 150
Ignition Leads	<b>83390</b>
<b>Croma (154) 2000 i.e. Turbo</b>	<b>1986-88</b>
834 C.146	111 151
Ignition Leads	<b>83390</b>
<b>Croma (194) 1.8 16V</b>	<b>2005-&gt;</b>
939 A4.000	103 140
Ignition Coil	<b>80291</b>
<b>Doblo (119) 1,2</b>	<b>2001-&gt;</b>
223 A5.000	48 65
Ignition Coil 223 A5.000	<b>80217</b>
Ignition Leads	<b>85625</b>
<b>Doblo (119) 1.4</b>	<b>2005-&gt;</b>
350 A1.000	57 77
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Doblo (119) 1.6 16V</b>	<b>2001-&gt;</b>
182 B6.000	76 103
Ignition Coil	<b>80256</b>
Ignition Leads	<b>86050</b>
<b>Doblo (119) 1.6 Natural Power</b>	<b>2002-&gt;</b>
182 B6.000	76 103
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Doblo Cargo (223) 1,2</b>	<b>2001-&gt;</b>
223 A5.000	48 65
Ignition Coil 223 A5.000	<b>80217</b>
Ignition Leads	<b>85625</b>
<b>Doblo Cargo (223) 1.4</b>	<b>2005-&gt;</b>
350 A1.000	57 77
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Doblo Cargo (223) 1.6 16V</b>	<b>2001-&gt;</b>
182 B6.000	76 103
Ignition Coil	<b>80256</b>
Ignition Leads	<b>86050</b>
<b>Doblo Cargo (223) 1.6 Natural Power</b>	<b>2002-&gt;</b>
182 B6.000	76 103
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Doblo Chassis (263) 1.4</b>	<b>2011-&gt;</b>
198 A4.000	88 120
Ignition Coil ->11.2014; Euro 5; Euro 6	<b>80267</b>
<b>Doblo Chassis (263) 1.4</b>	<b>2010-&gt;</b>
843 A1.000	70 95
Ignition Coil	<b>80233</b>
<b>Doblo Chassis (263) 1.4 Natural Power</b>	<b>2010-&gt;</b>
198 A4.000	88 120
Ignition Coil ->11.2014; Euro 5; Euro 6	<b>80267</b>



FIAT Cont.	
<b>Doblo Combi (263) 1.4</b>	2011->
198 A4.000	88 120
Ignition Coil	<b>80233</b>
Ignition Coil	<b>80267</b>
<b>Doblo Combi (263) 1.4</b>	2010->
843 A1.000	70 95
Ignition Coil	<b>80233</b>
<b>Doblo Combi (263) 1.4 Natural Power</b>	2010->
198 A4.000	88 120
Ignition Coil	<b>80267</b>
<b>Doblo MPV (152, 263) 1.4</b>	2011->
198 A4.000	88 120
Ignition Coil	<b>80267</b>
<b>Doblo MPV (152, 263) 1.4</b>	2010->
843 A1.000	70 95
Ignition Coil	<b>80233</b>
<b>Doblo MPV (152, 263) 1.4 Natural Power</b>	2010->
198 A4.000	88 120
Ignition Coil 06.2010->	<b>80267</b>
<b>Ducato Bus (230) 2.0 4x4</b>	1994-01
RFW	80 109
Ignition Coil	<b>80207</b>
<b>Ducato Bus (230) 2.0 Panorama/Combinato</b>	1994-02
RFW	80 109
Ignition Coil RFW	<b>80207</b>
<b>Ducato Bus (244, Z) 2.0</b>	2002->
RFL	81 110
Ignition Coil RFL	<b>80207</b>
<b>Ducato Bus (244, Z) 2.0 4x4</b>	2002-06
RFL	81 110
Ignition Coil	<b>80207</b>
<b>Ducato Bus (244, Z) 2.0 Bipower</b>	2002->
RFL	81 110
Ignition Coil	<b>80207</b>
<b>Ducato Bus (250) 140 Natural Power</b>	2009->
F1CFA401A/F1CE0441A	100 136
Ignition Coil	<b>80233</b>
<b>Ducato Chassis (230) 2.0</b>	1994-02
RFW	80 109
Ignition Coil RFW	<b>80207</b>
<b>Ducato Chassis (244) 2.0</b>	2002-06
RFL	81 110
Ignition Coil	<b>80207</b>
<b>Ducato Chassis (280) 2.0</b>	1985-90
XN 1T/170 B	55 75
Ignition Leads	<b>85190</b>
<b>Ducato Chassis (280) 2.0</b>	1988-90
170 D	62 84
Ignition Leads	<b>85190</b>
<b>Ducato Chassis (290) 2.0</b>	1990-94
170 D	62 84
Ignition Leads	<b>85190</b>
<b>Ducato Panorama (280) 1.8</b>	1982-88
XM7T	51 67
Ignition Leads	<b>85190</b>
<b>Ducato Panorama (280) 2.0</b>	1986-90
170 B	55 75
Ignition Leads	<b>85190</b>
<b>Ducato Panorama (280) 2.0</b>	1982-85
XN 1T	58 79
Ignition Leads	<b>85190</b>
<b>Ducato Panorama (280) 2.0</b>	1988-90
170 D	62 84
Ignition Leads	<b>85190</b>
<b>Ducato Panorama (290) 2.0</b>	1990-94
170 D	62 84
Ignition Leads	<b>85190</b>
<b>Ducato Van (230L) 2.0</b>	1994-02
RFW	80 109
Ignition Coil RFW	<b>80207</b>
<b>Ducato Van (230L) 2.0 4x4</b>	1994-02
RFW	80 109
Ignition Coil	<b>80207</b>
<b>Ducato Van (244) 2.0</b>	2002->
RFL	81 110
Ignition Coil RFL	<b>80207</b>
<b>Ducato Van (244) 2.0 4x4</b>	2002-06
RFL	81 110
Ignition Coil	<b>80207</b>

FIAT Cont.	
<b>Ducato Van (244) 2.0 Bipower</b>	2002->
RFL	81 110
Ignition Coil	<b>80207</b>
<b>Ducato Van (250) 140 Natural Power</b>	2009->
F1CE0441A	100 136
Ignition Coil	<b>80233</b>
<b>Ducato Van (280) 1.8</b>	1982-88
169 B	49 67
Ignition Leads	<b>85190</b>
<b>Ducato Van (280) 2.0</b>	1985-90
170 B	55 75
Ignition Leads	<b>85190</b>
<b>Ducato Van (280) 2.0</b>	1982-90
XN 1T	58 79
Ignition Leads	<b>85190</b>
<b>Ducato Van (280) 2.0</b>	1989-90
170 D	62 84
Ignition Leads	<b>85190</b>
<b>Duna (146 B) 60 1.1</b>	1987-91
146 A6.000	43 58
Ignition Leads	<b>83140</b>
<b>Duna (146 B) 70 1.3</b>	1987-91
146 A5.000	49 67
Ignition Leads	<b>83140</b>
<b>Duna Weekend (146 B) 60 1.1</b>	1987-91
146 A6.000	43 58
Ignition Leads	<b>83140</b>
<b>Duna Weekend (146 B) 70 1.3</b>	1987-91
146 A5.000	49 67
Ignition Leads	<b>83140</b>
<b>Elba (146) 1.5</b>	1992-96
149 C1.000	49 67
Ignition Coil	<b>80217</b>
<b>Fiorino (127) 900</b>	1977-86
100 GL.000	33 45
Ignition Leads	<b>83140</b>
<b>Fiorino (147) 1.0</b>	1986-88
156 A.000	41 56
Ignition Leads	<b>83140</b>
<b>Fiorino (147) 1.1 60</b>	1986-88
146 A9.000	40 55
Ignition Leads	<b>83140</b>
<b>Fiorino (147) 1.3</b>	1987-93
146 A5.000	49 67
Ignition Leads	<b>83140</b>
<b>Fiorino Combi (225) 1.4 Natural Power</b>	2008->
350 A1.000	57 78
Ignition Coil	<b>80340</b>
<b>Fiorino Pick Up (146) 1.3</b>	1988-94
146 A5.000	49 67
Ignition Leads 146 A5.000	<b>83140</b>
<b>Fiorino Pick Up (146) 1.4</b>	1994-01
146 D5.000	49 67
Ignition Coil	<b>80279</b>
<b>Fiorino Pick Up (146) 1.6</b>	1994-01
146 D6.000/146 C6.000	55 75
Ignition Coil	<b>80279</b>
<b>Fiorino Pick Up (147) 1.1</b>	1986-89
156 A.000	41 56
Ignition Leads	<b>83140</b>
<b>Fiorino Van (146) 60 1.1</b>	1988-93
146 A9.000	40 54
Ignition Leads 146 A9.000	<b>83140</b>
<b>Fiorino Van (146) 70 1.3</b>	1988-94
146 A5.000	49 67
Ignition Leads 146 A5.000	<b>83140</b>
<b>Fiorino Van (146) 70 i.e. 1.4</b>	1994-01
146 C5.000/146 D5.000	49 67
Ignition Coil	<b>80279</b>
<b>Fiorino Van (146) 75 i.e. 1.6</b>	1993-01
146 D6.000/146 C6.000	55 75
Ignition Coil	<b>80279</b>
<b>Grande Punto (199) 1.4 16V</b>	2007-12
198 A1.000	112 152
Ignition Coil	<b>80267</b>
<b>Idea 1.2 16V</b>	2004->
188 A5.000	59 80
Ignition Coil 188 A5.000	<b>80233</b>



FIAT Cont.		
<b>Idea 1.4</b>	2005->	
350 A1.000	57 77	
Ignition Coil	<b>80340</b>	
Ignition Leads	<b>85626</b>	
<b>Idea 1.4</b>	2003->	
192 B2.000	66 90	
Ignition Coil ->12.2012	<b>80233</b>	
<b>Idea 1.4 16V</b>	2004->	
843 A1.000	70 95	
Ignition Coil 843 A1.000	<b>80233</b>	
<b>Idea 1.4 LPG</b>	2009->	
350 A1.000	57 78	
Ignition Coil	<b>80340</b>	
Ignition Leads	<b>85626</b>	
<b>Linea (323) 1.4</b>	2007->	
350 A1.000	57 77	
Ignition Coil	<b>80340</b>	
Ignition Leads	<b>85626</b>	
<b>Linea (323) 1.4 T-Jet</b>	2007->	
198 A4.000	88 120	
Ignition Coil	<b>80267</b>	
<b>Marea (185) 1.2 16V</b>	1998-02	
182 B2.000	60 82	
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>85648</b>	
<b>Marea (185) 1.4 80 12V</b>	1996-02	
182 A3.000	59 80	
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>86040</b>	
<b>Marea (185) 1.6</b>	2000-02	
182 B6.000	76 103	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Marea (185) 1.6 100 16V</b>	1996-02	
182 A4.000	76 103	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Marea (185) 1.6 100 16V Bipower</b>	1999-02	
186 A4.000/185 A3.000	76 103	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Marea (185) 1.6 SX</b>	2000-02	
182 B5.098	72 98	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Marea (185) 1.8 115 16V</b>	1996-02	
182 A2.000	83 113	
Ignition Coil 01.1999->	<b>80228</b>	
<b>Marea (185) 2.0 150 20V</b>	2001-02	
185 A8.000	110 150	
Ignition Coil	<b>80312</b>	
<b>Marea (185) 2.0 155 20V</b>	1999-01	
182 B7.000	113 154	
Ignition Coil	<b>80312</b>	
<b>Marea Weekend (185) 1.2 16V</b>	1998-02	
182 B2.000	60 82	
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>85648</b>	
<b>Marea Weekend (185) 1.4 80 12V</b>	1996-02	
182 A3.000	59 80	
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>86040</b>	
<b>Marea Weekend (185) 1.6 100 16V</b>	1996-02	
182 A4.000	76 103	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Marea Weekend (185) 1.8 115 16V</b>	1996-02	
182 A2.000	83 113	
Ignition Coil 01.1999->	<b>80228</b>	
<b>Marea Weekend (185) 2.0 150 20V</b>	2001-02	
185 A8.000	110 150	
Ignition Coil	<b>80312</b>	
<b>Marea Weekend (185) 2.0 155 20V</b>	1999-03	
182 B7.000	113 154	
Ignition Coil	<b>80312</b>	
<b>Multipla (186) 1.6</b>	2000-10	
182 B6.000	76 103	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	

FIAT Cont.		
<b>Multipla (186) 1.6 100 16V</b>	1999-10	
182 A4.000	76 103	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Multipla (186) 1.6 16V</b>	2002-10	
182 B6.000	70 95	
Ignition Coil	<b>80256</b>	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Multipla (186) 1.6 16V Bipower</b>	1999-10	
186 A4.000	76 103	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Multipla (186) 1.6 16V Bipower</b>	2001-10	
182 B6.000	76 103	
Ignition Coil	<b>80256</b>	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Multipla (186) 1.6 16V Blupower</b>	1999-10	
186 A3.000	70 95	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Palio (178Bx) 1.0</b>	1996-03	
178 A1.000	45 61	
Ignition Coil	<b>80217</b>	
<b>Palio (178Bx) 1.2</b>	1997-02	
178 B7.045/178 C4.066/188 A4.000	44 60	
Ignition Coil 01.2001->	<b>80217</b>	
Ignition Leads	<b>85625</b>	
<b>Palio (178Bx) 1.2</b>	1999-00	
178 E2.000	50 68	
Ignition Coil	<b>80217</b>	
Ignition Leads	<b>85625</b>	
<b>Palio (178Bx) 1.2</b>	1998->	
178 B5.000/178 E2.000/176 A8.000	54 73	
Ignition Coil 178 E2.000	<b>80217</b>	
Ignition Leads	<b>85280</b>	
Ignition Leads ->09.2001	<b>85625</b>	
<b>Palio (178Bx) 1.4</b>	1996-02	
178 B2.000	51 69	
Ignition Coil 178 B2.000	<b>80217</b>	
<b>Palio (178Bx) 1.4 KAT</b>	1996-01	
178 B2.016	51 69	
Ignition Coil 178 B2.016	<b>80217</b>	
<b>Palio (178Bx) 1.6 16V</b>	1996->	
178 B3.000	74 100	
Ignition Coil 03.1998-12.2000	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Palio Weekend (178Dx) 1,2</b>	2001->	
178 C4.066/188 A4.000	44 60	
Ignition Coil 188 A4.000	<b>80217</b>	
Ignition Leads	<b>85625</b>	
<b>Palio Weekend (178Dx) 1,2</b>	1996-01	
178 B5.000	54 73	
Ignition Coil 178 B5.000	<b>80217</b>	
Ignition Leads	<b>85625</b>	
<b>Palio Weekend (178Dx) 1.2</b>	2001->	
188 A5.000	59 80	
Ignition Coil 10.2001-12.2008	<b>80279</b>	
Ignition Leads 10.2001-12.2008	<b>85648</b>	
<b>Palio Weekend (178Dx) 1.2 Flex</b>	1997-02	
188 A4.000	44 60	
Ignition Coil	<b>80217</b>	
<b>Palio Weekend (178Dx) 1.2 LPG</b>	1997-02	
188 A4.000	44 60	
Ignition Coil	<b>80217</b>	
<b>Palio Weekend (178Dx) 1.6 16V</b>	2001->	
182 B6.000	76 103	
Ignition Coil	<b>80256</b>	
Ignition Coil ->09.2001	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Palio Weekend (178Dx) 1.6 16V</b>	1996-01	
178 B3.000	74 100	
Ignition Coil	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Panda (141A) 1000</b>	1986-92	
156 A2.100	32 44	
Ignition Leads	<b>83890</b>	



FIAT Cont.		
<b>Panda (141A) 1000</b>		<b>1985-92</b>
156 A3.000		37 50
Ignition Leads 153 A3.000		<b>83890</b>
<b>Panda (141A) 1000 4x4</b>		<b>1986-89</b>
156 A3.100/156 A2.100		32 44
Ignition Leads		<b>83890</b>
<b>Panda (141A) 1000 4x4</b>		<b>1986-92</b>
156 A3.000		37 50
Ignition Leads		<b>83890</b>
Ignition Leads Engine 5524923->		<b>85280</b>
<b>Panda (141A) 1000 4x4</b>		<b>1986-94</b>
141 C2.000/156 A2.246		33 45
Ignition Coil		<b>80217</b>
Ignition Leads Engine 5524923->		<b>85280</b>
Ignition Leads Engine 5524924->; 07.1990-04.1992		<b>85625</b>
<b>Panda (141A) 1000 i.e. KAT</b>		<b>1987-98</b>
141 C2.000/156 A2.246		33 45
Ignition Coil 156 A2.246; 07.1990-03.1997		<b>80217</b>
Ignition Coil 141 C2.000; 01.1995->		<b>80217</b>
Ignition Coil 156 A2.246; ->06.1990		<b>80265</b>
Ignition Leads Engine 5524923->		<b>85280</b>
Ignition Leads 156 A2.246<M7/M16>; Engine 5524924->		<b>85625</b>
<b>Panda (141A) 1100</b>		<b>1991-99</b>
156 C.046		37 50
Ignition Coil 156 C.046		<b>80217</b>
Ignition Coil		<b>80265</b>
Ignition Leads Engine 5524924->; 01.1993-03.1997		<b>85625</b>
<b>Panda (141A) 1100</b>		<b>1995-03</b>
187 A1.000/176 B2.000		40 54
Ignition Coil		<b>80217</b>
Ignition Leads		<b>85280</b>
Ignition Leads Engine 5524924->		<b>85625</b>
<b>Panda (141A) 1100 4x4</b>		<b>1995-04</b>
176 B2.000		40 54
Ignition Coil 176 B2.000		<b>80217</b>
Ignition Leads		<b>85280</b>
Ignition Leads Engine 5524924->; ->09.2003		<b>85625</b>
<b>Panda (141A) 1100 Trekking 4x4</b>		<b>1991-04</b>
156 C.046		37 50
Ignition Coil 156 C.046		<b>80217</b>
Ignition Coil		<b>80265</b>
Ignition Leads Engine 5524924->; 01.1993-12.1994		<b>85625</b>
<b>Panda (141A) 750</b>		<b>1986-03</b>
156 A4.000		25 34
Ignition Leads With ignition distributor		<b>83890</b>
<b>Panda (141A) 800</b>		<b>1981-85</b>
100 GL6.000		25 34
Ignition Leads		<b>83910</b>
<b>Panda (141A) 900</b>		<b>1992-96</b>
1170 A1.046		29 40
Ignition Coil 1170 A1.046		<b>80217</b>
Ignition Leads		<b>85250</b>
<b>Panda (141A) 950 4x4</b>		<b>1983-86</b>
A 112 B1.054		35 48
Ignition Leads A 112 B1.054		<b>83030</b>
<b>Panda (169) 1.1</b>		<b>2003-&gt;</b>
187 A1.000		40 54
Ignition Coil 187 A1.000		<b>80217</b>
Ignition Leads		<b>85625</b>
<b>Panda (169) 1.2</b>		<b>2003-&gt;</b>
188 A4.000		44 60
Ignition Coil 188 A4.000		<b>80217</b>
Ignition Leads		<b>85625</b>
<b>Panda (169) 1.2</b>		<b>2010-&gt;</b>
169 A4.000		51 69
Ignition Coil OE 55208723; OE 55200112; OE 55200486		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Panda (169) 1.2 4x4</b>		<b>2009-&gt;</b>
169 A4.000		51 69
Ignition Coil OE 55200112 OE 55200486 OE 55208723		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Panda (169) 1.2 4x4</b>		<b>2004-&gt;</b>
188 A4.000		44 60
Ignition Coil 188 A4.000		<b>80217</b>
Ignition Leads		<b>85625</b>
<b>Panda (169) 1.2 Bi-Power / Natural Power</b>		<b>2007-09</b>
188 A4.000		44 60
Ignition Coil		<b>80217</b>
Ignition Leads		<b>85626</b>
<b>Panda (169) 1.2 LPG</b>		<b>2009-&gt;</b>
188 A4.000		44 60
Ignition Coil ->12.2012		<b>80217</b>
<b>Panda Van (169) 1.2 LPG</b>		<b>2010-&gt;</b>
169 A4.000		51 69
Ignition Coil OE 55208723; OE 55200112; OE 55200486		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Panda Van (169) 1.2 Natural Power</b>		<b>2007-09</b>
188 A4.000		44 60
Ignition Coil		<b>80217</b>
<b>Panda Van (169) 1.4 Natural Power</b>		<b>2009-&gt;</b>
350 A1.000		57 78
Ignition Coil		<b>80233</b>
Ignition Leads		<b>80340</b>
<b>Panda Van (312) 0.9</b>		<b>2012-&gt;</b>
312 A4.000		48 65
Ignition Coil		<b>80233</b>
Ignition Leads		<b>1985-96</b>
<b>Premio 1.5</b>		49 67
146 D1.011		<b>80217</b>
Ignition Coil 06.1992-09.1994		<b>80217</b>
<b>Premio 1.6</b>		<b>1985-96</b>
159 A3.000		62 84
Ignition Coil		<b>80217</b>
Ignition Leads ->Engine 2888158		<b>85625</b>

FIAT Cont.		
<b>Panda (169) 1.2 LPG</b>		<b>2009-&gt;</b>
188 A4.000		44 60
Ignition Coil		<b>80217</b>
Ignition Leads ->Engine 2888158		<b>85625</b>
<b>Panda (169) 1.2 LPG</b>		<b>2010-&gt;</b>
169 A4.000		51 69
Ignition Coil		<b>80217</b>
Ignition Coil OE 55200486; OE 55200112; OE 55208723		<b>80340</b>
<b>Panda (169) 1.4</b>		<b>2006-&gt;</b>
169 A3.000		74 100
Ignition Coil		<b>80233</b>
<b>Panda (169) 1.4 Bi-Power / Natural Power</b>		<b>2010-&gt;</b>
350 A1.000		57 78
Ignition Coil		<b>80340</b>
<b>Panda (519, 319) 0.9</b>		<b>2013-&gt;</b>
312 A4.000		44 60
Ignition Coil		<b>80233</b>
<b>Panda (519, 319) 0.9</b>		<b>2013-&gt;</b>
312 A5.000		59 80
Ignition Coil		<b>80233</b>
<b>Panda (519, 319) 0.9</b>		<b>2012-&gt;</b>
312 A4.000		48 65
Ignition Coil		<b>80217</b>
Ignition Coil		<b>80233</b>
<b>Panda (519, 319) 1.2</b>		<b>2012-&gt;</b>
169 A4.000		51 69
Ignition Coil OE 55200486; OE 55208723; OE 55200112		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Panda (519, 319) 1.2 LPG</b>		<b>2012-&gt;</b>
169 A4.000		51 69
Ignition Coil		<b>80340</b>
<b>Panda Van (141) 1000</b>		<b>1986-92</b>
156 A3.100/156 A2.100		32 44
Ignition Leads		<b>83890</b>
<b>Panda Van (141) 1000 i.e</b>		<b>1992-04</b>
156 A2.246		33 45
Ignition Coil		<b>80217</b>
Ignition Coil ->03.1997		<b>80265</b>
Ignition Leads Engine 5524924->; ->03.1997		<b>85625</b>
<b>Panda Van (169) 1.1</b>		<b>2004-&gt;</b>
187 A1.000		40 54
Ignition Coil ->12.2011		<b>80217</b>
<b>Panda Van (169) 1.2</b>		<b>2010-&gt;</b>
169 A4.000		51 69
Ignition Leads		<b>85626</b>
<b>Panda Van (169) 1.2</b>		<b>2004-&gt;</b>
188 A4.000		44 60
Ignition Coil		<b>80217</b>
Ignition Leads		<b>85625</b>
<b>Panda Van (169) 1.2 4x4</b>		<b>2010-&gt;</b>
169 A4.000		51 69
Ignition Coil OE 55208723; OE 55200112; OE 55200486		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Panda Van (169) 1.2 4x4</b>		<b>2004-&gt;</b>
188 A4.000		44 60
Ignition Coil		<b>80217</b>
Ignition Leads		<b>85625</b>
<b>Panda Van (169) 1.2 LPG</b>		<b>2009-&gt;</b>
188 A4.000		44 60
Ignition Coil ->12.2012		<b>80217</b>
<b>Panda Van (169) 1.2 LPG</b>		<b>2010-&gt;</b>
169 A4.000		51 69
Ignition Coil OE 55208723; OE 55200112; OE 55200486		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Panda Van (169) 1.2 Natural Power</b>		<b>2007-09</b>
188 A4.000		44 60
Ignition Coil		<b>80217</b>
<b>Panda Van (169) 1.4 Natural Power</b>		<b>2009-&gt;</b>
350 A1.000		57 78
Ignition Coil		<b>80233</b>
Ignition Leads		<b>80340</b>
<b>Panda Van (312) 0.9</b>		<b>2012-&gt;</b>
312 A4.000		48 65
Ignition Coil		<b>80233</b>
<b>Premio 1.5</b>		<b>1985-96</b>
146 D1.011		49 67
Ignition Coil 06.1992-09.1994		<b>80217</b>
<b>Premio 1.6</b>		<b>1985-96</b>
159 A3.000		62 84
Ignition Coil		<b>80217</b>
Ignition Leads 10.1993-10.1994		<b>80217</b>



FIAT Cont.	
<b>Premio 1.6 i.e.</b>	<b>1993-96</b>
160 A2.011/146 B7.011	60 82
Ignition Coil 10.1993-10.1994	<b>80217</b>
<b>Punto (176) 1.2 16V</b>	<b>1997-99</b>
176 B9.000	63 86
Ignition Coil 176 B9.000	<b>80217</b>
Ignition Leads	<b>85647</b>
<b>Punto (176) 1.4 GT Turbo</b>	<b>1994-96</b>
176 A4.000	98 133
Ignition Coil	<b>80279</b>
<b>Punto (176) 1.4 GT Turbo</b>	<b>1996-99</b>
176 B6.000	96 131
Ignition Coil	<b>80279</b>
<b>Punto (176) 1.6</b>	<b>1994-97</b>
176 A9.000	65 88
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85650</b>
<b>Punto (176) 55 1.1</b>	<b>1993-99</b>
176 A6.000/176 B2.000	40 54
Ignition Coil	<b>80217</b>
Ignition Leads	<b>85280</b>
Ignition Leads ->08.1999	<b>85625</b>
<b>Punto (176) 60 1.2</b>	<b>1994-99</b>
176 A7.000	43 58
Ignition Coil 176 A7.000	<b>80217</b>
Ignition Leads ->05.1994	<b>85625</b>
<b>Punto (176) 60 1.2</b>	<b>1993-99</b>
176 B1.000/176 B4.000	44 60
Ignition Coil	<b>80217</b>
Ignition Leads 06.1994-08.1999	<b>85625</b>
<b>Punto (176) 75 1.2</b>	<b>1993-99</b>
176 A8.000	54 73
Ignition Coil 176 A8.000	<b>80217</b>
Ignition Leads ->08.1999	<b>85625</b>
<b>Punto (188) 1.2 16V 80</b>	<b>1999-06</b>
188 A5.000	59 80
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85648</b>
<b>Punto (188) 1.2 60</b>	<b>1999-10</b>
188 A4.000	44 60
Ignition Coil 188 A4.000	<b>80217</b>
Ignition Leads	<b>85625</b>
<b>Punto (188) 1.2 Natural Power</b>	<b>2003-12</b>
188 A4.000	44 60
Ignition Coil 188 A4.000	<b>80217</b>
Ignition Leads	<b>85625</b>
<b>Punto (188) 1.4</b>	<b>2003-12</b>
843 A1.000	70 95
Ignition Coil	<b>80233</b>
<b>Punto (188) 1.8 130 HGT</b>	<b>1999-12</b>
183 A1.000/188 A6.000	96 130
Ignition Coil	<b>80228</b>
<b>Punto (199) 1.2</b>	<b>2012-&gt;</b>
169 A4.000	51 69
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Punto (199) 1.4</b>	<b>2012-&gt;</b>
350 A1.000	57 78
Ignition Coil	<b>80340</b>
<b>Punto (199) 1.4</b>	<b>2012-&gt;</b>
199 A7.000	55 75
Ignition Coil	<b>80340</b>
<b>Punto (199) 1.4 Bifuel</b>	<b>2012-&gt;</b>
350 A1.000	57 78
Ignition Coil	<b>80340</b>
<b>Punto (199) 1.4 Natural Power</b>	<b>2012-&gt;</b>
350 A1.000	57 78
Ignition Coil	<b>80340</b>
<b>Punto / Grande Punto (199) 1.2</b>	<b>2005-&gt;</b>
199 A4.000	48 65
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Punto / Grande Punto (199) 1.2</b>	<b>2010-&gt;</b>
169 A4.000	51 69
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>

FIAT Cont.	
<b>Punto / Grande Punto (199) 1.4</b>	<b>2005-&gt;</b>
350 A1.000	57 77
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Punto / Grande Punto (199) 1.4</b>	<b>2006-&gt;</b>
199 A7.000	55 75
Ignition Coil	<b>80340</b>
<b>Punto / Grande Punto (199) 1.4 16V</b>	<b>2005-&gt;</b>
199 A6.000	70 95
Ignition Coil	<b>80233</b>
<b>Punto / Grande Punto (199) 1.4 LPG</b>	<b>2008-&gt;</b>
350 A1.000	57 78
Ignition Leads	<b>85626</b>
<b>Punto / Grande Punto (199) 1.4 Natural Power</b>	<b>2008-&gt;</b>
350 A1.000	57 78
Ignition Leads	<b>85626</b>
<b>Punto / Grande Punto (199) 1.4 T-Jet</b>	<b>2007-&gt;</b>
198 A4.000	88 120
Ignition Coil ->12.2009	<b>80267</b>
<b>Punto Cabriolet (176C) 60 1.2</b>	<b>1994-00</b>
176 A7.000	43 58
Ignition Coil 176 A7.000	<b>80217</b>
Ignition Leads ->04.1997	<b>85625</b>
<b>Punto Cabriolet (176C) 60 1.2</b>	<b>1995-00</b>
176 B1.000/176 B4.000	44 60
Ignition Coil	<b>80217</b>
Ignition Leads ->08.1999	<b>85625</b>
<b>Punto Cabriolet (176C) 85 16V 1.2</b>	<b>1997-00</b>
176 B9.000	63 86
Ignition Coil 176 B9.000	<b>80217</b>
Ignition Leads	<b>85647</b>
<b>Punto Cabriolet (176C) 90 1.6</b>	<b>1994-97</b>
176 A9.000	65 88
Ignition Leads	<b>85650</b>
<b>Punto Evo (199) 1.2</b>	<b>2009-12</b>
169 A4.000	51 69
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Punto Evo (199) 1.2</b>	<b>2009-12</b>
199 A4.000	48 65
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Punto Evo (199) 1.4</b>	<b>2009-12</b>
350 A1.000	57 77
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Punto Evo (199) 1.4</b>	<b>2009-12</b>
199 A7.000	55 75
Ignition Coil	<b>80340</b>
<b>Punto Evo (199) 1.4 16V</b>	<b>2009-12</b>
955 A6.000	77 105
Ignition Coil	<b>80266</b>
<b>Punto Evo (199) 1.4 LPG</b>	<b>2009-12</b>
350 A1.000	57 78
Ignition Coil	<b>80340</b>
<b>Punto Evo (199) 1.4 Natural Power</b>	<b>2009-12</b>
350 A1.000	57 78
Ignition Coil	<b>80340</b>
<b>Punto Van (176L) 1.1</b>	<b>1996-00</b>
176 B2.000	40 54
Ignition Coil 176 B2.000	<b>80217</b>
Ignition Leads ->08.1999	<b>85625</b>
<b>Punto Van (188AX) 1.2 60</b>	<b>2000-09</b>
188 A4.000	44 60
Ignition Coil 188 A4.000	<b>80217</b>
Ignition Leads	<b>85625</b>
<b>Punto Van (199) 1.4</b>	<b>2006-&gt;</b>
350 A1.000	57 78
Ignition Coil	<b>80340</b>
Ignition Leads	<b>85626</b>
<b>Punto Van (199) 1.4 LPG</b>	<b>2009-&gt;</b>
350 A1.000	57 78
Ignition Coil	<b>80340</b>
<b>Punto Van (199) 1.4 Natural Power</b>	<b>2009-&gt;</b>
350 A1.000	57 78
Ignition Coil	<b>80340</b>
<b>Qubo (225) 1.4 Natural Power</b>	<b>2009-&gt;</b>
350 A1.000	57 78
Ignition Coil	<b>80340</b>





FIAT Cont.		
<b>Regata (138) 100 Super 1.6</b>	1983-90	
149 A2.000/149 A4.000	74 101	
Ignition Leads 149 A2.000	<b>83060</b>	
<b>Regata (138) 70 1.3</b>	1983-86	
138 B2.000	50 68	
Ignition Leads	<b>83940</b>	
<b>Regata (138) 70 1.3</b>	1983-89	
149 A3.000/149 A7.000	48 65	
Ignition Leads	<b>83940</b>	
<b>Regata Weekend 100 1.6</b>	1984-90	
149 C3.000/149 A4.000	74 101	
Ignition Leads 149 A4.000	<b>83060</b>	
<b>Ritmo I (138A) 65 1.3</b>	1978-85	
149 A3.000/149 A7.000/138 A1.000	48 65	
Ignition Leads 138 A1.000	<b>83030</b>	
<b>Ritmo I (138A) 75 1.3</b>	1981-82	
138 A3.000	55 75	
Ignition Leads 138 A3.000	<b>83030</b>	
<b>Ritmo I (138A) 75 1.5</b>	1978-88	
138 C3.048/149 C1.000/138 A2.000/138 C2.048	55 75	
Ignition Leads 138 A2.000	<b>83030</b>	
<b>Ritmo II (138A) 85 1.5</b>	1983-87	
138 B3.000	60 82	
Ignition Leads 138 B3.000	<b>83030</b>	
<b>Scudo Combinato (220P) 1.6</b>	1996-06	
220 A 2.000	58 79	
Ignition Coil	<b>80279</b>	
<b>Scudo Combinato (220P) 2.0 16V</b>	2000-06	
RFN (EW10J4)	100 136	
Ignition Coil	<b>80275</b>	
<b>Scudo Van (220L) 1.6</b>	1996-06	
220 A 2.000	58 79	
Ignition Coil	<b>80279</b>	
<b>Scudo Van (220L) 2.0</b>	2000-06	
RFN (EW10J4)	100 136	
Ignition Coil	<b>80275</b>	
<b>Sedici 1.6 16V</b>	2006-14	
M16A	88 120	
Ignition Coil	<b>80268</b>	
Ignition Coil ->06.2009	<b>80343</b>	
<b>Sedici 1.6 16V</b>	2006-14	
M16A	79 107	
Ignition Coil	<b>80268</b>	
Ignition Coil ->06.2009	<b>80343</b>	
<b>Sedici 1.6 16V 4x4</b>	2006-14	
M16A	88 120	
Ignition Coil 09.2009->	<b>80268</b>	
Ignition Coil ->06.2009	<b>80343</b>	
<b>Sedici 1.6 16V 4x4</b>	2006-14	
M16A	79 107	
Ignition Coil	<b>80268</b>	
Ignition Coil ->06.2009	<b>80343</b>	
<b>Seicento (187) 0,9</b>	1998-10	
1170 A1.046	29 39	
Ignition Coil 1170 A1.046	<b>80217</b>	
Ignition Leads	<b>85250</b>	
<b>Seicento (187) 1,1</b>	1998-10	
187 A1.000/176 B2.000	40 54	
Ignition Coil	<b>80217</b>	
Ignition Leads	<b>85625</b>	
<b>Siena (178) 1.2</b>	1998-09	
178 B5.000	54 73	
Ignition Coil 178 B5.000	<b>80217</b>	
Ignition Leads	<b>85280</b>	
Ignition Leads ->10.2001	<b>85625</b>	
<b>Siena (178) 1.4</b>	1996-09	
178 B2.000	51 69	
Ignition Coil 178 B2.000	<b>80217</b>	
<b>Siena (178) 1.4 KAT</b>	1996-09	
178 B2.016	51 69	
Ignition Coil 178 B2.016	<b>80217</b>	
<b>Siena (178) 1.6 16V</b>	1998->	
178 B3.000	78 106	
Ignition Coil ->12.2001	<b>80280</b>	
Ignition Leads	<b>86050</b>	
<b>Stilo (192) 1.2 16V</b>	2002-06	
188 A5.000	59 80	
Ignition Coil 188 A5.000	<b>80233</b>	

FIAT Cont.		
<b>Stilo (192) 1.4 16V</b>	2004-06	
843 A1.000	70 95	
Ignition Coil 843 A1.000	<b>80233</b>	
<b>Stilo (192) 1.4 16V</b>	2005-06	
192 B2.000	66 90	
Ignition Coil	<b>80233</b>	
<b>Stilo (192) 1.6 16V</b>	2001-06	
182 B6.000	76 103	
Ignition Coil	<b>80256</b>	
<b>Stilo (192) 1.6 16V</b>	2005-06	
192 B3.000	77 105	
Ignition Coil	<b>80291</b>	
<b>Stilo (192) 1.8 16V</b>	2001-06	
192 A4.000	98 133	
Ignition Coil	<b>80228</b>	
<b>Stilo Multi Wagon (192) 1.4 16V</b>	2004-08	
843 A1.000	70 95	
Ignition Coil	<b>80233</b>	
<b>Stilo Multi Wagon (192) 1.4 16V</b>	2005-08	
192 B2.000	66 90	
Ignition Coil	<b>80233</b>	
<b>Stilo Multi Wagon (192) 1.6 16V</b>	2003-08	
182 B6.000	76 103	
Ignition Coil	<b>80256</b>	
<b>Stilo Multi Wagon (192) 1.6 16V</b>	2005-07	
192 B3.000	77 105	
Ignition Coil	<b>80291</b>	
<b>Stilo Multi Wagon (192) 1.8 16V</b>	2003-08	
192 A4.000	98 133	
Ignition Coil	<b>80228</b>	
<b>Strada Pick-Up (178E) 1.2</b>	1999-06	
178 B5.000	54 73	
Ignition Coil 178 B5.000	<b>80217</b>	
Ignition Leads ->03.2005	<b>85625</b>	
<b>Strada Pick-Up (178E) 1.2</b>	2003->	
188 A4.000	44 60	
Ignition Coil 188 A4.000	<b>80217</b>	
Ignition Leads	<b>85625</b>	
<b>Tempra (159) 1.4 i.e.</b>	1990-96	
836 A4.000/160 A1.046/159 A2.000	51 69	
Ignition Coil	<b>80265</b>	
Ignition Coil	<b>80279</b>	
Ignition Leads ->Engine 8503994	<b>85270</b>	
Ignition Leads Engine 8503994->	<b>85271</b>	
<b>Tempra (159) 1.4 i.e.</b>	1991-96	
159 A2.000	57 78	
Ignition Coil	<b>80265</b>	
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>83940</b>	
<b>Tempra (159) 1.6</b>	1990-96	
159 B9.000/159 A3.000	63 86	
Ignition Leads	<b>85271</b>	
<b>Tempra (159) 1.6 i.e.</b>	1992-96	
159 A3.048/835 C1.000	55 75	
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>85271</b>	
<b>Tempra (159) 1.6 i.e.</b>	1990-92	
159 A3.046	57 78	
Ignition Leads	<b>85271</b>	
<b>Tempra (159) 1.6 i.e.</b>	1994-96	
159 B9.000	66 90	
Ignition Coil	<b>80279</b>	
Ignition Leads	<b>85650</b>	
<b>Tempra (159) 1.6 i.e.</b>	1994-96	
159 B9.000	63 87	
Ignition Leads	<b>85650</b>	
<b>Tempra (159) 1.8 i.e.</b>	1992-96	
159 A4.046	77 105	
Ignition Coil	<b>80217</b>	
<b>Tempra (159) 1.8 i.e.</b>	1994-96	
836 A5.000	74 101	
Ignition Coil 836 A5.000	<b>80217</b>	
<b>Tempra (159) 1.8 i.e.</b>	1993-96	
835 C2.000	76 103	
Ignition Coil 835 C2.000	<b>80217</b>	
<b>Tempra (159) 1.8 i.e.</b>	1993-96	
835 C4.000	66 90	
Ignition Coil 835 C4.000	<b>80217</b>	



FIAT Cont.		
<b>Tempra (159) 1.8 i.e.</b>		<b>1990-96</b>
159 A4.000	81 110	
Ignition Coil		<b>80217</b>
<b>Tempra (159) 2.0 i.e.</b>		<b>1990-96</b>
159 A6.046	83 113	
Ignition Leads		<b>83040</b>
<b>Tempra S.W. (159) 1.4 i.e.</b>		<b>1992-96</b>
836 A4.000/160 A1.046/159 A2.000	51 69	
Ignition Coil		<b>80265</b>
Ignition Coil		<b>80279</b>
Ignition Leads ->Engine 8503995; 160 A1.046<M2>; ->03.1993		<b>85271</b>
<b>Tempra S.W. (159) 1.6</b>		<b>1990-93</b>
159 A3.000	63 86	
Ignition Leads		<b>85271</b>
<b>Tempra S.W. (159) 1.6 i.e.</b>		<b>1992-96</b>
159 A3.048/835 C1.000	55 75	
Ignition Coil		<b>80279</b>
Ignition Leads		<b>85271</b>
<b>Tempra S.W. (159) 1.6 i.e.</b>		<b>1990-96</b>
159 A3.046/835 C1.000	57 78	
Ignition Leads		<b>85271</b>
<b>Tempra S.W. (159) 1.6 i.e.</b>		<b>1994-96</b>
159 B9.000	66 90	
Ignition Leads		<b>85650</b>
<b>Tempra S.W. (159) 1.8 i.e.</b>		<b>1992-93</b>
159 A4.046	77 105	
Ignition Coil		<b>80217</b>
<b>Tempra S.W. (159) 1.8 i.e.</b>		<b>1994-96</b>
836 A5.000	74 101	
Ignition Coil 836 A5.000		<b>80217</b>
<b>Tempra S.W. (159) 1.8 i.e.</b>		<b>1993-96</b>
835 C2.000	76 103	
Ignition Coil 835 C2.000		<b>80217</b>
<b>Tempra S.W. (159) 1.8 i.e.</b>		<b>1993-96</b>
835 C4.000	66 90	
Ignition Coil 835 C4.000		<b>80217</b>
<b>Tempra S.W. (159) 1.8 i.e.</b>		<b>1990-96</b>
159 A4.000	81 110	
Ignition Leads		<b>83040</b>
<b>Tipo (160) 1,1</b>		<b>1988-91</b>
160 A3.000	41 56	
Ignition Coil		<b>80265</b>
Ignition Leads		<b>83890</b>
<b>Tipo (160) 1,4</b>		<b>1987-89</b>
160 A1.000/160 A1.048	52 71	
Ignition Coil		<b>80265</b>
<b>Tipo (160) 1,6</b>		<b>1988-91</b>
160 A2.000	61 83	
Ignition Leads ->03.1990		<b>85271</b>
<b>Tipo (160) 1.4 i.e.</b>		<b>1989-95</b>
159 A2.000	57 78	
Ignition Coil		<b>80265</b>
Ignition Leads		<b>85271</b>
<b>Tipo (160) 1.4 i.e.</b>		<b>1989-95</b>
836 A4.000/160 A1.046	51 70	
Ignition Coil		<b>80265</b>
Ignition Coil		<b>80279</b>
Ignition Leads		<b>85271</b>
<b>Tipo (160) 1.6 i.e.</b>		<b>1992-95</b>
159 A3.048/835 C1.000	55 75	
Ignition Coil		<b>80279</b>
Ignition Leads		<b>85271</b>
<b>Tipo (160) 1.6 i.e.</b>		<b>1990-93</b>
159 A3.046	57 78	
Ignition Leads		<b>85271</b>
<b>Tipo (160) 1.6 i.e.</b>		<b>1988-91</b>
149 C2.046	66 90	
Ignition Leads		<b>85271</b>
<b>Tipo (160) 1.8 i.e.</b>		<b>1993-95</b>
836 A5.000	71 97	
Ignition Coil		<b>80217</b>
<b>Tipo (160) 1.8 i.e.</b>		<b>1990-93</b>
159 A4.000	81 110	
Ignition Coil		<b>80217</b>
Ignition Leads		<b>83040</b>
<b>Tipo (160) 1.8 i.e.</b>		<b>1993-95</b>
835 C2.000	76 103	
Ignition Coil 835 C2.000		<b>80217</b>

FIAT Cont.		
<b>Tipo (160) 1.8 i.e.</b>		<b>1994-95</b>
836 A5.000/159 A4.000	74 101	
Ignition Coil		<b>80217</b>
Ignition Leads		<b>83040</b>
<b>Tipo (160) 1.8 i.e.</b>		<b>1993-95</b>
835 C4.000	66 90	
Ignition Coil 835 C4.000		<b>80217</b>
Ignition Leads		<b>85271</b>
<b>Tipo (160) 1.8 i.e.</b>		<b>1990-93</b>
159 A4.046	77 105	
Ignition Coil		<b>80217</b>
Ignition Leads		<b>83040</b>
<b>Tipo (160) 1.8 i.e.16V Sport</b>		<b>1989-92</b>
160 A5.000	100 136	
Ignition Leads Without A.C.		<b>85610</b>
<b>Tipo (160) 2.0 16V</b>		<b>1991-95</b>
160 A8.046	107 146	
Ignition Leads		<b>85610</b>
<b>Tipo (160) 2.0 i.e.</b>		<b>1990-92</b>
159 A5.046	80 109	
Ignition Leads		<b>83040</b>
<b>Tipo (160) 2.0 i.e.</b>		<b>1990-95</b>
159 A6.046	83 113	
Ignition Leads		<b>83040</b>
<b>Tipo (160) 2.0 i.e. 16V Sport</b>		<b>1993-95</b>
836 A3.000	102 139	
Ignition Leads		<b>85610</b>
<b>Tipo Fastback (356) 1.4</b>		<b>2016-&gt;</b>
843 A1.000	70 95	
Ignition Coil		<b>80233</b>
<b>Tipo Kombi (356) 1.4</b>		<b>2016-&gt;</b>
843 A1.000	70 95	
Ignition Coil		<b>80233</b>
<b>Tipo Sedan (356) 1.4</b>		<b>2015-&gt;</b>
843 A1.000	70 95	
Ignition Coil		<b>80233</b>
<b>Ulysse (179AX) 2.0</b>		<b>2002-11</b>
RFN (EW10J4)	100 136	
Ignition Coil		<b>80275</b>
<b>Ulysse (179AX) 3.0</b>		<b>2002-11</b>
XFW	150 204	
Ignition Coil		<b>80309</b>
<b>Ulysse (220) 1,8</b>		<b>1997-02</b>
LFW	73 99	
Ignition Coil LFW		<b>80207</b>
Ignition Leads		<b>83330</b>
Ignition Leads		<b>85010</b>
<b>Ulysse (220) 2.0</b>		<b>1994-02</b>
RFU (XU10J2C)	89 121	
Ignition Coil RFU (XU10J2C)		<b>80207</b>
Ignition Leads		<b>83330</b>
<b>Ulysse (220) 2.0 16V</b>		<b>1998-00</b>
RFV	97 132	
Ignition Coil		<b>80274</b>
<b>Ulysse (220) 2.0 16V</b>		<b>2000-02</b>
RFN (EW10J4)	100 136	
Ignition Coil		<b>80275</b>
<b>Ulysse (220) 2.0 Turbo</b>		<b>1994-02</b>
RGX (XU10J2CTE)	108 147	
Ignition Coil RGX (XU10J2CTE)		<b>80207</b>
Ignition Leads		<b>83330</b>
<b>Uno (146A/E) 1.6 R</b>		<b>1992-95</b>
159 A3.048	66 90	
Ignition Coil		<b>80279</b>
<b>Uno (146A/E) 45 0.9</b>		<b>1983-92</b>
146 A.000/146 A1.000	33 45	
Ignition Leads		<b>83910</b>
<b>Uno (146A/E) 45 1.0</b>		<b>1986-93</b>
156 A2.048/156 A2.100	32 44	
Ignition Coil		<b>80265</b>
Ignition Leads		<b>83890</b>
<b>Uno (146A/E) 45 i.e. 1.0</b>		<b>1984-95</b>
156 A2.246	33 45	
Ignition Coil		<b>80265</b>
Ignition Leads		<b>83890</b>
<b>Uno (146A/E) 50 1.1</b>		<b>1986-89</b>
146 A4.044	37 50	
Ignition Leads		<b>83890</b>



FIAT Cont.	
<b>Uno (146A/E) 50 1.1</b>	<b>1990-93</b>
156 C.046	37 50
Ignition Coil	<b>80265</b>
Ignition Leads With ignition distributor	<b>83890</b>
Ignition Leads	<b>83940</b>
<b>Uno (146A/E) 50 i.e. 1.1</b>	<b>1992-93</b>
146 C3.000	36 49
Ignition Coil	<b>80265</b>
Ignition Leads	<b>83890</b>
<b>Uno (146A/E) 60 1.1</b>	<b>1989-92</b>
160 A3.000	42 57
Ignition Coil	<b>80265</b>
Ignition Leads	<b>83890</b>
<b>Uno (146A/E) 60 1.1</b>	<b>1985-89</b>
146 A4.048	43 58
Ignition Coil	<b>80265</b>
<b>Uno (146A/E) 70 1.3</b>	<b>1985-89</b>
149 A7.000	48 65
Ignition Leads	<b>83900</b>
<b>Uno (146A/E) 70 1.3</b>	<b>1983-85</b>
138 B2.000	50 68
Ignition Leads	<b>83900</b>
<b>Uno (146A/E) 70 i.e. 1.4</b>	<b>1989-96</b>
160 A1.046	51 70
Ignition Leads	<b>85271</b>
<b>Uno (146A/E) 70 S 1.4</b>	<b>1989-92</b>
160 A1.048	52 71
Ignition Leads	<b>85271</b>
<b>Uno (146A/E) 75 i.e. 1.5</b>	<b>1985-93</b>
149 C1.000/138 C2.048	55 75
Ignition Coil	<b>80265</b>

FORD	
<b>B-Max 1.4</b>	<b>2012-&gt;</b>
SPJD	66 90
Ignition Coil	<b>80284</b>
<b>B-Max 1.4 LPG</b>	<b>2013-&gt;</b>
RTJC	63 86
Ignition Coil 03.2014->	<b>80284</b>
<b>B-Max 1.4 LPG</b>	<b>2013-&gt;</b>
RTJC	66 90
Ignition Coil 03.2014->	<b>80284</b>
<b>B-Max 1.6 Ti</b>	<b>2012-&gt;</b>
IQJA	77 105
Ignition Coil	<b>80284</b>
<b>Capri (ECJ) 1300</b>	<b>1971-72</b>
EV 13 H	39 53
Ignition Leads	<b>83400</b>
<b>Capri (ECJ) 1300</b>	<b>1972-73</b>
JA	40 55
Ignition Leads	<b>83400</b>
<b>Capri (ECJ) 1300</b>	<b>1973-73</b>
JA	43 59
Ignition Leads	<b>83400</b>
<b>Capri (ECJ) 1300</b>	<b>1968-72</b>
EV 13 L	37 50
Ignition Leads	<b>83400</b>
<b>Capri (ECJ) 1500</b>	<b>1968-74</b>
EX	44 60
Ignition Leads	<b>83400</b>
<b>Capri (ECJ) 1500</b>	<b>1968-74</b>
EV 15 H	48 65
Ignition Leads	<b>83400</b>
<b>Capri (ECJ) 1600</b>	<b>1972-74</b>
LE	65 88
Ignition Leads	<b>83400</b>
<b>Capri (ECJ) 1600</b>	<b>1972-74</b>
OHC TL 16 H	53 72
Ignition Leads	<b>83400</b>
<b>Capri (ECJ) 1600 GT</b>	<b>1969-72</b>
	60 82
Ignition Leads	<b>83400</b>
<b>Capri II (GCEP) 1.3</b>	<b>1974-77</b>
J1E	40 54
Ignition Leads	<b>83400</b>
<b>Capri II (GCEP) 1.3</b>	<b>1974-77</b>
J1E	42 57
Ignition Leads	<b>83400</b>

FORD Cont.	
<b>Capri II (GCEP) 1.6</b>	<b>1974-77</b>
LEC	65 88
Ignition Leads	<b>83400</b>
<b>Capri II (GCEP) 1.6</b>	<b>1974-77</b>
LAC	50 68
Ignition Leads	<b>83400</b>
<b>Capri II (GCEP) 1.6</b>	<b>1974-77</b>
LCE	53 72
Ignition Leads	<b>83400</b>
<b>Capri III (GCEP) 1.3</b>	<b>1978-85</b>
J1E	40 54
Ignition Leads	<b>83400</b>
<b>Capri III (GCEP) 1.6</b>	<b>1978-87</b>
LCN	54 73
Ignition Leads	<b>83400</b>
<b>Capri III (GCEP) 2.0</b>	<b>1978-85</b>
	64 87
Ignition Leads	<b>83400</b>
<b>Capri III (GCEP) 2.0</b>	<b>1978-82</b>
NYL	66 90
Ignition Leads	<b>83400</b>
<b>Capri III (GCEP) 2.0</b>	<b>1978-85</b>
NEN/OHC TL 20 H	74 101
Ignition Leads	<b>83400</b>
<b>C-Max (DM2) 1.6</b>	<b>2007-10</b>
SHDA/HWDB/SHDB/HWDA/SHDC	74 100
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>C-Max (DM2) 1.8</b>	<b>2007-10</b>
QQDA/QQDB	92 125
Ignition Coil	<b>80231</b>
<b>C-Max (DM2) 1.8 Flexifuel</b>	<b>2007-10</b>
Q7DA	92 125
Ignition Coil	<b>80231</b>
<b>C-Max (DM2) 2.0</b>	<b>2007-10</b>
AODA/AODB/SYDA/AODE	107 145
Ignition Coil	<b>80231</b>
<b>C-Max II (DXA/CB7, DXA/CEU) 1.6 Ti</b>	<b>2012-&gt;</b>
MUDA	88 120
Ignition Coil MUDD<Euro 6>	<b>80284</b>
<b>C-Max II 1.6 EcoBoost</b>	<b>2010-&gt;</b>
JQDA/JQDB	110 150
Ignition Coil	<b>80284</b>
<b>C-Max II 1.6 EcoBoost</b>	<b>2010-&gt;</b>
JTDB/JTDA	134 182
Ignition Coil	<b>80284</b>
<b>C-Max II 1.6 Flexifuel</b>	<b>2011-&gt;</b>
MUDA	88 120
Ignition Coil MUDD<Euro 6>	<b>80284</b>
Ignition Leads	<b>85115</b>
<b>C-Max II 1.6 LPG</b>	<b>2012-&gt;</b>
MUDA	86 117
Ignition Coil MUDD<Euro 6>	<b>80284</b>
<b>C-Max II 1.6 LPG</b>	<b>2012-&gt;</b>
MUDA	88 120
Ignition Coil MUDD<Euro 6>	<b>80284</b>
<b>C-Max II 1.6 Ti</b>	<b>2010-&gt;</b>
XTDA	63 85
Ignition Coil 08.2011->	<b>80284</b>
<b>C-Max II 1.6 Ti</b>	<b>2010-&gt;</b>
PNDA	92 125
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>C-Max II 1.6 Ti</b>	<b>2010-&gt;</b>
IQDB/IQDA	77 105
Ignition Coil ->03.2015	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Cougar (EC) 2.0 16V</b>	<b>1998-01</b>
EDBB/EDBC/EDBD/EDBA	96 131
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil ->12.2000	<b>80285</b>
<b>Cougar (EC) 2.5 ST 200</b>	<b>2000-01</b>
SGA	151 205
Ignition Coil	<b>80306</b>
Ignition Leads	<b>85127</b>



FORD Cont.	
<b>Cougar (EC) 2.5 V6 24V</b>	<b>2000-01</b>
LCBC/LCBB/LCBE	125 170
Ignition Coil	<b>80306</b>
Ignition Leads	<b>85127</b>
<b>Cougar (EC) 2.5 V6 24V</b>	<b>1998-01</b>
LCBA	125 170
Ignition Coil	<b>80306</b>
Ignition Leads	<b>85127</b>
<b>Ecosport 1.5 Ti</b>	<b>2013-&gt;</b>
UEJB	82 112
Ignition Coil	<b>80284</b>
<b>Escort '86 Express (AVF) 1.1</b>	<b>1986-90</b>
GSG	37 50
Ignition Coil	<b>80213</b>
<b>Escort '86 Express (AVF) 1.3</b>	<b>1986-90</b>
JLA/JBB/JLB	44 60
Ignition Coil	<b>80213</b>
Ignition Leads JBB	<b>83450</b>
<b>Escort '86 Express (AVF) 1.3</b>	<b>1988-90</b>
JBA	46 63
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort '86 Express (AVF) 1.4 i</b>	<b>1986-90</b>
F6D/F6B/FUC	54 73
Ignition Coil	<b>80213</b>
<b>Escort '91 Express (AVL) 1.3</b>	<b>1990-94</b>
JBD	46 63
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort '91 Express (AVL) 1.4</b>	<b>1990-94</b>
F6F/F6G	52 71
Ignition Coil	<b>80213</b>
<b>Escort '95 Express (AVL) 1.4</b>	<b>1995-00</b>
F4B	54 73
Ignition Coil	<b>80213</b>
<b>Escort Classic (AAL, ABL) 1.6 16V</b>	<b>1998-00</b>
L1E	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Escort Classic Turnier (ANL) 1.6 16V</b>	<b>1999-00</b>
L1E	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Escort II (ATH) 2.0 RS</b>	<b>1975-80</b>
NE	80 110
Ignition Leads	<b>83400</b>
<b>Escort II (ATH) 2.0 RS</b>	<b>1973-77</b>
NE	73 100
Ignition Leads	<b>83400</b>
<b>Escort III (GAA) RS 1600i</b>	<b>1982-85</b>
LUAE	85 115
Ignition Leads	<b>83450</b>
<b>Escort III Break (AWA) 1.6</b>	<b>1980-85</b>
LP1/LPA	58 79
Ignition Leads	<b>83450</b>
<b>Escort III Cabriolet (ALD) 1.6</b>	<b>1983-85</b>
LP1/LPA	58 79
Ignition Leads	<b>83450</b>
<b>Escort III Cabriolet (ALD) 1.6 i</b>	<b>1983-85</b>
LRA/LR1	77 105
Ignition Leads	<b>83450</b>
<b>Escort IV (GAF, AWF, ABFT) 1,3</b>	<b>1988-90</b>
JBA	46 63
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV (GAF, AWF, ABFT) 1.3</b>	<b>1986-90</b>
JLA/JBB/JLB	44 60
Ignition Coil 08.1988->	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV (GAF, AWF, ABFT) 1.4</b>	<b>1986-90</b>
F6D/F6B/FUC	54 73
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV (GAF, AWF, ABFT) 1.4</b>	<b>1986-90</b>
FUA	55 75
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV (GAF, AWF, ABFT) 1.4</b>	<b>1985-90</b>
FUAA	51 70
Ignition Leads ->12.1987	<b>83400</b>

FORD Cont.	
<b>Escort IV (GAF, AWF, ABFT) 1.6</b>	<b>1989-90</b>
LUG	65 88
Ignition Coil	<b>80213</b>
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Escort IV (GAF, AWF, ABFT) 1.6 i</b>	<b>1986-90</b>
L4B	66 90
Ignition Coil	<b>80213</b>
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Escort IV (GAF, AWF, ABFT) 1.6 i</b>	<b>1989-90</b>
LJB	75 102
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV (GAF, AWF, ABFT) 1.6 Turbo RS</b>	<b>1986-90</b>
LNB	97 132
Ignition Coil	<b>80213</b>
<b>Escort IV (GAF, AWF, ABFT) 1.6 XR3i</b>	<b>1986-89</b>
LRB/LR2	77 105
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV Break (AWF, AVF) 1.3</b>	<b>1986-90</b>
JLA/JBB/JLB	44 60
Ignition Coil 08.1988->	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV Break (AWF, AVF) 1.4</b>	<b>1986-90</b>
F6D/F6B/FUC	54 73
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV Break (AWF, AVF) 1.4</b>	<b>1986-90</b>
FUA	55 75
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV Break (AWF, AVF) 1.6 i</b>	<b>1986-90</b>
L4B	66 90
Ignition Coil	<b>80213</b>
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Escort IV Cabriolet (ALF) 1.4</b>	<b>1987-90</b>
F6D/F6B/FUC	54 73
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV Cabriolet (ALF) 1.4</b>	<b>1986-90</b>
FUA	55 75
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV Cabriolet (ALF) 1.6</b>	<b>1986-87</b>
LP2/LPA	58 79
Ignition Leads	<b>83400</b>
<b>Escort IV Cabriolet (ALF) 1.6 i</b>	<b>1986-90</b>
L4B	66 90
Ignition Coil	<b>80213</b>
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Escort IV Cabriolet (ALF) 1.6 i</b>	<b>1989-90</b>
LJB	75 102
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort IV Cabriolet (ALF) 1.6 XR3i</b>	<b>1986-90</b>
LRB/LR2	77 105
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort V (GAL) 1.3</b>	<b>1990-92</b>
J6A/J4B	44 60
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Escort V (GAL) 1.4</b>	<b>1990-92</b>
F6F/F6G	52 71
Ignition Coil	<b>80213</b>
Ignition Leads	<b>85110</b>
<b>Escort V (GAL) 1.6</b>	<b>1990-92</b>
LJF	77 105
Ignition Coil	<b>80213</b>
Ignition Leads	<b>85110</b>
<b>Escort V (GAL) 1.6</b>	<b>1990-92</b>
LUJ/LUK	66 90
Ignition Coil	<b>80213</b>



FORD Cont.		
<b>Escort V (GAL) 1.8 16V XR3i</b>		<b>1992-92</b>
RDA		77 105
Ignition Coil With regul.cat.(3way)		<b>80213</b>
Ignition Leads		<b>85110</b>
<b>Escort V (GAL) 1.8 16V XR3i</b>		<b>1992-92</b>
RQB		96 130
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort V (GAL) RS 2000</b>		<b>1991-92</b>
N7A		110 150
Ignition Coil		<b>80305</b>
<b>Escort V Break (GAL, AVL) 1.3</b>		<b>1991-92</b>
J6A/J4B		44 60
Ignition Coil		<b>80213</b>
Ignition Leads		<b>83450</b>
<b>Escort V Break (GAL, AVL) 1.4</b>		<b>1990-92</b>
F6F/F6G		52 71
Ignition Coil		<b>80213</b>
<b>Escort V Break (GAL, AVL) 1.6</b>		<b>1990-92</b>
LJF		77 105
Ignition Coil		<b>80213</b>
<b>Escort V Break (GAL, AVL) 1.6</b>		<b>1990-92</b>
LUJ/LUK		66 90
Ignition Coil		<b>80213</b>
<b>Escort V Break (GAL, AVL) 1.8 16V</b>		<b>1992-92</b>
RDA		77 105
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort V Cabriolet (ALL) 1.4</b>		<b>1990-92</b>
F6F/F6G		52 71
Ignition Coil		<b>80213</b>
<b>Escort V Cabriolet (ALL) 1.6</b>		<b>1990-92</b>
LJF		77 105
Ignition Coil		<b>80213</b>
<b>Escort V Cabriolet (ALL) 1.8 16V XR3i</b>		<b>1992-92</b>
RDA		77 105
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort V Cabriolet (ALL) 1.8 16V XR3i</b>		<b>1992-92</b>
RQB		96 130
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI (GAL) 1.3</b>		<b>1992-95</b>
J6A/J4B		44 60
Ignition Coil		<b>80213</b>
Ignition Leads		<b>83450</b>
<b>Escort VI (GAL) 1.4</b>		<b>1992-95</b>
F6F/F6G		52 71
Ignition Coil		<b>80213</b>
Ignition Leads		<b>85110</b>
<b>Escort VI (GAL) 1.4</b>		<b>1994-95</b>
F4B/FUH		55 75
Ignition Coil		<b>80213</b>
Ignition Leads		<b>85110</b>
<b>Escort VI (GAL) 1.6 i 16V</b>		<b>1992-95</b>
L1E		66 90
Ignition Coil With regul.cat.(3way)		<b>80213</b>
Ignition Leads		<b>85120</b>
<b>Escort VI (GAL) 1.6 i 16V</b>		<b>1994-95</b>
L1H		65 88
Ignition Coil With regul.cat.(3way)		<b>80213</b>
Ignition Leads		<b>85120</b>
<b>Escort VI (GAL) 1.8 16V XR3i</b>		<b>1992-95</b>
RQB		96 130
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI (GAL) 1.8 i 16V</b>		<b>1992-95</b>
RDA		77 105
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI (GAL) 1.8 XR3i 16V 4x4</b>		<b>1993-95</b>
RDA		77 105
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI (GAL) 1.8 XR3i 16V 4x4</b>		<b>1993-95</b>
RQB		96 130
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI (GAL) RS 2000</b>		<b>1992-95</b>
N7A		110 150
Ignition Coil		<b>80305</b>
<b>Escort VI (GAL) RS 2000 4x4</b>		<b>1993-95</b>
N7A		110 150
Ignition Coil		<b>80305</b>

FORD Cont.		
<b>Escort VI Break (GAL) 1.3</b>		<b>1992-95</b>
J6A/J4B		44 60
Ignition Coil		<b>80213</b>
Ignition Leads		<b>83450</b>
<b>Escort VI Break (GAL) 1.4</b>		<b>1992-95</b>
F6F/F6G		52 71
Ignition Coil		<b>80213</b>
<b>Escort VI Break (GAL) 1.4</b>		<b>1994-95</b>
F4B/FUH		55 75
Ignition Coil		<b>80213</b>
<b>Escort VI Break (GAL) 1.6 i 16V</b>		<b>1992-95</b>
L1E		66 90
Ignition Coil L1E; With regul.cat.(3way)		<b>80213</b>
<b>Escort VI Break (GAL) 1.6 i 16V</b>		<b>1994-95</b>
L1H		65 88
Ignition Coil		<b>80213</b>
<b>Escort VI Break (GAL) 1.8 i 16V</b>		<b>1993-95</b>
RDA		77 105
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI Break (GAL) 1.8 i 16V</b>		<b>1993-95</b>
RQB		96 130
Ignition Coil RQB; With regul.cat.(3way)		<b>80213</b>
<b>Escort VI Cabriolet (ALL) 1.4</b>		<b>1992-94</b>
F6F/F6G		52 71
Ignition Coil		<b>80213</b>
<b>Escort VI Cabriolet (ALL) 1.4 i</b>		<b>1993-95</b>
F4B		55 75
Ignition Coil		<b>80213</b>
<b>Escort VI Cabriolet (ALL) 1.6 16V XR3i</b>		<b>1992-95</b>
L1E		66 90
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI Cabriolet (ALL) 1.6 i 16V</b>		<b>1994-95</b>
L1H		65 88
Ignition Coil		<b>80213</b>
<b>Escort VI Cabriolet (ALL) 1.8 16V XR3i</b>		<b>1992-95</b>
RQB		96 130
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI Cabriolet (ALL) 1.8 16V XR3i</b>		<b>1992-95</b>
RDA		77 105
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI Sedan (GAL) 1.3</b>		<b>1993-95</b>
J6A/J4B		44 60
Ignition Coil		<b>80213</b>
Ignition Leads		<b>83450</b>
<b>Escort VI Sedan (GAL) 1.4</b>		<b>1993-94</b>
F6F/F6G		52 71
Ignition Coil		<b>80213</b>
<b>Escort VI Sedan (GAL) 1.4</b>		<b>1993-95</b>
F4B/FUH		55 75
Ignition Coil		<b>80213</b>
<b>Escort VI Sedan (GAL) 1.6 i 16V</b>		<b>1993-95</b>
L1E/L1K		66 90
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VI Sedan (GAL) 1.6 i 16V</b>		<b>1994-95</b>
L1H		65 88
Ignition Coil		<b>80213</b>
<b>Escort VI Sedan (GAL) 1.8 i 16V</b>		<b>1993-95</b>
RDA		77 105
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Escort VII (GAL, AAL, ABL) 1.3</b>		<b>1995-98</b>
J6A/J4B		44 60
Ignition Coil ->08.1998		<b>80213</b>
Ignition Coil 09.1998->; With regul.cat.(3way)		<b>80214</b>
Ignition Coil 09.1998->		<b>80285</b>
Ignition Leads ->12.1997		<b>83450</b>
<b>Escort VII (GAL, AAL, ABL) 1.4</b>		<b>1995-98</b>
F4B		55 75
Ignition Coil		<b>80213</b>
Ignition Leads		<b>85110</b>
<b>Escort VII (GAL, AAL, ABL) 1.6 16V</b>		<b>1995-98</b>
L1E		66 90
Ignition Coil With regul.cat.(3way)		<b>80213</b>
Ignition Leads		<b>85120</b>
<b>Escort VII (GAL, AAL, ABL) 1.6 16V 4x4</b>		<b>1995-98</b>
L1E		66 90
Ignition Coil With regul.cat.(3way)		<b>80213</b>
Ignition Leads		<b>85120</b>





FORD Cont.	
<b>Escort VII (GAL, AAL, ABL) 1.6 i 16V</b>	<b>1995-95</b>
L1H	65 88
Ignition Coil	<b>80213</b>
Ignition Leads	<b>85120</b>
<b>Escort VII (GAL, AAL, ABL) 1.8 16V</b>	<b>1995-95</b>
RDA	77 105
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Escort VII (GAL, AAL, ABL) 1.8 16V</b>	<b>1995-98</b>
RKC	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Escort VII (GAL, AAL, ABL) RS 2000</b>	<b>1995-98</b>
N7A	110 150
Ignition Coil	<b>80305</b>
<b>Escort VII (GAL, AAL, ABL) RS 2000 4x4</b>	<b>1995-98</b>
N7A	110 150
Ignition Coil	<b>80305</b>
<b>Escort VII Cabriolet (ALL) 1.4</b>	<b>1995-98</b>
F4B	55 75
Ignition Coil	<b>80213</b>
<b>Escort VII Cabriolet (ALL) 1.6 16V XR3i</b>	<b>1995-96</b>
L1H	65 88
Ignition Coil With regul.cat.(3way)	<b>80213</b>
Ignition Leads	<b>85120</b>
<b>Escort VII Cabriolet (ALL) 1.6 16V XR3i</b>	<b>1995-99</b>
L1E	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>
Ignition Leads	<b>85120</b>
<b>Escort VII Cabriolet (ALL) 1.8 16V XR3i</b>	<b>1995-00</b>
RQB	96 130
Ignition Coil	<b>80213</b>
<b>Escort VII Cabriolet (ALL) 1.8 16V XR3i</b>	<b>1995-98</b>
RDA	77 105
Ignition Coil	<b>80213</b>
<b>Escort VII Cabriolet (ALL) 1.8 16V XR3i</b>	<b>1995-98</b>
RKC	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Escort VII Estate (GAL, ANL) 1.3</b>	<b>1995-99</b>
J6A/J4B	44 60
Ignition Coil ->08.1998	<b>80213</b>
Ignition Coil 09.1998-> With regul.cat.(3way)	<b>80214</b>
Ignition Coil 09.1998->	<b>80285</b>
Ignition Leads ->12.1997	<b>83450</b>
<b>Escort VII Estate (GAL, ANL) 1.4</b>	<b>1995-99</b>
F4B/FUH	55 75
Ignition Coil	<b>80213</b>
<b>Escort VII Estate (GAL, ANL) 1.6 16V</b>	<b>1995-99</b>
L1E	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>
Ignition Leads	<b>85120</b>
<b>Escort VII Estate (GAL, ANL) 1.6 i 16V</b>	<b>1995-95</b>
L1H	65 88
Ignition Coil	<b>80213</b>
Ignition Leads	<b>85120</b>
<b>Escort VII Estate (GAL, ANL) 1.8 16V</b>	<b>1995-95</b>
RDA	77 105
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Escort VII Estate (GAL, ANL) 1.8 16V</b>	<b>1995-99</b>
RKC	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Escort VII Sedan (GAL, AFL) 1.3</b>	<b>1995-99</b>
J6A/J4B	44 60
Ignition Coil ->08.1998	<b>80213</b>
Ignition Coil 09.1998-> With regul.cat.(3way)	<b>80214</b>
Ignition Coil 09.1998->	<b>80285</b>
Ignition Leads	<b>83450</b>
<b>Escort VII Sedan (GAL, AFL) 1.4</b>	<b>1995-99</b>
F4B/FUH	55 75
Ignition Coil	<b>80213</b>
<b>Escort VII Sedan (GAL, AFL) 1.6 i 16V</b>	<b>1995-99</b>
L1E/L1K	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>
Ignition Leads	<b>85120</b>
<b>Escort VII Sedan (GAL, AFL) 1.6 i 16V</b>	<b>1995-95</b>
L1H	65 88
Ignition Coil	<b>80213</b>
Ignition Leads	<b>85120</b>
<b>Escort VII Sedan (GAL, AFL) 1.8 16V</b>	<b>1995-95</b>
RDA	77 105
Ignition Coil With regul.cat.(3way)	<b>80213</b>

FORD Cont.	
<b>Escort VII Sedan (GAL, AFL) 1.8 16V</b>	<b>1995-99</b>
RKC	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Fiesta I (GFBT) 1.3</b>	<b>1977-83</b>
J3E	49 66
Ignition Leads	<b>83400</b>
<b>Fiesta I (GFBT) 1.6 XR2</b>	<b>1981-83</b>
L3E	62 84
Ignition Leads	<b>83400</b>
<b>Fiesta II (FBD) 1,3</b>	<b>1983-87</b>
JPC	51 69
Ignition Leads	<b>83400</b>
Ignition Leads DIN	<b>83450</b>
<b>Fiesta II (FBD) 1,4</b>	<b>1986-89</b>
F6C/F6A	52 71
Ignition Leads	<b>83450</b>
<b>Fiesta II (FBD) 1,4</b>	<b>1987-89</b>
FUD	54 73
Ignition Leads	<b>83450</b>
<b>Fiesta II (FBD) 1,4</b>	<b>1985-89</b>
FUB	55 75
Ignition Leads	<b>83450</b>
<b>Fiesta II (FBD) 1.4</b>	<b>1983-87</b>
FUBA	51 69
Ignition Leads	<b>83450</b>
<b>Fiesta II (FBD) 1.6 XR2</b>	<b>1984-89</b>
LUD	70 95
Ignition Leads	<b>83400</b>
<b>Fiesta II (FBD) 1.6 XR2</b>	<b>1984-89</b>
LUB	71 97
Ignition Leads	<b>83400</b>
<b>Fiesta III (GFJ) 1.1</b>	<b>1989-95</b>
GUD/GUE	40 55
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Fiesta III (GFJ) 1.1</b>	<b>1989-95</b>
G6A	37 50
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Fiesta III (GFJ) 1.3</b>	<b>1989-95</b>
JBC/JBB	44 60
Ignition Coil	<b>80213</b>
<b>Fiesta III (GFJ) 1.3</b>	<b>1989-92</b>
JBC	44 60
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Fiesta III (GFJ) 1.3 KAT</b>	<b>1991-97</b>
J6B	44 60
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Fiesta III (GFJ) 1.4</b>	<b>1989-95</b>
FUG/FUJ	54 73
Ignition Coil	<b>80213</b>
Ignition Leads 01.1992->	<b>85110</b>
<b>Fiesta III (GFJ) 1.4</b>	<b>1989-95</b>
F6E	52 71
Ignition Coil	<b>80213</b>
Ignition Leads 01.1992->	<b>85110</b>
<b>Fiesta III (GFJ) 1.4 KAT</b>	<b>1989-95</b>
F4A	54 73
Ignition Coil	<b>80213</b>
Ignition Leads 01.1992->	<b>85110</b>
<b>Fiesta III (GFJ) 1.6</b>	<b>1989-92</b>
LUH	66 90
Ignition Coil	<b>80213</b>
<b>Fiesta III (GFJ) 1.6</b>	<b>1989-94</b>
LUH	65 88
Ignition Coil	<b>80213</b>
Ignition Leads ->12.1989	<b>83450</b>
Ignition Leads 01.1991->	<b>85110</b>
<b>Fiesta III (GFJ) 1.6 i 16V</b>	<b>1994-95</b>
L1G	65 88
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Fiesta III (GFJ) 1.6 Turbo</b>	<b>1990-92</b>
LHA	96 131
Ignition Coil	<b>80213</b>
Ignition Leads	<b>85110</b>



FORD Cont.		
<b>Fiesta III (GFJ) 1.6 XR2i</b>		<b>1989-93</b>
LJD		76 103
Ignition Coil		<b>80213</b>
Ignition Leads 01.1991->		<b>85110</b>
<b>Fiesta III (GFJ) 1.6 XR2i</b>		<b>1989-94</b>
LJC		81 110
Ignition Leads 01.1991->		<b>85110</b>
<b>Fiesta III (GFJ) 1.8 16V</b>		<b>1992-95</b>
RDB		77 105
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Fiesta III (GFJ) 1.8 XR2i 16V</b>		<b>1992-95</b>
RQC		96 130
Ignition Coil With regul.cat.(3way)		<b>80213</b>
<b>Fiesta IV (JA, JB) 1.0 i</b>		<b>1997-99</b>
ZH1QJRB		38 52
Ignition Coil 09.1998->; Intake manifold injection		<b>80214</b>
<b>Fiesta IV (JA, JB) 1.0 i</b>		<b>1999-02</b>
		48 65
Ignition Coil		<b>80285</b>
<b>Fiesta IV (JA, JB) 1.25 i 16V</b>		<b>1995-02</b>
DHG/DHB/DHC/DHE/DHF/DHA/DHD		55 75
Ignition Coil ->04.1998		<b>80213</b>
Ignition Coil 05.1998->; With regul.cat.(3way)		<b>80214</b>
Ignition Coil 06.1998->		<b>80285</b>
Ignition Leads ->04.1998		<b>85111</b>
Ignition Leads 05.1998->		<b>85115</b>
<b>Fiesta IV (JA, JB) 1.3 i</b>		<b>1995-02</b>
JJA/JJE/JJM/JJC/JJJ/JJK		37 50
Ignition Coil ->08.1998		<b>80213</b>
Ignition Coil 09.1998->; With regul.cat.(3way)		<b>80214</b>
Ignition Coil 10.1998->		<b>80285</b>
Ignition Leads ->08.1998		<b>85112</b>
Ignition Leads 09.1998->		<b>85114</b>
<b>Fiesta IV (JA, JB) 1.3 i</b>		<b>1995-02</b>
J4R/JBC/J4C/J4L/J4J/J4Q/J4T		44 60
Ignition Coil ->08.1998		<b>80213</b>
Ignition Coil 09.1998->; With regul.cat.(3way)		<b>80214</b>
Ignition Coil 10.1998->		<b>80285</b>
Ignition Leads ->12.1996		<b>83450</b>
Ignition Leads		<b>85114</b>
<b>Fiesta IV (JA, JB) 1.4 i 16V</b>		<b>1996-02</b>
FHE/FHA		66 90
Ignition Coil ->04.1998		<b>80213</b>
Ignition Coil 05.1998->; With regul.cat.(3way)		<b>80214</b>
Ignition Coil 06.1998-12.2000		<b>80285</b>
Ignition Leads ->04.1998		<b>85111</b>
Ignition Leads 04.1998->		<b>85115</b>
<b>Fiesta IV (JA, JB) 1.6 16V Sport</b>		<b>2000-02</b>
L1V/L1T		76 103
Ignition Coil DIN		<b>80213</b>
Ignition Coil ->10.2001		<b>80214</b>
Ignition Coil		<b>80285</b>
<b>Fiesta V (JH, JD) 1.25 16V</b>		<b>2003-08</b>
M7JA/M7JB		51 70
Ignition Coil ->02.2005; Intake manifold injection		<b>80214</b>
Ignition Coil ->03.2005		<b>80284</b>
Ignition Coil ->02.2005		<b>80285</b>
Ignition Leads ->01.2007		<b>85115</b>
Ignition Leads 02.2007->		<b>85125</b>
Ignition Leads		<b>85126</b>
<b>Fiesta V (JH, JD) 1.25 16V</b>		<b>2002-08</b>
FUJA/FUJB		55 75
Ignition Coil ->02.2005; Intake manifold injection		<b>80214</b>
Ignition Coil 03.2005->		<b>80284</b>
Ignition Coil ->02.2005		<b>80285</b>
Ignition Leads ->01.2007		<b>85115</b>
Ignition Leads 02.2007->		<b>85125</b>
Ignition Leads		<b>85126</b>
<b>Fiesta V (JH, JD) 1.3</b>		<b>2001-08</b>
BAJA		44 60
Ignition Coil With regul.cat.(3way)		<b>80214</b>
Ignition Coil 09.2007->		<b>80284</b>
Ignition Coil ->08.2007		<b>80285</b>
Ignition Leads		<b>85112</b>
Ignition Leads 07.2002->		<b>85126</b>

FORD Cont.		
<b>Fiesta V (JH, JD) 1.3</b>		<b>2001-08</b>
A9JA/A9JB		51 69
Ignition Coil With regul.cat.(3way)		<b>80214</b>
Ignition Coil 09.2007->		<b>80284</b>
Ignition Coil ->08.2007		<b>80285</b>
Ignition Leads		<b>85112</b>
Ignition Leads 07.2002->		<b>85126</b>
<b>Fiesta V (JH, JD) 1.4 16V</b>		<b>2001-08</b>
FXJB/FXJA		59 80
Ignition Coil ->02.2005; With regul.cat.(3way)		<b>80214</b>
Ignition Coil ->03.2005		<b>80284</b>
Ignition Coil ->02.2005		<b>80285</b>
Ignition Leads ->01.2007		<b>85115</b>
Ignition Leads		<b>85116</b>
Ignition Leads 02.2007->		<b>85125</b>
<b>Fiesta V (JH, JD) 1.6 16V</b>		<b>2001-08</b>
FYJA/FYJB		74 100
Ignition Coil ->02.2005; With regul.cat.(3way)		<b>80214</b>
Ignition Coil ->03.2005		<b>80284</b>
Ignition Coil ->02.2005		<b>80285</b>
Ignition Leads ->02.2005		<b>85115</b>
Ignition Leads ->02.2005		<b>85116</b>
Ignition Leads		<b>85125</b>
<b>Fiesta Van (F3L, F5L) 1.3</b>		<b>1991-96</b>
J6B		44 60
Ignition Coil		<b>80213</b>
Ignition Leads		<b>83450</b>
Ignition Leads 01.1992->		<b>85110</b>
<b>Fiesta Van (J5, J3) 1.3</b>		<b>1996-03</b>
J4C		44 60
Ignition Coil ->08.1998		<b>80213</b>
Ignition Coil 09.1998->; With regul.cat.(3way)		<b>80214</b>
Ignition Coil 10.1998-12.2002		<b>80285</b>
Ignition Leads		<b>85112</b>
Ignition Leads 09.1998->		<b>85114</b>
<b>Fiesta Van (J5, J3) 1.4 i</b>		<b>1996-99</b>
FHA		66 90
Ignition Coil ->05.1998		<b>80213</b>
Ignition Coil 06.1998->		<b>80285</b>
<b>Fiesta Van 1.25</b>		<b>2009-&gt;</b>
SNJA/SNJB		60 82
Ignition Coil		<b>80284</b>
Ignition Leads		<b>85115</b>
Ignition Leads		<b>85125</b>
<b>Fiesta Van 1.3</b>		<b>2003-05</b>
A9JA/A9JB		51 69
Ignition Coil		<b>80214</b>
Ignition Coil		<b>80285</b>
Ignition Leads		<b>85126</b>
<b>Fiesta Vi 1.25</b>		<b>2008-&gt;</b>
STJA/STJB		44 60
Ignition Coil		<b>80284</b>
Ignition Leads		<b>85115</b>
Ignition Leads		<b>85125</b>
<b>Fiesta Vi 1.25</b>		<b>2008-&gt;</b>
SNJD/SNJA/SNJC/SNJB		60 82
Ignition Coil		<b>80284</b>
Ignition Leads		<b>85115</b>
Ignition Leads		<b>85125</b>
<b>Fiesta Vi 1.4</b>		<b>2008-&gt;</b>
SPJA/SPJC		71 97
Ignition Coil		<b>80284</b>
Ignition Leads		<b>85115</b>
Ignition Leads		<b>85125</b>
<b>Fiesta Vi 1.4 LPG</b>		<b>2009-&gt;</b>
RTJA/RTJB		71 97
Ignition Coil		<b>80284</b>
Ignition Leads		<b>85115</b>
Ignition Leads		<b>85125</b>
<b>Fiesta Vi 1.4 LPG</b>		<b>2009-&gt;</b>
RTJA/RTJB		68 92
Ignition Coil 05.2009->		<b>80284</b>
<b>Fiesta Vi 1.6 Ti</b>		<b>2010-&gt;</b>
U5JA		99 134
Ignition Coil		<b>80284</b>
Ignition Leads		<b>85125</b>



FORD Cont.		
<b>Fiesta Vi 1.6 Ti</b>	2008->	
HXJB/HXJA	88 120	
Ignition Coil	<b>80284</b>	
Ignition Leads	<b>85115</b>	
Ignition Leads	<b>85125</b>	
<b>Fiesta Vi 1.6 Ti</b>	2012->	
IQJA	77 105	
Ignition Coil	<b>80284</b>	
<b>Focus (DAW, DBW) 1.4 16V</b>	1998-04	
FXDA/FXDD/FXDC/FXDB	55 75	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
Ignition Leads	<b>85115</b>	
<b>Focus (DAW, DBW) 1.6 16V</b>	1998-04	
FYDH/FYDA/FYDB/FYDD/FYDC	74 100	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
Ignition Leads	<b>85115</b>	
<b>Focus (DAW, DBW) 1.8 16V</b>	1998-04	
EYDD/EYDC/EYDE/EYDL/EYDF/EYDG/EYDB/EYDJ/EYDI	85 115	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
Ignition Leads	<b>85125</b>	
<b>Focus (DAW, DBW) 2.0 16V</b>	1998-04	
EDDC/EDDB/EDDD/EDDF	96 131	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
Ignition Leads	<b>85125</b>	
<b>Focus (DAW, DBW) RS</b>	2002-04	
HMDA	158 215	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
<b>Focus (DAW, DBW) ST170</b>	2002-04	
ALDA	127 173	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
<b>Focus C-Max 1.6</b>	2003-07	
HWDB/HWDA	74 100	
Ignition Coil ->02.2005; With regul.cat.(3way)	<b>80214</b>	
Ignition Coil 03.2005->	<b>80284</b>	
Ignition Coil ->02.2005	<b>80285</b>	
Ignition Leads ZH16FYDG	<b>85115</b>	
Ignition Leads ->03.2005	<b>85116</b>	
Ignition Leads	<b>85125</b>	
<b>Focus C-Max 1.6 Ti</b>	2004-07	
SIDA/HXDA	85 115	
Ignition Coil HXDA; ->02.2005; Intake manifold injection	<b>80214</b>	
Ignition Coil 03.2005->	<b>80284</b>	
Ignition Coil ->02.2005	<b>80285</b>	
Ignition Leads ZH16HXDA	<b>85115</b>	
Ignition Leads ->03.2005	<b>85116</b>	
Ignition Leads	<b>85125</b>	
<b>Focus C-Max 1.8</b>	2003-07	
CSDB/CSDA	88 120	
Ignition Coil CSDA,CSDB	<b>80231</b>	
<b>Focus C-Max 1.8</b>	2004-07	
QQDA/QQDB/Q7DA	92 125	
Ignition Coil QQDA,QQDB,Q7DA	<b>80231</b>	
<b>Focus C-Max 1.8 Flexifuel</b>	2006-07	
Q7DA	92 125	
Ignition Coil	<b>80231</b>	
<b>Focus C-Max 2.0</b>	2004-07	
AODA/AODB/SYDA	107 145	
Ignition Coil AODA,AODB	<b>80231</b>	
<b>Focus Estate/Clipper (DNW) 1.4 16V</b>	1999-04	
FXDA/FXDD/FXDC/FXDB	55 75	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
Ignition Leads	<b>85115</b>	
<b>Focus Estate/Clipper (DNW) 1.6 16V</b>	1999-04	
FYDH/FYDA/FYDB/FYDD/FYDC	74 100	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
Ignition Leads	<b>85115</b>	
<b>Focus Estate/Clipper (DNW) 1.8 16V</b>	1999-04	
EYDD/EYDC/EYDE/EYDL/EYDF/EYDG/EYDB/EYDJ/EYDI	85 115	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	

FORD Cont.		
<b>Focus Estate/Clipper (DNW) 2.0 16V</b>	1999-04	
EDDC/EDDB/EDDD/EDDF	96 131	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
<b>Focus Estate/Clipper (DNW) ST170</b>	2002-04	
ALDA	127 173	
Ignition Coil With regul.cat.(3way)	<b>80214</b>	
Ignition Coil	<b>80285</b>	
<b>Focus II (DA) 1.4</b>	2004-12	
ASDB/ASDA	59 80	
Ignition Coil ->02.2005; Intake manifold injection	<b>80214</b>	
Ignition Coil 03.2005->	<b>80284</b>	
Ignition Coil ->02.2005	<b>80285</b>	
Ignition Leads	<b>85115</b>	
Ignition Leads ->03.2005	<b>85116</b>	
Ignition Leads	<b>85125</b>	
<b>Focus II (DA) 1.6</b>	2004-12	
SHDA/HWDB/SHDB/HWDA/SHDC	74 100	
Ignition Coil HWDB,HWDA; ->02.2005; Intake manifold injection	<b>80214</b>	
Ignition Coil 03.2005->	<b>80284</b>	
Ignition Coil ->02.2005	<b>80285</b>	
Ignition Leads	<b>85115</b>	
Ignition Leads ->03.2007	<b>85116</b>	
Ignition Leads	<b>85125</b>	
<b>Focus II (DA) 1.6 LPG</b>	2009-11	
SIDA	85 115	
Ignition Coil	<b>80284</b>	
Ignition Leads	<b>85115</b>	
<b>Focus II (DA) 1.6 Ti</b>	2004-12	
HXDB/SIDA/HXDA	85 115	
Ignition Coil HXDA; ->02.2005; Intake manifold injection	<b>80214</b>	
Ignition Coil 03.2005->	<b>80284</b>	
Ignition Coil ->02.2005	<b>80285</b>	
Ignition Leads ZH16HXDA	<b>85115</b>	
Ignition Leads ->03.2005	<b>85116</b>	
Ignition Leads	<b>85125</b>	
<b>Focus II (DA) 1.8</b>	2006-12	
QQDB	92 125	
Ignition Coil	<b>80231</b>	
<b>Focus II (DA) 1.8 Flexifuel</b>	2006-12	
Q7DA	92 125	
Ignition Coil	<b>80231</b>	
<b>Focus II (DA) 2.0</b>	2004-12	
AODA/AODB/AODE	107 145	
Ignition Coil AODB,AODA	<b>80231</b>	
Ignition Coil 10.2008->; Manual	<b>80285</b>	
<b>Focus II (DA) 2.0 CNG</b>	2009-11	
SYDA	107 145	
Ignition Coil	<b>80231</b>	
<b>Focus II (DA) 2.0 LPG</b>	2008-11	
SYDA	107 145	
Ignition Coil	<b>80231</b>	
<b>Focus II (DA) 2.5 RS</b>	2009->	
JZDA	224 305	
Ignition Coil	<b>80304</b>	
<b>Focus II (DA) 2.5 RS 500</b>	2010->	
JZDA	257 350	
Ignition Coil	<b>80304</b>	
<b>Focus II (DA) 2.5 ST</b>	2005-12	
HYDA	166 225	
Ignition Coil	<b>80304</b>	
<b>Focus II Cabriolet 1.6</b>	2006-11	
SHDA/HWDB/SHDB/HWDA/SHDC	74 100	
Ignition Coil	<b>80284</b>	
Ignition Leads	<b>85115</b>	
Ignition Leads Without ignition lead	<b>85116</b>	
Ignition Leads	<b>85125</b>	
<b>Focus II Cabriolet 2.0</b>	2006-11	
AODA/AODB	107 145	
Ignition Coil	<b>80231</b>	
<b>Focus II Sedan (DA) 1.4</b>	2005-12	
ASDB/ASDA	59 80	
Ignition Coil	<b>80284</b>	
Ignition Leads C14HDEZ	<b>85115</b>	
Ignition Leads SAE	<b>85116</b>	
Ignition Leads	<b>85125</b>	



FORD Cont.	
<b>Focus II Sedan (DA) 1.6</b>	<b>2005-12</b>
SHDA/HWDB/SHDB/HWDA/SHDC	74 100
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads SAE	<b>85116</b>
Ignition Leads	<b>85125</b>
<b>Focus II Sedan (DA) 1.6 Ti</b>	<b>2005-12</b>
HXDB/HXDA	85 115
Ignition Coil	<b>80284</b>
Ignition Leads C14HDEZ	<b>85115</b>
Ignition Leads Without ignition lead	<b>85116</b>
Ignition Leads	<b>85125</b>
<b>Focus II Sedan (DA) 1.8</b>	<b>2006-12</b>
QQDB	92 125
Ignition Coil	<b>80231</b>
<b>Focus II Sedan (DA) 1.8 Flexifuel</b>	<b>2006-11</b>
Q7DA	92 125
Ignition Coil	<b>80231</b>
<b>Focus II Sedan (DA) 2.0</b>	<b>2005-11</b>
AODA/AODB	107 145
Ignition Coil AODB,AODA	<b>80231</b>
Ignition Coil 06.2005->; Manual	<b>80285</b>
<b>Focus II Station Wagon (DA) 1.4</b>	<b>2004-12</b>
ASDB/ASDA	59 80
Ignition Coil ->02.2005; Intake manifold injection	<b>80214</b>
Ignition Coil 03.2005->	<b>80284</b>
Ignition Coil ->02.2005	<b>80285</b>
Ignition Leads ->03.2007	<b>85115</b>
Ignition Leads ->02.2005	<b>85116</b>
Ignition Leads	<b>85125</b>
<b>Focus II Station Wagon (DA) 1.6</b>	<b>2004-11</b>
SHDA/HWDB/SHDB/HWDA/SHDC	74 100
Ignition Coil ->02.2005; Intake manifold injection	<b>80214</b>
Ignition Coil 03.2005->	<b>80284</b>
Ignition Coil ->02.2005	<b>80285</b>
Ignition Leads	<b>85115</b>
Ignition Leads ->03.2005	<b>85116</b>
Ignition Leads	<b>85125</b>
<b>Focus II Station Wagon (DA) 1.6 LPG</b>	<b>2009-12</b>
SIDA	85 115
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
<b>Focus II Station Wagon (DA) 1.6 Ti</b>	<b>2004-12</b>
HXDB/HXDA	85 115
Ignition Coil HXDA; ->02.2005; Intake manifold injection	<b>80214</b>
Ignition Coil 03.2005->	<b>80284</b>
Ignition Coil ->02.2005	<b>80285</b>
Ignition Leads	<b>85115</b>
Ignition Leads ->03.2005	<b>85116</b>
Ignition Leads	<b>85125</b>
<b>Focus II Station Wagon (DA) 1.8</b>	<b>2006-12</b>
QQDB/Q7DA	92 125
Ignition Coil	<b>80231</b>
<b>Focus II Station Wagon (DA) 1.8 Flexifuel</b>	<b>2006-12</b>
Q7DA	92 125
Ignition Coil	<b>80231</b>
<b>Focus II Station Wagon (DA) 2.0</b>	<b>2004-12</b>
AODA/AODB/AODE	107 145
Ignition Coil AODB.AODA	<b>80231</b>
<b>Focus II Station Wagon (DA) 2.0 LPG</b>	<b>2008-11</b>
SYDA	107 145
Ignition Coil	<b>80231</b>
<b>Focus III 1.6 Flexifuel</b>	<b>2010-&gt;</b>
MUDA	88 120
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III 1.6 LPG</b>	<b>2012-&gt;</b>
MUDA	86 120
Ignition Coil MUDD<Euro 6>	<b>80284</b>
<b>Focus III 1.6 LPG</b>	<b>2012-&gt;</b>
MUDA	88 120
Ignition Coil ->12.2014	<b>80284</b>
<b>Focus III 1.6 Ti</b>	<b>2012-&gt;</b>
MUDA	88 120
Ignition Coil MUDD<Euro 6>	<b>80284</b>
<b>Focus III 1.6 Ti</b>	<b>2011-&gt;</b>
XTDA	63 85
Ignition Coil	<b>80284</b>
<b>Focus III 1.6 Ti</b>	<b>2010-&gt;</b>
IQDB	77 105
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III 1.6 Ti</b>	<b>2010-&gt;</b>
PNDA	92 125
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III 2.0 ST</b>	<b>2012-&gt;</b>
R9DA	184 250
Ignition Coil	<b>80255</b>
<b>Focus III 2.0 Ti-GDi</b>	<b>2011-&gt;</b>
MGDA	125 170
Ignition Coil	<b>80255</b>
<b>Focus III Sedan 1.6 Flexifuel</b>	<b>2010-&gt;</b>
MUDA	88 120
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Sedan 1.6 Ti</b>	<b>2011-&gt;</b>
XTDA	63 85
Ignition Coil 02.2012->	<b>80284</b>
<b>Focus III Sedan 1.6 Ti</b>	<b>2010-&gt;</b>
IQDB	77 105
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Sedan 1.6 Ti</b>	<b>2010-&gt;</b>
PNDA	92 125
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Turnier 1.6 Flexifuel</b>	<b>2010-&gt;</b>
MUDA	88 120
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Turnier 1.6 LPG</b>	<b>2012-&gt;</b>
MUDA	86 120
Ignition Coil MUDD<Euro 6>	<b>80284</b>
<b>Focus III Turnier 1.6 LPG</b>	<b>2012-&gt;</b>
MUDA	88 120
Ignition Coil ->12.2014	<b>80284</b>
<b>Focus III Turnier 1.6 Ti</b>	<b>2012-&gt;</b>
MUDA	88 120
Ignition Coil MUDD<Euro 6>	<b>80284</b>
<b>Focus III Turnier 1.6 Ti</b>	<b>2011-&gt;</b>
XTDA	63 85
Ignition Coil 02.2012->	<b>80284</b>
<b>Focus III Turnier 1.6 Ti</b>	<b>2010-&gt;</b>
IQDB	77 105
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Turnier 1.6 Ti</b>	<b>2010-&gt;</b>
PNDA	92 125
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Turnier 2.0 ST</b>	<b>2012-&gt;</b>
R9DA	184 250
Ignition Coil	<b>80255</b>
<b>Focus Sedan (DFW) 1.4 16V</b>	<b>1999-04</b>
FXDA/FXDD/FXDC/FXDB	55 75
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil	<b>80285</b>
Ignition Leads	<b>85115</b>
<b>Focus Sedan (DFW) 1.6 16V</b>	<b>1999-04</b>
FYDH/FYDA/FYDB/FYDD/FYDC	74 100
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil	<b>80285</b>
Ignition Leads	<b>85115</b>
<b>Focus Sedan (DFW) 1.8 16V</b>	<b>1999-04</b>
EYDD/EYDC/EYDE/EYDL/EYDF/EYDG/EYDB/EYDJ/EYDI	85 115
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil	<b>80285</b>

FORD Cont.	
<b>Focus III 1.6 Ti</b>	<b>2010-&gt;</b>
IQDB	77 105
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III 1.6 Ti</b>	<b>2010-&gt;</b>
PNDA	92 125
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III 2.0 ST</b>	<b>2012-&gt;</b>
R9DA	184 250
Ignition Coil	<b>80255</b>
<b>Focus III 2.0 Ti-GDi</b>	<b>2011-&gt;</b>
MGDA	125 170
Ignition Coil	<b>80255</b>
<b>Focus III Sedan 1.6 Flexifuel</b>	<b>2010-&gt;</b>
MUDA	88 120
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Sedan 1.6 Ti</b>	<b>2011-&gt;</b>
XTDA	63 85
Ignition Coil 02.2012->	<b>80284</b>
<b>Focus III Sedan 1.6 Ti</b>	<b>2010-&gt;</b>
IQDB	77 105
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Sedan 1.6 Ti</b>	<b>2010-&gt;</b>
PNDA	92 125
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Turnier 1.6 Flexifuel</b>	<b>2010-&gt;</b>
MUDA	88 120
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Turnier 1.6 LPG</b>	<b>2012-&gt;</b>
MUDA	86 120
Ignition Coil MUDD<Euro 6>	<b>80284</b>
<b>Focus III Turnier 1.6 LPG</b>	<b>2012-&gt;</b>
MUDA	88 120
Ignition Coil ->12.2014	<b>80284</b>
<b>Focus III Turnier 1.6 Ti</b>	<b>2012-&gt;</b>
MUDA	88 120
Ignition Coil MUDD<Euro 6>	<b>80284</b>
<b>Focus III Turnier 1.6 Ti</b>	<b>2011-&gt;</b>
XTDA	63 85
Ignition Coil 02.2012->	<b>80284</b>
<b>Focus III Turnier 1.6 Ti</b>	<b>2010-&gt;</b>
IQDB	77 105
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Turnier 1.6 Ti</b>	<b>2010-&gt;</b>
PNDA	92 125
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Focus III Turnier 2.0 ST</b>	<b>2012-&gt;</b>
R9DA	184 250
Ignition Coil	<b>80255</b>
<b>Focus Sedan (DFW) 1.4 16V</b>	<b>1999-04</b>
FXDA/FXDD/FXDC/FXDB	55 75
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil	<b>80285</b>
Ignition Leads	<b>85115</b>
<b>Focus Sedan (DFW) 1.6 16V</b>	<b>1999-04</b>
FYDH/FYDA/FYDB/FYDD/FYDC	74 100
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil	<b>80285</b>
Ignition Leads	<b>85115</b>
<b>Focus Sedan (DFW) 1.8 16V</b>	<b>1999-04</b>
EYDD/EYDC/EYDE/EYDL/EYDF/EYDG/EYDB/EYDJ/EYDI	85 115
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil	<b>80285</b>



FORD Cont.		
<b>Focus Sedan (DFW) 2.0 16V</b>		1999-04
EDDC/EDDB/EDDD/EDDF		96 131
Ignition Coil With regul.cat.(3way)		80214
Ignition Coil		80285
<b>Fusion (JU) 1.25</b>		2004-12
FUJA/FUJB		55 75
Ignition Coil ->02.2005; Intake manifold injection		80214
Ignition Coil 03.2005->		80284
Ignition Leads FYDD		85115
Ignition Leads 02.2007->		85125
Ignition Leads		85126
<b>Fusion (JU) 1.4</b>		2002-12
FXJC/FXJB/FXJA		59 80
Ignition Coil FXJB,FXJA; ->02.2005; With regul.cat.(3way)		80214
Ignition Coil 03.2005->		80284
Ignition Coil 10.2002-02.2005		80285
Ignition Leads		85115
Ignition Leads 03.2005->		85116
Ignition Leads		85125
<b>Fusion (JU) 1.4 LPG</b>		2010->
UTJA		59 80
Ignition Coil ->06.2012		80284
<b>Fusion (JU) 1.6</b>		2002-08
FYJC/FYJA/FYJB		74 100
Ignition Coil FYJA,FYJB; ->02.2005; With regul.cat.(3way)		80214
Ignition Coil 03.2005->		80284
Ignition Coil ->02.2005		80285
Ignition Leads		85115
Ignition Leads 03.2005->		85116
Ignition Leads		85125
<b>Galaxy (WA6) 2.0</b>		2006-15
AOWB/AOWA		107 145
Ignition Coil		80231
<b>Galaxy (WA6) 2.0 EcoBoost</b>		2010-15
TNWA		149 203
Ignition Coil		80255
<b>Galaxy (WA6) 2.0 EcoBoost</b>		2010-15
TNWB		146 199
Ignition Coil		80255
<b>Galaxy (WA6) 2.3</b>		2007-15
SEWA		118 160
Ignition Coil		80230
<b>Galaxy (WGR) 2.0 i</b>		1995-06
NSE/ZVSA		85 116
Ignition Coil		80285
<b>Galaxy (WGR) 2.3 16V</b>		2001-06
E5SB		103 140
Ignition Coil		80214
Ignition Coil		80285
<b>Galaxy (WGR) 2.3 16V</b>		1997-06
Y5B/E5SA		107 146
Ignition Coil E5SA; 04.2000->		80285
Ignition Coil Y5B; ->03.2000		80305
<b>Galaxy (WGR) 2.8 i V6</b>		1995-00
AAA/AMY		128 174
Ignition Leads		85070
<b>Galaxy 2.0 EcoBoost</b>		2015->
R9CD/R9CI		176 240
Ignition Coil		80255
<b>Granada (GGTL, GGFL) 1.7</b>		1974-77
MWB		51 70
Ignition Leads		83400
<b>Granada (GGTL, GGFL) 1.7</b>		1972-75
TV 17 HC		48 65
Ignition Leads		83400
<b>Granada (GGTL, GGFL) 1.7</b>		1972-75
TV 17 H		55 75
Ignition Leads		83400
<b>Granada (GU) 1.6</b>		1981-85
LCK		55 75
Ignition Leads		83450
<b>Granada (GU) 1.7</b>		1977-82
TV 17 LC		51 70
Ignition Leads		83400
<b>Granada (GU) 1.7</b>		1977-81
MY		54 73
Ignition Leads		83400

FORD Cont.		
<b>Granada (GU) 2.0</b>		1979-85
NEP		74 101
Ignition Leads		83400
<b>Granada (GU) 2.0</b>		1981-85
NEK		77 105
Ignition Leads		83400
<b>Granada Break (GGNL) 1.7</b>		1974-77
MWB		51 70
Ignition Leads		83400
<b>Granada Break (GGNL) 1.7</b>		1972-75
TV 17 HC		48 65
Ignition Leads		83400
<b>Granada Break (GNU) 1.7</b>		1977-81
MYE		54 74
Ignition Leads		83400
<b>Granada Break (GNU) 2.0</b>		1979-85
NEP		74 101
Ignition Leads		83400
<b>Granada Break (GNU) 2.0</b>		1981-85
NEK		77 105
Ignition Leads		83400
<b>Granada Coupe (GGCL) 1.7</b>		1972-75
TV 17 LC		48 65
Ignition Leads		83400
<b>Granada Coupe (GGCL) 2.0</b>		1972-75
		73 99
Ignition Leads		83400
<b>Grand C-Max 1.6 EcoBoost</b>		2010->
JQDA/JQDB		110 150
Ignition Coil		80284
<b>Grand C-Max 1.6 EcoBoost</b>		2010->
JTDB/JTDA		134 182
Ignition Coil		80284
<b>Grand C-Max 1.6 Ti</b>		2010->
IQDB/IQDA		77 105
Ignition Coil		80284
Ignition Leads		85115
Ignition Leads		85125
<b>Grand C-Max 1.6 Ti</b>		2010->
PNDA		92 125
Ignition Coil		80284
Ignition Leads		85115
Ignition Leads		85125
<b>Ka (RB) 1.0 i</b>		1997-99
ZH10JRB		38 52
Ignition Coil ->07.1999		80213
Ignition Leads		85112
<b>Ka (RB) 1.0 i</b>		1999-08
		48 65
Ignition Coil ->12.2007		80285
Ignition Leads		85112
<b>Ka (RB) 1.3 i</b>		1998-08
JJH/JJD/JJF/JJG/JJL		36 49
Ignition Coil ->08.1998		80213
Ignition Coil 09.1998->; With regul.cat.(3way)		80214
Ignition Coil ->10.2002		80285
Ignition Leads ->09.1998		85112
Ignition Leads 09.1998->		85114
Ignition Leads		85126
<b>Ka (RB) 1.3 i</b>		2002-08
A9B/A9A		51 70
Ignition Coil Intake manifold injection		80214
Ignition Coil 10.2002-09.2008		80285
Ignition Leads		85112
Ignition Leads SAE		85126
<b>Ka (RB) 1.3 i</b>		1996-02
JJB		37 50
Ignition Coil ->08.1998		80213
Ignition Coil 09.1998->; With regul.cat.(3way)		80214
Ignition Coil		80285
Ignition Leads ->08.1998		85112
Ignition Leads 09.1998->		85114





FORD Cont.	
<b>Ka (RB) 1.3 i</b>	1996-08
J4S/BAA/J4K/J4M/J4P/J4N/J4D	44 60
Ignition Coil ->08.1998	<b>80213</b>
Ignition Coil 09.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil BAA; 10.2002-09.2008	<b>80285</b>
Ignition Coil J4S/J4K/J4M/J4P/J4N/J4D; ->10.2002	<b>80285</b>
Ignition Leads ->08.1998	<b>85112</b>
Ignition Leads 09.1998->	<b>85114</b>
Ignition Leads BAA; 10.2002->	<b>85126</b>
<b>Ka (RB) 1.6 i</b>	<b>2003-08</b>
CDC/CDB	70 95
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil 08.2007->	<b>80284</b>
Ignition Coil ->09.2008	<b>80285</b>
Ignition Leads	<b>85112</b>
Ignition Leads 01.2004->	<b>85126</b>
<b>Ka (RU8) 1.2</b>	<b>2008-&gt;</b>
FP4	51 69
Ignition Coil	<b>80340</b>
<b>Ka Van (RB) 1.3 i</b>	<b>2002-05</b>
J4S/BAA/J4K/J4M/J4P/J4N/J4D	44 60
Ignition Coil ->10.2002	<b>80213</b>
Ignition Coil	<b>80285</b>
Ignition Leads	<b>85126</b>
<b>Kuga I 2.5 4x4</b>	<b>2009-&gt;</b>
HYDB	147 200
Ignition Coil	<b>80304</b>
<b>Maverick (UDS, UNS) 2.4 i</b>	<b>1993-96</b>
KA24-E	91 124
Ignition Coil	<b>80286</b>
<b>Maverick (UDS, UNS) 2.4 i</b>	<b>1996-98</b>
KA-24	85 116
Ignition Coil	<b>80286</b>
<b>Maverick (UDS, UNS) 2.4 i</b>	<b>1996-98</b>
KA-24	87 118
Ignition Coil	<b>80286</b>
<b>Maverick 2.0 16V</b>	<b>2001-&gt;</b>
YF	91 124
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil ->12.2003	<b>80285</b>
<b>Maverick 2.3 16V</b>	<b>2004-&gt;</b>
GZ	110 150
Ignition Coil	<b>80231</b>
<b>Mondeo Fastback 2.0 EcoBoost</b>	<b>2014-&gt;</b>
R9CF/R9CH/R9CB	176 240
Ignition Coil	<b>80255</b>
<b>Mondeo I (GBP) 1.6 i 16V</b>	<b>1993-96</b>
L1F	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I (GBP) 1.6 i 16V</b>	<b>1994-96</b>
L1J	65 88
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I (GBP) 1.8 i 16V</b>	<b>1993-96</b>
RKA	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I (GBP) 1.8 i 16V</b>	<b>1994-96</b>
RKB	82 112
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I (GBP) 1.8 i 16V 4x4</b>	<b>1993-96</b>
RKA	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I (GBP) 2.0 i 16V</b>	<b>1993-96</b>
NGA	100 136
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I (GBP) 2.0 i 16V 4x4</b>	<b>1993-96</b>
NGA	100 136
Ignition Coil 07.1993-07.1996	<b>80213</b>
<b>Mondeo I (GBP) 2.0 i 16V 4x4</b>	<b>1994-96</b>
NGA	97 132
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I (GBP) 2.5 i 24V</b>	<b>1994-96</b>
SEA	125 170
Ignition Coil	<b>80306</b>
Ignition Leads	<b>85127</b>
<b>Mondeo I Estate/Clipper (BNP) 1.6 i 16V</b>	<b>1993-96</b>
L1F	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>

FORD Cont.	
<b>Mondeo I Estate/Clipper (BNP) 1.6 i 16V</b>	<b>1994-96</b>
L1J	65 88
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Estate/Clipper (BNP) 1.8 i 16V</b>	<b>1993-96</b>
RKA	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Estate/Clipper (BNP) 1.8 i 16V</b>	<b>1994-96</b>
RKB	82 112
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Estate/Clipper (BNP) 1.8 i 16V 4x4</b>	<b>1993-96</b>
RKA	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Estate/Clipper (BNP) 2.0 i 16V</b>	<b>1993-96</b>
NGA	100 136
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Estate/Clipper (BNP) 2.0 i 16V 4x4</b>	<b>1993-96</b>
NGA	100 136
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Estate/Clipper (BNP) 2.0 i 16V 4x4</b>	<b>1994-96</b>
NGA	97 132
Ignition Coil	<b>80213</b>
<b>Mondeo I Estate/Clipper (BNP) 2.5 i 24V</b>	<b>1994-96</b>
SEA	125 170
Ignition Coil	<b>80306</b>
Ignition Leads	<b>85127</b>
<b>Mondeo I Sedan (GBP) 1.6 i 16V</b>	<b>1993-96</b>
L1F	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Sedan (GBP) 1.6 i 16V</b>	<b>1994-96</b>
L1J	65 88
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Sedan (GBP) 1.8 i 16V</b>	<b>1993-96</b>
RKA	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Sedan (GBP) 1.8 i 16V</b>	<b>1994-96</b>
RKB	82 112
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Sedan (GBP) 2.0 i 16V</b>	<b>1993-96</b>
NGA	100 136
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Sedan (GBP) 2.0 i 16V 4x4</b>	<b>1994-96</b>
NGA	97 132
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Mondeo I Sedan (GBP) 2.5 i 24V</b>	<b>1994-96</b>
SEA	125 170
Ignition Coil	<b>80306</b>
Ignition Leads	<b>85127</b>
<b>Mondeo II (BAP) 1.6 i</b>	<b>1996-00</b>
L1J	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>
Ignition Coil 05.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil 05.1998-08.1998	<b>80285</b>
Ignition Leads 05.1998->	<b>85115</b>
<b>Mondeo II (BAP) 1.6 i 16V</b>	<b>1998-00</b>
L1N/L1L/L1Q	70 95
Ignition Coil Hydraulic Brake; With regul.cat.(3way)	<b>80213</b>
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil 08.1998-08.2000	<b>80285</b>
<b>Mondeo II (BAP) 1.8 i</b>	<b>1996-00</b>
RKK/RKJ/RKB/RKF/RKH	85 115
Ignition Coil With regul.cat.(3way)	<b>80213</b>
Ignition Coil 05.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil 08.1998-08.2000	<b>80285</b>
Ignition Leads	<b>85125</b>
<b>Mondeo II (BAP) 2.0 i</b>	<b>1996-00</b>
NGA/NGB/NGD/NGC	96 131
Ignition Coil With regul.cat.(3way)	<b>80213</b>
Ignition Coil 05.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil 08.1998-08.2000	<b>80285</b>
Ignition Leads	<b>85125</b>
<b>Mondeo II (BAP) 2.5 24V</b>	<b>2000-00</b>
SEB/SEC	125 170
Ignition Coil	<b>80306</b>
Ignition Leads DIN FORD	<b>85127</b>
Ignition Leads	<b>85128</b>
<b>Mondeo II (BAP) 2.5 24V</b>	<b>1996-00</b>
SEA	125 170
Ignition Coil	<b>80306</b>
Ignition Leads	<b>85127</b>



FORD Cont.		
<b>Mondeo II (BAP) 2.5 ST 200</b>		<b>1999-00</b>
SGA		151 205
Ignition Coil		<b>80306</b>
Ignition Leads		<b>85127</b>
<b>Mondeo II Estate/Clipper (BNP) 1.6 i</b>		<b>1996-00</b>
L1J		66 90
Ignition Coil	With regul.cat.(3way)	<b>80213</b>
Ignition Coil	05.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil	05.1998-08.1998	<b>80285</b>
Ignition Leads	09.1998->	<b>85115</b>
<b>Mondeo II Estate/Clipper (BNP) 1.6 i 16V</b>		<b>1998-00</b>
L1N/L1L/L1Q		70 95
Ignition Coil	Hydraulic Brake; With regul.cat.(3way)	<b>80213</b>
Ignition Coil	With regul.cat.(3way)	<b>80214</b>
Ignition Coil	08.1998-08.2000	<b>80285</b>
<b>Mondeo II Estate/Clipper (BNP) 1.8 i</b>		<b>1996-00</b>
RKK/RKJ/RKB/RKF/RKH		85 115
Ignition Coil	With regul.cat.(3way)	<b>80213</b>
Ignition Coil	05.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil	08.1998-08.2000	<b>80285</b>
<b>Mondeo II Estate/Clipper (BNP) 2.0 i</b>		<b>1996-00</b>
NGA/NGB/NGD/NGC		96 131
Ignition Coil	With regul.cat.(3way)	<b>80213</b>
Ignition Coil	05.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil	08.1998-08.2000	<b>80285</b>
<b>Mondeo II Estate/Clipper (BNP) 2.5 24V</b>		<b>1999-00</b>
SEB/SEC		125 170
Ignition Coil		<b>80306</b>
Ignition Leads	DIN FORD	<b>85127</b>
Ignition Leads		<b>85128</b>
<b>Mondeo II Estate/Clipper (BNP) 2.5 24V</b>		<b>1996-00</b>
SEA		125 170
Ignition Coil		<b>80306</b>
Ignition Leads		<b>85127</b>
<b>Mondeo II Estate/Clipper (BNP) 2.5 ST 200</b>		<b>1999-00</b>
SGA		151 205
Ignition Coil		<b>80306</b>
Ignition Leads		<b>85127</b>
<b>Mondeo II Sedan (BFP) 1.6 i</b>		<b>1996-00</b>
L1J		66 90
Ignition Coil	With regul.cat.(3way)	<b>80213</b>
Ignition Coil	05.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil	05.1998-08.1998	<b>80285</b>
Ignition Leads	09.1998->	<b>85115</b>
<b>Mondeo II Sedan (BFP) 1.6 i 16V</b>		<b>1998-00</b>
L1N/L1L/L1Q		70 95
Ignition Coil	Hydraulic Brake; With regul.cat.(3way)	<b>80213</b>
Ignition Coil	With regul.cat.(3way)	<b>80214</b>
Ignition Coil	->08.2000	<b>80285</b>
<b>Mondeo II Sedan (BFP) 1.8 i</b>		<b>1996-00</b>
RKK/RKJ/RKB/RKF/RKH		85 115
Ignition Coil	With regul.cat.(3way)	<b>80213</b>
Ignition Coil	05.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil	05.1998->	<b>80285</b>
<b>Mondeo II Sedan (BFP) 2.0 i</b>		<b>1996-00</b>
NGA/NGB/NGD/NGC		96 131
Ignition Coil	With regul.cat.(3way)	<b>80213</b>
Ignition Coil	05.1998->; With regul.cat.(3way)	<b>80214</b>
Ignition Coil	05.1998->	<b>80285</b>
<b>Mondeo II Sedan (BFP) 2.5 24V</b>		<b>2000-00</b>
SEB/LCBD/SEC		125 170
Ignition Coil		<b>80306</b>
Ignition Leads	DIN FORD	<b>85127</b>
Ignition Leads		<b>85128</b>
<b>Mondeo II Sedan (BFP) 2.5 24V</b>		<b>1996-00</b>
SEA		125 170
Ignition Coil		<b>80306</b>
Ignition Leads		<b>85127</b>
<b>Mondeo II Sedan (BFP) 2.5 ST 200</b>		<b>1999-00</b>
SGA		151 205
Ignition Coil		<b>80306</b>
Ignition Leads		<b>85127</b>
<b>Mondeo III (B5Y) 1.8 16V</b>		<b>2000-07</b>
CGBB/CGBA		81 110
Ignition Coil	03.2005->	<b>80284</b>
Ignition Coil	->02.2005	<b>80285</b>

FORD Cont.		
<b>Mondeo III (B5Y) 1.8 16V</b>		<b>2000-07</b>
CHBA/CHBB		92 125
Ignition Coil	03.2005->	<b>80284</b>
Ignition Coil	->02.2005	<b>80285</b>
<b>Mondeo III (B5Y) 2.0 16V</b>		<b>2000-07</b>
CJBA/CJBB		107 146
Ignition Coil	03.2005->	<b>80284</b>
Ignition Coil	->02.2005	<b>80285</b>
<b>Mondeo III (B5Y) 2.5 V6 24V</b>		<b>2000-07</b>
LCBD		125 170
Ignition Leads		<b>85128</b>
<b>Mondeo III Estate/Clipper (BWY) 1.8 16V</b>		<b>2000-07</b>
CGBB/CGBA		81 110
Ignition Coil	03.2005->	<b>80284</b>
Ignition Coil	->02.2005	<b>80285</b>
<b>Mondeo III Estate/Clipper (BWY) 1.8 16V</b>		<b>2000-07</b>
CHBA/CHBB		92 125
Ignition Coil	03.2005->	<b>80284</b>
Ignition Coil	->02.2005	<b>80285</b>
<b>Mondeo III Estate/Clipper (BWY) 2.0 16V</b>		<b>2000-07</b>
CJBA/CJBB		107 146
Ignition Coil	03.2005->	<b>80284</b>
Ignition Coil	->02.2005	<b>80285</b>
<b>Mondeo III Estate/Clipper (BWY) 2.5 V6 24V</b>		<b>2000-07</b>
LCBD		125 170
Ignition Leads		<b>85128</b>
<b>Mondeo III Sedan (B4Y) 1.8 16V</b>		<b>2000-07</b>
CGBB/CGBA		81 110
Ignition Coil	03.2005->	<b>80284</b>
Ignition Coil	->02.2005	<b>80285</b>
<b>Mondeo III Sedan (B4Y) 1.8 16V</b>		<b>2000-07</b>
CHBA/CHBB		92 125
Ignition Coil	03.2005->	<b>80284</b>
Ignition Coil	->02.2005	<b>80285</b>
<b>Mondeo III Sedan (B4Y) 2.0 16V</b>		<b>2000-07</b>
CJBA/CJBB		107 146
Ignition Coil	03.2005->	<b>80284</b>
Ignition Coil	->02.2005	<b>80285</b>
<b>Mondeo III Sedan (B4Y) 2.5 V6 24V</b>		<b>2000-07</b>
LCBD		125 170
Ignition Leads		<b>85128</b>
<b>Mondeo IV (BA7) 1.6 Ti</b>		<b>2007-15</b>
RHBA		81 110
Ignition Coil		<b>80284</b>
Ignition Leads		<b>85115</b>
Ignition Leads	SAE	<b>85116</b>
Ignition Leads		<b>85125</b>
<b>Mondeo IV (BA7) 1.6 Ti</b>		<b>2007-15</b>
PNBA		92 125
Ignition Coil		<b>80284</b>
Ignition Leads		<b>85115</b>
Ignition Leads	SAE	<b>85116</b>
Ignition Leads		<b>85125</b>
<b>Mondeo IV (BA7) 1.6 Ti</b>		<b>2010-15</b>
KGBA		88 120
Ignition Coil		<b>80284</b>
Ignition Leads		<b>85115</b>
Ignition Leads		<b>85125</b>
<b>Mondeo IV (BA7) 2.0</b>		<b>2007-15</b>
AOBC/AOBA/TBBA		107 145
Ignition Coil		<b>80231</b>
<b>Mondeo IV (BA7) 2.0 EcoBoost</b>		<b>2010-15</b>
TPBA		176 240
Ignition Coil		<b>80255</b>
<b>Mondeo IV (BA7) 2.0 Flexifuel</b>		<b>2009-15</b>
TBBB/TBBA		107 145
Ignition Coil		<b>80231</b>
<b>Mondeo IV (BA7) 2.0 SCTI</b>		<b>2010-15</b>
TNBA		149 203
Ignition Coil		<b>80255</b>
<b>Mondeo IV (BA7) 2.3</b>		<b>2007-15</b>
SEBA		118 160
Ignition Coil		<b>80230</b>
<b>Mondeo IV (BA7) 2.5</b>		<b>2007-15</b>
HUBA		162 220
Ignition Coil		<b>80304</b>



FORD Cont.	
<b>Mondeo IV Sedan (BA7) 1.6 Ti</b>	<b>2007-15</b>
PNBA	92 125
Ignition Coil	<b>80284</b>
Ignition Leads ->08.2010	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Mondeo IV Sedan (BA7) 2.0</b>	<b>2007-15</b>
AOBC/AOBA/TBBA	107 145
Ignition Coil	<b>80231</b>
<b>Mondeo IV Sedan (BA7) 2.0 Flexifuel</b>	<b>2009-15</b>
TBBB/TBBA	107 145
Ignition Coil	<b>80231</b>
<b>Mondeo IV Sedan (BA7) 2.3</b>	<b>2007-15</b>
SEBA	118 160
Ignition Coil	<b>80230</b>
<b>Mondeo IV Sedan (BA7) 2.5</b>	<b>2007-15</b>
HUBA	162 220
Ignition Coil	<b>80304</b>
<b>Mondeo IV Turnier (BA7) 1.6 Ti</b>	<b>2007-12</b>
RHBA	81 110
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads SAE	<b>85116</b>
Ignition Leads	<b>85125</b>
<b>Mondeo IV Turnier (BA7) 1.6 Ti</b>	<b>2007-10</b>
PNBA	92 125
Ignition Coil	<b>80284</b>
Ignition Leads ->08.2010	<b>85115</b>
Ignition Leads SAE	<b>85116</b>
Ignition Leads	<b>85125</b>
<b>Mondeo IV Turnier (BA7) 1.6 Ti</b>	<b>2010-15</b>
KGBA	88 120
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>Mondeo IV Turnier (BA7) 2.0</b>	<b>2007-15</b>
AOBC/AOBA/TBBA	107 145
Ignition Coil	<b>80231</b>
<b>Mondeo IV Turnier (BA7) 2.0 EcoBoost</b>	<b>2010-15</b>
TPBA	176 240
Ignition Coil	<b>80255</b>
<b>Mondeo IV Turnier (BA7) 2.0 Flexifuel</b>	<b>2009-15</b>
TBBB/TBBA	107 145
Ignition Coil	<b>80231</b>
<b>Mondeo IV Turnier (BA7) 2.0 SCTi</b>	<b>2010-15</b>
TNBA	149 203
Ignition Coil	<b>80255</b>
<b>Mondeo IV Turnier (BA7) 2.3</b>	<b>2007-15</b>
SEBA	118 160
Ignition Coil	<b>80230</b>
<b>Mondeo IV Turnier (BA7) 2.5</b>	<b>2007-12</b>
HUBA	162 220
Ignition Coil	<b>80304</b>
<b>Mondeo V Fastback 2.0 EcoBoost</b>	<b>2014-&gt;</b>
TNCD/TNCF	149 203
Ignition Coil	<b>80255</b>
<b>Mondeo V Sedan 2.0 EcoBoost</b>	<b>2015-&gt;</b>
TNCD/TNCF	149 203
Ignition Coil	<b>80255</b>
<b>Mondeo V Sedan 2.0 EcoBoost</b>	<b>2015-&gt;</b>
TNCC	146 199
Ignition Coil	<b>80255</b>
<b>Mondeo V Sedan 2.0 EcoBoost</b>	<b>2015-&gt;</b>
R9CF/R9CH/R9CB	176 240
Ignition Coil	<b>80255</b>
<b>Mondeo V Turnier 2.0 EcoBoost</b>	<b>2014-&gt;</b>
TNCD/TNCF	149 203
Ignition Coil	<b>80255</b>
<b>Mondeo V Turnier 2.0 EcoBoost</b>	<b>2014-&gt;</b>
R9CF/R9CH/R9CB	176 240
Ignition Coil	<b>80255</b>
<b>Orion I (AFD) 1.3</b>	<b>1983-86</b>
JPA	51 69
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Orion I (AFD) 1.6</b>	<b>1983-86</b>
LP1/LPA	58 79
Ignition Leads	<b>83400</b>

FORD Cont.	
<b>Orion I (AFD) 1.6 i</b>	<b>1983-86</b>
LRA/LR1	77 105
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Orion II (AFF) 1.3</b>	<b>1985-90</b>
JLA/JBB/JLB	44 60
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83400</b>
<b>Orion II (AFF) 1.4</b>	<b>1986-90</b>
FUC	54 73
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Orion II (AFF) 1.4</b>	<b>1985-90</b>
FUA	55 75
Ignition Coil	<b>80213</b>
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Orion II (AFF) 1.4</b>	<b>1986-90</b>
FUAA	52 72
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Orion II (AFF) 1.4 KAT</b>	<b>1987-90</b>
F6D/F6B	54 73
Ignition Coil	<b>80213</b>
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Orion II (AFF) 1.6</b>	<b>1985-90</b>
LUC	66 90
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Orion II (AFF) 1.6 i</b>	<b>1989-90</b>
LJB	75 102
Ignition Coil	<b>80213</b>
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Orion II (AFF) 1.6 i</b>	<b>1986-90</b>
LRB	77 105
Ignition Coil	<b>80213</b>
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Orion II (AFF) 1.6 i KAT</b>	<b>1986-90</b>
L4B	66 90
Ignition Coil	<b>80213</b>
Ignition Leads DIN	<b>83400</b>
Ignition Leads	<b>83450</b>
<b>Orion III (GAL) 1.3</b>	<b>1990-93</b>
J6A/J4B	44 60
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83450</b>
<b>Orion III (GAL) 1.4</b>	<b>1990-93</b>
F6F/F6G	52 71
Ignition Coil	<b>80213</b>
<b>Orion III (GAL) 1.4</b>	<b>1990-93</b>
FUH	54 73
Ignition Coil	<b>80213</b>
<b>Orion III (GAL) 1.6</b>	<b>1990-92</b>
LUJ/LUK	66 90
Ignition Coil	<b>80213</b>
<b>Orion III (GAL) 1.6 i</b>	<b>1990-92</b>
LJF	77 105
Ignition Coil	<b>80213</b>
<b>Orion III (GAL) 1.6 i 16V</b>	<b>1992-93</b>
L1E/L1K	66 90
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Orion III (GAL) 1.8 i 16V</b>	<b>1992-93</b>
RDA	77 105
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>Orion III (GAL) 1.8 i 16V</b>	<b>1992-93</b>
RQB	96 130
Ignition Coil With regul.cat.(3way)	<b>80213</b>
<b>P 100 II 2.0</b>	<b>1987-92</b>
NAE	57 78
Ignition Leads	<b>83400</b>
<b>Puma (EC) 1.4 16V</b>	<b>1997-00</b>
FHD/FHF	66 90
Ignition Coil ->04.1998	<b>80213</b>
Ignition Coil ->05.1998; With regul.cat.(3way)	<b>80214</b>
Ignition Coil 06.1998->	<b>80285</b>
Ignition Leads 06.1998->	<b>85115</b>



FORD Cont.		
<b>Puma (EC) 1.6 16V</b>		<b>2000-02</b>
L1W		76 103
Ignition Coil With regul.cat.(3way)		<b>80214</b>
Ignition Coil ->12.2001		<b>80285</b>
Ignition Leads		<b>85115</b>
<b>Puma (EC) 1.7 16V</b>		<b>1997-02</b>
MHB/MHA		92 125
Ignition Coil ->04.1998		<b>80213</b>
Ignition Coil 05.1998->; With regul.cat.(3way)		<b>80214</b>
Ignition Coil 06.1998-12.2001		<b>80285</b>
Ignition Leads MHA; Engine 01.1998->		<b>85115</b>
<b>Puma (EC) ST 160</b>		<b>1999-02</b>
		118 160
Ignition Leads 05.2000-04.2001		<b>85116</b>
<b>Scorpio I (GAE, GGE) 1.8</b>		<b>1985-92</b>
REC		66 90
Ignition Leads		<b>83400</b>
<b>Scorpio I (GAE, GGE) 2.0</b>		<b>1985-89</b>
N8D/NEL		77 105
Ignition Leads		<b>83400</b>
<b>Scorpio I (GAE, GGE) 2.0 i</b>		<b>1985-90</b>
NRC		74 100
Ignition Leads NRC		<b>83400</b>
<b>Scorpio I (GAE, GGE) 2.0 i</b>		<b>1985-92</b>
NRI/NRA		85 115
Ignition Leads ->12.1989		<b>83400</b>
Ignition Leads NRA		<b>83460</b>
Ignition Leads 01.1990->		<b>85710</b>
<b>Scorpio I (GAE, GGE) 2.0 i</b>		<b>1992-94</b>
NRI/NRA		85 115
Ignition Leads		<b>85710</b>
<b>Scorpio I (GAE, GGE) 2.0 i</b>		<b>1989-94</b>
N9D		88 120
Ignition Leads ->12.1991		<b>83460</b>
Ignition Leads 01.1992->		<b>85710</b>
<b>Scorpio I (GAE, GGE) 2.9 i 24V</b>		<b>1991-94</b>
BOA		143 195
Ignition Coil		<b>80306</b>
<b>Scorpio I Break (GGE) 2.0 i</b>		<b>1991-94</b>
N9F		85 115
Ignition Leads		<b>85710</b>
<b>Scorpio I Break (GGE) 2.0 i</b>		<b>1991-94</b>
N9D		88 120
Ignition Leads		<b>85710</b>
<b>Scorpio I Break (GGE) 2.9 24V</b>		<b>1993-94</b>
BOA		143 195
Ignition Coil		<b>80306</b>
<b>Scorpio I Sedan (GGE) 2.0 i</b>		<b>1992-94</b>
N9F		85 115
Ignition Leads		<b>85710</b>
<b>Scorpio I Sedan (GGE) 2.0 i</b>		<b>1989-94</b>
N9D		88 120
Ignition Coil		<b>80213</b>
Ignition Leads		<b>85710</b>
<b>Scorpio I Sedan (GGE) 2.9 i 24V</b>		<b>1991-94</b>
BOA		143 195
Ignition Coil		<b>80306</b>
<b>Scorpio II (GFR, GGR) 2.0 i 16V</b>		<b>1994-98</b>
N3A		100 136
Ignition Coil		<b>80305</b>
<b>Scorpio II (GFR, GGR) 2.3 i 16V</b>		<b>1996-98</b>
Y5A		108 147
Ignition Coil		<b>80305</b>
<b>Scorpio II (GFR, GGR) 2.9 i 24V</b>		<b>1994-98</b>
BOB		152 207
Ignition Coil		<b>80306</b>
<b>Scorpio II Break (Gnr, GGR) 2.0 i 16V</b>		<b>1994-98</b>
N3A		100 136
Ignition Coil		<b>80305</b>
<b>Scorpio II Break (Gnr, GGR) 2.3 i 16V</b>		<b>1996-98</b>
Y5A		108 147
Ignition Coil		<b>80305</b>
<b>Scorpio II Break (Gnr, GGR) 2.9 i 24V</b>		<b>1994-98</b>
BOB		152 207
Ignition Coil		<b>80306</b>

FORD Cont.		
<b>Sierra (GBG, GB4) 1.6</b>		<b>1987-93</b>
LSE		55 75
Ignition Coil		<b>80213</b>
Ignition Leads ->12.1991		<b>83400</b>
Ignition Leads		<b>83460</b>
<b>Sierra (GBG, GB4) 1.6</b>		<b>1988-93</b>
LSF		53 72
Ignition Leads LSF		<b>83400</b>
Ignition Leads		<b>83460</b>
<b>Sierra (GBG, GB4) 1.6 i</b>		<b>1989-93</b>
L6B		59 80
Ignition Coil		<b>80213</b>
Ignition Leads 01.1991->		<b>83450</b>
Ignition Leads		<b>83460</b>
<b>Sierra (GBG, GB4) 1.8</b>		<b>1988-93</b>
R2C/R6A		64 87
Ignition Coil		<b>80213</b>
Ignition Leads R2C		<b>83460</b>
<b>Sierra (GBG, GB4) 1.8</b>		<b>1987-89</b>
RED/REF		59 80
Ignition Leads RED		<b>83460</b>
<b>Sierra (GBG, GB4) 2.0</b>		<b>1987-93</b>
N8C/NES		77 105
Ignition Leads NES		<b>83460</b>
Ignition Leads N8C; 05.1989->		<b>85710</b>
<b>Sierra (GBG, GB4) 2.0 4x4</b>		<b>1990-93</b>
N9C		92 125
Ignition Leads		<b>83460</b>
Ignition Leads DIN		<b>85710</b>
<b>Sierra (GBG, GB4) 2.0 4x4</b>		<b>1990-93</b>
N9C		88 120
Ignition Leads		<b>83460</b>
<b>Sierra (GBG, GB4) 2.0 i</b>		<b>1990-93</b>
N9C		92 125
Ignition Leads		<b>83460</b>
Ignition Leads DIN		<b>85710</b>
<b>Sierra (GBG, GB4) 2.0 i</b>		<b>1990-93</b>
N9C		88 120
Ignition Leads		<b>83460</b>
<b>Sierra Break/Estate (BNC) 1.6</b>		<b>1982-86</b>
LCS/LCT/LSD		55 75
Ignition Leads		<b>83400</b>
<b>Sierra Break/Estate (BNC) 1.8</b>		<b>1984-86</b>
REB		66 90
Ignition Leads		<b>83400</b>
<b>Sierra Break/Estate (BNC) 2.0</b>		<b>1985-86</b>
NRD		74 100
Ignition Leads		<b>83400</b>
<b>Sierra Break/Estate (BNC) 2.0</b>		<b>1982-86</b>
NET		77 105
Ignition Leads		<b>83400</b>
<b>Sierra Break/Estate (BNC) 2.0</b>		<b>1985-86</b>
NR2/NRB		85 115
Ignition Leads		<b>83400</b>
<b>Sierra Estate (BNG) 1.6</b>		<b>1988-93</b>
LSF		53 72
Ignition Leads		<b>83460</b>
<b>Sierra Estate (BNG) 1.6</b>		<b>1987-93</b>
LSE		55 75
Ignition Leads ->12.1991		<b>83400</b>
Ignition Leads		<b>83460</b>
<b>Sierra Estate (BNG) 1.6 i</b>		<b>1989-93</b>
L6B		59 80
Ignition Coil		<b>80213</b>
Ignition Leads		<b>83400</b>
<b>Sierra Estate (BNG) 1.8</b>		<b>1988-93</b>
R2C/R6A		64 87
Ignition Coil		<b>80213</b>
Ignition Leads		<b>83460</b>
<b>Sierra Estate (BNG) 1.8</b>		<b>1987-88</b>
RED/REF		59 80
Ignition Leads		<b>83460</b>
<b>Sierra Estate (BNG) 1.8</b>		<b>1987-88</b>
RED/R2A		66 90
Ignition Leads		<b>83460</b>
<b>Sierra Estate (BNG) 2.0</b>		<b>1987-93</b>
N8C/NES		77 105
Ignition Leads		<b>83460</b>
Ignition Leads 05.1989->		<b>85710</b>





FORD Cont.	
<b>Sierra Estate (BNG) 2.0 4x4</b>	<b>1989-93</b>
N9C	92 125
Ignition Leads	<b>83460</b>
Ignition Leads DIN	<b>85710</b>
<b>Sierra Estate (BNG) 2.0 4x4</b>	<b>1990-93</b>
N9C	88 120
Ignition Leads	<b>83460</b>
Ignition Leads DIN	<b>85710</b>
<b>Sierra Estate (BNG) 2.0 i</b>	<b>1989-93</b>
N9C	92 125
Ignition Leads	<b>83460</b>
Ignition Leads DIN	<b>85710</b>
<b>Sierra Estate (BNG) 2.0 i</b>	<b>1987-93</b>
N41/N4A	85 115
Ignition Leads	<b>83460</b>
<b>Sierra Estate (BNG) 2.0 i</b>	<b>1989-93</b>
N9C	88 120
Ignition Leads	<b>83460</b>
Ignition Leads DIN	<b>85710</b>
<b>Sierra Estate (BNG) 2.0 i</b>	<b>1987-93</b>
NE5/NEJ	74 100
Ignition Leads	<b>83460</b>
<b>Sierra Estate (BNG) 2.0 i KAT</b>	<b>1987-93</b>
N4B	74 100
Ignition Leads	<b>83460</b>
<b>Sierra Hatchback (GBC) 1.3</b>	<b>1982-86</b>
JCT	44 60
Ignition Leads	<b>83400</b>
<b>Sierra Hatchback (GBC) 1.6</b>	<b>1982-86</b>
LCS/LCT/LSD	55 75
Ignition Leads	<b>83400</b>
<b>Sierra Hatchback (GBC) 1.6</b>	<b>1984-86</b>
LSD	58 79
Ignition Leads	<b>83400</b>
<b>Sierra Hatchback (GBC) 1.8</b>	<b>1984-86</b>
REB	66 90
Ignition Leads	<b>83400</b>
<b>Sierra Hatchback (GBC) 2.0</b>	<b>1985-86</b>
NRD	74 100
Ignition Leads	<b>83400</b>
<b>Sierra Hatchback (GBC) 2.0</b>	<b>1982-86</b>
NET	77 105
Ignition Leads	<b>83400</b>
<b>Sierra Hatchback (GBC, GBG) 1.6</b>	<b>1987-93</b>
LSE	55 75
Ignition Coil	<b>80213</b>
Ignition Leads ->12.1991	<b>83400</b>
Ignition Leads 01.1992->	<b>83460</b>
<b>Sierra Hatchback (GBC, GBG) 1.6</b>	<b>1988-93</b>
LSF	53 72
Ignition Leads ->12.1991	<b>83400</b>
Ignition Leads	<b>83460</b>
<b>Sierra Hatchback (GBC, GBG) 1.6 i</b>	<b>1989-93</b>
L6B	59 80
Ignition Coil	<b>80213</b>
Ignition Leads 01.1991->	<b>83450</b>
Ignition Leads	<b>83460</b>
<b>Sierra Hatchback (GBC, GBG) 1.8</b>	<b>1988-93</b>
R2C/R6A	64 87
Ignition Coil	<b>80213</b>
Ignition Leads R6A	<b>83460</b>
<b>Sierra Hatchback (GBC, GBG) 2.0</b>	<b>1987-93</b>
N8C/NES	77 105
Ignition Leads	<b>85710</b>
Ignition Leads N8C	<b>85760</b>
<b>Sierra Hatchback (GBC, GBG) 2.0 16V Cosworth 4x4</b>	<b>1990-93</b>
N5D	162 220
Ignition Leads	<b>83460</b>
<b>Sierra Hatchback (GBC, GBG) 2.0 16V Cosworth 4x4 KAT</b>	<b>1990-93</b>
N5C	162 220
Ignition Leads	<b>83460</b>
<b>Sierra Hatchback (GBC, GBG) 2.0 i</b>	<b>1987-93</b>
N41/N4A	85 115
Ignition Leads N4A	<b>83460</b>
<b>Sierra Hatchback (GBC, GBG) 2.0 i</b>	<b>1989-93</b>
N9C	88 120
Ignition Leads	<b>83460</b>
Ignition Leads DIN	<b>85710</b>

FORD Cont.	
<b>Sierra Hatchback (GBC, GBG) 2.0 i</b>	<b>1989-93</b>
N9B	92 125
Ignition Leads	<b>83460</b>
Ignition Leads DIN	<b>85710</b>
<b>Sierra Hatchback (GBC, GBG) 2.0 i</b>	<b>1987-93</b>
NE5/NEJ	74 100
Ignition Leads NEJ	<b>83460</b>
<b>Sierra Hatchback (GBC, GBG) 2.0 RS Cosworth</b>	<b>1987-90</b>
N5B	150 204
Ignition Leads	<b>83460</b>
<b>S-Max (WA6) 2.0</b>	<b>2006-14</b>
AOWB/AOWA	107 145
Ignition Coil	<b>80231</b>
<b>S-Max (WA6) 2.0 EcoBoost</b>	<b>2010-14</b>
TNWA	149 203
Ignition Coil	<b>80255</b>
<b>S-Max (WA6) 2.0 EcoBoost</b>	<b>2010-14</b>
TNWB	146 199
Ignition Coil	<b>80255</b>
<b>S-Max (WA6) 2.0 EcoBoost</b>	<b>2010-14</b>
TPWA	176 240
Ignition Coil	<b>80255</b>
<b>S-Max (WA6) 2.0 Flexifuel</b>	<b>2006-14</b>
TBWA/TBWB	107 145
Ignition Coil	<b>80231</b>
<b>S-Max (WA6) 2.3</b>	<b>2007-14</b>
SEWA	118 160
Ignition Coil	<b>80230</b>
<b>S-Max (WA6) 2.5 ST</b>	<b>2006-14</b>
HUWA	162 220
Ignition Coil	<b>80304</b>
<b>S-Max 2.0 EcoBoost</b>	<b>2015-&gt;</b>
R9CD/R9CI	176 240
Ignition Coil R9CI	<b>80255</b>
<b>Street Ka (RI2) 1.6</b>	<b>2003-05</b>
CDRA/CDRB	70 95
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil	<b>80285</b>
Ignition Leads 01.2004->	<b>85126</b>
<b>Tourneo Connect 1.8 16V</b>	<b>2002-13</b>
EYPC/EYPA/EYPD	85 116
Ignition Coil DIN	<b>80213</b>
Ignition Coil EYPC,EYPA; With regul.cat.(3way)	<b>80214</b>
Ignition Coil ->06.2010	<b>80285</b>
<b>Tourneo Connect 1.8 TDCi /TDDi /DI</b>	<b>2002-13</b>
BHPA/P7PA/P7PB/R2PA	55 75
Ignition Leads	<b>85146</b>
<b>Transit Box (T) 1,6</b>	<b>1985-92</b>
LAT	46 63
Ignition Leads	<b>83400</b>
<b>Transit Box (T) 2.0</b>	<b>1985-92</b>
NAT/NAV	57 78
Ignition Leads	<b>83400</b>
<b>Transit Box (V) 1,6</b>	<b>1977-86</b>
4RB	48 65
Ignition Leads	<b>83400</b>
<b>Transit Box (V) 2.0</b>	<b>1977-86</b>
4RC	57 78
Ignition Leads	<b>83400</b>
<b>Transit Box (V) 2.0</b>	<b>1977-82</b>
4RC	43 59
Ignition Leads	<b>83400</b>
<b>Transit Box (V) 2.0</b>	<b>1977-86</b>
4RC	55 75
Ignition Leads	<b>83400</b>
<b>Transit Bus (E) 2.0</b>	<b>1991-94</b>
NBA	66 90
Ignition Leads	<b>83400</b>
<b>Transit Bus (E) 2.0 i</b>	<b>1991-94</b>
NCA	72 98
Ignition Leads 01.1993->	<b>83400</b>
<b>Transit Bus (FD , FB , FS , FZ , FC ) 2.3 16V [RWD]</b>	<b>2000-06</b>
E5FC/E5FA	107 146
Ignition Coil	<b>80305</b>
<b>Transit Bus (T) 1,6</b>	<b>1985-89</b>
LAT	46 63
Ignition Leads	<b>83400</b>





<b>FORD Cont.</b>	
<b>Transit Bus (T) 2.0</b>	<b>1985-92</b>
NAT/NAV	57 78
Ignition Leads	<b>83400</b>
Ignition Leads NAV	<b>83460</b>
<b>Transit Bus (T) 2.0 KAT</b>	<b>1985-92</b>
N6T	57 78
Ignition Leads	<b>83400</b>
<b>Transit Bus (V) 1,6</b>	<b>1977-86</b>
4RB	48 65
Ignition Leads	<b>83400</b>
<b>Transit Bus (V) 2.0</b>	<b>1977-86</b>
4RC	57 78
Ignition Leads	<b>83400</b>
<b>Transit Bus (V) 2.0</b>	<b>1977-82</b>
4RC	43 59
Ignition Leads	<b>83400</b>
<b>Transit Bus (V) 2.0</b>	<b>1977-86</b>
4RC	55 75
Ignition Leads	<b>83400</b>
<b>Transit Chassis (E) 2.0</b>	<b>1991-94</b>
NCA	72 98
Ignition Leads 01.1993->	<b>83400</b>
<b>Transit Chassis (FM, FN) 2.3 16V</b>	<b>2001-06</b>
E5FC/E5FA	107 146
Ignition Coil	<b>80305</b>
<b>Transit Chassis (T) 2.0</b>	<b>1986-92</b>
NAT/NAV	57 78
Ignition Leads	<b>83400</b>
Ignition Leads NAV	<b>83460</b>
<b>Transit Chassis (T) 2.0 KAT</b>	<b>1985-92</b>
N6T	57 78
Ignition Leads	<b>83400</b>
<b>Transit Chassis (V) 1,6</b>	<b>1977-86</b>
B	48 65
Ignition Leads	<b>83400</b>
<b>Transit Chassis (V) 2.0</b>	<b>1977-82</b>
4RC	43 59
Ignition Leads	<b>83400</b>
<b>Transit Chassis (V) 2.0</b>	<b>1977-86</b>
4RC	57 78
Ignition Leads	<b>83400</b>
<b>Transit Chassis 2.3 16V</b>	<b>2006-14</b>
GZFA/GZFC/GZFB	107 145
Ignition Coil	<b>80231</b>
<b>Transit Connect (P65, P70, P80) 1.8 16V</b>	<b>2002-13</b>
EYPC/EYPA/EYPD	85 116
Ignition Coil DIN	<b>80213</b>
Ignition Coil EYPA,EYPC; With regul.cat.(3way)	<b>80214</b>
Ignition Coil ->06.2010	<b>80285</b>
<b>Transit Van (E) 2.0</b>	<b>1991-94</b>
NBA	66 90
Ignition Leads 01.1993->	<b>83400</b>
<b>Transit Van (E) 2.0 i</b>	<b>1991-94</b>
NCA	72 98
Ignition Leads 01.1993->	<b>83400</b>
<b>Transit Van (FA) 2.3 16V [RWD]</b>	<b>2001-06</b>
E5FC/E5FA	107 146
Ignition Coil	<b>80305</b>
<b>Transit Van 2.3 16V</b>	<b>2006-14</b>
GZFA/GZFC/GZFB	107 145
Ignition Coil	<b>80231</b>

<b>FORD AUSTRALIA</b>	
<b>Mustang Cabriolet 4.6 V8</b>	<b>2005-&gt;</b>
	224 305
Ignition Coil	<b>80360</b>
<b>Mustang Coupe 4.6 V8</b>	<b>2004-&gt;</b>
	224 305
Ignition Coil	<b>80360</b>

<b>FORD USA</b>	
<b>Expedition 5.4</b>	<b>2002-06</b>
	194 264
Ignition Coil	<b>80360</b>
<b>Expedition 5.4 4x4</b>	<b>2002-06</b>
	194 264
Ignition Coil	<b>80360</b>

<b>FORD USA Cont.</b>	
<b>Explorer (U251) 4.6</b>	<b>2006-10</b>
	218 296
Ignition Coil	<b>80360</b>
<b>Explorer (U251) 4.6 4WD</b>	<b>2006-08</b>
	218 296
Ignition Coil	<b>80360</b>
<b>Explorer 4.6 4WD</b>	<b>2001-05</b>
	178 242
Ignition Coil	<b>80360</b>
<b>F-150 5.4</b>	<b>2007-&gt;</b>
	221 300
Ignition Coil	<b>80360</b>
<b>F-150 5.4 4x4</b>	<b>2007-&gt;</b>
	221 300
Ignition Coil	<b>80360</b>
<b>F-150 5.4 SVT 4x4</b>	<b>2004-07</b>
	194 264
Ignition Coil	<b>80360</b>
<b>F-250 5.4</b>	<b>2003-07</b>
	194 264
Ignition Coil	<b>80360</b>
<b>F-250 5.4</b>	<b>2007-&gt;</b>
	221 300
Ignition Coil	<b>80360</b>
<b>F-250 5.4 4x4</b>	<b>2003-07</b>
	194 264
Ignition Coil	<b>80360</b>
<b>F-250 5.4 4x4</b>	<b>2007-&gt;</b>
	221 300
Ignition Coil	<b>80360</b>
<b>F-350 5.4</b>	<b>2007-&gt;</b>
	221 300
Ignition Coil	<b>80360</b>
<b>F-350 5.4 4x4</b>	<b>2007-&gt;</b>
	221 300
Ignition Coil	<b>80360</b>
<b>F-350 5.4 4x4</b>	<b>2003-07</b>
	194 264
Ignition Coil	<b>80360</b>
<b>Mustang Convertible 2.3 EcoBoost</b>	<b>2015-&gt;</b>
	231 314
Ignition Coil 04.2015->	<b>80255</b>
<b>Mustang Convertible 2.3 EcoBoost</b>	<b>2015-&gt;</b>
	233 317
Ignition Coil	<b>80255</b>
<b>Mustang Convertible 4.6 V8</b>	<b>2005-&gt;</b>
	224 305
Ignition Coil	<b>80360</b>
<b>Mustang Coupe 2.3 EcoBoost</b>	<b>2015-&gt;</b>
N38H/N48H	231 314
Ignition Coil 04.2015->	<b>80255</b>
<b>Mustang Coupe 2.3 EcoBoost</b>	<b>2015-&gt;</b>
	233 317
Ignition Coil	<b>80255</b>
<b>Mustang Coupe 4.6 V8</b>	<b>2004-&gt;</b>
	224 305
Ignition Coil	<b>80360</b>
<b>Windstar (A3) 3.0 V6</b>	<b>1999-&gt;</b>
	108 147
Ignition Coil	<b>80306</b>
<b>Windstar (A3) 3.0 V6</b>	<b>1995-99</b>
	109 148
Ignition Coil	<b>80306</b>

<b>FSO</b>	
<b>Polonez III 1.4 i 16V</b>	<b>1992-02</b>
Rover K16 DOHC	76 103
Ignition Coil	<b>80254</b>
<b>Polonez III 1.6 i</b>	<b>1992-02</b>
147CK46	57 78
Ignition Coil CE/CF	<b>80279</b>
<b>Polonez III Sedan 1.6 i</b>	<b>1992-02</b>
147CK46	57 78
Ignition Coil	<b>80279</b>



<b>HOLDEN</b>		
<b>Adentra Kombi (VZ) 3.6 i V6 AWD</b>	<b>2006-09</b>	
H7/LY7	195	265
Ignition Coil H7	<b>80355</b>	
<b>Astra Cabriolet (TS) 2.0 i Turbo</b>	<b>2002-04</b>	
Z 20 LET/Z 20 LER	147	200
Ignition Coil	<b>80354</b>	
<b>Astra Fastback (TS) 2.0 i Turbo</b>	<b>2003-04</b>	
Z 20 LET	147	200
Ignition Coil	<b>80354</b>	
<b>Astra Spotsback (AH) 2.0 i Turbo</b>	<b>2006-10</b>	
Z 20 LER	147	200
Ignition Coil	<b>80354</b>	
<b>Barina Fastback (XC) 1.4 Efi</b>	<b>2004-05</b>	
Z 14 XEP	66	90
Ignition Coil	<b>80350</b>	
<b>Caprice Sedan (WL) 3.6 i V6</b>	<b>2004-06</b>	
H7/LY7	190	258
Ignition Coil H7	<b>80355</b>	
<b>Combo Kasten (XC) 1.4 i</b>	<b>2005-12</b>	
Z 14 XEP	66	90
Ignition Coil ->04.2012	<b>80350</b>	
<b>Commodore Kombi (VZ) 3.6 i V6</b>	<b>2004-06</b>	
HB/LEO	175	238
Ignition Coil HB	<b>80355</b>	
<b>Commodore Kombi (VZ) 3.6 i V6</b>	<b>2004-07</b>	
HB/LEO	180	245
Ignition Coil	<b>80355</b>	
<b>Commodore Pick-up (VZ) 3.6 i V6</b>	<b>2004-06</b>	
HB/LEO	175	238
Ignition Coil HB	<b>80355</b>	
<b>Commodore Sedan (VZ) 3.6 i V6</b>	<b>2004-06</b>	
HB/LEO	175	238
Ignition Coil HB	<b>80355</b>	
<b>Commodore Sedan (VZ) 3.6 i V6</b>	<b>2004-06</b>	
H7/LY7	190	258
Ignition Coil LY7	<b>80355</b>	
<b>Cruze Sedan (JG) 1.8 i</b>	<b>2009-11</b>	
F18D	104	141
Ignition Coil	<b>80351</b>	
<b>Frontera (UES) 2.2 i 4x4</b>	<b>1999-02</b>	
X 22 SE	96	131
Ignition Coil	<b>80318</b>	
<b>One Tonner Chassis(VZ) 3.6 i V6</b>	<b>2004-05</b>	
HB/LEO	175	238
Ignition Coil HB	<b>80355</b>	
<b>Statesman Sedan (WL) 3.6 VVT</b>	<b>2004-06</b>	
H7/LY7	190	258
Ignition Coil H7	<b>80355</b>	

<b>HONDA</b>		
<b>Accord III (CA) 2.0 i 16V</b>	<b>1987-89</b>	
B20A8	98	133
Ignition Leads B20A8	<b>85811</b>	
<b>Accord III (CA) 2.0 i 16V</b>	<b>1987-87</b>	
B20A2	101	137
Ignition Leads B20A2	<b>85811</b>	
<b>Accord IV (CB) 2.0 16V</b>	<b>1990-93</b>	
F20A6	66	90
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord IV (CB) 2.0 16V</b>	<b>1990-93</b>	
F20A3/F20A2	81	110
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord IV (CB) 2.0 i 16V</b>	<b>1990-93</b>	
F20A4/F20A8	98	133
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord IV (CB) 2.2 i 16V</b>	<b>1990-93</b>	
F22A3	110	150
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	

<b>HONDA Cont.</b>		
<b>Accord IV (CB) 2.2 i 16V Automatik</b>	<b>1990-93</b>	
F22A3	108	147
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord IV Aerodeck (CB) 2.0 i 16V</b>	<b>1993-93</b>	
F20Z3	98	133
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
<b>Accord IV Aerodeck (CB) 2.2 i 16V</b>	<b>1991-93</b>	
F22A8	108	147
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord IV Aerodeck (CB) 2.2 i 16V</b>	<b>1991-93</b>	
F22A7	110	150
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord IV Coupe (CB, CC) 2.0 i 16V</b>	<b>1992-93</b>	
F20A7	98	133
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads ->08.1993	<b>85821</b>	
<b>Accord V (CC, CD) 2.0 i</b>	<b>1993-96</b>	
F20Z2	85	116
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
<b>Accord V (CC, CD) 2.0 i S</b>	<b>1993-96</b>	
F20Z1	96	131
Ignition Coil	<b>80250</b>	
Ignition Coil ->09.1995; With ignition distributor	<b>80299</b>	
Ignition Leads	<b>85811</b>	
<b>Accord V (CC, CD) 2.3 i SR</b>	<b>1993-96</b>	
H23A3	116	158
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
<b>Accord V (CE, CF) 1.9 i</b>	<b>1996-98</b>	
F18A3	85	116
Ignition Coil F18A3	<b>80250</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord V (CE, CF) 2.0 i LS</b>	<b>1996-98</b>	
F20Z1	96	131
Ignition Coil F20Z1	<b>80250</b>	
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
<b>Accord V (CE, CF) 2.2 i VTEC</b>	<b>1996-98</b>	
F22Z2	110	150
Ignition Coil F22Z2	<b>80250</b>	
Ignition Leads F22Z2	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord V Aerodeck (CE) 2.0 i LS 16V</b>	<b>1993-98</b>	
F20B3	100	136
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
<b>Accord V Aerodeck (CE) 2.2 i ES</b>	<b>1993-98</b>	
F22B5	110	150
Ignition Coil	<b>80299</b>	
Ignition Leads ->12.1994	<b>85811</b>	
Ignition Leads 01.1995->	<b>85821</b>	
<b>Accord V Coupe (CD) 2.0</b>	<b>1993-97</b>	
F20B3	100	136
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85811</b>	
<b>Accord V Coupe (CD) 2.2 i ES</b>	<b>1993-98</b>	
F22B5	110	150
Ignition Coil	<b>80299</b>	
Ignition Leads ->12.1994	<b>85811</b>	
Ignition Leads 01.1995->	<b>85821</b>	
<b>Accord VI (CG, CK) 1.8 i</b>	<b>1998-02</b>	
F18B2	100	136
Ignition Coil F18B2	<b>80250</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord VI (CG, CK) 2,3</b>	<b>2001-03</b>	
F23Z5/F23A1	113	154
Ignition Coil	<b>80250</b>	
Ignition Leads	<b>85821</b>	



<b>HONDA Cont.</b>		
<b>Accord VI (CG, CK) 2.0 i</b>	<b>1998-01</b>	
F20B6	108 147	
Ignition Coil F20B6	<b>80250</b>	
Ignition Leads	<b>85821</b>	
<b>Accord VI (CG, CK) 2.2 Type-R</b>	<b>1999-02</b>	
H22A7	156 212	
Ignition Coil	<b>80299</b>	
<b>Accord VI Coupe (CG) 2.0 i 16V</b>	<b>1998-03</b>	
F20B7/F20B5	108 147	
Ignition Coil F20B5,F20B7	<b>80250</b>	
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85821</b>	
<b>Accord VI Coupe (CG) 3.0 V6 24V</b>	<b>1998-03</b>	
J30A1	147 200	
Ignition Coil	<b>80300</b>	
<b>Accord VI Hatchback (Ch) 1.8 i</b>	<b>1999-02</b>	
F18B2	100 136	
Ignition Coil	<b>80250</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Accord VI Hatchback (Ch) 2,3</b>	<b>2000-02</b>	
F23Z5	113 154	
Ignition Coil	<b>80250</b>	
Ignition Leads	<b>85821</b>	
<b>Accord VI Hatchback (Ch) 2.0</b>	<b>1999-02</b>	
F20B6	108 147	
Ignition Coil F20B6	<b>80250</b>	
Ignition Leads	<b>85821</b>	
<b>Accord VII (CL) 2.0 4WD</b>	<b>2003-08</b>	
K20A6	114 155	
Ignition Coil	<b>80348</b>	
<b>Accord VIII (CU) 2.0 i</b>	<b>2008-15</b>	
R20A3	115 156	
Ignition Coil	<b>80347</b>	
<b>Accord VIII Tourer 2.0 i</b>	<b>2008-&gt;</b>	
R20A3	115 156	
Ignition Coil	<b>80347</b>	
<b>Airwave 1.5 i-DSI</b>	<b>2004-&gt;</b>	
L15A2	81 110	
Ignition Coil	<b>80336</b>	
<b>Airwave 1.5 i-DSI MDS 4x4</b>	<b>2004-&gt;</b>	
L15A2	81 110	
Ignition Coil	<b>80336</b>	
<b>City Sedan (GE4) 1.3 i-DSI 4WD</b>	<b>2002-08</b>	
L13A1/L13A8	63 86	
Ignition Coil	<b>80297</b>	
Ignition Coil	<b>80298</b>	
<b>City Sedan (GE4) 1.3 SES</b>	<b>2003-08</b>	
L13A1/L13A8	63 86	
Ignition Coil	<b>80297</b>	
Ignition Coil	<b>80298</b>	
<b>City Sedan (GM) 1.4 i-V TEC</b>	<b>2008-&gt;</b>	
L13Z1	73 99	
Ignition Coil Entry	<b>80297</b>	
Ignition Coil Departure	<b>80298</b>	
<b>Civic II Shuttle (EE) 1.4 i 16V</b>	<b>1988-92</b>	
D14A1	66 90	
Ignition Leads D14A1	<b>85811</b>	
Ignition Leads ->09.1989	<b>85821</b>	
<b>Civic II Shuttle (EE) 1.5 i 16V</b>	<b>1988-91</b>	
D15B2	69 94	
Ignition Leads	<b>85821</b>	
<b>Civic II Shuttle (EE) 1.6 i 16V 4WD</b>	<b>1988-95</b>	
D16A6	81 110	
Ignition Leads	<b>85811</b>	
<b>Civic III Hatchback (AL, AJ, AG, AH) 1,2</b>	<b>1984-87</b>	
ZA2/D12B1	40 54	
Ignition Leads	<b>86030</b>	
<b>Civic III Hatchback (AL, AJ, AG, AH) 1,3</b>	<b>1983-87</b>	
EV2	52 71	
Ignition Leads	<b>86030</b>	
<b>Civic III Sedan (AM, AK, AU) 1.2</b>	<b>1985-87</b>	
ZA2/D12B1	40 54	
Ignition Leads	<b>86030</b>	
<b>Civic III Sedan (AM, AK, AU) 1.3</b>	<b>1983-87</b>	
EV2	52 71	
Ignition Leads	<b>86030</b>	

<b>HONDA Cont.</b>		
<b>Civic IV Hatchback (EC, ED, EE) 1,3</b>	<b>1987-89</b>	
D13B1	55 75	
Ignition Leads	<b>85811</b>	
Ignition Leads With ignition distributor	<b>85821</b>	
<b>Civic IV Hatchback (EC, ED, EE) 1.3 16 V KAT</b>	<b>1989-91</b>	
D13B2	55 75	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Civic IV Hatchback (EC, ED, EE) 1.4 L</b>	<b>1987-89</b>	
D14A1	66 90	
Ignition Leads	<b>85390</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Civic IV Hatchback (EC, ED, EE) 1.5 i 16V</b>	<b>1988-91</b>	
D15B2	66 90	
Ignition Leads With ignition distributor	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Civic IV Hatchback (EC, ED, EE) 1.5 i 16V</b>	<b>1988-91</b>	
D15B2	69 94	
Ignition Leads D15B2	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Civic IV Hatchback (EC, ED, EE) 1.6 i 16V</b>	<b>1987-91</b>	
D16A6	80 109	
Ignition Leads	<b>85821</b>	
<b>Civic IV Hatchback (EC, ED, EE) 1.6 i 16V</b>	<b>1987-91</b>	
D16Z2	81 110	
Ignition Leads	<b>85811</b>	
Ignition Leads D16A6	<b>85821</b>	
<b>Civic IV Hatchback (EC, ED, EE) 1.6 i 16V</b>	<b>1987-91</b>	
D16A9/D16A7	96 130	
Ignition Leads D16A7	<b>85811</b>	
<b>Civic IV Sedan (ED) 1.3</b>	<b>1987-89</b>	
D13B1	55 75	
Ignition Leads	<b>85811</b>	
Ignition Leads With ignition distributor	<b>85821</b>	
<b>Civic IV Sedan (ED) 1.4 L</b>	<b>1987-89</b>	
D14A1	66 90	
Ignition Leads	<b>85390</b>	
Ignition Leads	<b>85811</b>	
Ignition Leads	<b>85821</b>	
<b>Civic IV Sedan (ED) 1.5 i 16V</b>	<b>1987-91</b>	
D15B2	66 90	
Ignition Leads	<b>85821</b>	
<b>Civic IV Sedan (ED) 1.5 i 16V</b>	<b>1987-91</b>	
D15B2	69 94	
Ignition Leads	<b>85821</b>	
<b>Civic IV Sedan (ED) 1.6 i 16V</b>	<b>1987-91</b>	
D16A6	80 109	
Ignition Leads D16A6	<b>85811</b>	
<b>Civic IV Sedan (ED) 1.6 i 16V</b>	<b>1987-91</b>	
D16Z2	81 110	
Ignition Leads	<b>85811</b>	
<b>Civic IV Sedan (ED) 1.6 i 16V</b>	<b>1987-91</b>	
D16A7	96 130	
Ignition Leads	<b>85811</b>	
<b>Civic IV Sedan (ED) 1.6 i 16V 4x4</b>	<b>1989-91</b>	
D16A6	80 109	
Ignition Leads	<b>85811</b>	
<b>Civic Ix (FK) 1.4 i-VTEC</b>	<b>2012-&gt;</b>	
L13Z4	73 99	
Ignition Coil	<b>80290</b>	
<b>Civic V Coupe (EJ) 1.5 i LSi</b>	<b>1993-95</b>	
D15B7	74 101	
Ignition Coil	<b>80299</b>	
Ignition Leads With ignition distributor	<b>85821</b>	
<b>Civic V Coupe (EJ) 1.6 i</b>	<b>1994-95</b>	
D16Y7	77 105	
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85821</b>	
<b>Civic V Coupe (EJ) 1.6 i Vtec</b>	<b>1994-95</b>	
B16A2	118 160	
Ignition Coil	<b>80299</b>	
<b>Civic V Coupe (EJ) 1.6 i Vtec</b>	<b>1994-96</b>	
D16Y6/D16Z9	92 125	
Ignition Coil D16Z9,D16Y6	<b>80250</b>	
Ignition Coil	<b>80299</b>	
Ignition Leads	<b>85821</b>	



HONDA Cont.	
<b>Civic V Hatchback (EG) 1.3 16V</b>	<b>1991-95</b>
D13B2	55 75
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85811</b>
Ignition Leads With ignition distributor	<b>85821</b>
<b>Civic V Hatchback (EG) 1.5 i 16V</b>	<b>1991-95</b>
D15B2/D15Z2	66 90
Ignition Coil	<b>80299</b>
Ignition Leads D15Z2	<b>85821</b>
<b>Civic V Hatchback (EG) 1.5 i 16V</b>	<b>1991-95</b>
D15Z1 /D15B2	69 94
Ignition Coil	<b>80299</b>
Ignition Leads D15Z1	<b>85821</b>
<b>Civic V Hatchback (EG) 1.6 16V Vtec</b>	<b>1991-95</b>
D16Z6	92 125
Ignition Coil	<b>80299</b>
Ignition Leads ->09.1995	<b>85821</b>
<b>Civic V Hatchback (EG) 1.6 VTi 16V</b>	<b>1991-95</b>
B16A2	118 160
Ignition Coil	<b>80299</b>
<b>Civic V Sedan (EG, EH) 1.3</b>	<b>1992-92</b>
D13B2	55 75
Ignition Leads	<b>85811</b>
Ignition Leads	<b>85821</b>
<b>Civic V Sedan (EG, EH) 1.5 i 16V</b>	<b>1991-95</b>
D15Z1 /D15B2	69 94
Ignition Coil	<b>80299</b>
Ignition Leads D15B2	<b>85821</b>
<b>Civic V Sedan (EG, EH) 1.6 16V Vtec</b>	<b>1991-95</b>
D16Z6/D16Z7	92 125
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic V Sedan (EG, EH) 1.6 VTi</b>	<b>1991-95</b>
B16A2	118 160
Ignition Coil	<b>80299</b>
<b>Civic VI Aerodeck (MB, MC) 1.4 16V</b>	<b>1998-01</b>
D14A7	55 75
Ignition Leads	<b>85821</b>
<b>Civic VI Aerodeck (MB, MC) 1.4 16V</b>	<b>1998-01</b>
D14A8	66 90
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Aerodeck (MB, MC) 1.5 16V</b>	<b>1998-01</b>
D15Z8	84 114
Ignition Coil D15Z8	<b>80250</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Aerodeck (MB, MC) 1.6 16V</b>	<b>1998-01</b>
D16B2	85 116
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Aerodeck (MB, MC) 1.6 16V (MC1)</b>	<b>1998-01</b>
D16W4	92 125
Ignition Leads ->12.2000	<b>85821</b>
<b>Civic VI Aerodeck (MB, MC) 1.8 16V</b>	<b>1998-01</b>
B18C4	124 169
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85811</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Coupe (EJ, EM1) 1.6 i</b>	<b>1996-00</b>
D16Y7	77 105
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Coupe (EJ, EM1) 1.6 i Vtec</b>	<b>1996-00</b>
D16Y8	92 125
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Coupe (EJ, EM1) 1.6 i Vtec</b>	<b>1999-00</b>
B16A2	118 160
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85811</b>
<b>Civic VI Fastback (MA, MB) 1.4 i</b>	<b>1994-01</b>
D14A8/D14Z4/D14A6/D14A2	66 90
Ignition Coil D14A2; 01.1996->	<b>80250</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Fastback (MA, MB) 1.4 i</b>	<b>1995-01</b>
D14A5/D14A7/D14Z3	55 75
Ignition Coil D14A5; 01.1996->	<b>80250</b>
Ignition Leads	<b>85821</b>

HONDA Cont.	
<b>Civic VI Fastback (MA, MB) 1.5 16V</b>	<b>1997-01</b>
D15Z8	84 114
Ignition Coil D15Z8	<b>80250</b>
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Fastback (MA, MB) 1.5 i Vtec-E</b>	<b>1994-97</b>
D15Z3	66 90
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Fastback (MA, MB) 1.6 16V</b>	<b>1997-01</b>
D16B2	85 116
Ignition Coil	<b>80250</b>
Ignition Coil With ignition distributor	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Fastback (MA, MB) 1.6 i</b>	<b>1994-97</b>
D16Y3	83 113
Ignition Coil 01.1996->	<b>80250</b>
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85811</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Fastback (MA, MB) 1.6 i Vtec</b>	<b>1994-97</b>
D16Y2	93 126
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Fastback (MA, MB) 1.6 VTi</b>	<b>1997-01</b>
B16A2	118 160
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85811</b>
Ignition Leads D16B2	<b>85821</b>
<b>Civic VI Fastback (MA, MB) 1.8 16V</b>	<b>1997-01</b>
B18C4	124 169
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Hatchback (EJ, EK) 1.4 i</b>	<b>1995-01</b>
D14Z1/D14A3	55 75
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Hatchback (EJ, EK) 1.4 i S</b>	<b>1995-01</b>
D14A4/D14Z4/D14Z2	66 90
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Hatchback (EJ, EK) 1.5 i</b>	<b>1995-01</b>
D15Z6	84 114
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Hatchback (EJ, EK) 1.6 i</b>	<b>1995-01</b>
D16Y5	84 114
Ignition Coil D16Y5	<b>80250</b>
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Hatchback (EJ, EK) 1.6 VTi</b>	<b>1995-01</b>
B16A2	118 160
Ignition Coil	<b>80299</b>
Ignition Leads SAE/ DIN	<b>85811</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Sedan (EJ, EK) 1.4 i</b>	<b>1995-01</b>
D14A4/D14Z4/D14Z2	66 90
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Sedan (EJ, EK) 1.5 i</b>	<b>1995-01</b>
D15Z6	84 114
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Sedan (EJ, EK) 1.6 i Vtec</b>	<b>1995-01</b>
D16Y6/D16Y8	92 125
Ignition Coil	<b>80250</b>
Ignition Coil With ignition distributor	<b>80299</b>
Ignition Leads	<b>85821</b>
<b>Civic VI Sedan (EJ, EK) 1.6 VTi</b>	<b>1995-01</b>
B16A2	118 160
Ignition Coil	<b>80299</b>
Ignition Leads SAE/ DIN	<b>85811</b>
Ignition Leads	<b>85821</b>
<b>Civic VII Coupe (EM2) 1.6 i</b>	<b>2001-05</b>
D16V1	81 110
Ignition Coil	<b>80300</b>
<b>Civic VII Coupe (EM2) 1.7 i</b>	<b>2001-05</b>
D17A8	88 120
Ignition Coil	<b>80300</b>



HONDA Cont.		
<b>Civic VII Coupe (EM2) 1.7 i VTEC</b>		<b>2001-05</b>
D17A5/D17A9		92 125
Ignition Coil		<b>80300</b>
<b>Civic VII Hatchback (EU, EP, EV) 1.4 i</b>		<b>2001-05</b>
D14Z6		55 75
Ignition Coil		<b>80300</b>
Ignition Leads		<b>85821</b>
<b>Civic VII Hatchback (EU, EP, EV) 1.4 iS</b>		<b>2001-05</b>
D14Z5/D14Z6		66 90
Ignition Coil		<b>80300</b>
<b>Civic VII Hatchback (EU, EP, EV) 1.6 i</b>		<b>2001-05</b>
D16V1		81 110
Ignition Coil		<b>80300</b>
<b>Civic VII Hatchback (EU, EP, EV) 2.0 i Sport</b>		<b>2001-05</b>
K20A3		118 160
Ignition Coil		<b>80348</b>
<b>Civic VII Hatchback (EU, EP, EV) 2.0 Type-R</b>		<b>2001-05</b>
K20A2		147 200
Ignition Coil		<b>80348</b>
<b>Civic VII Sedan (ES) 1,4</b>		<b>2000-05</b>
D14Z5		66 90
Ignition Coil		<b>80300</b>
<b>Civic VII Sedan (ES) 1,7</b>		<b>2001-05</b>
D17A6		85 116
Ignition Coil		<b>80300</b>
<b>Civic VII Sedan (ES) 1.3 IMA</b>		<b>2003-05</b>
LDA1		61 83
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Civic VII Sedan (ES) 1.6</b>		<b>2001-05</b>
D16V1		81 110
Ignition Coil		<b>80300</b>
<b>Civic VII Sedan (ES) 1.8</b>		<b>2001-05</b>
R18A1		103 140
Ignition Coil		<b>80347</b>
<b>Civic VII Sedan (ES, ET) 1.2 i-DSI</b>		<b>2001-04</b>
L12A1		58 79
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Civic VII Sedan (ES, ET) 2.0 (ET1)</b>		<b>2003-05</b>
K20A3		118 160
Ignition Coil		<b>80348</b>
<b>Civic VIII Hatchback (FN, FK) 1.4</b>		<b>2005-&gt;</b>
L13A7		61 83
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Civic VIII Hatchback (FN, FK) 1.4</b>		<b>2008-&gt;</b>
L13Z1		73 100
Ignition Coil		<b>80290</b>
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Civic VIII Hatchback (FN, FK) 1.8</b>		<b>2005-&gt;</b>
R18A2		103 140
Ignition Coil		<b>80347</b>
<b>Civic VIII Hatchback (FN, FK) 2.0</b>		<b>2006-&gt;</b>
K20Z4		110 150
Ignition Coil		<b>80348</b>
<b>Civic VIII Hatchback (FN, FK) Type R</b>		<b>2006-&gt;</b>
K20Z4		148 201
Ignition Coil		<b>80348</b>
<b>Civic VIII Sedan (ES, ET) 1.6</b>		<b>2001-05</b>
R16A1		84 114
Ignition Coil		<b>80347</b>
<b>Civic VIII Sedan (FD, FA) 1.3 Hybrid</b>		<b>2006-&gt;</b>
LDA2		70 95
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Civic VIII Sedan (FD, FA) 1.6</b>		<b>2005-&gt;</b>
R16A1		84 114
Ignition Coil		<b>80347</b>
<b>Civic VIII Sedan (FD, FA) 1.8 (FD1)</b>		<b>2005-12</b>
R18A1		103 140
Ignition Coil		<b>80347</b>
<b>Civic VIII Sedan (FD, FA) 2.0</b>		<b>2006-12</b>
K20A3/K20Z2		114 155
Ignition Coil		<b>80348</b>

HONDA Cont.		
<b>Concerto (HW) 1.4</b>		<b>1989-91</b>
D14A8/D14A1		66 90
Ignition Leads		<b>85811</b>
Ignition Leads	->09.1991	<b>85821</b>
<b>Concerto (HW) 1.4</b>		<b>1989-92</b>
D14A1		61 83
Ignition Leads		<b>85811</b>
Ignition Leads	->09.1991	<b>85821</b>
<b>Concerto (HW) 1.5 i 16V</b>		<b>1989-95</b>
D15B2		66 90
Ignition Leads		<b>85821</b>
<b>Concerto (HW) 1.6 16V</b>		<b>1989-95</b>
D16Z2		78 106
Ignition Leads		<b>85811</b>
Ignition Leads		<b>85821</b>
<b>Concerto (HW) 1.6 i 16V</b>		<b>1989-95</b>
D16Z2		82 112
Ignition Leads		<b>85811</b>
Ignition Leads		<b>85821</b>
<b>Concerto (HW) 1.6 i 16V</b>		<b>1989-95</b>
D16A8		90 122
Ignition Leads	->07.1993	<b>85821</b>
<b>Concerto Sedan (HWW) 1.4</b>		<b>1989-91</b>
D14A8/D14A1		66 90
Ignition Leads		<b>85811</b>
Ignition Leads	->09.1991	<b>85821</b>
<b>Concerto Sedan (HWW) 1.4</b>		<b>1989-92</b>
D14A1		61 83
Ignition Leads		<b>85811</b>
Ignition Leads	->09.1991	<b>85821</b>
<b>Concerto Sedan (HWW) 1.5 i 16V</b>		<b>1989-95</b>
D15B2		66 90
Ignition Leads	->03.1995	<b>85821</b>
<b>Concerto Sedan (HWW) 1.6 16V</b>		<b>1989-95</b>
D16Z2		78 106
Ignition Leads		<b>85811</b>
Ignition Leads		<b>85821</b>
<b>Concerto Sedan (HWW) 1.6 i 16V</b>		<b>1989-95</b>
D16Z2		82 112
Ignition Leads		<b>85811</b>
Ignition Leads		<b>85821</b>
<b>CR-V I (RD) 2.0 16V</b>		<b>1999-02</b>
B20Z1		108 147
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85801</b>
<b>CR-V I (RD) 2.0 16V 4WD</b>		<b>1995-01</b>
B20B		94 128
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85801</b>
<b>CR-V II (RD) 2.0</b>		<b>2001-06</b>
K20A4		110 150
Ignition Coil		<b>80348</b>
Ignition Leads		<b>85801</b>
<b>CR-V III (RE) 2.0 i 4WD</b>		<b>2007-&gt;</b>
R20A2		110 150
Ignition Coil		<b>80348</b>
<b>CRX II (ED, EE) 1.6 i 16V</b>		<b>1987-92</b>
D16Z5		91 124
Ignition Leads		<b>85821</b>
<b>CRX II (ED, EE) 1.6 i 16V Vtec</b>		<b>1989-92</b>
B16A1		110 150
Ignition Leads		<b>85801</b>
<b>CRX III (EH, EG) 1.6 ESi</b>		<b>1992-98</b>
D16Y8/D16Z6		92 125
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85821</b>
<b>CRX III (EH, EG) 1.6 i VTi</b>		<b>1992-98</b>
B16A2		118 160
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85811</b>
Ignition Leads	B16A	<b>85821</b>
<b>CR-Z (ZF1) 1.5 Hybrid</b>		<b>2010-&gt;</b>
LEA1		84 114
Ignition Coil		<b>80290</b>
<b>CR-Z (ZF1) 1.5 Hybrid</b>		<b>2012-&gt;</b>
LEA1/LEA3		89 121
Ignition Coil		<b>80290</b>





HONDA Cont.		
<b>FR-V (BE) 1.7</b>		2004->
D17A2		92 125
Ignition Coil		<b>80300</b>
<b>FR-V (BE) 1.8</b>		2007->
R18A1		103 140
Ignition Coil		<b>80347</b>
<b>FR-V (BE) 2.0</b>		2005->
K20A9		110 150
Ignition Coil		<b>80348</b>
<b>HR-V (GH) 1.6 16V</b>		1999->
D16W1		77 105
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85821</b>
<b>HR-V (GH) 1.6 16V 4WD</b>		1999->
D16W1		77 105
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85821</b>
<b>HR-V (GH) 1.6 16V 4WD</b>		1999->
D16W5		91 124
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85821</b>
<b>Integra (DC5) 2.0</b>		2002->
K20A3		118 160
Ignition Coil		<b>80348</b>
<b>Integra Coupe (DC2, DC4) 1.8 Type-R</b>		1997-01
B18C6		140 190
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85801</b>
Ignition Leads		<b>85811</b>
<b>Jazz II (GD) 1.2</b>		2002-08
L12A1/L12A4		57 78
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Jazz II (GD) 1.3</b>		2002-08
L13A1		61 83
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Jazz II (GD, GE3, GE2) 1.3 i-DSI</b>		2002-07
L13A1		63 86
Ignition Coil		<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Jazz II (GD, GE3, GE2) 1.5</b>		2002-08
L15A		81 110
Ignition Coil		<b>80336</b>
<b>Jazz II (GD, GE3, GE2) 1.5 FF</b>		2002-07
L15A1		79 107
Ignition Coil		<b>80336</b>
<b>Jazz III (GE) 1.2</b>		2008->
L12B1		66 90
Ignition Coil		<b>80290</b>
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Jazz III (GE) 1.3 i</b>		2008->
L13Z1		73 100
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Jazz III (GE, GG, GP) 1.4</b>		2008->
L13Z1		74 101
Ignition Coil	Entry	<b>80297</b>
<b>Jazz Sedan 1.3</b>		2003-08
L13A1		63 86
Ignition Coil	Entry	<b>80297</b>
Ignition Coil	Departure	<b>80298</b>
<b>Legend I (HS, KA) 2.7 i 24V</b>		1988-90
C27A1		124 169
Ignition Leads		<b>85821</b>
<b>Legend I Coupe (KA3) 2.7 i 24V</b>		1987-90
C27A1		124 169
Ignition Leads		<b>85821</b>
<b>Logo (GA3) 1.3</b>		1999-02
D13B7		48 65
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85821</b>
<b>Prelude III (BA) 2.0</b>		1987-92
B20A4		84 114
Ignition Coil		<b>80299</b>
<b>Prelude III (BA) 2.0 EX</b>		1987-92
B20A3		80 109
Ignition Coil		<b>80299</b>

HONDA Cont.		
<b>Prelude III (BA) 2.0 i EX 16V</b>		1986-87
B20A1		101 137
Ignition Coil		<b>80299</b>
<b>Prelude III (BA) 2.0 i EX 16V</b>		1987-90
B20A7		110 150
Ignition Coil		<b>80299</b>
<b>Prelude III (BA) 2.0 i EX 16V</b>		1986-87
B20A1		101 137
Ignition Coil		<b>80299</b>
<b>Prelude III (BA) 2.0 i EX 16V</b>		1987-92
B20A9		103 140
Ignition Coil		<b>80299</b>
<b>Prelude III (BA) 2.0 i EX 16V KAT</b>		1987-92
B20A5		101 137
Ignition Coil		<b>80299</b>
<b>Prelude IV (BB) 2.0 i 16V</b>		1992-96
F20A4		98 133
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85811</b>
<b>Prelude IV (BB) 2.2 i 16V Vtec</b>		1993-96
H22A2		136 185
Ignition Coil		<b>80299</b>
<b>Prelude IV (BB) 2.3 i 16V</b>		1992-96
H23A2		118 160
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85811</b>
<b>Prelude V (BB) 2.0 16V</b>		1996-00
F20A4		98 133
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85811</b>
<b>Prelude V (BB) 2.2 16V</b>		1996-00
H22A5		147 200
Ignition Coil		<b>80299</b>
<b>Prelude V (BB) 2.2 16V</b>		1996-00
H22A2 /H22A5		136 185
Ignition Coil		<b>80299</b>
<b>S2000 (AP) 2.0</b>		1999->
F20C VTEC		177 240
Ignition Coil		<b>80348</b>
<b>S2000 (AP) 2.2 Vtec</b>		2003->
F22C1		176 239
Ignition Coil		<b>80348</b>
<b>Shuttle (RA) 2.2 16V</b>		1994-98
F22B8		110 150
Ignition Coil		<b>80299</b>
Ignition Leads		<b>85811</b>
<b>Shuttle (RA) 2.3 16V</b>		1997-04
F23A7		110 150
Ignition Coil	F23A7	<b>80250</b>
Ignition Coil	01.1998-05.2001	<b>80299</b>
<b>Stream (RN) 1.7 16V</b>		2001->
D17A2		92 125
Ignition Coil		<b>80300</b>
<b>Stream (RN) 2.0 16V</b>		2001->
K20A1		115 156
Ignition Coil		<b>80348</b>

HYUNDAI		
<b>Accent I (X-3) 1.3</b>		1994-00
G4EH		44 60
Ignition Coil	G4EH	<b>80253</b>
Ignition Leads	->07.1999	<b>85998</b>
<b>Accent I (X-3) 1.3</b>		1994-00
G4EH		55 75
Ignition Coil	G4EH	<b>80253</b>
Ignition Leads	->07.1999	<b>85998</b>
<b>Accent I (X-3) 1.3 i 12V</b>		1994-00
G4EH		62 84
Ignition Coil	G4EH	<b>80253</b>
Ignition Coil	->12.1999	<b>80271</b>
Ignition Leads	->07.1999	<b>85998</b>
<b>Accent I (X-3) 1.5 16V</b>		1994-00
G4FK		76 104
Ignition Leads	11.1995-07.1999	<b>85998</b>



HYUNDAI Cont.		
<b>Accent I (X-3) 1.5 i 12V</b>		<b>1994-00</b>
G4EK		65 88
Ignition Coil G4EK		<b>80253</b>
Ignition Coil ->12.1999		<b>80271</b>
Ignition Leads DOHC		<b>85394</b>
Ignition Leads ->07.1999		<b>85998</b>
<b>Accent I (X-3) 1.5 i 16V</b>		<b>1995-00</b>
G4ER		73 99
Ignition Coil		<b>80253</b>
Ignition Leads 12.1996->		<b>85394</b>
Ignition Leads ->07.1999		<b>85998</b>
<b>Accent II (LC) 1.3</b>		<b>2000-05</b>
G4EA		55 75
Ignition Leads ->07.2000		<b>85998</b>
<b>Accent II (LC) 1.3</b>		<b>2000-05</b>
G4EA		63 86
Ignition Leads		<b>85998</b>
<b>Accent II (LC) 1.3</b>		<b>2002-05</b>
G4EH		62 84
Ignition Leads		<b>85998</b>
<b>Accent II (LC) 1.5</b>		<b>2000-05</b>
G4EC-G		75 102
Ignition Leads		<b>85394</b>
<b>Accent II (LC) 1.5</b>		<b>2000-05</b>
G4EB		66 90
Ignition Coil		<b>80253</b>
Ignition Leads		<b>85998</b>
<b>Accent II (LC) 1.5</b>		<b>1999-02</b>
G4EK		65 88
Ignition Coil		<b>80334</b>
<b>Accent II (LC) 1.6</b>		<b>2002-05</b>
G4ED-G		77 105
Ignition Coil		<b>80334</b>
<b>Accent II Sedan (LC) 1.3</b>		<b>2000-05</b>
G4EA		55 75
Ignition Leads		<b>85998</b>
<b>Accent II Sedan (LC) 1.3</b>		<b>2000-05</b>
G4EA		63 86
Ignition Leads		<b>85998</b>
<b>Accent II Sedan (LC) 1.5</b>		<b>2000-05</b>
G4EB		66 90
Ignition Coil		<b>80253</b>
Ignition Leads		<b>85998</b>
<b>Accent II Sedan (LC) 1.6</b>		<b>2002-05</b>
G4ED-G		77 105
Ignition Coil		<b>80334</b>
<b>Accent III (MC) 1.4 GL</b>		<b>2005-10</b>
G4EE		71 97
Ignition Leads		<b>85394</b>
<b>Accent III (MC) 1.6 GLS</b>		<b>2005-10</b>
G4ED		82 112
Ignition Coil		<b>80334</b>
<b>Accent III Sedan (MC) 1.4 GL</b>		<b>2005-10</b>
G4EE		71 97
Ignition Coil		<b>80334</b>
Ignition Leads		<b>85394</b>
<b>Accent III Sedan (MC) 1.6 GLS</b>		<b>2005-10</b>
G4ED		82 112
Ignition Coil		<b>80334</b>
<b>Accent IV (RB) 1.4</b>		<b>2010-&gt;</b>
G4FA		79 107
Ignition Coil		<b>80332</b>
<b>Accent IV (RB) 1.6</b>		<b>2010-&gt;</b>
G4FC		91 124
Ignition Coil 01.2011->		<b>80332</b>
<b>Accent IV Sedan (RB) 1.4</b>		<b>2010-14</b>
G4FA		80 109
Ignition Coil 01.2011->		<b>80332</b>
<b>Accent IV Sedan (RB) 1.6</b>		<b>2010-&gt;</b>
G4FC		90 122
Ignition Coil		<b>80332</b>
<b>Accent IV Sedan (RB) 1.6</b>		<b>2010-&gt;</b>
G4FC		91 123
Ignition Coil		<b>80332</b>
<b>Accent Sedan (X-3) 1.3</b>		<b>1994-00</b>
G4EH		44 60
Ignition Coil G4EH		<b>80253</b>
Ignition Leads ->07.1999		<b>85998</b>

HYUNDAI Cont.		
<b>Accent Sedan (X-3) 1.3</b>		<b>1994-00</b>
G4EH		55 75
Ignition Coil G4EH		<b>80253</b>
Ignition Leads ->07.1999		<b>85998</b>
<b>Accent Sedan (X-3) 1.3 i 12V</b>		<b>1994-00</b>
G4EH		62 84
Ignition Coil G4EH		<b>80253</b>
Ignition Coil ->12.1999		<b>80271</b>
Ignition Leads ->07.1999		<b>85998</b>
<b>Accent Sedan (X-3) 1.5 i 12V</b>		<b>1994-00</b>
G4EK		65 88
Ignition Coil G4EK		<b>80253</b>
Ignition Coil ->09.1999		<b>80271</b>
Ignition Leads DOHC		<b>85394</b>
Ignition Leads ->07.1999		<b>85998</b>
<b>Accent Sedan (X-3) 1.5 i 16V</b>		<b>1995-00</b>
G4ER		73 99
Ignition Coil		<b>80253</b>
Ignition Leads 12.1996->		<b>85394</b>
Ignition Leads ->07.1999		<b>85998</b>
<b>Atos (MX) 1.0 i</b>		<b>2001-03</b>
G4HC-E		43 58
Ignition Coil G4HC-E		<b>80251</b>
Ignition Leads		<b>85997</b>
Ignition Leads 04.2003->		<b>85998</b>
<b>Atos (MX) 1.0 i</b>		<b>1998-14</b>
G4HC		40 54
Ignition Coil 09.2000-06.2001		<b>80245</b>
Ignition Coil 11.1998-02.2001		<b>80251</b>
Ignition Leads		<b>85997</b>
Ignition Leads 09.2000-06.2001		<b>85998</b>
<b>Atos (MX) 1.1</b>		<b>2004-&gt;</b>
G4HG		46 63
Ignition Coil ->05.2005		<b>80245</b>
<b>Atos (MX) 1.1</b>		<b>2003-05</b>
G4HD		43 58
Ignition Coil OE N° 2730102600		<b>80251</b>
<b>Atos Prime (MX) 1.0 i</b>		<b>1999-&gt;</b>
G4HC		40 54
Ignition Coil 09.1999-08.2000		<b>80245</b>
Ignition Coil ->02.2001		<b>80251</b>
Ignition Leads 09.1999-08.2000		<b>85997</b>
Ignition Leads 09.2000-06.2001		<b>85998</b>
<b>Atos Prime (MX) 1.0 i</b>		<b>2001-&gt;</b>
G4HC-E		43 58
Ignition Coil G4HC-E		<b>80251</b>
Ignition Leads 05.2003->		<b>85998</b>
<b>Atos Prime (MX) 1.1</b>		<b>2003-&gt;</b>
G4HD		43 59
Ignition Coil		<b>80251</b>
<b>Atos Prime (MX) 1.1</b>		<b>2005-&gt;</b>
G4HG		46 63
Ignition Coil ->12.2006		<b>80251</b>
Ignition Leads		<b>85998</b>
<b>Coupe (GK) 1.6 16V</b>		<b>2002-09</b>
G4ED-G		77 105
Ignition Leads		<b>85394</b>
<b>Coupe (GK) 1.6 16V</b>		<b>2002-09</b>
G4ED-G		79 107
Ignition Leads		<b>85394</b>
<b>Coupe (GK) 2.7 V6</b>		<b>2002-09</b>
G6BA-G		123 167
Ignition Leads		<b>85396</b>
<b>Coupe (RD) 1.6 16V</b>		<b>1998-02</b>
G4GR		85 116
Ignition Leads		<b>85391</b>
Ignition Leads 05.2000->		<b>85394</b>
<b>Coupe (RD) 1.6 i 16V</b>		<b>1996-02</b>
G4GR		84 114
Ignition Leads		<b>85391</b>
<b>Coupe (RD) 2.0</b>		<b>1999-02</b>
G4DF		101 137
Ignition Leads		<b>85391</b>
<b>Coupe (RD) 2.0 16V</b>		<b>2001-02</b>
G4DF		99 135
Ignition Leads		<b>85391</b>
<b>Coupe (RD) 2.0 16V</b>		<b>1996-02</b>
G4GF		102 139
Ignition Leads		<b>85391</b>



HYUNDAI Cont.	
<b>Elantra (XD) 1.6</b>	<b>2000-06</b>
G4ED-G	79 107
Ignition Leads	<b>85394</b>
<b>Elantra Sedan (HD) 1.6 CVT</b>	<b>2006-11</b>
G4FC	90 122
Ignition Coil	<b>80331</b>
<b>Elantra Sedan (MD, UD) 1.6</b>	<b>2011-&gt;</b>
G4FG	94 128
Ignition Coil	<b>80332</b>
<b>Elantra Sedan (MD, UD) 1.8</b>	<b>2010-&gt;</b>
G4NB-B	110 150
Ignition Coil	<b>80342</b>
<b>Elantra Sedan (XD) 1.6</b>	<b>2000-06</b>
G4ED-G	79 107
Ignition Leads	<b>85394</b>
<b>Elantra Sedan (XD) 1.6</b>	<b>2003-06</b>
G4ED-G	77 105
Ignition Leads	<b>85394</b>
<b>Elantra Sedan (XD) 1.6</b>	<b>2000-06</b>
G4GR	66 90
Ignition Leads	<b>85394</b>
<b>Equus / Centennial 4.6 V8</b>	<b>2009-&gt;</b>
G8BA	269 366
Ignition Coil	<b>80341</b>
<b>Equus / Centennial 4.6 V8</b>	<b>2009-&gt;</b>
G8BA	274 373
Ignition Coil	<b>80341</b>
<b>Equus / Centennial 5.0 GDI</b>	<b>2009-&gt;</b>
G8BE	316 430
Ignition Coil	<b>80341</b>
<b>Galloper II (JK-01) 3.0 V6</b>	<b>1998-03</b>
G6AT	104 141
Ignition Coil	<b>80315</b>
<b>Genesis Coupe 2.0 T</b>	<b>2012-14</b>
G4KF	204 277
Ignition Coil	<b>80341</b>
<b>Genesis Coupe 2.0 T</b>	<b>2011-14</b>
G4KF	202 275
Ignition Coil	<b>80341</b>
<b>Genesis Coupe 2.0 T</b>	<b>2008-12</b>
G4KF	157 214
Ignition Coil	<b>80341</b>
<b>Getz (TB) 1.1</b>	<b>2002-05</b>
G4HD	46 63
Ignition Leads	<b>85998</b>
<b>Getz (TB) 1.1</b>	<b>2005-09</b>
G4HG/G4HD	49 67
Ignition Coil	<b>80253</b>
<b>Getz (TB) 1.3</b>	<b>2003-05</b>
G4EA	63 85
Ignition Leads	<b>85998</b>
<b>Getz (TB) 1.3 i</b>	<b>2002-04</b>
G4EA	60 82
Ignition Leads	<b>85998</b>
<b>Getz (TB) 1.4 i</b>	<b>2005-10</b>
G4EE	71 97
Ignition Leads	<b>85394</b>
<b>Getz (TB) 1.6</b>	<b>2002-05</b>
G4ED-G	77 106
Ignition Leads	<b>85394</b>
<b>H-1 / Starex 2.4 4WD</b>	<b>2001-04</b>
G4JS	99 135
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>H-1 Cargo (TQ) 2.4</b>	<b>2010-&gt;</b>
G4KC	128 174
Ignition Coil	<b>80341</b>
<b>H-1 Van 2.4</b>	<b>2000-04</b>
G4CS	82 112
Ignition Leads	<b>85398</b>
<b>H100 Bus (P) 2.4</b>	<b>1993-00</b>
G4CS	90 122
Ignition Leads ->12.1997	<b>85390</b>
Ignition Leads	<b>85398</b>
<b>H100 Bus (P) 2.4</b>	<b>1997-00</b>
G4CS	84 114
Ignition Leads ->12.1997	<b>85390</b>
Ignition Leads	<b>85398</b>

HYUNDAI Cont.	
<b>H100 Van 2.4</b>	<b>1997-04</b>
G4CS	82 111
Ignition Leads	<b>85398</b>
<b>I10 (BA, IA) 1.0</b>	<b>2013-&gt;</b>
G3LA	49 67
Ignition Coil	<b>80333</b>
<b>i10 (BA, IA) 1.0 LPG</b>	<b>2014-&gt;</b>
B3LA	49 67
Ignition Coil	<b>80333</b>
<b>i10 (BA, IA) 1.2</b>	<b>2013-&gt;</b>
G4LA	64 87
Ignition Leads	<b>85397</b>
<b>I10 (PA) 1.0</b>	<b>2011-13</b>
G3LA	51 69
Ignition Coil ->09.2013	<b>80333</b>
<b>I10 (PA) 1.2</b>	<b>2008-11</b>
G4LA	57 78
Ignition Leads	<b>85397</b>
<b>I10 (PA) 1.2</b>	<b>2011-13</b>
G4LA	63 86
Ignition Leads	<b>85397</b>
<b>i20 (GB) 1.2</b>	<b>2014-&gt;</b>
G4LA	55 75
Ignition Coil With Start&Stop system	<b>80314</b>
Ignition Leads	<b>85397</b>
<b>i20 (GB) 1.2</b>	<b>2014-&gt;</b>
G4LA	62 84
Ignition Coil With Start&Stop system	<b>80314</b>
Ignition Leads	<b>85397</b>
<b>i20 (GB) 1.2 LPGI</b>	<b>2014-&gt;</b>
G4LA	61 83
Ignition Coil With Start&Stop system	<b>80314</b>
<b>I20 (PB, PBT) 1.2</b>	<b>2008-12</b>
G4LA	57 78
Ignition Leads	<b>85397</b>
<b>I20 (PB, PBT) 1.2</b>	<b>2012-15</b>
G4LA	63 86
Ignition Coil With Start&Stop system	<b>80314</b>
<b>I20 (PB, PBT) 1.4</b>	<b>2008-15</b>
G4FA	74 101
Ignition Coil	<b>80332</b>
<b>I20 (PB, PBT) 1.6</b>	<b>2008-12</b>
G4FC	93 126
Ignition Coil 01.2009-03.2012	<b>80332</b>
<b>i20 Coupe (GB) 1.2</b>	<b>2015-&gt;</b>
G4LA	62 84
Ignition Coil With Start&Stop system	<b>80314</b>
<b>I30 (FD) 1.4</b>	<b>2007-11</b>
G4FA	80 109
Ignition Coil ->11.2008	<b>80331</b>
Ignition Coil 11.2008->	<b>80332</b>
<b>I30 (FD) 1.4</b>	<b>2007-11</b>
G4FA	77 105
Ignition Coil ->10.2008	<b>80331</b>
Ignition Coil 11.2008->	<b>80332</b>
<b>I30 (FD) 1.6</b>	<b>2007-11</b>
G4FC	90 122
Ignition Coil ->10.2008	<b>80331</b>
Ignition Coil 11.2008->	<b>80332</b>
<b>I30 (FD) 1.6</b>	<b>2007-11</b>
G4FC	85 116
Ignition Coil ->10.2008	<b>80331</b>
Ignition Coil 11.2008->	<b>80332</b>
<b>I30 (FD) 1.6</b>	<b>2008-11</b>
G4FC	93 126
Ignition Coil ->10.2008	<b>80331</b>
Ignition Coil 11.2008->	<b>80332</b>
<b>I30 (GD) 1.4</b>	<b>2011-15</b>
G4FA	73 99
Ignition Coil	<b>80332</b>
<b>I30 (GD) 1.6</b>	<b>2012-16</b>
G4FC	88 120
Ignition Coil	<b>80332</b>
<b>I30 (GD) 1.6 16V Flex</b>	<b>2011-16</b>
G4FC	94 128
Ignition Coil ->01.2014	<b>80332</b>
<b>I30 (GD) 1.6 GDI</b>	<b>2011-16</b>
G4FD	99 135
Ignition Coil	<b>80335</b>



HYUNDAI Cont.	
<b>I30 (GD) 1.6 GDI</b>	<b>2011-15</b>
G4FG	95 129
Ignition Coil	<b>80335</b>
<b>I30 (GD) 1.8</b>	<b>2012-&gt;</b>
G4NB/G4NB-B	110 150
Ignition Coil	<b>80342</b>
<b>i30 Coupe 1.4</b>	<b>2013-&gt;</b>
G4FA	73 99
Ignition Coil	<b>80332</b>
<b>I30 Coupe 1.6 GDI</b>	<b>2013-&gt;</b>
G4FD	99 135
Ignition Coil	<b>80335</b>
<b>I30 Cw (FD) 1.4</b>	<b>2007-12</b>
G4FA	77 105
Ignition Coil 08.2009->	<b>80332</b>
<b>I30 Cw (FD) 1.4</b>	<b>2009-12</b>
G4FA	80 109
Ignition Coil	<b>80332</b>
<b>I30 Cw (FD) 1.6</b>	<b>2008-12</b>
G4FC	90 122
Ignition Coil 03.2008-10.2008	<b>80331</b>
Ignition Coil 11.2008->	<b>80332</b>
<b>I30 Cw (FD) 1.6</b>	<b>2008-12</b>
G4FC	85 116
Ignition Coil 03.2008-10.2008	<b>80331</b>
Ignition Coil 11.2008->	<b>80332</b>
<b>I30 Cw (FD) 1.6</b>	<b>2008-12</b>
G4FC	93 126
Ignition Coil 03.2008-10.2008	<b>80331</b>
Ignition Coil 11.2008->	<b>80332</b>
<b>I30 Cw (GD) 1.4</b>	<b>2015-&gt;</b>
G4LC	74 101
Ignition Coil G4FA	<b>80332</b>
<b>I30 Cw (GD) 1.4</b>	<b>2012-15</b>
G4FA	73 99
Ignition Coil	<b>80332</b>
<b>I30 Cw (GD) 1.6</b>	<b>2012-&gt;</b>
G4FG	88 120
Ignition Coil	<b>80332</b>
<b>I30 CW (GD) 1.6</b>	<b>2012-15</b>
G4FG	95 129
Ignition Coil	<b>80332</b>
<b>I30 Cw (GD) 1.6 GDI</b>	<b>2012-&gt;</b>
G4FD	99 135
Ignition Coil	<b>80335</b>
<b>I40 (VF) 1.6 GDI</b>	<b>2012-&gt;</b>
G4FD	99 135
Ignition Coil	<b>80335</b>
<b>I40 (VF) 2.0 GDI</b>	<b>2012-&gt;</b>
G4NC	131 178
Ignition Coil	<b>80342</b>
<b>I40 Cw (VF) 1.6 GDI</b>	<b>2011-&gt;</b>
G4FD	99 135
Ignition Coil	<b>80335</b>
<b>I40 Cw (VF) 2.0 GDI</b>	<b>2011-&gt;</b>
G4NC	130 177
Ignition Coil	<b>80342</b>
<b>ix20 (JC) 1.4</b>	<b>2010-&gt;</b>
G4FA	66 90
Ignition Coil	<b>80332</b>
<b>ix20 (JC) 1.6</b>	<b>2010-&gt;</b>
G4FC	92 125
Ignition Coil	<b>80332</b>
<b>ix35 (LM, EL, ELH) 1.6</b>	<b>2010-&gt;</b>
G4FD	99 135
Ignition Coil	<b>80335</b>
<b>ix35 (LM, EL, ELH) 2.0</b>	<b>2010-&gt;</b>
G4KD	120 163
Ignition Coil	<b>80341</b>
<b>ix35 (LM, EL, ELH) 2.0</b>	<b>2010-&gt;</b>
G4KD	122 166
Ignition Coil	<b>80341</b>
<b>ix35 (LM, EL, ELH) 2.0 4WD</b>	<b>2010-&gt;</b>
G4KD	120 163
Ignition Coil	<b>80341</b>
<b>Lantra I (J-1) 1.5 i.e.</b>	<b>1990-95</b>
G15B/G4DJ	63 86
Ignition Leads	<b>85390</b>

HYUNDAI Cont.	
<b>Lantra I (J-1) 1.6 i.e. 16V</b>	<b>1990-95</b>
G4CR	78 106
Ignition Leads	<b>85999</b>
<b>Lantra I (J-1) 1.6 i.e. 16V</b>	<b>1990-95</b>
G4CR	84 114
Ignition Leads G4CR	<b>85999</b>
<b>Lantra I (J-1) 1.8 i.e. 16V</b>	<b>1990-95</b>
G4CN	93 127
Ignition Leads G4CN	<b>85999</b>
<b>Lantra II (J-2) 1.5 12V</b>	<b>1996-00</b>
G4EK	65 88
Ignition Coil	<b>80253</b>
Ignition Coil ->07.2000	<b>80271</b>
Ignition Leads	<b>85390</b>
Ignition Leads	<b>85998</b>
<b>Lantra II (J-2) 1.6 16V</b>	<b>1995-00</b>
G4GR	84 114
Ignition Leads	<b>85391</b>
<b>Lantra II (J-2) 1.6 i</b>	<b>1995-00</b>
G4GR	66 90
Ignition Leads	<b>85391</b>
Ignition Leads	<b>85999</b>
<b>Lantra II (J-2) 1.8 16V</b>	<b>1995-00</b>
G4GM	94 128
Ignition Leads	<b>85391</b>
Ignition Leads G4GM	<b>85999</b>
<b>Lantra II (J-2) 2.0 16V</b>	<b>1996-00</b>
G4GF	102 139
Ignition Leads	<b>85391</b>
<b>Lantra II Wagon (J-2) 1.5 12V</b>	<b>1997-00</b>
G4EK	65 88
Ignition Coil	<b>80253</b>
Ignition Coil ->07.2000	<b>80271</b>
Ignition Leads	<b>85390</b>
Ignition Leads ->09.2000	<b>85998</b>
<b>Lantra II Wagon (J-2) 1.6 16V</b>	<b>1996-00</b>
G4GR	84 114
Ignition Leads	<b>85391</b>
<b>Lantra II Wagon (J-2) 1.6 i</b>	<b>1996-00</b>
G4GR	66 90
Ignition Leads	<b>85391</b>
Ignition Leads	<b>85999</b>
<b>Lantra II Wagon (J-2) 1.8 16V</b>	<b>1996-00</b>
G4GM	94 128
Ignition Leads	<b>85391</b>
Ignition Leads G4GM	<b>85999</b>
<b>Lantra II Wagon (J-2) 2.0 16V</b>	<b>1996-00</b>
G4GF	102 139
Ignition Leads	<b>85391</b>
<b>Matrix (FC) 1.6</b>	<b>2001-10</b>
G4ED-G	76 103
Ignition Leads	<b>85394</b>
<b>Pony (X-2) 1.3</b>	<b>1989-95</b>
G4DG	43 58
Ignition Leads	<b>86030</b>
<b>Pony (X-2) 1.5</b>	<b>1989-95</b>
G15B/G4DJ	53 72
Ignition Leads	<b>85390</b>
<b>Pony (X-2) 1.5 i</b>	<b>1989-95</b>
G15B/G4DJ	61 83
Ignition Leads	<b>85390</b>
<b>Pony (X-2) 1.5 i</b>	<b>1989-95</b>
G15B/G4DJ	62 84
Ignition Leads	<b>85390</b>
<b>S COUPE (SLC) 1.5 i</b>	<b>1990-96</b>
G15B/G4DJ	62 84
Ignition Leads	<b>85390</b>
<b>S COUPE (SLC) 1.5 i</b>	<b>1992-96</b>
G4EK	65 88
Ignition Leads	<b>85390</b>
<b>S COUPE (SLC) 1.5 i Turbo</b>	<b>1991-96</b>
G4EK-TC	85 116
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85997</b>
<b>Santa Fé I (SM) 2.0</b>	<b>2001-06</b>
G4BP	99 135
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>



HYUNDAI Cont.	
<b>Santa Fé I (SM) 2.4 16V</b>	<b>2001-06</b>
G4JS-G	100 136
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>Santa Fé I (SM) 2.4 16V</b>	<b>2001-06</b>
G4JS-G	107 146
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>Santa Fé I (SM) 2.4 16V 4x4</b>	<b>2001-06</b>
G4JS-G	100 136
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>Santa Fé I (SM) 2.4 16V 4x4</b>	<b>2001-06</b>
G4JS-G	107 146
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>Santa Fé I (SM) 2.7 V6 4x4</b>	<b>2001-06</b>
G6BA-G	127 173
Ignition Leads	<b>85396</b>
<b>Santa Fé II (CM) 2.4</b>	<b>2010-12</b>
G4KE	128 174
Ignition Coil	<b>80341</b>
<b>Santa Fé II (CM) 2.4 4x4</b>	<b>2010-12</b>
G4KE	128 174
Ignition Coil	<b>80341</b>
<b>Santa Fé II (CM) 2.7</b>	<b>2006-12</b>
G6BA	125 170
Ignition Coil 11.2006->	<b>80363</b>
<b>Santa Fé II (CM) 2.7 4x4</b>	<b>2006-12</b>
G6BA	125 170
Ignition Coil 11.2006->	<b>80363</b>
<b>Santa Fé II (CM) 2.7 V6 GLS</b>	<b>2006-09</b>
G6EA	139 189
Ignition Coil 11.2006->; left	<b>80363</b>
<b>Santa Fé II (CM) 2.7 V6 GLS 4x4</b>	<b>2006-09</b>
G6EA	139 189
Ignition Coil 11.2006->	<b>80363</b>
<b>Santa Fé III (DM) 2.4</b>	<b>2012-15</b>
G4KJ	141 192
Ignition Coil	<b>80341</b>
<b>Santa Fé III (DM) 2.4 4WD</b>	<b>2012-15</b>
G4KJ	141 192
Ignition Coil	<b>80341</b>
<b>Santamo 2.0 16V</b>	<b>1999-02</b>
G4JP	102 139
Ignition Leads	<b>85999</b>
<b>Santamo 2.0 16V 4x4</b>	<b>1999-02</b>
G4CP-D	102 139
Ignition Leads	<b>85999</b>
<b>Sonata II (Y-2) 2.0 i</b>	<b>1991-93</b>
G4CP-U	80 109
Ignition Leads	<b>86030</b>
<b>Sonata II (Y-2) 2.0 i 16V</b>	<b>1991-93</b>
G4CP-D	96 130
Ignition Leads G4CP.D	<b>85999</b>
<b>Sonata III (Y-3) 1.8 i</b>	<b>1993-98</b>
G4CM	72 98
Ignition Leads	<b>85999</b>
<b>Sonata III (Y-3) 2.0 i</b>	<b>1996-98</b>
	70 95
Ignition Leads G4CP<New Sirius>	<b>85999</b>
<b>Sonata III (Y-3) 2.0 i 16V</b>	<b>1993-98</b>
G4CP-D	102 139
Ignition Leads G4CP.D	<b>85999</b>
<b>Sonata III (Y-3) 2.0 i 16V</b>	<b>1996-98</b>
G4CP-DM	92 125
Ignition Leads G4CP.DM	<b>85999</b>
<b>Sonata IV (EF) 2.0 16V</b>	<b>2001-04</b>
G4JP-EG	96 131
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>Sonata IV (EF) 2.0 16V</b>	<b>1998-01</b>
G4JP-G	100 136
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>Sonata IV (EF) 2.4 16V</b>	<b>1998-01</b>
G4BS	105 143
Ignition Coil ->03.2001	<b>80316</b>
Ignition Leads	<b>85393</b>

HYUNDAI Cont.	
<b>Sonata IV (EF) 2.5 V6 24V</b>	<b>1998-01</b>
G6BV-G	118 160
Ignition Leads	<b>85396</b>
<b>Sonata IV (EF) 2.7 V6</b>	<b>2001-04</b>
G6BA-G	127 173
Ignition Leads	<b>85396</b>
<b>Sonata V (NF) 2.0 VVTi GLS</b>	<b>2005-10</b>
G4KA	106 144
Ignition Coil 01.2008->	<b>80341</b>
<b>Sonata V (NF) 2.0 VVTi GLS</b>	<b>2008-10</b>
G4KD	121 165
Ignition Coil	<b>80341</b>
<b>Sonata V (NF) 2.4</b>	<b>2005-10</b>
G4KC	119 162
Ignition Coil 12.2007->	<b>80341</b>
<b>Sonata V (NF) 2.4</b>	<b>2008-10</b>
G4KE	127 173
Ignition Coil	<b>80341</b>
<b>Sonata VI (YF) 2.0</b>	<b>2009-14</b>
G4KD	110 150
Ignition Coil	<b>80341</b>
<b>Sonata VI (YF) 2.0 i</b>	<b>2011-14</b>
G4KD	121 165
Ignition Coil 10.2012->	<b>80342</b>
<b>Sonata VI (YF) 2.4</b>	<b>2009-10</b>
G4KC	128 174
Ignition Coil	<b>80341</b>
<b>Sonata VI (YF) 2.4</b>	<b>2009-&gt;</b>
G4KC	131 178
Ignition Coil	<b>80341</b>
<b>Trajet (FO) 2.0</b>	<b>2000-08</b>
G4JP-G	100 136
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>Trajet (FO) 2.0</b>	<b>2004-08</b>
G4GC-G	103 140
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>Trajet (FO) 2.7 V6</b>	<b>2000-08</b>
G6BA-G	127 173
Ignition Leads	<b>85396</b>
<b>Tucson (JM) 2.0 4WD</b>	<b>2004-10</b>
G4GC	104 141
Ignition Coil	<b>80316</b>
<b>Tucson (TLE) 1.6 Gdi</b>	<b>2015-&gt;</b>
G4FD	97 132
Ignition Coil	<b>80335</b>
<b>Veloster (FS) 1.6</b>	<b>2011-&gt;</b>
G4FC	95 129
Ignition Coil G4FG	<b>80332</b>
<b>Veloster (FS) 1.6 GDI</b>	<b>2011-&gt;</b>
G4FD	103 140
Ignition Coil	<b>80335</b>
<b>Veloster (FS) 1.6 MPI</b>	<b>2011-&gt;</b>
G4FG	97 132
Ignition Coil 06.2011->	<b>80332</b>
INFINITI	
<b>EX 35</b>	<b>2008-&gt;</b>
VQ35HR	221 301
Ignition Coil	<b>80372</b>
<b>FX 50 AWD</b>	<b>2008-&gt;</b>
VK50VE	287 390
Ignition Coil ->11.2010	<b>80375</b>
<b>FX 50 AWD</b>	<b>2013-&gt;</b>
VK50VE	309 420
Ignition Coil ->12.2014	<b>80375</b>
<b>G Sedan 25</b>	<b>2011-&gt;</b>
VQ25HR	163 222
Ignition Coil	<b>80372</b>
<b>G20 2.0</b>	<b>1990-97</b>
SR20DE	85 115
Ignition Coil	<b>80286</b>
<b>M (Y51) 35h</b>	<b>2011-&gt;</b>
VQ35HR	225 306
Ignition Coil	<b>80372</b>





<b>INFINITI Cont.</b>			
<b>M (Y51) 56</b>		2010->	
		300 408	
Ignition Coil	07.2010-06.2014		<b>80375</b>
<b>M (Y51) 56 X</b>		2010->	
		300 408	
Ignition Coil	07.2010-06.2014		<b>80375</b>
<b>M30 Convertible 3.0</b>		1990-93	
VG30E		121 164	
Ignition Coil			<b>80286</b>
<b>M30 Coupe 3.0</b>		1989-93	
VG30E		121 164	
Ignition Coil			<b>80286</b>
<b>M35 3.5 h</b>		2010->	
VQ35HR		268 364	
Ignition Coil			<b>80372</b>
<b>Q50 50 Hybrid</b>		2013->	
VQ35HR		268 364	
Ignition Coil			<b>80372</b>
<b>Q50 50 Hybrid AWD</b>		2013->	
VQ35HR		268 364	
Ignition Coil			<b>80372</b>
<b>Qx70 50 AWD</b>		2013->	
VK50VE		287 390	
Ignition Coil	11.2013->		<b>80375</b>

<b>INNOCENTI</b>			
<b>Elba (146) 1,3</b>		1991-96	
146 A5.000		49 67	
Ignition Leads			<b>83140</b>
<b>Elba (146) 1.4 i.e.</b>		1994-96	
146 C5.000/146 D5.000		49 67	
Ignition Coil			<b>80207</b>
Ignition Coil			<b>80279</b>
<b>Elba (146) 1.6 i.e.</b>		1994-96	
146 D6.000/146 C6.000		55 75	
Ignition Coil			<b>80207</b>
Ignition Coil			<b>80279</b>

<b>ISUZU</b>			
<b>Trooper Soft Top (UBS) 2,3</b>		1985-91	
4ZD1		66 90	
Ignition Coil			<b>80319</b>
<b>Trooper Soft Top (UBS) 2.6 i</b>		1987-91	
4ZE1		85 116	
Ignition Leads			<b>86030</b>

<b>JAGUAR</b>			
<b>S-Type (CCX) 4.0 V8</b>		1999-02	
AJ-V8		203 276	
Ignition Coil	Ch.M45255->		<b>80360</b>
Ignition Coil	Ch.M45255->		<b>80361</b>
<b>S-Type (CCX) 4.2 V8</b>		2002-07	
AJ8FT		219 298	
Ignition Coil	Ch.M45255->		<b>80361</b>
<b>S-Type (CCX) R 4,2 V8</b>		2002-07	
AJ8FT		291 396	
Ignition Coil	Ch.M45255->		<b>80361</b>
<b>XE (JA_) 2.0</b>		2015->	
204PT		147 200	
Ignition Coil	X760		<b>80255</b>
<b>XE (JA_) 2.0</b>		2015->	
204PT		177 241	
Ignition Coil	X760		<b>80255</b>
<b>XF (CC9) 3.0 AWD</b>		2012-15	
AJ 126		250 340	
Ignition Coil			<b>80361</b>
<b>XF (J05, CC9) 2.0</b>		2012-15	
204PT		177 241	
Ignition Coil			<b>80255</b>
<b>XF (J05, CC9) 3.0</b>		2012-15	
AJ 126		250 340	
Ignition Coil			<b>80361</b>
<b>XF (J05, CC9) 4.2</b>		2008-15	
SV82G		219 298	
Ignition Coil			<b>80361</b>

<b>JAGUAR Cont.</b>			
<b>XF (J05, CC9) 4.2 Kompressor</b>		2008-15	
SV8TS		306 416	
Ignition Coil			<b>80361</b>
<b>XJ (X35, J12, J24) 2.0</b>		2012->	
204PT		177 241	
Ignition Coil			<b>80255</b>
<b>XJ (X35, J12, J24) 3.0</b>		2012->	
AJ 126		250 340	
Ignition Coil			<b>80361</b>
<b>XJ (X350, X358) 3.5</b>		2003-09	
RG (AJ-V8)		190 258	
Ignition Coil			<b>80361</b>
<b>XJ (X350, X358) 4.2</b>		2003-09	
AJ8FT		219 298	
Ignition Coil			<b>80361</b>
<b>XJ (X350, X358) R 4.2</b>		2003-09	
AJ8FT		291 395	
Ignition Coil			<b>80361</b>
<b>XK 8 Convertible (QDV) 4.2</b>		2002-05	
AJ8FT		219 298	
Ignition Coil			<b>80361</b>
<b>XK 8 Convertible (QDV) R 4,2</b>		2002-05	
AJ8FT		291 396	
Ignition Coil			<b>80361</b>
<b>XK 8 Coupe (QEV) 4.2</b>		2002-05	
AJ8FT		219 298	
Ignition Coil			<b>80361</b>
<b>XK 8 Coupe (QEV) R 4,2</b>		2002-05	
AJ8FT		291 396	
Ignition Coil			<b>80361</b>
<b>XK Cabriolet (J43) 3.6</b>		2007-14	
RG (AJ-V8)		190 258	
Ignition Coil			<b>80361</b>
<b>XK Cabriolet (J43) 4.2 XK8</b>		2006-14	
AJ8FT		219 298	
Ignition Coil			<b>80361</b>
<b>XK Cabriolet (J43) 4.2 XKR</b>		2006-14	
SV8TS		306 416	
Ignition Coil			<b>80361</b>
<b>XK Coupe (J43) 3.5</b>		2007-14	
RG (AJ-V8)		190 258	
Ignition Coil			<b>80361</b>
<b>XK Coupe (J43) 4.2 XK8</b>		2006-14	
AJ8FT		219 298	
Ignition Coil			<b>80361</b>
<b>XK Coupe (J43) 4.2 XKR</b>		2006-14	
AJ8FT		291 396	
Ignition Coil			<b>80361</b>
<b>XK Coupe (J43) 4.2 XKR</b>		2006-14	
SV8TS		306 416	
Ignition Coil			<b>80361</b>

<b>JEEP</b>			
<b>Cherokee (KJ) 2.4 4x4</b>		2001-08	
ED1		108 147	
Ignition Coil			<b>80295</b>
Ignition Coil	01.2004->		<b>80296</b>
<b>Cherokee (KJ) 2.4 Laredo</b>		2001-04	
ED1		108 147	
Ignition Coil	01.2004->		<b>80296</b>
<b>Cherokee (KJ) 3.7 4x4</b>		2001-08	
EKG		155 211	
Ignition Coil			<b>80345</b>
<b>Cherokee (KJ) 3.7 4x4</b>		2003-08	
EKG		150 204	
Ignition Coil			<b>80345</b>
<b>Cherokee (KJ) 3.7 Laredo</b>		2001-04	
EKG		150 204	
Ignition Coil			<b>80345</b>
<b>Cherokee (KK) 3.7 V6 4x4</b>		2008->	
EKG		151 205	
Ignition Coil			<b>80345</b>
<b>Cherokee (XJ) 2.5</b>		1990-96	
EPE		89 121	
Ignition Coil			<b>80362</b>
Ignition Leads			<b>86011</b>



JEEP Cont.	
<b>Cherokee (XJ) 2.5</b>	<b>1986-90</b>
EPE	90 122
Ignition Coil	<b>80362</b>
<b>Cherokee (XJ) 2.5</b>	<b>1995-01</b>
EPE	89 121
Ignition Coil ->12.1997	<b>80362</b>
Ignition Leads	<b>86011</b>
<b>Cherokee (XJ) 2.5 4x4</b>	<b>1986-90</b>
EPE	90 122
Ignition Coil	<b>80362</b>
<b>Cherokee (XJ) 2.5 i 4x4</b>	<b>1991-01</b>
EPE/HX	90 122
Ignition Coil ->12.1997	<b>80362</b>
Ignition Leads	<b>86011</b>
<b>Cherokee (XJ) 2.5 i 4x4</b>	<b>1984-01</b>
EPE	87 118
Ignition Coil ->12.1997	<b>80362</b>
<b>Cherokee (XJ) 2.5 SE</b>	<b>1996-99</b>
EPE	87 118
Ignition Coil ->12.1997	<b>80362</b>
<b>Cherokee (XJ) 4.0 i</b>	<b>1998-01</b>
ERH	127 173
Ignition Coil ->07.1998	<b>80362</b>
Ignition Leads	<b>86010</b>
<b>Cherokee (XJ) 4.0 i</b>	<b>1991-01</b>
MX	135 184
Ignition Coil	<b>80362</b>
Ignition Leads	<b>86010</b>
<b>Cherokee (XJ) 4.0 i</b>	<b>1988-01</b>
ERH	136 185
Ignition Coil	<b>80264</b>
Ignition Coil	<b>80362</b>
Ignition Leads	<b>86010</b>
<b>Cherokee (XJ) 4.0 i 4x4</b>	<b>1995-01</b>
ERH	131 178
Ignition Coil ->09.1998	<b>80362</b>
Ignition Leads	<b>86010</b>
<b>Comanche (MJ) 2.5</b>	<b>1986-90</b>
EPE	90 122
Ignition Coil	<b>80362</b>
<b>Comanche (MJ) 2.5 4x4</b>	<b>1986-90</b>
EPE	90 122
Ignition Coil	<b>80362</b>
<b>Comanche (MJ) 4.0</b>	<b>1990-96</b>
ERH	130 178
Ignition Coil	<b>80362</b>
<b>Comanche (MJ) 4.0 4x4</b>	<b>1987-96</b>
ERH	130 178
Ignition Coil	<b>80362</b>
<b>Commander (XK) 3.7 V6 4x4</b>	<b>2005-10</b>
EKG	157 214
Ignition Coil	<b>80345</b>
<b>Commander (XK) 4.7 V8 4x4</b>	<b>2005-10</b>
EVA	170 231
Ignition Coil	<b>80345</b>
<b>Grand Cherokee I (ZJ) 4.0 i 4x4</b>	<b>1991-99</b>
ERH	132 180
Ignition Coil	<b>80362</b>
Ignition Leads	<b>86010</b>
<b>Grand Cherokee I (ZJ) 4.0 i 4x4</b>	<b>1991-99</b>
MX	135 184
Ignition Coil ->12.1997	<b>80362</b>
Ignition Leads	<b>86010</b>
<b>Grand Cherokee I (ZJ) 4.0 i 4x4</b>	<b>1995-99</b>
S01	130 177
Ignition Coil ->12.1997	<b>80362</b>
Ignition Leads	<b>86010</b>
<b>Grand Cherokee I (ZJ) 4.0 Laredo</b>	<b>1996-98</b>
ERH	131 178
Ignition Coil	<b>80362</b>
Ignition Leads	<b>86010</b>
<b>Grand Cherokee I (ZJ) 5.2</b>	<b>1996-98</b>
ELF	164 223
Ignition Coil ->12.1997	<b>80362</b>
<b>Grand Cherokee I (ZJ) 5.2 4x4</b>	<b>1996-98</b>
ELF	164 223
Ignition Coil	<b>80362</b>

JEEP Cont.	
<b>Grand Cherokee I (ZJ) 5.2 4x4</b>	<b>1995-99</b>
Y01	156 212
Ignition Coil ->12.1997	<b>80362</b>
<b>Grand Cherokee I (ZJ) 5.2 i 4x4</b>	<b>1992-99</b>
ELF	155 211
Ignition Coil ->12.1997	<b>80362</b>
<b>Grand Cherokee I (ZJ) 5.2 i 4x4</b>	<b>1992-99</b>
Y	158 215
Ignition Coil ->12.1997	<b>80362</b>
<b>Grand Cherokee I (ZJ) 5.2 Limited 4x4</b>	<b>1996-98</b>
ELF	136 185
Ignition Coil	<b>80362</b>
<b>Grand Cherokee II (WJ, WG) 4.0 4x4</b>	<b>1999-05</b>
ERH	140 190
Ignition Leads	<b>86010</b>
<b>Grand Cherokee II (WJ, WG) 4.7 V8</b>	<b>2004-05</b>
EVA	167 227
Ignition Coil	<b>80345</b>
<b>Grand Cherokee II (WJ, WG) 4.7 V8 4x4</b>	<b>1999-00</b>
EVA	162 220
Ignition Coil	<b>80345</b>
<b>Grand Cherokee II (WJ, WG) 4.7 V8 4x4</b>	<b>1999-05</b>
EVA	164 223
Ignition Coil	<b>80345</b>
<b>Grand Cherokee II (WJ, WG) 4.7 V8 4x4</b>	<b>2001-05</b>
EVC	190 258
Ignition Coil	<b>80345</b>
<b>Grand Cherokee II (WJ, WG) 4.7 V8 4x4</b>	<b>2003-05</b>
EVA	167 227
Ignition Coil	<b>80345</b>
<b>Grand Cherokee III (WH, WK) 3.7 V6</b>	<b>2005-10</b>
EKG	157 214
Ignition Coil	<b>80345</b>
<b>Grand Cherokee III (WH, WK) 3.7 V6 4x4</b>	<b>2005-10</b>
EKG	157 214
Ignition Coil	<b>80345</b>
<b>Grand Cherokee III (WH, WK) 4.7 V8 4x4</b>	<b>2005-10</b>
EVA	170 231
Ignition Coil	<b>80345</b>
<b>Wrangler I (YJ, SJ) 2.5</b>	<b>1988-91</b>
	76 103
Ignition Coil	<b>80264</b>
Ignition Coil 01.1991->	<b>80362</b>
<b>Wrangler I (YJ, SJ) 2.5</b>	<b>1991-96</b>
EPE	89 121
Ignition Coil	<b>80362</b>
Ignition Leads	<b>86011</b>
<b>Wrangler I (YJ, SJ) 4.0</b>	<b>1991-96</b>
ERH	131 178
Ignition Coil	<b>80362</b>
Ignition Leads	<b>86010</b>
<b>Wrangler II (TJ) 2.4</b>	<b>2002-07</b>
ED1	105 143
Ignition Coil	<b>80295</b>
Ignition Coil 01.2004->	<b>80296</b>
<b>Wrangler II (TJ) 2.5</b>	<b>1996-07</b>
P00	87 118
Ignition Coil ->12.1997	<b>80362</b>
Ignition Leads	<b>86011</b>
<b>Wrangler II (TJ) 4.0</b>	<b>1996-07</b>
S01	130 177
Ignition Coil ->12.1997	<b>80362</b>
Ignition Leads	<b>86010</b>
KIA	
<b>Borrego 4.6</b>	<b>2008-11</b>
G8BA	250 340
Ignition Coil	<b>80341</b>
<b>Carens I (FC) 1.8 i</b>	<b>2000-02</b>
T8	81 110
Ignition Leads	<b>85145</b>
<b>Carens II (FJ) 1.8</b>	<b>2002-&gt;</b>
TB	93 126
Ignition Leads	<b>85145</b>
<b>Carens III (UN) 1.6 CVT</b>	<b>2009-&gt;</b>
G4FC	97 132
Ignition Coil	<b>80332</b>



KIA Cont.	
<b>Carens III (UN) 1.6 CVT</b>	2010->
G4FC	93 126
Ignition Coil	<b>80332</b>
<b>Carens IV 1.6</b>	2013->
G4FD	99 135
Ignition Coil	<b>80335</b>
<b>Carens IV 2.0 GDi</b>	2013->
G4NC	130 177
Ignition Coil	<b>80342</b>
<b>Carens IV 2.0 GDi</b>	2013->
G4NC	122 166
Ignition Coil	<b>80342</b>
<b>Carnival / Grand Carnival III (VQ) 2.7 V6</b>	2006->
G6EA	139 189
Ignition Coil 01.2007->	<b>80363</b>
<b>Carnival I (UP) 2.5 V6</b>	1999-01
KRV6	121 165
Ignition Leads	<b>85149</b>
<b>Carnival II (GQ) 2.5 V6</b>	2001-06
K5	110 150
Ignition Leads	<b>85149</b>
<b>Cee'D Sportswagon 1.4 CVT</b>	2012->
G4FA	73 100
Ignition Coil	<b>80332</b>
<b>Cee'D Sportswagon 1.6 GDI</b>	2012->
G4FD	99 135
Ignition Coil	<b>80335</b>
<b>Cee'D 1.4 CVT</b>	2012->
G4FA	73 100
Ignition Coil	<b>80332</b>
<b>Cee'D 1.6 CVT</b>	2012->
G4FC	92 125
Ignition Coil ->12.2012	<b>80332</b>
<b>Cee'D 1.6 GDI</b>	2012->
G4FD	99 135
Ignition Coil	<b>80335</b>
<b>Cee'D Fastback (ED) 1.4</b>	2006-12
G4FA	80 109
Ignition Coil ->03.2009	<b>80331</b>
Ignition Coil 04.2009-08.2009	<b>80332</b>
<b>Cee'D Fastback (ED) 1.4</b>	2006-12
G4FA	77 105
Ignition Coil	<b>80332</b>
<b>Cee'D Fastback (ED) 1.6</b>	2006-12
G4FC	90 122
Ignition Coil ->01.2008	<b>80331</b>
<b>Cee'D Fastback (ED) 1.6</b>	2008-12
G4FC	93 126
Ignition Coil ->03.2009	<b>80331</b>
Ignition Coil 04.2009->	<b>80332</b>
<b>Cee'D Fastback (ED) 1.6</b>	2007-12
G4FC	85 115
Ignition Coil 02.2008-03.2009	<b>80331</b>
Ignition Coil	<b>80332</b>
<b>Cee'D Fastback (ED) 1.6 CVT</b>	2010-12
G4FC	92 125
Ignition Coil	<b>80332</b>
<b>Cee'D SW (ED) 1.4</b>	2007-12
G4FA	80 109
Ignition Coil ->03.2009	<b>80331</b>
Ignition Coil 04.2009-08.2009	<b>80332</b>
<b>Cee'D SW (ED) 1.4</b>	2010-12
G4FA	77 105
Ignition Coil	<b>80332</b>
<b>Cee'D SW (ED) 1.4 CVT</b>	2009-12
G4FA-L	66 90
Ignition Coil	<b>80332</b>
<b>Cee'D SW (ED) 1.6</b>	2007-12
G4FC	90 122
Ignition Coil ->03.2009	<b>80331</b>
Ignition Coil 04.2009->	<b>80332</b>
<b>Cee'D SW (ED) 1.6</b>	2007-12
G4FC	93 126
Ignition Coil ->03.2009	<b>80331</b>
Ignition Coil 04.2009->	<b>80332</b>
<b>Cee'D SW (ED) 1.6</b>	2007-12
G4FC	85 115
Ignition Coil ->03.2009	<b>80331</b>
Ignition Coil 04.2009->	<b>80332</b>

KIA Cont.	
<b>Cee'D SW (ED) 1.6 CVT</b>	2009-12
G4FC	92 125
Ignition Coil	<b>80332</b>
<b>Cee'D SW (ED) 1.6 LPG</b>	2008-12
G4FC	91 124
Ignition Coil ->03.2009	<b>80331</b>
Ignition Coil 04.2009->	<b>80332</b>
<b>Cerato (LD) 1.6</b>	2004->
G4ED	77 105
Ignition Leads	<b>85394</b>
<b>Cerato (LD) 1.6</b>	2006->
G4FC	90 122
Ignition Coil ->01.2008	<b>80331</b>
Ignition Coil 02.2008-11.2009	<b>80332</b>
<b>Cerato II (TD) 1.6</b>	2009->
G4FC	91 124
Ignition Coil 08.2010->	<b>80332</b>
<b>Cerato II Sedan (TD) 1.6</b>	2010->
G4FC	90 122
Ignition Coil 08.2010->	<b>80332</b>
Ignition Coil	<b>80341</b>
<b>Cerato II Sedan (TD) 1.6</b>	2010->
G4FC	93 126
Ignition Coil 08.2010->	<b>80332</b>
<b>Cerato II Sedan (TD) 2.0</b>	2010->
G4KD	116 158
Ignition Coil	<b>80341</b>
<b>Cerato II Sedan (TD) 2.0</b>	2009->
G4KD	115 156
Ignition Coil	<b>80341</b>
<b>Cerato Koup (TD) 1.6 CVT</b>	2010-13
G4FC	93 126
Ignition Coil 08.2010->	<b>80332</b>
<b>Cerato Koup (TD) 1.6 CVT</b>	2009->
G4FC	91 124
Ignition Coil 08.2010->	<b>80332</b>
<b>Cerato Koup (TD) 2.0</b>	2009->
G4KD	115 156
Ignition Coil	<b>80341</b>
<b>Cerato Sedan (LD) 1.6</b>	2004->
G4ED	77 105
Ignition Leads	<b>85394</b>
<b>Cerato Sedan (LD) 1.6</b>	2006->
G4FC	90 122
Ignition Coil ->01.2008	<b>80331</b>
Ignition Coil 02.2008-11.2009	<b>80332</b>
<b>Cerato Sedan 1.6 Mpi</b>	2013->
G4FC	96 130
Ignition Coil	<b>80332</b>
<b>Cerato Sedan 2.0 Mpi</b>	2013->
G4KD	110 150
Ignition Coil	<b>80341</b>
<b>Clarus (K9A) 1.8 i 16V</b>	1996-01
T8	85 116
Ignition Leads	<b>85145</b>
<b>Joice 2.0</b>	2000->
G4CP	102 139
Ignition Leads	<b>85999</b>
<b>Joice 2.0</b>	2001->
G4CP	88 120
Ignition Leads	<b>85999</b>
<b>Magentis (GD) 2.0</b>	2001-05
G4JP	100 136
Ignition Coil	<b>80316</b>
Ignition Leads	<b>85393</b>
<b>Magentis (MG) 2.0</b>	2009->
G4KD	121 165
Ignition Coil OE 27300-3F100	<b>80341</b>
<b>Magentis (MG) 2.7</b>	2005->
G6EA	138 188
Ignition Coil 11.2006->	<b>80363</b>
<b>Magentis (MG) 2.7 V6</b>	2009->
G6EA	142 193
Ignition Coil	<b>80363</b>
<b>Optima 2.0</b>	2012->
G4KD	125 170
Ignition Coil	<b>80341</b>



KIA Cont.		
<b>Optima 2.0</b>		2010->
G4KH		204 277
Ignition Coil	OE 27300-3F100	<b>80341</b>
Ignition Coil	OE 27300-2E000	<b>80342</b>
<b>Optima 2.0 CVVL</b>		2012->
G4KD		121 165
Ignition Coil		<b>80341</b>
<b>Optima 2.0 CVVT Hybrid</b>		2012->
		140 190
Ignition Coil		<b>80342</b>
<b>Optima 2.0 CVVT Hybrid</b>		2012->
G4NE		110 150
Ignition Coil		<b>80342</b>
<b>Optima 2.4</b>		2010->
G4KJ		149 203
Ignition Coil		<b>80341</b>
<b>Optima 2.4</b>		2012->
G4KJ		132 179
Ignition Coil		<b>80341</b>
<b>Optima 2.4 Hybrid</b>		2011->
		154 209
Ignition Coil		<b>80342</b>
<b>Picanto (BA) 1.0</b>		2004->
G4HE		45 61
Ignition Leads		<b>85998</b>
<b>Picanto (BA) 1.1</b>		2004->
G4HG		48 65
Ignition Leads		<b>85998</b>
<b>Picanto (TA) 1.0</b>		2015->
G3LA		49 67
Ignition Coil		<b>80333</b>
<b>Picanto (TA) 1.0</b>		2011->
G3LA		51 69
Ignition Coil		<b>80333</b>
<b>Picanto (TA) 1.0 Bi-Fuel</b>		2011->
B3LA		60 82
Ignition Coil		<b>80333</b>
<b>Picanto (TA) 1.2</b>		2011->
G4LA		63 85
Ignition Coil	With Start&Stop system	<b>80314</b>
Ignition Leads	Without Start&Stop system	<b>85397</b>
<b>Pride (DA) 1.1 i</b>		1991-00
B1		38 52
Ignition Coil		<b>80315</b>
<b>Pride (DA) 1.3 16V</b>		1990-00
B3		44 60
Ignition Coil		<b>80315</b>
<b>Pride (DA) 1.3 16V</b>		1990-01
B3		53 72
Ignition Coil		<b>80315</b>
<b>Pride (DA) 1.3 16V</b>		1996-01
B3		47 64
Ignition Coil		<b>80315</b>
<b>Pride (DA) 1.3 i</b>		1990-97
		51 69
Ignition Coil		<b>80315</b>
<b>Pride SW 1.3</b>		1999-01
B3A5		47 64
Ignition Coil		<b>80315</b>
<b>Pro Cee'D (ED) 1.4</b>		2008-12
G4FA		80 109
Ignition Coil	->03.2009	<b>80331</b>
Ignition Coil	04.2009->	<b>80332</b>
<b>Pro Cee'D (ED) 1.4</b>		2008-12
G4FA		77 105
Ignition Coil		<b>80332</b>
<b>Pro Cee'D (ED) 1.4 CVVT</b>		2010-12
G4FA-L		66 90
Ignition Coil		<b>80332</b>
<b>Pro Cee'D (ED) 1.6</b>		2008-12
G4FC		90 122
Ignition Coil	03.2008-03.2009	<b>80331</b>
Ignition Coil	04.2009->	<b>80332</b>
<b>Pro Cee'D (ED) 1.6</b>		2008-12
G4FC		93 126
Ignition Coil	03.2008-03.2009	<b>80331</b>
Ignition Coil	04.2009->	<b>80332</b>

KIA Cont.		
<b>Pro Cee'D (ED) 1.6 CVVT</b>		2010-13
G4FC		92 125
Ignition Coil	->12.2012	<b>80332</b>
<b>Pro Cee'D (JD) 1.4 CVVT</b>		2013->
G4FA		73 100
Ignition Coil		<b>80332</b>
<b>Pro Cee'D 1.6 GDI</b>		2013->
G4FD		99 135
Ignition Coil		<b>80335</b>
<b>Rio 4 (DC) 1.3</b>		2000-05
A3E		55 75
Ignition Leads		<b>85147</b>
<b>Rio 4 (DC) 1.3</b>		2002-05
A3E		60 82
Ignition Leads		<b>85147</b>
<b>Rio 4 (DC) 1.5 16V</b>		2000-05
A5D		72 98
Ignition Leads		<b>85146</b>
<b>Rio 5 (DC) 1.3</b>		2000-05
A3E		60 82
Ignition Leads		<b>85147</b>
<b>Rio 5 (DC) 1.3</b>		2000-05
A3E		55 75
Ignition Leads		<b>85147</b>
<b>Rio 5 (DC) 1.5 16V</b>		2000-05
A5D		72 98
Ignition Leads		<b>85146</b>
<b>Rio 5 (DC) 1.5 16V</b>		2002-05
A5D		71 97
Ignition Leads		<b>85146</b>
<b>Rio II (JB) 1.4 16V</b>		2005->
G4EE		71 97
Ignition Coil	->10.2011	<b>80334</b>
<b>Rio II (JB) 1.6 CVVT</b>		2005->
G4ED		82 112
Ignition Coil	->10.2011	<b>80334</b>
<b>Rio II Sedan (JB) 1.4 16V</b>		2005->
G4EE		71 97
Ignition Coil	->10.2011	<b>80334</b>
<b>Rio II Sedan (JB) 1.6 16V</b>		2005->
G4ED		82 112
Ignition Coil	->10.2011	<b>80334</b>
<b>Rio III (UB) 1.2</b>		2011->
G4LA		51 69
Ignition Coil	With Start&Stop system	<b>80314</b>
<b>Rio III (UB) 1.25 CVVT</b>		2011->
G4LA		63 86
Ignition Coil	With Start&Stop system	<b>80314</b>
Ignition Leads	Without Start&Stop system	<b>85397</b>
<b>Rio III (UB) 1.25 CVVT</b>		2011->
G4LA		65 88
Ignition Coil	With Start&Stop system	<b>80314</b>
<b>Rio III (UB) 1.25 LPG</b>		2011->
G4LA		63 86
Ignition Coil	With Start&Stop system	<b>80314</b>
Ignition Leads	Without Start&Stop system	<b>85397</b>
<b>Rio III (UB) 1.4 CVVT</b>		2011->
G4FA		80 109
Ignition Coil		<b>80332</b>
<b>Rio III (UB) 1.4 CVVT</b>		2011->
G4FA		79 107
Ignition Coil		<b>80332</b>
<b>Rio III (UB) 1.6 CVVT</b>		2012->
G4FC		90 123
Ignition Coil		<b>80332</b>
<b>Rio III Sedan (UB) 1.25 CVVT</b>		2011->
G4LA		63 86
Ignition Coil	With Start&Stop system	<b>80314</b>
Ignition Leads	Without Start&Stop system	<b>85397</b>
<b>Rio III Sedan (UB) 1.4 CVVT</b>		2011->
G4FA		79 107
Ignition Coil		<b>80332</b>
<b>Rio III Sedan (UB) 1.4 CVVT</b>		2011->
G4FA		80 109
Ignition Coil		<b>80332</b>
<b>Rio III Sedan (UB) 1.6 CVVT</b>		2012->
G4FC		90 123
Ignition Coil		<b>80332</b>



KIA Cont.	
<b>Sephia (FA) 1.8 i 16V</b>	<b>1995-97</b>
OK24N/OK26Y	82 112
Ignition Leads	<b>85145</b>
<b>Sephia Sedan (FA) 1.8 i 16V</b>	<b>1995-97</b>
OK24N/OK26Y	82 112
Ignition Leads	<b>85145</b>
<b>Shuma (FB) 1.5 i 16V</b>	<b>1997-01</b>
ZYVE/BFD	65 88
Ignition Leads	<b>85145</b>
<b>Shuma (FB) 1.8 i 16V</b>	<b>1997-01</b>
T8	81 110
Ignition Leads	<b>85145</b>
<b>Shuma II (FB) 1.6</b>	<b>2001-04</b>
GA6D	75 101
Ignition Leads	<b>85146</b>
<b>Shuma II (FB) 1.8</b>	<b>2003-04</b>
T8	84 114
Ignition Leads	<b>85145</b>
<b>Shuma II Sedan (FB) 1.6</b>	<b>2001-04</b>
GA6D	75 101
Ignition Leads	<b>85146</b>
<b>Shuma Sedan (FB) 1.5</b>	<b>1996-98</b>
OK280	59 80
Ignition Leads	<b>85145</b>
<b>Sorento I (JC) 2.4</b>	<b>2002-&gt;</b>
G4JS	102 139
Ignition Coil	<b>80316</b>
Ignition Leads ->04.2006	<b>85393</b>
<b>Sorento II (XM) 2.4 CVVT</b>	<b>2009-&gt;</b>
G4KE	128 174
Ignition Coil	<b>80341</b>
<b>Sorento II (XM) 2.4 CVVT</b>	<b>2012-&gt;</b>
	141 192
Ignition Coil	<b>80341</b>
<b>Sorento II (XM) 2.4 CVVT 4WD</b>	<b>2009-&gt;</b>
G4KE	128 174
Ignition Coil	<b>80341</b>
<b>Sorento II (XM) 2.4 CVVT 4WD</b>	<b>2012-&gt;</b>
	141 192
Ignition Coil	<b>80341</b>
<b>Sorento II (XM) 2.4 GDI</b>	<b>2012-&gt;</b>
G4KJ	141 192
Ignition Coil	<b>80341</b>
<b>Sorento II (XM) 2.4 GDI 4WD</b>	<b>2012-&gt;</b>
G4KJ	141 192
Ignition Coil	<b>80341</b>
<b>Soul (AM) 1.6 CVVT</b>	<b>2009-&gt;</b>
G4FC	93 126
Ignition Coil ->07.2011	<b>80332</b>
<b>Soul (AM) 1.6 CVVT</b>	<b>2009-&gt;</b>
G4FC	77 105
Ignition Coil ->07.2011	<b>80332</b>
<b>Soul (AM) 1.6 CVVT</b>	<b>2012-&gt;</b>
G4FC	95 129
Ignition Coil ->12.2014	<b>80332</b>
<b>Soul (AM) 1.6 GDI</b>	<b>2011-&gt;</b>
G4FD	103 140
Ignition Coil 08.2011-12.2014	<b>80335</b>
<b>Soul (AM) 1.6 LPG</b>	<b>2009-14</b>
G4FC	92 125
Ignition Coil ->07.2011	<b>80332</b>
<b>Soul II (PS) 1.6 CVVT</b>	<b>2014-&gt;</b>
G4FG	91 124
Ignition Coil	<b>80332</b>
<b>Soul II (PS) 1.6 GDI</b>	<b>2014-&gt;</b>
G4FD	97 132
Ignition Coil	<b>80335</b>
<b>Sportage (K00) 2.0</b>	<b>2000-03</b>
FE (16V)	87 118
Ignition Leads	<b>85148</b>
<b>Sportage (K00) 2.0 4WD</b>	<b>2000-03</b>
FE (16V)	87 118
Ignition Leads	<b>85148</b>
<b>Sportage (K00) 2.0 i 16V</b>	<b>1999-03</b>
FE (16V)	94 128
Ignition Leads	<b>85148</b>

KIA Cont.	
<b>Sportage (K00) 2.0 i 16V 4WD</b>	<b>1994-03</b>
FE (16V)	94 128
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85148</b>
<b>Sportage (K00) 2.0 i 4WD</b>	<b>1994-99</b>
FE (8V)	70 95
Ignition Coil	<b>80279</b>
<b>Sportage (QL) 1.6 GDI</b>	<b>2015-&gt;</b>
G4FD	97 132
Ignition Coil	<b>80335</b>
<b>Sportage (SL) 1.6 GDI</b>	<b>2011-&gt;</b>
G4FD	99 135
Ignition Coil	<b>80335</b>
<b>Sportage (SL) 2.0 CVVT</b>	<b>2010-&gt;</b>
G4KD	120 163
Ignition Coil	<b>80341</b>
<b>Sportage (SL) 2.0 CVVT</b>	<b>2010-&gt;</b>
G4KD	122 166
Ignition Coil	<b>80341</b>
<b>Sportage (SL) 2.0 CVVT AWD</b>	<b>2010-&gt;</b>
G4KD	122 166
Ignition Coil	<b>80341</b>
<b>Sportage (SL) 2.0 CVVT AWD</b>	<b>2010-&gt;</b>
G4KD	120 163
Ignition Coil	<b>80341</b>
<b>Sportage (SL) 2.0 GDI</b>	<b>2014-&gt;</b>
G4NC	122 166
Ignition Coil	<b>80342</b>
<b>Sportage (SL) 2.0 Gdi AWD</b>	<b>2014-&gt;</b>
G4NC	122 166
Ignition Coil	<b>80342</b>
<b>Venga (YN) 1.4 CVVT</b>	<b>2010-&gt;</b>
G4FA-L	66 90
Ignition Coil	<b>80332</b>
<b>Venga (YN) 1.4 LPG</b>	<b>2010-&gt;</b>
G4FA-L	66 90
Ignition Coil	<b>80332</b>
<b>Venga (YN) 1.6 CVVT</b>	<b>2010-&gt;</b>
G4FC	92 125
Ignition Coil	<b>80332</b>

LADA	
<b>110 (2110) 1.6</b>	<b>1995-07</b>
VAZ-21114	72 98
Ignition Coil	<b>80359</b>
<b>110 (2110) 1.6 LPG</b>	<b>2004-07</b>
VAZ-21114	60 82
Ignition Coil 01.2005->	<b>80358</b>
<b>110 1.5</b>	<b>1995-05</b>
BA3 2111	54 73
Ignition Coil OE 2112 3705010	<b>80359</b>
Ignition Leads	<b>83100</b>
<b>110 1.5</b>	<b>1995-05</b>
VAZ-2111	57 78
Ignition Coil OE 2111 3705010	<b>80358</b>
Ignition Coil OE 2112 3705010	<b>80359</b>
<b>110 1.5 16V</b>	<b>1995-05</b>
VAZ-2112	70 95
Ignition Coil	<b>80318</b>
Ignition Coil OE 2112 3705010	<b>80359</b>
<b>110 1.5 16V</b>	<b>2000-10</b>
VAZ-2112	67 91
Ignition Coil	<b>80318</b>
Ignition Coil OE 2112 3705010	<b>80359</b>
<b>110 1.6</b>	<b>2000-12</b>
VAZ-21114	60 82
Ignition Coil OE 2111 3705010	<b>80358</b>
<b>110 1.6</b>	<b>2000-07</b>
VAZ-21124	66 90
Ignition Coil OE 21123705010	<b>80359</b>
<b>111 1.5</b>	<b>1996-05</b>
VAZ-2111	57 78
Ignition Coil	<b>80359</b>
<b>111 1.5 16V</b>	<b>1995-02</b>
VAZ-2112	70 95
Ignition Coil OE 2112 3705010	<b>80359</b>





LADA Cont.		
<b>111 1.5 16V</b>		<b>2000-05</b>
VAZ-2112		67 91
Ignition Coil OE 2112 3705010		<b>80359</b>
<b>111 1.6</b>		<b>2004-13</b>
VAZ-21114		60 82
Ignition Coil		<b>80358</b>
<b>111 1.6</b>		<b>2004-&gt;</b>
VAZ-21124		66 90
Ignition Coil		<b>80358</b>
<b>112 (2112) 1.5</b>		<b>1995-04</b>
VAZ-2111		57 78
Ignition Coil OE 2112 3705010		<b>80359</b>
<b>112 (2112) 1.5</b>		<b>2000-05</b>
VAZ-2111		56 76
Ignition Coil OE 2112 3705010		<b>80359</b>
<b>112 (2112) 1.6</b>		<b>2006-08</b>
VAZ-21124		66 90
Ignition Coil OE 2112 3705010		<b>80359</b>
<b>112 (2112) 1.6</b>		<b>2005-11</b>
VAZ-21114		60 82
Ignition Coil		<b>80358</b>
<b>112 1.5 16V</b>		<b>1995-00</b>
VAZ-2112		70 95
Ignition Coil OE 2112 3705010		<b>80359</b>
<b>112 1.5 16V</b>		<b>2000-05</b>
VAZ-2112		67 91
Ignition Coil OE 2112 3705010		<b>80359</b>
<b>1200-1500 Combi 1500</b>		<b>1973-85</b>
BA3 2103		54 73
Ignition Leads ->08.1984		<b>83100</b>
<b>1200-1600 1200 L/S</b>		<b>1970-86</b>
BA3 2101		44 60
Ignition Leads		<b>83100</b>
<b>1200-1600 1300</b>		<b>1974-84</b>
BA3 2105		51 69
Ignition Leads 05.1978-08.1982		<b>83100</b>
<b>1200-1600 1300</b>		<b>1978-87</b>
BA3 21011		48 65
Ignition Leads ->08.1982		<b>83100</b>
<b>1200-1600 1500</b>		<b>1972-84</b>
BA3 2103		55 75
Ignition Leads		<b>83100</b>
<b>1200-1600 1500 N/S</b>		<b>1975-86</b>
BA3 2103		55 75
Ignition Leads ->08.1984		<b>83100</b>
<b>1200-1600 1600</b>		<b>1972-84</b>
BA3 2106		58 79
Ignition Leads 09.1975->		<b>83100</b>
<b>1200-1600 1600 N/L</b>		<b>1979-86</b>
BA3 2106		57 78
Ignition Leads		<b>83100</b>
<b>Granta (2190) 1.6</b>		<b>2013-&gt;</b>
VAZ-21127		78 106
Ignition Coil		<b>80359</b>
<b>Granta (2190) 1.6</b>		<b>2011-&gt;</b>
VAZ-11186		64 87
Ignition Coil		<b>80358</b>
<b>Granta (2190) 1.6</b>		<b>2011-&gt;</b>
VAZ-11183		60 82
Ignition Coil		<b>80358</b>
<b>Granta (2190) 1.6 Sport</b>		<b>2014-&gt;</b>
VAZ-21127		87 118
Ignition Coil		<b>80359</b>
<b>Kalina Combi (1117) 1.6</b>		<b>2004-13</b>
VAZ-21114		60 82
Ignition Coil		<b>80358</b>
<b>Kalina Fastback (1119) 1.6</b>		<b>2010-13</b>
VAZ11110		62 84
Ignition Coil		<b>80358</b>
<b>Kalina Fastback (1119) 1.6</b>		<b>2004-13</b>
VAZ-21114		60 82
Ignition Coil		<b>80358</b>
<b>Kalina Fastback (1119) 1.6 16V</b>		<b>2004-13</b>
VAZ-11186		66 90
Ignition Coil		<b>80358</b>
<b>Kalina Fastback (2192) 1.6</b>		<b>2013-&gt;</b>
VAZ-11186		64 87
Ignition Coil		<b>80358</b>

LADA Cont.		
<b>Kalina Fastback (2192) 1.6</b>		<b>2013-&gt;</b>
VAZ-21126		72 98
Ignition Coil		<b>80359</b>
<b>Kalina Fastback (2192) 1.6</b>		<b>2013-&gt;</b>
VAZ-21127		78 106
Ignition Coil		<b>80359</b>
<b>Kalina Kombi (1117) 1.6</b>		<b>2010-&gt;</b>
VAZ11110		62 84
Ignition Coil		<b>80358</b>
<b>Kalina Kombi (2194) 1.6</b>		<b>2013-&gt;</b>
VAZ-11186		64 87
Ignition Coil		<b>80358</b>
<b>Kalina Kombi (2194) 1.6</b>		<b>2013-&gt;</b>
VAZ-21126		72 98
Ignition Coil		<b>80359</b>
<b>Kalina Kombi (2194) 1.6</b>		<b>2013-&gt;</b>
VAZ-21127		78 106
Ignition Coil		<b>80359</b>
<b>Kalina Sedan (1118) 1.6</b>		<b>2010-&gt;</b>
VAZ11110		62 84
Ignition Coil		<b>80358</b>
<b>Kalina Sedan (1118) 1.6</b>		<b>2004-09</b>
VAZ-21124/VAZ-21114		60 82
Ignition Coil VAZ-21114		<b>80358</b>
<b>Kalina Sedan (1118) 1.6 16V</b>		<b>2004-&gt;</b>
VAZ-11186		66 90
Ignition Coil		<b>80358</b>
<b>Nadeschda (2120) 1.7</b>		<b>1997-06</b>
VAZ-2121.3		60 82
Ignition Coil		<b>80358</b>
<b>Nadeschda (2120) 1.7 i</b>		<b>1997-06</b>
BA3 21214		59 80
Ignition Coil		<b>80358</b>
<b>Nadeschda (2120) 1.8</b>		<b>1997-06</b>
VAZ-2130		60 82
Ignition Coil		<b>80358</b>
<b>Nadeschda (2120) 1.8 i</b>		<b>1997-06</b>
VAZ-2130.1		67 91
Ignition Coil		<b>80358</b>
<b>Niva (2121) 1600</b>		<b>1980-87</b>
BA3 2121		56 76
Ignition Leads		<b>83100</b>
<b>Niva (2121) 1600</b>		<b>1987-95</b>
BA3 2121		54 73
Ignition Leads		<b>83100</b>
<b>Niva (2121) 1600</b>		<b>1976-93</b>
BA3 2121		56 76
Ignition Leads		<b>83100</b>
<b>Niva (2121) 1700 i</b>		<b>1996-06</b>
BA3 21214		59 80
Ignition Coil		<b>80358</b>
<b>Niva (2121) 1700 i 4x4</b>		<b>2010-&gt;</b>
BA3 21214		61 83
Ignition Coil		<b>80358</b>
<b>Niva (2121) 1700 i 4x4</b>		<b>2000-10</b>
BA3 21214		60 82
Ignition Coil		<b>80358</b>
<b>Niva II (2123) 1.7</b>		<b>2004-&gt;</b>
BA3 21214		61 83
Ignition Coil		<b>80358</b>
<b>Niva II (2123) 1.7</b>		<b>2002-&gt;</b>
BA3 21214		59 80
Ignition Coil		<b>80358</b>
<b>Niva II (2123) 1.7 LPG</b>		<b>2002-&gt;</b>
BA3 21214		57 78
Ignition Coil		<b>80358</b>
<b>Nova (2105) 1200 Junior/L</b>		<b>1981-&gt;</b>
BA3 2101		44 60
Ignition Leads ->12.1993		<b>83100</b>
<b>Nova (2105) 1300 Special/L</b>		<b>1981-&gt;</b>
BA3 2105		48 65
Ignition Leads ->12.1993		<b>83100</b>
<b>Nova (2105) 1500 S</b>		<b>1989-12</b>
BA3 21083		52 71
Ignition Leads		<b>83100</b>
<b>Nova (2105) 1500 Special</b>		<b>1985-&gt;</b>
BA3 2103		55 75
Ignition Leads ->12.1993		<b>83100</b>



LADA Cont.	
<b>Nova (2105) 1600</b>	<b>1988-01</b>
BA3 2106	56 76
Ignition Leads	<b>83100</b>
<b>Nova (2105) 1700 i Classic</b>	<b>1996-&gt;</b>
	62 84
Ignition Coil	<b>80279</b>
<b>Nova Kombi (2104) 1300</b>	<b>1985-91</b>
BA3 2105	48 65
Ignition Leads	<b>83100</b>
<b>Nova Kombi (2104) 1500</b>	<b>1985-93</b>
BA3 2103	55 75
Ignition Leads	<b>83100</b>
<b>Nova Kombi (2104) 1700</b>	<b>1994-&gt;</b>
	62 84
Ignition Coil	<b>80279</b>
<b>Priora Fastback (2172) 1.6</b>	<b>2008-&gt;</b>
BA3 21703	60 82
Ignition Coil ->12.2015	<b>80358</b>
<b>Priora Fastback (2172) 1.6</b>	<b>2014-&gt;</b>
VAZ-21127	78 106
Ignition Coil	<b>80359</b>
<b>Priora Fastback (2172) 1.6</b>	<b>2011-&gt;</b>
	64 87
Ignition Coil ->12.2015	<b>80358</b>
<b>Priora Kombi (2171) 1.6</b>	<b>2014-&gt;</b>
VAZ-21127	78 106
Ignition Coil	<b>80359</b>
<b>Priora Sedan (2170) 1.6</b>	<b>2008-&gt;</b>
BA3 21703	60 82
Ignition Coil	<b>80358</b>
<b>Priora Sedan (2170) 1.6</b>	<b>2014-&gt;</b>
VAZ-21127	78 106
Ignition Coil	<b>80359</b>
<b>Priora Sedan (2170) 1.6</b>	<b>2011-&gt;</b>
	64 87
Ignition Coil	<b>80358</b>
<b>Samara (2108, 2109, 2115) 1100</b>	<b>1988-94</b>
BA3 21081	39 53
Ignition Leads DIN	<b>83100</b>
Ignition Leads	<b>83450</b>
<b>Samara (2108, 2109, 2115) 1100</b>	<b>1996-99</b>
BA3 21081	43 58
Ignition Leads	<b>83100</b>
<b>Samara (2108, 2109, 2115) 1300</b>	<b>1987-96</b>
BA3 2108	46 63
Ignition Leads	<b>83100</b>
<b>Samara (2108, 2109, 2115) 1300</b>	<b>1986-94</b>
BA3 2108	48 65
Ignition Leads	<b>83100</b>
<b>Samara (2108, 2109, 2115) 1300</b>	<b>1991-99</b>
BA3 2108	45 61
Ignition Leads	<b>83100</b>
<b>Samara (2108, 2109, 2115) 1500</b>	<b>1987-96</b>
BA3 21083	53 72
Ignition Leads	<b>83100</b>
<b>Samara (2108, 2109, 2115) 1500</b>	<b>1991-96</b>
BA3 21083	50 68
Ignition Leads BA3 21083 (KAT)	<b>83100</b>
Ignition Leads	<b>83450</b>
<b>Samara (2108, 2109, 2115, 2113, 2114) 1.6</b>	<b>2009-13</b>
	60 82
Ignition Coil	<b>80358</b>
<b>Samara Forma (21099) 1100</b>	<b>1991-99</b>
BA3 21081	39 53
Ignition Leads	<b>83100</b>
<b>Samara Forma (21099) 1300</b>	<b>1989-97</b>
BA3 2108	48 65
Ignition Leads	<b>83100</b>
<b>Samara Forma (21099) 1300</b>	<b>1990-99</b>
BA3 2108	46 63
Ignition Leads	<b>83100</b>
<b>Samara Forma (21099) 1300</b>	<b>1991-99</b>
BA3 2108	45 61
Ignition Leads	<b>83100</b>
<b>Samara Forma (21099) 1300</b>	<b>1996-06</b>
BA3 21115	50 68
Ignition Leads	<b>83100</b>

LADA Cont.	
<b>Samara Forma (21099) 1500</b>	<b>1991-96</b>
BA3 21083	53 72
Ignition Leads	<b>83100</b>
<b>Samara Forma (21099) 1500</b>	<b>1991-96</b>
BA3 21083	50 68
Ignition Leads BA3 21083 (KAT)	<b>83100</b>
<b>Toscana (2107) 1300</b>	<b>1985-12</b>
BA3 2105	48 65
Ignition Leads 01.1986->	<b>83100</b>
<b>Toscana (2107) 1500</b>	<b>1983-93</b>
BA3 2103	55 75
Ignition Leads BA3 2103	<b>83100</b>
<b>Vesta 1.6</b>	<b>2015-&gt;</b>
	78 106
Ignition Coil	<b>80359</b>
<b>LAMBORGHINI</b>	
<b>Diablo SE</b>	<b>1994-96</b>
	386 525
Ignition Coil	<b>80217</b>
<b>Diablo VT Allrad</b>	<b>1990-98</b>
	361 492
Ignition Coil	<b>80217</b>
<b>Gallardo 5.0</b>	<b>2003-&gt;</b>
L 510	368 500
Ignition Coil	<b>80248</b>
<b>Gallardo 5.0</b>	<b>2005-&gt;</b>
	382 520
Ignition Coil	<b>80248</b>
<b>Gallardo Spyder 5.0</b>	<b>2005-&gt;</b>
	382 520
Ignition Coil	<b>80248</b>
<b>LANCIA</b>	
<b>Dedra (835) 1.6 16V</b>	<b>1996-99</b>
182 A4.000	76 103
Ignition Coil	<b>80280</b>
Ignition Leads With Tempomat	<b>86050</b>
<b>Dedra (835) 1.6 i.e.</b>	<b>1989-94</b>
835 A1.000	66 90
Ignition Leads 06.1994->; With catalytic converter	<b>85270</b>
<b>Dedra (835) 1.6 i.e.</b>	<b>1993-99</b>
835 C1.000	55 75
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85650</b>
<b>Dedra (835) 1.6 LE KAT</b>	<b>1994-99</b>
159 B9.000	66 90
Ignition Coil	<b>80279</b>
Ignition Leads	<b>85650</b>
<b>Dedra (835) 1.8 i.e.</b>	<b>1989-94</b>
835 A2.000	80 109
Ignition Coil	<b>80217</b>
Ignition Leads 06.1994->; With catalytic converter	<b>85270</b>
<b>Dedra (835) 1.8 i.e.</b>	<b>1989-99</b>
835 A2.046	77 105
Ignition Coil	<b>80217</b>
Ignition Leads 06.1994->; With catalytic converter	<b>85270</b>
Ignition Leads 07.1994->	<b>85650</b>
<b>Dedra (835) 1.8 i.e.</b>	<b>1994-99</b>
836 A5.000	74 101
Ignition Coil 836 A5.000	<b>80217</b>
Ignition Leads With catalytic converter	<b>85270</b>
Ignition Leads	<b>85650</b>
<b>Dedra (835) 1.8 i.e.</b>	<b>1993-99</b>
835 C5.000	66 90
Ignition Coil	<b>80217</b>
Ignition Leads 06.1994->; With catalytic converter	<b>85270</b>
Ignition Leads 07.1994->	<b>85650</b>
<b>Dedra (835) 2.0 16V</b>	<b>1994-99</b>
836 A3.000	102 139
Ignition Leads	<b>85610</b>
<b>Dedra (835) 2.0 HF Integrale</b>	<b>1990-94</b>
835 A7.046	124 169
Ignition Leads	<b>83040</b>
<b>Dedra (835) 2.0 i.e.</b>	<b>1989-99</b>
835 A5.046	83 113
Ignition Leads	<b>83040</b>



LANCIA Cont.	
<b>Dedra (835) 2.0 i.e. Turbo</b>	<b>1991-99</b>
835 A8.046	119 162
Ignition Leads	<b>83040</b>
<b>Dedra (835) 2.0 i.e. Turbo Integrale</b>	<b>1990-94</b>
835 A7.000	121 165
Ignition Leads	<b>83040</b>
<b>Dedra (835) 2.0 Turbo</b>	<b>1990-94</b>
835 A8.000	130 177
Ignition Leads	<b>83040</b>
<b>Dedra SW (835) 1.6</b>	<b>1994-99</b>
159 B9.000	66 90
Ignition Leads	<b>85650</b>
<b>Dedra SW (835) 1.6 16V</b>	<b>1996-99</b>
182 A4.000	76 103
Ignition Coil	<b>80280</b>
Ignition Leads With Tempomat	<b>86050</b>
<b>Dedra SW (835) 1.8 i.e.</b>	<b>1994-99</b>
836 A5.000	74 101
Ignition Coil 836 A5.000	<b>80217</b>
Ignition Leads With catalytic converter	<b>85270</b>
Ignition Leads	<b>85650</b>
<b>Dedra SW (835) 2.0 16V</b>	<b>1994-99</b>
836 A3.000	102 139
Ignition Leads	<b>85610</b>
<b>Dedra SW (835) 2.0 Integrale</b>	<b>1994-99</b>
836 A3.000	102 139
Ignition Leads	<b>85610</b>
<b>Delta I (831AB0) 1,1</b>	<b>1986-90</b>
831 B8.000	47 64
Ignition Leads	<b>83940</b>
<b>Delta I (831AB0) 1.6 GT i.e.</b>	<b>1986-88</b>
831 B7.000	80 109
Ignition Leads	<b>83390</b>
<b>Delta I (831AB0) 2.0 16V HF Evo Integrale</b>	<b>1993-94</b>
831 E5.046/831 E5.000	155 211
Ignition Coil	<b>80217</b>
Ignition Leads	<b>85620</b>
<b>Delta I (831AB0) 2.0 16V HF Integrale</b>	<b>1989-91</b>
831 D5.000	144 196
Ignition Coil	<b>80217</b>
<b>Delta II (836) 1.4 i.e.</b>	<b>1994-99</b>
836 A4.000/160 A1.046	51 69
Ignition Coil	<b>80279</b>
Ignition Leads Version MM	<b>85271</b>
<b>Delta II (836) 1.6 i.e.</b>	<b>1993-99</b>
835 C1.000	55 75
Ignition Coil	<b>80279</b>
<b>Delta II (836) 1.6 i.e.</b>	<b>1996-99</b>
182 A6.000	66 90
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Delta II (836) 1.6 i.e. 16V</b>	<b>1996-99</b>
182 A4.000	76 103
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Delta II (836) 1.8 i.e.</b>	<b>1993-99</b>
835 C2.000	76 103
Ignition Coil 835 C2.000	<b>80217</b>
Ignition Leads	<b>83330</b>
<b>Delta II (836) 1.8 i.e.</b>	<b>1994-99</b>
835 C4.000/836 C4.000/836 A6.000	66 90
Ignition Coil	<b>80217</b>
<b>Delta II (836) 1.8 i.e. 16V GT</b>	<b>1996-99</b>
183 A1.000	96 131
Ignition Coil 07.1999->	<b>80228</b>
<b>Delta II (836) 2.0 16V</b>	<b>1993-99</b>
836 A3.000	102 139
Ignition Leads	<b>85610</b>
<b>Delta II (836) 2.0 16V Turbo</b>	<b>1996-99</b>
175 A4.000	142 193
Ignition Coil 175 A4.000	<b>80217</b>
Ignition Leads	<b>85620</b>
<b>Delta II (836) 2.0 16V Turbo</b>	<b>1993-99</b>
836 A2.000	137 186
Ignition Coil 836 A2.000	<b>80217</b>
Ignition Leads	<b>85620</b>
<b>Delta III (844) 1.4</b>	<b>2008-14</b>
198 A4.000	88 120
Ignition Coil	<b>80267</b>

LANCIA Cont.	
<b>Delta III (844) 1.4</b>	<b>2008-14</b>
198 A1.000	110 150
Ignition Coil ->07.2010	<b>80267</b>
<b>Delta III (844) 1.4 16V</b>	<b>2010-14</b>
198 A7.000	103 140
Ignition Coil 08.2010->	<b>80267</b>
<b>Delta III (844) 1.4 Bifuel</b>	<b>2011-14</b>
198 A4.000	88 120
Ignition Coil	<b>80267</b>
<b>Kappa (838A) 2.0 16V Turbo</b>	<b>1995-01</b>
838 A4.000	151 205
Ignition Coil	<b>80279</b>
<b>Kappa (838A) 2.0 20V</b>	<b>1994-01</b>
838 A1.000	107 146
Ignition Coil	<b>80312</b>
<b>Kappa (838A) 2.0 20V</b>	<b>1996-01</b>
838 A6.000	114 155
Ignition Coil	<b>80312</b>
<b>Kappa (838A) 2.0 20V Turbo</b>	<b>1998-01</b>
175 A3.000	162 220
Ignition Coil	<b>80312</b>
<b>Kappa (838A) 2.4 20V</b>	<b>1994-01</b>
838 A2.000/838 A2.027	129 175
Ignition Coil	<b>80312</b>
<b>Kappa Coupe (838) 2.0 16V Turbo</b>	<b>1996-01</b>
838 A4.000	151 205
Ignition Coil	<b>80279</b>
<b>Kappa Coupe (838) 2.0 20V</b>	<b>1996-01</b>
838 A6.000	114 155
Ignition Coil	<b>80312</b>
<b>Kappa Coupe (838) 2.4 20V</b>	<b>1996-01</b>
838 A2.000	129 175
Ignition Coil	<b>80312</b>
<b>Kappa SW (838B) 2.0 16V Turbo</b>	<b>1996-01</b>
838 A4.000	151 205
Ignition Coil	<b>80279</b>
<b>Kappa SW (838B) 2.0 20V</b>	<b>1996-01</b>
838 A6.000	114 155
Ignition Coil	<b>80312</b>
<b>Kappa SW (838B) 2.0 20V Turbo</b>	<b>1998-01</b>
175 A3.000	162 220
Ignition Coil	<b>80312</b>
<b>Kappa SW (838B) 2.4 20V</b>	<b>1996-01</b>
838 A2.000	129 175
Ignition Coil	<b>80312</b>
<b>Lybra (839AX) 1.6 16V</b>	<b>1999-05</b>
182 A4.000	76 103
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Lybra (839AX) 1.8 16V</b>	<b>1999-05</b>
839 A7.000/839 A9.000/839 A4.000	96 131
Ignition Coil 839 A4.000	<b>80228</b>
<b>Lybra (839AX) 2.0 20V</b>	<b>1999-00</b>
182 B7.000	113 154
Ignition Coil	<b>80312</b>
<b>Lybra (839AX) 2.0 20V</b>	<b>2000-05</b>
185 A8.000	110 150
Ignition Coil	<b>80312</b>
<b>Lybra (839AX) 2.4 20V</b>	<b>2001-05</b>
192 A2.000	125 170
Ignition Coil ->05.2002	<b>80312</b>
<b>Lybra SW (839BX) 1.6 16V</b>	<b>1999-05</b>
182 A4.000	76 103
Ignition Coil	<b>80280</b>
Ignition Leads	<b>86050</b>
<b>Lybra SW (839BX) 1.8 16V</b>	<b>1999-05</b>
839 A7.000/839 A4.000	96 131
Ignition Coil	<b>80228</b>
<b>Lybra SW (839BX) 2.0 20V</b>	<b>1999-00</b>
182 B7.000	113 154
Ignition Coil	<b>80312</b>
<b>Lybra SW (839BX) 2.0 20V</b>	<b>2000-05</b>
185 A8.000	110 150
Ignition Coil	<b>80312</b>
<b>Musa (350) 1.4</b>	<b>2004-12</b>
843 A 1.000	70 95
Ignition Coil 843 A 1.000	<b>80233</b>



LANCIA Cont.		
<b>Musa (350) 1.4</b>		<b>2005-12</b>
350 A1.000		57 78
Ignition Coil		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Musa (350) 1.4</b>		<b>2007-12</b>
192 B2.000		66 90
Ignition Coil		<b>80233</b>
<b>Musa (350) 1.4 LPG</b>		<b>2010-12</b>
350 A1.000		57 78
Ignition Coil		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Phedra (179) 3.0 V6</b>		<b>2002-10</b>
ES9 J4S		150 204
Ignition Coil		<b>80309</b>
<b>Thema (834) 2000 16V</b>		<b>1992-93</b>
834 F1.000		112 152
Ignition Coil		<b>80279</b>
<b>Thema (834) 2000 16V Turbo</b>		<b>1992-94</b>
834 F2.000		148 201
Ignition Coil		<b>80279</b>
<b>Thema (834) 2000 16V Turbo</b>		<b>1988-90</b>
834 C1.000		133 181
Ignition Coil 834 C1.000		<b>80217</b>
Ignition Leads		<b>85620</b>
<b>Thema (834) 2000 i.e.</b>		<b>1987-92</b>
834 B.146		85 115
Ignition Coil		<b>80279</b>
<b>Thema (834) 2000 i.e. 16V</b>		<b>1988-92</b>
834 B2.000		108 147
Ignition Coil 834 B2.000		<b>80217</b>
Ignition Leads		<b>85620</b>
<b>Thema (834) 2000 i.e. 16V</b>		<b>1989-92</b>
834 B2.246		104 141
Ignition Coil 834 B2.246		<b>80217</b>
Ignition Leads		<b>85620</b>
<b>Thema (834) 2000 i.e. 16V Turbo</b>		<b>1989-92</b>
834 C1.246		130 177
Ignition Coil 834 C1.246		<b>80217</b>
Ignition Leads		<b>85620</b>
<b>Thema (834) 2000 i.e. Turbo</b>		<b>1986-90</b>
834 C.146		110 150
Ignition Leads		<b>83390</b>
<b>Thema (834) 2850 V6 i.e.</b>		<b>1984-88</b>
834 E.000		110 150
Ignition Leads		<b>85580</b>
<b>Thema (834) 8,32</b>		<b>1987-89</b>
F 105 L		158 215
Ignition Leads		<b>85580</b>
<b>Thema SW (834) 2000 16V</b>		<b>1992-94</b>
834 F1.000		112 152
Ignition Coil		<b>80279</b>
<b>Thema SW (834) 2000 i.e. 16V</b>		<b>1989-92</b>
834 B2.000		108 147
Ignition Coil 834 B2.000		<b>80217</b>
Ignition Coil		<b>80279</b>
Ignition Leads		<b>85620</b>
<b>Thema SW (834) 2000 i.e. 16V</b>		<b>1989-92</b>
834 B2.246		104 141
Ignition Coil 834 B2.246		<b>80217</b>
Ignition Leads		<b>85620</b>
<b>Thema SW (834) 2000 i.e. 16V Turbo</b>		<b>1988-90</b>
834 C1.000		133 181
Ignition Coil 834 C1.000		<b>80217</b>
Ignition Leads		<b>85620</b>
<b>Thema SW (834) 2000 i.e. 16V Turbo</b>		<b>1989-93</b>
834 C1.246		130 177
Ignition Coil 834 C1.246		<b>80217</b>
Ignition Leads		<b>85620</b>
<b>Thema SW (834) 2000 Turbo</b>		<b>1988-92</b>
834 C.146		110 150
Ignition Leads		<b>83390</b>
Ignition Leads 834 C.146		<b>85620</b>
<b>Thema SW (834) 2000 Turbo 16V</b>		<b>1992-94</b>
834 F2.000		148 201
Ignition Coil		<b>80279</b>
<b>Thesis (841AX) 2,4</b>		<b>2002-09</b>
841 D.000		125 170
Ignition Coil		<b>80312</b>

LANCIA Cont.		
<b>Thesis (841AX) 2.0 Turbo</b>		<b>2002-09</b>
841 E.000		136 185
Ignition Coil		<b>80312</b>
<b>Y (840A) 1,1</b>		<b>1995-03</b>
176 B2.000		40 54
Ignition Coil 176 B2.000		<b>80217</b>
Ignition Leads 01.1996-06.2000		<b>85625</b>
<b>Y (840A) 1,2</b>		<b>1996-03</b>
840 A3.000/188 A4.000		44 60
Ignition Coil		<b>80217</b>
Ignition Leads 188 A4.000		<b>85625</b>
Ignition Leads		<b>86040</b>
<b>Y (840A) 1.2 16V</b>		<b>2000-03</b>
188 A5.000		59 80
Ignition Coil		<b>80279</b>
Ignition Leads		<b>85648</b>
<b>Y (840A) 1.2 16V</b>		<b>1997-03</b>
176 B9.000		63 86
Ignition Coil 176 B9.000		<b>80217</b>
Ignition Leads		<b>85647</b>
<b>Y (840A) 1.4 12V</b>		<b>1996-03</b>
840 A4.000		55 75
Ignition Coil		<b>80279</b>
Ignition Leads		<b>86040</b>
<b>Y (840A) 1.4 12V</b>		<b>1996-03</b>
840 A2.000		59 80
Ignition Coil		<b>80279</b>
Ignition Leads		<b>86040</b>
<b>Y10 (156) 1.0 Fire</b>		<b>1985-89</b>
156 A2.000		33 45
Ignition Coil		<b>80265</b>
<b>Y10 (156) 1.0 Fire</b>		<b>1985-91</b>
156 A2.100		32 44
Ignition Coil		<b>80265</b>
Ignition Leads		<b>83890</b>
<b>Y10 (156) 1.0 Fire</b>		<b>1985-90</b>
156 A2.000		37 50
Ignition Coil		<b>80265</b>
<b>Y10 (156) 1.0 Fire 4WD</b>		<b>1986-89</b>
156 A2.100		32 44
Ignition Coil		<b>80265</b>
Ignition Leads		<b>83890</b>
<b>Y10 (156) 1.0 Fire KAT</b>		<b>1987-92</b>
156 A2.246		33 45
Ignition Coil		<b>80265</b>
<b>Y10 (156) 1.1 Avenue</b>		<b>1995-95</b>
176 B2.000		40 54
Ignition Coil		<b>80279</b>
<b>Y10 (156) 1.1 Avenue 4WD</b>		<b>1995-95</b>
176 B2.000		40 54
Ignition Coil		<b>80279</b>
<b>Y10 (156) 1.1 i.e</b>		<b>1989-92</b>
156 C.000		42 57
Ignition Coil		<b>80265</b>
Ignition Leads		<b>83890</b>
<b>Y10 (156) 1.1 i.e 4WD</b>		<b>1989-92</b>
156 C.000		42 57
Ignition Coil		<b>80265</b>
Ignition Leads		<b>83890</b>
<b>Y10 (156) 1.1 i.e. Fire</b>		<b>1989-95</b>
156 C.046		37 50
Ignition Coil		<b>80265</b>
Ignition Coil		<b>80279</b>
Ignition Leads		<b>83890</b>
<b>Y10 (156) 1.1 i.e. Fire 4WD</b>		<b>1992-95</b>
156 C.046		37 50
Ignition Coil		<b>80279</b>
Ignition Leads		<b>83890</b>
<b>Ypsilon (843) 1.2</b>		<b>2003-11</b>
188 A4.000		44 60
Ignition Coil 188 A4.000		<b>80217</b>
Ignition Leads		<b>85625</b>
<b>Ypsilon (843) 1.2</b>		<b>2003-11</b>
188 A5.000		59 80
Ignition Coil 188 A5.000		<b>80233</b>
Ignition Coil		<b>80340</b>



LANCIA Cont.		
<b>Ypsilon (843) 1.2</b>	2010-11	
169 A4.000	51	69
Ignition Coil	->11.2011; Euro 4	<b>80217</b>
Ignition Coil		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Ypsilon (843) 1.4</b>	2006-11	
350 A1.000	57	78
Ignition Coil		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Ypsilon (843) 1.4 16V</b>	2003-11	
843 A 1.000	70	95
Ignition Coil	843 A 1.000	<b>80233</b>
<b>Ypsilon (843) 1.4 LPG</b>	2010-11	
350 A1.000	57	78
Ignition Coil		<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Ypsilon (846) 1.2</b>	2011->	
169 A4.000	51	69
Ignition Coil	Euro 4	<b>80217</b>
Ignition Leads		<b>85626</b>
<b>Ypsilon (846) 1.2 Bifuel</b>	2011->	
169 A4.000	49	67
Ignition Coil	Euro 4	<b>80217</b>
Ignition Coil	OE 55208723; OE 55200486; OE 55200112	<b>80340</b>
Ignition Leads		<b>85626</b>
<b>Zeta (220) 2.0 16V</b>	1998-00	
RFV (XU10J4R)	97	132
Ignition Coil		<b>80274</b>
<b>Zeta (220) 2.0 Turbo</b>	1995-02	
RGX (XU10J2TE)	108	147
Ignition Coil	RGX	<b>80207</b>
Ignition Leads		<b>83330</b>

LANDROVER		
<b>Discovery II (LJ, LT) 4.0 V8 4x4</b>	1998-04	
35 D/56 D/94 D	136	185
Ignition Coil		<b>80279</b>
<b>Discovery III (TAA) 4.4 4x4</b>	2004-09	
448PN	220	299
Ignition Coil		<b>80361</b>
<b>Discovery Sport (LC) 2.0 4WD</b>	2014->	
204PT	177	241
Ignition Coil		<b>80255</b>
<b>Freelander (LN) 1.8 16V 4x4</b>	2000-06	
18 K4F	86	117
Ignition Coil		<b>80254</b>
Ignition Leads		<b>85765</b>
Ignition Leads		<b>85766</b>
<b>Freelander (LN) 1.8 i 16V 4x4</b>	1998-00	
18 K4F	88	120
Ignition Coil		<b>80254</b>
Ignition Leads		<b>85765</b>
Ignition Leads		<b>85767</b>
<b>Freelander (LN) 2.5 V6 4x4</b>	2000-06	
25 K4F	130	177
Ignition Coil		<b>80216</b>
Ignition Leads		<b>85765</b>
Ignition Leads		<b>85768</b>
<b>Freelander 2 (FA) 2.0 Si4 4x4</b>	2011-14	
204PT	177	241
Ignition Coil		<b>80255</b>
Ignition Leads		<b>85766</b>
<b>Freelander Soft Top 1.8 i 16V 4x4</b>	1998-06	
18 K4F	88	120
Ignition Coil		<b>80254</b>
Ignition Leads		<b>85765</b>
Ignition Leads		<b>85767</b>
<b>Range Rover Evoque (LV) 2.0 4x4</b>	2016->	
204PT	177	241
Ignition Coil	->Ch.FH077413	<b>80255</b>
<b>Range Rover Evoque (LV) 2.0 4x4</b>	2011->	
204PT	177	241
Ignition Coil		<b>80255</b>
<b>Range Rover II (LP) 3.9 4x4</b>	1994-02	
42 D	140	190
Ignition Coil		<b>80279</b>

LANDROVER Cont.		
<b>Range Rover II (LP) 4.0 4x4</b>	1998-02	
42 D	136	185
Ignition Coil		<b>80279</b>
<b>Range Rover II (LP) 4.6 4x4</b>	1998-02	
60 D	160	218
Ignition Coil		<b>80279</b>
<b>Range Rover II (LP) 4.6 4x4</b>	1994-02	
46 D	165	224
Ignition Coil		<b>80279</b>
<b>Range Rover III (LM) 4.2 4x4</b>	2005-12	
428PS	291	396
Ignition Coil		<b>80361</b>
<b>Range Rover III (LM) 4.4 4x4</b>	2002-05	
M62 B44	210	286
Ignition Coil		<b>80216</b>
<b>Range Rover III (LM) 4.4 4x4</b>	2005-12	
448PN	225	306
Ignition Coil		<b>80361</b>
<b>Range Rover Sport (LS) 4.2 4x4</b>	2005-13	
428PS	287	390
Ignition Coil		<b>80361</b>
<b>Range Rover Sport (LS) 4.4 4x4</b>	2005-13	
448PN	220	299
Ignition Coil		<b>80361</b>

LEXUS		
<b>CT (ZWA1) 200h</b>	2010->	
5ZR-FXE/2ZR-FXE	73	99
Ignition Coil		<b>80337</b>
<b>ES (V6) 250 (AVV60_, ASV60_)</b>	2012->	
2AR-FE	135	184
Ignition Coil		<b>80367</b>
<b>ES (V6) 300h (ASV60_, AVV60_)</b>	2012->	
2AR-FXE	118	160
Ignition Coil		<b>80367</b>
<b>GS (GRS19, UZS19, GWS19) 300</b>	2005-11	
3GR-FSE	183	249
Ignition Coil		<b>80367</b>
<b>GS (GRS19, UZS19, GWS19) 450h</b>	2006-11	
2GR-FSE	218	296
Ignition Coil		<b>80367</b>
<b>GS (GRS19, UZS19, URS19) 300 (GRS195_, GRS190_)</b>	2005-11	
3GR-FE	170	231
Ignition Coil		<b>80367</b>
<b>GS (GRS19, UZS19, URS19) 350 AWD (GRS196_, GRS191_)</b>	2008-11	
2GR-FSE	232	316
Ignition Coil		<b>80367</b>
<b>GS (GRS19, UZS19, URS19) 450h (GWS191_, GRS196_)</b>	2006-11	
2GR-FSE	254	345
Ignition Coil		<b>80367</b>
<b>GS (L1) 250 (GRL11_)</b>	2012->	
4GR-FSE	154	209
Ignition Coil		<b>80367</b>
<b>GS (L1) 300h (AWL10_, GRL11_)</b>	2013->	
2AR-FSE	133	181
Ignition Coil		<b>80367</b>
<b>GS (L1) 350 (GRL10_, GRL15_, GWL10_)</b>	2012->	
2GR-FSE	234	318
Ignition Coil		<b>80367</b>
<b>GS (L1) 350 AWD (GRL10_)</b>	2012->	
2GR-FSE	234	318
Ignition Coil		<b>80367</b>
<b>GS (L1) 450h (GRL10_, GRL15_, GWL10_)</b>	2012->	
2GR-FXE	215	292
Ignition Coil		<b>80367</b>
<b>GX (URJ15) 460 4WD</b>	2009->	
1UR-FE	218	296
Ignition Coil		<b>80367</b>
<b>IS C (GSE2) 250</b>	2009->	
4GR-FSE	153	208
Ignition Coil		<b>80367</b>
<b>IS II (GSE2, ALE2, USE2) 250</b>	2005-13	
4GR-FSE	153	208
Ignition Coil		<b>80367</b>
<b>IS II (GSE2, ALE2, USE2) 250 AWD</b>	2005-13	
4GR-FSE	153	208
Ignition Coil		<b>80367</b>





<b>LEXUS Cont.</b>	
<b>IS III (E3) 300h (AVE30_)</b>	<b>2013-&gt;</b>
2AR-FSE	133 181
Ignition Coil	<b>80367</b>
<b>LS (UVF4, USF4) 460</b>	<b>2006-&gt;</b>
1UR-FSE	280 381
Ignition Coil	<b>80367</b>
<b>LS (UVF4, USF4) 460</b>	<b>2008-&gt;</b>
1UR-FE	255 347
Ignition Coil	<b>80367</b>
<b>LS (UVF4, USF4) 460</b>	<b>2012-&gt;</b>
1UR-FSE	285 388
Ignition Coil	<b>80367</b>
<b>LS (UVF4, USF4) 460 AWD</b>	<b>2008-&gt;</b>
1UR-FSE	270 367
Ignition Coil	<b>80367</b>
<b>LS (UVF4, USF4) 460 AWD</b>	<b>2012-&gt;</b>
1UR-FSE	272 370
Ignition Coil	<b>80367</b>
<b>LS (UVF4, USF4) 600h</b>	<b>2007-&gt;</b>
2UR-FSE	290 394
Ignition Coil	<b>80367</b>
<b>LX (J2) 570 (URJ201_)</b>	<b>2007-&gt;</b>
3UR-FE	270 367
Ignition Coil	<b>80367</b>
<b>RX (GYL1, GGL15, AGL10) 350 AWD</b>	<b>2008-12</b>
2GR-FXE/2GR-FE	204 277
Ignition Coil 2GR-FXE	<b>80368</b>
<b>RX (GYL1, GGL15, AGL10) 450h</b>	<b>2008-15</b>
2GR-FXE	183 249
Ignition Coil	<b>80368</b>
<b>RX (GYL1, GGL15, AGL10) 450h AWD</b>	<b>2008-15</b>
2GR-FXE	183 249
Ignition Coil	<b>80368</b>
<b>RX (L1) 270 (AGL10_)</b>	<b>2008-15</b>
1AR-FE	138 188
Ignition Coil	<b>80367</b>
<b>RX (MHU3, GSU3, MCU3) 350 AWD</b>	<b>2006-08</b>
2GR-FE	203 276
Ignition Coil	<b>80368</b>
<b>LINCOLN</b>	
<b>Mark LT 5.4</b>	<b>2005-&gt;</b>
	224 305
Ignition Coil	<b>80360</b>
<b>LOTUS</b>	
<b>Elise 1.8</b>	<b>2000-05</b>
18 K4F	90 122
Ignition Leads	<b>85765</b>
<b>Elise 1.8</b>	<b>2002-&gt;</b>
	118 160
Ignition Leads	<b>85765</b>
<b>Elise 1.8</b>	<b>1995-00</b>
18 K4F	88 120
Ignition Leads 03.1999->	<b>85764</b>
Ignition Leads	<b>85765</b>
<b>MAZDA</b>	
<b>121 II (DB) 1.3 16V</b>	<b>1990-96</b>
B3 (16V)	39 53
Ignition Leads	<b>86030</b>
<b>121 II (DB) 1.3 i 16V</b>	<b>1990-96</b>
B3 (16V)	53 72
Ignition Leads	<b>86030</b>
<b>121 III (JASM, JBSM) 1.25</b>	<b>1996-03</b>
DHG/DHF	55 75
Ignition Coil With regul.cat.(3way)	<b>80213</b>
Ignition Coil Saw tooth	<b>80214</b>
<b>121 III (JASM, JBSM) 1.3</b>	<b>1996-03</b>
JJM/JJK	37 50
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil ->10.1999	<b>80285</b>
Ignition Leads SAE	<b>85112</b>
Ignition Leads SAE	<b>85114</b>

<b>MAZDA Cont.</b>	
<b>121 III (JASM, JBSM) 1.3</b>	<b>1996-03</b>
J4R/J4T	44 60
Ignition Coil 05.1997-06.1998	<b>80213</b>
Ignition Coil With regul.cat.(3way)	<b>80214</b>
Ignition Coil ->10.1999	<b>80285</b>
Ignition Leads SAE	<b>85112</b>
Ignition Leads SAE	<b>85114</b>
<b>2 (DY) 1.25</b>	<b>2003-07</b>
FUJA	55 75
Ignition Coil ->02.2005	<b>80214</b>
Ignition Coil 03.2005->	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>2 (DY) 1.4</b>	<b>2003-07</b>
FXJA	59 80
Ignition Coil ->02.2005	<b>80214</b>
Ignition Coil 03.2005->	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads SAE	<b>85116</b>
Ignition Leads	<b>85125</b>
<b>2 (DY) 1.6</b>	<b>2003-07</b>
FYJA	74 100
Ignition Coil	<b>80214</b>
Ignition Coil 03.2005->	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads SAE	<b>85116</b>
Ignition Leads	<b>85125</b>
<b>3 (BK) 2.0</b>	<b>2003-09</b>
LF17	110 150
Ignition Coil	<b>80231</b>
Ignition Coil 03.2006->	<b>80283</b>
Ignition Coil ->02.2006	<b>80285</b>
<b>3 (BK) 2.3 DiSi Turbo MPS</b>	<b>2006-09</b>
L3YH	184 250
Ignition Coil	<b>80283</b>
<b>3 (BK) 2.3 MPS Turbo</b>	<b>2006-09</b>
L3-VDT/L3N9	191 260
Ignition Coil	<b>80283</b>
<b>3 (BK) 2.3 MZR</b>	<b>2004-09</b>
L3-VE	115 156
Ignition Coil	<b>80283</b>
<b>3 (BK) 2.3 MZR Sport</b>	<b>2003-09</b>
L3YS/L3YT	126 171
Ignition Coil	<b>80283</b>
<b>3 (BL) 2.0 MZR</b>	<b>2009-14</b>
LF17/LF-DE	110 150
Ignition Coil	<b>80283</b>
<b>3 (BL) 2.0 MZR</b>	<b>2010-14</b>
LF5H	108 147
Ignition Coil	<b>80283</b>
<b>3 (BL) 2.0 MZR DISI</b>	<b>2008-13</b>
LF5W/LF5H	111 151
Ignition Coil	<b>80283</b>
<b>3 Sedan (BK) 2.0</b>	<b>2004-09</b>
LF17	110 150
Ignition Coil	<b>80231</b>
Ignition Coil 03.2006->	<b>80283</b>
Ignition Coil ->02.2006	<b>80285</b>
<b>3 Sedan (BK) 2.3</b>	<b>2000-03</b>
L3-VE	126 171
Ignition Coil	<b>80283</b>
<b>3 Sedan (BK) 2.3</b>	<b>2004-09</b>
L3-VE	118 160
Ignition Coil	<b>80283</b>
<b>3 Sedan (BL) 2.0 MZR</b>	<b>2009-14</b>
LF17/LF-DE	110 150
Ignition Coil	<b>80283</b>
<b>3 Sedan (BL) 2.0 MZR DISI</b>	<b>2009-13</b>
LF5W/LF5H	111 151
Ignition Coil	<b>80283</b>
<b>323 C V (BA) 1.5 16V</b>	<b>1994-98</b>
Z5-DE	65 88
Ignition Leads ->07.1998	<b>83261</b>
<b>323 C V (BA) 1.8 16V</b>	<b>1994-98</b>
BP-ZE	84 114
Ignition Leads	<b>83261</b>
<b>323 F V (BA) 1.5 16V</b>	<b>1994-98</b>
Z5-DE	65 88
Ignition Leads ->07.1995	<b>83261</b>



MAZDA Cont.	
<b>323 F V (BA) 1.8 16V</b>	<b>1994-98</b>
BP-ZE	84 114
Ignition Leads	<b>83261</b>
<b>323 F VI (BJ) 1.4</b>	<b>2001-04</b>
B3 (16V)	53 72
Ignition Leads	<b>83266</b>
<b>323 F VI (BJ) 1.4 16V</b>	<b>1998-01</b>
B3 ME	54 73
Ignition Leads	<b>83266</b>
<b>323 F VI (BJ) 1.5 16V</b>	<b>1998-01</b>
ZL06/ZL05	65 88
Ignition Leads	<b>83264</b>
<b>323 F VI (BJ) 1.6</b>	<b>2001-04</b>
ZM	72 98
Ignition Leads	<b>83264</b>
<b>323 F VI (BJ) 1.6</b>	<b>2001-04</b>
ZM	70 95
Ignition Leads	<b>83264</b>
<b>323 F VI (BJ) 1.9 16V</b>	<b>1998-01</b>
FP /FP55	84 114
Ignition Coil	<b>80307</b>
Ignition Leads	<b>83267</b>
<b>323 F VI (BJ) 2.0</b>	<b>2001-04</b>
FS7G/FS7E	96 131
Ignition Coil	<b>80307</b>
Ignition Leads	<b>83265</b>
<b>323 I (FA) 1.0</b>	<b>1977-80</b>
P/PC	33 45
Ignition Leads	<b>86030</b>
<b>323 I (FA) 1.3</b>	<b>1977-80</b>
T/TC	44 60
Ignition Leads	<b>86030</b>
<b>323 I (FA) 1.4</b>	<b>1978-80</b>
U/UC	51 69
Ignition Leads	<b>86030</b>
<b>323 I Station Wagon (FA) 1.3</b>	<b>1978-86</b>
TC	44 60
Ignition Leads	<b>86030</b>
<b>323 I Station Wagon (FA) 1.4</b>	<b>1978-82</b>
UC	51 69
Ignition Leads	<b>86030</b>
<b>323 I Station Wagon (FA) 1.5</b>	<b>1982-86</b>
D5	52 70
Ignition Leads	<b>86030</b>
<b>323 II (BD) 1.1</b>	<b>1980-85</b>
E1	40 54
Ignition Leads	<b>86030</b>
<b>323 II (BD) 1.3</b>	<b>1981-85</b>
E3	44 60
Ignition Leads	<b>86030</b>
<b>323 II (BD) 1.5</b>	<b>1981-85</b>
E5	55 75
Ignition Leads	<b>86030</b>
<b>323 II (BD) 1.5</b>	<b>1982-86</b>
E5	65 88
Ignition Leads	<b>86030</b>
<b>323 II Hatchback (BD) 1.1</b>	<b>1980-85</b>
E1	40 54
Ignition Leads	<b>86030</b>
<b>323 II Hatchback (BD) 1.3</b>	<b>1980-85</b>
E3	44 60
Ignition Leads	<b>86030</b>
<b>323 II Hatchback (BD) 1.5</b>	<b>1981-85</b>
E5	55 75
Ignition Leads	<b>86030</b>
<b>323 II Hatchback (BD) 1.5</b>	<b>1980-83</b>
E5	63 86
Ignition Leads	<b>86030</b>
<b>323 II Hatchback (BD) 1.5</b>	<b>1982-85</b>
E5	65 88
Ignition Leads	<b>86030</b>
<b>323 III (BF) 1.3</b>	<b>1985-89</b>
E3	44 60
Ignition Coil	<b>80286</b>
<b>323 III (BF) 1.5</b>	<b>1985-89</b>
E5	55 75
Ignition Leads	<b>83261</b>

MAZDA Cont.	
<b>323 III Hatchback (BF) 1.3</b>	<b>1985-87</b>
E3	44 60
Ignition Coil	<b>80286</b>
<b>323 III Hatchback (BF) 1.5</b>	<b>1985-89</b>
E5	55 75
Ignition Leads	<b>83261</b>
<b>323 III Station Wagon (BW) 1.5</b>	<b>1986-89</b>
B50/B53/E5	55 75
Ignition Leads	<b>83261</b>
<b>323 P V (BA) 1.3 16V</b>	<b>1996-98</b>
B3 (16V)	54 73
Ignition Leads	<b>83266</b>
<b>323 P V (BA) 1.5 16V</b>	<b>1996-&gt;</b>
Z5-DE	65 88
Ignition Leads	<b>83261</b>
<b>323 S V (BA) 1.5 16V</b>	<b>1994-98</b>
Z5-DE	65 88
Ignition Leads ->06.1998	<b>83261</b>
<b>323 S V (BA) 1.8 16V</b>	<b>1994-98</b>
BP-ZE	84 114
Ignition Leads	<b>83261</b>
<b>323 S VI (BJ) 1.4</b>	<b>2001-04</b>
B3 (16V)	53 72
Ignition Leads	<b>83266</b>
<b>323 S VI (BJ) 1.4 16V</b>	<b>1998-01</b>
B3 ME	54 73
Ignition Leads	<b>83266</b>
<b>323 S VI (BJ) 1.5 16V</b>	<b>1998-01</b>
ZL06/ZL05	65 88
Ignition Leads	<b>83264</b>
<b>323 S VI (BJ) 1.6</b>	<b>2001-04</b>
ZM	70 95
Ignition Leads	<b>83264</b>
<b>323 S VI (BJ) 1.6</b>	<b>2001-04</b>
ZM	72 98
Ignition Leads	<b>83264</b>
<b>323 S VI (BJ) 1.9 16V</b>	<b>1998-04</b>
FP /FP55	84 114
Ignition Coil	<b>80307</b>
Ignition Leads	<b>83267</b>
<b>323 S VI (BJ) 2.0</b>	<b>2001-04</b>
FS7G/FS7E	96 131
Ignition Coil	<b>80307</b>
Ignition Leads	<b>83265</b>
<b>5 (CR19) 2.0</b>	<b>2005-10</b>
LFF7	107 146
Ignition Coil 09.2007->	<b>80328</b>
<b>5 (CW) 2.0</b>	<b>2011-&gt;</b>
LFZB	108 147
Ignition Coil	<b>80328</b>
<b>5 (CW) 2.0</b>	<b>2011-&gt;</b>
LFZB	106 144
Ignition Coil	<b>80328</b>
<b>5 (CW) 2.0</b>	<b>2010-&gt;</b>
LF5H	110 150
Ignition Coil	<b>80328</b>
<b>6 (GG) 1.8</b>	<b>2002-07</b>
L813/L823/L828	88 120
Ignition Coil	<b>80243</b>
Ignition Leads	<b>83263</b>
<b>6 (GG) 2.0</b>	<b>2002-07</b>
LF18/LF17	104 141
Ignition Coil LF17	<b>80243</b>
Ignition Leads	<b>83263</b>
<b>6 (GG) 2.0</b>	<b>2005-07</b>
LFF7	108 147
Ignition Leads	<b>83263</b>
<b>6 (GG) 2.3</b>	<b>2002-07</b>
L3C1	122 166
Ignition Coil	<b>80243</b>
Ignition Coil	<b>80285</b>
Ignition Leads	<b>83263</b>
<b>6 (GH) 2.0 MZR</b>	<b>2007-12</b>
LF17	108 147
Ignition Coil	<b>80283</b>
<b>6 (GH) 2.5 MZR</b>	<b>2007-13</b>
L5-VE	125 170
Ignition Coil	<b>80283</b>



MAZDA Cont.	
<b>6 Combi (GH) 2.0 MZR</b>	<b>2007-13</b>
LF17	108 147
Ignition Coil	<b>80283</b>
<b>6 Combi (GH) 2.5 MZR</b>	<b>2008-13</b>
L5-VE	125 170
Ignition Coil	<b>80283</b>
<b>6 Fastback (GH) 2.0 MZR</b>	<b>2007-13</b>
LF17	108 147
Ignition Coil	<b>80283</b>
<b>6 Fastback (GH) 2.5 MZR</b>	<b>2007-13</b>
L5-VE	125 170
Ignition Coil	<b>80283</b>
<b>6 Hatchback (GG) 1.8</b>	<b>2002-07</b>
L813	88 120
Ignition Coil	<b>80243</b>
Ignition Leads	<b>83263</b>
<b>6 Hatchback (GG) 2.0</b>	<b>2002-07</b>
LF18/LF17	104 141
Ignition Coil LF17	<b>80243</b>
Ignition Leads	<b>83263</b>
<b>6 Hatchback (GG) 2.0</b>	<b>2005-07</b>
LFF7	108 147
Ignition Leads	<b>83263</b>
<b>6 Hatchback (GG) 2.3</b>	<b>2002-07</b>
L3C1	122 166
Ignition Coil	<b>80243</b>
Ignition Coil 06.2005->	<b>80285</b>
Ignition Leads	<b>83263</b>
<b>6 Station Wagon (GY) 1.8</b>	<b>2002-07</b>
L813	88 120
Ignition Coil	<b>80243</b>
Ignition Leads	<b>83263</b>
<b>6 Station Wagon (GY) 2.0</b>	<b>2002-07</b>
LF18/LF17	104 141
Ignition Coil LF17	<b>80243</b>
Ignition Leads	<b>83263</b>
<b>6 Station Wagon (GY) 2.0</b>	<b>2005-07</b>
LFF7	108 147
Ignition Leads	<b>83263</b>
<b>6 Station Wagon (GY) 2.3</b>	<b>2002-07</b>
L3C1	122 166
Ignition Coil 02.2005->	<b>80243</b>
Ignition Coil 03.2005->	<b>80283</b>
Ignition Coil	<b>80285</b>
Ignition Leads	<b>83263</b>
<b>6 Station Wagon (GY) 2.3 AWD</b>	<b>2002-07</b>
L3C1	119 162
Ignition Coil ->02.2005	<b>80243</b>
Ignition Coil 03.2005->	<b>80283</b>
Ignition Coil	<b>80285</b>
<b>626 IV (GE) 1.8 i</b>	<b>1992-97</b>
FP	77 105
Ignition Leads	<b>83641</b>
<b>626 IV (GE) 1.8 i</b>	<b>1994-97</b>
	66 90
Ignition Leads	<b>83641</b>
<b>626 IV (GE) 2.0 i</b>	<b>1992-97</b>
FS	85 115
Ignition Leads	<b>83641</b>
<b>626 IV (GE) 2.0 i 4WD</b>	<b>1992-97</b>
FS	85 116
Ignition Leads	<b>83641</b>
<b>626 IV Hatchback (GE) 1.8</b>	<b>1991-97</b>
FP	77 105
Ignition Leads	<b>83641</b>
<b>626 IV Hatchback (GE) 1.8</b>	<b>1994-97</b>
FP01LP	66 90
Ignition Leads	<b>83641</b>
<b>626 IV Hatchback (GE) 2.0 i</b>	<b>1991-97</b>
FS	85 115
Ignition Leads	<b>83641</b>
<b>626 IV Hatchback (GE) 2.0 i 4WD</b>	<b>1992-97</b>
FS	85 116
Ignition Leads	<b>83641</b>
<b>626 IV Hatchback (GE) 2.5 24V</b>	<b>1992-97</b>
KL	121 165
Ignition Leads	<b>83641</b>

MAZDA Cont.	
<b>626 IV Hatchback (GE) 2.5 24V</b>	<b>1994-97</b>
KL	120 163
Ignition Leads	<b>83641</b>
<b>626 V (GF) 1.8</b>	<b>1999-02</b>
FP9A	74 100
Ignition Coil ->03.2002	<b>80213</b>
Ignition Leads	<b>83262</b>
<b>626 V (GF) 1.8</b>	<b>1997-99</b>
FPY3	66 90
Ignition Coil	<b>80213</b>
Ignition Leads	<b>83262</b>
<b>626 V (GF) 2.0</b>	<b>1998-02</b>
FS2C	100 136
Ignition Coil 11.1998-04.2002	<b>80213</b>
<b>626 V (GF) 2.0</b>	<b>1997-02</b>
FS	85 115
Ignition Coil 09.1999-04.2002	<b>80213</b>
Ignition Leads	<b>83262</b>
<b>626 V Hatchback (GF) 1.8</b>	<b>1999-02</b>
FP	74 100
Ignition Coil ->06.2000	<b>80213</b>
Ignition Leads	<b>83262</b>
<b>626 V Hatchback (GF) 1.8</b>	<b>1997-99</b>
FPY3	66 90
Ignition Coil ->09.1999	<b>80213</b>
Ignition Leads	<b>83262</b>
<b>626 V Hatchback (GF) 2.0</b>	<b>1997-02</b>
FS	85 115
Ignition Coil ->04.2002	<b>80213</b>
Ignition Leads	<b>83262</b>
<b>626 V Hatchback (GF) 2.0 H.P.</b>	<b>1998-02</b>
FS2C	100 136
Ignition Coil ->04.2002	<b>80213</b>
Ignition Coil	<b>80222</b>
Ignition Leads	<b>83262</b>
<b>626 V Station Wagon (GW) 1.8</b>	<b>2000-02</b>
FP9A	74 100
Ignition Coil ->04.2002	<b>80213</b>
Ignition Leads	<b>83262</b>
<b>626 V Station Wagon (GW) 1.8</b>	<b>1998-00</b>
FPY3	66 90
Ignition Coil ->10.1999	<b>80213</b>
Ignition Leads	<b>83262</b>
<b>626 V Station Wagon (GW) 2.0</b>	<b>1998-02</b>
FS	85 116
Ignition Coil ->04.2002	<b>80213</b>
Ignition Leads	<b>83262</b>
<b>626 V Station Wagon (GW) 2.0 H.P.</b>	<b>1998-02</b>
FS2C	100 136
Ignition Coil ->04.2002	<b>80213</b>
<b>CX-7 (ER) 2.3 MZR DISI Turbo</b>	<b>2007-09</b>
L3-VDT	190 258
Ignition Coil	<b>80283</b>
<b>CX-7 (ER) 2.3 MZR DISI Turbo AWD</b>	<b>2006-14</b>
L3-VDT	175 238
Ignition Coil	<b>80283</b>
<b>MPV II (LW) 2.0</b>	<b>1999-00</b>
FS-DS	90 122
Ignition Leads	<b>83265</b>
<b>MPV II (LW) 2.0</b>	<b>2000-02</b>
FS	88 120
Ignition Coil	<b>80213</b>
<b>MPV II (LW) 2.3</b>	<b>2002-06</b>
L3	104 141
Ignition Coil	<b>80243</b>
<b>MX-3 (EC) 1.6 i</b>	<b>1991-97</b>
B69	65 88
Ignition Leads 11.1993->	<b>83261</b>
<b>MX-3 (EC) 1.6 i</b>	<b>1994-97</b>
B6D	79 107
Ignition Leads	<b>83261</b>
<b>MX-5 III (NC) 2.0</b>	<b>2008-14</b>
LF62/LF-DE	118 160
Ignition Coil	<b>80283</b>
<b>MX-6 (GE) 2.0</b>	<b>1992-97</b>
FS	85 115
Ignition Leads	<b>83641</b>



MAZDA Cont.	
<b>Premacy (Cp) 1.9</b>	<b>1999-05</b>
FP	74 100
Ignition Coil	<b>80307</b>
Ignition Leads	<b>83265</b>
<b>Premacy (Cp) 1.9</b>	<b>1999-05</b>
FP	84 114
Ignition Coil	<b>80307</b>
Ignition Leads	<b>83265</b>
<b>Premacy (Cp) 2.0</b>	<b>2001-05</b>
FS7G/FS7E	96 131
Ignition Coil	<b>80307</b>
<b>Tribute (EP) 2.0</b>	<b>2000-08</b>
YF	91 124
Ignition Coil ->12.2005	<b>80214</b>
Ignition Coil ->12.2003	<b>80285</b>
<b>Tribute (EP) 2.0 4WD</b>	<b>2000-08</b>
YF	91 124
Ignition Coil ->12.2003	<b>80214</b>
Ignition Coil	<b>80285</b>

MERCEDES-BENZ	
<b>190 (W201) 2.0</b>	<b>1982-84</b>
M 102.921	66 90
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) 2.0</b>	<b>1986-90</b>
M 102.924	75 102
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) 2.0</b>	<b>1984-90</b>
M 102.924	77 105
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) E 1.8</b>	<b>1990-93</b>
M 102.910	80 109
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) E 2.0</b>	<b>1985-86</b>
M 102.961/M 102.962	83 113
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) E 2.0</b>	<b>1985-86</b>
M 102.962	85 116
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) E 2.0</b>	<b>1985-93</b>
M 102.962	87 118
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) E 2.0</b>	<b>1982-93</b>
M 102.961/M 102.962	90 122
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) E 2.0</b>	<b>1982-93</b>
M 102.961	93 126
Ignition Leads	<b>83990</b>
<b>190 (W201) E 2.3</b>	<b>1986-91</b>
M 102.985	97 132
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) E 2.3</b>	<b>1986-93</b>
M 102.985	100 136
Ignition Leads SAE	<b>83990</b>
<b>190 (W201) E 2.3-16</b>	<b>1985-87</b>
M 102.983	125 170
Ignition Leads	<b>83990</b>
<b>190 (W201) E 2.3-16</b>	<b>1985-88</b>
M 102.983	130 177
Ignition Leads	<b>83990</b>
<b>190 (W201) E 2.3-16</b>	<b>1984-87</b>
M 102.983	136 185
Ignition Leads	<b>83990</b>
<b>190 (W201) E 2.6</b>	<b>1986-89</b>
M 103.942	122 166
Ignition Leads	<b>85050</b>
<b>190 (W201) E 2.6</b>	<b>1986-93</b>
M 103.942	118 160
Ignition Leads	<b>85050</b>
<b>Cabriolet (A124) 300 CE-24</b>	<b>1992-93</b>
M 104.980	162 220
Ignition Leads	<b>85500</b>
<b>Clase A (W168) A 140</b>	<b>2001-04</b>
M 166.960	60 82
Ignition Coil	<b>80325</b>
<b>Clase A (W168) A 140</b>	<b>1997-04</b>
M 166.940	60 82
Ignition Coil	<b>80325</b>

MERCEDES-BENZ Cont.	
<b>Clase A (W168) A 160</b>	<b>1997-04</b>
M 166.960	75 102
Ignition Coil	<b>80325</b>
<b>Clase A (W168) A 190</b>	<b>1999-04</b>
M 166.990	92 125
Ignition Coil	<b>80325</b>
<b>Clase A (W168) A 210</b>	<b>2002-04</b>
M 166.995	103 140
Ignition Coil	<b>80325</b>
<b>Clase A (W169) A 150</b>	<b>2004-12</b>
M 266.920	70 95
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase A (W169) A 160</b>	<b>2009-12</b>
M 266.920	70 95
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase A (W169) A 170</b>	<b>2004-12</b>
M 266.940	85 116
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase A (W169) A 180</b>	<b>2009-12</b>
M 266.940	85 116
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase A (W169) A 200</b>	<b>2004-12</b>
M 266.960	100 136
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase A (W169) A 200 TURBO</b>	<b>2005-12</b>
M 266.980	142 193
Ignition Coil	<b>80294</b>
<b>Clase B (W245) B 150</b>	<b>2005-11</b>
M 266.920	70 95
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase B (W245) B 160</b>	<b>2009-11</b>
M 266.920	70 95
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase B (W245) B 170</b>	<b>2005-11</b>
M 266.940	85 116
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase B (W245) B 170 NGT</b>	<b>2008-11</b>
M 266.960	85 116
Ignition Coil	<b>80294</b>
<b>Clase B (W245) B 180</b>	<b>2009-11</b>
M 266.940	85 116
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase B (W245) B 180 NGT</b>	<b>2008-11</b>
M 266.960	85 116
Ignition Coil	<b>80294</b>
<b>Clase B (W245) B 200</b>	<b>2005-11</b>
M 266.960	100 136
Ignition Coil	<b>80294</b>
Ignition Leads	<b>83991</b>
<b>Clase B (W245) B 200 TURBO</b>	<b>2005-11</b>
M 266.980	142 193
Ignition Coil	<b>80294</b>
<b>Clase C (W202) C 180</b>	<b>1994-00</b>
M 111.921	89 121
Ignition Coil SAE; 09.1995->; With regul.cat.(3way)	<b>80211</b>
Ignition Coil Saw tooth; ->08.1995	<b>80212</b>
Ignition Leads 09.1995->	<b>85051</b>
Ignition Leads	<b>85490</b>
<b>Clase C (W202) C 180</b>	<b>1993-00</b>
M 111.921/M 111.920	90 122
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Coil M 111.920,M 111.921	<b>80212</b>
Ignition Leads 09.1995->	<b>85051</b>
<b>Clase C (W202) C 200</b>	<b>1994-00</b>
M 111.945/M 111.941	100 136
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Coil M 111.945,M 111.941	<b>80212</b>
Ignition Leads 09.1995->	<b>85051</b>
Ignition Leads	<b>85490</b>

**MERCEDES-BENZ Cont.**

<b>Clase C (W202) C 200 Kompressor</b>	<b>1995-00</b>
M 111.944	132 180
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase C (W202) C 200 Kompressor</b>	<b>1996-00</b>
M 111.944	141 192
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase C (W202) C 220</b>	<b>1993-00</b>
M 111.961	110 150
Ignition Coil SAE; 09.1995->	<b>80211</b>
Ignition Coil Saw tooth; ->08.1995	<b>80212</b>
<b>Clase C (W202) C 230</b>	<b>1996-97</b>
M 111.974	110 150
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase C (W202) C 230 Kompressor</b>	<b>1995-00</b>
M 111.975	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase C (W202) C 240</b>	<b>1997-00</b>
M 112.910	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C (W202) C 280</b>	<b>1997-00</b>
M 112.920	145 197
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
Ignition Leads	<b>85510</b>
<b>Clase C (W202) C 280</b>	<b>1993-00</b>
M 104.941	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads	<b>85510</b>
<b>Clase C (W202) C 36 AMG</b>	<b>1994-00</b>
M 104.941 (AMG 3.6)	206 280
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Clase C (W202) C 43 AMG</b>	<b>1997-00</b>
M 113.944	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase C (W203) C 180</b>	<b>2000-02</b>
M 111.951	95 129
Ignition Coil	<b>80324</b>
<b>Clase C (W203) C 180 Kompressor</b>	<b>2002-07</b>
M 271.946	105 143
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C (W203) C 200 CGI Kompressor</b>	<b>2003-07</b>
M 271.942	125 170
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C (W203) C 200 Kompressor</b>	<b>2000-02</b>
M 111.955	120 163
Ignition Coil	<b>80324</b>
<b>Clase C (W203) C 200 Kompressor</b>	<b>2002-07</b>
M 271.940	120 163
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C (W203) C 230</b>	<b>2005-07</b>
M 272.920	150 204
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C (W203) C 230 Kompressor</b>	<b>2004-07</b>
M 271.948	141 192
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C (W203) C 240</b>	<b>2000-07</b>
M 112.912	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C (W203) C 240 4-matic</b>	<b>2002-07</b>
M 112.916	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C (W203) C 32 AMG Kompressor</b>	<b>2001-07</b>
M 112.961	260 354
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C (W203) C 320</b>	<b>2000-07</b>
M 112.946	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>

**MERCEDES-BENZ Cont.**

<b>Clase C (W203) C 320 4-matic</b>	<b>2002-07</b>
M 112.953	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C (W203) C 350</b>	<b>2005-07</b>
M 272.960	200 272
Ignition Leads	<b>85053</b>
<b>Clase C (W203) C 350 4-matic</b>	<b>2005-07</b>
M 272.960/M 272.970	200 272
Ignition Leads	<b>85053</b>
<b>Clase C (W203) C 55 AMG</b>	<b>2004-07</b>
M 113.988	270 367
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase C Break (S202) C 180 T</b>	<b>2000-01</b>
M 111.952	95 129
Ignition Coil	<b>80324</b>
<b>Clase C Break (S202) C 180 T</b>	<b>1996-00</b>
M 111.921/M 111.920	90 122
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Coil M 111.920,M 111.921	<b>80212</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase C Break (S202) C 200 T</b>	<b>1996-01</b>
M 111.945/M 111.941	100 136
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Coil M 111.941,M 111.945	<b>80212</b>
Ignition Leads M 111.945	<b>85051</b>
<b>Clase C Break (S202) C 200 T Kompressor</b>	<b>2000-01</b>
M 111.956	120 163
Ignition Coil	<b>80324</b>
<b>Clase C Break (S202) C 200 T Kompressor</b>	<b>1996-01</b>
M 111.944	141 192
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase C Break (S202) C 230 T</b>	<b>1996-98</b>
M 111.974	110 150
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase C Break (S202) C 230 T Kompressor</b>	<b>1997-00</b>
M 111.975	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase C Break (S202) C 240 T</b>	<b>2000-01</b>
M 112.915	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C Break (S202) C 240 T</b>	<b>1997-00</b>
M 112.910	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C Break (S202) C 280 T</b>	<b>1997-01</b>
M 112.920	145 197
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C Break (S202) C 43 AMG</b>	<b>1997-01</b>
M 113.944	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase C Coupe (CI203) C 160 Kompressor</b>	<b>2002-08</b>
M 271.921	90 122
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C Coupe (CI203) C 180</b>	<b>2001-02</b>
M 111.951	95 129
Ignition Coil	<b>80324</b>
<b>Clase C Coupe (CI203) C 180 Kompressor</b>	<b>2002-08</b>
M 271.946	105 143
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C Coupe (CI203) C 200 CGI Kompressor</b>	<b>2003-08</b>
M 271.942	125 170
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C Coupe (CI203) C 200 Kompressor</b>	<b>2001-02</b>
M 111.955	120 163
Ignition Coil	<b>80324</b>
<b>Clase C Coupe (CI203) C 200 Kompressor</b>	<b>2002-08</b>
M 271.940	120 163
Ignition Coil ->11.2006	<b>80292</b>





MERCEDES-BENZ Cont.	
<b>Clase C Coupe (CI203) C 230 Kompressor</b>	<b>2001-02</b>
M 111.981	145 197
Ignition Coil	<b>80324</b>
<b>Clase C Coupe (CI203) C 230 Kompressor</b>	<b>2002-08</b>
M 271.948	141 192
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C Coupe (CI203) C 32 AMG Kompressor</b>	<b>2002-08</b>
M 112.961	260 354
Ignition Coil ->01.2004	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C Coupe (CI203) C 320</b>	<b>2002-08</b>
M 112.946	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C Coupe (CI203) C 350</b>	<b>2005-08</b>
M 272.960	200 272
Ignition Leads	<b>85053</b>
<b>Clase C T-Model (S203) C 180</b>	<b>2001-02</b>
M 111.951	95 129
Ignition Coil	<b>80324</b>
<b>Clase C T-Model (S203) C 180 Kompressor</b>	<b>2002-07</b>
M 271.946	105 143
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C T-Model (S203) C 200 CGI Kompressor</b>	<b>2003-07</b>
M 271.942	125 170
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C T-Model (S203) C 200 Kompressor</b>	<b>2001-02</b>
M 111.955	120 163
Ignition Coil	<b>80324</b>
<b>Clase C T-Model (S203) C 200 Kompressor</b>	<b>2002-07</b>
M 271.940	120 163
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C T-Model (S203) C 230 Kompressor</b>	<b>2004-07</b>
M 271.948	141 192
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase C T-Model (S203) C 240</b>	<b>2001-07</b>
M 112.912	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C T-Model (S203) C 240 4-matic</b>	<b>2002-07</b>
M 112.916	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C T-Model (S203) C 32 AMG Kompressor</b>	<b>2001-07</b>
M 112.961	260 354
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C T-Model (S203) C 320</b>	<b>2001-07</b>
M 112.946	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C T-Model (S203) C 320 4-matic</b>	<b>2002-07</b>
M 112.953	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase C T-Model (S203) C 350</b>	<b>2005-07</b>
M 272.960	200 272
Ignition Leads	<b>85053</b>
<b>Clase C T-Model (S203) C 350 4-matic</b>	<b>2005-07</b>
M 272.970	200 272
Ignition Leads	<b>85053</b>
<b>Clase C T-Model (S203) C 55 AMG</b>	<b>2004-07</b>
M 113.988	270 367
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E (W124) E 200</b>	<b>1993-95</b>
M 111.940	100 136
Ignition Coil M 111.940	<b>80212</b>
<b>Clase E (W124) E 220</b>	<b>1993-95</b>
M 111.960	110 150
Ignition Coil	<b>80212</b>
<b>Clase E (W124) E 280</b>	<b>1993-95</b>
M 104.942	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads	<b>85510</b>
<b>Clase E (W124) E 280</b>	<b>1993-95</b>
M 104.942	145 197
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads	<b>85510</b>

MERCEDES-BENZ Cont.	
<b>Clase E (W124) E 320</b>	<b>1993-95</b>
M 104.992	162 220
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Clase E (W124) E 420</b>	<b>1993-95</b>
M 119.975	205 279
Ignition Leads	<b>85520</b>
<b>Clase E (W124) E 500</b>	<b>1993-95</b>
M 119.974	235 320
Ignition Leads	<b>85520</b>
<b>Clase E (W210) E 200</b>	<b>1995-00</b>
M 111.942	100 136
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase E (W210) E 200 Kompressor</b>	<b>2000-02</b>
M 111.957	120 163
Ignition Coil	<b>80324</b>
<b>Clase E (W210) E 200 Kompressor</b>	<b>1997-02</b>
M 111.947	137 186
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Clase E (W210) E 230</b>	<b>1995-97</b>
M 111.970	110 150
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads 07.1995->	<b>85051</b>
Ignition Leads	<b>85052</b>
<b>Clase E (W210) E 240</b>	<b>2000-02</b>
M 112.914	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E (W210) E 240</b>	<b>1997-00</b>
M 112.911	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E (W210) E 280</b>	<b>1996-97</b>
M 104.945	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads	<b>85510</b>
<b>Clase E (W210) E 280</b>	<b>1996-02</b>
M 112.921	150 204
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
Ignition Leads	<b>85510</b>
<b>Clase E (W210) E 280 4-matic</b>	<b>1996-02</b>
M 112.921	150 204
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
Ignition Leads	<b>85510</b>
<b>Clase E (W210) E 320</b>	<b>1995-97</b>
M 104.995	162 220
Ignition Coil	<b>80211</b>
<b>Clase E (W210) E 320</b>	<b>1997-02</b>
M 112.941	165 224
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E (W210) E 320 4-matic</b>	<b>1997-02</b>
M 112.941	165 224
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E (W210) E 430</b>	<b>1997-02</b>
M 113.940	205 279
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E (W210) E 430 4-matic</b>	<b>1999-02</b>
M 113.940	205 279
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E (W210) E 55 AMG</b>	<b>1997-02</b>
M 113.980	260 354
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E (W210) E 55 AMG 4-matic</b>	<b>2001-02</b>
M 113.980	260 354
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E (W211) E 200 Kompressor</b>	<b>2002-08</b>
M 271.941	120 163
Ignition Coil ->11.2006	<b>80292</b>

**MERCEDES-BENZ Cont.**

<b>Clase E (W211) E 200 Kompressor</b>	<b>2006-08</b>
M 271.956	135 184
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase E (W211) E 240</b>	<b>2002-08</b>
M 112.917/M 112.913	130 177
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E (W211) E 240 4-matic</b>	<b>2003-08</b>
M 112.917	130 177
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E (W211) E 320</b>	<b>2002-08</b>
M 112.949	165 224
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E (W211) E 320 4-matic</b>	<b>2003-08</b>
M 112.954	165 224
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E (W211) E 500</b>	<b>2002-08</b>
M 113.967	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E (W211) E 500</b>	<b>2006-08</b>
M 273.960	285 388
Ignition Leads	<b>85054</b>
<b>Clase E (W211) E 500 4-matic</b>	<b>2003-08</b>
M 113.969	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E (W211) E 500 4-matic</b>	<b>2006-08</b>
M 273.962	285 388
Ignition Leads	<b>85054</b>
<b>Clase E (W211) E 55 AMG Kompressor</b>	<b>2002-08</b>
M 113.990	350 476
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E Break (S124) E 200 T</b>	<b>1993-96</b>
M 111.940	100 136
Ignition Coil M 111.940	<b>80212</b>
<b>Clase E Break (S124) E 220 T</b>	<b>1993-96</b>
M 111.960	110 150
Ignition Coil M 111.960	<b>80212</b>
<b>Clase E Break (S124) E 280 T</b>	<b>1993-96</b>
M 104.942	145 197
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads	<b>85510</b>
<b>Clase E Break (S124) E 280 T</b>	<b>1993-96</b>
M 104.942	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads	<b>85510</b>
<b>Clase E Break (S124) E 320 T</b>	<b>1993-96</b>
M 104.992	162 220
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Clase E Break (S124) E 36 T AMG</b>	<b>1994-96</b>
M 104.992 (AMG 3.6)	200 272
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Clase E Break (S210) E 200 T</b>	<b>1996-00</b>
M 111.942	100 136
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase E Break (S210) E 200 T Kompressor</b>	<b>2000-03</b>
M 111.957	120 163
Ignition Coil	<b>80324</b>
<b>Clase E Break (S210) E 200 T Kompressor</b>	<b>1997-03</b>
M 111.947	137 186
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Clase E Break (S210) E 230 T</b>	<b>1996-97</b>
M 111.970	110 150
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads Without ignition lead	<b>85051</b>
<b>Clase E Break (S210) E 240 T</b>	<b>2000-03</b>
M 112.914	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>

**MERCEDES-BENZ Cont.**

<b>Clase E Break (S210) E 240 T</b>	<b>1997-03</b>
M 112.911	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E Break (S210) E 280 T</b>	<b>1996-03</b>
M 112.921	150 204
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
Ignition Leads	<b>85510</b>
<b>Clase E Break (S210) E 280 T 4-matic</b>	<b>1996-03</b>
M 112.921	150 204
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
Ignition Leads	<b>85510</b>
<b>Clase E Break (S210) E 320 T</b>	<b>1996-03</b>
M 112.941	165 224
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
Ignition Leads	<b>85510</b>
<b>Clase E Break (S210) E 320 T</b>	<b>1996-03</b>
M 112.941	165 224
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase E Break (S210) E 430 T</b>	<b>1997-03</b>
M 113.940	205 279
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E Break (S210) E 430 T 4-matic</b>	<b>1999-03</b>
M 113.940	205 279
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E Break (S210) E 55 T AMG</b>	<b>1997-03</b>
M 113.980	260 354
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E Break (S210) E 55 T AMG 4-matic</b>	<b>2001-03</b>
M 113.980	260 354
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase E Cabriolet (A124) E 200</b>	<b>1993-98</b>
M 111.940	100 136
Ignition Coil SAE; 09.1995->	<b>80211</b>
Ignition Coil Saw tooth; ->08.1995	<b>80212</b>
<b>Clase E Cabriolet (A124) E 220</b>	<b>1993-98</b>
M 111.960	110 150
Ignition Coil SAE; 09.1995->	<b>80211</b>
Ignition Coil Saw tooth; ->08.1995	<b>80212</b>
<b>Clase E Cabriolet (A124) E 320</b>	<b>1993-98</b>
M 104.992	162 220
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Clase E Cabriolet (A124) E 36 AMG</b>	<b>1994-98</b>
M 104.992 (AMG 3.6)	200 272
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Clase E Coupe (C124) E 200</b>	<b>1993-97</b>
M 111.940	100 136
Ignition Coil SAE; 09.1995->	<b>80211</b>
Ignition Coil Saw tooth; ->08.1995	<b>80212</b>
<b>Clase E Coupe (C124) E 220</b>	<b>1993-97</b>
M 111.960	110 150
Ignition Coil SAE; 09.1995->	<b>80211</b>
Ignition Coil Saw tooth; ->08.1995	<b>80212</b>
<b>Clase E Coupe (C124) E 320</b>	<b>1993-97</b>
M 104.992	162 220
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Clase E Coupe (C124) E 36 AMG</b>	<b>1993-95</b>
M 104.992 (AMG 3.6)	195 265
Ignition Coil	<b>80211</b>
<b>Clase E Coupe (C124) E 36 AMG</b>	<b>1994-97</b>
M 104.992 (AMG 3.6)	200 272
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Clase E T-Model (S211) E 200 Kompressor</b>	<b>2006-09</b>
M 271.956	135 184
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase E T-Model (S211) E 200 T Kompressor</b>	<b>2003-09</b>
M 271.941	120 163
Ignition Coil ->11.2006	<b>80292</b>
<b>Clase E T-Model (S211) E 240 T</b>	<b>2003-09</b>
M 112.913	130 177
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>



MERCEDES-BENZ Cont.	
<b>Clase E T-Model (S211) E 240 T 4-matic</b>	2003-09
M 112.917	130 177
Ignition Coil	80294
Ignition Leads	85053
<b>Clase E T-Model (S211) E 320 T</b>	2003-09
M 112.949	165 224
Ignition Coil	80294
Ignition Leads	85053
<b>Clase E T-Model (S211) E 320 T 4-matic</b>	2003-09
M 112.954	165 224
Ignition Coil	80294
Ignition Leads	85053
<b>Clase E T-Model (S211) E 500 T</b>	2003-09
M 113.967	225 306
Ignition Coil	80294
Ignition Leads	85054
<b>Clase E T-Model (S211) E 500 T</b>	2006-09
M 273.960	285 388
Ignition Leads	85054
<b>Clase E T-Model (S211) E 500 T 4-matic</b>	2003-09
M 113.969	225 306
Ignition Coil	80294
Ignition Leads	85054
<b>Clase E T-Model (S211) E 500 T 4-matic</b>	2006-09
M 273.962	285 388
Ignition Leads	85054
<b>Clase E T-Model (S211) E 55 T AMG Kompressor</b>	2003-09
M 113.990	350 476
Ignition Coil	80294
Ignition Leads	85054
<b>Clase G (W460) 230 GE</b>	1982-92
M 102.987/M 102.981/M 102.989	92 125
Ignition Leads SAE	83990
<b>Clase G (W460) 230 Ge 230 GE</b>	1987-92
M 102.979/M 102.987	90 122
Ignition Leads SAE	83990
<b>Clase G (W460) 280 GE</b>	1984-89
M 110.994	110 150
Ignition Leads	85050
<b>Clase G (W461) 230 GE</b>	1993-00
M 102.996/M 102.997	92 125
Ignition Leads SAE	83990
<b>Clase G (W461) 230 GE</b>	1989-96
M 102.979	90 122
Ignition Leads SAE	83990
<b>Clase G (W463) 230 GE</b>	1990-93
M 102.989	93 126
Ignition Leads SAE	83990
<b>Clase G (W463) 300 GE</b>	1990-97
M 103.987	128 174
Ignition Leads	85050
<b>Clase G (W463) 300 GE</b>	1989-93
M 103.987	125 170
Ignition Leads	85050
<b>Clase G (W463) G 320</b>	1994-97
M 104.996	155 211
Ignition Coil With regul.cat.(3way)	80211
<b>Clase G (W463) G 320</b>	1997->
M 112.945	158 215
Ignition Coil	80294
Ignition Leads	85053
<b>Clase G (W463) G 36 AMG</b>	1995-98
M 104.996 (AMG 3.6)	200 272
Ignition Coil With regul.cat.(3way)	80211
<b>Clase G (W463) G 500</b>	1998->
M 113.962	218 296
Ignition Coil	80294
Ignition Leads	85054
<b>Clase G (W463) G 55 AMG</b>	1999->
M 113.982	260 354
Ignition Coil	80294
Ignition Leads	85054
<b>Clase G (W463) G 55 AMG</b>	2004->
M 113.993	350 476
Ignition Coil	80294
Ignition Leads	85054

MERCEDES-BENZ Cont.	
<b>Clase G (W463) G 55 AMG</b>	2006->
M 113.993	368 500
Ignition Coil	80294
Ignition Leads	85054
<b>Clase G (W463) G 55 AMG</b>	2008->
M 113.993	373 507
Ignition Coil	80294
Ignition Leads	85054
<b>Clase G Cabrio (W463) 230 GE</b>	1990-93
M 102.989	93 126
Ignition Leads SAE	83990
<b>Clase G Cabrio (W463) 300 GE</b>	1989-97
M 103.987	125 170
Ignition Leads	85050
<b>Clase G Cabrio (W463) 320 GE</b>	1994-97
M 104.996	155 211
Ignition Coil With regul.cat.(3way)	80211
<b>Clase G Cabrio (W463) G 320</b>	1997->
M 112.945	158 215
Ignition Coil	80294
Ignition Leads	85053
<b>Clase G Cabrio (W463) G 500</b>	1998->
M 113.962	218 296
Ignition Coil	80294
Ignition Leads	85054
<b>Clase M (W163) ML 230</b>	1998-05
M 111.977	110 150
Ignition Coil With regul.cat.(3way)	80211
Ignition Leads	85052
<b>Clase M (W163) ML 320</b>	1998-02
M 112.942	160 218
Ignition Coil	80294
Ignition Leads	85053
<b>Clase M (W163) ML 350</b>	2002-05
M 112.970	180 245
Ignition Coil	80294
Ignition Leads	85053
<b>Clase M (W163) ML 350 4-matic</b>	2003-05
M 112.970	173 235
Ignition Coil	80294
Ignition Leads	85053
<b>Clase M (W163) ML 430</b>	1998-05
M 113.942	200 272
Ignition Coil	80294
Ignition Leads	85054
<b>Clase M (W163) ML 500</b>	2001-05
M 113.964/M 113.965	215 292
Ignition Coil	80294
Ignition Leads	85054
<b>Clase M (W163) ML 55 AMG</b>	2000-05
M 113.981	255 347
Ignition Coil	80294
Ignition Leads	85054
<b>Clase M (W164) ML 500 4-matic</b>	2005-11
M 113.964	225 306
Ignition Coil	80294
Ignition Leads	85054
<b>Clase R (W251, V251) R 500 4-matic</b>	2006->
M 113.960/M 113.971	225 306
Ignition Coil	80294
Ignition Leads	85054
<b>Clase S (W126) 260 SE</b>	1985-91
M 103.941	118 160
Ignition Leads M 103.941	85050
<b>Clase S (W126) 260 SE</b>	1985-91
M 103.941	122 166
Ignition Leads M 103.941	85050
<b>Clase S (W126) 300 SE,SEL</b>	1985-89
M 103.981	138 188
Ignition Leads	85050
<b>Clase S (W140) 300 SE 2.8</b>	1993-98
M 104.944	145 197
Ignition Coil With regul.cat.(3way)	80211
<b>Clase S (W140) 300 SE,SEL/S320</b>	1991-98
M 104.990/M 104.994	170 231
Ignition Coil With regul.cat.(3way)	80211
<b>Clase S (W140) 400 SE,SEL/S420</b>	1991-98
M 119.971	210 286
Ignition Leads	85520

**MERCEDES-BENZ Cont.**

<b>Clase S (W140) 500 SE,SEL</b>	<b>1991-98</b>
M 119.970	240 326
Ignition Leads	<b>85520</b>
<b>Clase S (W140) S 280</b>	<b>1993-98</b>
M 104.944	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Clase S (W220) S 280</b>	<b>1998-05</b>
M 112.922	150 204
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase S (W220) S 320</b>	<b>1998-05</b>
M 112.944	165 224
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase S (W220) S 350</b>	<b>2002-05</b>
M 112.972	180 245
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase S (W220) S 350 4-matic</b>	<b>2003-05</b>
M 112.975	180 245
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Clase S (W220) S 430</b>	<b>1998-05</b>
M 113.941	205 279
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase S (W220) S 430 4-matic</b>	<b>2002-05</b>
M 113.948	205 279
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase S (W220) S 500</b>	<b>1998-05</b>
M 113.960/M 113.966	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase S (W220) S 500 4-matic</b>	<b>2002-05</b>
M 113.966	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase S (W220) S 55 AMG</b>	<b>1999-05</b>
M 113.986	265 360
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase S (W220) S 55 AMG Kompressor</b>	<b>2002-05</b>
M 113.991	368 500
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase S Coupe (C140) SEC/CL 420</b>	<b>1994-99</b>
M 119.971/M 119.981	205 279
Ignition Leads	<b>85520</b>
<b>Clase S Coupe (C140) SEC/CL 500</b>	<b>1992-99</b>
M 119.970	235 320
Ignition Leads	<b>85520</b>
<b>Clase S Coupe (C215) CL 500</b>	<b>1999-06</b>
M 113.960	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase S Coupe (C215) CL 55 AMG</b>	<b>1999-06</b>
M 113.986	265 360
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase S Coupe (C215) CL 55 AMG Kompressor</b>	<b>2002-06</b>
M 113.991	368 500
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Clase V (638/2) V 200</b>	<b>1997-03</b>
M 111.948/M 111.950	95 129
Ignition Coil M 111.948; With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Clase V (638/2) V 230</b>	<b>1996-03</b>
M 111.978	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>CLK (C208) 200</b>	<b>1997-02</b>
M 111.945	100 136
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Coil M 111.941	<b>80212</b>
Ignition Leads M 111.945	<b>85051</b>

**MERCEDES-BENZ Cont.**

<b>CLK (C208) 200 Kompressor</b>	<b>2000-02</b>
M 111.956	120 163
Ignition Coil	<b>80324</b>
<b>CLK (C208) 200 Kompressor</b>	<b>1997-00</b>
M 111.944	141 192
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>CLK (C208) 230 Kompressor</b>	<b>2000-02</b>
M 111.982	145 197
Ignition Coil	<b>80324</b>
<b>CLK (C208) 230 Kompressor</b>	<b>1997-00</b>
M 111.975/M 111.973	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>CLK (C208) 320</b>	<b>1997-02</b>
M 112.940	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>CLK (C208) 430</b>	<b>1998-02</b>
M 113.943	205 279
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLK (C208) 55 AMG</b>	<b>1999-02</b>
M 113.981/M 113.984	255 347
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLK (C209) 200 CGI</b>	<b>2003-09</b>
M 271.942	125 170
Ignition Coil ->11.2006	<b>80292</b>
<b>CLK (C209) 200 Kompressor</b>	<b>2002-09</b>
M 271.940	120 163
Ignition Coil ->11.2006	<b>80292</b>
<b>CLK (C209) 240</b>	<b>2002-09</b>
M 112.912	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>CLK (C209) 320</b>	<b>2002-09</b>
M 112.955	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>CLK (C209) 500</b>	<b>2002-09</b>
M 113.968	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLK (C209) 500</b>	<b>2006-09</b>
M 273.965	285 388
Ignition Leads	<b>85054</b>
<b>CLK (C209) 55 AMG</b>	<b>2002-09</b>
M 113.987	270 367
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLK (C209) DTM AMG</b>	<b>2004-09</b>
M 113.994	428 582
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLK Cabriolet (A208) 200</b>	<b>1998-02</b>
M 111.945/M 111.941	100 136
Ignition Coil M 111.945; With regul.cat.(3way)	<b>80211</b>
Ignition Coil M 111.941	<b>80212</b>
Ignition Leads M 111.945	<b>85051</b>
<b>CLK Cabriolet (A208) 200 Kompressor</b>	<b>2000-02</b>
M 111.956	120 163
Ignition Coil	<b>80324</b>
<b>CLK Cabriolet (A208) 200 Kompressor</b>	<b>1998-00</b>
M 111.944	141 192
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>CLK Cabriolet (A208) 230 Kompressor</b>	<b>2000-02</b>
M 111.982	145 197
Ignition Coil	<b>80324</b>
<b>CLK Cabriolet (A208) 230 Kompressor</b>	<b>1998-00</b>
M 111.975/M 111.973	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads M 111.975	<b>85051</b>
<b>CLK Cabriolet (A208) 320</b>	<b>1998-02</b>
M 112.940	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>





MERCEDES-BENZ Cont.	
<b>CLK Cabriolet (A208) 430</b>	<b>1998-02</b>
M 113.943	205 279
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLK Cabriolet (A208) 55 AMG</b>	<b>2000-02</b>
M 113.981/M 113.984	255 347
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLK Cabriolet (A209) CLK 200 CGI</b>	<b>2003-10</b>
M 271.942	125 170
Ignition Coil ->11.2006	<b>80292</b>
<b>CLK Cabriolet (A209) CLK 200 Kompressor</b>	<b>2003-10</b>
M 271.940	120 163
Ignition Coil ->11.2006	<b>80292</b>
<b>CLK Cabriolet (A209) CLK 240</b>	<b>2003-10</b>
M 112.912	125 170
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>CLK Cabriolet (A209) CLK 320</b>	<b>2003-10</b>
M 112.955	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>CLK Cabriolet (A209) CLK 500</b>	<b>2003-10</b>
M 113.968	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLK Cabriolet (A209) CLK 55 AMG</b>	<b>2003-10</b>
M 113.987	270 367
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLK Cabriolet (A209) CLK AMG DTM</b>	<b>2004-10</b>
M 113.994	428 582
Ignition Coil	<b>80294</b>
<b>CLS (C219) CLS 500</b>	<b>2004-10</b>
M 113.967	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>CLS (C219) CLS 55 AMG</b>	<b>2005-10</b>
M 113.990	350 476
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Coupe (C123) 230 CE</b>	<b>1980-85</b>
M 102.980	100 136
Ignition Leads	<b>83990</b>
<b>Coupe (C124) 220 CE</b>	<b>1992-93</b>
M 111.960	110 150
Ignition Coil M 111.960	<b>80212</b>
Ignition Leads	<b>83990</b>
<b>Coupe (C124) 230 CE</b>	<b>1987-92</b>
M 102.982	97 132
Ignition Leads SAE	<b>83990</b>
<b>Coupe (C124) 230 CE</b>	<b>1987-92</b>
M 102.982	100 136
Ignition Leads SAE	<b>83990</b>
<b>Coupe (C124) 230 CE KAT</b>	<b>1989-92</b>
M 102.982	97 132
Ignition Leads SAE	<b>83990</b>
<b>Coupe (C124) 300 CE</b>	<b>1987-93</b>
M 103.983	132 180
Ignition Leads	<b>85050</b>
<b>Coupe (C124) 300 CE-24</b>	<b>1989-92</b>
M 104.980	162 220
Ignition Leads	<b>85500</b>
<b>Coupe (C124) 320 CE</b>	<b>1992-93</b>
M 104.992	162 220
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Kombi Break (S123) 200 T</b>	<b>1980-85</b>
M 102.939	74 101
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S123) 200 T</b>	<b>1980-85</b>
M 102.920	80 109
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S123) 230 TE</b>	<b>1980-85</b>
M 102.980	100 136
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S123) 250 T</b>	<b>1978-82</b>
M 123.921	103 140
Ignition Leads	<b>85050</b>

MERCEDES-BENZ Cont.	
<b>Kombi Break (S123) 280 TE</b>	<b>1977-85</b>
M 110.988	136 185
Ignition Leads 01.1983->	<b>85050</b>
<b>Kombi Break (S124) 200 T</b>	<b>1986-90</b>
M 102.922	77 105
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S124) 200 T</b>	<b>1985-89</b>
M 102.922	80 109
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S124) 200 TE</b>	<b>1986-93</b>
M 111.940	100 136
Ignition Coil M 111.940	<b>80212</b>
Ignition Leads	<b>83990</b>
<b>Kombi Break (S124) 200 TE</b>	<b>1988-92</b>
M 102.963	87 118
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S124) 200 TE</b>	<b>1988-89</b>
M 102.962	90 122
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S124) 220 TE</b>	<b>1992-93</b>
M 111.960	110 150
Ignition Coil M 111.960	<b>80212</b>
Ignition Leads	<b>83990</b>
<b>Kombi Break (S124) 230 TE</b>	<b>1985-92</b>
M 102.982	97 132
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S124) 230 TE</b>	<b>1985-92</b>
M 102.982	100 136
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S124) 230 TE KAT</b>	<b>1989-92</b>
M 102.982	97 132
Ignition Leads SAE	<b>83990</b>
<b>Kombi Break (S124) 260 TE FGST.</b>	<b>1989-92</b>
M 103.940	118 160
Ignition Leads	<b>85050</b>
<b>Kombi Break (S124) 260 TE FGST.</b>	<b>1985-89</b>
M 103.940	122 166
Ignition Leads M 103.940	<b>85050</b>
<b>Kombi Break (S124) 280 TE</b>	<b>1992-93</b>
M 104.942	145 197
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Kombi Break (S124) 300 TE</b>	<b>1986-92</b>
M 103.983	132 180
Ignition Leads	<b>85050</b>
<b>Kombi Break (S124) 300 TE</b>	<b>1986-89</b>
M 103.983	138 188
Ignition Leads	<b>85050</b>
<b>Kombi Break (S124) 300 TE 4-matic</b>	<b>1986-93</b>
M 103.985	132 180
Ignition Leads	<b>85050</b>
<b>Kombi Break (S124) 300 TE 4-matic</b>	<b>1986-89</b>
M 103.983	138 188
Ignition Leads	<b>85050</b>
<b>Kombi Break (S124) 300 TE-24</b>	<b>1989-92</b>
M 104.980	162 220
Ignition Leads	<b>85500</b>
<b>Kombi Break (S124) 320 TE</b>	<b>1992-93</b>
M 104.992	162 220
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Sedan (W123) 200</b>	<b>1980-85</b>
M 102.939	74 101
Ignition Leads SAE	<b>83990</b>
<b>Sedan (W123) 200</b>	<b>1980-85</b>
M 102.920	80 109
Ignition Leads SAE	<b>83990</b>
<b>Sedan (W123) 280 E</b>	<b>1976-85</b>
M 110.988/M 110.984	136 185
Ignition Leads 01.1983->	<b>85050</b>
<b>Sedan (W124) 200</b>	<b>1986-90</b>
M 102.922	75 102
Ignition Leads SAE	<b>83990</b>
<b>Sedan (W124) 200</b>	<b>1985-90</b>
M 102.922	80 109
Ignition Leads SAE	<b>83990</b>



**MERCEDES-BENZ Cont.**

<b>Sedan (W124) 200</b>	<b>1986-90</b>
M 102.922	77 105
Ignition Leads SAE	<b>83990</b>
<b>Sedan (W124) 200 E</b>	<b>1988-92</b>
M 102.963	87 118
Ignition Leads SAE	<b>83990</b>
<b>Sedan (W124) 200 E</b>	<b>1988-89</b>
M 102.963	90 122
Ignition Leads SAE	<b>83990</b>
<b>Sedan (W124) 200 E</b>	<b>1992-93</b>
M 111.940	100 136
Ignition Coil M 111.940	<b>80212</b>
Ignition Leads	<b>83990</b>
<b>Sedan (W124) 220 E</b>	<b>1992-93</b>
M 111.960	110 150
Ignition Coil M 111.960	<b>80212</b>
Ignition Leads	<b>83990</b>
<b>Sedan (W124) 230 E</b>	<b>1984-92</b>
M 102.982	97 132
Ignition Leads SAE	<b>83990</b>
<b>Sedan (W124) 230 E</b>	<b>1985-93</b>
M 102.982	100 136
Ignition Leads SAE	<b>83990</b>
<b>Sedan (W124) 230 E KAT</b>	<b>1989-93</b>
M 102.982	97 132
Ignition Leads SAE	<b>83990</b>
<b>Sedan (W124) 260 E</b>	<b>1985-92</b>
M 103.940	118 160
Ignition Leads M 103.940	<b>85050</b>
<b>Sedan (W124) 260 E</b>	<b>1985-89</b>
M 103.940	122 166
Ignition Leads	<b>85050</b>
<b>Sedan (W124) 260 E 4-matic</b>	<b>1986-92</b>
M 103.943	118 160
Ignition Leads	<b>85050</b>
<b>Sedan (W124) 260 E 4-matic</b>	<b>1986-89</b>
M 103.940	122 166
Ignition Leads	<b>85050</b>
<b>Sedan (W124) 280 E</b>	<b>1992-93</b>
M 104.942	145 197
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Sedan (W124) 300 E</b>	<b>1985-85</b>
M 103.980	138 188
Ignition Leads	<b>85050</b>
<b>Sedan (W124) 300 E</b>	<b>1985-92</b>
M 103.983	132 180
Ignition Leads	<b>85050</b>
<b>Sedan (W124) 300 E</b>	<b>1985-92</b>
M 103.983	138 188
Ignition Leads	<b>85050</b>
<b>Sedan (W124) 300 E 4-matic</b>	<b>1986-93</b>
M 103.985	132 180
Ignition Leads	<b>85050</b>
<b>Sedan (W124) 300 E 4-matic</b>	<b>1986-92</b>
M 103.983	138 188
Ignition Leads	<b>85050</b>
<b>Sedan (W124) 300 E-24</b>	<b>1988-92</b>
M 104.980	162 220
Ignition Leads	<b>85500</b>
<b>Sedan (W124) 320 E</b>	<b>1992-93</b>
M 104.992	162 220
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Sedan (W124) 400 E 4.2</b>	<b>1992-93</b>
M 119.975	205 279
Ignition Leads	<b>85520</b>
<b>Sedan (W124) 500 E</b>	<b>1991-93</b>
M 119.974	240 326
Ignition Leads	<b>85520</b>
<b>SL (R107) 300 SL</b>	<b>1985-89</b>
M 103.982	132 180
Ignition Leads	<b>85050</b>
<b>SL (R107) 300 SL</b>	<b>1985-89</b>
M 103.982	138 188
Ignition Leads	<b>85050</b>
<b>SL (R129) 280</b>	<b>1993-01</b>
M 104.943	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>

**MERCEDES-BENZ Cont.**

<b>SL (R129) 280</b>	<b>1998-01</b>
M 112.923	150 204
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>SL (R129) 300 SL</b>	<b>1989-93</b>
M 103.984	140 190
Ignition Leads	<b>85500</b>
<b>SL (R129) 300 SL-24</b>	<b>1989-93</b>
M 104.981	170 231
Ignition Leads	<b>85500</b>
<b>SL (R129) 320</b>	<b>1993-01</b>
M 104.991	170 231
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>SL (R129) 320</b>	<b>1998-01</b>
M 112.943	165 224
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>SL (R129) 500</b>	<b>1992-01</b>
M 119.982/M 119.972	235 320
Ignition Leads	<b>85520</b>
<b>SL (R129) 500</b>	<b>1998-01</b>
M 113.961	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>SL (R129) 500 SL</b>	<b>1989-92</b>
M 119.960/M 119.972	240 326
Ignition Leads	<b>85520</b>
<b>SL (R129) 55 AMG</b>	<b>2000-01</b>
M 113.985	260 354
Ignition Leads	<b>85054</b>
<b>SL (R230) 350</b>	<b>2003-12</b>
M 112.973	180 245
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>SL (R230) 500</b>	<b>2001-12</b>
M 113.963	225 306
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>SL (R230) 500</b>	<b>2006-12</b>
M 273.965	285 388
Ignition Leads	<b>85054</b>
<b>SL (R230) 55 AMG</b>	<b>2001-02</b>
M 113.992	350 476
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>SL (R230) 55 AMG</b>	<b>2006-12</b>
M 113.995	380 517
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>SL (R230) 55 AMG Kompressor</b>	<b>2002-12</b>
M 113.992	368 500
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>SLK (R170) 200</b>	<b>1996-00</b>
M 111.946	100 136
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>SLK (R170) 200 Kompressor</b>	<b>2000-04</b>
M 111.958	120 163
Ignition Coil	<b>80324</b>
Ignition Leads	<b>85052</b>
<b>SLK (R170) 200 Kompressor</b>	<b>1996-00</b>
M 111.943	141 192
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>SLK (R170) 230 Kompressor</b>	<b>2000-04</b>
M 111.983	145 197
Ignition Coil	<b>80324</b>
<b>SLK (R170) 230 Kompressor</b>	<b>1996-00</b>
M 111.973	142 193
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>SLK (R170) 32 AMG Kompressor</b>	<b>2001-04</b>
M 112.960	260 354
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>



MERCEDES-BENZ Cont.	
<b>SLK (R170) 320</b>	2000-04
M 112.947	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>SLK (R171) 200 Kompressor</b>	2004-11
M 271.944	120 163
Ignition Coil ->11.2006	<b>80292</b>
<b>SLK (R171) 55 AMG</b>	2004-11
M 113.989	265 360
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>SLR (R199) 5,4</b>	2004->
M 155.980	460 626
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>SLR (R199) 5.4 722 Edition</b>	2006->
M 155.980	478 650
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>SLR Roadster (R199) 5.4</b>	2007->
M 155.980	460 626
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>SLR Roadster (R199) 5.4</b>	2006->
M 155.980	478 650
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85054</b>
<b>Sprinter 2-T Bus (901, 902) 214</b>	1995-06
M 111.979	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 2-T Bus (901, 902) 214 NGT</b>	2000-06
M 111.984	92 125
Ignition Coil	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Sprinter 2-T Chassis (901, 902) 214</b>	1995-06
M 111.979	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 2-T Chassis (901, 902) 214 NGT</b>	2000-06
M 111.984	92 125
Ignition Coil	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Sprinter 2-T Van (901, 902) 214</b>	1995-06
M 111.979/M 111.984	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 2-T Van (901, 902) 214 NGT</b>	2000-06
M 111.984	92 125
Ignition Coil	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Sprinter 3-T Bus (903) 314</b>	1995-06
M 111.984	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 3-T Bus (903) 314 4x4</b>	2002-06
M 111.984	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads Without ignition lead	<b>85051</b>
<b>Sprinter 3-T Bus (903) 314 NGT</b>	2000-06
M 111.984	92 125
Ignition Coil	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Sprinter 3-T Chassis (903) 314</b>	1995-06
M 111.984	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 3-T Chassis (903) 314 4x4</b>	2002-06
M 111.984	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 3-T Chassis (903) 314 NGT</b>	2000-06
M 111.984	92 125
Ignition Coil	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Sprinter 3-T Van (903) 314</b>	1995-06
M 111.979/M 111.984	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>

MERCEDES-BENZ Cont.	
<b>Sprinter 3-T Van (903) 314 4x4</b>	2002-06
M 111.984	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 3-T Van (903) 314 NGT</b>	2000-06
M 111.984	92 125
Ignition Coil	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Sprinter 4-T Bus (904) 414</b>	1996-06
M 111.979	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 4-T Chassis (904) 414</b>	1996-06
M 111.979/M 111.984	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 4-T Chassis (904) 414 4x4</b>	1997-06
M 111.979	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 4-T Van (904) 414</b>	1996-06
M 111.979	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Sprinter 4-T Van (904) 414 4x4</b>	1997-06
M 111.979	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Vaneo (414) 1,6</b>	2002-05
M 166.961	75 102
Ignition Coil	<b>80325</b>
<b>Vaneo (414) 1,6</b>	2002-05
M 166.961	60 82
Ignition Coil	<b>80325</b>
<b>Vaneo (414) 1,9</b>	2002-05
M 166.991	92 125
Ignition Coil	<b>80325</b>
<b>Viano (W639) 3,0</b>	2003->
M 112.951	140 190
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Viano (W639) 3.2</b>	2003->
M 112.951	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Viano (W639) 3.7</b>	2004->
M 112.976	170 231
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Vito / Mixto Van (W639) 119</b>	2003->
M 112.951	140 190
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Vito / Mixto Van (W639) 122</b>	2003->
M 112.951	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Vito / Mixto Van (W639) 123</b>	2004-08
M 112.976	170 231
Ignition Coil	<b>80294</b>
<b>Vito Bus (638) 113 2.0</b>	1996-03
M 111.948/M 111.950	95 129
Ignition Coil M 111.948; With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Vito Bus (638) 114 2.3</b>	1996-03
M 111.978	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Vito Bus (W639) 119</b>	2003->
M 112.951	140 190
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Vito Bus (W639) 122</b>	2003->
M 112.951	160 218
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>

**MERCEDES-BENZ Cont.**

<b>Vito Bus (W639) 123</b>	<b>2004-&gt;</b>
M 112.976	170 231
Ignition Coil	<b>80294</b>
Ignition Leads	<b>85053</b>
<b>Vito Van (638) 113 2.0</b>	<b>1997-03</b>
M 111.948/M 111.950	95 129
Ignition Coil M 111.948; With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Vito Van (638) 114 2.3</b>	<b>1997-03</b>
M 111.978	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>

**MG**

<b>1300 MKII 1300</b>	<b>1967-70</b>
	52 71
Ignition Leads	<b>83850</b>
<b>Metro 1300</b>	<b>1982-90</b>
12 H	54 73
Ignition Leads	<b>83850</b>
<b>Metro Turbo</b>	<b>1982-90</b>
12 HC	69 94
Ignition Leads	<b>83850</b>
<b>MG TF 115</b>	<b>2002-09</b>
16 K4F	85 116
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85765</b>
<b>MG TF 120</b>	<b>2002-09</b>
18 K4F	88 120
Ignition Coil	<b>80254</b>
Ignition Leads ->05.2005; Manual gear	<b>85765</b>
Ignition Leads ->05.2005; Automatic transmission	<b>85766</b>
<b>MG TF 135</b>	<b>2002-09</b>
18 K4F	100 136
Ignition Coil	<b>80254</b>
Ignition Leads Manual gear	<b>85765</b>
Ignition Leads Automatic transmission	<b>85766</b>
<b>MG TF 160</b>	<b>2002-09</b>
18 K4K	118 160
Ignition Leads	<b>85764</b>
<b>MG ZR 105</b>	<b>2001-05</b>
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads ->Ch.YD 471564	<b>85765</b>
Ignition Leads Ch.YD 471565->	<b>85766</b>
<b>MG ZR 120</b>	<b>2001-05</b>
18 K4F	86 117
Ignition Coil	<b>80254</b>
Ignition Leads ->Ch.YD 471564	<b>85765</b>
Ignition Leads Ch.YD 471565->	<b>85766</b>
<b>MG ZR 160</b>	<b>2001-05</b>
18 K4K	118 160
Ignition Leads	<b>85764</b>
Ignition Leads ->Ch.YD 471564; 10.2001->	<b>85765</b>
Ignition Leads Ch.YD 471565->	<b>85766</b>
<b>MG ZS 120</b>	<b>2001-05</b>
18 K4F	86 117
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>MG ZS 180</b>	<b>2001-05</b>
25 K4F	130 177
Ignition Coil	<b>80216</b>
Ignition Leads ->Ch.YD 471564	<b>85765</b>
Ignition Leads Ch.YD 471565->	<b>85766</b>
Ignition Leads	<b>85768</b>
<b>MG ZS Hatchback 120</b>	<b>2001-05</b>
18 K4F	86 117
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>MG ZS Hatchback 180</b>	<b>2001-05</b>
25 K4F	130 177
Ignition Coil	<b>80216</b>
Ignition Leads	<b>85765</b>
Ignition Leads Ch.YD 471565->; 10.2001-05.2005	<b>85766</b>
Ignition Leads	<b>85768</b>

**MG Cont.**

<b>MG ZT 1.8 16V</b>	<b>2003-05</b>
18 K4F	88 120
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>MG ZT 1.8 T 16V</b>	<b>2003-05</b>
18 K4G	118 160
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>MG ZT 160</b>	<b>2001-05</b>
25 K4F	118 160
Ignition Coil 25 K4F	<b>80216</b>
<b>MG ZT 180</b>	<b>2003-05</b>
25 K4F	130 177
Ignition Coil	<b>80216</b>
Ignition Leads	<b>85768</b>
<b>MG ZT 190</b>	<b>2001-05</b>
25 K4F	140 190
Ignition Coil 25 K4F	<b>80216</b>
<b>MG ZT- T 1.8 16V</b>	<b>2003-05</b>
18 K4F	88 120
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>MG ZT- T 1.8 T 16V</b>	<b>2003-05</b>
18 K4G	118 160
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>MG ZT- T 160</b>	<b>2001-05</b>
25 K4F	118 160
Ignition Coil 25 K4F	<b>80216</b>
<b>MG ZT- T 180</b>	<b>2003-05</b>
25 K4F	130 177
Ignition Coil	<b>80216</b>
Ignition Leads	<b>85768</b>
<b>MG ZT- T 190</b>	<b>2001-05</b>
25 K4F	140 190
Ignition Coil 25 K4F	<b>80216</b>
<b>MGB GT 1.8</b>	<b>1965-80</b>
18G	68 92
Ignition Leads	<b>83850</b>
<b>MGB GT 1.8</b>	<b>1965-80</b>
18G	70 95
Ignition Leads	<b>83850</b>
<b>MGF (RD) 1,8 i VVC</b>	<b>2001-02</b>
18 K4K	118 160
Ignition Leads ->Ch.YD 522572	<b>85765</b>
Ignition Leads Ch.YD 522573->	<b>85766</b>
<b>MGF (RD) 1.6</b>	<b>2000-02</b>
16 K4F	82 111
Ignition Coil	<b>80254</b>
Ignition Leads ->Ch.YD 522572; 10.2001->	<b>85765</b>
Ignition Leads Ch.YD 522573->; 10.2001->	<b>85766</b>
<b>MGF (RD) 1.8 i 16V</b>	<b>1995-02</b>
18 K4F	88 120
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85765</b>
Ignition Leads Ch.YD 522573->; 10.1995->	<b>85766</b>
<b>MGF (RD) 1.8 i VVC</b>	<b>1995-02</b>
18 K4K	107 146
Ignition Leads	<b>85764</b>
Ignition Leads ->Ch.YD 522572; 10.1995->	<b>85765</b>
Ignition Leads Ch.YD 522573->; 10.1995->	<b>85766</b>

**MINI**

<b>Mini (R50, R53) Cooper</b>	<b>2001-06</b>
W10 B16 A	85 116
Ignition Coil	<b>80349</b>
Ignition Leads	<b>83985</b>
<b>Mini (R50, R53) Cooper S</b>	<b>2002-06</b>
W11 B16 A	120 163
Ignition Coil	<b>80349</b>
Ignition Leads W11B16A	<b>83985</b>
<b>Mini (R50, R53) Cooper S</b>	<b>2004-06</b>
W11 B16 A	125 170
Ignition Coil	<b>80349</b>
Ignition Leads W11B16A	<b>83985</b>
<b>Mini (R50, R53) John Cooper Works</b>	<b>2006-06</b>
W11 B16 A	160 218
Ignition Coil	<b>80349</b>



MINI Cont.	
<b>Mini (R50, R53) One</b>	2001-06
W10 B16 A	66 90
Ignition Coil	80349
Ignition Leads	83985
<b>Mini (R50, R53) One</b>	2003-06
W10 B14 A	55 75
Ignition Coil	80349
<b>Mini (R50, R53) S Works</b>	2003-05
W11 B16 A	147 200
Ignition Coil	80349
<b>Mini (R50, R53) Works</b>	2003-06
W11 B16 A	155 210
Ignition Coil	80349
Ignition Leads 08.2004->	83985
<b>Mini (R56) Cooper</b>	2006-12
N12 B16 A	88 120
Ignition Coil	80247
<b>Mini (R56) Cooper</b>	2009-13
N16 B16 A/N12 B16 A	90 122
Ignition Coil	80247
<b>Mini (R56) Cooper</b>	2010->
N16 B16 A/N12 B16 A	85 115
Ignition Coil	80247
<b>Mini (R56) Cooper S</b>	2006-11
N14 B16 A	128 174
Ignition Coil	80247
<b>Mini (R56) Cooper S</b>	2010-13
N18 B16 A	135 184
Ignition Coil	80247
<b>Mini (R56) John Cooper Works</b>	2007-13
N14 B16 C/N18 B16 C	155 211
Ignition Coil	80247
<b>Mini (R56) One</b>	2006-10
N12 B14 A	70 95
Ignition Coil	80247
<b>Mini (R56) One</b>	2009-10
N12 B14 A	55 75
Ignition Coil	80247
<b>Mini (R56) One</b>	2010-13
N16 B16 A	55 75
Ignition Coil	80247
<b>Mini (R56) One</b>	2010-13
N16 B16 A	72 98
Ignition Coil	80247
<b>Mini Cabriolet (R52) Cooper</b>	2004-07
W10 B16 A	85 116
Ignition Coil	80349
Ignition Leads 08.2004-11.2006	83985
<b>Mini Cabriolet (R52) Cooper S</b>	2004-07
W11 B16 A	125 170
Ignition Coil	80349
Ignition Leads	83985
<b>Mini Cabriolet (R52) Cooper S</b>	2004-07
W11 B16 A	120 163
Ignition Coil	80349
<b>Mini Cabriolet (R52) John Cooper Works</b>	2004-07
W11 B16 A	155 210
Ignition Coil	80349
Ignition Leads	83985
<b>Mini Cabriolet (R52) One</b>	2004-07
W10 B16 A	66 90
Ignition Coil	80349
Ignition Leads	83985
<b>Mini Cabriolet (R57) Cooper</b>	2009->
N16 B16 A	85 116
Ignition Coil	80247
<b>Mini Cabriolet (R57) Cooper</b>	2007-15
N12 B16 A	88 120
Ignition Coil	80247
<b>Mini Cabriolet (R57) Cooper</b>	2009-15
N16 B16 A/N12 B16 A	90 122
Ignition Coil	80247
<b>Mini Cabriolet (R57) Cooper S</b>	2007-10
N14 B16 A	128 174
Ignition Coil	80247
<b>Mini Cabriolet (R57) Cooper S</b>	2009-15
N18 B16 A	135 184
Ignition Coil	80247

MINI Cont.	
<b>Mini Cabriolet (R57) John Cooper Works</b>	2008-15
N14 B16 C/N18 B16 C	155 211
Ignition Coil	80247
<b>Mini Cabriolet (R57) One</b>	2009-15
N16 B16 A	72 98
Ignition Coil	80247
<b>Mini Clubman (R55) Cooper</b>	2010->
N16 B16 A	85 115
Ignition Coil	80247
<b>Mini Clubman (R55) Cooper</b>	2007-13
N16 B16 A/N12 B16 A	88 120
Ignition Coil	80247
<b>Mini Clubman (R55) Cooper</b>	2010-14
N16 B16 A	90 122
Ignition Coil	80247
<b>Mini Clubman (R55) Cooper S</b>	2007-10
N14 B16 A	120 163
Ignition Coil	80247
<b>Mini Clubman (R55) Cooper S</b>	2007-10
N14 B16 A	128 174
Ignition Coil	80247
<b>Mini Clubman (R55) John Cooper Works</b>	2007-14
N14 B16 C/N18 B16 C	155 211
Ignition Coil	80247
<b>Mini Clubman (R55) One</b>	2010-14
N16 B16 A	72 98
Ignition Coil	80247
<b>Mini Clubman (R55) One</b>	2009-10
N12 B14 A	70 95
Ignition Coil	80247
<b>Mini Clubvan (R55) Cooper</b>	2012->
N16 B16 A	90 122
Ignition Coil	80247
<b>Mini Clubvan (R55) One</b>	2012->
N16 B16 A	72 98
Ignition Coil	80247
<b>Mini Countryman (R60) Cooper</b>	2010->
N16 B16 A	85 115
Ignition Coil	80247
<b>Mini Countryman (R60) Cooper</b>	2010-16
N16 B16 A	90 122
Ignition Coil	80247
<b>Mini Countryman (R60) Cooper ALL4</b>	2012-16
N16 B16 A	90 122
Ignition Coil	80247
<b>Mini Countryman (R60) Cooper S</b>	2010-16
N18 B16 A	135 184
Ignition Coil	80247
<b>Mini Countryman (R60) Cooper S ALL4</b>	2010-16
N14 B16 A/N18 B16 A	135 184
Ignition Coil	80247
<b>Mini Countryman (R60) One</b>	2010-16
N16 B16 A	72 98
Ignition Coil	80247
<b>Mini Coupe (R58) Cooper</b>	2010-15
N16 B16 A	90 122
Ignition Coil	80247
<b>Mini Coupe (R58) Cooper</b>	2011->
N16 B16 A	85 115
Ignition Coil	80247
<b>Mini Paceman (R61) Cooper</b>	2012->
N16 B16 A	90 122
Ignition Coil	80247
<b>Mini Paceman (R61) Cooper ALL4</b>	2013-16
N16 B16 A	90 122
Ignition Coil	80247
<b>Mini Roadster (R59) Cooper</b>	2012->
N16 B16 A	90 122
Ignition Coil	80247
<b>Mini Roadster (R59) Cooper</b>	2012->
N16 B16 A	85 115
Ignition Coil	80247



MITSUBISHI	
<b>ASX (GAW) 1.8</b>	2010->
4B10	102 139
Ignition Coil	<b>80338</b>
<b>ASX (GAW) 2.0 i</b>	2010->
4B11	110 150
Ignition Coil	<b>80338</b>
<b>ASX (GAW) 2.0 i 4WD</b>	2010->
4B11	110 150
Ignition Coil	<b>80338</b>
<b>Carisma (DA) 1,6</b>	1998-06
4G92 (SOHC 16V)	70 95
Ignition Coil	<b>80346</b>
<b>Carisma (DA) 1,6</b>	2000-06
4G92 (SOHC 16V)	76 103
Ignition Coil	<b>80346</b>
<b>Carisma (DA) 1,6</b>	1995-06
4G92 (SOHC 16V)	66 90
Ignition Coil	<b>80346</b>
Ignition Leads ->04.1997	<b>85381</b>
<b>Carisma (DA) 1,6</b>	1997-06
4G92 (SOHC 16V)	73 99
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85381</b>
<b>Carisma (DA) 1,8</b>	1995-97
4G93 (SOHC 16V)	85 116
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85382</b>
<b>Carisma (DA) 1.8 GDI</b>	2000-06
4G93 (GDI)	90 122
Ignition Leads	<b>85381</b>
<b>Carisma Sedan (DA) 1,6</b>	1998-06
4G92 (SOHC 16V)	70 95
Ignition Coil	<b>80346</b>
<b>Carisma Sedan (DA) 1,6</b>	2000-06
4G92 (SOHC 16V)	76 103
Ignition Coil	<b>80346</b>
<b>Carisma Sedan (DA) 1,6</b>	1996-06
4G92 (SOHC 16V)	66 90
Ignition Coil	<b>80346</b>
Ignition Leads ->04.1997	<b>85381</b>
<b>Carisma Sedan (DA) 1,6</b>	1997-06
4G92 (SOHC 16V)	73 99
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85381</b>
<b>Carisma Sedan (DA) 1,8</b>	1996-97
4G93 (SOHC 16V)	85 115
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85382</b>
<b>Carisma Sedan (DA) 1.3 12V (DA6A)</b>	2000-04
4G13 (12V)	55 75
Ignition Coil	<b>80365</b>
<b>Carisma Sedan (DA) 1.8 16V GDI</b>	1997-06
4G93 (GDI)	92 125
Ignition Leads	<b>85381</b>
<b>Celeste (A7) 2.0 GSR</b>	1975-81
4G52	66 90
Ignition Leads	<b>85380</b>
<b>Colt CZC Cabriolet (RG) 1.5</b>	2006-09
4A91	80 109
Ignition Coil	<b>80339</b>
<b>Colt I (A15A) 1.2 GL</b>	1978-84
4G11	40 55
Ignition Leads	<b>86030</b>
<b>Colt I (A15A) 1.4 GLX,GT</b>	1979-84
4G12	51 70
Ignition Leads	<b>85380</b>
<b>Colt I (A15A) 1.4 Turbo</b>	1981-84
4G12 T	77 105
Ignition Leads	<b>85380</b>
<b>Colt III (C5A) 1.5 GLXi</b>	1988-92
4G15 (8V)	62 84
Ignition Leads	<b>86030</b>
<b>Colt III (C5A) 1.5 KAT</b>	1990-92
4G15 (12V)	66 90
Ignition Leads	<b>86030</b>
<b>Colt III (C5A) 1.6 GTi 16V</b>	1988-90
4G61	91 124
Ignition Leads	<b>85999</b>

MITSUBISHI Cont.	
<b>Colt III (C5A) 1.8 GTi 16V KAT</b>	1990-92
4G67	100 136
Ignition Leads	<b>85999</b>
<b>Colt IV (CAA) 1,6</b>	1994-96
4G92 (SOHC 16V)	66 90
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85381</b>
<b>Colt IV (CAA) 1.3 GLi 12V</b>	1992-96
4G13 (12V)	55 75
Ignition Leads	<b>85379</b>
<b>Colt IV (CAA) 1.6 4WD</b>	1993-95
4G92	84 114
Ignition Leads	<b>85381</b>
<b>Colt IV (CAA) 1.6 GLXi 16V</b>	1992-96
4G92 (SOHC 16V)	83 113
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85381</b>
<b>Colt IV (CAA) 1.8 GTi 16V</b>	1992-96
4G93 (DOHC 16V)	103 140
Ignition Leads	<b>85999</b>
<b>Colt V (CJ, CP) 1300</b>	2000-03
4G13 (16V)	60 82
Ignition Coil	<b>80365</b>
Ignition Leads	<b>85382</b>
Ignition Leads	<b>85383</b>
<b>Colt V (CJ, CP) 1300 GL, GLX</b>	1996-00
4G13 (12V)	55 75
Ignition Coil ->05.2000	<b>80253</b>
Ignition Coil 06.2000->	<b>80365</b>
Ignition Leads	<b>85379</b>
Ignition Leads 06.2000->	<b>85382</b>
<b>Colt V (CJ, CP) 1500</b>	1999-03
4G15 (16V)	69 94
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85379</b>
<b>Colt V (CJ, CP) 1600</b>	2000-03
4G92 (SOHC 16V)	76 103
Ignition Coil	<b>80346</b>
<b>Colt V (CJ, CP) 1600 GLX</b>	1996-00
4G92 (SOHC 16V)	66 90
Ignition Coil	<b>80346</b>
<b>Colt VI (Z3A, Z2A) 1.1</b>	2004-12
3A91	55 75
Ignition Coil ->06.2010	<b>80339</b>
<b>Colt VI (Z3A, Z2A) 1.1 LPG</b>	2004-12
3A91	55 75
Ignition Coil ->06.2010	<b>80339</b>
<b>Colt VI (Z3A, Z2A) 1.3</b>	2004-12
4A90	70 95
Ignition Coil ->06.2010	<b>80339</b>
<b>Colt VI (Z3A, Z2A) 1.3</b>	2004-12
4A90	68 92
Ignition Coil ->06.2010	<b>80339</b>
<b>Colt VI (Z3A, Z2A) 1.3 4WD</b>	2004-12
4A90	67 91
Ignition Coil ->06.2010	<b>80339</b>
<b>Colt VI (Z3A, Z2A) 1.3 LPG</b>	2004-12
4A90	70 95
Ignition Coil ->06.2010	<b>80339</b>
<b>Colt VI (Z3A, Z2A) 1.5</b>	2004-12
4A91	80 109
Ignition Coil	<b>80339</b>
<b>Cordia (A21A, AB) 1.6 GSL</b>	1982-86
4G32	55 75
Ignition Leads	<b>85350</b>
<b>Cordia (A21A, AB) 1.6 Turbo</b>	1982-85
4G32 T	84 114
Ignition Leads	<b>85350</b>
<b>Cordia (A21A, AB) 1.6 Turbo</b>	1983-85
4G32 T	85 116
Ignition Leads	<b>85350</b>
<b>Eclipse I (D2A) 2.0 i 16V</b>	1991-95
4G63 (DOHC 16V)	110 150
Ignition Coil	<b>80295</b>
Ignition Leads	<b>85999</b>
<b>Eclipse I (D2A) 2.0 i 16V 4WD</b>	1991-95
4G63 (DOHC 16V)	110 150
Ignition Leads	<b>85999</b>





MITSUBISHI Cont.	
<b>Eclipse II (D3A) 2000 GS 16V</b>	<b>1995-99</b>
4G63 (DOHC 16V)	107 146
Ignition Leads	<b>85999</b>
<b>Eclipse II (D3A) 2000 GT 16V</b>	<b>1995-99</b>
4G63 T (DOHC 16V)	157 214
Ignition Coil	<b>80295</b>
Ignition Leads	<b>85999</b>
<b>Eclipse II (D3A) 2400 GS 16V</b>	<b>1998-99</b>
4G64 (SOHC 16V)	105 143
Ignition Coil	<b>80296</b>
<b>Galant I Station Wagon (A12V) 2.0 GLX</b>	<b>1979-80</b>
4G52	72 98
Ignition Leads	<b>85380</b>
<b>Galant II (A16) 1.6 GLX</b>	<b>1980-84</b>
4G32	55 75
Ignition Leads	<b>85350</b>
<b>Galant II Station Wagon (A16V) 1.6 GLX</b>	<b>1980-84</b>
4G32	55 75
Ignition Leads	<b>85350</b>
<b>Galant II Station Wagon (A16V) 2.0 GLX</b>	<b>1980-83</b>
4G63 (SOHC 8V)	75 102
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85380</b>
<b>Galant III (E1A) 1.6 GLX</b>	<b>1984-90</b>
4G32	55 75
Ignition Leads	<b>85380</b>
<b>Galant III (E1A) 2.0 GLS</b>	<b>1986-90</b>
G63B	66 90
Ignition Leads	<b>85380</b>
<b>Galant III (E1A) 2.0 GLS</b>	<b>1984-90</b>
4G63 (SOHC 8V)	75 102
Ignition Leads	<b>85380</b>
<b>Galant IV (E3A) 1,8</b>	<b>1988-92</b>
4G37	66 90
Ignition Leads	<b>85381</b>
<b>Galant IV (E3A) 2.0</b>	<b>1989-92</b>
4G63 (SOHC 8V)	80 109
Ignition Leads	<b>85381</b>
<b>Galant IV (E3A) 2.0 GTi 16V</b>	<b>1988-92</b>
4G63 (DOHC 16V)	106 144
Ignition Leads	<b>85999</b>
<b>Galant IV (E3A) 2.0 GTi 16V</b>	<b>1988-92</b>
4G63 (DOHC 16V)	107 146
Ignition Leads	<b>85999</b>
<b>Galant IV (E3A) 2.0 GTi 16V 4x4</b>	<b>1989-92</b>
4G63 (DOHC 16V)	106 144
Ignition Leads	<b>85999</b>
<b>Galant IV Sedan (E3A) 1,8</b>	<b>1987-92</b>
4G37	66 90
Ignition Leads	<b>85381</b>
<b>Galant IV Sedan (E3A) 2.0</b>	<b>1987-92</b>
4G63 (SOHC 8V)	80 109
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85381</b>
<b>Galant IV Sedan (E3A) 2.0 4WD</b>	<b>1988-92</b>
4G63 (SOHC 8V)	80 109
Ignition Leads	<b>85381</b>
<b>Galant IV Sedan (E3A) 2.0 GTi 16V</b>	<b>1988-92</b>
4G63 (DOHC 16V)	107 145
Ignition Leads	<b>85381</b>
Ignition Leads	<b>85999</b>
<b>Galant IV Sedan (E3A) 2.0 GTi 16V</b>	<b>1987-92</b>
4G63 (DOHC 16V)	106 144
Ignition Leads	<b>85381</b>
Ignition Leads	<b>85999</b>
<b>Galant IV Sedan (E3A) 2.0 GTi 16V 4WD</b>	<b>1988-92</b>
4G63 (DOHC 16V)	106 144
Ignition Leads	<b>85999</b>
<b>Galant IV Sedan (E3A) 2.0 GTi 16V 4WD KAT</b>	<b>1991-92</b>
4G63 (DOHC 16V)	110 150
Ignition Leads	<b>85999</b>
<b>Galant V (E5A, E7A, E8A) 1,8</b>	<b>1994-96</b>
4G93	85 116
Ignition Leads	<b>85381</b>
<b>Galant V (E5A, E7A, E8A) 1.8 GLSI</b>	<b>1992-96</b>
4G93 (GDI)	93 126
Ignition Leads	<b>85381</b>

MITSUBISHI Cont.	
<b>Galant V (E5A, E7A, E8A) 2.0 GLSI</b>	<b>1992-96</b>
4G63 (SOHC 16V)	101 137
Ignition Leads	<b>85381</b>
<b>Galant V (E5A, E7A, E8A) 2.0 GLSI 4WD</b>	<b>1992-96</b>
4G63 (SOHC 16V)	101 137
Ignition Leads	<b>85381</b>
<b>Galant V Sedan (E5A, E7A, E8A) 1,8</b>	<b>1994-96</b>
4G93	85 116
Ignition Leads	<b>85381</b>
<b>Galant V Sedan (E5A, E7A, E8A) 1.8 GLSI</b>	<b>1992-96</b>
4G93 (GDI)	93 126
Ignition Leads	<b>85381</b>
<b>Galant V Sedan (E5A, E7A, E8A) 2.0 GLSI</b>	<b>1992-96</b>
4G63 (SOHC 16V)	101 137
Ignition Leads	<b>85381</b>
<b>Galant V Sedan (E5A, E7A, E8A) 2.0 GLSI 4WD</b>	<b>1992-96</b>
4G63 (SOHC 16V)	101 137
Ignition Leads	<b>85381</b>
<b>Galant VI (EA) 2.0</b>	<b>2000-04</b>
4G63 (SOHC 16V)	98 133
Ignition Coil	<b>80346</b>
<b>Galant VI (EA) 2.0</b>	<b>1996-00</b>
4G63 (SOHC 16V)	100 136
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85382</b>
<b>Galant VI Station Wagon (EA) 2.0</b>	<b>2000-03</b>
4G63 (SOHC 16V)	98 133
Ignition Coil	<b>80346</b>
<b>Galant VI Station Wagon (EA) 2.0</b>	<b>1996-00</b>
4G63 (SOHC 16V)	100 136
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85382</b>
<b>Galant VI Station Wagon (EA) 2.4 GDI</b>	<b>1999-03</b>
4G64 (GDI)	110 150
Ignition Leads	<b>85382</b>
<b>L 200 (K3T, K2T, K1T, K0T) 2.6 4WD</b>	<b>1989-95</b>
G54B	76 103
Ignition Leads	<b>85380</b>
<b>L 200 (K7T, K6T) 2.0</b>	<b>1996-07</b>
4G63 (SOHC 16V)	90 122
Ignition Leads	<b>85385</b>
<b>L 200 (K7T, K6T) 2.4 4WD</b>	<b>1996-07</b>
4G64 (SOHC 16V)	97 132
Ignition Leads	<b>85385</b>
<b>L 300 Bus (L03P/G, L02P) 1,6</b>	<b>1981-86</b>
4G32	48 65
Ignition Leads	<b>85380</b>
<b>L 300 Bus (L03P/G, L02P) 1,6</b>	<b>1984-87</b>
4G32	51 70
Ignition Leads	<b>85380</b>
<b>L 300 Bus (L03P/G, L02P) 1.8 4WD</b>	<b>1984-87</b>
4G62	60 82
Ignition Leads	<b>85380</b>
<b>L 300 Bus (L03P/G, L02P) 2.0 4WD</b>	<b>1986-87</b>
4G63 (SOHC 8V)	65 88
Ignition Leads	<b>85380</b>
<b>L 300 Bus (P0W, P1W, P2W) 1,6</b>	<b>1986-04</b>
4G32	51 69
Ignition Leads	<b>85380</b>
<b>L 300 Bus (P0W, P1W, P2W) 2,4</b>	<b>1990-04</b>
4G64 (8V)	82 112
Ignition Leads	<b>85380</b>
<b>L 300 Bus (P0W, P1W, P2W) 2.0</b>	<b>1986-04</b>
G63B	64 87
Ignition Leads	<b>85380</b>
<b>L 300 Bus (P0W, P1W, P2W) 2.0 i</b>	<b>1994-98</b>
4G63 (SOHC 16V)	83 113
Ignition Leads	<b>85380</b>
<b>L 300 Bus (P0W, P1W, P2W) 2.4 4WD</b>	<b>1986-90</b>
G64B	80 109
Ignition Leads	<b>85380</b>
<b>L 300 Bus (P0W, P1W, P2W) 2.4 4WD</b>	<b>1990-04</b>
4G64 (8V)	82 112
Ignition Leads	<b>85380</b>
<b>L 300 Chassis (L03P) 1,6</b>	<b>1983-94</b>
4G32	51 70
Ignition Leads	<b>85380</b>



MITSUBISHI Cont.	
<b>L 300 Chassis (P1T) 2.0</b>	<b>1994-00</b>
4G63 (SOHC 16V)	85 116
Ignition Leads	<b>85385</b>
<b>L 300 Van (L03P) 1,6</b>	<b>1980-86</b>
4G32	48 65
Ignition Leads	<b>85380</b>
<b>L 300 Van (P0W, P1W) 1,6</b>	<b>1986-94</b>
4G32	51 69
Ignition Leads	<b>85380</b>
<b>L 400 / Space Gear Bus (PDW, PCW, PAV, PBV) 2.4 i 4WD</b>	<b>1995-00</b>
4G64 (SOHC 16V)	97 132
Ignition Leads	<b>85385</b>
<b>Lancer IV (C6A, C7A) 1.6 16V</b>	<b>1992-94</b>
4G92 (SOHC 16V)	83 113
Ignition Leads	<b>85381</b>
<b>Lancer IV (C6A, C7A) 1.8 GTi 16V</b>	<b>1992-93</b>
4G93 (DOHC 16V)	103 140
Ignition Leads	<b>85999</b>
<b>Lancer IV (C6A, C7A) 1.8 GTi 16V</b>	<b>1989-92</b>
4G67	100 136
Ignition Leads	<b>85999</b>
<b>Lancer Kombi (CSW) 1.6</b>	<b>2003-08</b>
4G18	72 98
Ignition Coil	<b>80365</b>
Ignition Leads	<b>85382</b>
Ignition Leads ->06.2008	<b>85383</b>
<b>Lancer Kombi (CSW) 2.0</b>	<b>2003-07</b>
4G63 (DOHC 16V)	99 135
Ignition Leads	<b>85384</b>
<b>Lancer Sedan (CSA, CT0) 1,6</b>	<b>2003-&gt;</b>
4G18	72 98
Ignition Coil	<b>80365</b>
Ignition Leads	<b>85382</b>
Ignition Leads ->04.2010	<b>85383</b>
<b>Lancer Sedan (CSA, CT0) 1.3</b>	<b>2003-&gt;</b>
4G13 (16V)	60 82
Ignition Coil	<b>80365</b>
Ignition Leads	<b>85382</b>
Ignition Leads ->04.2010	<b>85383</b>
<b>Lancer Sedan (CSA, CT0) 2.0</b>	<b>2003-&gt;</b>
4G63 (DOHC 16V)	99 135
Ignition Leads	<b>85384</b>
<b>Lancer Sedan (CY/ZA) 1.8</b>	<b>2008-&gt;</b>
4B10	105 143
Ignition Coil	<b>80338</b>
<b>Lancer Sedan (CY/ZA) 1.8</b>	<b>2010-&gt;</b>
4B10	103 140
Ignition Coil	<b>80338</b>
<b>Lancer Sedan (CY/ZA) 1.8 Bifuel</b>	<b>2010-&gt;</b>
4B10	105 143
Ignition Coil	<b>80338</b>
<b>Lancer Sedan (CY/ZA) 1.8 Flex</b>	<b>2009-&gt;</b>
4B10	103 140
Ignition Coil	<b>80338</b>
<b>Lancer Sportback (CXA) 1,8</b>	<b>2008-&gt;</b>
4B10	105 143
Ignition Coil	<b>80338</b>
<b>Lancer Sportback (CXA) 1.8</b>	<b>2009-&gt;</b>
4B10	103 140
Ignition Coil	<b>80338</b>
<b>Lancer Sportback (CXA) 1.8 Bifuel</b>	<b>2010-&gt;</b>
4B10	105 143
Ignition Coil	<b>80338</b>
<b>Lancer Sportback (CXA) 1.8 Flex</b>	<b>2009-&gt;</b>
4B10	103 140
Ignition Coil	<b>80338</b>
<b>Lancer V (CB/DA) 1,3</b>	<b>1992-96</b>
4G13 (12V)	55 75
Ignition Leads	<b>85379</b>
<b>Lancer V (CB/DA) 1,6</b>	<b>1994-96</b>
4G92	66 90
Ignition Leads	<b>85381</b>
<b>Lancer V (CB/DA) 1.5</b>	<b>1992-96</b>
4G15 (12V)	65 88
Ignition Leads	<b>85379</b>
<b>Lancer V (CB/DA) 1.6 16V</b>	<b>1992-96</b>
4G92 (SOHC 16V)	83 113
Ignition Leads	<b>85381</b>

MITSUBISHI Cont.	
<b>Lancer V (CB/DA) 1.6 16V 4WD</b>	<b>1992-96</b>
4G92 (SOHC 16V)	83 113
Ignition Leads	<b>85381</b>
<b>Lancer V Station Wagon (CBW, CDW) 1.6 16V</b>	<b>1992-03</b>
4G92	83 113
Ignition Leads ->05.1997	<b>85381</b>
<b>Lancer V Station Wagon (CBW, CDW) 1.6 16V 4WD</b>	<b>1992-03</b>
4G92	83 113
Ignition Leads ->05.1997	<b>85381</b>
<b>Lancer VI (CJ-CP) 1.3 12V</b>	<b>1995-03</b>
4G13 (12V)	55 75
Ignition Leads	<b>85379</b>
<b>Lancer VI (CJ-CP) 1.5 16V</b>	<b>1999-03</b>
4G15 (16V)	69 94
Ignition Leads	<b>85379</b>
<b>Lancer VI (CJ-CP) 1.6 16V</b>	<b>1995-03</b>
4G92 (SOHC 16V)	66 90
Ignition Leads	<b>85381</b>
<b>Lancer VI (CJ-CP) 2.0 16V EVO</b>	<b>1998-98</b>
4G63 Turbo	206 280
Ignition Leads	<b>85384</b>
<b>Lancer VII (CSA, CTA) 2.0 i</b>	<b>2007-&gt;</b>
4B11	113 154
Ignition Coil	<b>80338</b>
<b>Lancer VII (CYA, CZA) 2.0</b>	<b>2009-&gt;</b>
4B11	108 147
Ignition Coil	<b>80338</b>
<b>Montero (Pajero/Shogun) (L04G) 2,6</b>	<b>1983-90</b>
4G54	76 103
Ignition Leads	<b>85380</b>
<b>Montero (Pajero/Shogun) (L04G, L14G) 3.0 V6</b>	<b>1988-90</b>
6G72 (SOHC 12V)	104 141
Ignition Leads	<b>85380</b>
<b>Montero (Pajero/Shogun) (V2W, V4W) 2,4</b>	<b>1991-00</b>
4G64 (12V)	82 112
Ignition Coil	<b>80315</b>
<b>Montero (Pajero/Shogun) (V3W, V2W, V4W) 2,4</b>	<b>1991-99</b>
4G64 (12V)	82 112
Ignition Coil	<b>80315</b>
<b>Montero IO (Pajero/Shogun) (H6W, H7W) 1,8</b>	<b>2001-07</b>
4G93 (SOHC 16V)	84 114
Ignition Leads	<b>85382</b>
<b>Montero IO (Pajero/Shogun) (H6W, H7W) 1.8 GDI</b>	<b>1999-01</b>
4G93 (GDI)	88 120
Ignition Leads	<b>85382</b>
<b>Montero Sport (KH, KG) 3.0 4WD</b>	<b>2008-&gt;</b>
6B31	162 220
Ignition Coil	<b>80338</b>
<b>Outlander I (CUW) 2.0</b>	<b>2003-06</b>
4G63 (DOHC 16V)	100 136
Ignition Leads	<b>85384</b>
<b>Outlander I (CUW) 2.0 4WD</b>	<b>2003-06</b>
4G63 (DOHC 16V)	100 136
Ignition Leads	<b>85384</b>
<b>Outlander I (CUW) 2.0 4WD</b>	<b>2002-06</b>
4G63 Turbo	177 241
Ignition Leads	<b>85384</b>
<b>Outlander I (CUW) 2.0 4WD</b>	<b>2003-06</b>
4G63 (DOHC 16V)	93 126
Ignition Leads	<b>85384</b>
<b>Outlander I (CUW) 2.0 Turbo 4WD</b>	<b>2004-06</b>
4G63 T (DOHC 16V)	148 201
Ignition Leads	<b>85384</b>
<b>Outlander I (CUW) 2.4 4WD</b>	<b>2003-06</b>
4G64 (SOHC 16V)	102 139
Ignition Coil	<b>80346</b>
<b>Outlander II (CWW) 2.0</b>	<b>2006-12</b>
4B11	108 147
Ignition Coil	<b>80338</b>
<b>Outlander II (CWW) 2.0 4WD</b>	<b>2006-12</b>
4B11	108 147
Ignition Coil	<b>80338</b>
<b>Outlander II (CWW) 2.4</b>	<b>2006-12</b>
4B12	125 170
Ignition Coil	<b>80338</b>
<b>Outlander II (CWW) 2.4 4WD</b>	<b>2007-12</b>
4B12	125 170
Ignition Coil	<b>80338</b>



<b>MITSUBISHI Cont.</b>	
<b>Outlander II (CWW) 2.4 Flex 4WD</b>	<b>2007-12</b>
4B12	125 170
Ignition Coil	<b>80338</b>
<b>Outlander II (CWW) 3.0 4WD</b>	<b>2006-12</b>
6B31	162 220
Ignition Coil	<b>80338</b>
<b>Outlander II (CWW) 3.0 AWD</b>	<b>2006-10</b>
6B31	164 223
Ignition Coil	<b>80338</b>
<b>Santamo 2.0 16V</b>	<b>1999-04</b>
4G63 (DOHC 16V)	102 139
Ignition Leads	<b>85999</b>
<b>Sapporo I (A12) 2.0</b>	<b>1978-80</b>
4G52	66 90
Ignition Leads	<b>85380</b>
<b>Sapporo I (A12) 2.0</b>	<b>1978-80</b>
4G52	72 98
Ignition Leads	<b>85380</b>
<b>Sapporo I (A12) 2.0</b>	<b>1979-80</b>
4G52	79 107
Ignition Leads	<b>85380</b>
<b>Sapporo II (A16A) 2.0 GSL</b>	<b>1980-83</b>
4G63 (SOHC 8V)	75 102
Ignition Leads	<b>85380</b>
<b>Sapporo II (A16A) 2.0 GSR</b>	<b>1980-84</b>
4G63 (SOHC 8V)	82 112
Ignition Leads	<b>85380</b>
<b>Sapporo II (A16A) 2.0 Turbo ECI</b>	<b>1982-83</b>
4G63 T (ECI)	125 170
Ignition Leads	<b>85380</b>
<b>Sigma (F2A, F1A) 3.0 V6</b>	<b>1990-96</b>
6G72 (SOHC 12V)	130 177
Ignition Coil	<b>80315</b>
<b>Sigma Station Wagon (F0W) 3.0</b>	<b>1992-96</b>
6G72 (SOHC 12V)	125 170
Ignition Coil	<b>80315</b>
<b>Space Runner (N1W, N2W) 1,8</b>	<b>1996-99</b>
4G93 (SOHC 16V)	85 116
Ignition Leads	<b>85381</b>
<b>Space Runner (N1W, N2W) 1,8</b>	<b>1991-99</b>
4G93 (SOHC 16V)	90 122
Ignition Leads	<b>85381</b>
<b>Space Runner (N1W, N2W) 1.8 4WD</b>	<b>1996-99</b>
4G93 (SOHC 16V)	85 116
Ignition Leads	<b>85381</b>
<b>Space Runner (N1W, N2W) 1.8 4WD</b>	<b>1991-99</b>
4G93 (SOHC 16V)	90 122
Ignition Leads	<b>85381</b>
<b>Space Runner (N1W, N2W) 2.0 16V</b>	<b>1997-99</b>
4G63 (DOHC 16V)	98 133
Ignition Leads	<b>85381</b>
<b>Space Runner (N6W) 2.0</b>	<b>1999-02</b>
4G63 (SOHC 16V)	100 136
Ignition Coil	<b>80346</b>
Ignition Leads	<b>85381</b>
<b>Space Runner (N6W) 2.4 GDI</b>	<b>1999-03</b>
4G64 (GDI)	110 150
Ignition Leads	<b>85382</b>
<b>Space Star (DGA) 1.3 16V</b>	<b>1998-04</b>
4G13 (16V)	63 86
Ignition Coil	<b>80365</b>
Ignition Leads 06.2000->	<b>85382</b>
Ignition Leads	<b>85383</b>
<b>Space Star (DGA) 1.3 16V</b>	<b>1998-04</b>
4G13 (16V)	61 83
Ignition Coil	<b>80365</b>
Ignition Leads 06.2000->	<b>85382</b>
Ignition Leads	<b>85383</b>
<b>Space Star (DGA) 1.3 16V</b>	<b>2000-04</b>
4G13 (16V)	60 82
Ignition Coil	<b>80365</b>
Ignition Leads	<b>85382</b>
Ignition Leads	<b>85383</b>
<b>Space Star (DGA) 1.6 16V</b>	<b>2001-04</b>
4G18	72 98
Ignition Coil	<b>80365</b>
Ignition Leads	<b>85382</b>
Ignition Leads 04.2001->	<b>85383</b>

<b>MITSUBISHI Cont.</b>	
<b>Space Star (DGA) 1.8 MPI</b>	<b>2002-04</b>
4G93 (DOHC 16V)	82 112
Ignition Coil	<b>80365</b>
<b>Space Star MPV (DGA) 1.6</b>	<b>2001-04</b>
4G92 (SOHC 16V)	72 98
Ignition Coil	<b>80365</b>
<b>Space Wagon (DOV/W) 2.0 4WD</b>	<b>1985-91</b>
4G63 (SOHC 8V)	75 102
Ignition Leads	<b>85381</b>
Ignition Leads	<b>85385</b>
<b>Space Wagon (DOV/W) 2.0 GLX</b>	<b>1986-88</b>
G63B	62 84
Ignition Leads	<b>85385</b>
<b>Space Wagon (DOV/W) 2.0 GLX 4WD</b>	<b>1986-88</b>
G63B	62 84
Ignition Leads	<b>85385</b>
<b>Space Wagon (DOV/W) 2.0 GLXi</b>	<b>1988-91</b>
4G63 (SOHC 8V)	74 101
Ignition Leads	<b>85381</b>
<b>Space Wagon (DOV/W) 2.0 GLXi 4WD</b>	<b>1988-91</b>
4G63 (SOHC 8V)	74 101
Ignition Leads	<b>85381</b>
<b>Space Wagon (N3W, N4W) 1,8</b>	<b>1991-98</b>
4G93 (SOHC 16V)	90 122
Ignition Leads	<b>85381</b>
<b>Space Wagon (N3W, N4W) 1.8 4WD</b>	<b>1991-98</b>
4G93 (SOHC 16V)	90 122
Ignition Leads	<b>85381</b>
<b>Space Wagon (N3W, N4W) 2.0</b>	<b>1992-98</b>
4G63 (SOHC 16V)	98 133
Ignition Leads DIN; SAE	<b>85381</b>
Ignition Leads SAE	<b>85382</b>
<b>Space Wagon (N3W, N4W) 2.0 4WD</b>	<b>1992-98</b>
4G63 (SOHC 16V)	98 133
Ignition Leads	<b>85381</b>
Ignition Leads 01.1997->	<b>85382</b>
<b>Space Wagon (N9W, N8W) 2.0 GDI</b>	<b>1998-04</b>
4G63 (SOHC 16V)	98 133
Ignition Coil	<b>80346</b>
<b>Space Wagon (N9W, N8W) 2.4 GDI</b>	<b>1998-04</b>
4G64 (GDI)	110 150
Ignition Leads	<b>85382</b>
<b>Space Wagon (N9W, N8W) 2.4 GDI</b>	<b>2000-04</b>
4G64 (GDI)	108 147
Ignition Leads	<b>85382</b>
<b>Space Wagon (N9W, N8W) 2.4 GDI 4WD</b>	<b>1998-04</b>
4G64 (GDI)	110 150
Ignition Leads	<b>85382</b>
<b>Starion (A18A) 2.0 Turbo ECI</b>	<b>1982-85</b>
4G63 T (ECI)	125 170
Ignition Leads	<b>85380</b>
<b>Starion (A18A) 2.0 Turbo ECI</b>	<b>1985-87</b>
4G63 T/C	132 180
Ignition Leads	<b>85380</b>
<b>MORRIS</b>	
<b>Marina 1.8</b>	<b>1971-79</b>
	59 82
Ignition Leads	<b>83850</b>
<b>Marina 1300</b>	<b>1971-75</b>
	44 60
Ignition Leads	<b>83850</b>
<b>Marina II Sedan 1300</b>	<b>1975-78</b>
	42 57
Ignition Leads	<b>83850</b>
<b>Marina III 1,3</b>	<b>1978-80</b>
	42 57
Ignition Leads	<b>83850</b>



NISSAN	
<b>100 NX (B13) 1.6</b>	<b>1990-94</b>
GA16DS	66 90
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85840</b>
Ignition Leads GA16DS	<b>85850</b>
Ignition Leads GA16DS	<b>85861</b>
<b>100 NX (B13) 1.6 SR</b>	<b>1993-94</b>
GA16DE	75 102
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads	<b>85861</b>
<b>100 NX (B13) 2.0 GTI</b>	<b>1991-94</b>
SR20DE	105 143
Ignition Coil	<b>80286</b>
Ignition Leads <B13EGA,B13ESA>; ->10.1993	<b>85840</b>
Ignition Leads ->04.1992	<b>85850</b>
Ignition Leads	<b>85861</b>
<b>200 SX (S13) 1.8 Turbo</b>	<b>1988-93</b>
CA18DET	124 169
Ignition Leads	<b>86030</b>
<b>200 SX (S14) 2.0 i 16V Turbo</b>	<b>1993-99</b>
SR20DET	147 200
Ignition Coil	<b>80286</b>
<b>Almera Classic (B10) 1.6 16V</b>	<b>2006-&gt;</b>
QG16DE	79 107
Ignition Coil	<b>80370</b>
<b>Almera I (N15) 1.4</b>	<b>1995-00</b>
GA14DE	64 87
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads ->04.2000	<b>85861</b>
<b>Almera I (N15) 1.4 GX,LX</b>	<b>1995-00</b>
GA14DE	55 75
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads ->04.2000	<b>85861</b>
<b>Almera I (N15) 1.6</b>	<b>1995-00</b>
GA16DE	73 99
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads ->04.2000	<b>85861</b>
<b>Almera I (N15) 1.6 SLX</b>	<b>1995-00</b>
GA16DE	66 90
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads ->04.2000	<b>85861</b>
<b>Almera I Hatchback (N15) 1.4</b>	<b>1995-00</b>
GA14DE	64 87
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads	<b>85861</b>
<b>Almera I Hatchback (N15) 1.4 S,GX,LX</b>	<b>1995-00</b>
GA14DE	55 75
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads	<b>85861</b>
<b>Almera I Hatchback (N15) 1.6</b>	<b>1995-00</b>
GA16DE	73 99
Ignition Leads	<b>85860</b>
Ignition Leads	<b>85861</b>
<b>Almera I Hatchback (N15) 1.6 SR,SLX</b>	<b>1995-00</b>
GA16DE	66 90
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads	<b>85861</b>
<b>Almera I Hatchback (N15) 2.0 GTI</b>	<b>1996-00</b>
SR20DE	105 143
Ignition Leads	<b>85861</b>
<b>Almera II (N16) 1.5</b>	<b>2000-&gt;</b>
QG15DE	66 90
Ignition Coil	<b>80244</b>
Ignition Coil 04.2001->	<b>80370</b>
<b>Almera II (N16) 1.5</b>	<b>2002-&gt;</b>
QG15DE	72 98
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>

NISSAN Cont.	
<b>Almera II (N16) 1.8</b>	<b>2000-&gt;</b>
QG18DE	84 114
Ignition Coil ->04.2003	<b>80244</b>
Ignition Coil 04.2001->	<b>80370</b>
<b>Almera II (N16) 1.8</b>	<b>2002-&gt;</b>
QG18DE	85 116
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Almera II Hatchback (N16) 1.5</b>	<b>2000-&gt;</b>
QG15DE	66 90
Ignition Coil	<b>80244</b>
Ignition Coil 11.2000->	<b>80370</b>
<b>Almera II Hatchback (N16) 1.5</b>	<b>2002-&gt;</b>
QG15DE	72 98
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Almera II Hatchback (N16) 1.8</b>	<b>2000-&gt;</b>
QG18DE	84 114
Ignition Coil ->04.2003	<b>80244</b>
Ignition Coil 11.2000->	<b>80370</b>
<b>Almera II Hatchback (N16) 1.8</b>	<b>2002-&gt;</b>
QG18DE	85 116
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Almera Tino (V10) 1.8</b>	<b>2000-&gt;</b>
QG18DE	84 114
Ignition Coil ->04.2003	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Almera Tino (V10) 1.8</b>	<b>2002-&gt;</b>
QG18DE	85 116
Ignition Coil ->04.2003	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Almera Tino (V10) 2.0</b>	<b>2000-&gt;</b>
SR20DE	100 136
Ignition Leads	<b>85861</b>
<b>Altima (L32) 2.5</b>	<b>2006-13</b>
QR25DE	128 174
Ignition Coil ->05.2012	<b>80375</b>
<b>Bluebird (910) 1.8</b>	<b>1980-83</b>
L18S	65 88
Ignition Leads	<b>86030</b>
<b>Bluebird (T72 , T12) 1.6</b>	<b>1986-90</b>
CA16S	61 83
Ignition Leads	<b>86030</b>
<b>Bluebird (T72 , T12) 1.8 i 16V</b>	<b>1989-90</b>
CA18D	95 129
Ignition Leads	<b>86030</b>
<b>Bluebird (T72 , T12) 1.8 Turbo</b>	<b>1985-90</b>
CA18T	99 135
Ignition Coil	<b>80315</b>
<b>Bluebird (T72 , T12) 2.0</b>	<b>1985-87</b>
CA20S	75 102
Ignition Coil	<b>80286</b>
Ignition Leads	<b>86030</b>
<b>Bluebird (T72 , T12) 2.0 i</b>	<b>1985-90</b>
CA20S/CA20E	77 105
Ignition Coil	<b>80286</b>
Ignition Leads	<b>86030</b>
<b>Bluebird (U11) 1.8</b>	<b>1983-88</b>
CA18S	66 90
Ignition Leads	<b>86030</b>
<b>Bluebird (U11) 1.8 Turbo</b>	<b>1984-90</b>
CA18T	99 135
Ignition Coil	<b>80315</b>
<b>Bluebird (U11) 2.0 i</b>	<b>1984-88</b>
CA20E	77 105
Ignition Coil	<b>80286</b>
Ignition Leads	<b>86030</b>
<b>Bluebird Hatchback (T72, T12) 1.6</b>	<b>1986-90</b>
CA16S	61 83
Ignition Leads	<b>86030</b>
<b>Bluebird Hatchback (T72, T12) 1.6</b>	<b>1986-91</b>
CA16S	66 90
Ignition Leads	<b>86030</b>
<b>Bluebird Hatchback (T72, T12) 1.8 i 16V</b>	<b>1989-90</b>
CA18D	95 129
Ignition Leads	<b>86030</b>



NISSAN Cont.	
<b>Bluebird Hatchback (T72, T12) 1.8 Turbo</b>	<b>1985-92</b>
CA18T	99 135
Ignition Coil	<b>80315</b>
<b>Bluebird Hatchback (T72, T12) 2.0</b>	<b>1985-87</b>
CA20S	75 102
Ignition Leads	<b>86030</b>
<b>Bluebird Hatchback (T72, T12) 2.0 i</b>	<b>1985-90</b>
CA20E	77 105
Ignition Coil	<b>80286</b>
Ignition Leads	<b>86030</b>
<b>Bluebird Sedan (910) 1.8</b>	<b>1980-84</b>
L18T	66 90
Ignition Leads	<b>86030</b>
<b>Bluebird Station Wagon (WU11) 2.0</b>	<b>1986-90</b>
CA20S	75 102
Ignition Leads	<b>86030</b>
<b>Bluebird Station Wagon (WU11) 2.0 i</b>	<b>1984-90</b>
CA20E	77 105
Ignition Coil	<b>80286</b>
Ignition Leads	<b>86030</b>
<b>Bluebird Sylphy II (G11) 1.5</b>	<b>2005-12</b>
HR15DE	80 109
Ignition Coil	<b>80372</b>
<b>Bluebird Sylphy II (G11) 1.5 4x4</b>	<b>2005-12</b>
HR15DE	80 109
Ignition Coil	<b>80372</b>
<b>Bluebird Traveller (W910) 1.8</b>	<b>1980-84</b>
L18S	65 88
Ignition Leads	<b>86030</b>
<b>Caravan Bus (E25) 2.5</b>	<b>2001-10</b>
QR25DE	108 147
Ignition Coil 08.2007->	<b>80375</b>
<b>Cherry II Coupe (N10) 1.2</b>	<b>1978-81</b>
A12	38 52
Ignition Leads A12	<b>83210</b>
<b>Cherry II Hatchback (N10) 1.0</b>	<b>1978-81</b>
A10S	32 44
Ignition Leads A10S	<b>83210</b>
<b>Cherry II Hatchback (N10) 1.2</b>	<b>1978-81</b>
A12	38 52
Ignition Leads A12	<b>83210</b>
<b>Cherry II Traveller (VN10) 1.2</b>	<b>1978-81</b>
A12	38 52
Ignition Leads A12	<b>83210</b>
<b>Cherry III (N12) 1.3</b>	<b>1982-86</b>
E13	44 60
Ignition Leads E13	<b>83010</b>
<b>Cherry III (N12) 1.5</b>	<b>1983-86</b>
E15S	55 75
Ignition Leads E15S	<b>83010</b>
<b>Cherry III (N12) 1.5 ET Turbo</b>	<b>1983-85</b>
E15ET	77 105
Ignition Leads	<b>86030</b>
<b>Cube (Z12) 1.6 16V</b>	<b>2010-&gt;</b>
HR16DE	81 110
Ignition Coil	<b>80288</b>
Ignition Coil ->03.2011	<b>80375</b>
<b>Juke (F15) 1.6</b>	<b>2010-&gt;</b>
HR16DE	86 117
Ignition Coil	<b>80375</b>
<b>Juke (F15) 1.6</b>	<b>2013-&gt;</b>
HR16DE	69 94
Ignition Coil	<b>80375</b>
<b>Kubistar (X76) 1.2</b>	<b>2003-&gt;</b>
D7F 764	44 60
Ignition Coil ->03.2009	<b>80203</b>
Ignition Coil	<b>80222</b>
Ignition Leads	<b>85991</b>
<b>Kubistar (X76) 1.2 16V</b>	<b>2006-09</b>
D4F 712	55 75
Ignition Coil Without ignition distributor	<b>80206</b>
Ignition Coil	<b>80222</b>
Ignition Coil Includes spark plug connector	<b>80225</b>
Ignition Coil Without ignition lead	<b>80287</b>
Ignition Leads	<b>85988</b>
<b>Kubistar (X76) 1.6 16V</b>	<b>2003-09</b>
K4M 752	70 95
Ignition Coil	<b>80203</b>

NISSAN Cont.	
<b>Kubistar Van (X80) 1.2</b>	<b>2003-&gt;</b>
D7F 764	44 60
Ignition Coil	<b>80203</b>
Ignition Leads	<b>85991</b>
<b>Kubistar Van (X80) 1.2 16V</b>	<b>2006-&gt;</b>
D4F 712	55 75
Ignition Coil	<b>80206</b>
Ignition Coil	<b>80225</b>
Ignition Coil Without ignition lead	<b>80287</b>
Ignition Leads	<b>85988</b>
<b>Kubistar Van (X80) 1.6 16V</b>	<b>2003-&gt;</b>
K4M 752	70 95
Ignition Coil	<b>80203</b>
<b>Latio Sedan 1.5</b>	<b>2004-&gt;</b>
HR15DE	80 109
Ignition Coil	<b>80372</b>
<b>Latio Sedan 1.5 4x4</b>	<b>2004-&gt;</b>
HR15DE	80 109
Ignition Coil	<b>80372</b>
<b>Maxima II (J30) 3.0 i</b>	<b>1988-94</b>
VG30E	125 170
Ignition Coil	<b>80286</b>
<b>Micra C+C (K12) 1.6 160 SR</b>	<b>2005-&gt;</b>
HR16DE	81 110
Ignition Coil	<b>80288</b>
<b>Micra I (K10) 1.0</b>	<b>1982-89</b>
MA10S	40 54
Ignition Leads MA10S	<b>83010</b>
<b>Micra I (K10) 1.0</b>	<b>1982-89</b>
MA10S	37 50
Ignition Leads MA10S	<b>83010</b>
<b>Micra I (K10) 1.2</b>	<b>1986-92</b>
MA12S	40 54
Ignition Coil	<b>80286</b>
<b>Micra II (K11) 1.0 i 16V</b>	<b>2000-03</b>
CG10DE	44 60
Ignition Leads	<b>85830</b>
<b>Micra II (K11) 1.0 i 16V</b>	<b>1992-00</b>
CG10DE	40 54
Ignition Leads	<b>85830</b>
<b>Micra II (K11) 1.3 i 16V</b>	<b>1992-00</b>
CG13DE	55 75
Ignition Leads	<b>85830</b>
<b>Micra III (K12) 1.0 16V</b>	<b>2003-10</b>
CG10DE	48 65
Ignition Leads	<b>85830</b>
<b>Micra III (K12) 160 SR</b>	<b>2005-10</b>
HR16DE	81 110
Ignition Coil	<b>80288</b>
<b>Micra IV (K13) 1.2</b>	<b>2010-&gt;</b>
HR12DE	59 80
Ignition Coil ->10.2015	<b>80375</b>
<b>Micra IV (K13) 1.2</b>	<b>2010-&gt;</b>
HR12DE	56 76
Ignition Coil	<b>80375</b>
<b>Murano (Z51) 3.5 4x4</b>	<b>2008-14</b>
VQ35DE	188 256
Ignition Coil	<b>80372</b>
<b>Murano II (Z51) 3.5</b>	<b>2007-14</b>
VQ35DE	195 265
Ignition Coil	<b>80372</b>
<b>Murano II (Z51) 3.5 4x4</b>	<b>2010-14</b>
VQ35DE	183 249
Ignition Coil	<b>80372</b>
<b>Murano II (Z51) 3.5 4x4</b>	<b>2007-14</b>
VQ35DE	195 265
Ignition Coil	<b>80372</b>
<b>Note (E11) 1.6</b>	<b>2006-12</b>
HR16DE	81 110
Ignition Coil	<b>80288</b>
Ignition Coil Euro 5	<b>80375</b>
<b>Note (E12) 1.2</b>	<b>2013-&gt;</b>
HR12DE	58 79
Ignition Coil 08.2013->	<b>80375</b>
<b>Note 1.2</b>	<b>2013-&gt;</b>
HR12DE	59 80
Ignition Coil	<b>80375</b>





NISSAN Cont.	
<b>NV200 Evalia 1.6 16V</b>	2010->
HR16DE	81 110
Ignition Coil	<b>80288</b>
Ignition Coil	<b>80375</b>
<b>NV200 Van 1.6 16V</b>	2010->
HR16DE	81 110
Ignition Coil	<b>80288</b>
Ignition Coil M20M; Euro 5	<b>80375</b>
<b>Pick Up (D21) 2.4 i 12V</b>	1992-98
KA24E	91 124
Ignition Coil	<b>80286</b>
<b>Pick Up (D21) 2.4 i 12V 4WD</b>	1992-98
KA24E	93 124
Ignition Coil	<b>80286</b>
<b>Prairie (M10, NM10) 1.5 S</b>	1984-87
E15S	55 75
Ignition Leads	<b>85350</b>
<b>Prairie (M10, NM10) 1.8 SGL</b>	1983-85
CA18S	65 88
Ignition Leads	<b>86030</b>
<b>Prairie (M10, NM10) 1.8 SGL</b>	1985-87
CA18S	66 90
Ignition Leads	<b>86030</b>
<b>Prairie Pro (M11) 2.0 i</b>	1988-92
CA20E	72 98
Ignition Coil	<b>80286</b>
<b>Prairie Pro (M11) 2.0 i 4x4</b>	1988-92
CA20E	72 98
Ignition Coil	<b>80286</b>
<b>Prairie Pro (M11) 2.4 i</b>	1992-94
KA24E	98 133
Ignition Coil	<b>80286</b>
<b>Prairie Pro (M11) 2.4 i 4x4</b>	1992-94
KA24E	98 133
Ignition Coil	<b>80286</b>
<b>Primastar Bus (X83) 2.0</b>	2001->
F4R 722/F4R 720	88 120
Ignition Coil 02.2003->	<b>80203</b>
<b>Primastar Van (X83) 2.0</b>	2003->
F4R 720	88 120
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Primera (P10) 1.6</b>	1993-96
GA16DE	75 102
Ignition Coil	<b>80286</b>
Ignition Coil	<b>80370</b>
Ignition Leads	<b>85840</b>
Ignition Leads	<b>85850</b>
Ignition Leads	<b>85860</b>
Ignition Leads	<b>85861</b>
<b>Primera (P10) 1.6</b>	1990-96
GA16DS	66 90
Ignition Coil	<b>80286</b>
Ignition Leads 04.1991->	<b>85840</b>
Ignition Leads GA16DS	<b>85850</b>
Ignition Leads	<b>85861</b>
<b>Primera (P10) 1.6</b>	1990-96
GA16DS	71 97
Ignition Leads 04.1991->	<b>85840</b>
Ignition Leads GA16DS	<b>85850</b>
Ignition Leads GA16D	<b>85861</b>
<b>Primera (P10) 2.0 16V</b>	1990-96
SR20DI	85 115
Ignition Coil	<b>80286</b>
Ignition Leads 01.1992->	<b>85850</b>
<b>Primera (P10) 2.0 16V 4x4</b>	1991-96
SR20DI	85 115
Ignition Coil	<b>80286</b>
Ignition Leads 01.1992->	<b>85850</b>
<b>Primera (P10) 2.0 GT</b>	1990-96
SR20DE	110 150
Ignition Coil	<b>80286</b>
Ignition Leads 01.1992-01.1995	<b>85850</b>
<b>Primera (P10) 2.0 i</b>	1995-96
SR20DE	92 125
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85850</b>

NISSAN Cont.	
<b>Primera (P11) 1.6 16V</b>	1996-01
QG16DE	78 106
Ignition Coil	<b>80244</b>
Ignition Coil 10.2000->	<b>80370</b>
Ignition Leads	<b>85860</b>
<b>Primera (P11) 1.6 16V</b>	1996-00
GA16DE	73 99
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads	<b>85861</b>
<b>Primera (P11) 1.6 16V</b>	1996-01
GA16DE	66 90
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads ->05.1999	<b>85861</b>
<b>Primera (P11) 1.8 16V</b>	1999-01
QG18DE	84 114
Ignition Coil	<b>80244</b>
Ignition Coil 10.2000->	<b>80370</b>
<b>Primera (P11) 2.0 16V</b>	1999-01
SR20DE	103 140
Ignition Leads	<b>85861</b>
<b>Primera (P11) 2.0 16V</b>	1996-01
SR20DE	96 131
Ignition Leads	<b>85861</b>
<b>Primera (P11) 2.0 16V</b>	1996-01
SR20De	85 115
Ignition Leads	<b>85861</b>
<b>Primera (P11) 2.0 16V</b>	1996-01
SR20DE	110 150
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85861</b>
<b>Primera (P12) 1.6</b>	2002->
QG16DE	78 106
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Primera (P12) 1.6</b>	2002->
QG16DE	80 109
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Primera (P12) 1.8</b>	2002->
QG18DE	85 115
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Primera (P12) 2.0</b>	2002->
QR20DE	103 140
Ignition Coil	<b>80371</b>
<b>Primera Break (Wp12) 1.6 Visia</b>	2002->
QG16DE	80 109
Ignition Coil	<b>80370</b>
<b>Primera Break (Wp12) 1.8</b>	2002->
QG18DE	85 115
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Primera Break (Wp12) 2.0</b>	2002->
QR20DE	103 140
Ignition Coil	<b>80371</b>
<b>Primera Hatchback (P10) 1.6</b>	1990-96
GA16DS	66 90
Ignition Coil	<b>80286</b>
Ignition Leads 04.1991->	<b>85840</b>
Ignition Leads GA16DS	<b>85850</b>
Ignition Leads GA16DS	<b>85861</b>
<b>Primera Hatchback (P10) 2.0</b>	1990-96
SR20DE	110 150
Ignition Leads 01.1992-01.1995	<b>85850</b>
<b>Primera Hatchback (P10) 2.0 16V</b>	1990-96
SR20DI	85 116
Ignition Coil	<b>80286</b>
Ignition Leads 01.1992->	<b>85850</b>
<b>Primera Hatchback (P10) 2.0 16V 4x4</b>	1991-96
SR20DI	85 115
Ignition Coil	<b>80286</b>
Ignition Leads 01.1992->	<b>85850</b>
<b>Primera Hatchback (P10) 2.0 i</b>	1995-96
SR20DE	92 125
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85850</b>



NISSAN Cont.	
<b>Primera Hatchback (P11) 1.6 16V</b>	<b>2000-02</b>
QG16DE	78 106
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
Ignition Leads	<b>85860</b>
<b>Primera Hatchback (P11) 1.6 16V</b>	<b>1996-02</b>
GA16DE	73 99
Ignition Coil ->09.2000	<b>80244</b>
Ignition Coil	<b>80286</b>
Ignition Coil 10.2000->	<b>80370</b>
Ignition Leads	<b>85860</b>
Ignition Leads ->12.2001	<b>85861</b>
<b>Primera Hatchback (P11) 1.6 16V</b>	<b>1996-02</b>
GA16DE	66 90
Ignition Coil	<b>80286</b>
Ignition Coil	<b>80370</b>
Ignition Leads	<b>85860</b>
Ignition Leads ->05.1999	<b>85861</b>
<b>Primera Hatchback (P11) 1.8 16V</b>	<b>1999-02</b>
QG18DE	84 114
Ignition Coil	<b>80244</b>
Ignition Coil 10.2000->	<b>80370</b>
<b>Primera Hatchback (P11) 2.0 16V</b>	<b>1999-02</b>
SR20DE	103 140
Ignition Leads	<b>85861</b>
<b>Primera Hatchback (P11) 2.0 16V</b>	<b>1996-02</b>
SR20DE	96 131
Ignition Leads	<b>85861</b>
<b>Primera Hatchback (P11) 2.0 16V</b>	<b>1996-02</b>
SR20De	85 115
Ignition Leads	<b>85861</b>
<b>Primera Hatchback (P11) 2.0 16V</b>	<b>1996-02</b>
SR20DE	110 150
Ignition Leads	<b>85861</b>
<b>Primera Hatchback (P12) 1.6</b>	<b>2002-&gt;</b>
QG16DE	78 106
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Primera Hatchback (P12) 1.6</b>	<b>2002-&gt;</b>
QG16DE	80 109
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Primera Hatchback (P12) 1.8</b>	<b>2002-&gt;</b>
QG18DE	85 115
Ignition Coil	<b>80244</b>
Ignition Coil	<b>80370</b>
<b>Primera Hatchback (P12) 2.0</b>	<b>2002-&gt;</b>
QR20DE	103 140
Ignition Coil	<b>80371</b>
<b>Primera Traveller (W10) 1.6 i</b>	<b>1990-98</b>
GA16DS	66 90
Ignition Coil	<b>80286</b>
Ignition Leads 04.1991->	<b>85840</b>
Ignition Leads ->05.1993	<b>85861</b>
<b>Primera Traveller (W10) 1.6 i</b>	<b>1991-98</b>
GA16DE	75 102
Ignition Leads	<b>85840</b>
Ignition Leads ->12.1997	<b>85861</b>
<b>Primera Traveller (W10) 2.0 i</b>	<b>1990-98</b>
SR20DI	85 116
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85850</b>
<b>Primera Traveller (Wp11) 1.6 16V</b>	<b>1998-01</b>
GA16DE	66 90
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads ->06.1999	<b>85861</b>
<b>Primera Traveller (Wp11) 1.6 16V</b>	<b>1998-01</b>
GA16DE	73 99
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85860</b>
Ignition Leads	<b>85861</b>
<b>Primera Traveller (Wp11) 1.8 16V</b>	<b>1999-01</b>
QG18DE	84 114
Ignition Coil	<b>80244</b>
Ignition Coil 10.2000->	<b>80370</b>
<b>Primera Traveller (Wp11) 2.0 16V</b>	<b>1999-01</b>
SR20DE	103 140
Ignition Leads	<b>85861</b>

NISSAN Cont.	
<b>Primera Traveller (Wp11) 2.0 16V</b>	<b>1996-01</b>
SR20De	85 115
Ignition Leads	<b>85861</b>
<b>Primera Traveller (Wp11) 2.0 16V</b>	<b>1998-01</b>
SR20DE	96 131
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85861</b>
<b>Qashqai / Qashqai +2 (J10, JJ10) 1.6</b>	<b>2010-13</b>
HR16DE	86 117
Ignition Coil	<b>80288</b>
Ignition Coil	<b>80375</b>
<b>Qashqai / Qashqai +2 (J10, JJ10) 1.6</b>	<b>2007-13</b>
HR16DE	84 114
Ignition Coil	<b>80288</b>
<b>Qashqai / Qashqai +2 (J10, JJ10) 2.0</b>	<b>2007-13</b>
MR20DE	104 141
Ignition Coil	<b>80288</b>
Ignition Coil	<b>80375</b>
<b>Qashqai / Qashqai +2 (J10, JJ10) 2.0 4WD</b>	<b>2007-13</b>
MR20DE	104 141
Ignition Coil	<b>80288</b>
Ignition Coil	<b>80375</b>
<b>Qashqai / Qashqai +2 I (J10, JJ10) 2.0</b>	<b>2007-13</b>
MR20DE	102 139
Ignition Coil	<b>80375</b>
<b>Qashqai / Qashqai +2 I (J10, JJ10) 2.0 Allrad</b>	<b>2007-13</b>
MR20DE	102 139
Ignition Coil	<b>80375</b>
<b>Sentra VI (B16) 2.0</b>	<b>2006-12</b>
MR20DE	104 141
Ignition Coil 05.2009-08.2012	<b>80375</b>
<b>Sentra VII (B17) 1.6</b>	<b>2014-&gt;</b>
HR16DE	86 117
Ignition Coil	<b>80375</b>
<b>Serena (C23M) 1.6 16V</b>	<b>1993-01</b>
GA16DE	71 97
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85320</b>
<b>Serena (C23M) 2.0 16V</b>	<b>1992-01</b>
SR20DE	93 126
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85320</b>
<b>Stanza (T11) 1.6</b>	<b>1981-85</b>
CA16S	60 82
Ignition Leads	<b>86030</b>
<b>Stanza Hatchback (T11) 1.6</b>	<b>1981-85</b>
CA16S	60 82
Ignition Leads	<b>86030</b>
<b>Sunny I (B11) 1.3</b>	<b>1982-87</b>
E13	44 60
Ignition Leads 01.1984->	<b>85350</b>
<b>Sunny I (B11) 1.5</b>	<b>1982-86</b>
E15S	55 75
Ignition Leads	<b>85350</b>
<b>Sunny I Coupe (B11) 1.5</b>	<b>1982-86</b>
E15S	55 75
Ignition Leads	<b>85350</b>
<b>Sunny I Traveller (B11) 1.5</b>	<b>1982-86</b>
E15S	55 75
Ignition Leads	<b>85350</b>
<b>Sunny II (N13) 1.3</b>	<b>1986-91</b>
E13S	44 60
Ignition Leads ->12.1987	<b>85350</b>
<b>Sunny II (N13) 1.4 LX</b>	<b>1988-91</b>
GA14S	55 75
Ignition Leads GA14S	<b>85840</b>
<b>Sunny II (N13) 1.6</b>	<b>1986-88</b>
E16S	62 84
Ignition Leads	<b>85350</b>
<b>Sunny II (N13) 1.6 i</b>	<b>1986-90</b>
E16i	54 73
Ignition Coil	<b>80315</b>
Ignition Leads	<b>86030</b>
<b>Sunny II (N13) 1.6 i 12V</b>	<b>1988-91</b>
GA16i/GA16S	66 90
Ignition Coil	<b>80286</b>



NISSAN Cont.	
<b>Sunny II (N13) 1.6 i 4x4</b>	<b>1986-90</b>
E16i	54 73
Ignition Coil	<b>80315</b>
Ignition Leads	<b>86030</b>
<b>Sunny II Coupe (B12) 1.6</b>	<b>1986-88</b>
E16S	62 84
Ignition Leads	<b>85350</b>
<b>Sunny II Coupe (B12) 1.6 i</b>	<b>1986-89</b>
E16i	54 73
Ignition Leads	<b>86030</b>
<b>Sunny II Coupe (B12) 1.6 i 12V</b>	<b>1988-91</b>
GA16i	66 90
Ignition Coil ->09.1990	<b>80286</b>
<b>Sunny II Hatchback (N13) 1.3</b>	<b>1986-88</b>
E13S	44 60
Ignition Leads	<b>85350</b>
<b>Sunny II Hatchback (N13) 1.4 LX</b>	<b>1989-91</b>
GA14S	55 75
Ignition Leads GA14DS	<b>85861</b>
<b>Sunny II Hatchback (N13) 1.6</b>	<b>1986-88</b>
E16S	62 84
Ignition Leads	<b>85350</b>
<b>Sunny II Hatchback (N13) 1.6 GTI 16V</b>	<b>1987-89</b>
CA16D	81 110
Ignition Leads	<b>86030</b>
<b>Sunny II Hatchback (N13) 1.6 i</b>	<b>1986-90</b>
E16i	54 73
Ignition Coil	<b>80315</b>
Ignition Leads	<b>86030</b>
<b>Sunny II Hatchback (N13) 1.6 i 12V</b>	<b>1986-90</b>
GA16i	66 90
Ignition Coil	<b>80286</b>
<b>Sunny II Traveller (B12) 1.6</b>	<b>1986-88</b>
E16S	62 84
Ignition Leads	<b>86030</b>
<b>Sunny II Traveller (B12) 1.6 i</b>	<b>1986-89</b>
E16i	54 73
Ignition Coil	<b>80315</b>
Ignition Leads	<b>86030</b>
<b>Sunny II Traveller (B12) 1.6 i 12V</b>	<b>1988-91</b>
GA16i	66 90
Ignition Coil ->09.1990	<b>80286</b>
<b>Sunny II Traveller (B12) 1.6 i 4x4</b>	<b>1986-89</b>
E16i	54 73
Ignition Coil	<b>80315</b>
Ignition Leads	<b>86030</b>
<b>Sunny III (N14) 1.4 i</b>	<b>1990-95</b>
GA14DE /GA14DS	55 75
Ignition Coil	<b>80286</b>
Ignition Leads GA14DS; ->09.1992	<b>85840</b>
Ignition Leads ->09.1992	<b>85850</b>
Ignition Leads GA14DE; 10.1992->	<b>85860</b>
Ignition Leads 10.1992->	<b>85861</b>
<b>Sunny III (N14) 1.4 i 16V</b>	<b>1990-95</b>
GA14DE	64 87
Ignition Leads ->10.1992	<b>85860</b>
<b>Sunny III (N14) 1.6 i</b>	<b>1990-95</b>
GA16DE/GA16DEL/GA16DS	66 90
Ignition Coil	<b>80286</b>
Ignition Leads GA16DS	<b>85840</b>
Ignition Leads GA16DS	<b>85850</b>
Ignition Leads GA16DS	<b>85861</b>
<b>Sunny III (N14) 1.6 i 16V</b>	<b>1992-95</b>
GA16DE	75 102
Ignition Leads	<b>85860</b>
Ignition Leads	<b>85861</b>
<b>Sunny III (N14) 1.6 i 16V 4WD</b>	<b>1990-95</b>
GA16DS	66 90
Ignition Coil	<b>80286</b>
Ignition Leads ->10.1992	<b>85840</b>
Ignition Leads GA16DS	<b>85850</b>
Ignition Leads GA16DS	<b>85861</b>
<b>Sunny III Hatchback (N14) 1.4 i</b>	<b>1990-95</b>
GA14DE /GA14DS	55 75
Ignition Coil	<b>80286</b>
Ignition Leads GA14DE; 10.1992->	<b>85840</b>
Ignition Leads GA14DS	<b>85850</b>
Ignition Leads GA14DE; 11.1992->	<b>85860</b>
Ignition Leads GA14DS	<b>85861</b>

NISSAN Cont.	
<b>Sunny III Hatchback (N14) 1.4 i 16V</b>	<b>1990-95</b>
GA14DE	64 87
Ignition Leads ->10.1992	<b>85860</b>
<b>Sunny III Hatchback (N14) 1.6 i</b>	<b>1990-95</b>
GA16DE/GA16DEL/GA16DS	66 90
Ignition Coil	<b>80286</b>
Ignition Leads GA16DS	<b>85840</b>
Ignition Leads GA16DS	<b>85850</b>
Ignition Leads GA16DS	<b>85861</b>
<b>Sunny III Hatchback (N14) 2.0 GTI 16V</b>	<b>1990-95</b>
SR20DE	105 143
Ignition Coil	<b>80286</b>
Ignition Leads ->09.1994	<b>85850</b>
<b>Sunny III Hatchback (N14) 2.0 GTI-R 4x4</b>	<b>1990-95</b>
SR20DET	162 220
Ignition Coil	<b>80286</b>
Ignition Leads DIN; SAE	<b>85850</b>
<b>Sunny III Liftback (N14) 1.4 i</b>	<b>1990-95</b>
GA14DE /GA14DS	55 75
Ignition Coil	<b>80286</b>
Ignition Leads GA14DS; ->09.1992	<b>85840</b>
Ignition Leads	<b>85850</b>
Ignition Leads GA14DE; 10.1992->	<b>85860</b>
<b>Sunny III Liftback (N14) 1.4 i 16V</b>	<b>1990-95</b>
GA14DE	64 87
Ignition Leads ->10.1992	<b>85860</b>
<b>Sunny III Liftback (N14) 1.6 i</b>	<b>1990-95</b>
GA16DE/GA16DEL/GA16DS	66 90
Ignition Coil	<b>80286</b>
Ignition Leads GA16DS	<b>85840</b>
Ignition Leads GA16DE	<b>85850</b>
Ignition Leads GA16DS	<b>85861</b>
<b>Sunny III Liftback (N14) 2.0 i 16V</b>	<b>1990-95</b>
SR20DE	105 143
Ignition Leads 08.1991->	<b>85850</b>
<b>Sunny III Traveller (Y10) 1.6 i</b>	<b>1991-00</b>
GA16DE/GA16DS	66 90
Ignition Coil	<b>80286</b>
Ignition Leads GA16DS; ->07.1995	<b>85840</b>
Ignition Leads GA16DS; ->10.1992	<b>85850</b>
Ignition Leads GA16DE	<b>85860</b>
<b>Sunny III Traveller (Y10) 1.6 i 16V 4x4</b>	<b>1992-00</b>
GA16DE	75 102
Ignition Leads ->06.1995	<b>85860</b>
Ignition Leads ->07.1995	<b>85861</b>
<b>Sunny Van (Y10) 1.6 i 16V</b>	<b>1992-00</b>
GA16DE	66 90
Ignition Coil ->07.1995	<b>80286</b>
Ignition Leads ->07.1995	<b>85840</b>
Ignition Leads ->06.1995	<b>85860</b>
<b>Teana I (J31) 2.0</b>	<b>2003-08</b>
QR20DE	103 140
Ignition Coil	<b>80371</b>
<b>Teana II (J32) 2.5</b>	<b>2008-13</b>
VQ25DE	134 182
Ignition Coil	<b>80372</b>
<b>Teana II (J32) 3.5</b>	<b>2008-13</b>
VQ35DE	183 249
Ignition Coil	<b>80372</b>
<b>Terrano I (Wd21) 3.0 i 4WD</b>	<b>1990-95</b>
VG30E	109 148
Ignition Coil	<b>80286</b>
<b>Terrano II (R20) 2.4 4WD</b>	<b>1996-02</b>
KA24E	85 116
Ignition Coil	<b>80286</b>
<b>Terrano II (R20) 2.4 4WD</b>	<b>1996-07</b>
KA24E	87 118
Ignition Coil	<b>80286</b>
<b>Terrano II (R20) 2.4 i 12V 4WD</b>	<b>1993-97</b>
KA24E	91 124
Ignition Coil	<b>80286</b>
<b>Tiida Fastback (C11) 1.5</b>	<b>2004-12</b>
HR15DE	80 109
Ignition Coil	<b>80372</b>
Ignition Coil	<b>80375</b>
<b>Tiida Fastback (C11) 1.5 4x4</b>	<b>2004-07</b>
HR15DE	80 109
Ignition Coil	<b>80372</b>



NISSAN Cont.	
<b>Tiida Fastback (C11) 1.8 Flex</b>	2009-11
MR18DE	92 125
Ignition Coil	<b>80375</b>
<b>Tiida Fastback (C11X) 1.6</b>	2007-11
HR16DE	81 110
Ignition Coil	<b>80288</b>
Ignition Coil Euro 5	<b>80375</b>
<b>Tiida Fastback (C11X) 1.8</b>	2007-11
MR18DE	93 126
Ignition Coil	<b>80288</b>
<b>Tiida Sedan (Sc11X) 1.6</b>	2007-12
HR16DE	81 110
Ignition Coil	<b>80288</b>
Ignition Coil 03.2010->; Euro 5	<b>80375</b>
<b>Tiida Sedan (Sc11X) 1.8</b>	2007-12
MR18DE	93 126
Ignition Coil	<b>80288</b>
<b>Vanette Bus (Kc120) 1.5</b>	1983-87
A15	51 69
Ignition Leads A15	<b>83210</b>
<b>Vanette Cargo Bus (HC 23) 1.6 i</b>	1996-01
GA16DE	72 98
Ignition Coil	<b>80286</b>
Ignition Leads	<b>85320</b>
Ignition Leads	<b>85850</b>
<b>Vanette Cargo Van (HC 23) 1.6 i</b>	1994-01
GA16DE	71 97
Ignition Coil	<b>80286</b>
<b>X-Trail (T30) 2.0</b>	2001-13
QR20DE	103 140
Ignition Coil	<b>80371</b>
<b>X-Trail (T30) 2.0 4x4</b>	2001-13
QR20DE	103 140
Ignition Coil	<b>80371</b>
<b>X-Trail (T30) 2.5 4x4</b>	2002-13
QR25DE	121 165
Ignition Coil	<b>80371</b>
<b>X-Trail (T30) 2.5 4x4</b>	2002-13
QR25DE	132 179
Ignition Coil	<b>80371</b>
Ignition Coil ->01.2010	<b>80375</b>
<b>X-Trail (T31) 2.0</b>	2007-13
MR20DE	104 141
Ignition Coil	<b>80288</b>
<b>X-Trail (T31) 2.0</b>	2008-13
MR20DE	103 140
Ignition Coil	<b>80288</b>
<b>X-Trail (T31) 2.0 FWD</b>	2008-13
MR20DE	103 140
Ignition Coil	<b>80288</b>
<b>X-Trail (T31) 2.5 4x4</b>	2007->
QR25DE	124 169
Ignition Coil	<b>80288</b>
Ignition Coil	<b>80375</b>

OPEL	
<b>Adam 1.2</b>	2012->
A 12 XEL/B 12 XEL	51 69
Ignition Coil	<b>80322</b>
<b>Adam 1.4</b>	2012->
A 14 XEL/B 14 XEL	64 87
Ignition Coil	<b>80322</b>
<b>Adam 1.4</b>	2012->
A 14 XER/B 14 XER	74 101
Ignition Coil	<b>80322</b>
<b>Adam 1.4 LPG</b>	2013->
A 14 XEL/B 14 XEL	64 87
Ignition Coil	<b>80322</b>
<b>Agila A (H00) 1.0</b>	2003-07
Z 10 XEP	44 60
Ignition Coil	<b>80259</b>
<b>Agila A (H00) 1.0 12V</b>	2000-07
Z 10 XE	43 58
Ignition Coil	<b>80259</b>
<b>Agila A (H00) 1.2 16V</b>	2000-07
Z 12 XE	55 75
Ignition Coil	<b>80257</b>

OPEL Cont.	
<b>Agila A (H00) 1.2 16V Twinport</b>	2004-07
Z 12 XEP	59 80
Ignition Coil	<b>80350</b>
<b>Agila B (H08) 1.0</b>	2011->
K10B	50 68
Ignition Coil	<b>80268</b>
<b>Agila B (H08) 1.0</b>	2008->
K10B	48 65
Ignition Coil	<b>80268</b>
<b>Agila B (H08) 1.0 LPG</b>	2010->
K10B	48 65
Ignition Coil	<b>80268</b>
<b>Agila B (H08) 1.2</b>	2008->
K12B	63 86
Ignition Coil	<b>80268</b>
<b>Agila B (H08) 1.2</b>	2010->
K12B	69 94
Ignition Coil	<b>80268</b>
<b>Agila B (H08) 1.2 LPG</b>	2008->
K12B	63 86
Ignition Coil	<b>80268</b>
<b>Ampera EV 150</b>	2011->
A 14 XFL	111 151
Ignition Coil	<b>80322</b>
<b>Antara 2.4</b>	2006->
Z 24 XED	104 141
Ignition Coil	<b>80317</b>
<b>Antara 2.4</b>	2008->
Z 24 XE	103 140
Ignition Coil	<b>80317</b>
<b>Antara 2.4</b>	2010->
A 24 XE	123 167
Ignition Coil	<b>80329</b>
<b>Antara 2.4 4x4</b>	2007->
Z 24 XE	103 140
Ignition Coil	<b>80317</b>
<b>Antara 2.4 4x4</b>	2010->
A 24 XE	123 167
Ignition Coil	<b>80329</b>
<b>Antara 2.4 LPG</b>	2008->
Z 24 XE	103 140
Ignition Coil	<b>80317</b>
<b>Antara 2.4 LPG 4x4</b>	2008->
Z 24 XE	103 140
Ignition Coil	<b>80317</b>
<b>Ascona A (81, 86, 87, 88) 1.2 S</b>	1972-75
12 S	44 60
Ignition Leads	<b>83550</b>
<b>Ascona A (81, 86, 87, 88) 1.6 N</b>	1975-75
16 N	44 60
Ignition Leads	<b>83550</b>
<b>Ascona A (81, 86, 87, 88) 1.6 N</b>	1970-75
16 N	50 68
Ignition Leads	<b>83550</b>
<b>Ascona A (81, 86, 87, 88) 1.6 S</b>	1975-75
16 S	55 75
Ignition Leads	<b>83550</b>
<b>Ascona A (81, 86, 87, 88) 1.6 S</b>	1970-75
16 S	59 80
Ignition Leads	<b>83550</b>
<b>Ascona B (81, 86, 87, 88) 1.3 N</b>	1979-81
13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads BOSCH	<b>83550</b>
<b>Ascona B (81, 86, 87, 88) 1.3 S</b>	1979-81
13 S	55 75
Ignition Coil	<b>80261</b>
<b>Ascona B (81, 86, 87, 88) 1.6 N</b>	1975-81
16 N	44 60
Ignition Leads BOSCH	<b>83550</b>
<b>Ascona B (81, 86, 87, 88) 1.6 S</b>	1975-81
16 S	55 75
Ignition Leads BOSCH	<b>83550</b>
<b>Ascona B (81, 86, 87, 88) 1.9 N</b>	1976-81
19 N	55 75
Ignition Leads	<b>83550</b>
<b>Ascona B (81, 86, 87, 88) 1.9 S</b>	1975-81
19 S	66 90
Ignition Leads	<b>83550</b>



OPEL Cont.	
<b>Ascona B (81, 86, 87, 88) 2.0 E</b>	<b>1979-81</b>
20 E	81 110
Ignition Leads	<b>83550</b>
<b>Ascona B (81, 86, 87, 88) 2.0 N</b>	<b>1977-81</b>
20 N	66 90
Ignition Leads	<b>83550</b>
<b>Ascona B (81, 86, 87, 88) 2.0 S</b>	<b>1977-81</b>
20 S	74 100
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83550</b>
<b>Ascona C (81, 86, 87, 88) 1.3 N</b>	<b>1981-86</b>
13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
Ignition Leads BOSCH	<b>83550</b>
Ignition Leads Engine 879422->	<b>83570</b>
<b>Ascona C (81, 86, 87, 88) 1.3 S</b>	<b>1981-88</b>
13 S	55 75
Ignition Coil	<b>80261</b>
Ignition Leads BOSCH	<b>83550</b>
Ignition Leads Engine 885919->	<b>83570</b>
<b>Ascona C (81, 86, 87, 88) 1.6</b>	<b>1981-87</b>
16 N	55 75
Ignition Coil	<b>80261</b>
Ignition Leads BOSCH	<b>83550</b>
<b>Ascona C (81, 86, 87, 88) 1.6</b>	<b>1986-88</b>
16 SV	60 82
Ignition Coil	<b>80261</b>
Ignition Leads BOSCH	<b>83550</b>
Ignition Leads	<b>83570</b>
<b>Ascona C (81, 86, 87, 88) 1.6 i</b>	<b>1987-88</b>
E 16 NZ/E 16 LZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads BOSCH	<b>83550</b>
Ignition Leads	<b>83570</b>
<b>Ascona C (81, 86, 87, 88) 1.6 i KAT</b>	<b>1986-88</b>
C 16 NZ/C 16 LZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads BOSCH	<b>83550</b>
Ignition Leads	<b>83560</b>
Ignition Leads	<b>83570</b>
<b>Ascona C (81, 86, 87, 88) 1.8</b>	<b>1987-88</b>
E 18 NV	62 84
Ignition Leads	<b>83550</b>
<b>Ascona C (81, 86, 87, 88) 1.8 E</b>	<b>1985-86</b>
S 18 NV/C 18 NE	74 100
Ignition Leads DIN	<b>83550</b>
<b>Ascona C (81, 86, 87, 88) 2.0 i</b>	<b>1987-88</b>
C 20 NEF	74 100
Ignition Leads	<b>83550</b>
<b>Ascona C (81, 86, 87, 88) 2.0 i</b>	<b>1986-88</b>
20 NE	85 115
Ignition Leads	<b>83550</b>
<b>Ascona C (81, 86, 87, 88) 2.0 i GT</b>	<b>1987-88</b>
20 SEH	95 130
Ignition Leads	<b>83550</b>
<b>Ascona C (81, 86, 87, 88) 2.0 i KAT</b>	<b>1986-88</b>
C 20 NE	85 116
Ignition Leads	<b>83550</b>
<b>Ascona C CC (84, 89) 1.3 N</b>	<b>1981-86</b>
13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
Ignition Leads Engine 879422->	<b>83570</b>
<b>Ascona C CC (84, 89) 1.3 S</b>	<b>1981-88</b>
13 S	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
Ignition Leads Engine 885919->	<b>83570</b>
<b>Ascona C CC (84, 89) 1.6</b>	<b>1981-88</b>
16 N	55 75
Ignition Coil	<b>80261</b>
<b>Ascona C CC (84, 89) 1.6</b>	<b>1986-88</b>
16 SV	60 82
Ignition Leads	<b>83570</b>

OPEL Cont.	
<b>Ascona C CC (84, 89) 1.6 i</b>	<b>1987-88</b>
E 16 NZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83550</b>
Ignition Leads	<b>83570</b>
<b>Ascona C CC (84, 89) 1.6 i KAT</b>	<b>1986-88</b>
C 16 NZ/C 16 LZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads	<b>83570</b>
<b>Ascona C CC (84, 89) 1.8</b>	<b>1987-88</b>
E 18 NV	62 84
Ignition Leads	<b>83550</b>
<b>Ascona C CC (84, 89) 1.8 E</b>	<b>1985-86</b>
S 18 NV/C 18 NE	74 100
Ignition Leads DIN	<b>83550</b>
<b>Ascona C CC (84, 89) 2.0 i</b>	<b>1986-88</b>
20 NE	85 115
Ignition Leads	<b>83550</b>
<b>Ascona C CC (84, 89) 2.0 i GT</b>	<b>1987-88</b>
20 SEH	95 130
Ignition Leads	<b>83550</b>
<b>Ascona C CC (84, 89) 2.0 i KAT</b>	<b>1986-88</b>
C 20 NE	85 116
Ignition Leads	<b>83550</b>
<b>Astra F (56, 57) 1.4</b>	<b>1991-93</b>
14 NV	55 75
Ignition Coil	<b>80210</b>
Ignition Coil Bosch	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Astra F (56, 57) 1.4</b>	<b>1992-98</b>
14 SE	60 82
Ignition Coil	<b>80210</b>
Ignition Coil ->Engine 02T14052; ->02.1998; SAGEM	<b>80262</b>
Ignition Leads Engine 02V57975-02BD0921; 11.1994->	<b>85100</b>
Ignition Leads Engine M19585416-02T14052; 05.1993->	<b>85105</b>
<b>Astra F (56, 57) 1.4 i</b>	<b>1991-98</b>
C 14 NZ/X 14 NZ	44 60
Ignition Coil C 14 NZ; With regul.cat.(3way)	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads C 14 NZ; ->Engine 19241623; ->07.1995	<b>83800</b>
Ignition Leads C 14 NZ; Engine 19241624->; ->08.1995	<b>85105</b>
<b>Astra F (56, 57) 1.4 i 16V</b>	<b>1996-98</b>
X 14 XE	66 90
Ignition Coil	<b>80210</b>
<b>Astra F (56, 57) 1.4 Si</b>	<b>1992-98</b>
C 14 SE	60 82
Ignition Coil With regul.cat.(3way)	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads Engine 02BD0922->; 08.1995->	<b>85085</b>
Ignition Leads Engine 02V57975-02BD0921; 11.1994->	<b>85100</b>
Ignition Leads ->Engine 02T14052; 05.1993->	<b>85105</b>
<b>Astra F (56, 57) 1.6</b>	<b>1995-98</b>
16 NZR/16 LZ2	55 75
Ignition Coil	<b>80210</b>
Ignition Coil	<b>80261</b>
Ignition Coil ->02.1998	<b>80262</b>
Ignition Leads Engine 02BE6167->	<b>85085</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85087</b>
Ignition Leads ->Engine 02BE6166	<b>85100</b>
<b>Astra F (56, 57) 1.6 i</b>	<b>1993-96</b>
X 16 SZ	52 71
Ignition Coil	<b>80210</b>
Ignition Leads Engine 02BE6167->	<b>85085</b>
Ignition Leads ->Engine 02BE6166	<b>85100</b>
<b>Astra F (56, 57) 1.6 i</b>	<b>1992-98</b>
C 16 NZ/X 16 SZR	55 75
Ignition Coil C 16 NZ; With regul.cat.(3way)	<b>80210</b>
Ignition Coil	<b>80261</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85087</b>
<b>Astra F (56, 57) 1.6 i 16V</b>	<b>1994-98</b>
X 16 XEL	74 100
Ignition Coil	<b>80210</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85080</b>
<b>Astra F (56, 57) 1.6 Si</b>	<b>1992-94</b>
C 16 SE	74 100
Ignition Coil	<b>80210</b>
Ignition Leads Engine 02V65826->	<b>85100</b>





OPEL Cont.	
<b>Astra F (56, 57) 1.8 i</b>	1992-98
C 18 NZ	66 90
Ignition Coil	80262
<b>Astra F (56, 57) 1.8 i 16V</b>	1995-96
18 SE	82 112
Ignition Leads ->Engine 14258179	83550
<b>Astra F (56, 57) 1.8 i 16V</b>	1993-94
C 18 XE	92 125
Ignition Coil With regul.cat.(3way)	80223
<b>Astra F (56, 57) 1.8 i 16V</b>	1994-98
C 18 XEL/X 18 XE	85 116
Ignition Coil With regul.cat.(3way)	80223
<b>Astra F (56, 57) 2.0 i 16V</b>	1995-98
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	80223
<b>Astra F Cabriolet (53B) 1.4 i 16V</b>	1996-01
X 14 XE	66 90
Ignition Coil	80210
<b>Astra F Cabriolet (53B) 1.4 Si</b>	1993-01
C 14 SE	60 82
Ignition Coil With regul.cat.(3way)	80210
Ignition Coil	80262
Ignition Leads Engine 02BD0922->; 08.1995->	85085
Ignition Leads Engine 02V57975-02BD0921; 11.1994->	85100
Ignition Leads	85105
<b>Astra F Cabriolet (53B) 1.6 i</b>	1993-96
X 16 SZ	52 71
Ignition Coil	80210
Ignition Leads Engine 02BE6167->	85085
Ignition Leads ->Engine 02BE6166	85100
<b>Astra F Cabriolet (53B) 1.6 i</b>	1996-01
X 16 SZR	55 75
Ignition Coil	80210
Ignition Leads Engine 02BE6167->	85085
Ignition Leads ->Engine 02BE6166	85100
<b>Astra F Cabriolet (53B) 1.8 i 16V</b>	1994-01
C 18 XEL/X 18 XE	85 116
Ignition Coil With regul.cat.(3way)	80223
<b>Astra F Caravan (51, 52) 1.4</b>	1991-93
14 NV	55 75
Ignition Coil	80210
Ignition Coil Bosch	80262
Ignition Leads SAE	83800
Ignition Leads	85105
<b>Astra F Caravan (51, 52) 1.4</b>	1992-98
14 SE	60 82
Ignition Coil	80210
Ignition Coil ->Engine 02T14052; SAGEM	80262
Ignition Leads Engine 02V57975-02BD0921; 11.1994->	85100
Ignition Leads Engine M19585416-02T14052; 05.1993->	85105
<b>Astra F Caravan (51, 52) 1.4 i</b>	1991-98
C 14 NZ	44 60
Ignition Coil With regul.cat.(3way)	80210
Ignition Coil	80262
Ignition Leads ->Engine 19241623; ->07.1995	83800
Ignition Leads Engine 19241624->; ->08.1995	85105
<b>Astra F Caravan (51, 52) 1.4 i 16V</b>	1996-98
X 14 XE	66 90
Ignition Coil	80210
<b>Astra F Caravan (51, 52) 1.4 Si</b>	1992-98
C 14 SE	60 82
Ignition Coil With regul.cat.(3way)	80210
Ignition Coil	80262
Ignition Leads Engine 02BD0922->; 08.1995->	85085
Ignition Leads Engine 02V57975-02BD0921; 11.1994->	85100
Ignition Leads ->Engine 02T14052; 05.1993->	85105
<b>Astra F Caravan (51, 52) 1.6</b>	1995-98
16 NZR/16 LZ2	55 75
Ignition Coil	80210
Ignition Coil SAGEM	80262
Ignition Leads Engine 02BE6167->	85085
Ignition Leads Engine 02BF1477,19241624->	85087
Ignition Leads ->Engine 02BE6166	85100
<b>Astra F Caravan (51, 52) 1.6 i</b>	1993-96
X 16 SZ	52 71
Ignition Coil	80210
Ignition Leads Engine 02BE6167->	85085
Ignition Leads ->Engine 02BE6166	85100

OPEL Cont.	
<b>Astra F Caravan (51, 52) 1.6 i</b>	1991-98
C 16 NZ/X 16 SZR	55 75
Ignition Coil With regul.cat.(3way)	80210
Ignition Coil	80261
Ignition Leads X 16 SZR; Engine 02BE6167->	85085
Ignition Leads X 16 SZR; ->Engine 02BE6166	85100
<b>Astra F Caravan (51, 52) 1.6 i 16V</b>	1994-98
X 16 XEL	74 100
Ignition Coil	80210
Ignition Leads Engine 02BF1477,19241624->	85080
<b>Astra F Caravan (51, 52) 1.6 Si</b>	1992-94
C 16 SE	74 100
Ignition Coil	80210
Ignition Leads	85100
<b>Astra F Caravan (51, 52) 1.8 i</b>	1991-98
C 18 NZ	66 90
Ignition Coil	80262
<b>Astra F Caravan (51, 52) 1.8 i 16V</b>	1993-98
C 18 XE	92 125
Ignition Coil With regul.cat.(3way)	80223
<b>Astra F Caravan (51, 52) 1.8 i 16V</b>	1994-98
C 18 XEL/X 18 XE	85 116
Ignition Coil With regul.cat.(3way)	80223
<b>Astra F Caravan (51, 52) 2.0 i 16V</b>	1993-98
C 20 XE	110 150
Ignition Coil	80289
<b>Astra F Caravan (51, 52) 2.0 i 16V</b>	1995-98
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	80223
<b>Astra F CC (53, 54, 58, 59) 1.4</b>	1991-93
14 NV	55 75
Ignition Coil	80210
Ignition Coil Bosch	80262
Ignition Leads SAE	83800
Ignition Leads	85105
<b>Astra F CC (53, 54, 58, 59) 1.4</b>	1992-98
14 SE	60 82
Ignition Coil	80210
Ignition Coil ->Engine 02T14052; SAGEM	80262
Ignition Leads Engine 02V57974-02B01413	83800
Ignition Leads Engine 02BD0922->; 11.1994->	85085
Ignition Leads Engine 02V57975-02BD0921; 11.1994->	85100
Ignition Leads Engine M19585416-02T14052; 05.1993->	85105
<b>Astra F CC (53, 54, 58, 59) 1.4 i</b>	1992-98
C 14 NZ	44 60
Ignition Coil With regul.cat.(3way)	80210
Ignition Coil	80262
Ignition Leads ->Engine 19241623; ->07.1995	83800
Ignition Leads Engine 19241624->; ->08.1995	85105
<b>Astra F CC (53, 54, 58, 59) 1.4 i 16V</b>	1996-98
X 14 XE	66 90
Ignition Coil	80210
<b>Astra F CC (53, 54, 58, 59) 1.4 Si</b>	1992-98
C 14 SE	60 82
Ignition Coil With regul.cat.(3way)	80210
Ignition Coil	80262
Ignition Leads Engine 02BD0922->; 08.1995->	85085
Ignition Leads Engine 02V57975-02BD0921; 11.1994->	85100
Ignition Leads ->Engine 02T14052; 05.1993->	85105
<b>Astra F CC (53, 54, 58, 59) 1.6</b>	1995-98
16 NZR/16 LZ2	55 75
Ignition Coil	80210
Ignition Coil	80262
Ignition Leads Engine 02BE6167->	85085
Ignition Leads Engine 02BF1477,19241624->	85087
Ignition Leads ->Engine 02BE6166	85100
<b>Astra F CC (53, 54, 58, 59) 1.6 i</b>	1993-96
X 16 SZ	52 71
Ignition Coil	80210
Ignition Leads Engine 02BE6167->	85085
Ignition Leads ->Engine 02BE6166	85100
<b>Astra F CC (53, 54, 58, 59) 1.6 i</b>	1991-98
C 16 NZ/X 16 SZR	55 75
Ignition Coil With regul.cat.(3way)	80210
Ignition Coil	80261
Ignition Leads X 16 SZR; Engine 02BE6167->	85085
Ignition Leads X 16 SZR; ->Engine 02BE6166	85100



OPEL Cont.	
<b>Astra F CC (53, 54, 58, 59) 1.6 i 16V</b>	<b>1994-98</b>
X 16 XEL	74 100
Ignition Coil	<b>80210</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85080</b>
<b>Astra F CC (53, 54, 58, 59) 1.6 Si</b>	<b>1992-94</b>
C 16 SE	74 100
Ignition Coil	<b>80210</b>
Ignition Leads	<b>85100</b>
<b>Astra F CC (53, 54, 58, 59) 1.8 i</b>	<b>1991-98</b>
C 18 NZ	66 90
Ignition Coil	<b>80262</b>
<b>Astra F CC (53, 54, 58, 59) 1.8 i 16V</b>	<b>1994-98</b>
C 18 XEL/X 18 XE	85 116
Ignition Coil With regul.cat.(3way)	<b>80223</b>
<b>Astra F CC (53, 54, 58, 59) 1.8 i 16V</b>	<b>1993-94</b>
C 18 XE	92 125
Ignition Coil With regul.cat.(3way)	<b>80223</b>
<b>Astra F CC (53, 54, 58, 59) 2.0 GSI 16V</b>	<b>1991-98</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Astra F CC (53, 54, 58, 59) 2.0 i 16V</b>	<b>1995-98</b>
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	<b>80223</b>
<b>Astra F Classic Caravan 1.4 i</b>	<b>1998-05</b>
X 14 NZ	44 60
Ignition Coil	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astra F Classic Caravan 1.6 i</b>	<b>1998-05</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
Ignition Leads	<b>85085</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85087</b>
<b>Astra F Classic Caravan 1.6 i 16V</b>	<b>1998-05</b>
X 16 XEL	74 101
Ignition Coil	<b>80210</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85080</b>
<b>Astra F Classic Cc 1.4 i</b>	<b>1998-02</b>
X 14 NZ	44 60
Ignition Coil	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads Engine 02BE6167->	<b>85085</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85087</b>
Ignition Leads ->Engine 02BE6166	<b>85100</b>
Ignition Leads	<b>85105</b>
<b>Astra F Classic Cc 1.6 i</b>	<b>1998-02</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
Ignition Leads	<b>85085</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85087</b>
<b>Astra F Classic Cc 1.6 i 16V</b>	<b>1998-02</b>
X 16 XEL	74 101
Ignition Coil	<b>80210</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85080</b>
<b>Astra F Classic Sedan 1.4 i</b>	<b>1998-02</b>
X 14 NZ	44 60
Ignition Coil	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astra F Classic Sedan 1.6 i</b>	<b>1998-02</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
Ignition Leads	<b>85085</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85087</b>
<b>Astra F Classic Sedan 1.6 i 16V</b>	<b>1998-02</b>
X 16 XEL	74 101
Ignition Coil	<b>80210</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85080</b>
<b>Astra F Van (55) 1.4 i</b>	<b>1991-99</b>
C 14 NZ	44 60
Ignition Coil With regul.cat.(3way)	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads ->Engine 19241623	<b>83800</b>
Ignition Leads Engine 19241624->	<b>85105</b>

OPEL Cont.	
<b>Astra F Van (55) 1.6 i</b>	<b>1991-93</b>
C 16 NZ	55 75
Ignition Coil With regul.cat.(3way)	<b>80210</b>
Ignition Coil	<b>80261</b>
Ignition Leads Engine 02BF1477,19241624->	<b>85087</b>
Ignition Leads ->Engine 02BE6166	<b>85100</b>
<b>Astra F Van (55) 1.6 i</b>	<b>1993-96</b>
X 16 SZ	52 71
Ignition Coil	<b>80210</b>
Ignition Leads Engine 02BE61167->	<b>85085</b>
Ignition Leads ->Engine 02BE6166	<b>85100</b>
<b>Astra G Cabriolet (F67) 1.6</b>	<b>2003-05</b>
Z 16 XEP	76 103
Ignition Coil	<b>80291</b>
<b>Astra G Cabriolet (F67) 1.6 16V</b>	<b>2001-05</b>
Z 16 XE	74 101
Ignition Coil With regul.cat.(3way)	<b>80209</b>
Ignition Leads	<b>85080</b>
<b>Astra G Cabriolet (F67) 1.8 16V</b>	<b>2001-05</b>
Z 18 XE	92 125
Ignition Coil ->08.2004	<b>80224</b>
<b>Astra G Cabriolet (F67) 2.0 16V Turbo</b>	<b>2002-05</b>
Z 20 LET	147 200
Ignition Coil ->08.2005	<b>80354</b>
<b>Astra G Cabriolet (F67) 2.0 OPC</b>	<b>2002-05</b>
Z 20 LET	141 192
Ignition Coil ->08.2005	<b>80354</b>
<b>Astra G Caravan (F35) 1.2 16V</b>	<b>2000-04</b>
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Astra G Caravan (F35) 1.2 16V</b>	<b>1998-00</b>
X 12 XE	48 65
Ignition Coil	<b>80257</b>
<b>Astra G Caravan (F35) 1.4</b>	<b>2004-09</b>
Z 14 XEP	66 90
Ignition Coil ->07.2009	<b>80350</b>
<b>Astra G Caravan (F35) 1.4 16V</b>	<b>1998-04</b>
X 14 XE/Z 14 XE	66 90
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Astra G Caravan (F35) 1.6</b>	<b>2000-04</b>
Z 16 SE	62 84
Ignition Coil	<b>80320</b>
Ignition Leads	<b>85085</b>
<b>Astra G Caravan (F35) 1.6</b>	<b>2002-09</b>
Z 16 XEP	76 103
Ignition Coil	<b>80291</b>
<b>Astra G Caravan (F35) 1.6</b>	<b>1998-00</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
Ignition Leads	<b>85084</b>
<b>Astra G Caravan (F35) 1.6 16V</b>	<b>1998-04</b>
Z 16 XE/X 16 XEL	74 101
Ignition Coil With regul.cat.(3way)	<b>80209</b>
Ignition Leads	<b>85080</b>
<b>Astra G Caravan (F35) 1.6 CNG</b>	<b>2003-04</b>
Z 16 YNG	71 97
Ignition Coil	<b>80209</b>
<b>Astra G Caravan (F35) 1.8 16V</b>	<b>2000-04</b>
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra G Caravan (F35) 1.8 16V</b>	<b>1998-00</b>
X 18 XE1	85 116
Ignition Coil X 18 XE1	<b>80224</b>
<b>Astra G Caravan (F35) 2.0 16V</b>	<b>1998-04</b>
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	<b>80223</b>
Ignition Coil X 20 XEV	<b>80224</b>
<b>Astra G Caravan (F35) 2.0 OPC</b>	<b>2002-04</b>
Z 20 LET	141 192
Ignition Coil ->06.2004	<b>80354</b>
<b>Astra G Caravan (F35) 2.0 OPC</b>	<b>2002-04</b>
Z 20 LET	147 200
Ignition Coil ->06.2004	<b>80354</b>
<b>Astra G CC (F48, F08) 1.2 16V</b>	<b>2000-05</b>
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Astra G CC (F48, F08) 1.2 16V</b>	<b>1998-00</b>
X 12 XE	48 65
Ignition Coil	<b>80257</b>



OPEL Cont.	
<b>Astra G CC (F48, F08) 1.4</b>	<b>2007-09</b>
Z 14 XEP	66 90
Ignition Coil ->06.2009	<b>80350</b>
<b>Astra G CC (F48, F08) 1.4 16V</b>	<b>1998-05</b>
X 14 XE/Z 14 XE	66 90
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Astra G CC (F48, F08) 1.6</b>	<b>2000-05</b>
Z 16 SE	62 84
Ignition Leads	<b>85085</b>
<b>Astra G CC (F48, F08) 1.6</b>	<b>2002-09</b>
Z 16 XEP	76 103
Ignition Coil	<b>80291</b>
<b>Astra G CC (F48, F08) 1.6</b>	<b>1998-00</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
Ignition Leads	<b>85084</b>
<b>Astra G CC (F48, F08) 1.6 16V</b>	<b>1998-05</b>
Z 16 XE/X 16 XEL/C 16 SEL	74 101
Ignition Coil Z 16 XE, X 16 XEL; With regul.cat.(3way)	<b>80209</b>
Ignition Leads	<b>85080</b>
<b>Astra G CC (F48, F08) 1.8 16V</b>	<b>2000-05</b>
Z 18 XE	92 125
Ignition Coil ->08.2004	<b>80224</b>
<b>Astra G CC (F48, F08) 1.8 16V</b>	<b>1998-00</b>
X 18 XE1	85 116
Ignition Coil X 18 XE1	<b>80224</b>
<b>Astra G CC (F48, F08) 2.0 16V</b>	<b>1998-05</b>
X 20 XEV/C 20 SEL	100 136
Ignition Coil X 20 XEV; With regul.cat.(3way)	<b>80223</b>
Ignition Coil X 20 XEV; ->08.2004	<b>80224</b>
<b>Astra G CC (F48, F08) 2.0 16V OPC</b>	<b>1999-02</b>
X 20 XER	118 160
Ignition Coil With regul.cat.(3way)	<b>80223</b>
<b>Astra G CC (F48, F08) 2.0 OPC</b>	<b>2002-05</b>
Z 20 LET	141 192
Ignition Coil ->02.2004	<b>80354</b>
<b>Astra G CC (F48, F08) 2.0 OPC</b>	<b>2002-05</b>
Z 20 LET	147 200
Ignition Coil ->02.2004	<b>80354</b>
<b>Astra G Coupe (F07) 1.6 16V</b>	<b>2000-05</b>
Z 16 XEP	76 103
Ignition Coil	<b>80291</b>
Ignition Leads	<b>85080</b>
<b>Astra G Coupe (F07) 1.6 16V</b>	<b>2000-05</b>
Z 16 XE	74 101
Ignition Coil ->Engine 41000000	<b>80209</b>
<b>Astra G Coupe (F07) 1.8 16V</b>	<b>2000-00</b>
X 18 XE1	85 116
Ignition Coil X 18 XE1	<b>80224</b>
<b>Astra G Coupe (F07) 1.8 16V</b>	<b>2000-05</b>
Z 18 XE	92 125
Ignition Coil ->08.2004	<b>80224</b>
<b>Astra G Coupe (F07) 2.0 16V Turbo</b>	<b>2000-01</b>
Z 20 LET	140 190
Ignition Coil	<b>80354</b>
<b>Astra G Coupe (F07) 2.0 16V Turbo</b>	<b>2001-05</b>
Z 20 LET	141 192
Ignition Coil ->02.2005	<b>80354</b>
<b>Astra G Coupe (F07) 2.0 16V Turbo</b>	<b>2002-05</b>
Z 20 LET	147 200
Ignition Coil ->02.2005	<b>80354</b>
<b>Astra G Sedan (F69) 1.2 16V</b>	<b>1998-00</b>
X 12 XE	48 65
Ignition Coil	<b>80257</b>
<b>Astra G Sedan (F69) 1.2 16V</b>	<b>2000-05</b>
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Astra G Sedan (F69) 1.4</b>	<b>2007-09</b>
Z 14 XEP	66 90
Ignition Coil ->06.2009	<b>80350</b>
<b>Astra G Sedan (F69) 1.4 16V</b>	<b>1998-05</b>
X 14 XE/Z 14 XE	66 90
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Astra G Sedan (F69) 1.6</b>	<b>2000-05</b>
Z 16 SE	62 84
Ignition Leads	<b>85085</b>
<b>Astra G Sedan (F69) 1.6</b>	<b>2002-09</b>
Z 16 XEP	76 103
Ignition Coil	<b>80291</b>

OPEL Cont.	
<b>Astra G Sedan (F69) 1.6</b>	<b>1998-00</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
Ignition Leads	<b>85084</b>
<b>Astra G Sedan (F69) 1.6 16V</b>	<b>1998-05</b>
Z 16 XE/X 16 XEL	74 101
Ignition Coil With regul.cat.(3way)	<b>80209</b>
Ignition Leads	<b>85080</b>
<b>Astra G Sedan (F69) 1.8 16V</b>	<b>2000-05</b>
Z 18 XE	92 125
Ignition Coil ->08.2004	<b>80224</b>
<b>Astra G Sedan (F69) 1.8 16V</b>	<b>1998-00</b>
X 18 XE1	85 116
Ignition Coil X 18 XE1	<b>80224</b>
<b>Astra G Sedan (F69) 2.0 16V</b>	<b>1998-05</b>
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	<b>80223</b>
Ignition Coil X 20 XEV	<b>80224</b>
<b>Astra G Van (F70) 1.6</b>	<b>1999-00</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
Ignition Leads	<b>85084</b>
<b>Astra G Van (F70) 1.6</b>	<b>2000-05</b>
Z 16 SE	62 84
Ignition Leads	<b>85085</b>
<b>Astra GTC J 1.4</b>	<b>2011-&gt;</b>
A 14 XER	74 101
Ignition Coil	<b>80322</b>
<b>Astra GTC J 1.4</b>	<b>2011-&gt;</b>
B 14 NEL/A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Astra GTC J 1.4</b>	<b>2011-&gt;</b>
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Astra GTC J 1.6</b>	<b>2011-&gt;</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Astra GTC J 1.8</b>	<b>2011-&gt;</b>
A 18 XER	103 140
Ignition Coil	<b>80321</b>
<b>Astra GTC J 2.0</b>	<b>2012-&gt;</b>
A 20 NFT/B 20 NFT	206 280
Ignition Coil	<b>80329</b>
<b>Astra H (L48) 1.2</b>	<b>2005-10</b>
Z 12 XEP	59 80
Ignition Coil ->03.2009	<b>80350</b>
<b>Astra H (L48) 1.4</b>	<b>2004-10</b>
Z 14 XEP	66 90
Ignition Coil ->03.2010	<b>80350</b>
<b>Astra H (L48) 1.4</b>	<b>2004-04</b>
Z 14 XEL	59 80
Ignition Coil 09.2004->	<b>80350</b>
<b>Astra H (L48) 1.4</b>	<b>2004-04</b>
Z 14 XEL	55 75
Ignition Coil 09.2004->	<b>80350</b>
<b>Astra H (L48) 1.4 LPG</b>	<b>2009-10</b>
Z 14 XEP	66 90
Ignition Coil ->03.2010	<b>80350</b>
<b>Astra H (L48) 1.6</b>	<b>2004-10</b>
Z 16 XE1/Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Astra H (L48) 1.6</b>	<b>2006-14</b>
A 16 XER/Z 16 XER	85 116
Ignition Coil	<b>80291</b>
<b>Astra H (L48) 1.6 Turbo</b>	<b>2007-10</b>
Z 16 LET	132 180
Ignition Coil	<b>80291</b>
<b>Astra H (L48) 1.8</b>	<b>2004-10</b>
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra H (L48) 1.8</b>	<b>2006-10</b>
Z 18 XER/A 18 XER	103 140
Ignition Coil	<b>80291</b>
<b>Astra H (L48) 2.0 Turbo</b>	<b>2004-10</b>
Z 20 LEL	125 170
Ignition Coil ->02.2009	<b>80354</b>
<b>Astra H (L48) 2.0 Turbo</b>	<b>2004-10</b>
Z 20 LER	147 200
Ignition Coil ->03.2010	<b>80354</b>



OPEL Cont.	
<b>Astra H (L48) 2.0 Turbo</b>	<b>2005-10</b>
Z 20 LEH	177 240
Ignition Coil ->03.2010	<b>80354</b>
<b>Astra H Caravan (L35) 1.4</b>	<b>2004-10</b>
Z 14 XEP	66 90
Ignition Coil ->03.2010	<b>80350</b>
<b>Astra H Caravan (L35) 1.4</b>	<b>2004-10</b>
Z 14 XEL	55 75
Ignition Coil ->09.2005	<b>80350</b>
<b>Astra H Caravan (L35) 1.4 LPG</b>	<b>2009-10</b>
Z 14 XEP	66 90
Ignition Coil ->03.2010	<b>80350</b>
<b>Astra H Caravan (L35) 1.6</b>	<b>2004-10</b>
Z 16 XE1/Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Astra H Caravan (L35) 1.6</b>	<b>2006-14</b>
A 16 XER/Z 16 XER	85 116
Ignition Coil	<b>80291</b>
<b>Astra H Caravan (L35) 1.6 LPG</b>	<b>2009-10</b>
Z 16 XER	85 116
Ignition Coil	<b>80291</b>
<b>Astra H Caravan (L35) 1.6 Turbo</b>	<b>2007-10</b>
Z 16 LET	132 180
Ignition Coil	<b>80291</b>
<b>Astra H Caravan (L35) 1.8</b>	<b>2004-10</b>
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra H Caravan (L35) 1.8</b>	<b>2005-10</b>
Z 18 XER/A 18 XER	103 140
Ignition Coil	<b>80291</b>
<b>Astra H Caravan (L35) 2.0 Turbo</b>	<b>2004-10</b>
Z 20 LEL	125 170
Ignition Coil ->02.2009	<b>80354</b>
<b>Astra H Caravan (L35) 2.0 Turbo</b>	<b>2004-10</b>
Z 20 LER	147 200
Ignition Coil ->03.2010	<b>80354</b>
<b>Astra H GTC (L08) 1.4</b>	<b>2005-10</b>
Z 14 XEP	66 90
Ignition Coil ->03.2009	<b>80350</b>
<b>Astra H GTC (L08) 1.4</b>	<b>2005-10</b>
Z 14 XEL	55 75
Ignition Coil ->02.2009	<b>80350</b>
<b>Astra H GTC (L08) 1.6</b>	<b>2005-10</b>
Z 16 XE1/Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Astra H GTC (L08) 1.6</b>	<b>2006-10</b>
Z 16 XER	85 116
Ignition Coil	<b>80291</b>
<b>Astra H GTC (L08) 1.6 Turbo</b>	<b>2007-10</b>
Z 16 LET	132 180
Ignition Coil	<b>80291</b>
<b>Astra H GTC (L08) 1.8</b>	<b>2005-&gt;</b>
Z 18 XE	92 125
Ignition Coil	<b>80224</b>
<b>Astra H GTC (L08) 1.8</b>	<b>2006-10</b>
Z 18 XER	103 140
Ignition Coil	<b>80291</b>
<b>Astra H GTC (L08) 2.0 Turbo</b>	<b>2005-10</b>
Z 20 LER	147 200
Ignition Coil ->09.2009	<b>80354</b>
<b>Astra H GTC (L08) 2.0 Turbo</b>	<b>2005-10</b>
Z 20 LEL	125 170
Ignition Coil ->02.2009	<b>80354</b>
<b>Astra H GTC (L08) 2.0 Turbo</b>	<b>2005-10</b>
Z 20 LEH	177 240
Ignition Coil ->03.2009	<b>80354</b>
<b>Astra H Twintop (L67) 1.6</b>	<b>2005-10</b>
Z 16 XE1/Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Astra H Twintop (L67) 1.6</b>	<b>2006-10</b>
Z 16 XER	85 116
Ignition Coil	<b>80291</b>
<b>Astra H Twintop (L67) 1.6 Turbo</b>	<b>2007-10</b>
Z 16 LET	132 180
Ignition Coil	<b>80291</b>
<b>Astra H Twintop (L67) 1.8</b>	<b>2005-&gt;</b>
Z 18 XE	92 125
Ignition Coil	<b>80224</b>

OPEL Cont.	
<b>Astra H Twintop (L67) 1.8</b>	<b>2005-10</b>
Z 18 XER/A 18 XER	103 140
Ignition Coil	<b>80291</b>
<b>Astra H Twintop (L67) 2.0 Turbo</b>	<b>2005-10</b>
Z 20 LEL	125 170
Ignition Coil ->02.2009	<b>80354</b>
<b>Astra H Twintop (L67) 2.0 Turbo</b>	<b>2005-10</b>
Z 20 LER	147 200
Ignition Coil	<b>80354</b>
<b>Astra J 1.4</b>	<b>2009-&gt;</b>
A 14 XEL	64 87
Ignition Coil	<b>80322</b>
<b>Astra J 1.4</b>	<b>2009-&gt;</b>
A 14 XER	74 100
Ignition Coil	<b>80322</b>
<b>Astra J 1.4 LPG</b>	<b>2012-&gt;</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Astra J 1.4 Turbo</b>	<b>2009-&gt;</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Astra J 1.4 Turbo</b>	<b>2010-&gt;</b>
B 14 NEL/A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Astra J 1.6</b>	<b>2009-&gt;</b>
A 16 XER/B 16 XER	85 115
Ignition Coil A16XER	<b>80321</b>
Ignition Coil A 16 XER; Engine 20SD0232->	<b>80352</b>
<b>Astra J 1.6 Turbo</b>	<b>2009-&gt;</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Astra J Sedan 1.4</b>	<b>2012-&gt;</b>
A 14 XER	74 101
Ignition Coil	<b>80322</b>
<b>Astra J Sedan 1.4 Turbo</b>	<b>2012-&gt;</b>
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Astra J Sedan 1.4 Turbo</b>	<b>2012-&gt;</b>
B 14 NEL/A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Astra J Sedan 1.6</b>	<b>2012-&gt;</b>
A 16 XER/B 16 XER	85 116
Ignition Coil A 16 XER	<b>80352</b>
<b>Astra J Sedan 1.6 Turbo</b>	<b>2012-&gt;</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Astra J Sports Tourer 1.4</b>	<b>2010-&gt;</b>
A 14 XER	74 101
Ignition Coil	<b>80322</b>
<b>Astra J Sports Tourer 1.4 LPG</b>	<b>2012-&gt;</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Astra J Sports Tourer 1.4 Turbo</b>	<b>2010-&gt;</b>
B 14 NEL/A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Astra J Sports Tourer 1.4 Turbo</b>	<b>2010-&gt;</b>
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Astra J Sports Tourer 1.6</b>	<b>2010-&gt;</b>
A 16 XER/B 16 XER	85 116
Ignition Coil A16XER	<b>80321</b>
<b>Astra J Sports Tourer 1.6 Turbo</b>	<b>2010-&gt;</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Calibra A (85) 2.0 i</b>	<b>1990-97</b>
C 20 NE	85 115
Ignition Leads Engine 14672353->; ->03.1997	<b>83800</b>
<b>Calibra A (85) 2.0 i 16V</b>	<b>1990-94</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Calibra A (85) 2.0 i 16V</b>	<b>1994-97</b>
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	<b>80223</b>
<b>Calibra A (85) 2.0 i 16V 4x4</b>	<b>1990-94</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Calibra A (85) 2.0 i 16V 4x4</b>	<b>1994-97</b>
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	<b>80223</b>





OPEL Cont.	
<b>Calibra A (85) 2.0 i 4x4</b>	1990-97
C 20 NE	85 115
Ignition Leads ->03.1997	<b>83800</b>
<b>Cascada (W13) 1.4</b>	2013->
A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Cascada (W13) 1.4 Turbo</b>	2013->
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Combo (71) 1.2</b>	1994-01
C 12 NZ/X 12 SZ	33 45
Ignition Coil	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads X 12 SZ; Engine 19330001->	<b>85085</b>
Ignition Leads C 12 NZ	<b>85105</b>
<b>Combo (71) 1.4</b>	1994-01
C 14 NZ/X 14 SZ	44 60
Ignition Coil With regul.cat.(3way)	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83570</b>
Ignition Leads X 14 SZ	<b>85084</b>
Ignition Leads	<b>85085</b>
Ignition Leads C 14 NZ	<b>85105</b>
<b>Combo (71) 1.4</b>	1994-01
C 14 SE	60 82
Ignition Coil	<b>80210</b>
Ignition Leads Engine 02BF1476,19241623->	<b>85085</b>
Ignition Leads ->Engine 02BD1412,19262000	<b>85100</b>
Ignition Leads ->Engine 02T14052	<b>85105</b>
<b>Combo Tour (X12) 1.4</b>	2012->
A 14 FC	88 120
Ignition Coil	<b>80267</b>
<b>Combo Tour (X12) 1.4 CNG</b>	2012->
A 14 FC	88 120
Ignition Coil	<b>80267</b>
<b>Combo Tour 1.4</b>	2004->
Z 14 XEP	66 90
Ignition Coil ->01.2011	<b>80350</b>
<b>Combo Tour 1.6 CNG</b>	2006->
Z 16 YNG	69 94
Ignition Coil	<b>80209</b>
<b>Combo Tour 1.6 CNG</b>	2005->
Z 16 YNG	71 97
Ignition Coil	<b>80209</b>
<b>Combo Van/Kombi (X12) 1.4</b>	2012->
A 14 FC	88 120
Ignition Coil	<b>80267</b>
<b>Combo Van/Kombi (X12) 1.4 CNG</b>	2012->
A 14 FC	88 120
Ignition Coil	<b>80267</b>
<b>Combo Van/Kombi 1.4 16V</b>	2005->
Z 14 XEP	66 90
Ignition Coil ->01.2011	<b>80350</b>
<b>Combo Van/Kombi 1.6 CNG 16V</b>	2006->
Z 16 YNG	69 94
Ignition Coil	<b>80209</b>
<b>Combo Van/Kombi 1.6 CNG 16V</b>	2005->
Z 16 YNG	71 97
Ignition Coil	<b>80209</b>
<b>Corsa A (93, 94, 98, 99) 1.0</b>	1982-93
10 S	33 45
Ignition Leads	<b>83500</b>
<b>Corsa A (93, 94, 98, 99) 1.2</b>	1982-90
12 S	44 60
Ignition Coil	<b>80261</b>
<b>Corsa A (93, 94, 98, 99) 1.2</b>	1982-90
E 12 GV/12 NC	33 45
Ignition Coil	<b>80262</b>
Ignition Leads	<b>83490</b>
Ignition Leads ->10.1987	<b>83500</b>
Ignition Leads SAE	<b>83570</b>
<b>Corsa A (93, 94, 98, 99) 1.2 i</b>	1989-93
C 12 NZ	33 45
Ignition Coil	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>

OPEL Cont.	
<b>Corsa A (93, 94, 98, 99) 1.2 N</b>	1990-93
12 NV	38 52
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
Ignition Leads	<b>83500</b>
<b>Corsa A (93, 94, 98, 99) 1.2 S</b>	1982-90
12 ST	40 55
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Corsa A (93, 94, 98, 99) 1.3</b>	1985-89
13 NB	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Corsa A (93, 94, 98, 99) 1.3 i</b>	1986-90
C 13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Corsa A (93, 94, 98, 99) 1.3 S</b>	1982-89
13 SB	51 70
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Corsa A (93, 94, 98, 99) 1.4 i</b>	1990-93
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83570</b>
Ignition Leads	<b>85105</b>
<b>Corsa A (93, 94, 98, 99) 1.4 S</b>	1990-93
14 NV	53 72
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83570</b>
Ignition Leads	<b>85105</b>
<b>Corsa A (93, 94, 98, 99) 1.4 Si</b>	1991-93
C 14 SE	60 82
Ignition Coil With regul.cat.(3way)	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads	<b>83570</b>
Ignition Leads ->Engine 02T14052	<b>83800</b>
Ignition Leads Engine 02T14053->	<b>85100</b>
Ignition Leads ->Engine 02T14052	<b>85105</b>
<b>Corsa A (93, 94, 98, 99) 1.6 GSI</b>	1988-92
C 16 NZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
<b>Corsa A (93, 94, 98, 99) 1.6 GSI</b>	1989-93
C 16 SEI	72 98
Ignition Coil	<b>80262</b>
Ignition Leads	<b>83550</b>
<b>Corsa A (93, 94, 98, 99) 1.6 GSI</b>	1988-92
E 16 SE	74 100
Ignition Coil Ch.L4000001->	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads	<b>83550</b>
<b>Corsa A (93, 94, 98, 99) 1.6 GSI KAT</b>	1992-93
C 16 SE	74 101
Ignition Coil With regul.cat.(3way)	<b>80210</b>
Ignition Coil	<b>80262</b>
Ignition Leads Engine 02V57974->	<b>85105</b>
<b>Corsa A Sedan (91, 92, 96, 97) 1.0</b>	1982-92
10 S	33 45
Ignition Leads	<b>83500</b>
<b>Corsa A Sedan (91, 92, 96, 97) 1.2 i</b>	1989-93
C 12 NZ	33 45
Ignition Coil	<b>80210</b>
Ignition Coil Ch.L4000001->; 09.1990->; SAGEM	<b>80262</b>
Ignition Leads SAE	<b>83570</b>
Ignition Leads	<b>85105</b>
<b>Corsa A Sedan (91, 92, 96, 97) 1.2 N</b>	1985-87
E 12 GV/12 NC	33 45
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83500</b>
<b>Corsa A Sedan (91, 92, 96, 97) 1.2 S</b>	1982-93
12 ST	40 55
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Corsa A Sedan (91, 92, 96, 97) 1.2 S</b>	1982-87
12 S	43 58
Ignition Coil	<b>80261</b>





OPEL Cont.		
<b>Corsa A Sedan (91, 92, 96, 97) 1.3</b>		<b>1985-87</b>
13 NB/C 13 N		44 60
Ignition Coil 03.1986->		<b>80261</b>
Ignition Leads		<b>83490</b>
<b>Corsa A Sedan (91, 92, 96, 97) 1.3 S</b>		<b>1982-87</b>
13 SB		51 70
Ignition Coil		<b>80261</b>
Ignition Leads		<b>83490</b>
<b>Corsa A Sedan (91, 92, 96, 97) 1.4 i</b>		<b>1989-93</b>
C 14 NZ		44 60
Ignition Coil		<b>80262</b>
Ignition Leads SAE		<b>83570</b>
Ignition Leads		<b>83800</b>
Ignition Leads With ignition lead		<b>85105</b>
<b>Corsa A Sedan (91, 92, 96, 97) 1.4 S</b>		<b>1989-93</b>
14 NV		53 72
Ignition Coil		<b>80210</b>
Ignition Leads SAE		<b>83570</b>
Ignition Leads SAE		<b>83800</b>
Ignition Leads 01.1990->		<b>85105</b>
<b>Corsa A Van 1.0</b>		<b>1986-89</b>
10 S		33 45
Ignition Leads		<b>83500</b>
<b>Corsa A Van 1.2</b>		<b>1986-90</b>
12 S		44 60
Ignition Coil		<b>80261</b>
<b>Corsa A Van 1.2</b>		<b>1986-89</b>
E 12 GV/12 NC		33 45
Ignition Coil		<b>80261</b>
Ignition Leads		<b>83500</b>
<b>Corsa A Van 1.2</b>		<b>1986-89</b>
12 ST		40 54
Ignition Coil		<b>80261</b>
Ignition Leads		<b>83490</b>
<b>Corsa A Van 1.3</b>		<b>1986-89</b>
13 NB		44 60
Ignition Coil		<b>80261</b>
Ignition Leads		<b>83490</b>
<b>Corsa A Van 1.3</b>		<b>1986-89</b>
13 SB		51 69
Ignition Coil		<b>80261</b>
Ignition Leads		<b>83490</b>
<b>Corsa B (73, 78, 79) 1.0 i 12V</b>		<b>1996-00</b>
X 10 XE		40 54
Ignition Coil		<b>80259</b>
<b>Corsa B (73, 78, 79) 1.2 i</b>		<b>1993-00</b>
12 NZ		33 45
Ignition Coil		<b>80210</b>
Ignition Coil ->08.2000		<b>80262</b>
Ignition Leads SAE		<b>83800</b>
Ignition Leads		<b>85105</b>
<b>Corsa B (73, 78, 79) 1.2 i</b>		<b>1993-00</b>
C 12 NZ/X 12 SZ		33 45
Ignition Coil With regul.cat.(3way)		<b>80210</b>
Ignition Coil		<b>80262</b>
Ignition Leads C 12 NZ; ->Engine 19334656		<b>83800</b>
Ignition Leads Engine 02BD0922->; 08.1995->		<b>85085</b>
Ignition Leads X 12 SZ; ->Engine 19552964		<b>85100</b>
Ignition Leads C 12 NZ		<b>85105</b>
<b>Corsa B (73, 78, 79) 1.2 i 16V</b>		<b>1998-00</b>
X 12 XE		48 65
Ignition Coil		<b>80257</b>
<b>Corsa B (73, 78, 79) 1.4 i</b>		<b>1993-00</b>
C 14 NZ/X 14 SZ		44 60
Ignition Coil With regul.cat.(3way)		<b>80210</b>
Ignition Coil		<b>80262</b>
Ignition Leads SAE		<b>83800</b>
Ignition Leads		<b>85084</b>
Ignition Leads X 14 SZ; ->Ch.02HY3579		<b>85085</b>
Ignition Leads With ignition lead		<b>85105</b>
<b>Corsa B (73, 78, 79) 1.4 i 16V</b>		<b>1994-00</b>
X 14 XE		66 90
Ignition Coil		<b>80210</b>
Ignition Leads Ch.20C17331		<b>85080</b>
<b>Corsa B (73, 78, 79) 1.4 i 16V</b>		<b>1994-00</b>
X 14 XE		67 91
Ignition Coil		<b>80210</b>

OPEL Cont.		
<b>Corsa B (73, 78, 79) 1.4 Si</b>		<b>1993-00</b>
C 14 SE		60 82
Ignition Coil		<b>80210</b>
Ignition Coil		<b>80262</b>
Ignition Leads Engine 02BD1413-02HY3579; 08.1995->		<b>85085</b>
Ignition Leads Engine 02V57975-02BD0921		<b>85100</b>
<b>Corsa B (73, 78, 79) 1.6 GSI 16V</b>		<b>1993-00</b>
C 16 XE		80 109
Ignition Coil		<b>80210</b>
Ignition Leads Ch.20C17331		<b>85080</b>
<b>Corsa B (73, 78, 79) 1.6 i 16V</b>		<b>1997-00</b>
C 16 SEL		74 100
Ignition Leads Ch.20C17331		<b>85080</b>
<b>Corsa B (73, 78, 79) 1.6 i 16V</b>		<b>1994-00</b>
X 16 XE		78 106
Ignition Coil		<b>80210</b>
Ignition Leads Ch.20C17331		<b>85080</b>
<b>Corsa B Van (73) 1.4 i</b>		<b>1999-00</b>
C 14 NZ/X 14 SZ		44 60
Ignition Coil		<b>80210</b>
Ignition Leads ->Engine 02HY3579		<b>85085</b>
Ignition Leads		<b>85105</b>
<b>Corsa C (F08, F68) 1.0</b>		<b>2000-03</b>
Z 10 XE		43 58
Ignition Coil		<b>80259</b>
<b>Corsa C (F08, F68) 1.0</b>		<b>2003-09</b>
Z 10 XEP		44 60
Ignition Coil		<b>80259</b>
<b>Corsa C (F08, F68) 1.2</b>		<b>2000-09</b>
Z 12 XE		55 75
Ignition Coil		<b>80257</b>
Ignition Coil Ch.43000001; Ch.44000001; Ch.46000001; ->06.2004		<b>80350</b>
<b>Corsa C (F08, F68) 1.2 Twinport</b>		<b>2004-09</b>
Z 12 XEP		59 80
Ignition Coil ->09.2006		<b>80350</b>
<b>Corsa C (F08, F68) 1.4</b>		<b>2000-09</b>
Z 14 XE		66 90
Ignition Coil With regul.cat.(3way)		<b>80209</b>
<b>Corsa C (F08, F68) 1.4 Twinport</b>		<b>2003-09</b>
Z 14 XEP		66 90
Ignition Coil 09.2003-09.2006		<b>80350</b>
<b>Corsa C (F08, F68) 1.8</b>		<b>2000-09</b>
Z 18 XE		92 125
Ignition Coil Z 18 XE		<b>80224</b>
<b>Corsa C Van (F08, W5L) 1.2</b>		<b>2005-&gt;</b>
Z 12 XEP		59 80
Ignition Coil ->09.2006		<b>80350</b>
<b>Corsa C Van (F08, W5L) 1.2 16V</b>		<b>2000-&gt;</b>
Z 12 XE		55 75
Ignition Coil		<b>80257</b>
Ignition Coil Ch.43000001; Ch.44000001; Ch.46000001; ->06.2004		<b>80350</b>
<b>Corsa C Van (F08, W5L) 1.4</b>		<b>2003-&gt;</b>
Z 14 XEP		66 90
Ignition Coil		<b>80209</b>
Ignition Coil 09.2003-09.2006		<b>80350</b>
<b>Corsa D 1.0</b>		<b>2006-&gt;</b>
Z 10 XEP		44 60
Ignition Coil		<b>80259</b>
<b>Corsa D 1.0</b>		<b>2010-&gt;</b>
A 10 XEP		48 65
Ignition Coil		<b>80258</b>
Ignition Coil		<b>80259</b>
<b>Corsa D 1.2</b>		<b>2006-&gt;</b>
Z 12 XEP		59 80
Ignition Coil ->12.2011		<b>80350</b>
<b>Corsa D 1.2</b>		<b>2010-&gt;</b>
A 12 XEL		51 69
Ignition Coil		<b>80322</b>
<b>Corsa D 1.2</b>		<b>2010-&gt;</b>
A 12 XER		63 86
Ignition Coil		<b>80322</b>
<b>Corsa D 1.2 LPG</b>		<b>2011-&gt;</b>
A 12 XER		61 83
Ignition Coil		<b>80322</b>
<b>Corsa D 1.2 LPG</b>		<b>2009-&gt;</b>
Z 12 XEP		55 75
Ignition Coil ->12.2011		<b>80350</b>



OPEL Cont.	
<b>Corsa D 1.2 LPG</b>	2011->
A 12 XER	63 86
Ignition Coil	<b>80322</b>
<b>Corsa D 1.2 LPG</b>	2009->
Z 12 XEP	59 80
Ignition Coil ->12.2011	<b>80350</b>
<b>Corsa D 1.4</b>	2006->
Z 14 XEP	66 90
Ignition Coil ->11.2010	<b>80350</b>
<b>Corsa D 1.4</b>	2009->
A 14 XEL	64 87
Ignition Coil	<b>80322</b>
<b>Corsa D 1.4</b>	2010->
A 14 XER	74 100
Ignition Coil	<b>80322</b>
<b>Corsa D 1.4</b>	2012->
A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Corsa D 1.4 LPG</b>	2006->
Z 14 XEP	66 90
Ignition Coil 09.2009-11.2010	<b>80350</b>
<b>Corsa D 1.4 LPG</b>	2009->
A 14 XEL	64 87
Ignition Coil	<b>80322</b>
Ignition Coil ->11.2010	<b>80350</b>
<b>Corsa D 1.6 Turbo</b>	2011->
A 16 LES/B 16 LES	155 211
Ignition Coil	<b>80291</b>
<b>Corsa D 1.6 Turbo</b>	2007->
B 16 LER/A 16 LER/Z 16 LER	141 192
Ignition Coil	<b>80291</b>
<b>Corsa D 1.6 Turbo</b>	2007->
Z 16 LEL/A 16 LEL	110 150
Ignition Coil	<b>80291</b>
<b>Corsa D Van 1.0</b>	2010->
A 10 XEP	48 65
Ignition Coil	<b>80258</b>
Ignition Coil	<b>80259</b>
<b>Corsa D Van 1.0</b>	2006->
A 10 XEP	44 60
Ignition Coil 11.2006->	<b>80258</b>
<b>Corsa D Van 1.2</b>	2010->
A 12 XEL	51 69
Ignition Coil	<b>80322</b>
<b>Corsa D Van 1.2</b>	2009->
Z 12 XEP	59 80
Ignition Coil ->12.2011	<b>80350</b>
<b>Corsa D Van 1.2</b>	2010->
A 12 XER	63 86
Ignition Coil	<b>80322</b>
<b>Corsa E 1.2</b>	2014->
B 12 XER/B 12 XEL	51 69
Ignition Coil B 12 XEL	<b>80322</b>
<b>Corsa E 1.4</b>	2014->
B 14 XEL	66 90
Ignition Coil	<b>80322</b>
<b>Frontera A (5MwI4) 2.2 i</b>	1995-98
X 22 XE	100 136
Ignition Coil	<b>80289</b>
<b>Frontera A Sport (5Sud2) 2.0 i</b>	1992-98
C 20 NE/X 20 SE	85 115
Ignition Coil	<b>80289</b>
Ignition Leads C 20 NE; Engine 14672354->; 08.1995->	<b>83800</b>
Ignition Leads X 20 SE	<b>85083</b>
Ignition Leads C 20 NE; ->Engine 14672353; ->08.1995	<b>85980</b>
<b>Frontera B (6B) 2.2 i</b>	1998->
X 22 SE/Y 22 SE	100 136
Ignition Coil	<b>80318</b>
<b>GT Cabriolet 2.0</b>	2007->
LNF/Z 20 NHH	194 264
Ignition Coil Z20NNH	<b>80329</b>
<b>Insignia 1.4</b>	2011->
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia 1.4 LPG</b>	2012->
A 14 NET	103 140
Ignition Coil	<b>80322</b>

OPEL Cont.	
<b>Insignia 1.6</b>	2008->
A 16 XER	85 116
Ignition Coil	<b>80321</b>
<b>Insignia 1.6 Turbo</b>	2008->
A 16 LET	132 180
Ignition Coil	<b>80291</b>
Ignition Coil	<b>80321</b>
<b>Insignia 1.8</b>	2008->
A 18 XER	103 140
Ignition Coil	<b>80321</b>
<b>Insignia 2.0 E85 Turbo</b>	2010->
A 20 NHT	162 220
Ignition Coil	<b>80329</b>
<b>Insignia 2.0 Turbo</b>	2014->
A 20 NHT	184 250
Ignition Coil	<b>80329</b>
<b>Insignia 2.0 Turbo</b>	2008->
A 20 NHT	162 220
Ignition Coil	<b>80329</b>
<b>Insignia 2.0 Turbo 4x4</b>	2011->
A 20 NFT	184 250
Ignition Coil	<b>80329</b>
<b>Insignia 2.0 Turbo 4x4</b>	2008->
A 20 NHT	162 220
Ignition Coil	<b>80329</b>
<b>Insignia Caravan 1.4</b>	2011->
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia Caravan 1.4 LPG</b>	2012->
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia Caravan 1.6</b>	2008->
A 16 XER	85 116
Ignition Coil	<b>80321</b>
<b>Insignia Caravan 1.6 Turbo</b>	2009->
A 16 LET	132 180
Ignition Coil	<b>80291</b>
Ignition Coil	<b>80321</b>
<b>Insignia Caravan 1.8</b>	2008->
A 18 XER	103 140
Ignition Coil	<b>80321</b>
<b>Insignia Caravan 2.0 E85 Turbo</b>	2010->
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>Insignia Caravan 2.0 Turbo</b>	2014->
A 20 NHT	184 250
Ignition Coil	<b>80329</b>
<b>Insignia Caravan 2.0 Turbo</b>	2008->
A 20 NHT	162 220
Ignition Coil	<b>80329</b>
<b>Insignia Caravan 2.0 Turbo 4x4</b>	2011->
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia Sedan 1.4 LPG</b>	2012->
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia Sedan 1.6</b>	2008->
A 16 XER	85 116
Ignition Coil	<b>80321</b>
<b>Insignia Sedan 1.6 Turbo</b>	2009->
A 16 LET	132 180
Ignition Coil	<b>80291</b>
Ignition Coil	<b>80321</b>
<b>Insignia Sedan 1.8</b>	2008->
A 18 XER	103 140
Ignition Coil	<b>80321</b>
<b>Insignia Sedan 2.0 Turbo</b>	2014->
A 20 NHT	184 250
Ignition Coil	<b>80329</b>
<b>Insignia Sedan 2.0 Turbo</b>	2008->
A 20 NHT	162 220
Ignition Coil	<b>80329</b>



OPEL Cont.	
Insignia Sedan 2.0 Turbo 4x4	2011->
A 20 NFT	184 250
Ignition Coil	<b>80329</b>
Insignia Sedan 2.0 Turbo 4x4	2008->
A 20 NHT	162 220
Ignition Coil	<b>80329</b>
Insignia Sedan 2.0 Turbo E85	2008->
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>Kadett D (31-34, 41-44) 1.2</b>	<b>1982-84</b>
12 ST	40 55
Ignition Leads	<b>83570</b>
<b>Kadett D (31-34, 41-44) 1.2</b>	<b>1979-82</b>
12 N	39 53
Ignition Leads	<b>83500</b>
<b>Kadett D (31-34, 41-44) 1.2 S</b>	<b>1979-84</b>
12 S	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83500</b>
<b>Kadett D (31-34, 41-44) 1.3 N</b>	<b>1979-84</b>
13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
Ignition Leads Engine 879422->	<b>83570</b>
<b>Kadett D (31-34, 41-44) 1.3 S</b>	<b>1979-84</b>
13 S	55 75
Ignition Coil	<b>80261</b>
Ignition Leads Engine 885919->	<b>83570</b>
<b>Kadett D (32,37,39, 42) 1.2 S</b>	<b>1979-84</b>
12 S	44 60
Ignition Leads SAE	<b>83490</b>
Ignition Leads	<b>83500</b>
<b>Kadett D (32,37,39, 42) 1.3 N</b>	<b>1979-84</b>
C 13 N	44 60
Ignition Coil	<b>80261</b>
<b>Kadett D (32,37,39, 42) 1.3 S</b>	<b>1979-84</b>
13 S	55 75
Ignition Coil	<b>80261</b>
<b>Kadett D Caravan (35, 36, 45, 46) 1.2</b>	<b>1979-82</b>
12 N	39 53
Ignition Leads	<b>83500</b>
<b>Kadett D Caravan (35, 36, 45, 46) 1.2 S</b>	<b>1979-84</b>
12 S	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
Ignition Leads	<b>83500</b>
<b>Kadett D Caravan (35, 36, 45, 46) 1.3 N</b>	<b>1979-84</b>
13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
Ignition Leads Engine 879422->	<b>83570</b>
<b>Kadett D Caravan (35, 36, 45, 46) 1.3 S</b>	<b>1979-84</b>
13 S	55 75
Ignition Coil	<b>80261</b>
Ignition Leads Engine 885919->	<b>83570</b>
<b>Kadett E (39, 49) 1.2</b>	<b>1984-86</b>
12 SC	40 55
Ignition Leads	<b>83500</b>
<b>Kadett E (39, 49) 1.3 i KAT</b>	<b>1985-91</b>
C 13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Kadett E (39, 49) 1.3 N</b>	<b>1984-89</b>
13 NB/13 N	44 60
Ignition Coil MM	<b>80261</b>
Ignition Leads SAE	<b>83490</b>
Ignition Leads	<b>83560</b>
<b>Kadett E (39, 49) 1.3 S</b>	<b>1984-87</b>
13 S	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Kadett E (39, 49) 1.4 i</b>	<b>1990-91</b>
C 14 NZ	44 60
Ignition Coil ->Engine 02E85672	<b>80261</b>
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>

OPEL Cont.	
<b>Kadett E (39, 49) 1.4 S</b>	<b>1990-91</b>
14 NV	55 75
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E (39, 49) 1.6 i</b>	<b>1986-91</b>
E 16 NZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads ->Engine 02V65825	<b>83570</b>
<b>Kadett E (39, 49) 1.6 i KAT</b>	<b>1986-91</b>
C 16 NZ/C 16 LZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads ->Engine 02V65825	<b>83570</b>
<b>Kadett E (39, 49) 1.6 S</b>	<b>1986-91</b>
16 SV	60 82
Ignition Coil ->Engine 02E85672	<b>80261</b>
Ignition Coil	<b>80262</b>
Ignition Leads ->Engine 02E85672	<b>83570</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E (39, 49) 1.6 S</b>	<b>1984-86</b>
16 SH	66 90
Ignition Coil	<b>80262</b>
<b>Kadett E (39, 49) 1.8</b>	<b>1987-90</b>
18 E	84 114
Ignition Coil	<b>80262</b>
Ignition Leads ->12.1989	<b>83550</b>
<b>Kadett E (39, 49) 1.8 i</b>	<b>1985-86</b>
C 18 NE	74 100
Ignition Leads	<b>83550</b>
<b>Kadett E (39, 49) 1.8 i</b>	<b>1990-91</b>
C 18 NZ/C 18 NT/18 SV	66 90
Ignition Coil	<b>80262</b>
<b>Kadett E (39, 49) 1.8 S</b>	<b>1987-91</b>
E 18 NV	62 84
Ignition Leads ->Engine 14258179	<b>83550</b>
Ignition Leads Engine 14258180->	<b>83800</b>
<b>Kadett E (39, 49) 2.0 i</b>	<b>1987-91</b>
20 NE/20 SE	85 115
Ignition Leads ->Engine 14180385	<b>83550</b>
Ignition Leads Engine 14258180->	<b>83800</b>
<b>Kadett E (39, 49) 2.0 i KAT</b>	<b>1987-91</b>
C 20 NE	85 115
Ignition Leads ->Engine 14180385	<b>83550</b>
Ignition Leads Engine 14258180->	<b>83800</b>
<b>Kadett E Cabriolet (43B) 1.3 S</b>	<b>1987-93</b>
13 S	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Kadett E Cabriolet (43B) 1.4 i</b>	<b>1990-91</b>
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E Cabriolet (43B) 1.4 S</b>	<b>1990-93</b>
14 NV	55 75
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E Cabriolet (43B) 1.6 i</b>	<b>1989-93</b>
16 SV	60 82
Ignition Coil SAE; ->08.1991	<b>80261</b>
Ignition Coil M4; ->08.1991	<b>80262</b>
Ignition Leads ->Engine 02E85672	<b>83570</b>
Ignition Leads Engine 02N39786->	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E Cabriolet (43B) 1.6 i</b>	<b>1986-93</b>
E 16 NZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads ->Engine 02V65825	<b>83570</b>
<b>Kadett E Cabriolet (43B) 1.6 i KAT</b>	<b>1987-93</b>
C 16 NZ/C 16 LZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads ->Engine 02V65825	<b>83570</b>



OPEL Cont.	
<b>Kadett E Cabriolet (43B) 2.0</b>	<b>1990-92</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Kadett E Cabriolet (43B) 2.0 GSi</b>	<b>1990-92</b>
20 SER	115 156
Ignition Leads ->08.1991	<b>83550</b>
<b>Kadett E Cabriolet (43B) 2.0 i</b>	<b>1986-93</b>
20 NE	85 115
Ignition Leads ->Engine 14180385; ->08.1991	<b>83550</b>
Ignition Leads Engine 14258180->	<b>83800</b>
<b>Kadett E Cabriolet (43B) 2.0 i KAT</b>	<b>1986-93</b>
C 20 NE	85 116
Ignition Leads ->Engine 14180385; ->08.1991	<b>83550</b>
Ignition Leads Engine 14258180->	<b>83800</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.2</b>	<b>1984-86</b>
12 SC	40 55
Ignition Leads	<b>83500</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.3 i KAT</b>	<b>1985-91</b>
C 13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.3 N</b>	<b>1984-91</b>
13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads SAE	<b>83490</b>
Ignition Leads	<b>83560</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.3 S</b>	<b>1984-87</b>
13 S	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.4 i</b>	<b>1990-91</b>
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.4 S</b>	<b>1990-91</b>
14 NV	55 75
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.6</b>	<b>1986-91</b>
16 SV	60 82
Ignition Coil SAE	<b>80261</b>
Ignition Coil M4	<b>80262</b>
Ignition Leads ->Engine 02E85672	<b>83570</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.6 i</b>	<b>1986-91</b>
E 16 NZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads ->Engine 02V65825	<b>83570</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.6 i KAT</b>	<b>1986-91</b>
C 16 NZ/C 16 LZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads ->Engine 02V65825	<b>83570</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.6 S</b>	<b>1984-86</b>
16 SH	66 90
Ignition Coil	<b>80262</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.8</b>	<b>1988-91</b>
18 SE	82 112
Ignition Coil SAGEM	<b>80262</b>
Ignition Leads ->Engine 14258179	<b>83550</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.8 i</b>	<b>1985-91</b>
C 18 NZ/C 18 NT	66 90
Ignition Coil	<b>80262</b>
<b>Kadett E Caravan (35, 36, 45, 46) 1.8 S</b>	<b>1987-91</b>
E 18 NV	62 84
Ignition Leads ->Engine 14258179	<b>83550</b>
Ignition Leads Engine 14258180->	<b>83800</b>
<b>Kadett E Caravan (35, 36, 45, 46) 2.0 i</b>	<b>1987-91</b>
20 NE	85 115
Ignition Leads ->Engine 14180385	<b>83550</b>
<b>Kadett E Caravan (35, 36, 45, 46) 2.0 i KAT</b>	<b>1987-91</b>
C 20 NE	85 115
Ignition Leads ->Engine 14180385	<b>83550</b>

OPEL Cont.	
<b>Kadett E CC (33, 34, 43, 44) 1.2</b>	<b>1984-86</b>
12 SC	40 55
Ignition Leads	<b>83500</b>
<b>Kadett E CC (33, 34, 43, 44) 1.3 i KAT</b>	<b>1985-91</b>
C 13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Kadett E CC (33, 34, 43, 44) 1.3 N</b>	<b>1984-91</b>
13 NB/13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads 13 NB	<b>83490</b>
Ignition Leads 13 N	<b>83560</b>
<b>Kadett E CC (33, 34, 43, 44) 1.3 S</b>	<b>1984-87</b>
13 S	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Kadett E CC (33, 34, 43, 44) 1.4 i</b>	<b>1990-91</b>
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E CC (33, 34, 43, 44) 1.4 S</b>	<b>1989-91</b>
C 14 SE	60 82
Ignition Coil	<b>80262</b>
<b>Kadett E CC (33, 34, 43, 44) 1.4 S</b>	<b>1990-91</b>
14 NV	55 75
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E CC (33, 34, 43, 44) 1.6 i</b>	<b>1986-91</b>
E 16 NZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads ->Engine 02V65825	<b>83570</b>
<b>Kadett E CC (33, 34, 43, 44) 1.6 i KAT</b>	<b>1986-91</b>
C 16 NZ/C 16 LZ	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads ->Engine 02V65825	<b>83570</b>
<b>Kadett E CC (33, 34, 43, 44) 1.6 S</b>	<b>1986-91</b>
16 SV	60 82
Ignition Coil ->Engine -02E85672	<b>80261</b>
Ignition Coil 16SV	<b>80262</b>
Ignition Leads Engine 02E85672->	<b>83560</b>
Ignition Leads ->Engine 02E85672	<b>83570</b>
Ignition Leads SAE	<b>83800</b>
<b>Kadett E CC (33, 34, 43, 44) 1.6 S</b>	<b>1984-86</b>
16 SH	66 90
Ignition Coil	<b>80262</b>
<b>Kadett E CC (33, 34, 43, 44) 1.8 i</b>	<b>1985-91</b>
C 18 NZ/S 18 NV/C 18 NT	66 90
Ignition Coil C 18 NZ; 09.1990->	<b>80262</b>
Ignition Leads S 18 NV; 09.1986->	<b>83550</b>
<b>Kadett E CC (33, 34, 43, 44) 1.8 S</b>	<b>1987-91</b>
E 18 NV/S 18 NV	62 84
Ignition Leads ->Engine 14258179	<b>83550</b>
Ignition Leads Engine 14258180->	<b>83800</b>
<b>Kadett E CC (33, 34, 43, 44) 2.0 GSI</b>	<b>1986-91</b>
20 NE	85 115
Ignition Leads ->Engine 14180385	<b>83550</b>
Ignition Leads Engine 14258180->	<b>83800</b>
<b>Kadett E CC (33, 34, 43, 44) 2.0 GSI</b>	<b>1986-91</b>
20 SEH	95 129
Ignition Leads	<b>83550</b>
<b>Kadett E CC (33, 34, 43, 44) 2.0 GSI 16V KAT</b>	<b>1988-91</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Kadett E CC (33, 34, 43, 44) 2.0 GSI KAT</b>	<b>1986-91</b>
C 20 NE	85 115
Ignition Leads ->Engine 14180385	<b>83550</b>
<b>Kadett E Combo (38, 48) 1.3 N</b>	<b>1986-89</b>
13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>
<b>Kadett E Combo (38, 48) 1.3 S</b>	<b>1986-89</b>
13 S	55 75
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83490</b>



OPEL Cont.	
<b>Kadett E Combo (38, 48) 1.4 i</b>	1991-94
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads	<b>83800</b>
Ignition Leads ->08.1991	<b>85105</b>
<b>Kadett E Combo (38, 48) 1.4 S</b>	1989-91
14 NV	55 75
Ignition Coil	<b>80262</b>
Ignition Leads	<b>83800</b>
Ignition Leads 01.1990->	<b>85105</b>
<b>Kadett E Combo (38, 48) 1.6</b>	1986-91
16 SV	60 82
Ignition Coil SAE; ->08.1991	<b>80261</b>
Ignition Coil M4; ->08.1991	<b>80262</b>
Ignition Leads	<b>83570</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E Combo (38, 48) 1.6 i</b>	1991-94
C 16 NZ	55 75
Ignition Coil	<b>80210</b>
Ignition Coil ->08.1993	<b>80261</b>
Ignition Coil	<b>80262</b>
Ignition Leads ->Engine 02V65825	<b>83560</b>
Ignition Leads	<b>83570</b>
Ignition Leads Engine 02V65826->	<b>85570</b>
<b>Kadett E Van (37, 47) 1.2</b>	1984-86
12 SC	40 55
Ignition Leads	<b>83500</b>
<b>Kadett E Van (37, 47) 1.3 N</b>	1984-89
13 NB/13 N	44 60
Ignition Coil	<b>80261</b>
Ignition Leads SAE	<b>83490</b>
Ignition Leads	<b>83560</b>
<b>Kadett E Van (37, 47) 1.4 i</b>	1990-91
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Kadett E Van (37, 47) 1.6 i</b>	1989-93
C 16 NZ	55 75
Ignition Coil	<b>80210</b>
Ignition Coil	<b>80261</b>
Ignition Leads	<b>83560</b>
Ignition Leads ->Engine 02V65825	<b>83570</b>
<b>Kadett E Van (37, 47) 1.8 i</b>	1984-92
C 18 NT	66 90
Ignition Leads SAE	<b>83800</b>
<b>Manta B (58, 59) 1.3 S</b>	1981-86
13 S	55 75
Ignition Coil	<b>80261</b>
<b>Manta B CC (53, 55) 1.3 S</b>	1979-86
13 S	55 75
Ignition Coil	<b>80261</b>
<b>Meriva 1.4 16V Twinport</b>	2004-10
Z 14 XEP	66 90
Ignition Coil ->03.2010	<b>80350</b>
<b>Meriva 1.4 16V Twinport LPG</b>	2004-10
Z 14 XEP	66 90
Ignition Coil ->03.2010	<b>80350</b>
<b>Meriva 1.6</b>	2003-10
Z 16 SE	64 87
Ignition Coil	<b>80320</b>
Ignition Leads	<b>85084</b>
<b>Meriva 1.6</b>	2006-10
Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Meriva 1.6 16V</b>	2003-06
Z 16 XE	74 100
Ignition Coil Intake manifold injection	<b>80209</b>
<b>Meriva 1.6 Turbo</b>	2005-10
Z 16 LET	132 180
Ignition Coil	<b>80291</b>
<b>Meriva 1.8</b>	2003-10
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Meriva B 1.4</b>	2010->
A 14 XER/B 14 XER	74 100
Ignition Coil	<b>80322</b>

OPEL Cont.	
<b>Meriva B 1.4</b>	2010->
B 14 NEL/A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Meriva B 1.4</b>	2010->
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Meriva B 1.4 LPG</b>	2011->
B 14 NEL/A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Mokka 1.4</b>	2013->
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Mokka 1.4 4x4</b>	2012->
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Mokka 1.4 LPG</b>	2013->
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Mokka 1.6</b>	2012->
A 16 XER/B 16 XER	85 116
Ignition Coil A 16 XER	<b>80352</b>
<b>Mokka 1.8</b>	2013->
A 18 XER	103 140
Ignition Coil	<b>80321</b>
<b>Mokka 1.8 4x4</b>	2013->
A 18 XER	103 140
Ignition Coil	<b>80321</b>
<b>Monza A (22) 2.2 E</b>	1984-86
22 E	85 115
Ignition Coil	<b>80261</b>
<b>Monza A (22) 2.5 E</b>	1984-86
25 E	103 140
Ignition Coil	<b>80261</b>
<b>Monza A (22) 3.0 GSE</b>	1978-86
30 E	132 180
Ignition Coil	<b>80261</b>
<b>Omega A (16, 17, 19) 1.8</b>	1987-94
E 18 NVR	65 88
Ignition Leads ->Engine 14258179	<b>83530</b>
Ignition Leads Ch.L1204908->	<b>83800</b>
Ignition Leads Engine 14258180->	<b>85980</b>
<b>Omega A (16, 17, 19) 1.8</b>	1986-94
18 SEH	85 115
Ignition Coil	<b>80262</b>
Ignition Leads ->Engine 14258179	<b>83530</b>
Ignition Leads Ch.L1204908->	<b>83800</b>
Ignition Leads Engine 14258180->	<b>85980</b>
<b>Omega A (16, 17, 19) 1.8 N</b>	1986-87
18 NV	60 82
Ignition Leads ->Engine 14258179	<b>83530</b>
Ignition Leads Ch.L1204908->	<b>83800</b>
Ignition Leads Engine 14258180->	<b>85980</b>
<b>Omega A (16, 17, 19) 1.8 N</b>	1986-88
18 SV	63 86
Ignition Coil Engine 14258180->	<b>80262</b>
Ignition Leads ->Engine 14258179	<b>83530</b>
Ignition Leads Ch.L1204908->	<b>83800</b>
Ignition Leads Engine 14258180->	<b>85980</b>
<b>Omega A (16, 17, 19) 1.8 S</b>	1986-94
18 SV	66 90
Ignition Coil	<b>80262</b>
Ignition Leads ->Engine 14258179	<b>83530</b>
Ignition Leads Ch.L1204908->	<b>83800</b>
Ignition Leads Engine 14258180->	<b>85980</b>
<b>Omega A (16, 17, 19) 2.0</b>	1986-94
20 SE	90 122
Ignition Leads ->Engine 14180385; Ch.K1000099	<b>83530</b>
Ignition Leads Engine 14312951->	<b>83800</b>
Ignition Leads	<b>85980</b>
<b>Omega A (16, 17, 19) 2.0</b>	1990-94
C 20 NEF	74 100
Ignition Leads ->Engine 14180385; ->02.1992	<b>83530</b>
Ignition Leads Engine 14672353->; ->02.1992	<b>83800</b>
Ignition Leads Engine 14180386-14672352; ->02.1992	<b>85980</b>
<b>Omega A (16, 17, 19) 2.0</b>	1990-94
C 20 NEJ	73 99
Ignition Leads ->Engine 14180385; ->02.1992	<b>83530</b>
Ignition Leads Engine 14672353->; ->02.1992	<b>83800</b>
Ignition Leads Engine 14180386-14672352; ->02.1992	<b>85980</b>





OPEL Cont.		
<b>Omega A (16, 17, 19) 2.0 i</b>		<b>1986-94</b>
C 20 NE		85 115
Ignition Leads ->Engine 14180385		<b>83530</b>
Ignition Leads Engine 14672353->		<b>83800</b>
Ignition Leads Engine 14180386->		<b>85980</b>
<b>Omega A Caravan (66, 67) 1.8</b>		<b>1987-94</b>
E 18 NVR		65 88
Ignition Leads ->Engine 14258179		<b>83530</b>
Ignition Leads Ch.L1204908->		<b>83800</b>
Ignition Leads Engine 14258180->		<b>85980</b>
<b>Omega A Caravan (66, 67) 1.8</b>		<b>1986-94</b>
18 SEH		85 115
Ignition Coil		<b>80262</b>
Ignition Leads ->Engine 14258179		<b>83530</b>
Ignition Leads Ch.L1204908->		<b>83800</b>
Ignition Leads Engine 14258180->		<b>85980</b>
<b>Omega A Caravan (66, 67) 1.8 N</b>		<b>1986-87</b>
18 NV		60 82
Ignition Leads ->Engine 14258179		<b>83530</b>
Ignition Leads Ch.L1204908->		<b>83800</b>
Ignition Leads Engine 14258180->		<b>85980</b>
<b>Omega A Caravan (66, 67) 1.8 N</b>		<b>1986-88</b>
18 SV		63 86
Ignition Coil Engine 14258180->		<b>80262</b>
Ignition Leads ->Engine 14258179		<b>83530</b>
Ignition Leads Ch.L1204908->		<b>83800</b>
Ignition Leads Engine 14258180->; ->Ch.L1204907		<b>85980</b>
<b>Omega A Caravan (66, 67) 1.8 S</b>		<b>1986-94</b>
18 SV		66 90
Ignition Coil		<b>80262</b>
Ignition Leads ->Engine 14258179; ->08.1989		<b>83530</b>
Ignition Leads Ch.L1204908->		<b>83800</b>
Ignition Leads		<b>85980</b>
<b>Omega A Caravan (66, 67) 2.0</b>		<b>1986-94</b>
20 SE		90 122
Ignition Leads ->Engine 14180385		<b>83530</b>
Ignition Leads Engine 14312951->		<b>83800</b>
Ignition Leads Engine 14180386->		<b>85980</b>
<b>Omega A Caravan (66, 67) 2.0</b>		<b>1990-94</b>
C 20 NEF		74 100
Ignition Leads ->Engine 14180385; ->02.1992		<b>83530</b>
Ignition Leads Engine 14672353->; ->02.1992		<b>83800</b>
Ignition Leads Engine 14180386-14672352; ->02.1992		<b>85980</b>
<b>Omega A Caravan (66, 67) 2.0 i</b>		<b>1990-94</b>
C 20 NEJ		73 99
Ignition Leads ->Engine 14180385; ->02.1992		<b>83530</b>
Ignition Leads Engine 14672353->; ->02.1992		<b>83800</b>
Ignition Leads Engine 14180386-14672352; ->02.1992		<b>85980</b>
<b>Omega A Caravan (66, 67) 2.0 i</b>		<b>1986-94</b>
C 20 NE		85 115
Ignition Leads ->Engine 14180385		<b>83530</b>
Ignition Leads Engine 14672353->		<b>83800</b>
Ignition Leads Engine 14180386->		<b>85980</b>
<b>Omega B (25, 26, 27) 2.0</b>		<b>1994-00</b>
20 SE		85 115
Ignition Coil		<b>80289</b>
Ignition Leads		<b>85980</b>
<b>Omega B (25, 26, 27) 2.0</b>		<b>1994-99</b>
X 20 SE		85 116
Ignition Coil		<b>80289</b>
Ignition Leads		<b>85980</b>
<b>Omega B (25, 26, 27) 2.0 16V</b>		<b>1994-99</b>
X 20 XEV		100 136
Ignition Coil With regul.cat.(3way)		<b>80223</b>
<b>Omega B Caravan (21, 22, 23) 2.0</b>		<b>1994-99</b>
X 20 SE		85 116
Ignition Coil		<b>80289</b>
<b>Omega B Caravan (21, 22, 23) 2.0 16V</b>		<b>1994-99</b>
X 20 XEV		100 136
Ignition Coil With regul.cat.(3way)		<b>80223</b>
<b>Signum 1.8</b>		<b>2003-&gt;</b>
Z 18 XE		90 122
Ignition Coil Z 18 XE		<b>80224</b>
<b>Signum 1.8</b>		<b>2005-&gt;</b>
Z 18 XER		103 140
Ignition Coil		<b>80291</b>
<b>Signum 2.2 direct</b>		<b>2003-&gt;</b>
Z 22 YH		114 155
Ignition Coil ->09.2008		<b>80269</b>

OPEL Cont.		
<b>Signum 2.8 V6 Turbo</b>		<b>2005-&gt;</b>
Z 28 NEL		169 230
Ignition Coil		<b>80355</b>
<b>Signum 2.8 V6 Turbo</b>		<b>2006-&gt;</b>
Z 28 NET		184 250
Ignition Coil		<b>80355</b>
<b>Sintra 2.2 i 16V</b>		<b>1996-99</b>
X 22 XE		104 141
Ignition Coil		<b>80289</b>
<b>Speedster 2.0 Turbo</b>		<b>2003-&gt;</b>
Z 20 LET		147 200
Ignition Coil ->09.2006		<b>80354</b>
<b>Tigra (95) 1.4 16V</b>		<b>1994-00</b>
X 14 XE		66 90
Ignition Coil		<b>80210</b>
<b>Tigra (95) 1.6 16V</b>		<b>1997-98</b>
C 16 SEL		74 100
Ignition Leads Ch.20C17331		<b>85080</b>
<b>Tigra (95) 1.6 16V</b>		<b>1994-98</b>
X 16 XE		78 106
Ignition Coil		<b>80210</b>
Ignition Leads Ch.20C17331		<b>85080</b>
<b>Tigra Twintop 1.4</b>		<b>2004-&gt;</b>
Z 14 XEP		66 90
Ignition Coil ->12.2009		<b>80350</b>
<b>Tigra Twintop 1.8</b>		<b>2004-&gt;</b>
Z 18 XE		92 125
Ignition Coil Z 18 XE		<b>80224</b>
<b>Vectra A (86, 87) 1.4 S</b>		<b>1988-92</b>
14 NV		55 75
Ignition Coil		<b>80261</b>
Ignition Coil		<b>80262</b>
Ignition Leads SAE		<b>83800</b>
Ignition Leads		<b>85105</b>
<b>Vectra A (86, 87) 1.6</b>		<b>1988-93</b>
16 SV		60 82
Ignition Coil ->12.1990		<b>80261</b>
Ignition Coil		<b>80262</b>
Ignition Leads ->Engine 02E85672		<b>83570</b>
Ignition Leads SAE		<b>83800</b>
Ignition Leads		<b>85105</b>
<b>Vectra A (86, 87) 1.6 i</b>		<b>1993-95</b>
X 16 SZ		52 71
Ignition Coil		<b>80210</b>
Ignition Leads		<b>85085</b>
Ignition Leads Ch.R75, R5, R1		<b>85100</b>
<b>Vectra A (86, 87) 1.6 i</b>		<b>1993-95</b>
C 16 LZ2/16 LZ2		55 75
Ignition Coil		<b>80210</b>
Ignition Coil ->08.1995		<b>80262</b>
<b>Vectra A (86, 87) 1.6 i</b>		<b>1988-95</b>
C 16 NZ2/C 16 NZ/E 16 NZ		55 75
Ignition Coil		<b>80261</b>
Ignition Leads SAE		<b>83800</b>
Ignition Leads ->Ch.19585415		<b>85087</b>
<b>Vectra A (86, 87) 1.8 i KAT</b>		<b>1990-95</b>
C 18 NZ		66 90
Ignition Coil		<b>80262</b>
Ignition Leads ->Engine 14180385		<b>83530</b>
Ignition Leads Engine 14349311-14432540		<b>83800</b>
Ignition Leads Engine 14279655->		<b>85087</b>
<b>Vectra A (86, 87) 1.8 S</b>		<b>1989-90</b>
18 SV		66 90
Ignition Coil		<b>80262</b>
Ignition Leads ->Engine 14180385		<b>83550</b>
Ignition Leads Engine 14275382-14279654		<b>83800</b>
<b>Vectra A (86, 87) 1.8 S</b>		<b>1988-89</b>
E 18 NVR		65 88
Ignition Coil		<b>80262</b>
Ignition Leads ->Engine 14180385		<b>83550</b>
Ignition Leads Engine 14275382-14279654		<b>83800</b>
<b>Vectra A (86, 87) 1.8 S 4x4</b>		<b>1989-89</b>
E 18 NVR		65 88
Ignition Coil		<b>80262</b>
Ignition Leads ->Engine 14180385		<b>83550</b>
Ignition Leads Engine 14275382-14279654		<b>83800</b>



OPEL Cont.	
<b>Vectra A (86, 87) 2.0</b>	<b>1988-89</b>
C 20 NEF	74 100
Ignition Leads ->Engine 14180385	<b>83530</b>
Ignition Leads ->Engine 14180385	<b>83550</b>
Ignition Leads Engine 14672353-14841581	<b>83800</b>
Ignition Leads Engine 14279655->	<b>85087</b>
<b>Vectra A (86, 87) 2.0 i</b>	<b>1988-92</b>
20 SEH	95 129
Ignition Leads Engine 14672353->	<b>83800</b>
Ignition Leads	<b>85087</b>
<b>Vectra A (86, 87) 2.0 i</b>	<b>1988-90</b>
20 NE	85 115
Ignition Leads ->Engine 14180385	<b>83550</b>
Ignition Leads 20 NE	<b>83800</b>
<b>Vectra A (86, 87) 2.0 i 16V</b>	<b>1994-95</b>
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	<b>80223</b>
<b>Vectra A (86, 87) 2.0 i 16V 4x4</b>	<b>1994-95</b>
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	<b>80223</b>
<b>Vectra A (86, 87) 2.0 i 4x4</b>	<b>1989-90</b>
20 NE	85 115
Ignition Leads ->Engine 14180385	<b>83550</b>
Ignition Leads Engine 14672353-14841581	<b>83800</b>
<b>Vectra A (86, 87) 2.0 i 4x4</b>	<b>1989-92</b>
20 SEH	95 129
Ignition Leads Engine 14672353->	<b>83800</b>
Ignition Leads	<b>85087</b>
<b>Vectra A (86, 87) 2.0 i 4x4 KAT</b>	<b>1989-95</b>
C 20 NE	85 116
Ignition Leads ->Engine 14180385; ->08.1995	<b>83550</b>
Ignition Leads C 20 NE	<b>83800</b>
<b>Vectra A (86, 87) 2.0 i KAT</b>	<b>1988-95</b>
C 20 NE	85 116
Ignition Leads ->Engine 14180385; ->08.1995	<b>83550</b>
Ignition Leads -> Engine 14841581	<b>83800</b>
<b>Vectra A (86, 87) 2000/GT 16V 4x4 KAT</b>	<b>1990-95</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Vectra A (86, 87) 2000/GT 16V KAT</b>	<b>1990-95</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Vectra A CC (88, 89) 1.4 S</b>	<b>1988-92</b>
14 NV	55 75
Ignition Coil	<b>80261</b>
Ignition Coil	<b>80262</b>
Ignition Leads ->Ch.19585415	<b>83570</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads Engine 19585416->; 09.1988->	<b>85105</b>
<b>Vectra A CC (88, 89) 1.6 i</b>	<b>1993-95</b>
16 LZ2	55 75
Ignition Coil	<b>80210</b>
Ignition Coil ->08.1995	<b>80262</b>
Ignition Leads	<b>85087</b>
<b>Vectra A CC (88, 89) 1.6 i</b>	<b>1993-95</b>
X 16 SZ	52 71
Ignition Coil	<b>80210</b>
Ignition Leads Ch.R75, R5, R1	<b>85085</b>
Ignition Leads	<b>85100</b>
<b>Vectra A CC (88, 89) 1.6 i KAT</b>	<b>1988-95</b>
C 16 NZ2/C 16 NZ	55 75
Ignition Coil ->Engine -02E85672	<b>80261</b>
Ignition Coil	<b>80262</b>
Ignition Leads ->Ch.19585415	<b>83570</b>
Ignition Leads SAE	<b>83800</b>
<b>Vectra A CC (88, 89) 1.6 S</b>	<b>1988-93</b>
16 SV	60 82
Ignition Coil ->12.1990	<b>80261</b>
Ignition Coil	<b>80262</b>
Ignition Leads ->Engine 02E85672	<b>83570</b>
Ignition Leads SAE	<b>83800</b>
Ignition Leads	<b>85105</b>
<b>Vectra A CC (88, 89) 1.8 i</b>	<b>1988-90</b>
18 SV	66 90
Ignition Coil	<b>80262</b>
Ignition Leads ->Engine 14180385; 09.1989->	<b>83550</b>
Ignition Leads	<b>83800</b>

OPEL Cont.	
<b>Vectra A CC (88, 89) 1.8 i KAT</b>	<b>1990-95</b>
C 18 NZ	66 90
Ignition Coil	<b>80262</b>
Ignition Leads ->Engine 14180385	<b>83530</b>
Ignition Leads Engine 14349311-14432540	<b>83800</b>
Ignition Leads Engine 14279655->	<b>85087</b>
<b>Vectra A CC (88, 89) 1.8 S</b>	<b>1988-89</b>
E 18 NVR	65 88
Ignition Coil	<b>80262</b>
Ignition Leads ->Engine 14180385	<b>83550</b>
Ignition Leads Engine 14275382-14279654	<b>83800</b>
<b>Vectra A CC (88, 89) 2.0</b>	<b>1988-89</b>
C 20 NEF	74 100
Ignition Leads ->Engine 14180385	<b>83530</b>
Ignition Leads ->Engine 14180385; 09.1988->	<b>83550</b>
Ignition Leads Engine 14672353-14841581	<b>83800</b>
Ignition Leads Engine 14279655->	<b>85087</b>
<b>Vectra A CC (88, 89) 2.0 i</b>	<b>1988-90</b>
20 NE	85 115
Ignition Leads ->Engine 14180385	<b>83550</b>
Ignition Leads Engine 14672353-14841581	<b>83800</b>
<b>Vectra A CC (88, 89) 2.0 i 16V</b>	<b>1989-90</b>
20 XEJ	110 150
Ignition Leads Engine P1000001,P5000001->	<b>85080</b>
<b>Vectra A CC (88, 89) 2.0 i 16V</b>	<b>1994-95</b>
X 20 XEV	100 136
Ignition Coil With regul.cat.(3way)	<b>80223</b>
<b>Vectra A CC (88, 89) 2.0 i 16V KAT</b>	<b>1990-95</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
Ignition Leads Engine P1000001,P5000001->	<b>85080</b>
<b>Vectra A CC (88, 89) 2.0 i GT</b>	<b>1988-95</b>
20 SEH	95 129
Ignition Leads Engine 14672353->; ->08.1995	<b>83800</b>
<b>Vectra A CC (88, 89) 2.0 i KAT</b>	<b>1988-95</b>
C 20 NE	85 116
Ignition Leads ->Engine 14180385; ->08.1995	<b>83550</b>
Ignition Leads Engine 14672353-14841581	<b>83800</b>
<b>Vectra B (36) 1.6 i</b>	<b>1995-02</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
Ignition Leads ->Engine 02HP7704	<b>85085</b>
<b>Vectra B (36) 1.6 i 16V</b>	<b>1995-02</b>
Z 16 XE/X 16 XEL/Y 16 XE	74 100
Ignition Coil Ch.W1285447, W7154259->	<b>80209</b>
Ignition Coil	<b>80210</b>
Ignition Leads ->Ch.W1285446,W5276825	<b>85080</b>
<b>Vectra B (36) 1.8 i 16V</b>	<b>1995-00</b>
X 18 XE	85 115
Ignition Coil	<b>80223</b>
<b>Vectra B (36) 1.8 i 16V</b>	<b>2000-02</b>
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra B (36) 1.8 i 16V</b>	<b>1995-00</b>
Z 18 XEL/X 18 XE1	85 115
Ignition Coil	<b>80224</b>
<b>Vectra B (36) 2.0 i 16V</b>	<b>1995-00</b>
X 20 XEV/C 20 SEL	100 136
Ignition Coil With regul.cat.(3way)	<b>80223</b>
<b>Vectra B Caravan (31) 1.6 i</b>	<b>1996-00</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
Ignition Leads ->Engine 02HP7704	<b>85085</b>
<b>Vectra B Caravan (31) 1.6 i 16V</b>	<b>1996-02</b>
Z 16 XE/X 16 XEL/Y 16 XE	74 100
Ignition Coil Ch.W1285447, W7154259->	<b>80209</b>
Ignition Coil	<b>80210</b>
Ignition Leads ->Ch.W1285446,W5276825	<b>85080</b>
<b>Vectra B Caravan (31) 1.8 i 16V</b>	<b>1996-00</b>
X 18 XE	85 115
Ignition Coil	<b>80223</b>
<b>Vectra B Caravan (31) 1.8 i 16V</b>	<b>2000-03</b>
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra B Caravan (31) 1.8 i 16V</b>	<b>1996-00</b>
Z 18 XEL/X 18 XE1	85 115
Ignition Coil	<b>80224</b>



OPEL Cont.		
<b>Vectra B Caravan (31) 2.0 i 16V</b>	1996-00	
X 20 XEV/C 20 SEL	100	136
Ignition Coil With regul.cat.(3way)	<b>80223</b>	
<b>Vectra B CC (38) 1.6 i</b>	1995-03	
X 16 SZR	55	75
Ignition Coil	<b>80210</b>	
Ignition Leads ->Engine 02HP7704	<b>85085</b>	
<b>Vectra B CC (38) 1.6 i 16V</b>	1995-02	
Z 16 XE/X 16 XEL/Y 16 XE	74	101
Ignition Coil Ch.W1285447, W7154259->	<b>80209</b>	
Ignition Coil	<b>80210</b>	
Ignition Leads ->Ch.W1285446,W5276825	<b>85080</b>	
<b>Vectra B CC (38) 1.8 i 16V</b>	1995-00	
X 18 XE	85	116
Ignition Coil	<b>80223</b>	
<b>Vectra B CC (38) 1.8 i 16V</b>	2000-03	
Z 18 XE	92	125
Ignition Coil Z 18 XE	<b>80224</b>	
<b>Vectra B CC (38) 1.8 i 16V</b>	1995-00	
Z 18 XEL/X 18 XE1	85	116
Ignition Coil	<b>80224</b>	
<b>Vectra B CC (38) 2.0 i 16V</b>	1995-00	
X 20 XEV/C 20 SEL	100	136
Ignition Coil With regul.cat.(3way)	<b>80223</b>	
<b>Vectra C 1.6</b>	2006->	
Z 16 XEP	77	105
Ignition Coil	<b>80291</b>	
<b>Vectra C 1.6 16V</b>	2004->	
Z 16 XE	74	100
Ignition Coil Intake manifold injection	<b>80209</b>	
<b>Vectra C 1.8</b>	2002->	
Z 18 XEL	81	110
Ignition Coil	<b>80224</b>	
<b>Vectra C 1.8</b>	2006->	
Z 18 XER	103	140
Ignition Coil	<b>80291</b>	
<b>Vectra C 1.8 16V</b>	2002->	
Z 18 XE	90	122
Ignition Coil Z 18 XE	<b>80224</b>	
<b>Vectra C 2.2 direct</b>	2003->	
Z 22 YH	114	155
Ignition Coil ->10.2008	<b>80269</b>	
<b>Vectra C 2.8 V6 Turbo</b>	2005->	
Z 28 NEL	169	230
Ignition Coil	<b>80355</b>	
<b>Vectra C 2.8 V6 Turbo</b>	2005->	
Z 28 NET	188	255
Ignition Coil	<b>80355</b>	
<b>Vectra C 2.8 V6 Turbo</b>	2006->	
Z 28 NET	184	250
Ignition Coil	<b>80355</b>	
<b>Vectra C Caravan 1.6</b>	2006->	
Z 16 XEP	77	105
Ignition Coil	<b>80291</b>	
<b>Vectra C Caravan 1.6 16V</b>	2004->	
Z 16 XE	74	100
Ignition Coil	<b>80209</b>	
<b>Vectra C Caravan 1.8</b>	2003->	
Z 18 XE	90	122
Ignition Coil	<b>80224</b>	
<b>Vectra C Caravan 1.8</b>	2006->	
Z 18 XER	103	140
Ignition Coil	<b>80291</b>	
<b>Vectra C Caravan 2.2 direct</b>	2003->	
Z 22 YH	114	155
Ignition Coil ->10.2008	<b>80269</b>	
<b>Vectra C Caravan 2.8 V6 Turbo</b>	2005->	
Z 28 NEL	169	230
Ignition Coil	<b>80355</b>	
<b>Vectra C Caravan 2.8 V6 Turbo</b>	2005->	
Z 28 NET	188	255
Ignition Coil	<b>80355</b>	
<b>Vectra C Caravan 2.8 V6 Turbo</b>	2007->	
Z 28 NET	206	280
Ignition Coil	<b>80355</b>	
<b>Vectra C Caravan 2.8 V6 Turbo</b>	2007->	
Z 28 NET	184	250
Ignition Coil	<b>80355</b>	

OPEL Cont.		
<b>Vectra C GTS 1.6</b>	2005->	
Z 16 XE	74	100
Ignition Coil	<b>80209</b>	
<b>Vectra C GTS 1.6</b>	2006->	
Z 16 XEP	77	105
Ignition Coil	<b>80291</b>	
<b>Vectra C GTS 1.8</b>	2006->	
Z 18 XER	103	140
Ignition Coil	<b>80291</b>	
<b>Vectra C GTS 1.8 16V</b>	2002->	
Z 18 XE	90	122
Ignition Coil Z 18 XE	<b>80224</b>	
<b>Vectra C GTS 2.2 direct</b>	2003->	
Z 22 YH	114	155
Ignition Coil ->10.2008	<b>80269</b>	
<b>Vectra C GTS 2.8 V6 Turbo</b>	2005->	
Z 28 NEL	169	230
Ignition Coil	<b>80355</b>	
<b>Vectra C GTS 2.8 V6 Turbo</b>	2005->	
Z 28 NET	188	255
Ignition Coil	<b>80355</b>	
<b>Vectra C GTS 2.8 V6 Turbo</b>	2006->	
Z 28 NET	184	250
Ignition Coil	<b>80355</b>	
<b>Vectra C GTS 2.8 V6 Turbo</b>	2006->	
Z 28 NET	206	280
Ignition Coil	<b>80355</b>	
<b>Vivaro Chassis (E7) 2.0 16V</b>	2003->	
F4R 720	88	120
Ignition Coil	<b>80203</b>	
<b>Vivaro Chassis (E7) 2.0 ECOTEC</b>	2006->	
F4R 820	86	117
Ignition Coil ->Engine C002324; Intake manifold injection	<b>80203</b>	
<b>Vivaro Combi (J7) 2.0 16V</b>	2001->	
F4R 720	88	120
Ignition Coil ->Engine C002324	<b>80203</b>	
<b>Vivaro Combi (J7) 2.0 ECOTEC</b>	2006->	
F4R 820	86	117
Ignition Coil ->Engine C002324; Intake manifold injection	<b>80203</b>	
<b>Vivaro Van (F7) 2.0 16V</b>	2001->	
F4R 720	88	120
Ignition Coil ->Engine C002324	<b>80203</b>	
<b>Vivaro Van (F7) 2.0 ECOTEC</b>	2006->	
F4R 820	86	117
Ignition Coil ->Engine C002324; Intake manifold injection	<b>80203</b>	
<b>Zafira A (F75) 1.6 16V</b>	1999-05	
Z 16 XE/X 16 XEL	74	101
Ignition Coil With regul.cat.(3way)	<b>80209</b>	
<b>Zafira A (F75) 1.6 CNG</b>	2001-05	
Z 16 YNG	71	97
Ignition Coil With regul.cat.(3way)	<b>80209</b>	
Ignition Leads	<b>85085</b>	
<b>Zafira A (F75) 1.8 16V</b>	1999-00	
X 18 XE1	85	116
Ignition Coil	<b>80224</b>	
<b>Zafira A (F75) 1.8 16V</b>	2000-05	
Z 18 XE	92	125
Ignition Coil Z 18 XE	<b>80224</b>	
<b>Zafira A (F75) 2.0 OPC</b>	2001-05	
Z 20 LET	141	192
Ignition Coil	<b>80354</b>	
<b>Zafira A (F75) 2.0 OPC</b>	2002-05	
Z 20 LET/Z 20 LER	147	200
Ignition Coil	<b>80354</b>	
<b>Zafira B (A05) 1.6</b>	2005->	
Z 16 XE1/Z 16 XEP	77	105
Ignition Coil	<b>80291</b>	
<b>Zafira B (A05) 1.6</b>	2008->	
A 16 XER/Z 16 XER	85	115
Ignition Coil	<b>80291</b>	
<b>Zafira B (A05) 1.6 CNG</b>	2006->	
Z 16 YNG	69	94
Ignition Coil	<b>80209</b>	
<b>Zafira B (A05) 1.6 CNG Turbo</b>	2009->	
A 16 XNT/Z 16 XNT	110	150
Ignition Coil	<b>80291</b>	
<b>Zafira B (A05) 1.8</b>	2005->	
Z 18 XER/A 18 XER	103	140
Ignition Coil	<b>80291</b>	



OPEL Cont.	
<b>Zafira B (A05) 1.8</b>	2013->
A 18 XEL	88 120
Ignition Coil	<b>80321</b>
<b>Zafira B (A05) 2.0</b>	2005->
Z 20 LER	147 200
Ignition Coil ->12.2010	<b>80354</b>
<b>Zafira B (A05) 2.0</b>	2006->
Z 20 LEH	177 241
Ignition Coil ->12.2010	<b>80354</b>
<b>Zafira B (A05) 2.2</b>	2005->
Z 22 YH	110 150
Ignition Coil	<b>80269</b>
<b>Zafira B Van 1.6 CNG Turbo</b>	2009->
A 16 XNT/Z 16 XNT	110 150
Ignition Coil	<b>80291</b>
<b>Zafira B Van 1.8</b>	2005->
Z 18 XER/A 18 XER	103 140
Ignition Coil	<b>80291</b>
<b>Zafira Tourer C (P12) 1.4</b>	2011->
B 14 NEL/A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Zafira Tourer C (P12) 1.4</b>	2011->
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Zafira Tourer C (P12) 1.4 LPG</b>	2011->
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Zafira Tourer C (P12) 1.6 CNG</b>	2011->
A 16 XNT/B 16 XNT	110 150
Ignition Coil	<b>80291</b>
<b>Zafira Tourer C (P12) 1.8</b>	2011->
A 18 XER	103 140
Ignition Coil	<b>80291</b>
Ignition Coil	<b>80321</b>
<b>Zafira Tourer C (P12) 1.8</b>	2011->
A 18 XEL	85 115
Ignition Coil	<b>80321</b>
<b>Zafira Tourer C (P12) 1.8 LPG</b>	2011->
A 18 XER	101 137
Ignition Coil	<b>80291</b>
Ignition Coil	<b>80321</b>

PEUGEOT	
<b>1007 (Km) 1.4</b>	2005->
KFV (TU3JP)/KFV (TU3A)	54 75
Ignition Coil	<b>80208</b>
<b>1007 (Km) 1.4 16V</b>	2005->
KFU (ET3J4)	65 88
Ignition Coil	<b>80236</b>
<b>1007 (Km) 1.6 16V</b>	2005->
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
<b>104 1.1</b>	1980-88
109F (XW7)	37 50
Ignition Leads	<b>83370</b>
<b>104 Coupe 1.1</b>	1979-88
109F (XW7)	37 50
Ignition Leads	<b>83370</b>
<b>104 Coupe 1.4</b>	1979-84
150 (XY6B)	53 72
Ignition Leads	<b>83370</b>
<b>106 I (1A, 1C) 1.0</b>	1991-96
TU9/CDY (TU9M)	33 45
Ignition Coil	<b>80260</b>
Ignition Coil CDY; 07.1992->	<b>80272</b>
Ignition Leads TU9	<b>83650</b>
Ignition Leads	<b>85600</b>
<b>106 I (1A, 1C) 1.0</b>	1991-96
CDZ (TU9M)	37 50
Ignition Coil	<b>80260</b>
Ignition Coil 07.1992->	<b>80272</b>
Ignition Leads	<b>85600</b>
<b>106 I (1A, 1C) 1.1</b>	1991-96
HDZ (TU1M)	44 60
Ignition Coil ->07.1992	<b>80260</b>
Ignition Coil 08.1992->	<b>80272</b>
Ignition Leads SAE	<b>83650</b>
Ignition Leads	<b>85600</b>

PEUGEOT Cont.	
<b>106 I (1A, 1C) 1.3</b>	1993-96
TU2J2	72 98
Ignition Coil	<b>80272</b>
Ignition Leads	<b>85600</b>
<b>106 I (1A, 1C) 1.4</b>	1991-96
K5A (TU3)	51 69
Ignition Coil	<b>80260</b>
<b>106 I (1A, 1C) 1.4</b>	1991-96
KDX (TU3MC)/KDY (TU3M)	55 75
Ignition Coil KDY; ->02.1994	<b>80260</b>
Ignition Coil KDX; 12.1992->	<b>80272</b>
Ignition Leads KDY (TU3M)	<b>83650</b>
Ignition Leads	<b>85600</b>
<b>106 I (1A, 1C) 1.4</b>	1991-96
KFZ (TU3J2/Z)	69 94
Ignition Coil	<b>80272</b>
Ignition Leads	<b>85600</b>
<b>106 I (1A, 1C) 1.6</b>	1993-96
NFZ (TU5JP)	65 88
Ignition Coil	<b>80272</b>
Ignition Leads	<b>85600</b>
<b>106 I (1A, 1C) 1.6</b>	1994-96
NFY (TU5J2)	76 103
Ignition Coil	<b>80272</b>
Ignition Leads	<b>85600</b>
<b>106 II (1) 1.0 i</b>	1996-99
CDY (TU9M)	33 45
Ignition Coil ->05.1997	<b>80207</b>
Ignition Coil	<b>80208</b>
Ignition Coil 06.1997->	<b>80226</b>
Ignition Leads	<b>83650</b>
Ignition Leads	<b>85600</b>
<b>106 II (1) 1.0 i</b>	1997->
CDZ (TU9M)	37 50
Ignition Coil ->05.1997	<b>80207</b>
Ignition Coil 06.2000->	<b>80208</b>
Ignition Coil 06.1997-05.2000	<b>80226</b>
Ignition Leads	<b>85600</b>
<b>106 II (1) 1.1 i</b>	1996-04
HDZ (TU1M)/HFX (TU1JP)	44 60
Ignition Coil ->06.1997	<b>80207</b>
Ignition Coil 06.2000->	<b>80208</b>
Ignition Coil 06.1997-06.2000	<b>80226</b>
Ignition Leads	<b>85600</b>
<b>106 II (1) 1.1 i</b>	1997->
HDY (TU1M)	40 54
Ignition Coil ->05.1997	<b>80207</b>
Ignition Coil 06.2000->	<b>80208</b>
Ignition Coil 06.1997-05.2000	<b>80226</b>
Ignition Coil H3A<TU1>; ->05.2005	<b>80260</b>
Ignition Leads	<b>85600</b>
<b>106 II (1) 1.4 i</b>	1996-04
KFX (TU3JP)/KFW (TU3JP)	55 75
Ignition Coil	<b>80207</b>
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
Ignition Leads	<b>85600</b>
<b>106 II (1) 1.6 i</b>	1996-99
NFZ (TU5JP)	65 89
Ignition Coil NFZ (TU5JP)	<b>80207</b>
Ignition Leads	<b>85600</b>
<b>106 II (1) 1.6 i</b>	1996-01
NFW (TU5J2)/NFY (TU5J2)	74 101
Ignition Coil	<b>80272</b>
Ignition Leads	<b>85600</b>
<b>106 II (1) 1.6 S16</b>	1996-04
NFX (TU5J4)	87 118
Ignition Coil	<b>80310</b>
Ignition Leads	<b>85600</b>
<b>107 1.0</b>	2005->
CFA (384F)/CFB (1KR)	50 68
Ignition Coil	<b>80282</b>
<b>108 1.0 VTi</b>	2014->
1KR-FE	51 69
Ignition Coil	<b>80282</b>
<b>108 1.2</b>	2014->
HMT (EB2D)	60 82
Ignition Coil	<b>80273</b>





PEUGEOT Cont.	
<b>2008 1.2 Vti</b>	2013->
HMZ (EB2F)	60 82
Ignition Coil	<b>80273</b>
<b>2008 1.6 VTi</b>	2013->
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>205 I (741A/C) 1.6</b>	<b>1987-87</b>
B1E (XU51C)	53 72
Ignition Leads	<b>83380</b>
<b>205 I (741A/C) 1.6</b>	<b>1986-87</b>
B1A (XU51C)	55 75
Ignition Leads	<b>83380</b>
<b>205 I (741A/C) 1.6 GTI</b>	<b>1984-87</b>
180A (XU5J)	76 103
Ignition Leads	<b>83380</b>
<b>205 I (741A/C) 1.9 GTI</b>	<b>1986-87</b>
D6B (XU9JA)	94 128
Ignition Leads Ch.73300001->	<b>83380</b>
<b>205 I (741A/C) 1.9 GTI</b>	<b>1987-87</b>
DFZ (XU9J1)	75 102
Ignition Coil	<b>80263</b>
Ignition Leads Ch.73300001->	<b>83380</b>
<b>205 I Cabrio (741B, 20D) 1.1 CJ</b>	<b>1989-94</b>
HDZ (TU1M)	44 60
Ignition Coil Ch.S24902801->	<b>80207</b>
Ignition Coil ->Ch.S24902800	<b>80263</b>
Ignition Leads	<b>83650</b>
<b>205 I Cabrio (741B, 20D) 1.4 CJ</b>	<b>1988-89</b>
150D (XY7)/150G (XY7)	44 60
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 I Cabrio (741B, 20D) 1.4 CJ</b>	<b>1989-94</b>
K1D (TU3A)	49 67
Ignition Coil	<b>80263</b>
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 I Cabrio (741B, 20D) 1.4 CJ</b>	<b>1991-94</b>
KDZ (TU3M)/KDY (TU3M)	55 75
Ignition Coil	<b>80263</b>
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 I Cabrio (741B, 20D) 1.4 CJ KAT</b>	<b>1989-93</b>
KAY (TU3CP)	44 60
Ignition Coil	<b>80263</b>
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 I Cabrio (741B, 20D) 1.4 CT</b>	<b>1986-88</b>
150B (XY8)/150H (XY8)	58 79
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 I Cabrio (741B, 20D) 1.6 CJ</b>	<b>1992-94</b>
BDY (XU5M3Z)	65 88
Ignition Coil	<b>80207</b>
<b>205 I Cabrio (741B, 20D) 1.6 CTI</b>	<b>1986-90</b>
180A (XU5J)/180Z (XU5J)	76 103
Ignition Leads	<b>83380</b>
<b>205 I Cabrio (741B, 20D) 1.9 CTI</b>	<b>1987-94</b>
DFZ (XU9J1)	75 102
Ignition Coil	<b>80263</b>
Ignition Leads 01.1991-12.1994	<b>83320</b>
Ignition Leads Bosch	<b>83380</b>
<b>205 II (20A/C) 1.0</b>	<b>1987-98</b>
TU9	33 45
Ignition Coil	<b>80263</b>
Ignition Coil 07.1992->	<b>80272</b>
Ignition Leads	<b>83650</b>
<b>205 II (20A/C) 1.1</b>	<b>1987-90</b>
H1B (TU1)	40 54
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>
<b>205 II (20A/C) 1.1</b>	<b>1989-98</b>
HDZ (TU1M)	44 60
Ignition Coil Ch.S24902801->; 06.1993-06.1997	<b>80207</b>
Ignition Coil 06.1997->	<b>80226</b>
Ignition Coil 06.1991-05.1993	<b>80260</b>
Ignition Coil ->Ch.S24902800; ->05.1991	<b>80263</b>
Ignition Coil 01.1991-12.1994	<b>80272</b>
Ignition Leads	<b>83650</b>
<b>205 II (20A/C) 1.3</b>	<b>1990-92</b>
G1A	47 64
Ignition Leads	<b>83370</b>
<b>205 II (20A/C) 1.3 Rallye</b>	<b>1987-90</b>
TU24	74 101
Ignition Coil	<b>80263</b>

PEUGEOT Cont.	
<b>205 II (20A/C) 1.4</b>	<b>1987-88</b>
150 (XY6B)	53 72
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 II (20A/C) 1.4</b>	<b>1987-89</b>
150D (XY7)/150G (XY7)	44 60
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 II (20A/C) 1.4</b>	<b>1987-90</b>
K1D (TU3A)	49 67
Ignition Coil	<b>80263</b>
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 II (20A/C) 1.4</b>	<b>1988-89</b>
150B (XY8)/150H (XY8)	58 79
Ignition Coil	<b>80263</b>
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 II (20A/C) 1.4</b>	<b>1987-89</b>
K2B (TU3S)	62 84
Ignition Coil	<b>80263</b>
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 II (20A/C) 1.4</b>	<b>1988-98</b>
KFX (TU3JP)/KDZ (TU3M)/KDY (TU3M)	55 75
Ignition Coil	<b>80260</b>
Ignition Coil KDZ(TU3M), KDY(TU3M)	<b>80263</b>
Ignition Coil 01.1991->	<b>80272</b>
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 II (20A/C) 1.4</b>	<b>1990-98</b>
KDX (TU3MC)/TU32/KDZ (TU3M)/KDY (TU3M)	55 75
Ignition Coil KDX; Engine 18081179->; 01.1996->	<b>80207</b>
Ignition Coil ->08.1992	<b>80263</b>
Ignition Coil KDX; ->Engine 1808178; 09.1992-12.1995	<b>80272</b>
<b>205 II (20A/C) 1.4</b>	<b>1987-89</b>
Y2/K	63 86
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 II (20A/C) 1.4 KAT</b>	<b>1987-93</b>
KAY (TU3CP)	44 60
Ignition Coil	<b>80263</b>
Ignition Leads ->Ch.24902800	<b>83650</b>
<b>205 II (20A/C) 1.6</b>	<b>1987-98</b>
B1E (XU51C)	53 72
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83320</b>
Ignition Leads Bosch	<b>83380</b>
<b>205 II (20A/C) 1.6</b>	<b>1987-98</b>
BAZ (XU5CP)/B1A (XU51C)	55 75
Ignition Leads	<b>83320</b>
Ignition Leads ->01.1990	<b>83380</b>
<b>205 II (20A/C) 1.6 Aut.</b>	<b>1990-98</b>
BDY (XU5M2Z)/BDY (XU5M3Z)	65 88
Ignition Coil	<b>80207</b>
<b>205 II (20A/C) 1.6 GTI</b>	<b>1987-89</b>
180A (XU5J)/180Z (XU5J)	76 103
Ignition Leads	<b>83380</b>
<b>205 II (20A/C) 1.6 GTX</b>	<b>1987-91</b>
	69 94
Ignition Leads	<b>83370</b>
<b>205 II (20A/C) 1.9 GTI</b>	<b>1987-98</b>
D6B (XU9JA)	94 128
Ignition Coil	<b>80263</b>
Ignition Leads 01.1991->	<b>83320</b>
Ignition Leads Ch.73300001->	<b>83380</b>
<b>205 II (20A/C) 1.9 GTI</b>	<b>1987-89</b>
D2A (XU92C)	75 102
Ignition Leads Ch.73300001->	<b>83380</b>
<b>205 II (20A/C) 1.9 GTI</b>	<b>1987-94</b>
DKZ (XU9JAZ)	88 120
Ignition Coil	<b>80263</b>
Ignition Leads 01.1991->	<b>83320</b>
Ignition Leads Ch.73300001->	<b>83380</b>
<b>205 II (20A/C) 1.9 GTI KAT</b>	<b>1987-94</b>
DFZ (XU9J1)	75 102
Ignition Coil	<b>80263</b>
Ignition Leads 01.1991->	<b>83320</b>
Ignition Leads Ch.73300001->	<b>83380</b>
<b>205 Kasten 1.1</b>	<b>1987-90</b>
H1B (TU1)	40 54
Ignition Coil	<b>80263</b>
<b>206 CC (2D) 1.6 16V</b>	<b>2000-&gt;</b>
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>





PEUGEOT Cont.	
<b>206 CC (2D) 2.0 S16</b>	2000->
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>206 Fastback (2A/C) 1.1</b>	1998-00
HFY (TU1JP)	40 54
Ignition Coil	<b>80226</b>
<b>206 Fastback (2A/C) 1.1 i</b>	1998->
HFZ (TU1JP)/HFY (TU1JP)	44 60
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
<b>206 Fastback (2A/C) 1.4 16V</b>	2003->
KFU (ET3J4)	65 88
Ignition Coil	<b>80226</b>
Ignition Coil	<b>80236</b>
<b>206 Fastback (2A/C) 1.4 i</b>	1998->
KFX (TU3JP)/KFW (TU3JP)	55 75
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
<b>206 Fastback (2A/C) 1.4 LPG</b>	2006-07
KFV (TU3JP)	55 75
Ignition Coil	<b>80208</b>
<b>206 Fastback (2A/C) 1.6 16V</b>	2000->
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
<b>206 Fastback (2A/C) 1.6 i</b>	1998-00
NFZ (TU5JP)	65 89
Ignition Coil With regul.cat.(3way)	<b>80208</b>
Ignition Coil Hydraulic Brake	<b>80226</b>
Ignition Coil ->Ch.3200	<b>80272</b>
<b>206 Fastback (2A/C) 2.0 RC</b>	2003->
RFK (EW10J4S)	130 177
Ignition Coil	<b>80277</b>
<b>206 Fastback (2A/C) 2.0 S16</b>	1999-00
RFR (DEW10J4)	99 135
Ignition Coil	<b>80275</b>
<b>206 Fastback (2A/C) 2.0 S16</b>	1999->
RFN (EW10J4)/RFR (DEW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>206 Sedan 1.6 16V</b>	2007->
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>206 SW (2E/K) 1.1</b>	2002->
HFX (TU1JP)	44 60
Ignition Coil	<b>80208</b>
<b>206 SW (2E/K) 1.4</b>	2002->
KFV (TU3A)/KFW (TU3JP)	55 75
Ignition Coil	<b>80208</b>
<b>206 SW (2E/K) 1.4 16V</b>	2003->
KFU (ET3J4)	65 88
Ignition Coil	<b>80236</b>
<b>206 SW (2E/K) 1.6 16V</b>	2002->
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
<b>206 SW (2E/K) 2.0 16V</b>	2002->
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>207 (WA, WC) 1.4 16V</b>	2006->
KFU (ET3J4)	65 88
Ignition Coil	<b>80236</b>
<b>207 (WA, WC) 1.4 16V</b>	2007->
EP3C/8FS (EP3)/EP3	70 95
Ignition Coil EP3	<b>80247</b>
<b>207 (WA, WC) 1.4 16V</b>	2009->
8FR (EP3)	72 98
Ignition Coil	<b>80247</b>
<b>207 (WA, WC) 1.6 16V</b>	2006->
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>207 (WA, WC) 1.6 16V RC</b>	2007->
5FY (EP6DTS)	128 174
Ignition Coil	<b>80247</b>
<b>207 (WA, WC) 1.6 16V Turbo</b>	2006->
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>207 (WA, WC) 1.6 16V Turbo</b>	2009->
5FR (EP6DT)	115 156
Ignition Coil	<b>80247</b>

PEUGEOT Cont.	
<b>207 (WA, WC) 1.6 16V VTI</b>	2007->
5FS (EP6C)/EP6/5FW (EP6)	88 120
Ignition Coil	<b>80247</b>
<b>207 CC (WD) 1.6 16V</b>	2007->
5FS (EP6C)/EP6/5FW (EP6)	88 120
Ignition Coil EP6	<b>80247</b>
<b>207 CC (WD) 1.6 16V Turbo</b>	2007->
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>207 CC (WD) 1.6 16V Turbo</b>	2009->
EP6CDT/5FR (EP6DT)	115 156
Ignition Coil	<b>80247</b>
<b>207 SW (WK) 1.4 16V</b>	2007->
EP3C/8FS (EP3)/EP3	70 95
Ignition Coil	<b>80247</b>
<b>207 SW (WK) 1.4 16V</b>	2009->
8FR (EP3)	72 98
Ignition Coil	<b>80247</b>
<b>207 SW (WK) 1.6 16V</b>	2007->
5FS (EP6C)/EP6/5FW (EP6)	88 120
Ignition Coil EP6	<b>80247</b>
<b>207 SW (WK) 1.6 16V RC</b>	2007->
5FY (EP6DTS)	128 174
Ignition Coil	<b>80247</b>
<b>207 SW (WK) 1.6 16V Turbo</b>	2007->
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>208 1.0</b>	2012->
ZMZ (EB0)	50 68
Ignition Coil	<b>80273</b>
<b>208 1.2</b>	2012->
HMZ (EB2F)	60 82
Ignition Coil	<b>80273</b>
<b>208 1.4</b>	2012->
EP3C/8FS (EP3)	70 95
Ignition Coil EP3C	<b>80247</b>
<b>208 1.4 GPL</b>	2013->
EP3C	70 95
Ignition Coil	<b>80247</b>
<b>208 1.6</b>	2012->
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>208 1.6</b>	2012->
5FV (EP6CDT)	115 156
Ignition Coil	<b>80247</b>
<b>208 1.6 GTi</b>	2014->
	153 208
Ignition Coil	<b>80247</b>
<b>208 1.6 GTi</b>	2012->
5FU (EP6CDTX)	147 200
Ignition Coil	<b>80247</b>
<b>208 1.6 THP 165</b>	2015->
	121 165
Ignition Coil	<b>80247</b>
<b>3008 1.6 THP</b>	2009->
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>3008 1.6 THP</b>	2009->
5FV (EP6CDT)	115 156
Ignition Coil	<b>80247</b>
<b>3008 1.6 Turbo</b>	2014->
5GZ (EP6FDT)	121 165
Ignition Coil	<b>80247</b>
<b>3008 1.6 VTI</b>	2009->
5FS (EP6C)/EP6/5FW (EP6)	88 120
Ignition Coil	<b>80247</b>
<b>301 1.2 VTI 72</b>	2012->
HMY (EB2M)	53 72
Ignition Coil	<b>80273</b>
<b>301 1.6 VTI 115</b>	2012->
NFP (EC5)	85 115
Ignition Coil	<b>80271</b>
<b>304 (04M) 1.3 GT</b>	1969-75
XL3	48 65
Ignition Leads	<b>83370</b>
<b>304 Cabrio (04B) 1,3</b>	1972-76
XL3S	55 75
Ignition Leads	<b>83370</b>



PEUGEOT Cont.		
<b>304 Cabrio (04B) 1,3</b>	<b>1970-73</b>	
XL3	48 65	
Ignition Leads	<b>83370</b>	
<b>304 Coupe (04C) 1,3</b>	<b>1972-75</b>	
XL3S	55 75	
Ignition Leads	<b>83370</b>	
<b>304 Coupe (04C) 1,3</b>	<b>1970-73</b>	
XL3	48 65	
Ignition Leads	<b>83370</b>	
<b>305 II (581M) 1.6</b>	<b>1984-87</b>	
171 (XU5S)	66 90	
Ignition Leads	<b>83380</b>	
<b>305 II (581M) 1.6</b>	<b>1982-84</b>	
171 (XU5S)	71 97	
Ignition Leads	<b>83380</b>	
<b>305 II (581M) 1.6</b>	<b>1982-88</b>	
B1A (XU51C)	55 75	
Ignition Leads	<b>83380</b>	
<b>305 II (581M) 1.6</b>	<b>1986-88</b>	
BAZ (XU5CP)	54 73	
Ignition Leads	<b>83380</b>	
<b>305 II (581M) 1.9</b>	<b>1982-85</b>	
159 (XU9S)	75 102	
Ignition Leads	<b>83380</b>	
<b>305 II (581M) 1.9</b>	<b>1986-88</b>	
DFZ (XU9J1)	72 98	
Ignition Leads	<b>83380</b>	
<b>305 II Break (581E) 1.6</b>	<b>1986-88</b>	
B1A (XU51C)	55 75	
Ignition Leads	<b>83380</b>	
<b>305 II Break (581E) 1.6</b>	<b>1984-87</b>	
171 (XU5S)	66 90	
Ignition Leads	<b>83380</b>	
<b>305 II Break (581E) 1.9</b>	<b>1984-87</b>	
159 (XU9S)	75 102	
Ignition Leads	<b>83380</b>	
<b>305 II Break (581E) 1.9</b>	<b>1986-88</b>	
DFZ (XU9J1)	72 98	
Ignition Leads	<b>83380</b>	
<b>306 (7B, N3, N5) 1.1</b>	<b>1994-01</b>	
HDZ (TU1M)	44 60	
Ignition Coil 01.1996-04.1997	<b>80207</b>	
Ignition Coil ->12.1995	<b>80272</b>	
Ignition Leads	<b>85600</b>	
<b>306 (7B, N3, N5) 1.4 SL</b>	<b>1994-01</b>	
KDX (TU3MC)/KFX (TU3JP)/KFW (TU3JP)	55 75	
Ignition Coil KFX (TU3JP); 09.1996-06.1998	<b>80207</b>	
Ignition Coil 06.2000->; With regul.cat.(3way)	<b>80208</b>	
Ignition Coil KFX, KFW; 06.1997-06.2000	<b>80226</b>	
Ignition Coil KDX; ->04.1997	<b>80272</b>	
Ignition Leads	<b>85600</b>	
<b>306 (7B, N3, N5) 1.6</b>	<b>2000-01</b>	
NFT (TU5JP)	72 98	
Ignition Coil	<b>80208</b>	
<b>306 (7B, N3, N5) 1.6 SR</b>	<b>1994-00</b>	
NFZ (TU5JP)	65 89	
Ignition Coil 05.1997-06.1998	<b>80207</b>	
Ignition Coil With regul.cat.(3way)	<b>80208</b>	
Ignition Coil 07.1998->	<b>80226</b>	
Ignition Coil ->04.1997	<b>80272</b>	
Ignition Leads	<b>85600</b>	
<b>306 (7B, N3, N5) 1.8 16V</b>	<b>1997-01</b>	
LFY (XU7JP4)	81 110	
Ignition Coil ->12.1997; With regul.cat.(3way)	<b>80237</b>	
Ignition Coil SAE; Vet. 07609->	<b>80274</b>	
<b>306 (7B, N3, N5) 1.8 ST</b>	<b>1994-01</b>	
LFZ (XU7JP)	74 101	
Ignition Coil	<b>80207</b>	
Ignition Coil 03.1997-12.1997; With regul.cat.(3way)	<b>80237</b>	
<b>306 (7B, N3, N5) 2.0</b>	<b>1997-01</b>	
RFV (XU10J4R)	97 132	
Ignition Coil	<b>80207</b>	
Ignition Coil SAE	<b>80274</b>	
Ignition Leads	<b>83330</b>	
<b>306 (7B, N3, N5) 2.0 S16</b>	<b>1994-01</b>	
RFY (XU10J4Z)	112 152	
Ignition Coil	<b>80207</b>	

PEUGEOT Cont.		
<b>306 (7B, N3, N5) 2.0 ST</b>	<b>1994-01</b>	
RFX (XU10J2)	89 121	
Ignition Coil RFX (XU10J2)	<b>80207</b>	
Ignition Leads	<b>83330</b>	
<b>306 Break (7E, N3, N5) 1.4</b>	<b>1997-02</b>	
KFX (TU3JP)/KFW (TU3JP)	55 75	
Ignition Coil KFX (TU3JP); 05.1997-06.1998	<b>80207</b>	
Ignition Coil With regul.cat.(3way)	<b>80208</b>	
Ignition Coil Hydraulic Brake	<b>80226</b>	
Ignition Coil K5A<TU3.2>; 05.1997-03.2002	<b>80260</b>	
Ignition Leads	<b>83330</b>	
<b>306 Break (7E, N3, N5) 1.6</b>	<b>2000-02</b>	
NFT	72 98	
Ignition Coil	<b>80208</b>	
<b>306 Break (7E, N3, N5) 1.6</b>	<b>1997-00</b>	
NFZ (TU5JP)	65 89	
Ignition Coil 05.1997-05.1998	<b>80207</b>	
Ignition Coil With regul.cat.(3way)	<b>80208</b>	
Ignition Coil 06.1998->	<b>80226</b>	
Ignition Coil ->04.1997	<b>80272</b>	
Ignition Leads	<b>85600</b>	
<b>306 Break (7E, N3, N5) 1.8</b>	<b>1997-02</b>	
LFZ (XU7JP)	74 101	
Ignition Coil LFZ (XU7JP)	<b>80207</b>	
<b>306 Break (7E, N3, N5) 1.8 16V</b>	<b>1997-02</b>	
LFY (XU7JP4)	81 110	
Ignition Coil ->12.1997; With regul.cat.(3way)	<b>80237</b>	
Ignition Coil SAE; Vet. 07609->	<b>80274</b>	
<b>306 Break (7E, N3, N5) 2.0</b>	<b>1997-02</b>	
RFV (XU10J4R)	97 132	
Ignition Coil	<b>80207</b>	
Ignition Coil SAE	<b>80274</b>	
Ignition Leads	<b>83330</b>	
<b>306 Cabrio (7D, N3, N5) 1.6</b>	<b>2000-02</b>	
NFT (TU5JP)	72 98	
Ignition Coil	<b>80208</b>	
<b>306 Cabrio (7D, N3, N5) 1.6</b>	<b>1996-00</b>	
NFZ (TU5JP)	65 89	
Ignition Coil 05.1997-06.1998	<b>80207</b>	
Ignition Coil With regul.cat.(3way)	<b>80208</b>	
Ignition Coil 07.1998->	<b>80226</b>	
Ignition Coil ->04.1997	<b>80272</b>	
Ignition Leads	<b>85600</b>	
<b>306 Cabrio (7D, N3, N5) 1.8</b>	<b>1994-02</b>	
LFZ (XU7JP)	74 101	
Ignition Coil	<b>80207</b>	
Ignition Coil ->12.1997; With regul.cat.(3way)	<b>80237</b>	
<b>306 Cabrio (7D, N3, N5) 1.8 16V</b>	<b>2000-02</b>	
LFY (XU7JP4)	81 110	
Ignition Coil	<b>80237</b>	
Ignition Coil SAE; Vet. 07609->	<b>80274</b>	
<b>306 Cabrio (7D, N3, N5) 2.0</b>	<b>1994-02</b>	
RFX (XU10J2)	89 121	
Ignition Coil RFX (XU10J2)	<b>80207</b>	
Ignition Leads	<b>83330</b>	
<b>306 Cabrio (7D, N3, N5) 2.0 16V</b>	<b>1997-02</b>	
RFV (XU10J4R)	97 132	
Ignition Coil	<b>80207</b>	
Ignition Coil SAE	<b>80274</b>	
Ignition Leads	<b>83330</b>	
<b>306 Fastback (7A, 7C, N3, N5) 1.1</b>	<b>1993-01</b>	
HDZ (TU1M)	44 60	
Ignition Coil 01.1996-04.1997	<b>80207</b>	
Ignition Coil ->12.1995	<b>80272</b>	
Ignition Leads	<b>85600</b>	
<b>306 Fastback (7A, 7C, N3, N5) 1.4</b>	<b>1993-01</b>	
KDX (TU3MC)/KFX (TU3JP)/KFW (TU3JP)	55 75	
Ignition Coil KFX (TU3JP); 09.1996-04.1997	<b>80207</b>	
Ignition Coil KFX, KFW; 06.1998->; With regul.cat.(3way)	<b>80208</b>	
Ignition Coil KFX, KFW; Hydraulic Brake	<b>80226</b>	
Ignition Coil KDX; ->04.1997	<b>80272</b>	
Ignition Leads	<b>85600</b>	
<b>306 Fastback (7A, 7C, N3, N5) 1.6</b>	<b>2000-01</b>	
NFT	72 98	
Ignition Coil	<b>80208</b>	



PEUGEOT Cont.	
<b>306 Fastback (7A, 7C, N3, N5) 1.6</b>	<b>1993-00</b>
NFZ (TU5JP)	65 89
Ignition Coil 05.1997-06.1998	<b>80207</b>
Ignition Coil NFZ (TU5JP); With regul.cat.(3way)	<b>80208</b>
Ignition Coil 07.1998->	<b>80226</b>
Ignition Coil ->04.1997	<b>80272</b>
Ignition Leads	<b>85600</b>
<b>306 Fastback (7A, 7C, N3, N5) 1.8</b>	<b>1993-01</b>
LFZ (XU7JP)	74 101
Ignition Coil	<b>80207</b>
Ignition Coil With regul.cat.(3way); 03.1997-12.1997	<b>80237</b>
<b>306 Fastback (7A, 7C, N3, N5) 1.8 16V</b>	<b>1997-01</b>
LFY (XU7JP4)	81 110
Ignition Coil ->12.1997; With regul.cat.(3way)	<b>80237</b>
Ignition Coil SAE; Vet. 07609->	<b>80274</b>
<b>306 Fastback (7A, 7C, N3, N5) 2.0 16V</b>	<b>1997-01</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80207</b>
Ignition Coil SAE	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>306 Fastback (7A, 7C, N3, N5) 2.0 S16</b>	<b>1993-01</b>
RFY (XU10J4Z)	112 152
Ignition Coil	<b>80207</b>
<b>306 Fastback (7A, 7C, N3, N5) 2.0 XSi</b>	<b>1993-01</b>
RFX (XU10J2)	89 121
Ignition Coil RFX (XU10J2)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>307 (3A/C) 1.4</b>	<b>2000-&gt;</b>
KFW (TU3JP)	55 75
Ignition Coil	<b>80208</b>
<b>307 (3A/C) 1.4 16V</b>	<b>2003-&gt;</b>
KFU (ET3J4)	65 88
Ignition Coil	<b>80236</b>
<b>307 (3A/C) 1.6 16V</b>	<b>2000-&gt;</b>
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>307 (3A/C) 2.0 16V</b>	<b>2000-&gt;</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>307 (3A/C) 2.0 16V</b>	<b>2005-&gt;</b>
RFJ (EW10A)/RFN (EW10J4)	103 140
Ignition Coil	<b>80278</b>
<b>307 (3A/C) 2.0 16V</b>	<b>2005-&gt;</b>
RFK (EW10J4S)	130 177
Ignition Coil	<b>80277</b>
<b>307 Break (3E) 1.4 16V</b>	<b>2003-&gt;</b>
KFU (ET3J4)	65 88
Ignition Coil	<b>80236</b>
<b>307 Break (3E) 1.6 16V</b>	<b>2002-&gt;</b>
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>307 Break (3E) 2.0</b>	<b>2002-&gt;</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
Ignition Coil	<b>80278</b>
<b>307 Break (3E) 2.0 16V</b>	<b>2005-&gt;</b>
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>307 Break (3E) 2.0 16V</b>	<b>2005-&gt;</b>
RFK (EW10J4S)	130 177
Ignition Coil	<b>80277</b>
<b>307 CC (3B) 1.6 16V</b>	<b>2005-&gt;</b>
NFU (TU5JP4)	80 110
Ignition Coil	<b>80235</b>
<b>307 CC (3B) 2.0 16V</b>	<b>2003-&gt;</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>307 CC (3B) 2.0 16V</b>	<b>2003-&gt;</b>
RFK (EW10J4S)	130 177
Ignition Coil	<b>80277</b>
<b>307 CC (3B) 2.0 16V</b>	<b>2005-&gt;</b>
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>307 SW (3H) 1.4 16V</b>	<b>2003-&gt;</b>
KFU (ET3J4)	65 88
Ignition Coil	<b>80236</b>
<b>307 SW (3H) 1.6 16V</b>	<b>2002-&gt;</b>
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>

PEUGEOT Cont.	
<b>307 SW (3H) 2.0 16V</b>	<b>2002-&gt;</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>307 SW (3H) 2.0 16V</b>	<b>2005-&gt;</b>
RFJ (EW10A)/RFN (EW10J4)	103 140
Ignition Coil	<b>80278</b>
<b>308 (4A, 4C) 1.4 16V</b>	<b>2007-&gt;</b>
8FS (EP3)/EP3	70 95
Ignition Coil EP3	<b>80247</b>
<b>308 (4A, 4C) 1.4 16V</b>	<b>2009-&gt;</b>
8FR (EP3)	72 98
Ignition Coil	<b>80247</b>
<b>308 (4A, 4C) 1.6 16V</b>	<b>2007-&gt;</b>
EP6/5FW (EP6)	88 120
Ignition Coil EP6	<b>80247</b>
<b>308 (4A, 4C) 1.6 16V</b>	<b>2007-&gt;</b>
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>308 (4A, 4C) 1.6 16V</b>	<b>2008-&gt;</b>
5FY (EP6DTS)	128 174
Ignition Coil	<b>80247</b>
<b>308 (4A, 4C) 1.6 16V</b>	<b>2007-&gt;</b>
5FT (EP6DT)	103 140
Ignition Coil	<b>80247</b>
<b>308 (4A, 4C) 1.6 16V</b>	<b>2009-&gt;</b>
EP6CDT	115 156
Ignition Coil	<b>80247</b>
<b>308 (4A, 4C) 1.6 BioFlex</b>	<b>2008-&gt;</b>
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>308 (4A, 4C) 1.6 GTi</b>	<b>2010-&gt;</b>
EP6CDTX	147 200
Ignition Coil	<b>80247</b>
<b>308 Cc 1.6 16V</b>	<b>2009-&gt;</b>
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>
<b>308 Cc 1.6 16V</b>	<b>2009-&gt;</b>
EP6	88 120
Ignition Coil	<b>80247</b>
<b>308 Cc 1.6 16V</b>	<b>2009-&gt;</b>
EP6CDT	115 156
Ignition Coil	<b>80247</b>
<b>308 Cc 1.6 16V</b>	<b>2009-&gt;</b>
5FT (EP6DT)	103 140
Ignition Coil	<b>80247</b>
<b>308 Cc 1.6 THP</b>	<b>2010-&gt;</b>
EP6CDTX	147 200
Ignition Coil	<b>80247</b>
<b>308 II 1.2 VTi 72</b>	<b>2013-&gt;</b>
HMZ (EB2F)	60 82
Ignition Coil	<b>80273</b>
<b>308 II 1.6</b>	<b>2013-&gt;</b>
5FV (EP6CDT)	115 156
Ignition Coil	<b>80247</b>
<b>308 II 1.6 GT 205</b>	<b>2014-&gt;</b>
	151 205
Ignition Coil	<b>80247</b>
<b>308 II 1.6 GTi</b>	<b>2015-&gt;</b>
5GN (EP6FDTR)	200 272
Ignition Coil	<b>80247</b>
<b>308 II 1.6 GTi</b>	<b>2015-&gt;</b>
	184 250
Ignition Coil	<b>80247</b>
<b>308 II 1.6 THP 125</b>	<b>2013-&gt;</b>
5FA (EP6CDT)	92 125
Ignition Coil	<b>80247</b>
<b>308 SW 1.4 16V</b>	<b>2007-&gt;</b>
8FS (EP3)	70 95
Ignition Coil	<b>80247</b>
<b>308 SW 1.4 16V</b>	<b>2009-&gt;</b>
8FR (EP3)	72 98
Ignition Coil	<b>80247</b>
<b>308 SW 1.6 16V</b>	<b>2007-&gt;</b>
EP6/5FW (EP6)	88 120
Ignition Coil EP6	<b>80247</b>
<b>308 SW 1.6 16V</b>	<b>2007-&gt;</b>
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>



PEUGEOT Cont.	
<b>308 SW 1.6 16V</b>	<b>2008-&gt;</b>
5FY (EP6DTS)	128 174
Ignition Coil	<b>80247</b>
<b>308 SW 1.6 16V</b>	<b>2007-&gt;</b>
5FT (EP6DT)	103 140
Ignition Coil	<b>80247</b>
<b>308 SW 1.6 16V</b>	<b>2009-&gt;</b>
EP6CDT	115 156
Ignition Coil	<b>80247</b>
<b>308 SW 1.6 Bioflex</b>	<b>2009-&gt;</b>
NFU (TU5JP4)	82 112
Ignition Coil	<b>80235</b>
<b>308 SW II 1.6 GT 205</b>	<b>2014-&gt;</b>
	151 205
Ignition Coil	<b>80247</b>
<b>308 SW II 1.6 THP 125</b>	<b>2014-&gt;</b>
	92 125
Ignition Coil	<b>80247</b>
<b>309 I (10C, 10A) 1.1</b>	<b>1985-89</b>
E1	40 54
Ignition Leads	<b>83370</b>
<b>309 I (10C, 10A) 1.3</b>	<b>1985-89</b>
G1A	47 64
Ignition Leads	<b>83330</b>
<b>309 I (10C, 10A) 1.4</b>	<b>1989-89</b>
K1D (TU3A)	49 67
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>
<b>309 I (10C, 10A) 1.4</b>	<b>1989-89</b>
KDZ (TU3M)/KDY (TU3M)	55 75
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>
<b>309 I (10C, 10A) 1.4</b>	<b>1989-89</b>
K2B (TU3S)	62 84
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>
<b>309 I (10C, 10A) 1.5</b>	<b>1987-89</b>
Y2/K	63 86
Ignition Leads	<b>83370</b>
<b>309 I (10C, 10A) 1.6</b>	<b>1986-89</b>
	83 113
Ignition Leads	<b>83380</b>
<b>309 I (10C, 10A) 1.6</b>	<b>1987-89</b>
B1E (XU51C)	53 72
Ignition Leads	<b>83370</b>
<b>309 I (10C, 10A) 1.6</b>	<b>1985-89</b>
B1A (XU51C)	55 75
Ignition Leads	<b>83380</b>
<b>309 I (10C, 10A) 1.6</b>	<b>1985-88</b>
180Z (XU5J)/B6B (XU5J)	76 103
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83380</b>
<b>309 I (10C, 10A) 1.6</b>	<b>1986-89</b>
	69 94
Ignition Leads	<b>83320</b>
<b>309 I (10C, 10A) 1.9</b>	<b>1986-89</b>
DFZ (XU9J1)	72 98
Ignition Leads	<b>83380</b>
<b>309 I (10C, 10A) 1.9</b>	<b>1985-89</b>
D2B (XU9S)	75 102
Ignition Leads	<b>83380</b>
<b>309 I (10C, 10A) 1.9</b>	<b>1988-89</b>
DDZ (XU9M)	80 109
Ignition Leads	<b>83320</b>
<b>309 II (3C, 3A) 1.1</b>	<b>1990-93</b>
HDZ (TU1M)	44 60
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>
<b>309 II (3C, 3A) 1.4</b>	<b>1989-93</b>
KDZ (TU3M)/KDY (TU3M)	55 75
Ignition Coil	<b>80263</b>
Ignition Leads KDY (TU3M)	<b>83650</b>
Ignition Leads	<b>85600</b>
<b>309 II (3C, 3A) 1.4</b>	<b>1990-93</b>
K1D (TU3A)	49 67
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83650</b>

PEUGEOT Cont.	
<b>309 II (3C, 3A) 1.6</b>	<b>1989-93</b>
B2A (XU52C/K)	68 92
Ignition Leads	<b>83320</b>
<b>309 II (3C, 3A) 1.6</b>	<b>1989-93</b>
BDY (XU5M2Z)/BDZ (XU5M)/BDY (XU5M3Z)	65 88
Ignition Coil	<b>80207</b>
Ignition Leads	<b>83320</b>
<b>309 II (3C, 3A) 1.6</b>	<b>1989-93</b>
B2A (XU52C/K)	69 94
Ignition Leads	<b>83320</b>
<b>309 II (3C, 3A) 1.9</b>	<b>1989-93</b>
DFZ (XU9J1)	72 98
Ignition Coil	<b>80263</b>
Ignition Leads	<b>83380</b>
<b>309 II (3C, 3A) 1.9</b>	<b>1990-93</b>
DDZ (XU9M)	80 109
Ignition Leads	<b>83320</b>
Ignition Leads	<b>83380</b>
<b>309 II (3C, 3A) 1.9 GTI</b>	<b>1989-93</b>
DKZ (XU9JAZ)	88 120
Ignition Coil	<b>80263</b>
Ignition Leads 12.1989->	<b>83320</b>
<b>4007 (GP) 2.0</b>	<b>2010-&gt;</b>
4B11	108 147
Ignition Coil	<b>80338</b>
<b>4007 (GP) 2.0 4x4</b>	<b>2010-&gt;</b>
4B11	108 147
Ignition Coil	<b>80338</b>
<b>4007 (GP) 2.4 16V</b>	<b>2008-&gt;</b>
SFY (4B12-MMC)/SFZ (4B12-MMC)	125 170
Ignition Coil	<b>80338</b>
<b>404 1.6</b>	<b>1963-71</b>
XC6	48 65
Ignition Leads	<b>83340</b>
<b>404 1.6</b>	<b>1967-71</b>
XC6	54 73
Ignition Leads	<b>83340</b>
<b>404 1.6 GT</b>	<b>1971-71</b>
XC6	50 68
Ignition Leads	<b>83340</b>
<b>404 Cabrio 1.6</b>	<b>1963-68</b>
XC6	59 80
Ignition Leads	<b>83340</b>
<b>405 I (15B) 1.4</b>	<b>1987-92</b>
K5A (TU3)	47 64
Ignition Coil	<b>80263</b>
<b>405 I (15B) 1.6</b>	<b>1987-92</b>
B1E (XU51C)	53 72
Ignition Leads SAE	<b>83320</b>
Ignition Leads	<b>83380</b>
<b>405 I (15B) 1.6</b>	<b>1989-92</b>
BDZ (XU5M)	66 90
Ignition Leads	<b>83320</b>
<b>405 I (15B) 1.6</b>	<b>1987-88</b>
B1E (XU51C)/BAZ (XU5CP)	55 75
Ignition Leads	<b>83380</b>
<b>405 I (15B) 1.6</b>	<b>1987-92</b>
BDY (XU5M2Z)/BDZ (XU5M)	65 88
Ignition Coil	<b>80207</b>
<b>405 I (15B) 1.6</b>	<b>1987-92</b>
B2A (XU52C/K)	69 94
Ignition Leads	<b>83320</b>
<b>405 I (15B) 1.9</b>	<b>1987-92</b>
D2C (XU92C)	70 95
Ignition Leads SAE	<b>83320</b>
Ignition Leads	<b>83380</b>
<b>405 I (15B) 1.9</b>	<b>1988-92</b>
DDZ (XU9M)	80 109
Ignition Leads	<b>83320</b>
<b>405 I (15B) 1.9</b>	<b>1988-92</b>
DKZ (XU9JAZ)	88 120
Ignition Coil	<b>80263</b>
<b>405 I (15B) 1.9</b>	<b>1989-92</b>
D6A (XU9J2)	90 122
Ignition Leads	<b>83330</b>
<b>405 I (15B) 1.9</b>	<b>1987-93</b>
D6A (XU9J2)	93 126
Ignition Coil	<b>80207</b>



PEUGEOT Cont.	
<b>405 I (15B) 1.9 4x4</b>	<b>1988-92</b>
DDZ (XU9M)	80 109
Ignition Leads	<b>83320</b>
<b>405 I (15B) 1.9 Injection</b>	<b>1987-92</b>
DFZ (XU9J1)	77 105
Ignition Leads	<b>83380</b>
<b>405 I Break (15E) 1.4</b>	<b>1988-92</b>
K5A (TU3)	47 64
Ignition Coil	<b>80263</b>
<b>405 I Break (15E) 1.6</b>	<b>1988-92</b>
B1E (XU51C)	53 72
Ignition Leads SAE	<b>83320</b>
Ignition Leads	<b>83380</b>
<b>405 I Break (15E) 1.6</b>	<b>1988-92</b>
BDZ (XU5M)	66 90
Ignition Leads	<b>83320</b>
<b>405 I Break (15E) 1.6</b>	<b>1988-92</b>
BDY (XU5M2Z)/BDZ (XU5M)/BDY (XU5M3Z)	65 88
Ignition Coil	<b>80207</b>
<b>405 I Break (15E) 1.6</b>	<b>1988-92</b>
BAZ (XU5CP)	55 75
Ignition Leads	<b>83380</b>
<b>405 I Break (15E) 1.9</b>	<b>1988-92</b>
D2C (XU92C)	70 95
Ignition Leads SAE	<b>83320</b>
Ignition Leads	<b>83380</b>
<b>405 I Break (15E) 1.9</b>	<b>1988-92</b>
DKZ (XU9JAZ)	88 120
Ignition Coil	<b>80263</b>
<b>405 I Break (15E) 1.9</b>	<b>1988-92</b>
DFZ (XU9J1)	77 105
Ignition Leads	<b>83380</b>
<b>405 I Break (15E) 1.9</b>	<b>1988-92</b>
DDZ (XU9M)	80 109
Ignition Leads	<b>83320</b>
<b>405 I Break (15E) 1.9 4x4</b>	<b>1988-92</b>
DDZ (XU9M)	80 109
Ignition Leads SAE	<b>83320</b>
<b>405 II (4B) 1.4</b>	<b>1992-95</b>
KDX (TU3MC)	55 75
Ignition Coil	<b>80272</b>
<b>405 II (4B) 1.6</b>	<b>1992-95</b>
BFZ (XU5JP)/BDY (XU5M2Z)/BDZ (XU5M)/BDY (XU5M3Z)	65 88
Ignition Coil	<b>80207</b>
<b>405 II (4B) 1.8</b>	<b>1992-95</b>
LFZ (XU7JP)	74 101
Ignition Coil LFZ (XU7JP)	<b>80207</b>
<b>405 II (4B) 2.0</b>	<b>1992-95</b>
RFX (XU10J2)	89 121
Ignition Coil RFX (XU10J2)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>405 II (4B) 2.0 MI-16</b>	<b>1992-95</b>
RFY (XU10J4Z)	112 152
Ignition Coil	<b>80207</b>
Ignition Leads RFY (XU10J4Z)	<b>83330</b>
<b>405 II (4B) 2.0 T 16 X4</b>	<b>1992-95</b>
RGZ (XU10J4TE/Z)	144 196
Ignition Coil	<b>80207</b>
<b>405 II (4B) 2.0 X4</b>	<b>1992-95</b>
RFX (XU10J2)	89 121
Ignition Coil RFX (XU10J2)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>405 II Break (4E) 1.4</b>	<b>1992-96</b>
KDX (TU3MC)	55 75
Ignition Coil	<b>80272</b>
<b>405 II Break (4E) 1.6</b>	<b>1992-96</b>
BFZ (XU5JP)/BDY (XU5M2Z)/BDZ (XU5M)/BDY (XU5M3Z)	65 88
Ignition Coil	<b>80207</b>
<b>405 II Break (4E) 1.8</b>	<b>1992-96</b>
LFZ (XU7JP)	74 101
Ignition Coil LFZ (XU7JP)	<b>80207</b>
<b>405 II Break (4E) 2.0</b>	<b>1992-96</b>
RFX (XU10J2)	89 121
Ignition Coil RFX (XU10J2)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>405 II Break (4E) 2.0 4x4</b>	<b>1992-96</b>
RFX (XU10J2)	89 121
Ignition Coil RFX (XU10J2)	<b>80207</b>
Ignition Leads	<b>83330</b>

PEUGEOT Cont.	
<b>405 II Break (4E) 2.0 4x4</b>	<b>1992-95</b>
RGZ (XU10J4TE/Z)	144 196
Ignition Coil	<b>80207</b>
<b>406 (8B) 1.6</b>	<b>1995-04</b>
BFZ (XU5JP)	65 88
Ignition Coil BFZ (XU5JP)	<b>80207</b>
<b>406 (8B) 1.8</b>	<b>1997-04</b>
LFX (XU7JB)	66 90
Ignition Coil	<b>80207</b>
<b>406 (8B) 1.8 16V</b>	<b>2000-04</b>
6FZ (EW7J4)	85 116
Ignition Coil	<b>80275</b>
<b>406 (8B) 1.8 16V</b>	<b>1995-00</b>
LFY (XU7JP4)	81 110
Ignition Coil 03.1997-12.1997; With regul.cat.(3way)	<b>80237</b>
Ignition Coil SAE; Vet. 07609->	<b>80274</b>
<b>406 (8B) 2.0 16V</b>	<b>1999-00</b>
RFR (DEW10J4)	99 135
Ignition Coil	<b>80275</b>
<b>406 (8B) 2.0 16V</b>	<b>2000-04</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>406 (8B) 2.0 16V</b>	<b>1995-04</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80207</b>
Ignition Coil SAE	<b>80237</b>
Ignition Coil SAE; 09.1997->	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>406 (8B) 2.0 Turbo</b>	<b>1996-04</b>
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>406 (8B) 2.2</b>	<b>2000-04</b>
3FZ (EW12J4)	116 158
Ignition Coil	<b>80277</b>
<b>406 (8B) 3.0 24V</b>	<b>1996-04</b>
XFZ (ES9J4)	140 190
Ignition Coil	<b>80374</b>
<b>406 (8B) 3.0 V6</b>	<b>2000-04</b>
AFX (ES9J4S)	152 207
Ignition Coil	<b>80309</b>
<b>406 Break (8E/F) 1.8</b>	<b>1997-04</b>
LFX (XU7JB)	66 90
Ignition Coil LFX (XU7JB)	<b>80207</b>
<b>406 Break (8E/F) 1.8 16V</b>	<b>2000-04</b>
6FZ (EW7J4)	85 116
Ignition Coil	<b>80275</b>
<b>406 Break (8E/F) 1.8 16V</b>	<b>1996-00</b>
LFY (XU7JP4)	81 110
Ignition Coil 03.1997-12.1997; With regul.cat.(3way)	<b>80237</b>
Ignition Coil SAE; Vet. 07609->	<b>80274</b>
<b>406 Break (8E/F) 2.0 16V</b>	<b>1999-00</b>
RFR (DEW10J4)	99 135
Ignition Coil	<b>80275</b>
<b>406 Break (8E/F) 2.0 16V</b>	<b>2000-04</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>406 Break (8E/F) 2.0 16V</b>	<b>1996-04</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80207</b>
Ignition Coil ->09.1997	<b>80237</b>
Ignition Coil SAE; 09.1997->	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>406 Break (8E/F) 2.0 Turbo</b>	<b>1996-04</b>
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>406 Break (8E/F) 2.2</b>	<b>2000-04</b>
3FZ (EW12J4)	116 158
Ignition Coil	<b>80277</b>
<b>406 Break (8E/F) 3.0 24V</b>	<b>1996-04</b>
XFZ (ES9J4)	140 190
Ignition Coil	<b>80374</b>
<b>406 Break (8E/F) 3.0 V6</b>	<b>2000-04</b>
AFX (ES9J4S)	152 207
Ignition Coil	<b>80309</b>
<b>406 Coupe (8C) 2.0 16V</b>	<b>1999-00</b>
RFR (DEW10J4)	99 135
Ignition Coil	<b>80275</b>





PEUGEOT Cont.	
<b>406 Coupe (8C) 2.0 16V</b>	2000-04
RFV (XU10J4R)/RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>406 Coupe (8C) 2.0 16V</b>	1997-04
RFV (XU10J4R)	97 132
Ignition Coil	<b>80207</b>
Ignition Coil ->09.1997	<b>80237</b>
Ignition Coil SAE; 09.1997->	<b>80274</b>
Ignition Leads	<b>83330</b>
<b>406 Coupe (8C) 2.2</b>	2002-04
3FZ (EW12J4)	116 158
Ignition Coil	<b>80277</b>
<b>406 Coupe (8C) 3.0 V6</b>	2000-04
XFX (ES9J4S)	152 207
Ignition Coil	<b>80309</b>
<b>406 Coupe (8C) 3.0 V6 24V</b>	1997-04
XFZ (ES9J4)	140 190
Ignition Coil	<b>80374</b>
<b>407 (6D) 1.8</b>	2004->
6FZ (EW7J4)	85 116
Ignition Coil	<b>80275</b>
Ignition Coil	<b>80277</b>
<b>407 (6D) 1.8 16V</b>	2005->
6FY (EW7A)	92 125
Ignition Coil	<b>80277</b>
Ignition Coil	<b>80278</b>
<b>407 (6D) 2.0</b>	2004->
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>407 (6D) 2.0 16V</b>	2005->
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>407 (6D) 2.2</b>	2004->
3FZ (EW12J4)	116 158
Ignition Coil	<b>80277</b>
<b>407 (6D) 2.2 16V</b>	2005->
3FY (EW12J4)	120 163
Ignition Coil	<b>80277</b>
<b>407 (6D) 3.0</b>	2004->
XFV (ES9A)	155 211
Ignition Coil	<b>80309</b>
<b>407 Coupe (6C) 2.2 16V</b>	2005->
3FY (EW12J4)	120 163
Ignition Coil	<b>80277</b>
<b>407 Coupe (6C) 3.0 V6</b>	2005->
XFV (ES9A)	155 211
Ignition Coil	<b>80309</b>
<b>407 SW (6E) 1.8</b>	2004->
6FZ (EW7J4)	85 116
Ignition Coil	<b>80275</b>
Ignition Coil	<b>80277</b>
<b>407 SW (6E) 1.8 16V</b>	2005->
6FY (EW7A)	92 125
Ignition Coil	<b>80277</b>
Ignition Coil	<b>80278</b>
<b>407 SW (6E) 2.0</b>	2004->
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>407 SW (6E) 2.0 16V</b>	2005->
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>407 SW (6E) 2.2</b>	2004->
3FZ (EW12J4)	116 158
Ignition Coil	<b>80277</b>
<b>407 SW (6E) 2.2 16V</b>	2005->
3FY (EW12J4)	120 163
Ignition Coil	<b>80277</b>
<b>407 SW (6E) 3.0</b>	2004->
XFV (ES9A)	155 211
Ignition Coil	<b>80309</b>
<b>5008 1.6 16V</b>	2009->
5FS (EP6C)/EP6/5FW (EP6)	88 120
Ignition Coil	<b>80247</b>
<b>5008 1.6 16V</b>	2009->
5FV (EP6CDT)	115 156
Ignition Coil	<b>80247</b>
<b>5008 1.6 THP 150</b>	2012->
5FX (EP6DT)	110 150
Ignition Coil	<b>80247</b>

PEUGEOT Cont.	
<b>5008 1.6 THP 163</b>	2012->
5GZ (EP6FDT)	120 163
Ignition Coil	<b>80247</b>
<b>5008 1.6 THP 165</b>	2012->
5GZ (EP6FDT)	121 165
Ignition Coil	<b>80247</b>
<b>504 (A, M) 1,8</b>	1971-83
XM7	58 79
Ignition Leads	<b>83340</b>
<b>504 (A, M) 1,8</b>	1968-71
XM	60 82
Ignition Leads	<b>83340</b>
<b>504 (A, M) 1.8 Injection</b>	1968-71
KF6/KF5	71 97
Ignition Leads	<b>83340</b>
<b>504 (A, M) 2.0</b>	1971-86
106 (XN1)	71 97
Ignition Leads	<b>83340</b>
<b>504 (A, M) 2.0 TI</b>	1971-83
107 (XN2)	78 106
Ignition Leads	<b>83340</b>
<b>504 Break (D, F) 1,8</b>	1971-86
XM7	54 73
Ignition Leads	<b>83340</b>
<b>504 Break (D, F) 2.0</b>	1971-86
XN1	68 92
Ignition Leads	<b>83340</b>
<b>504 Cabrio 2.0</b>	1974-82
107 (XN2)	75 102
Ignition Leads	<b>83340</b>
<b>504 Cabrio 2.0</b>	1982-84
107 (XN2)	78 106
Ignition Leads	<b>83340</b>
<b>504 Coupe 2.0</b>	1974-82
107 (XN2)	75 102
Ignition Leads	<b>83340</b>
<b>504 Coupe 2.0</b>	1982-84
107 (XN2)	78 106
Ignition Leads	<b>83340</b>
<b>504 Coupe 2.7</b>	1977-84
140 (ZMJ)	106 144
Ignition Leads	<b>83340</b>
<b>505 (551A) 2.0</b>	1980-82
XN1	79 107
Ignition Leads	<b>83810</b>
<b>505 (551A) 2.0</b>	1980-85
106 (XN1)	71 97
Ignition Leads	<b>83810</b>
<b>505 (551A) 2.0</b>	1985-95
106E (XN1A)	72 98
Ignition Leads	<b>83810</b>
<b>505 (551A) 2.0 TI,STI</b>	1979-86
829 (ZEJ)	81 110
Ignition Leads	<b>83810</b>
<b>505 (551A) 2.2</b>	1986-93
851X (ZDJL)	84 114
Ignition Leads	<b>83810</b>
<b>505 (551A) 2.2</b>	1981-84
851 (ZDJ)	85 116
Ignition Leads	<b>83810</b>
<b>505 (551A) 2.2 GTI</b>	1983-93
851B (ZDJL)	90 122
Ignition Leads	<b>83810</b>
<b>505 (551A) 2.2 GTI</b>	1983-93
	96 130
Ignition Leads	<b>83810</b>
<b>505 Break (551D) 2.0</b>	1983-85
106 (XN1)	69 94
Ignition Leads	<b>83810</b>
<b>505 Break (551D) 2.0</b>	1985-87
106E (XN1A)	72 98
Ignition Leads	<b>83810</b>
<b>505 Break (551D) 2.0</b>	1982-87
	60 82
Ignition Leads	<b>83810</b>
<b>505 Break (551D) 2.2</b>	1986-93
851X (ZDJL)	84 114
Ignition Leads	<b>83810</b>



PEUGEOT Cont.	
<b>505 Break (551D) 2.2 GTI</b>	<b>1985-86</b>
851B (ZDJL)	90 122
Ignition Leads	<b>83810</b>
<b>508 1.6</b>	<b>2012-&gt;</b>
5GZ (EP6FDT)	120 163
Ignition Coil	<b>80247</b>
<b>508 1.6</b>	<b>2011-&gt;</b>
	121 165
Ignition Coil	<b>80247</b>
<b>508 1.6 THP</b>	<b>2010-&gt;</b>
5FN (EP6CDT)	110 150
Ignition Coil	<b>80247</b>
<b>508 1.6 THP</b>	<b>2010-&gt;</b>
EP6CDT	115 156
Ignition Coil	<b>80247</b>
<b>508 1.6 Vti</b>	<b>2010-&gt;</b>
5FH (EP6C)	85 116
Ignition Coil	<b>80247</b>
<b>508 1.6 VTI</b>	<b>2010-&gt;</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>508 SW 1.6</b>	<b>2012-&gt;</b>
	121 165
Ignition Coil	<b>80247</b>
<b>508 SW 1.6 THP</b>	<b>2010-&gt;</b>
EP6CDT	115 156
Ignition Coil	<b>80247</b>
<b>508 SW 1.6 Vti</b>	<b>2010-&gt;</b>
5FH (EP6C)	85 116
Ignition Coil	<b>80247</b>
<b>508 SW 1.6 VTI</b>	<b>2010-&gt;</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>605 (6B) 2.0</b>	<b>1989-99</b>
RFZ (XU10J2Z)	89 121
Ignition Coil RFZ (XU10J2Z)	<b>80207</b>
Ignition Coil	<b>80260</b>
Ignition Leads	<b>83330</b>
<b>605 (6B) 2.0 16V</b>	<b>1994-99</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80237</b>
Ignition Coil SAE; 09.1997->	<b>80274</b>
<b>605 (6B) 2.0 Turbo</b>	<b>1992-99</b>
RGY (XU10J2TE)	104 141
Ignition Coil RGY (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>605 (6B) 2.0 Turbo</b>	<b>1991-99</b>
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>605 (6B) 3.0 V6</b>	<b>1997-99</b>
XFZ (ES9J4)	140 190
Ignition Coil	<b>80374</b>
<b>607 (9D, 9U) 2.0</b>	<b>2000-&gt;</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>607 (9D, 9U) 2.2 16V</b>	<b>2000-&gt;</b>
3FZ (EW12J4)	116 158
Ignition Coil	<b>80277</b>
<b>607 (9D, 9U) 2.2 16V</b>	<b>2005-&gt;</b>
3FY (EW12J4)	120 163
Ignition Coil	<b>80277</b>
<b>607 (9D, 9U) 3.0 V6 24V</b>	<b>2000-&gt;</b>
XFJ (ES9J4S)	152 207
Ignition Coil	<b>80309</b>
<b>607 (9D, 9U) 3.0 V6 24V</b>	<b>2004-&gt;</b>
XFV (ES9A)/XFJ (ES9J4S)	155 211
Ignition Coil	<b>80309</b>
<b>806 (221) 1.8</b>	<b>1995-02</b>
LFW (XU7JP)	73 99
Ignition Coil LFW (XU7JP)	<b>80207</b>
<b>806 (221) 2.0</b>	<b>1994-02</b>
RFU (XU10J2)	89 121
Ignition Coil RFU (XU10J2)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>806 (221) 2.0 16V</b>	<b>1998-00</b>
RFV (XU10J4R)	97 132
Ignition Coil	<b>80274</b>
Ignition Leads	<b>83330</b>

PEUGEOT Cont.	
<b>806 (221) 2.0 16V</b>	<b>2000-02</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
Ignition Leads	<b>83330</b>
<b>806 (221) 2.0 Turbo</b>	<b>1994-02</b>
RGX (XU10J2TE)	108 147
Ignition Coil RGX (XU10J2TE)	<b>80207</b>
Ignition Leads	<b>83330</b>
<b>807 (E) 2.0</b>	<b>2002-&gt;</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>807 (E) 2.0 16V</b>	<b>2005-&gt;</b>
RFJ (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>807 (E) 2.2</b>	<b>2002-&gt;</b>
3FZ (EW12J4)	116 158
Ignition Coil	<b>80277</b>
<b>807 (E) 3.0 V6</b>	<b>2002-&gt;</b>
XFJ (ES9J4S)	150 204
Ignition Coil	<b>80309</b>
<b>Boxer Bus (230P) 2.0 i</b>	<b>1994-02</b>
RFW (XU10J2)	80 109
Ignition Coil RFW (XU10J2)	<b>80207</b>
<b>Boxer Bus (230P) 2.0 i 4x4</b>	<b>1996-02</b>
RFW (XU10J2)	80 109
Ignition Coil RFW (XU10J2)	<b>80207</b>
<b>Boxer Bus (244, Z) 2.0</b>	<b>2002-&gt;</b>
RFL (XU10J2U)	81 110
Ignition Coil RFL (XU10J2U)	<b>80207</b>
<b>Boxer Chassis (ZCT) 2.0 i</b>	<b>1994-02</b>
RFW (XU10J2)	80 109
Ignition Coil RFW (XU10J2)	<b>80207</b>
<b>Boxer Van (230L) 2.0 i</b>	<b>1994-02</b>
RFW (XU10J2)	80 109
Ignition Coil RFW (XU10J2)	<b>80207</b>
<b>Boxer Van (244) 2.0</b>	<b>2002-&gt;</b>
RFL (XU10J2U)	81 110
Ignition Coil	<b>80207</b>
<b>Expert (224) 1.6</b>	<b>1996-&gt;</b>
222A2 (1580 SPI)	58 79
Ignition Coil	<b>80279</b>
<b>Expert (224) 1.8</b>	<b>1996-00</b>
LFZ (XU7JP)	74 101
Ignition Coil	<b>80207</b>
<b>Expert (224) 2.0</b>	<b>2000-06</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>Expert Chassis (223) 1.6</b>	<b>1996-&gt;</b>
222A2 (1580 SPI)	58 79
Ignition Coil	<b>80279</b>
<b>Expert Tepee (VF3V) 2.0 16V</b>	<b>2007-&gt;</b>
RFJ (EW10A)/RFH (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>Expert Van (222) 1.6</b>	<b>1996-&gt;</b>
222A2 (1580 SPI)	58 79
Ignition Coil	<b>80279</b>
<b>Expert Van (222) 1.8</b>	<b>1996-00</b>
LFZ (XU7JP)	74 101
Ignition Coil	<b>80207</b>
<b>Expert Van (222) 2.0</b>	<b>2002-06</b>
RFN (EW10J4)	100 136
Ignition Coil	<b>80275</b>
<b>Expert Van (VF3A, VF3U, VF3X) 2.0 16V</b>	<b>2007-&gt;</b>
RFJ (EW10A)/RFH (EW10A)	103 140
Ignition Coil	<b>80278</b>
<b>J7 Bus 1.6</b>	<b>1968-70</b>
XC5P	50 68
Ignition Leads	<b>83340</b>
<b>J7 Bus 1.6</b>	<b>1970-80</b>
XC7P	44 60
Ignition Leads	<b>83340</b>
<b>J7 Bus 1.8</b>	<b>1970-80</b>
XM7P	48 65
Ignition Leads	<b>83340</b>
<b>J7 Chassis 1.6</b>	<b>1968-70</b>
XC5P	50 68
Ignition Leads	<b>83340</b>



<b>PEUGEOT Cont.</b>	
<b>J7 Chassis 1.6</b>	<b>1970-80</b>
XC7P	44 60
Ignition Leads	<b>83340</b>
<b>J7 Chassis 1.8</b>	<b>1970-80</b>
XM7P	48 65
Ignition Leads	<b>83340</b>
<b>J7 Van 1.5</b>	<b>1968-70</b>
XB5P	61 83
Ignition Leads	<b>83340</b>
<b>J7 Van 1.6</b>	<b>1968-80</b>
XC7P	44 60
Ignition Leads	<b>83340</b>
<b>J7 Van 1.6</b>	<b>1968-80</b>
XC5P	50 68
Ignition Leads	<b>83340</b>
<b>J7 Van 1.8</b>	<b>1970-80</b>
XM7P	48 65
Ignition Leads	<b>83340</b>
<b>J9 Bus 2.0</b>	<b>1980-87</b>
XN1P	57 78
Ignition Leads	<b>83340</b>
<b>J9 Chassis 2.0</b>	<b>1980-87</b>
XN1P	57 78
Ignition Leads	<b>83340</b>
<b>J9 Van 1.6</b>	<b>1980-87</b>
XC7P	44 60
Ignition Leads	<b>83340</b>
<b>J9 Van 2.0</b>	<b>1980-87</b>
XN1P	57 78
Ignition Leads	<b>83340</b>
<b>Partner Combispace (5F) 1.1</b>	<b>1996-02</b>
HDZ (TU1M)/HFX (TU1JP)	44 60
Ignition Coil HDZ (TU1M); ->05.1997	<b>80207</b>
Ignition Coil 06.2000->	<b>80208</b>
Ignition Coil 06.1997-05.2000	<b>80226</b>
<b>Partner Combispace (5F) 1.4</b>	<b>1996-15</b>
KFX (TU3JP)/TU32/KFW (TU3JP)	55 75
Ignition Coil KFX (TU3JP); 07.1996-06.1998	<b>80207</b>
Ignition Coil KFW (TU3JP); KFX (TU3JP); With regul.cat.(3way)	<b>80208</b>
Ignition Coil KFW (TU3JP); KFX (TU3JP); Hydraulic Brake	<b>80226</b>
Ignition Coil TU32; 11.1996-08.2002	<b>80260</b>
<b>Partner Combispace (5F) 1.6 16V</b>	<b>2001-08</b>
NFU (TU5JP4)	80 109
Ignition Coil NFU (TU5JP4)	<b>80235</b>
<b>Partner Combispace (5F) 1.8</b>	<b>1997-03</b>
LFX (XU7JB)	66 90
Ignition Coil LFX (XU7JB)	<b>80207</b>
<b>Partner Tepee 1.6</b>	<b>2008-&gt;</b>
NFR (TU5JP4B)	66 90
Ignition Coil	<b>80235</b>
<b>Partner Tepee 1.6</b>	<b>2008-&gt;</b>
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>Partner Tepee 1.6</b>	<b>2010-&gt;</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>Partner Tepee 1.6</b>	<b>2010-&gt;</b>
5FK (EP6CB)	72 98
Ignition Coil	<b>80247</b>
<b>Partner Van (5) 1.1</b>	<b>1996-05</b>
HDZ (TU1M)	44 60
Ignition Coil ->05.1997	<b>80207</b>
Ignition Coil 06.2000-06.2005	<b>80208</b>
Ignition Coil 06.1997-05.2000	<b>80226</b>
<b>Partner Van (5) 1.4</b>	<b>1996-15</b>
KFX (TU3JP)/TU32	55 75
Ignition Coil KFX (TU3JP); 07.1996-06.1998	<b>80207</b>
Ignition Coil KFX (TU3JP); With regul.cat.(3way)	<b>80208</b>
Ignition Coil KFX (TU3JP); Hydraulic Brake	<b>80226</b>
Ignition Coil TU32; 11.1996-08.2002	<b>80260</b>
<b>Partner Van (5) 1.4 BiFuel</b>	<b>2003-06</b>
KFW (TU3JP)	55 75
Ignition Coil	<b>80208</b>
<b>Partner Van 1.6</b>	<b>2010-&gt;</b>
5FS (EP6C)	88 120
Ignition Coil	<b>80247</b>
<b>Partner Van 1.6</b>	<b>2008-&gt;</b>
NFR (TU5JP4B)	66 90
Ignition Coil	<b>80235</b>

<b>PEUGEOT Cont.</b>	
<b>Partner Van 1.6</b>	<b>2008-&gt;</b>
NFU (TU5JP4)	80 109
Ignition Coil	<b>80235</b>
<b>Partner Van 1.6</b>	<b>2010-&gt;</b>
5FK (EP6CB)	72 98
Ignition Coil	<b>80247</b>
<b>Rcz 1.6 16V</b>	<b>2010-&gt;</b>
EP6CDT	115 156
Ignition Coil	<b>80247</b>
<b>Rcz 1.6 16V</b>	<b>2010-&gt;</b>
EP6CDTX	147 200
Ignition Coil	<b>80247</b>
<b>RCZ 1.6 THP 270</b>	<b>2013-&gt;</b>
5FG (EP6CDTR)	199 270
Ignition Coil	<b>80247</b>
<b>PLYMOUTH</b>	
<b>Breeze 2.0 16V</b>	<b>1995-01</b>
ECB	98 133
Ignition Coil	<b>80295</b>
Ignition Coil 01.1997->	<b>80296</b>
<b>Breeze 2.4 16V</b>	<b>1995-01</b>
EDZ	103 140
Ignition Coil	<b>80295</b>
Ignition Coil 01.1997->	<b>80296</b>
<b>Breeze 2.4 16V</b>	<b>1995-01</b>
EDZ	112 152
Ignition Coil	<b>80295</b>
Ignition Coil 01.1997->	<b>80296</b>
<b>Neon II Sedan 2.0 16V</b>	<b>1999-&gt;</b>
ECB	98 133
Ignition Coil	<b>80295</b>
Ignition Coil	<b>80296</b>
<b>Neon II Sedan 2.0 16V</b>	<b>1999-&gt;</b>
ECH	112 152
Ignition Coil	<b>80295</b>
Ignition Coil	<b>80296</b>
<b>Neon Sedan 2.0 16V</b>	<b>1994-99</b>
ECB	98 133
Ignition Coil	<b>80295</b>
<b>Neon Sedan 2.0 16V</b>	<b>1994-99</b>
ECC	107 145
Ignition Coil	<b>80295</b>
<b>Neon Sedan 2.0 16V</b>	<b>1996-99</b>
ECC	112 152
Ignition Coil	<b>80295</b>
<b>Voyager / Gran Voyager 2.4 i</b>	<b>1995-01</b>
EDZ	111 151
Ignition Coil	<b>80295</b>
Ignition Coil 01.1997->	<b>80296</b>
<b>Voyager/Grand Voyager 2.0 I</b>	<b>1995-01</b>
Ignition Coil	98 133
Ignition Coil 01.1997->	<b>80296</b>
<b>PORSCHE</b>	
<b>911 (964) 3.6 Carrera</b>	<b>1989-93</b>
M 64.01/M 64.02	184 250
Ignition Coil	<b>80332</b>
<b>Cayenne (955) 3.2</b>	<b>2003-07</b>
M02.2Y	184 250
Ignition Coil	<b>80327</b>
<b>Cayenne (955) 3.6</b>	<b>2007-10</b>
M 55.01	213 290
Ignition Coil ->04.2010	<b>80327</b>
<b>Cayenne 3.0 S E-Hybrid</b>	<b>2010-&gt;</b>
MCG.FA/M 06.EC/MCG.EA/MCG.E	245 333
Ignition Coil	<b>80248</b>
<b>Cayenne 3.6</b>	<b>2010-&gt;</b>
MCE.YA/M 55.02	220 300
Ignition Coil	<b>80327</b>
<b>Panamera 3.0 S E-Hybrid</b>	<b>2011-&gt;</b>
MCG.FA/MCG.EA	245 333
Ignition Coil	<b>80248</b>



PROTON		
<b>Gen 2 (Cm) 1.3</b>	2004->	
S4PE	70	95
Ignition Coil		<b>80279</b>
<b>Gen 2 (Cm) 1.6</b>	2004->	
S4PH	82	110
Ignition Coil		<b>80279</b>
<b>Impian 1.6</b>	2001->	
4 G 18 P	76	102
Ignition Coil		<b>80346</b>
Ignition Leads		<b>85382</b>
<b>Jumbuck Pick-up 1.5</b>	2002->	
4 G 15	64	86
Ignition Coil ->01.2007		<b>80279</b>
<b>Satria (C9M) 1.3</b>	1996-06	
4 G 13	55	74
Ignition Coil		<b>80279</b>
<b>Satria Neo 1.3</b>	2007-08	
S4PE	70	95
Ignition Coil		<b>80279</b>
<b>Satria Neo 1.6</b>	2007->	
S4PH	81	110
Ignition Coil		<b>80279</b>
<b>Wira 1.3</b>	2000->	
4 G 13	55	74
Ignition Coil		<b>80279</b>
<b>Wira 1.5</b>	2000->	
4 G 15	64	86
Ignition Coil		<b>80279</b>
<b>Wira Hatchback 1.3</b>	2000->	
4 G 13	55	74
Ignition Coil		<b>80279</b>
<b>Wira Hatchback 1.5</b>	2000->	
4 G 15 M	64	86
Ignition Coil		<b>80279</b>

PUCH		
<b>G-Modell (W 463) G 320</b>	1994-97	
M 104.996	155	211
Ignition Coil With regul.cat.(3way)		<b>80211</b>
<b>G-Modell (W 463) G 36 AMG</b>	1995-98	
M 104.952 (AMG 3,6)	200	272
Ignition Coil With regul.cat.(3way)		<b>80211</b>
<b>G-Modell (W 463) G 500</b>	1998->	
M 113.962	218	296
Ignition Coil		<b>80294</b>
<b>G-Modell (W 463) G 55 AMG</b>	1999->	
M 113.982	260	354
Ignition Coil		<b>80294</b>

RELIANT		
<b>Rebel 700</b>	1968-71	
	23	31
Ignition Leads		<b>83850</b>
<b>Rebel 750</b>	1971-73	
	24	32
Ignition Leads		<b>83850</b>

RENAULT		
<b>11 (B/C37) 1,1</b>	1983-86	
C1E 715/C1E 720	35	48
Ignition Leads C1E 715		<b>83210</b>
Ignition Leads		<b>83220</b>
<b>11 (B/C37) 1,2</b>	1984-88	
C1G 700/C1G 710	40	55
Ignition Coil		<b>80264</b>
Ignition Leads C1G 700		<b>83210</b>
<b>11 (B/C37) 1,4</b>	1983-88	
C1J 715/C2J 730	44	60
Ignition Coil		<b>80264</b>
Ignition Leads C1J 715		<b>83210</b>
Ignition Leads		<b>83220</b>
<b>11 (B/C37) 1,4</b>	1983-88	
C2J 766/C2J 720/C2J 768/C2J 767	49	67
Ignition Coil		<b>80264</b>
Ignition Leads C2J 720; ->01.1986		<b>83210</b>
Ignition Leads C2J 720		<b>83220</b>

RENAULT Cont.		
<b>11 (B/C37) 1,4</b>	1983-85	
C2J 757/C2J 718	50	68
Ignition Coil		<b>80264</b>
Ignition Leads		<b>83210</b>
Ignition Leads C2J 718		<b>83220</b>
<b>11 (B/C37) 1,4</b>	1983-85	
C2J 717/C2J 755	53	72
Ignition Coil		<b>80264</b>
Ignition Leads C2J 717		<b>83220</b>
<b>11 (B/C37) 1,7</b>	1986-88	
F2N 730	54	73
Ignition Coil		<b>80264</b>
Ignition Leads		<b>83230</b>
<b>11 (B/C37) 1,7</b>	1984-88	
F3N 718	55	75
Ignition Coil		<b>80264</b>
Ignition Leads		<b>83230</b>
<b>11 (B/C37) 1,7</b>	1983-87	
F2N 704/F2N 700	59	80
Ignition Coil		<b>80264</b>
Ignition Leads		<b>83230</b>
<b>11 (B/C37) 1,7</b>	1987-88	
F2N 732/F2N 742	64	87
Ignition Coil		<b>80264</b>
Ignition Leads		<b>83230</b>
<b>11 (B/C37) 1,7</b>	1986-88	
F2N 798/F2N 710/F2N 708	65	88
Ignition Coil		<b>80264</b>
Ignition Leads		<b>83230</b>
<b>11 (B/C37) 1,7</b>	1987-88	
F3N 708	69	94
Ignition Coil		<b>80264</b>
Ignition Leads		<b>83230</b>
<b>11 (B/C37) 1.4 Turbo</b>	1984-86	
C1J 764/C1J 760	77	105
Ignition Coil		<b>80264</b>
Ignition Leads C1J 760		<b>83220</b>
<b>11 (B/C37) 1.4 Turbo</b>	1986-88	
C1J 770/C1J 782	85	115
Ignition Coil		<b>80264</b>
Ignition Leads C1J 770		<b>83220</b>
<b>14 (121) 1,2</b>	1976-80	
129	42	57
Ignition Leads		<b>83200</b>
<b>14 (121) 1,2</b>	1980-83	
129	43	58
Ignition Leads		<b>83200</b>
<b>14 (121) 1,4</b>	1979-83	
150	52	71
Ignition Leads		<b>83200</b>
<b>14 (121) 1,4</b>	1981-83	
X5J	44	60
Ignition Leads		<b>83200</b>
<b>17 1.6</b>	1972-80	
807.10	66	90
Ignition Leads		<b>83210</b>
<b>17 1.6 Gordini</b>	1974-80	
844.12	79	108
Ignition Leads		<b>83210</b>
<b>18 (134) 1,4</b>	1978-86	
847 720/847 722	47	64
Ignition Coil		<b>80264</b>
Ignition Leads 847 720		<b>83140</b>
Ignition Leads		<b>83210</b>
<b>18 (134) 1,6</b>	1982-86	
841 717/A2M 723	54	73
Ignition Leads 841 717		<b>83210</b>
<b>18 (134) 1,6</b>	1978-82	
841 725/841 726	58	79
Ignition Leads 841 725		<b>83210</b>
<b>18 (134) 1.6 TS</b>	1982-86	
A6M 725/A6M 726	71	97
Ignition Coil		<b>80264</b>
Ignition Leads A6M 725		<b>83210</b>
<b>18 (134) 1.6 Turbo</b>	1980-82	
807 727	80	109
Ignition Leads 807 727		<b>83210</b>



RENAULT Cont.	
<b>18 (134) 1.6 Turbo</b>	<b>1982-86</b>
A5L 718/A5L 717	92 125
Ignition Coil	<b>80264</b>
Ignition Leads A5L 717	<b>83140</b>
<b>18 (134) 2.0</b>	<b>1982-86</b>
J6R 716	77 105
Ignition Coil	<b>80264</b>
<b>18 (134) 2.2 i</b>	<b>1984-86</b>
J7T 718	76 103
Ignition Coil	<b>80264</b>
<b>18 Variable (135) 1,4</b>	<b>1979-86</b>
847 720/847 722	47 64
Ignition Coil	<b>80264</b>
Ignition Leads 847 720	<b>83140</b>
Ignition Leads	<b>83210</b>
<b>18 Variable (135) 1,6</b>	<b>1982-86</b>
841 717/A2M 723	54 73
Ignition Leads 841 717	<b>83210</b>
<b>18 Variable (135) 1,6</b>	<b>1979-82</b>
841 725/841 726	58 79
Ignition Leads 841 725	<b>83210</b>
<b>18 Variable (135) 1.6 4x4</b>	<b>1983-86</b>
841 717/A2M 723	54 73
Ignition Leads 841 717	<b>83210</b>
<b>18 Variable (135) 1.6 TS</b>	<b>1982-86</b>
A6M 725/A6M 726	71 97
Ignition Leads A6M 725	<b>83210</b>
<b>18 Variable (135) 1.6 Turbo</b>	<b>1982-86</b>
A5L 718/A5L 717	92 125
Ignition Coil	<b>80264</b>
Ignition Leads A5L 717	<b>83140</b>
<b>19 I (B/C53) 1,4</b>	<b>1989-89</b>
C2J 772	43 58
Ignition Coil	<b>80264</b>
Ignition Leads C2J 772	<b>83220</b>
<b>19 I (B/C53) 1,7</b>	<b>1988-92</b>
F3N 741/F3N 740	54 73
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>19 I (B/C53) 1,7</b>	<b>1988-92</b>
F3N 743/F3N 742	66 90
Ignition Coil	<b>80264</b>
Ignition Leads F3N 742	<b>83190</b>
Ignition Leads	<b>83230</b>
<b>19 I (B/C53) 1,4</b>	<b>1990-92</b>
E7J 700	55 75
Ignition Leads	<b>83170</b>
<b>19 I (B/C53) 1.4</b>	<b>1988-92</b>
E6J 701/E6J 700	59 80
Ignition Coil	<b>80264</b>
Ignition Leads E6J 700	<b>83170</b>
<b>19 I (B/C53) 1.4 KAT</b>	<b>1989-92</b>
C3J 710	43 58
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83220</b>
<b>19 I (B/C53) 1.8 16V</b>	<b>1989-92</b>
F7P 704	99 135
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85230</b>
<b>19 I Cabrio (D53) 1.7</b>	<b>1991-92</b>
F2N 724	55 75
Ignition Leads	<b>83230</b>
<b>19 I Cabrio (D53) 1.7</b>	<b>1991-92</b>
F3N 743/F3N 742	70 95
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>19 I Cabrio (D53) 1.8 16V</b>	<b>1991-92</b>
F7P 704/F7P 700	101 137
Ignition Coil	<b>80264</b>
<b>19 I Chamade (L53) 1,4</b>	<b>1988-92</b>
C3J 710/C2J 772	43 58
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83220</b>
<b>19 I Chamade (L53) 1,7</b>	<b>1988-92</b>
F3N 746	79 107
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83190</b>

RENAULT Cont.	
<b>19 I Chamade (L53) 1,7</b>	<b>1989-92</b>
F3N 741/F3N 740	54 73
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>19 I Chamade (L53) 1,7</b>	<b>1988-92</b>
F3N 743/F3N 742	66 90
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>19 I Chamade (L53) 1,7</b>	<b>1988-92</b>
F2N 720/F2N 721	68 92
Ignition Coil	<b>80264</b>
<b>19 I Chamade (L53) 1.4</b>	<b>1990-92</b>
E7J 700	55 75
Ignition Leads	<b>83170</b>
<b>19 I Chamade (L53) 1.4</b>	<b>1988-90</b>
E6J 701/E6J 700	57 78
Ignition Leads	<b>83170</b>
<b>19 I Chamade (L53) 1.8 16V</b>	<b>1989-92</b>
F7P 704	99 135
Ignition Coil	<b>80264</b>
<b>19 I Van (S53) 1.4</b>	<b>1988-92</b>
E6J 700	59 80
Ignition Leads	<b>83170</b>
<b>19 II (B/C53) 1,4</b>	<b>1992-95</b>
C3J 710	43 58
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83220</b>
<b>19 II (B/C53) 1,4</b>	<b>1992-95</b>
E7J 742	55 75
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83170</b>
<b>19 II (B/C53) 1,7</b>	<b>1992-95</b>
F3N 743	66 90
Ignition Coil	<b>80264</b>
Ignition Leads F3N 743	<b>83190</b>
Ignition Leads	<b>83230</b>
<b>19 II (B/C53) 1,7</b>	<b>1992-95</b>
F3N 741/F3N 740	54 73
Ignition Coil	<b>80264</b>
Ignition Leads F3N 740	<b>83190</b>
Ignition Leads	<b>83230</b>
<b>19 II (B/C53) 1,8</b>	<b>1992-95</b>
F3P 706/F3P 707/F3P 760/F3P 708	65 88
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II (B/C53) 1,8</b>	<b>1992-94</b>
F3P 700	81 110
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II (B/C53) 1,8</b>	<b>1994-95</b>
F3P 765/F3P 682	79 107
Ignition Coil F3P 682	<b>80264</b>
Ignition Coil	<b>80308</b>
Ignition Leads	<b>85210</b>
<b>19 II (B/C53) 1,8</b>	<b>1992-95</b>
F3P 706/F3P 760	66 90
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II (B/C53) 1.2</b>	<b>1992-94</b>
E7F 730	44 60
Ignition Leads	<b>83170</b>
<b>19 II (B/C53) 1.4</b>	<b>1992-95</b>
E7J 706/E6J 700	59 80
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83170</b>
<b>19 II (B/C53) 1.8 16V</b>	<b>1992-95</b>
F7P 704	99 135
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85230</b>
<b>19 II Cabrio (D53, 853) 1,7</b>	<b>1992-93</b>
F3N 743/F3N 742	66 90
Ignition Coil	<b>80264</b>
Ignition Leads F3N 742	<b>83190</b>
Ignition Leads	<b>83230</b>
<b>19 II Cabrio (D53, 853) 1,8</b>	<b>1992-96</b>
F3P 704/F3P 706/F3P 707/F3P 760/F3P 708/F3P 705	65 88
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>





RENAULT Cont.	
<b>19 II Cabrio (D53, 853) 1,8</b>	<b>1994-96</b>
F3P 765/F3P 682/F3P 764	79 107
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II Cabrio (D53, 853) 1,8</b>	<b>1993-96</b>
F3P 706/F3P 760	66 90
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II Cabrio (D53, 853) 1.8 16V</b>	<b>1992-96</b>
F7P 704	99 135
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II Chamade (L53) 1,4</b>	<b>1992-95</b>
C3J 710	43 58
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83220</b>
<b>19 II Chamade (L53) 1,4</b>	<b>1993-95</b>
E7J 742	55 75
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83170</b>
<b>19 II Chamade (L53) 1,7</b>	<b>1992-95</b>
F3N 743/F3N 742	66 90
Ignition Coil	<b>80264</b>
Ignition Leads F3N 742	<b>83190</b>
<b>19 II Chamade (L53) 1,7</b>	<b>1992-95</b>
F3N 741/F3N 740	54 73
Ignition Coil	<b>80264</b>
Ignition Leads F3N 740	<b>83190</b>
Ignition Leads	<b>83230</b>
<b>19 II Chamade (L53) 1,7</b>	<b>1993-95</b>
F2N 720/F2N 721	68 92
Ignition Coil	<b>80264</b>
<b>19 II Chamade (L53) 1,8</b>	<b>1992-95</b>
F3P 704/F3P 706/F3P 707/F3P 760/F3P 708/F3P 705	65 88
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II Chamade (L53) 1,8</b>	<b>1994-95</b>
F3P 682	79 107
Ignition Coil F3P 682	<b>80264</b>
Ignition Coil	<b>80308</b>
Ignition Leads	<b>85210</b>
<b>19 II Chamade (L53) 1,8</b>	<b>1992-95</b>
F3P 706/F3P 760	66 90
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II Chamade (L53) 1,8</b>	<b>1992-94</b>
F3P 700	81 110
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II Chamade (L53) 1,4</b>	<b>1994-95</b>
E7J 706	59 80
Ignition Leads	<b>83170</b>
<b>19 II Chamade (L53) 1,4</b>	<b>1994-95</b>
E6J 700	57 78
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83170</b>
<b>19 II Chamade (L53) 1,4</b>	<b>1992-94</b>
C1J 742/C3J 710/C2J 772	44 60
Ignition Coil	<b>80264</b>
<b>19 II Chamade (L53) 1,7</b>	<b>1992-95</b>
F3N 741/F3N 740	55 75
Ignition Coil	<b>80264</b>
<b>19 II Chamade (L53) 1,8</b>	<b>1992-95</b>
F3P 706/F3P 700	79 107
Ignition Coil	<b>80264</b>
<b>19 II Chamade (L53) 1,8</b>	<b>1992-94</b>
F3P 765	67 91
Ignition Coil	<b>80264</b>
<b>19 II Chamade (L53) 1.8 16V</b>	<b>1992-95</b>
F7P 704	99 135
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>19 II Van (S53) 1.4</b>	<b>1992-95</b>
E6J 700	59 80
Ignition Leads	<b>83170</b>
<b>20 (127) 1,6</b>	<b>1977-83</b>
843 720/843 721	71 97
Ignition Leads 843 720	<b>83210</b>

RENAULT Cont.	
<b>20 (127) 1,6</b>	<b>1975-77</b>
843	66 90
Ignition Leads 843	<b>83210</b>
<b>21 (B48) 1,7</b>	<b>1989-92</b>
F3N 726	54 73
Ignition Coil	<b>80264</b>
<b>21 (B48) 1,7</b>	<b>1989-94</b>
F3N 723/F3N 722	66 90
Ignition Coil	<b>80264</b>
Ignition Leads F3N 722; 01.1992->	<b>83190</b>
<b>21 (B48) 2,2</b>	<b>1989-94</b>
J7T 754/J7T 755	79 107
Ignition Coil	<b>80264</b>
Ignition Leads ->02.1991	<b>83160</b>
Ignition Leads 01.1992->	<b>85220</b>
<b>21 (B48) 2.0</b>	<b>1990-92</b>
J7R 740	99 135
Ignition Coil	<b>80264</b>
Ignition Leads ->02.1991	<b>83160</b>
Ignition Leads 01.1992->	<b>85220</b>
<b>21 (B48) 2.0</b>	<b>1989-93</b>
J7R 747/J7R 746	88 120
Ignition Coil	<b>80264</b>
<b>21 (B48) 2.0 4x4</b>	<b>1990-92</b>
J7R 740	99 135
Ignition Coil	<b>80264</b>
Ignition Leads ->02.1991	<b>83160</b>
Ignition Leads 01.1992->	<b>85220</b>
<b>21 (B48) 2.2 4x4</b>	<b>1990-94</b>
J7T 754/J7T 755	79 107
Ignition Coil	<b>80264</b>
Ignition Leads ->02.1991	<b>83160</b>
Ignition Leads 01.1992->	<b>85220</b>
<b>21 Break (K48) 1,7</b>	<b>1986-88</b>
F2N 710	65 88
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 1,7</b>	<b>1986-89</b>
F3N 723/F3N 722	69 94
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 1,7</b>	<b>1989-93</b>
F3N 723/F3N 722	66 90
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 1,7</b>	<b>1986-93</b>
F2N 712	55 75
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 1,7</b>	<b>1986-89</b>
F2N 750	54 73
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 1,7</b>	<b>1987-89</b>
F2N 752	64 87
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 1.7 KAT</b>	<b>1988-93</b>
F3N 726	54 73
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 2,2</b>	<b>1986-93</b>
J7T 754/J7T 755	79 108
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 2.0</b>	<b>1989-92</b>
J7R 750/J7R 751	86 117
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 2.0</b>	<b>1991-93</b>
J6R 759/J6R 758/J6R 792	75 102
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 2.0</b>	<b>1986-88</b>
J7R 750/J7R 751	85 116
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 2.0</b>	<b>1990-94</b>
J7R 740	99 135
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 2.0</b>	<b>1986-93</b>
J7R 747/J7R 746	88 120
Ignition Coil	<b>80264</b>
<b>21 Break (K48) 2.2 4x4</b>	<b>1986-93</b>
J7T 754/J7T 755	79 107
Ignition Coil	<b>80264</b>
<b>21 Sedan (L48) 1,7</b>	<b>1986-87</b>
F2N 712	55 75
Ignition Coil	<b>80264</b>



RENAULT Cont.	
<b>21 Sedan (L48) 1,7</b>	<b>1986-94</b>
F3N 723/F3N 722	69 94
Ignition Coil	<b>80264</b>
Ignition Leads F3N 722; 01.1992->	<b>83190</b>
<b>21 Sedan (L48) 1,7</b>	<b>1986-93</b>
F2N 710	65 88
Ignition Coil	<b>80264</b>
<b>21 Sedan (L48) 1,7</b>	<b>1986-94</b>
F3N 726 /F2N 750	54 73
Ignition Coil	<b>80264</b>
Ignition Leads F2N 750; 01.1992->	<b>83190</b>
<b>21 Sedan (L48) 1,7</b>	<b>1989-94</b>
F3N 723/F3N 722	66 90
Ignition Coil	<b>80264</b>
Ignition Leads F3N 722; 01.1992->	<b>83190</b>
<b>21 Sedan (L48) 1,7</b>	<b>1987-89</b>
F2N 752	64 87
Ignition Coil	<b>80264</b>
<b>21 Sedan (L48) 2,2</b>	<b>1986-94</b>
J7T 754/J7T 755	79 107
Ignition Coil	<b>80264</b>
<b>21 Sedan (L48) 2.0</b>	<b>1986-93</b>
J6R 793/J6R 759/J6R 758/J6R 792	75 102
Ignition Leads ->12.1991	<b>83160</b>
Ignition Leads 01.1992->	<b>85220</b>
<b>21 Sedan (L48) 2.0</b>	<b>1991-93</b>
J6R 758	78 106
Ignition Coil	<b>80264</b>
Ignition Leads 01.1992->	<b>85220</b>
<b>21 Sedan (L48) 2.0</b>	<b>1986-88</b>
J7R 750/J7R 751	85 116
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>21 Sedan (L48) 2.0</b>	<b>1986-89</b>
J7R 750/J7R 751	86 117
Ignition Coil	<b>80264</b>
<b>21 Sedan (L48) 2.0</b>	<b>1990-94</b>
J7R 740	99 135
Ignition Coil	<b>80264</b>
Ignition Leads ->12.1991	<b>83160</b>
Ignition Leads 01.1992->	<b>85220</b>
<b>21 Sedan (L48) 2.0</b>	<b>1986-93</b>
J7R 747/J7R 746	88 120
Ignition Coil	<b>80264</b>
Ignition Leads ->12.1991	<b>83160</b>
Ignition Leads 01.1992->	<b>85220</b>
<b>21 Sedan (L48) 2.0 4x4</b>	<b>1989-94</b>
J7R 740	99 135
Ignition Coil	<b>80264</b>
Ignition Leads ->12.1991	<b>83160</b>
Ignition Leads 01.1992->	<b>85220</b>
<b>21 Sedan (L48) 2.0 Turbo</b>	<b>1987-90</b>
J7R 752	129 175
Ignition Coil	<b>80234</b>
Ignition Coil	<b>80264</b>
<b>21 Sedan (L48) 2.0 Turbo</b>	<b>1990-92</b>
J7R 756	119 162
Ignition Coil 07.1991->	<b>80234</b>
Ignition Coil	<b>80264</b>
<b>21 Sedan (L48) 2.0 Turbo 4x4</b>	<b>1989-93</b>
J7R 752	129 175
Ignition Coil	<b>80264</b>
<b>21 Sedan (L48) 2.0 Turbo 4x4</b>	<b>1990-92</b>
J7R 756	119 162
Ignition Coil 07.1991->	<b>80234</b>
Ignition Coil ->Ch.F00349091	<b>80264</b>
<b>21 Sedan (L48) 2.2 4x4</b>	<b>1990-94</b>
J7T 754/J7T 755	79 107
Ignition Coil	<b>80264</b>
<b>25 (B29) 2,2</b>	<b>1984-89</b>
J7T 707/J7T 706/J7T 714/J7T 715	89 121
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85220</b>
<b>25 (B29) 2,2</b>	<b>1986-92</b>
J7T 708/J7T 733 /J7T 732	79 108
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85220</b>

RENAULT Cont.	
<b>25 (B29) 2,2</b>	<b>1984-89</b>
J7T 730/J7T 731	91 124
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85220</b>
<b>25 (B29) 2,2</b>	<b>1985-89</b>
J7T 708/J7T 732	76 103
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85220</b>
<b>25 (B29) 2.0</b>	<b>1984-92</b>
J6R 763/J6R 707/J6R 760/J6R 706/J6R 762	74 101
Ignition Coil	<b>80264</b>
<b>25 (B29) 2.0</b>	<b>1987-93</b>
J7R 723/J7R 722	88 120
Ignition Leads	<b>83160</b>
<b>25 (B29) 2.0 12V</b>	<b>1988-93</b>
J7R 721/J7R 720	103 140
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>25 (B29) 2.0 12V</b>	<b>1989-92</b>
J7R 726	99 135
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>25 (B29) 2.4 V6 Turbo</b>	<b>1984-90</b>
Z7U 702	133 181
Ignition Coil	<b>80264</b>
<b>25 (B29) 2.5 V6 Turbo</b>	<b>1990-92</b>
Z7U 700	151 205
Ignition Coil	<b>80264</b>
<b>25 (B29) 2.8 V6</b>	<b>1987-90</b>
Z7W 700	115 156
Ignition Coil	<b>80264</b>
<b>25 (B29) 2.8 V6 Injection</b>	<b>1987-92</b>
Z7W 706/Z7W 707/Z7W 709	110 150
Ignition Coil	<b>80264</b>
<b>25 (B29) 2.8 V6 Injection</b>	<b>1986-88</b>
Z7W 702	100 136
Ignition Coil	<b>80264</b>
<b>4 (112) 0,8</b>	<b>1962-83</b>
800 705/800	19 26
Ignition Leads 800; ->07.1968	<b>83140</b>
<b>4 (112) 0,8</b>	<b>1983-88</b>
800 705/B1B 707	21 29
Ignition Leads 800 705; ->07.1985	<b>83140</b>
<b>4 (112) 0,8</b>	<b>1971-88</b>
800 01	25 34
Ignition Leads ->07.1985	<b>83140</b>
<b>4 Van (R21, R23) 0,8</b>	<b>1983-89</b>
800 705/B1B 707	21 29
Ignition Leads 800 705; ->07.1986	<b>83140</b>
<b>4 Van (R21, R23) 0,8</b>	<b>1966-88</b>
800 01	25 34
Ignition Leads 07.1968->	<b>83140</b>
<b>4 Van (R21, R23) 1,1</b>	<b>1976-89</b>
C1E 714/C1E 718/C1E 719/688 711/688 712	25 34
Ignition Leads 688 711; ->07.1985	<b>83140</b>
<b>4 Van (R21, R23) 1,1</b>	<b>1982-89</b>
C1E 718/C1E 719	26 35
Ignition Leads C1E 718; ->07.1986	<b>83140</b>
<b>5 (122) 0,8</b>	<b>1982-84</b>
800 710	27 37
Ignition Leads	<b>83210</b>
<b>5 (122) 1,1</b>	<b>1980-85</b>
C1E 726/688 713	33 45
Ignition Leads 688 713	<b>83140</b>
<b>5 (122) 1,3</b>	<b>1976-79</b>
810 726	31 42
Ignition Leads 810 726	<b>83140</b>
<b>5 (122) 1,3</b>	<b>1979-84</b>
810 719	33 45
Ignition Leads 810 719	<b>83140</b>
<b>5 (122) 1,3</b>	<b>1975-84</b>
810 725	47 64
Ignition Leads 810 725	<b>83140</b>
<b>5 (122) 1,4</b>	<b>1982-85</b>
847 725/C2J 713	46 63
Ignition Coil	<b>80264</b>
Ignition Leads 847 725	<b>83210</b>



RENAULT Cont.	
<b>5 (122) 1.0</b>	<b>1972-85</b>
689 710	32 44
Ignition Leads	<b>83210</b>
<b>5 (122) 1.3 Automatic</b>	<b>1979-84</b>
810 729	40 54
Ignition Leads 810 729	<b>83140</b>
<b>5 (122) 1.4 Alpine Turbo</b>	<b>1981-85</b>
840 726/C6J 750	79 108
Ignition Leads 840 726; 01.1983->	<b>83210</b>
<b>9 (L42) 1,1</b>	<b>1981-87</b>
C1E 715/C1E 720	35 48
Ignition Leads C1E 715	<b>83210</b>
<b>9 (L42) 1,2</b>	<b>1985-88</b>
C1G 700/C1G 710	40 54
Ignition Leads C1G 700	<b>83210</b>
<b>9 (L42) 1,4</b>	<b>1981-88</b>
C1J 715/C1J 792/C2J 730/C1J 796	44 60
Ignition Coil	<b>80264</b>
Ignition Leads C1J 715	<b>83210</b>
<b>9 (L42) 1,4</b>	<b>1985-88</b>
C2J 766/C2J 720/C2J 768/C2J 767	49 67
Ignition Coil	<b>80264</b>
Ignition Leads C2J 720; ->01.1986	<b>83210</b>
Ignition Leads C2J 720	<b>83220</b>
<b>9 (L42) 1,4</b>	<b>1981-85</b>
C2J 717/C2J 755	53 72
Ignition Coil	<b>80264</b>
Ignition Leads C2J 717	<b>83220</b>
<b>9 (L42) 1,7</b>	<b>1986-88</b>
F3N 718	54 73
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>9 (L42) 1,7</b>	<b>1986-88</b>
F2N 730	55 75
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>9 (L42) 1,7</b>	<b>1984-89</b>
F2N 704/F2N 700	59 80
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>9 (L42) 1,7</b>	<b>1987-88</b>
F3N 708	69 94
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>9 (L42) 1.4 Automatic</b>	<b>1981-85</b>
C2J 757/C2J 718	50 68
Ignition Coil	<b>80264</b>
Ignition Leads C2J 718	<b>83210</b>
<b>9 (L42) 1.4 Turbo</b>	<b>1986-89</b>
C1J 764	85 116
Ignition Coil	<b>80264</b>
Ignition Leads C1J 760	<b>83220</b>
<b>9 (L42) 1.4 Turbo</b>	<b>1984-86</b>
C1J 764/C1J 760	77 105
Ignition Coil	<b>80264</b>
Ignition Leads C1J 760	<b>83220</b>
<b>Avantime (De0) 2.0 16V Turbo</b>	<b>2001-03</b>
F4R 760/F4R 761	120 163
Ignition Coil	<b>80203</b>
<b>Avantime (De0) 3.0 V6</b>	<b>2001-03</b>
L7X 720/L7X 721	152 207
Ignition Coil	<b>80309</b>
<b>Clio Grandtour (Kr0/1) 1.2 16V</b>	<b>2010-&gt;</b>
D4F 786	76 103
Ignition Coil	<b>80222</b>
Ignition Leads	<b>85988</b>
<b>Clio Grandtour (Kr0/1) 1.2 16V</b>	<b>2008-&gt;</b>
D4F 740	55 75
Ignition Coil	<b>80225</b>
Ignition Coil Without ignition lead	<b>80287</b>
Ignition Leads	<b>85988</b>

<b>Clio Grandtour (Kr0/1) 1.2 16V</b>	<b>2008-&gt;</b>
D4F 764	58 78
Ignition Coil	<b>80225</b>
Ignition Coil Without ignition lead	<b>80287</b>
Ignition Leads	<b>85988</b>
<b>Clio Grandtour (Kr0/1) 1.2 16V</b>	<b>2008-&gt;</b>
D4F 784	74 101
Ignition Coil	<b>80222</b>
Ignition Coil ->05.2008; With ignition lead	<b>80225</b>
Ignition Coil 06.2008->; Without ignition lead	<b>80287</b>
Ignition Leads 06.2008->	<b>85988</b>
Ignition Leads	<b>85991</b>
<b>Clio Grandtour (Kr0/1) 1.2 16V Hi-Flex</b>	<b>2008-&gt;</b>
D4F 740	55 75
Ignition Coil	<b>80225</b>
Ignition Coil Without ignition lead	<b>80287</b>
Ignition Leads	<b>85988</b>
<b>Clio Grandtour (Kr0/1) 1.4 16V</b>	<b>2010-&gt;</b>
K4J 780	72 98
Ignition Coil	<b>80203</b>
<b>Clio Grandtour (Kr0/1) 1.6 16V</b>	<b>2008-&gt;</b>
K4M 800/K4M 801	82 112
Ignition Coil	<b>80203</b>
<b>Clio Grandtour (Kr0/1) 1.6 16V</b>	<b>2008-&gt;</b>
K4M 862	94 128
Ignition Coil	<b>80203</b>
<b>Clio Grandtour IV 1.2 16V</b>	<b>2013-&gt;</b>
D4F 740	54 73
Ignition Coil	<b>80225</b>
Ignition Coil	<b>80287</b>
<b>Clio I (B/C57, 5/357) 1,2</b>	<b>1991-96</b>
E7F 706	40 54
Ignition Coil E7F 706	<b>80264</b>
Ignition Coil	<b>80308</b>
Ignition Leads	<b>83170</b>
<b>Clio I (B/C57, 5/357) 1,2</b>	<b>1996-98</b>
D7F 730	40 54
Ignition Coil	<b>80373</b>
Ignition Leads 04.1996-02.1998	<b>83170</b>
Ignition Leads	<b>85990</b>
<b>Clio I (B/C57, 5/357) 1,2</b>	<b>1996-96</b>
C3G 720	40 54
Ignition Coil	<b>80308</b>
<b>Clio I (B/C57, 5/357) 1,2</b>	<b>1990-98</b>
E7F 750/E7F 700/E7F 708	43 58
Ignition Coil 06.1990-02.1998	<b>80264</b>
Ignition Coil	<b>80308</b>
Ignition Leads	<b>83170</b>
<b>Clio I (B/C57, 5/357) 1,2</b>	<b>1990-96</b>
E5F 710	44 60
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83170</b>
<b>Clio I (B/C57, 5/357) 1,2</b>	<b>1996-98</b>
D7F 730	43 58
Ignition Coil 03.1996-02.1998	<b>80222</b>
Ignition Coil	<b>80308</b>
Ignition Coil	<b>80373</b>
Ignition Leads 04.1996-02.1998	<b>83170</b>
Ignition Leads	<b>85990</b>
<b>Clio I (B/C57, 5/357) 1,4</b>	<b>1991-98</b>
E7J 756/E7J 757	55 75
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83170</b>
<b>Clio I (B/C57, 5/357) 1,4</b>	<b>1991-98</b>
E7J 719 /E7J 601 /E7J 718/E7J 754	58 79
Ignition Leads	<b>83170</b>
<b>Clio I (B/C57, 5/357) 1,7</b>	<b>1991-93</b>
F2N 770	68 92
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83190</b>
<b>Clio I (B/C57, 5/357) 1,8</b>	<b>1991-98</b>
F3P 710 /F3P 714	65 88
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>
<b>Clio I (B/C57, 5/357) 1,8</b>	<b>1994-98</b>
F3P 755 /F3P 754	66 90
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85210</b>



RENAULT Cont.	
<b>Clio I (B/C57, 5/357) 1.1</b>	1991-98
C1E 700	34 46
Ignition Leads	83210
Ignition Leads ->12.1996	83220
<b>Clio I (B/C57, 5/357) 1.4</b>	1991-98
E7J 710 /E7J 711	59 80
Ignition Coil	80264
Ignition Leads	83170
<b>Clio I (B/C57, 5/357) 1.8</b>	1991-98
F3P 710	70 95
Ignition Coil	80264
Ignition Leads	85210
<b>Clio I (B/C57, 5/357) 1.8 16V</b>	1991-96
F7P 722	99 135
Ignition Coil	80264
Ignition Leads	85230
<b>Clio I (B/C57, 5/357) 1.8 Rsi</b>	1995-98
F3P 758	79 107
Ignition Coil	80264
Ignition Leads	85210
<b>Clio I (B/C57, 5/357) 1.8 Rsi</b>	1993-95
F3P 712	80 109
Ignition Coil	80264
Ignition Leads	85210
<b>Clio I (B/C57, 5/357) Williams</b>	1994-98
F7R 700	108 147
Ignition Coil	80264
Ignition Leads	85230
<b>Clio I Van (S57) 1.2</b>	1991-98
E7F 706	40 54
Ignition Leads	85200
<b>Clio II (Bb0/1/2, Cb0/1/2) 1,2</b>	1999-01
D7F 722	44 60
Ignition Coil	80222
Ignition Leads OE N° 7700 114 549; 10.1999->	85988
Ignition Leads ->09.1999	85990
Ignition Leads 10.1999->	85991
<b>Clio II (Bb0/1/2, Cb0/1/2) 1,2</b>	1998->
D7F 710/D7F 766/D7F 722/D7F 720/D7F 764/D7F 726/D7F 746	43 58
Ignition Coil D7F 720/D7F 726; 10.1998->	80222
Ignition Coil D7F 720; D7F 726; ->10.1998	80373
Ignition Leads ->09.1999	85990
Ignition Leads 10.1999->	85991
<b>Clio II (Bb0/1/2, Cb0/1/2) 1,4</b>	1998-05
E7J 634/E7J 780/K7J 700	55 75
Ignition Coil Cyl. 1-4	80204
Ignition Coil Cyl. 2-3	80205
Ignition Coil 03.1999->	80222
Ignition Leads 03.1999->	85994
Ignition Leads	85996
<b>Clio II (Bb0/1/2, Cb0/1/2) 1,6</b>	1998-05
K7M 744/K7M 745	66 90
Ignition Coil 10.1999->	80203
Ignition Coil Cyl. 1-4	80204
Ignition Coil Cyl. 2-3	80205
Ignition Coil 03.1999->	80222
Ignition Leads K7M; K4M 746; 09.1999->	85994
Ignition Leads	85996
<b>Clio II (Bb0/1/2, Cb0/1/2) 1.2</b>	2001->
	55 75
Ignition Coil	80206
Ignition Leads	85991
<b>Clio II (Bb0/1/2, Cb0/1/2) 1.2 16V</b>	2001->
D4F 728/D4F 714/D4F 706/D4F 712/D4F 722	55 75
Ignition Coil D4F 714/D4F 712	80206
Ignition Coil D4F 714/D4F 712; 06.2004->	80225
Ignition Coil Without ignition lead	80287
Ignition Leads	85988
<b>Clio II (Bb0/1/2, Cb0/1/2) 1.2 LPG</b>	1998-09
D7F 766/D7F 764	43 58
Ignition Coil	80222
Ignition Leads OE N° 8200486877	85988
Ignition Leads ->Engine 991002	85990
<b>Clio II (Bb0/1/2, Cb0/1/2) 1.4 16V</b>	1999-04
K4J 712/K4J 713	70 95
Ignition Coil	80203
<b>Clio II (Bb0/1/2, Cb0/1/2) 1.4 16V</b>	2000->
K4J 712/K4J 711/K4J 710/K4J 713	72 98
Ignition Coil K4J700/K4J712/K4J713	80203

RENAULT Cont.	
<b>Clio II (Bb0/1/2, Cb0/1/2) 1.6 16V</b>	1998->
K4M 743/K4M 748/K4M 740/K4M 744/K4M 742/K4M 708/K4M 745	79 107
Ignition Coil K4M 748,K4M 708; With regul.cat.(3way)	80203
<b>Clio II (Bb0/1/2, Cb0/1/2) 2.0 16V Sport</b>	2000->
F4R 730/F4R 736	124 169
Ignition Coil SAE	80203
Ignition Coil	80222
Ignition Coil F4R 730	80373
<b>Clio II (Bb0/1/2, Cb0/1/2) 2.0 16V Sport</b>	2004->
F4R 738	132 179
Ignition Coil	80373
<b>Clio II (Bb0/1/2, Cb0/1/2) 3.0 V6 Sport</b>	2000-02
L7X 760	166 226
Ignition Coil	80309
<b>Clio II (Bb0/1/2, Cb0/1/2) 3.0 V6 Sport</b>	2002->
L7X 762	187 254
Ignition Coil	80309
<b>Clio II Van (Sb0/1/2) 1,1</b>	1998->
D7F 720/D7F 726/D7F 746	43 58
Ignition Coil 10.1998->	80222
Ignition Coil ->10.1998	80373
Ignition Leads ->09.1999	85990
Ignition Leads 10.1999->	85991
<b>Clio II Van (Sb0/1/2) 1,2</b>	1999-03
D7F 722/D7F 726/D7F 746	44 60
Ignition Coil	80222
Ignition Leads D7F 726; ->10.1999	85990
Ignition Leads 11.1999->	85991
<b>Clio III (Br0/1, Cr0/1) 1.2 16V</b>	2010->
D4F 786	76 103
Ignition Coil	80225
Ignition Coil	80287
Ignition Leads	85988
<b>Clio III (Br0/1, Cr0/1) 1.2 16V</b>	2005->
D4F 740/D4F 706/D4F 764	55 75
Ignition Coil D4F 740	80225
Ignition Coil Without ignition lead	80287
Ignition Leads	85988
<b>Clio III (Br0/1, Cr0/1) 1.2 16V</b>	2005->
D4F 764	58 78
Ignition Coil D4F 764	80225
Ignition Coil Without ignition lead	80287
Ignition Leads	85988
<b>Clio III (Br0/1, Cr0/1) 1.2 16V</b>	2005->
D4F 740	48 65
Ignition Coil	80225
Ignition Coil Without ignition lead	80287
Ignition Leads	85988
<b>Clio III (Br0/1, Cr0/1) 1.2 16V</b>	2007->
D4F 784	74 101
Ignition Coil	80222
Ignition Coil ->05.2008; With ignition lead	80225
Ignition Coil 06.2008->; Without ignition lead	80287
Ignition Leads	85988
<b>Clio III (Br0/1, Cr0/1) 1.2 16V Hi-Flex</b>	2008->
D4F 740/D4F 742	55 75
Ignition Coil	80225
Ignition Coil Without ignition lead	80287
Ignition Leads	85988
<b>Clio III (Br0/1, Cr0/1) 1.2 Ethanol</b>	2008->
	55 75
Ignition Coil D4F 742	80287
Ignition Leads	85988
<b>Clio III (Br0/1, Cr0/1) 1.4 16V</b>	2005->
K4J 780	72 98
Ignition Coil Intake manifold injection	80203
<b>Clio III (Br0/1, Cr0/1) 1.6 16V</b>	2005->
K4M 804	65 88
Ignition Coil Intake manifold injection	80203
<b>Clio III (Br0/1, Cr0/1) 1.6 16V</b>	2005->
K4M 800/K4M 801	82 112
Ignition Coil Intake manifold injection	80203
<b>Clio III (Br0/1, Cr0/1) 1.6 16V GT</b>	2009->
K4M 862	94 128
Ignition Coil	80203
<b>Clio III (Br0/1, Cr0/1) 2.0 16V</b>	2006->
M4R 700/M4R 701	102 139
Ignition Coil	80288



RENAULT Cont.	
<b>Clio III (Br0/1, Cr0/1) 2.0 16V Sport</b>	<b>2006-&gt;</b>
F4R 830	145 197
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Clio III (Br0/1, Cr0/1) 2.0 16V Sport</b>	<b>2008-&gt;</b>
F4R 830	148 200
Ignition Coil	<b>80203</b>
<b>Clio IV 1.2 16V</b>	<b>2012-&gt;</b>
D4F 740	54 73
Ignition Coil	<b>80225</b>
Ignition Coil D4F 744	<b>80287</b>
Ignition Leads	<b>85988</b>
<b>Espace I (J11) 2,2</b>	<b>1986-90</b>
J7T 770	79 108
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Espace I (J11) 2.0</b>	<b>1984-90</b>
J6R 234/J6R 236	80 109
Ignition Coil	<b>80264</b>
<b>Espace I (J11) 2.0</b>	<b>1988-90</b>
J6R 734	74 101
Ignition Coil	<b>80264</b>
<b>Espace I (J11) 2.0 i</b>	<b>1989-90</b>
J7R 760	87 118
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Espace I (J11) 2.0 i Quadra</b>	<b>1988-92</b>
J7R 760	87 118
Ignition Coil	<b>80264</b>
<b>Espace I (J11) 2.2 Quadra</b>	<b>1988-90</b>
J7T 770	79 108
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Espace II (J/S63) 2,2</b>	<b>1991-96</b>
J7T 772/J7T 776/J7T 773	79 108
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85220</b>
<b>Espace II (J/S63) 2.0</b>	<b>1991-96</b>
J7R 768	76 103
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85220</b>
<b>Espace II (J/S63) 2.2 4x4</b>	<b>1991-96</b>
J7T 772/J7T 773	79 108
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85220</b>
<b>Espace II (J/S63) 2.8 V6</b>	<b>1991-96</b>
Z7W 717/Z7W 712/Z7W 713	110 150
Ignition Coil	<b>80264</b>
<b>Espace III (JE0) 2.0</b>	<b>2001-02</b>
F4R 701/F4R 700	102 139
Ignition Coil	<b>80203</b>
Ignition Leads	<b>85985</b>
<b>Espace III (JE0) 2.0</b>	<b>1996-00</b>
F3R 769/F3R 728/F3R 742/F3R 729/F3R 768	84 114
Ignition Coil	<b>80203</b>
Ignition Coil 04.1997->	<b>80232</b>
Ignition Coil ->04.1997	<b>80234</b>
Ignition Leads SAE; ->03.1997	<b>85985</b>
Ignition Leads M4; 04.1997->	<b>86000</b>
<b>Espace III (JE0) 2.0 16V</b>	<b>1998-02</b>
F4R 701/F4R 700	103 140
Ignition Coil	<b>80203</b>
<b>Espace III (JE0) 3.0</b>	<b>1996-98</b>
Z7X 775	123 167
Ignition Coil Z7X 775	<b>80234</b>
<b>Espace III (JE0) 3.0 V6 24V</b>	<b>1998-02</b>
L7X 727	140 190
Ignition Coil	<b>80374</b>
<b>Espace IV (JK0/1) 2.0</b>	<b>2002-&gt;</b>
F4R 792	100 136
Ignition Coil	<b>80203</b>
<b>Espace IV (JK0/1) 2.0</b>	<b>2005-&gt;</b>
F4R 897/F4R 796/F4R 896/F4R 797	125 170
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Espace IV (JK0/1) 2.0</b>	<b>2002-05</b>
F4R 790	98 133
Ignition Coil	<b>80203</b>
<b>Espace IV (JK0/1) 2.0 Turbo</b>	<b>2002-&gt;</b>
F4R 796/F4R 795/F4R 794/F4R 797	120 163
Ignition Coil F4R794/F4R795/F4R797; ->12.2006	<b>80203</b>

RENAULT Cont.	
<b>Express Van (F40, G40) 1,1</b>	<b>1987-91</b>
C1E 756	33 45
Ignition Leads	<b>83210</b>
<b>Express Van (F40, G40) 1,2</b>	<b>1991-98</b>
C3G 712/C3G 710	40 55
Ignition Coil	<b>80308</b>
Ignition Leads C3G 710	<b>83210</b>
Ignition Leads	<b>83220</b>
<b>Express Van (F40, G40) 1,4</b>	<b>1986-91</b>
C2J 784	44 60
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83220</b>
<b>Express Van (F40, G40) 1,4</b>	<b>1991-98</b>
E7J 720/E7J 773/E7J 724/E7J 726	55 75
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83170</b>
<b>Express Van (F40, G40) 1,4</b>	<b>1994-98</b>
E7J 728	58 79
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83170</b>
<b>Express Van (F40, G40) 1,4</b>	<b>1985-91</b>
C1J 780/C1J 768	43 58
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83220</b>
<b>Express Van (F40, G40) 1.0</b>	<b>1986-92</b>
C1C 706	27 37
Ignition Leads	<b>83210</b>
<b>Express Van (F40, G40) 1.4 KAT</b>	<b>1988-98</b>
C3J 762/C3J 700/C3J 702/C3J 760	43 58
Ignition Coil	<b>80264</b>
Ignition Leads 09.1991-03.1997	<b>83170</b>
Ignition Leads C3J 700	<b>83210</b>
Ignition Leads	<b>83220</b>
<b>Fluence (L30) 1.6 16V</b>	<b>2010-&gt;</b>
K4M 839/K4M 838	81 110
Ignition Coil SAGEM	<b>80203</b>
<b>Fluence (L30) 1.6 16V</b>	<b>2010-&gt;</b>
K4M 838	82 111
Ignition Coil	<b>80203</b>
<b>Fluence (L30) 2.0 16V</b>	<b>2010-&gt;</b>
M4R 751/M4R 714	103 140
Ignition Coil	<b>80330</b>
<b>Fuego (136) 1.4 TL/GTL</b>	<b>1980-85</b>
847 720	47 64
Ignition Leads 847 720	<b>83210</b>
<b>Fuego (136) 1.6</b>	<b>1983-85</b>
A2M 723	52 71
Ignition Leads	<b>83210</b>
<b>Fuego (136) 1.6 TS/GTS</b>	<b>1980-85</b>
843 723/A6M 725/A6M 726/843 724	71 97
Ignition Leads 843 723	<b>83210</b>
<b>Fuego (136) 1.6 Turbo</b>	<b>1983-85</b>
A5L 750	97 132
Ignition Leads	<b>83210</b>
<b>Grand Scénic II (JM0/1) 1.6</b>	<b>2004-&gt;</b>
K4M 761/K4M 782	83 113
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Grand Scénic II (JM0/1) 2.0</b>	<b>2004-&gt;</b>
F4R 771/F4R 770	99 135
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Grand Scénic II (JM0/1) 2.0</b>	<b>2004-&gt;</b>
F4R 776	120 163
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Grand Scénic III (JZ0/1) 1.6 16V</b>	<b>2009-&gt;</b>
K4M 858	81 109
Ignition Coil	<b>80203</b>
<b>Grand Scénic III (JZ0/1) 2.0 16V</b>	<b>2009-&gt;</b>
M4R 711	103 140
Ignition Coil	<b>80330</b>
<b>Kangoo (KC0/1) 1,2</b>	<b>1997-&gt;</b>
D7F 710/D7F 744/D7F 722/D7F 720/D7F 726/D7F 746	43 58
Ignition Coil	<b>80206</b>
Ignition Coil 10.1998->	<b>80222</b>
Ignition Coil D7F710; D7F720; ->10.1998	<b>80373</b>
Ignition Leads OE N° 7700 114 549; 10.1999->	<b>85988</b>
Ignition Leads ->10.1999	<b>85990</b>
Ignition Leads 11.1999-06.2001	<b>85991</b>





RENAULT Cont.		
<b>Kangoo (KC0/1) 1,4</b>	1997->	
E7J 634/K7J 701/E7J 635/E7J 780/K7J 700	55	75
Ignition Coil Cyl. 1-4	<b>80204</b>	
Ignition Coil Cyl. 2-3	<b>80205</b>	
Ignition Coil	<b>80222</b>	
Ignition Leads ->08.1998	<b>83170</b>	
Ignition Leads K7J 700, K7J 701	<b>85994</b>	
Ignition Leads E7J 780	<b>85996</b>	
<b>Kangoo (KC0/1) 1.2 16V</b>	2001->	
D4F 714/D4F 716/D4F 712/D4F 730	55	75
Ignition Coil	<b>80206</b>	
Ignition Coil 06.2004->; With ignition lead	<b>80225</b>	
Ignition Coil D4F 714/D4F 716; 04.2004-12.2007	<b>80287</b>	
Ignition Leads	<b>85988</b>	
<b>Kangoo (KC0/1) 1.6 16V</b>	2001->	
K4M 706/K4M 750/K4M 753/K4M 752	70	95
Ignition Coil	<b>80203</b>	
<b>Kangoo (KC0/1) 1.6 16V 4x4</b>	2001->	
K4M 750/K4M 753/K4M 752	70	95
Ignition Coil	<b>80203</b>	
<b>Kangoo / Grand Kangoo (KW0/1) 1,6</b>	2008->	
K7M 750	64	87
Ignition Coil	<b>80222</b>	
Ignition Leads	<b>85994</b>	
<b>Kangoo / Grand Kangoo (KW0/1) 1.6 16V</b>	2008->	
K4M 830/K4M 831	78	106
Ignition Coil	<b>80203</b>	
<b>Kangoo / Grand Kangoo (KW0/1) 1.6 16V Hi-Flex</b>	2008->	
K4M 834/K4M 850	78	106
Ignition Coil	<b>80203</b>	
<b>Kangoo Be Bop (KW0/1) 1,6</b>	2009->	
K4M 830	78	106
Ignition Coil	<b>80203</b>	
<b>Kangoo Express (FC0/1) 1,2</b>	1998-01	
D7F 766/D7F 764	44	60
Ignition Coil	<b>80222</b>	
Ignition Coil ->10.1998	<b>80373</b>	
<b>Kangoo Express (FC0/1) 1,2</b>	1997->	
D7F 710/D7F 744/D7F 722/D7F 720/D7F 726/D7F 746	43	58
Ignition Coil 10.1998->	<b>80222</b>	
Ignition Coil D7F710; D7F720; ->10.1998	<b>80373</b>	
Ignition Leads ->10.1999	<b>85990</b>	
Ignition Leads D7F Eco; 11.1999-06.2001	<b>85991</b>	
<b>Kangoo Express (FC0/1) 1,4</b>	1997->	
E7J 634/K7J 701/E7J 635/E7J 780	55	75
Ignition Coil Cyl. 1-4; With regul.cat.(3way)	<b>80204</b>	
Ignition Coil Cyl. 2-3	<b>80205</b>	
Ignition Coil	<b>80222</b>	
Ignition Leads K7J701,E7J634,E7J635	<b>85994</b>	
Ignition Leads E7J 780	<b>85996</b>	
<b>Kangoo Express (FC0/1) 1.2 16V</b>	2001->	
D4F 714/D4F 712/D4F 730	55	75
Ignition Coil D4F 714/D4F 712	<b>80206</b>	
Ignition Coil 06.2008->; With ignition lead	<b>80225</b>	
Ignition Coil 06.2008->; Without ignition lead	<b>80287</b>	
Ignition Leads	<b>85988</b>	
<b>Kangoo Express (FC0/1) 1.6 16V</b>	2001->	
K4M 706/K4M 752	70	95
Ignition Coil	<b>80203</b>	
<b>Kangoo Express (FC0/1) 1.6 16V 4x4</b>	2001->	
K4M 750/K4M 753/K4M 752	70	95
Ignition Coil	<b>80203</b>	
<b>Kangoo Express (FC0/1) 1.6 16V bivalent</b>	2005->	
K4M 850	60	82
Ignition Coil	<b>80203</b>	
Ignition Coil	<b>80222</b>	
Ignition Leads	<b>85994</b>	
<b>Kangoo Express (FW0/1) 1.6</b>	2008->	
K7M 750	64	87
Ignition Coil	<b>80222</b>	
<b>Kangoo Express (FW0/1) 1.6 16V</b>	2008->	
K4M 830	78	106
Ignition Coil	<b>80203</b>	
<b>Kangoo Express (FW0/1) 1.6 16V LPG</b>	2008->	
K4M 834	72	98
Ignition Coil	<b>80203</b>	
<b>Koleos (HY) 2,5</b>	2008->	
2TR 702/2TR 700/2TR 703	126	171
Ignition Coil	<b>80375</b>	

RENAULT Cont.		
<b>Koleos (HY) 2.5 4x4</b>	2008->	
2TR 702/2TR 700/2TR 703	126	171
Ignition Coil 2TR 700	<b>80375</b>	
<b>Laguna Coupe (DT0/1) 2.0 16V Turbo</b>	2008->	
F4Rt 811/F4R 811	125	170
Ignition Coil	<b>80203</b>	
<b>Laguna Coupe (DT0/1) 2.0 GT</b>	2008->	
F4R 800	150	204
Ignition Coil	<b>80203</b>	
<b>Laguna Coupe (DT0/1) 3.5 V6</b>	2008->	
V4Y 713	175	238
Ignition Coil	<b>80372</b>	
<b>Laguna I (B56, 556) 1,8</b>	1993-01	
F3P 720/F3P 724	66	90
Ignition Coil	<b>80232</b>	
Ignition Coil SAE	<b>80234</b>	
Ignition Coil 01.1994-02.2001	<b>80264</b>	
Ignition Leads ->05.1995	<b>85260</b>	
Ignition Leads 06.1995-02.1997	<b>85985</b>	
Ignition Leads 03.1997->	<b>86000</b>	
<b>Laguna I (B56, 556) 1,8</b>	1995-01	
F3P 678/F3P 670	66	90
Ignition Coil F3P 670; 04.1997->	<b>80232</b>	
Ignition Coil F3P 670; 04.1997->	<b>80234</b>	
Ignition Coil F3P 678	<b>80264</b>	
Ignition Leads F3P 670; 09.1995-03.1997	<b>85985</b>	
Ignition Leads F3P 670; 04.1997->	<b>86000</b>	
<b>Laguna I (B56, 556) 1,8</b>	1995-01	
F3P 720/F3P 724	69	94
Ignition Coil M4	<b>80232</b>	
Ignition Coil SAE	<b>80234</b>	
Ignition Coil ->02.2001	<b>80264</b>	
Ignition Leads ->02.1997	<b>85985</b>	
Ignition Leads 03.1997->	<b>86000</b>	
<b>Laguna I (B56, 556) 1.6 16V</b>	1997-01	
K4M 720/K4M 724	79	107
Ignition Coil 05.1998->	<b>80203</b>	
Ignition Leads	<b>85996</b>	
<b>Laguna I (B56, 556) 1.8</b>	1995-98	
F3P 676	70	95
Ignition Coil 05.1998->	<b>80232</b>	
Ignition Coil Engine 970402->	<b>80234</b>	
Ignition Coil	<b>80264</b>	
Ignition Leads	<b>85985</b>	
Ignition Leads 05.1998->	<b>86000</b>	
<b>Laguna I (B56, 556) 1.8</b>	1995-01	
F3P 674	69	94
Ignition Coil 04.1997->	<b>80232</b>	
Ignition Coil ->03.1997	<b>80234</b>	
Ignition Leads	<b>85985</b>	
Ignition Leads 04.1997->	<b>86000</b>	
<b>Laguna I (B56, 556) 1.8 16V</b>	1998-01	
F4P 770/F4P 760	88	120
Ignition Coil	<b>80203</b>	
<b>Laguna I (B56, 556) 2.0</b>	1999-01	
F3R 611	80	109
Ignition Coil M4; ->02.2001	<b>80232</b>	
Ignition Coil SAE	<b>80234</b>	
Ignition Leads SAE	<b>85985</b>	
Ignition Leads M4; ->02.2001	<b>86000</b>	
<b>Laguna I (B56, 556) 2.0</b>	1999-01	
F4R 780	102	139
Ignition Coil	<b>80203</b>	
<b>Laguna I (B56, 556) 2.0</b>	1995-01	
N7Q 700/N7Q 704	103	140
Ignition Coil 09.1995->; Cyl. 1-4	<b>80220</b>	
Ignition Coil 09.1995->; Cyl. 2-3	<b>80221</b>	
<b>Laguna I (B56, 556) 2.0</b>	1995-01	
F3R 722/F3R 768	84	114
Ignition Coil 04.1997->	<b>80232</b>	
Ignition Coil SAE; ->04.1997	<b>80234</b>	
Ignition Leads	<b>85985</b>	
Ignition Leads 04.1997->	<b>86000</b>	



RENAULT Cont.	
<b>Laguna I (B56, 556) 2.0</b>	<b>1993-01</b>
F3R 722/F3R 723	83 113
Ignition Coil M4	<b>80232</b>
Ignition Coil SAE	<b>80234</b>
Ignition Coil 01.1994-02.2001	<b>80264</b>
Ignition Leads ->04.1995	<b>85260</b>
Ignition Leads SAE	<b>85985</b>
Ignition Leads	<b>86000</b>
<b>Laguna I (B56, 556) 2.0</b>	<b>1993-01</b>
	70 95
Ignition Leads ->04.1997	<b>85985</b>
Ignition Leads 05.1997->	<b>86000</b>
<b>Laguna I (B56, 556) 2.0 16V</b>	<b>1999-01</b>
F4R 780	103 140
Ignition Coil	<b>80203</b>
<b>Laguna I (B56, 556) 2.0 16V</b>	<b>1995-01</b>
N7Q 700/N7Q 704	102 139
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil Cyl. 2-3; With regul.cat.(3way)	<b>80221</b>
Ignition Leads	<b>85485</b>
<b>Laguna I (B56, 556) 3.0</b>	<b>1993-01</b>
Z7X 765/Z7X 760	123 167
Ignition Coil Z7X 760,Z7X 765	<b>80234</b>
<b>Laguna I (B56, 556) 3.0 24V</b>	<b>1997-01</b>
L7X 700/L7X 701	140 190
Ignition Coil	<b>80374</b>
<b>Laguna I Grandtour (K56) 1,8</b>	<b>1995-01</b>
F3P 678/F3P 670	66 90
Ignition Coil 04.1997->	<b>80232</b>
Ignition Coil F3P 670; ->04.1997	<b>80234</b>
Ignition Coil F3P 670	<b>80264</b>
Ignition Leads F3P 670; ->03.1997	<b>85985</b>
Ignition Leads F3P 670; 04.1997-04.1997	<b>86000</b>
<b>Laguna I Grandtour (K56) 1,8</b>	<b>1995-01</b>
F3P 720/F3P 724	69 94
Ignition Coil F3P 724	<b>80232</b>
Ignition Coil SAE; 07.1996->	<b>80234</b>
Ignition Coil ->02.2001	<b>80264</b>
Ignition Leads SAE; 07.1996->	<b>85985</b>
Ignition Leads	<b>86000</b>
<b>Laguna I Grandtour (K56) 1.6 16V</b>	<b>1997-01</b>
K4M 720/K4M 724	79 107
Ignition Coil Without ignition distributor	<b>80203</b>
Ignition Leads	<b>85996</b>
<b>Laguna I Grandtour (K56) 1.8 16V</b>	<b>1998-01</b>
F4P 760	88 120
Ignition Coil	<b>80203</b>
<b>Laguna I Grandtour (K56) 2.0</b>	<b>1998-01</b>
F3R 728/F3R 768	84 114
Ignition Coil	<b>80232</b>
Ignition Coil SAE	<b>80234</b>
Ignition Leads	<b>85985</b>
Ignition Leads	<b>86000</b>
<b>Laguna I Grandtour (K56) 2.0</b>	<b>1995-01</b>
F3R 722/F3R 723	83 113
Ignition Coil	<b>80232</b>
Ignition Coil SAE	<b>80234</b>
Ignition Coil 01.1996-02.2001	<b>80264</b>
Ignition Leads SAE	<b>85985</b>
Ignition Leads	<b>86000</b>
<b>Laguna I Grandtour (K56) 2.0 16V</b>	<b>1999-01</b>
F4R 780	103 140
Ignition Coil	<b>80203</b>
<b>Laguna I Grandtour (K56) 2.0 16V</b>	<b>1995-01</b>
N7Q 700/N7Q 704	102 139
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil Cyl. 2-3; With regul.cat.(3way)	<b>80221</b>
<b>Laguna I Grandtour (K56) 3.0</b>	<b>1996-01</b>
Z7X 765	123 167
Ignition Coil Z7X 765	<b>80234</b>
<b>Laguna I Grandtour (K56) 3.0 24V</b>	<b>1997-01</b>
L7X 700/L7X 701	140 190
Ignition Coil	<b>80374</b>
<b>Laguna II (BG0/1) 1.6 16V</b>	<b>2001-&gt;</b>
K4M 714/K4M 710	79 107
Ignition Coil ->09.2007	<b>80203</b>
<b>Laguna II (BG0/1) 1.6 16V</b>	<b>2005-&gt;</b>
K4M 716	82 112
Ignition Coil ->09.2007; Intake manifold injection	<b>80203</b>

RENAULT Cont.	
<b>Laguna II (BG0/1) 1.8 16V</b>	<b>2001-&gt;</b>
F4P 772/F4P 770	89 121
Ignition Coil ->09.2007	<b>80203</b>
<b>Laguna II (BG0/1) 1.8 16V</b>	<b>2001-&gt;</b>
F4P 770/F4P 773	88 120
Ignition Coil ->09.2007	<b>80203</b>
<b>Laguna II (BG0/1) 1.8 16V</b>	<b>2001-&gt;</b>
F4P 774/F4P 770/F4P 773/F4P 771/F4P 775	85 116
Ignition Coil ->09.2007	<b>80203</b>
<b>Laguna II (BG0/1) 1.8 16V</b>	<b>2001-&gt;</b>
F4P 774/F4P 770	86 117
Ignition Coil	<b>80203</b>
<b>Laguna II (BG0/1) 2.0 16V</b>	<b>2002-&gt;</b>
F4R 713/F4R 715/F4R 712/F4R 714	99 135
Ignition Coil ->09.2007; Intake manifold injection	<b>80203</b>
<b>Laguna II (BG0/1) 2.0 16V</b>	<b>2005-&gt;</b>
F4R 787/F4R 786/F4R 784	125 170
Ignition Coil	<b>80203</b>
<b>Laguna II (BG0/1) 2.0 16V</b>	<b>2005-&gt;</b>
F4R 887/F4R 886	150 204
Ignition Coil ->09.2007; Intake manifold injection	<b>80203</b>
<b>Laguna II (BG0/1) 2.0 16V</b>	<b>2002-&gt;</b>
F4R 714	98 133
Ignition Coil ->09.2007	<b>80203</b>
<b>Laguna II (BG0/1) 2.0 16V IDE</b>	<b>2001-&gt;</b>
F5R 701/F5R 700	103 140
Ignition Coil	<b>80203</b>
Ignition Coil	<b>80373</b>
<b>Laguna II (BG0/1) 2.0 16V Turbo</b>	<b>2003-&gt;</b>
F4R 764/F4R 787/F4R 786/F4R 765	120 163
Ignition Coil ->09.2007; Intake manifold injection	<b>80203</b>
<b>Laguna II (BG0/1) 3.0 V6 24V</b>	<b>2001-&gt;</b>
L7X 731	152 207
Ignition Coil	<b>80309</b>
<b>Laguna II Grandtour (KG0/1) 1.6 16V</b>	<b>2001-&gt;</b>
K4M 714/K4M 710	79 107
Ignition Coil ->09.2007	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 1.6 16V</b>	<b>2005-&gt;</b>
K4M 716	82 112
Ignition Coil ->09.2007; Intake manifold injection	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 1.8 16V</b>	<b>2001-&gt;</b>
F4P 774/F4P 770	89 121
Ignition Coil ->09.2007	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 1.8 16V</b>	<b>2001-&gt;</b>
F4P 774/F4P 770/F4P 771/F4P 775	85 116
Ignition Coil ->09.2007	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 1.8 16V</b>	<b>2001-&gt;</b>
F4P 770/F4P 773	88 120
Ignition Coil ->09.2007	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 1.8 16V</b>	<b>2001-&gt;</b>
F4P 770	86 117
Ignition Coil	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 2.0 16V</b>	<b>2002-&gt;</b>
F4R 713/F4R 715/F4R 712/F4R 714	99 135
Ignition Coil ->09.2007; Intake manifold injection	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 2.0 16V</b>	<b>2005-&gt;</b>
F4R 787/F4R 786/F4R 784	125 170
Ignition Coil	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 2.0 16V</b>	<b>2005-&gt;</b>
F4R 887/F4R 886	150 204
Ignition Coil ->09.2007; Intake manifold injection	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 2.0 16V</b>	<b>2004-07</b>
F4R 715/F4R 714	98 133
Ignition Coil	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 2.0 16V IDE</b>	<b>2001-&gt;</b>
F5R 701/F5R 700	103 140
Ignition Coil	<b>80203</b>
Ignition Coil	<b>80373</b>
<b>Laguna II Grandtour (KG0/1) 2.0 16V Turbo</b>	<b>2003-&gt;</b>
F4R 764/F4R 787/F4R 786/F4R 765	120 163
Ignition Coil ->09.2007; Intake manifold injection	<b>80203</b>
<b>Laguna II Grandtour (KG0/1) 3.0 V6 24V</b>	<b>2001-&gt;</b>
L7X 731	152 207
Ignition Coil	<b>80309</b>
<b>Laguna III (BT0/1) 1.6 16V</b>	<b>2007-&gt;</b>
K4M 824	81 110
Ignition Coil	<b>80203</b>



RENAULT Cont.	
Laguna III (BT0/1) 2.0 16V	2007->
M4R 704	103 140
Ignition Coil	80288
Ignition Coil	80330
Laguna III (BT0/1) 2.0 16V Hi-Flex	2007->
M4R 726	103 140
Ignition Coil	80288
Ignition Coil	80330
Laguna III (BT0/1) 2.0 16V Turbo	2007->
F4R 811	125 170
Ignition Coil	80203
Laguna III (BT0/1) 2.0 GT	2008->
F4R 800	150 204
Ignition Coil	80203
Laguna III (BT0/1) 3.5 V6	2008->
V4Y 713	175 238
Ignition Coil	80372
Laguna III Grandtour (KT0/1) 1.6 16V	2007->
K4M 824	81 110
Ignition Coil	80203
Laguna III Grandtour (KT0/1) 2.0 16V	2007->
M4R 704	103 140
Ignition Coil	80288
Ignition Coil	80330
Laguna III Grandtour (KT0/1) 2.0 16V Hi-Flex	2007->
M4R 704/M4R 726	103 140
Ignition Coil	80288
Ignition Coil	80330
Laguna III Grandtour (KT0/1) 2.0 16V Turbo	2007->
F4R 811	125 170
Ignition Coil	80203
Laguna III Grandtour (KT0/1) 2.0 GT	2008->
F4R 800	150 204
Ignition Coil	80203
Laguna III Grandtour (KT0/1) 3.5 V6	2008->
V4Y 713	175 238
Ignition Coil	80372
Latitude (L70) 2.0 16V	2011->
M4R 746	103 140
Ignition Coil	80330
Latitude (L70) 2.5 V6 (L702, L703, L704, L707)	2011->
2ZV 604	130 177
Ignition Coil	80372
Logan I (LS) 1.4	2004->
K7J 710	55 75
Ignition Coil	80222
Ignition Leads	85994
Logan I (LS) 1.6	2004->
K7M 710	64 87
Ignition Coil	80222
Ignition Leads	85994
Logan I (LS) 1.6	2007->
K4M 690	77 105
Ignition Coil	80203
Ignition Leads	85994
Logan I Combi (KS) 1.4	2007->
K7J 710	55 75
Ignition Coil	80222
Ignition Leads	85994
Logan I Combi (KS) 1.6	2007->
K7M 710	64 87
Ignition Coil	80222
Ignition Leads	85994
Logan I Combi (KS) 1.6	2007->
K4M 697	77 105
Ignition Coil	80203
Ignition Leads	85994
Master I Bus (T) 2.0	1985-89
J5R 728	60 82
Ignition Coil	80264
Master I Bus (T) 28-35 2.0	1980-86
829 731	59 80
Ignition Coil	80264
Master I Bus (T) 28-35 2.0	1986-98
J5R 718	58 79
Ignition Coil	80264
Master I Bus (T) 30 2,2	1980-98
J7T 782 /J7T 788	67 91
Ignition Coil	80264

RENAULT Cont.	
Master I Chassis (P) 28-35 2.0	1982-86
829 730	59 80
Ignition Coil	80264
Master I Chassis (P) 28-35 2.0	1986-98
J5R 728	58 79
Ignition Coil ->09.1997	80264
Master I Van (T) 28-35 2.0	1986-98
J5R 718	58 79
Ignition Coil	80264
Master I Van (T) 28-35 2.0	1980-86
829 731	59 80
Ignition Coil	80264
Master I Van (T) 30 2.2	1980-98
J7T 782 /J7T 788	67 91
Ignition Coil	80264
Megane CC (EZ0/1) 1.6 16V	2010->
K4M 858	81 110
Ignition Coil	80203
Megane CC (EZ0/1) 2.0 CVT	2010->
M4R 713/M4R 711	103 140
Ignition Coil	80330
Megane CC (EZ0/1) 2.0 TCe	2010->
F4R 870/F4R 872	132 180
Ignition Coil	80203
Megane I (BA0/1) 1.4 16V	1999-03
K4J 714/K4J 750	70 95
Ignition Coil ->10.2002	80203
Megane I (BA0/1) 1.4 e	1996-03
E7J 626/E7J 764	55 75
Ignition Coil	80203
Ignition Coil E7J 626; 03.1999-10.2002	80222
Ignition Coil E7J 764; ->02.1999	80264
Ignition Leads E7J 764; ->02.1999	83170
Ignition Leads E7J 626; 03.1999-10.2002	85994
Megane I (BA0/1) 1.4 Eco	1996-99
E7J 624	52 71
Ignition Coil	80264
Ignition Leads	83170
Megane I (BA0/1) 1.6 16V	1999-03
K4M 704/K4M 700/K4M 708/K4M 701	79 107
Ignition Coil ->10.2002	80203
Megane I (BA0/1) 1.6 e	1996-99
K7M 702/K7M 703/K7M 790	66 90
Ignition Coil 03.1997-07.1998; Cyl. 1-4	80204
Ignition Coil 03.1997-07.1998; Cyl. 2-3	80205
Ignition Coil Cyl. 1-4	80220
Ignition Coil Cyl. 2-3	80221
Ignition Coil 07.1998->	80222
Ignition Leads K7M 702, K7M 703; 07.1998->	85994
Ignition Leads ->03.1997	85995
Ignition Leads K7M 702, K7M 703; 04.1997-06.1998	85996
Megane I (BA0/1) 1.6 i	1996-99
K7M 720	55 75
Ignition Coil 03.1997-07.1998; With regul.cat.(3way); Cyl.1-4	80204
Ignition Coil 03.1997-07.1998; Cyl. 2-3	80205
Ignition Coil Cyl. 1-4	80220
Ignition Coil With regul.cat.(3way); Cyl. 2-3	80221
Ignition Coil 07.1998->	80222
Ignition Leads 07.1998->	85994
Ignition Leads ->03.1997	85995
Ignition Leads 04.1997-06.1998	85996
Megane I (BA0/1) 1.8 16V	2001-03
F4P 722/F4P 720	85 115
Ignition Coil ->10.2002; Intake manifold injection	80203
Megane I (BA0/1) 2.0 16V	1996-03
F7R 710/F7R 714	108 147
Ignition Coil	80203
Megane I (BA0/1) 2.0 i	1999-03
F3R 751/F3R 750	80 109
Ignition Coil M4	80232
Ignition Coil SAE	80234
Ignition Leads SAE	85985
Ignition Leads F3R 751; M4	86000



RENAULT Cont.		
<b>Megane I (BA0/1) 2.0 i</b>	<b>1996-03</b>	
F3R 751/F3R 750	84 114	
Ignition Coil 04.1997->	<b>80232</b>	
Ignition Coil ->04.1997	<b>80234</b>	
Ignition Leads ->03.1997	<b>85985</b>	
Ignition Leads ->03.1997	<b>85995</b>	
Ignition Leads 04.1997-02.1999	<b>86000</b>	
<b>Megane I Cabrio (EA0/1) 1.4 16V</b>	<b>1999-03</b>	
K4J 714/K4J 750	70 95	
Ignition Coil	<b>80203</b>	
<b>Megane I Cabrio (EA0/1) 1.6 16V</b>	<b>1999-03</b>	
K4M 700/K4M 708/K4M 701	79 107	
Ignition Coil	<b>80203</b>	
<b>Megane I Cabrio (EA0/1) 1.6 e</b>	<b>1996-99</b>	
K7M 702/K7M 703	66 90	
Ignition Coil 03.1997-07.1998; Cyl. 1-4; With regul.cat.(3way)	<b>80204</b>	
Ignition Coil 03.1997-07.1998; Cyl. 2-3	<b>80205</b>	
Ignition Coil Cyl. 1-4	<b>80220</b>	
Ignition Coil Cyl. 2-3; With regul.cat.(3way)	<b>80221</b>	
Ignition Coil 07.1998->	<b>80222</b>	
Ignition Leads 07.1998->	<b>85994</b>	
Ignition Leads ->03.1997	<b>85995</b>	
Ignition Leads 04.1997-06.1998	<b>85996</b>	
<b>Megane I Cabrio (EA0/1) 2.0</b>	<b>1997-03</b>	
F3R 798/F3R 750	84 114	
Ignition Coil	<b>80232</b>	
Ignition Coil SAE	<b>80234</b>	
Ignition Leads	<b>85985</b>	
Ignition Leads M4	<b>86000</b>	
<b>Megane I Cabrio (EA0/1) 2.0 16V</b>	<b>2002-03</b>	
F4R 746/F4R 770	102 139	
Ignition Coil F4R 770	<b>80203</b>	
<b>Megane I Cabrio (EA0/1) 2.0 16V IDE</b>	<b>1999-03</b>	
F5R 740	103 140	
Ignition Coil ->10.2000	<b>80222</b>	
Ignition Coil 10.2000->	<b>80373</b>	
<b>Megane I Cabrio (EA0/1) 2.0 i</b>	<b>1999-03</b>	
F3R 791/F3R 796	80 109	
Ignition Coil M4	<b>80232</b>	
Ignition Coil SAE	<b>80234</b>	
Ignition Leads SAE	<b>85985</b>	
Ignition Leads M4	<b>86000</b>	
<b>Megane I Classic (LA0/1) 1,4</b>	<b>1996-03</b>	
E7J 626/E7J 764	55 75	
Ignition Coil	<b>80203</b>	
Ignition Coil Saw tooth	<b>80222</b>	
Ignition Coil SAE	<b>80264</b>	
Ignition Leads E7J 764	<b>83170</b>	
Ignition Leads E7J 626; 02.1999->	<b>85994</b>	
<b>Megane I Classic (LA0/1) 1.4 16V</b>	<b>1999-03</b>	
K4J 714/K4J 750	70 95	
Ignition Coil Intake manifold injection	<b>80203</b>	
<b>Megane I Classic (LA0/1) 1.6 16V</b>	<b>1999-03</b>	
K4M 700/K4M 708/K4M 701	79 107	
Ignition Coil	<b>80203</b>	
<b>Megane I Classic (LA0/1) 1.6 e</b>	<b>1996-99</b>	
K7M 702/K7M 703/K7M 790	66 90	
Ignition Coil 03.1997-07.1998; Cyl. 1-4; With regul.cat.(3way)	<b>80204</b>	
Ignition Coil 03.1997-07.1998; Cyl. 2-3	<b>80205</b>	
Ignition Coil Cyl. 1-4	<b>80220</b>	
Ignition Coil Cyl. 2-3	<b>80221</b>	
Ignition Coil 07.1998->	<b>80222</b>	
Ignition Leads K7M 702, K7M 703; 07.1998->	<b>85994</b>	
Ignition Leads ->03.1997	<b>85995</b>	
Ignition Leads 04.1997-06.1998	<b>85996</b>	
<b>Megane I Classic (LA0/1) 1.6 i</b>	<b>1996-99</b>	
K7M 720	55 75	
Ignition Coil 03.1997-07.1998; Cyl. 1-4	<b>80204</b>	
Ignition Coil 03.1997-07.1998; Cyl. 2-3	<b>80205</b>	
Ignition Coil Cyl. 1-4	<b>80220</b>	
Ignition Coil Cyl. 2-3	<b>80221</b>	
Ignition Coil 07.1998->	<b>80222</b>	
Ignition Leads 07.1998->	<b>85994</b>	
Ignition Leads ->03.1997	<b>85995</b>	
Ignition Leads 04.1997-06.1998	<b>85996</b>	
<b>Megane I Classic (LA0/1) 1.8 16V</b>	<b>2001-03</b>	
F4P 722/F4P 720	85 115	
Ignition Coil Intake manifold injection	<b>80203</b>	

RENAULT Cont.		
<b>Megane I Classic (LA0/1) 2.0 i</b>	<b>1999-03</b>	
F3R 791/F3R 751/F3R 797/F3R 798/F3R 796/F3R 752/F3R 750	80 109	
Ignition Coil M4	<b>80232</b>	
Ignition Coil SAE	<b>80234</b>	
Ignition Leads SAE	<b>85985</b>	
Ignition Leads M4	<b>86000</b>	
<b>Megane I Classic (LA0/1) 2.0 i</b>	<b>1996-03</b>	
F3R 791/F3R 751/F3R 797/F3R 798/F3R 796/F3R 752/F3R 750	84 114	
Ignition Coil F3R 751,F3R 750; 04.1997->	<b>80232</b>	
Ignition Coil F3R 751,F3R 750; 04.1997->	<b>80234</b>	
Ignition Leads ->03.1997	<b>85985</b>	
Ignition Leads 04.1997->	<b>86000</b>	
<b>Megane I Coach (DA0/1) 1.4 16V</b>	<b>1999-03</b>	
K4J 714/K4J 750	70 95	
Ignition Coil ->10.2002	<b>80203</b>	
<b>Megane I Coach (DA0/1) 1.6 16V</b>	<b>1999-03</b>	
K4M 700/K4M 708/K4M 701	79 107	
Ignition Coil ->10.2002	<b>80203</b>	
<b>Megane I Coach (DA0/1) 1.6 e</b>	<b>1996-99</b>	
K7M 702/K7M 703	66 90	
Ignition Coil 03.1997-07.1998; Cyl. 1-4	<b>80204</b>	
Ignition Coil 03.1997-07.1998; Cyl. 2-3	<b>80205</b>	
Ignition Coil Cyl. 1-4	<b>80220</b>	
Ignition Coil Cyl. 2-3	<b>80221</b>	
Ignition Coil 07.1998->	<b>80222</b>	
Ignition Leads 07.1998->	<b>85994</b>	
Ignition Leads ->03.1997	<b>85995</b>	
Ignition Leads 04.1997-06.1998	<b>85996</b>	
<b>Megane I Coach (DA0/1) 2.0 16V</b>	<b>2002-03</b>	
F4R 746	102 139	
Ignition Coil ->10.2002	<b>80203</b>	
<b>Megane I Coach (DA0/1) 2.0 16V</b>	<b>1996-99</b>	
F7R 710/F7R 714	108 147	
Ignition Leads 03.1997->	<b>85985</b>	
Ignition Leads ->02.1997	<b>86000</b>	
<b>Megane I Coach (DA0/1) 2.0 16V IDE</b>	<b>1999-03</b>	
F5R 740	103 140	
Ignition Coil ->10.2000	<b>80222</b>	
Ignition Coil 10.2000->	<b>80373</b>	
Ignition Leads	<b>85985</b>	
Ignition Leads	<b>86000</b>	
<b>Megane I Coach (DA0/1) 2.0 i</b>	<b>1999-03</b>	
F3R 791/F3R 796	80 109	
Ignition Coil M4	<b>80232</b>	
Ignition Coil SAE	<b>80234</b>	
Ignition Leads SAE	<b>85985</b>	
Ignition Leads SAE/ Saw tooth	<b>86000</b>	
<b>Megane I Coach (DA0/1) 2.0 i</b>	<b>1996-03</b>	
F3R 751/F3R 798/F3R 750	84 114	
Ignition Coil F3R 751,F3R 750; 04.1997->	<b>80232</b>	
Ignition Coil F3R 751,F3R 750; ->04.1997	<b>80234</b>	
Ignition Leads ->03.1997	<b>85985</b>	
Ignition Leads	<b>86000</b>	
<b>Megane I Grandtour (KA0/1) 1.4 16V</b>	<b>1999-03</b>	
K4J 714/K4J 750	70 95	
Ignition Coil	<b>80203</b>	
<b>Megane I Grandtour (KA0/1) 1.4 e</b>	<b>1999-03</b>	
E7J 626	55 75	
Ignition Coil	<b>80203</b>	
Ignition Coil	<b>80222</b>	
Ignition Leads E7J 626	<b>85990</b>	
Ignition Leads	<b>85994</b>	
<b>Megane I Grandtour (KA0/1) 1.6 16V</b>	<b>1999-03</b>	
K4M 704/K4M 700/K4M 708/K4M 701	79 107	
Ignition Coil	<b>80203</b>	
<b>Megane I Grandtour (KA0/1) 1.6 e</b>	<b>1999-03</b>	
K7M 702/K7M 703	66 90	
Ignition Coil	<b>80222</b>	
Ignition Leads K7M 702	<b>85994</b>	
Ignition Leads	<b>85996</b>	
<b>Megane I Grandtour (KA0/1) 1.8 16V</b>	<b>2001-03</b>	
F4P 722/F4P 720	85 115	
Ignition Coil	<b>80203</b>	
<b>Megane II (BM0/1, CM0/1) 1.4 16V</b>	<b>2002-08</b>	
K4J 740/K4J 730	72 98	
Ignition Coil K4J 730	<b>80203</b>	
<b>Megane II (BM0/1, CM0/1) 1.4 16V</b>	<b>2003-08</b>	
K4J 732	60 82	
Ignition Coil	<b>80203</b>	





RENAULT Cont.	
<b>Megane II (BM0/1, CM0/1) 1.6</b>	2005->
K4M 788	77 105
Ignition Coil 10.2005->	<b>80203</b>
<b>Megane II (BM0/1, CM0/1) 1.6 16V</b>	2002-08
K4M 760	83 113
Ignition Coil	<b>80203</b>
<b>Megane II (BM0/1, CM0/1) 1.6 16V</b>	2006-08
K4M 812/K4M 760/K4M 813	82 112
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II (BM0/1, CM0/1) 1.6 Flex-Fuel</b>	2007-08
K4M 788	77 105
Ignition Coil	<b>80203</b>
<b>Megane II (BM0/1, CM0/1) 2.0</b>	2006-08
F4R 774	169 230
Ignition Coil	<b>80203</b>
<b>Megane II (BM0/1, CM0/1) 2.0 16V</b>	2002-08
F4R 770	99 135
Ignition Coil	<b>80203</b>
<b>Megane II (BM0/1, CM0/1) 2.0 16V Turbo</b>	2004-08
F4R 776	120 163
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II (BM0/1, CM0/1) 2.0 Renault Sport</b>	2004-09
F4R 774/F4Rt 774	165 224
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II Coupé-Cabrio (EM0/1) 1.6</b>	2003-09
K4M 760/K4M 761	83 113
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II Coupé-Cabrio (EM0/1) 1.6 16V</b>	2006-08
K4M 812/K4M 760/K4M 761/K4M 813	82 112
Ignition Coil	<b>80203</b>
<b>Megane II Coupé-Cabrio (EM0/1) 2.0</b>	2003-09
F4R 771/F4R 770	99 135
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II Coupé-Cabrio (EM0/1) 2.0 16V Turbo</b>	2004-09
F4R 776	120 163
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II Grandtour (KM0/1) 1.4</b>	2003-09
K4J 740/K4J 730	72 98
Ignition Coil K4J 730; Intake manifold injection	<b>80203</b>
<b>Megane II Grandtour (KM0/1) 1.6</b>	2003-09
K4M 760/K4M 761	83 113
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II Grandtour (KM0/1) 1.6 16V</b>	2006-09
K4M 812/K4M 760/K4M 761/K4M 813	82 112
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II Grandtour (KM0/1) 1.6 16V Hi-Flex</b>	2008->
K4M 856	77 105
Ignition Coil ->05.2009	<b>80203</b>
<b>Megane II Grandtour (KM0/1) 2.0</b>	2003-09
F4R 771/F4R 770	99 135
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II Sedan (LM0/1) 1.4</b>	2003->
K4J 732	60 82
Ignition Coil	<b>80203</b>
<b>Megane II Sedan (LM0/1) 1.4</b>	2003->
K4J 740/K4J 730	72 98
Ignition Coil K4J 730; 10.2003->; Intake manifold injection	<b>80203</b>
<b>Megane II Sedan (LM0/1) 1.6</b>	2003->
K4M 760/K4M 761	83 113
Ignition Coil 10.2003->; Intake manifold injection	<b>80203</b>
<b>Megane II Sedan (LM0/1) 1.6</b>	2005->
K4M 762	77 105
Ignition Coil K4M.7.64	<b>80203</b>
<b>Megane II Sedan (LM0/1) 1.6 16V</b>	2006->
K4M 812/K4M 813	82 112
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane II Sedan (LM0/1) 2.0</b>	2003->
F4R 771/F4R 770	99 135
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Megane III Coupe (DZ0/1) 1.6 16V</b>	2008->
K4M 848	74 101
Ignition Coil	<b>80203</b>
<b>Megane III Coupe (DZ0/1) 1.6 16V</b>	2008->
K4M 858	81 110
Ignition Coil	<b>80203</b>
<b>Megane III Coupe (DZ0/1) 1.6 16V Bifuel</b>	2008->
K4M 866	81 110
Ignition Coil	<b>80203</b>

RENAULT Cont.	
<b>Megane III Coupe (DZ0/1) 2.0 CVT</b>	2009->
M4R 711	103 140
Ignition Coil	<b>80330</b>
<b>Megane III Coupe (DZ0/1) 2.0 R.S.</b>	2008->
F4R 874	195 265
Ignition Coil	<b>80203</b>
<b>Megane III Coupe (DZ0/1) 2.0 TCe</b>	2008->
F4R 870	132 180
Ignition Coil	<b>80203</b>
<b>Megane III Coupe (DZ0/1) 2.0 TCe</b>	2009->
F4R 874	184 250
Ignition Coil	<b>80203</b>
<b>Megane III Coupe (DZ0/1) 2.0 TCe</b>	2012->
	140 190
Ignition Coil	<b>80203</b>
<b>Megane III Coupe (DZ0/1) 2.0 TCe 220</b>	2013->
	162 220
Ignition Coil	<b>80203</b>
<b>Megane III Fastback (BZ0) 1.6 16V</b>	2008->
	82 111
Ignition Coil 11.2011->	<b>80203</b>
<b>Megane III Fastback (BZ0) 1.6 16V</b>	2008->
K4M 848	74 101
Ignition Coil	<b>80203</b>
<b>Megane III Fastback (BZ0) 1.6 16V</b>	2008->
K4M 858	81 110
Ignition Coil	<b>80203</b>
<b>Megane III Fastback (BZ0) 1.6 16V Bifuel</b>	2008->
K4M 866	81 110
Ignition Coil	<b>80203</b>
<b>Megane III Fastback (BZ0) 2.0</b>	2011->
M4R 710/M4R 714	105 143
Ignition Coil	<b>80330</b>
<b>Megane III Fastback (BZ0) 2.0 CVT</b>	2009->
M4R 713/M4R 711	103 140
Ignition Coil	<b>80330</b>
<b>Megane III Fastback (BZ0) 2.0 TCe</b>	2008->
F4R 870	132 180
Ignition Coil	<b>80203</b>
<b>Megane III Fastback (BZ0) 2.0 TCe</b>	2012->
	140 190
Ignition Coil	<b>80203</b>
<b>Megane III Fastback (BZ0) 2.0 TCe 220</b>	2013->
	162 220
Ignition Coil	<b>80203</b>
<b>Megane III Grandtour (KZ0/1) 1.6 16V</b>	2009->
K4M 848	74 101
Ignition Coil	<b>80203</b>
<b>Megane III Grandtour (KZ0/1) 1.6 16V</b>	2009->
K4M 858	81 110
Ignition Coil	<b>80203</b>
<b>Megane III Grandtour (KZ0/1) 1.6 16V Bifuel</b>	2008->
K4M 866	81 110
Ignition Coil	<b>80203</b>
<b>Megane III Grandtour (KZ0/1) 2.0 CVT</b>	2009->
M4R 713/M4R 711/M4R F 713	103 140
Ignition Coil	<b>80330</b>
<b>Megane III Grandtour (KZ0/1) 2.0 TCe</b>	2008->
F4R 870/F4R 872	132 180
Ignition Coil	<b>80203</b>
<b>Megane III Grandtour (KZ0/1) 2.0 TCe</b>	2012->
	162 220
Ignition Coil	<b>80203</b>
<b>Megane III Grandtour (KZ0/1) 2.0 TCe</b>	2012->
	140 190
Ignition Coil	<b>80203</b>
<b>Megane Scenic (JA0/1) 1.4 i</b>	1997-99
E7J 764	55 75
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83170</b>
<b>Megane Scenic (JA0/1) 1.6 16V</b>	1998-99
K4M 704/K4M 700/K4M 708/K4M 701	79 107
Ignition Coil	<b>80203</b>





RENAULT Cont.		
<b>Megane Scenic (JA0/1) 1.6 e</b>		
K7M 702/K7M 703		1996-99 66 90
Ignition Coil	03.1997-07.1998; Cyl. 1-4	<b>80204</b>
Ignition Coil	03.1997-07.1998; Cyl. 2-3	<b>80205</b>
Ignition Coil	Cyl. 1-4	<b>80220</b>
Ignition Coil	Cyl. 2-3	<b>80221</b>
Ignition Coil	07.1998->	<b>80222</b>
Ignition Leads	07.1998->	<b>85994</b>
Ignition Leads	->03.1997	<b>85995</b>
Ignition Leads	04.1997-06.1998	<b>85996</b>
<b>Megane Scenic (JA0/1) 1.6 i</b>		
K7M 720		1997-99 55 75
Ignition Coil	03.1997-07.1998; Cyl. 1-4	<b>80204</b>
Ignition Coil	03.1997-07.1998; Cyl. 2-3	<b>80205</b>
Ignition Coil	Cyl. 1-4	<b>80220</b>
Ignition Coil	Cyl. 2-3	<b>80221</b>
Ignition Coil	07.1998->	<b>80222</b>
Ignition Leads	07.1998->	<b>85994</b>
Ignition Leads	->03.1997	<b>85995</b>
Ignition Leads	04.1997-06.1998	<b>85996</b>
<b>Megane Scenic (JA0/1) 2.0 i</b>		
F3R 791/F3R 796		1999-99 80 109
Ignition Coil	03.1999->; With regul.cat.(3way)	<b>80232</b>
Ignition Coil	SAE	<b>80234</b>
Ignition Leads	SAE	<b>85985</b>
Ignition Leads	SAE/ Saw tooth	<b>86000</b>
<b>Megane Scenic (JA0/1) 2.0 i</b>		
F3R 751/F3R 750		1997-99 84 114
Ignition Coil	F3R 751,F3R 750; 04.1997->	<b>80232</b>
Ignition Coil	F3R 751,F3R 750; ->04.1997	<b>80234</b>
Ignition Leads	->03.1997	<b>85985</b>
Ignition Leads		<b>86000</b>
<b>Modus / Grand Modus (F/JPO) 1,2</b>		
D4F 740		2004-> 55 75
Ignition Coil	D4F 740	<b>80225</b>
Ignition Coil	Without ignition lead	<b>80287</b>
Ignition Leads		<b>85988</b>
<b>Modus / Grand Modus (F/JPO) 1,2</b>		
D4F 740		2005-> 48 65
Ignition Coil		<b>80225</b>
Ignition Coil	Without ignition lead	<b>80287</b>
Ignition Leads		<b>85988</b>
<b>Modus / Grand Modus (F/JPO) 1,2</b>		
D4F 764		2004-> 58 78
Ignition Coil		<b>80222</b>
Ignition Coil		<b>80225</b>
Ignition Coil	Without ignition lead	<b>80287</b>
Ignition Leads		<b>85988</b>
<b>Modus / Grand Modus (F/JPO) 1,4</b>		
K4J 780/K4J 770		2004-> 72 98
Ignition Coil	->12.2006; Intake manifold injection	<b>80203</b>
<b>Modus / Grand Modus (F/JPO) 1,6</b>		
K4M 794		2004-> 65 88
Ignition Coil	->12.2006; Intake manifold injection	<b>80203</b>
<b>Modus / Grand Modus (F/JPO) 1,6</b>		
K4M 790/K4M 800/K4M 801/K4M 791		2004-> 82 112
Ignition Coil	SAE; Intake manifold injection	<b>80203</b>
Ignition Coil		<b>80222</b>
<b>Modus / Grand Modus (F/JPO) 1.2</b>		
D4F 786		2011-> 76 103
Ignition Coil		<b>80222</b>
Ignition Leads		<b>85988</b>
<b>Modus / Grand Modus (F/JPO) 1.2 16V</b>		
D4F 784		2007-> 74 101
Ignition Coil		<b>80222</b>
Ignition Leads		<b>85988</b>
Ignition Leads		<b>85991</b>
<b>Modus / Grand Modus (F/JPO) 1.2 16V Hi-Flex</b>		
D4F 740		2008-> 55 75
Ignition Coil		<b>80225</b>
Ignition Coil	Without ignition lead	<b>80287</b>
Ignition Leads		<b>85988</b>
<b>Safrane I (B54) 2,2</b>		
J7T 762		1992-96 79 107
Ignition Coil		<b>80264</b>
Ignition Leads	->12.1994	<b>85220</b>

RENAULT Cont.		
<b>Safrane I (B54) 2,2</b>		
J7T 760/J7T 761		1992-96 101 137
Ignition Coil		<b>80264</b>
Ignition Leads	->12.1994	<b>85220</b>
<b>Safrane I (B54) 2.0</b>		
J7R 732/J7R 733		1992-96 77 105
Ignition Leads	->12.1994	<b>85220</b>
<b>Safrane I (B54) 2.0 12V</b>		
J7R 735/J7R 734		1992-96 97 132
Ignition Coil		<b>80264</b>
<b>Safrane I (B54) 3.0 Biturbo 4x4</b>		
Z7X 726		1993-96 193 262
Ignition Coil		<b>80264</b>
<b>Safrane I (B54) 3.0 V6</b>		
Z7X 721/Z7X 723/Z7X 753/Z7X 722		1992-96 123 167
Ignition Coil		<b>80264</b>
<b>Safrane I (B54) 3.0 V6 4x4</b>		
Z7X 721/Z7X 723/Z7X 722		1992-96 123 167
Ignition Coil		<b>80264</b>
<b>Safrane II (B54) 2.0 16V</b>		
N7Q 710/N7Q 711		1996-00 100 136
Ignition Coil	Cyl. 1-4	<b>80220</b>
Ignition Coil	With regul.cat.(3way); Cyl. 2-3	<b>80221</b>
Ignition Leads		<b>85485</b>
<b>Safrane II (B54) 2.5 20V</b>		
N7U 700/N7U 701		1996-00 121 165
Ignition Coil		<b>80303</b>
<b>Safrane II (B54) 2.9 24V</b>		
L7X 713		1999-00 140 190
Ignition Coil		<b>80374</b>
<b>Safrane II (B54) 3.0 V6</b>		
Z7X 755		1996-00 123 167
Ignition Coil		<b>80264</b>
<b>Scénic I (JA0/1) 1.4 16V</b>		
K4J 714/K4J 750		1999-03 70 95
Ignition Coil	->04.2003	<b>80203</b>
<b>Scénic I (JA0/1) 1.6</b>		
K4M 708/K4M 709		2001-03 75 102
Ignition Coil		<b>80203</b>
<b>Scénic I (JA0/1) 1.6</b>		
K4M 706/K4M 700		1999-03 79 107
Ignition Coil	->04.2003	<b>80203</b>
<b>Scénic I (JA0/1) 1.8 16V</b>		
F4P 722/F4P 720		2001-03 85 115
Ignition Coil	->04.2003; Intake manifold injection	<b>80203</b>
<b>Scénic I (JA0/1) 2.0 16V</b>		
F4R 741/F4R 740/F4R 744/F4R 747		1999-03 103 140
Ignition Coil	11.2000-04.2003	<b>80203</b>
<b>Scénic I (JA0/1) 2.0 16V</b>		
F4R 741/F4R 740/F4R 746		2000-03 102 139
Ignition Coil	F4R 740/F4R 741; ->04.2003	<b>80203</b>
<b>Scénic I (JA0/1) 2.0 16V RX4</b>		
F4R 746/F4R 744		2000-03 102 139
Ignition Coil	F4R 744; ->04.2003	<b>80203</b>
<b>Scénic II (JM0/1) 1,4</b>		
K4J 740/K4J 730/K4J 770		2003-> 72 98
Ignition Coil	K4J 730; Intake manifold injection	<b>80203</b>
<b>Scénic II (JM0/1) 1,6</b>		
K4M 761/K4M 782		2003-> 83 113
Ignition Coil	Intake manifold injection	<b>80203</b>
<b>Scénic II (JM0/1) 1.6 16V</b>		
K4M 812/K4M 766/K4M 706/K4M 813		2005-> 82 112
Ignition Coil	Intake manifold injection	<b>80203</b>
<b>Scénic II (JM0/1) 2.0</b>		
F4R 771/F4R 770		2003-> 99 135
Ignition Coil	Intake manifold injection	<b>80203</b>
<b>Scénic II (JM0/1) 2.0 16V Turbo</b>		
F4R 776		2004-> 120 163
Ignition Coil	Intake manifold injection	<b>80203</b>
<b>Scénic III (JZ0/1) 1.6 16V</b>		
K4M 858/K4M R 858		2009-> 81 110
Ignition Coil		<b>80203</b>
<b>Scénic III (JZ0/1) 1.6 E85</b>		
K4M 866		2009-> 81 110
Ignition Coil		<b>80203</b>
<b>Scénic III (JZ0/1) 2.0 16V</b>		
M4R 713/M4R 711/M4R 710		2009-> 103 140
Ignition Coil	M4R 710/M4R 711	<b>80330</b>



RENAULT Cont.	
<b>Super 5 (B/C40) 1,1</b>	<b>1986-95</b>
C1E 752/C1E 750/C1E 756/C1E 760	33 45
Ignition Leads	<b>83210</b>
<b>Super 5 (B/C40) 1,1</b>	<b>1984-88</b>
C1E 752/C1E 750/C1E 754	34 46
Ignition Leads C1E 750	<b>83210</b>
<b>Super 5 (B/C40) 1,2</b>	<b>1987-90</b>
C1G 722/C1G 702/C1G 720	40 55
Ignition Leads	<b>83210</b>
<b>Super 5 (B/C40) 1,4</b>	<b>1984-88</b>
C1J 780/C1J 768	43 59
Ignition Coil	<b>80264</b>
Ignition Leads C1J 768	<b>83220</b>
<b>Super 5 (B/C40) 1,4</b>	<b>1984-89</b>
C2J 789/C2J 700/C2J 780/C2J 781/C2J 788/C2J 798	52 71
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83220</b>
<b>Super 5 (B/C40) 1,4</b>	<b>1987-90</b>
C2J 784	44 60
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83220</b>
<b>Super 5 (B/C40) 1,4</b>	<b>1987-89</b>
C2J 782	49 67
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83220</b>
<b>Super 5 (B/C40) 1,7</b>	<b>1987-95</b>
F2N 742/F2N 740	64 87
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>Super 5 (B/C40) 1,7</b>	<b>1986-95</b>
F3N 716 /F3N 717	54 73
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>Super 5 (B/C40) 1.0</b>	<b>1984-88</b>
C1C 700	30 41
Ignition Leads	<b>83210</b>
<b>Super 5 (B/C40) 1.4 KAT</b>	<b>1985-96</b>
C3J 700/C3J 702/C3J 760	43 58
Ignition Coil	<b>80264</b>
Ignition Leads C3J 700	<b>83210</b>
Ignition Leads	<b>83220</b>
<b>Super 5 (B/C40) 1.4 Turbo</b>	<b>1985-90</b>
C1J 784/C1J 782/C1J 788	88 120
Ignition Coil	<b>80264</b>
Ignition Leads C1J 782	<b>83220</b>
<b>Super 5 (B/C40) 1.7 i</b>	<b>1986-91</b>
F3N 722/F3N 702	69 94
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83230</b>
<b>Thalia I (LB0/1/2) 1.2</b>	<b>1998-03</b>
D7F 744/D7F 746	43 58
Ignition Coil	<b>80373</b>
<b>Thalia I (LB0/1/2) 1.2 16V</b>	<b>2002-&gt;</b>
D4F 706/D4F 712	55 75
Ignition Coil	<b>80206</b>
Ignition Coil	<b>80225</b>
Ignition Coil	<b>80287</b>
Ignition Leads	<b>85988</b>
<b>Thalia I (LB0/1/2) 1.4</b>	<b>2000-&gt;</b>
K7J 700	55 75
Ignition Coil	<b>80222</b>
Ignition Leads	<b>85994</b>
<b>Thalia I (LB0/1/2) 1.4 16V</b>	<b>2000-&gt;</b>
K4J 712	72 98
Ignition Coil	<b>80203</b>
<b>Traffic (T1, T3, T4) 1.4</b>	<b>1980-89</b>
847 701/847 700/C1J 700	35 48
Ignition Leads 847 700	<b>83210</b>
<b>Traffic (T1, T3, T4) 1.7</b>	<b>1986-89</b>
F1N 724	50 68
Ignition Coil	<b>80264</b>
<b>Traffic (T1, T3, T4) 2.0</b>	<b>1986-89</b>
J5R 722/J5R 716/J5R 726	59 80
Ignition Coil	<b>80264</b>
<b>Traffic (T1, T3, T4) 2.0</b>	<b>1985-89</b>
J5R 716	60 82
Ignition Coil	<b>80264</b>

RENAULT Cont.	
<b>Traffic (T1, T3, T4) 2.0 4x4</b>	<b>1986-89</b>
J5R 722/J5R 716/J5R 726	59 80
Ignition Coil	<b>80264</b>
<b>Traffic (TXX) 1.4</b>	<b>1989-91</b>
C1J 700	35 48
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83210</b>
<b>Traffic (TXX) 1.7</b>	<b>1992-94</b>
F1N 720	50 68
Ignition Coil	<b>80264</b>
<b>Traffic (TXX) 2.0</b>	<b>1989-90</b>
J5R 716	59 80
Ignition Coil	<b>80264</b>
<b>Traffic (TXX) 2.2</b>	<b>1989-94</b>
J7T 780	70 95
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Traffic (TXX) 2.2</b>	<b>1994-97</b>
J7T 600	74 101
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Traffic (TXX) 2.2 4x4</b>	<b>1994-97</b>
J7T 600	74 101
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Traffic (TXX) 2.2 4x4</b>	<b>1989-94</b>
J7T 780	70 95
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Traffic Bus (T5, T6, T7) 1.4</b>	<b>1980-89</b>
847 701/847 700/C1J 700	35 48
Ignition Leads 847 700	<b>83210</b>
<b>Traffic Bus (T5, T6, T7) 1.7</b>	<b>1986-89</b>
F1N 724	50 68
Ignition Coil	<b>80264</b>
<b>Traffic Bus (T5, T6, T7) 2.0</b>	<b>1986-89</b>
J5R 722/J5R 716/J5R 726	59 80
Ignition Coil	<b>80264</b>
<b>Traffic Bus (T5, T6, T7) 2.0 4x4</b>	<b>1986-89</b>
J5R 722/J5R 716/J5R 726	59 80
Ignition Coil	<b>80264</b>
<b>Traffic Bus (TXW) 1.7</b>	<b>1992-94</b>
F1N 724	50 68
Ignition Coil	<b>80264</b>
<b>Traffic Bus (TXW) 2.0</b>	<b>1989-90</b>
J5R 726	59 80
Ignition Coil	<b>80264</b>
<b>Traffic Bus (TXW) 2.2</b>	<b>1989-94</b>
J7T 780	70 95
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Traffic Bus (TXW) 2.2</b>	<b>1994-97</b>
J7T 600	74 101
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Traffic Bus (TXW) 2.2 4x4</b>	<b>1989-94</b>
J7T 780	70 95
Ignition Leads	<b>83160</b>
<b>Traffic Bus (TXW) 2.2 4x4</b>	<b>1994-97</b>
J7T 600	74 101
Ignition Leads	<b>83160</b>
<b>Traffic Chassis (P6) 1.4</b>	<b>1980-89</b>
847 700/C1J 700	35 48
Ignition Coil	<b>80264</b>
Ignition Leads 847 700	<b>83210</b>
<b>Traffic Chassis (P6) 1.7</b>	<b>1986-89</b>
F1N 722	50 68
Ignition Coil	<b>80264</b>
<b>Traffic Chassis (P6) 2.0</b>	<b>1980-89</b>
J5R 726	59 80
Ignition Coil	<b>80264</b>
<b>Traffic Chassis (P6) 2.0</b>	<b>1980-86</b>
829 721/829 720	63 86
Ignition Coil	<b>80264</b>
<b>Traffic Chassis (PXX) 1.7</b>	<b>1989-94</b>
F1N 722	50 68
Ignition Coil	<b>80264</b>



RENAULT Cont.	
<b>Trafic Chassis (PXX) 2.0 [RWD]</b>	<b>1989-97</b>
J5R 726	59 80
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83160</b>
<b>Trafic Chassis (PXX) 2.2</b>	<b>1994-98</b>
J7T 600	74 101
Ignition Leads	<b>83160</b>
<b>Trafic Chassis (PXX) 2.2</b>	<b>1989-94</b>
J7T 780	70 95
Ignition Coil	<b>80264</b>
<b>Trafic Chassis (PXX) 2.2 4x4</b>	<b>1994-98</b>
J7T 600	74 101
Ignition Leads	<b>83160</b>
<b>Trafic II Bus (JL) 2.0</b>	<b>2001-&gt;</b>
F4R 722/F4R 720	88 120
Ignition Coil 06.2001-12.2006	<b>80203</b>
<b>Trafic II Bus (JL) 2.0 16V</b>	<b>2006-&gt;</b>
F4R 820	86 117
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Trafic II Chassis (EL) 2.0</b>	<b>2001-&gt;</b>
F4R 720	88 120
Ignition Coil ->12.2006; Intake manifold injection	<b>80203</b>
<b>Trafic II Chassis (EL) 2.0 16V</b>	<b>2006-&gt;</b>
F4R 820	86 117
Ignition Coil	<b>80203</b>
<b>Trafic II Van (FL) 2.0</b>	<b>2001-&gt;</b>
F4R 722/F4R 720	88 120
Ignition Coil 06.2001-12.2006	<b>80203</b>
<b>Trafic II Van (FL) 2.0 16V</b>	<b>2006-&gt;</b>
F4R 820	86 117
Ignition Coil Intake manifold injection	<b>80203</b>
<b>Twingo I (C06) 1,2</b>	<b>1993-96</b>
C3G 702/C3G 700	40 55
Ignition Coil	<b>80308</b>
<b>Twingo I (C06) 1,2</b>	<b>1996-07</b>
D7F 700/D7F 701	40 54
Ignition Coil 10.1998->	<b>80222</b>
Ignition Coil	<b>80308</b>
Ignition Coil ->10.1998	<b>80373</b>
Ignition Leads OE N° 8200 713 680; 12.1999->	<b>85988</b>
Ignition Leads ->10.1999	<b>85990</b>
Ignition Leads D7F Eco; 11.1999-06.2001	<b>85991</b>
<b>Twingo I (C06) 1,2</b>	<b>1996-07</b>
D7F 700/D7F 702/D7F 704/D7F 701/D7F 703	43 58
Ignition Coil 10.1998->	<b>80222</b>
Ignition Coil	<b>80308</b>
Ignition Coil ->10.1998	<b>80373</b>
Ignition Leads OE N° 7700 114 549; 12.1999->	<b>85988</b>
Ignition Leads ->10.1999	<b>85990</b>
Ignition Leads D7F Eco; 11.1999-06.2001	<b>85991</b>
<b>Twingo I (C06) 1.2</b>	<b>1998-00</b>
D7F 702/D7F 704/D7F 703	44 60
Ignition Coil ->10.1998	<b>80373</b>
<b>Twingo I (C06) 1.2 16V</b>	<b>2001-07</b>
D4F 702	55 75
Ignition Coil	<b>80206</b>
Ignition Coil 09.2004->	<b>80222</b>
Ignition Leads	<b>85988</b>
<b>Twingo I (C06) 1.2 16V</b>	<b>2004-07</b>
D4F 708	44 60
Ignition Coil ->05.2007	<b>80222</b>
Ignition Coil With ignition lead	<b>80225</b>
Ignition Coil Without ignition lead	<b>80287</b>
Ignition Leads	<b>85988</b>
Ignition Leads ->05.2007	<b>85990</b>
<b>Twingo I Van (S06) 1,2</b>	<b>1996-04</b>
D7F 700/D7F 702/D7F 704/D7F 706/D7F 701/D7F 703	43 58
Ignition Coil ->10.1998	<b>80373</b>
<b>Twingo II (CNO) 1,2</b>	<b>2007-&gt;</b>
D7F 800	43 58
Ignition Coil	<b>80222</b>
Ignition Leads OE N° 7700 114 549	<b>85988</b>
Ignition Leads	<b>85991</b>
<b>Twingo II (CNO) 1.2 16V</b>	<b>2007-&gt;</b>
D4F 772	56 76
Ignition Coil	<b>80225</b>
Ignition Coil Without ignition lead	<b>80287</b>
Ignition Leads	<b>85988</b>

RENAULT Cont.	
<b>Twingo II (CNO) 1.2 16V</b>	<b>2007-&gt;</b>
D4F 764/D4F 772/D4F 770	55 75
Ignition Coil	<b>80225</b>
Ignition Coil	<b>80287</b>
Ignition Leads	<b>85988</b>
<b>Twingo II (CNO) 1.2 TCe 100</b>	<b>2011-&gt;</b>
D4F 780/D4F 782	75 102
Ignition Coil	<b>80222</b>
<b>Twingo II (CNO) 1.2 Turbo</b>	<b>2007-&gt;</b>
D4F 780/D4F 782	74 100
Ignition Coil D4F 780	<b>80222</b>
Ignition Leads	<b>85991</b>
<b>Twingo II (CNO) 1.6 RS</b>	<b>2008-&gt;</b>
K4M 854	98 133
Ignition Coil	<b>80203</b>
<b>Vel Satis (BJO) 2.0 16 V Turbo</b>	<b>2004-&gt;</b>
F4R 766/F4R 767	125 170
Ignition Coil 07.2005->; Intake manifold injection	<b>80203</b>
<b>Vel Satis (BJO) 2.0 16V Turbo</b>	<b>2002-&gt;</b>
F4R 762/F4R 763	120 163
Ignition Coil ->12.2006	<b>80203</b>
<b>Vel Satis (BJO) 2.0 Turbo</b>	<b>2005-&gt;</b>
F4R 867	108 147
Ignition Coil	<b>80203</b>
<b>Wind (E4M) 1,2</b>	<b>2010-&gt;</b>
D4F 782	74 101
Ignition Coil	<b>80222</b>
Ignition Leads	<b>85988</b>
<b>Wind (E4M) 1,6</b>	<b>2010-&gt;</b>
K4M 854	98 133
Ignition Coil	<b>80203</b>
<b>Wind (E4M) 1.2 TCe 100</b>	<b>2011-&gt;</b>
D4F 780	75 102
Ignition Coil	<b>80222</b>
Ignition Leads	<b>85988</b>
ROLLS-ROYCE	
<b>Ghost 6.6 V12</b>	<b>2008-&gt;</b>
N74 B66 A	420 571
Ignition Coil	<b>80247</b>
<b>Silver Seraph 5.4</b>	<b>1998-02</b>
M73 B54	240 326
Ignition Coil	<b>80216</b>
ROVER	
<b>100 / Metro (XP) 114 GSi</b>	<b>1994-95</b>
14 K4F	76 103
Ignition Leads 14 K4F	<b>85760</b>
<b>100 / Metro (XP) 114 GTI 16V</b>	<b>1990-91</b>
14 K4C/14 K4D	69 94
Ignition Leads	<b>85760</b>
<b>100 / Metro (XP) 114 GTI 16V</b>	<b>1991-98</b>
14 K4F	76 103
Ignition Leads 14 K4F	<b>85760</b>
<b>100 / Metro (XP) 114 GTI/GT 16V KAT</b>	<b>1990-98</b>
14 K4C/14 K4D	66 90
Ignition Leads	<b>85760</b>
<b>100 Cabriolet (XP) 111</b>	<b>1994-97</b>
11 K2D	44 60
Ignition Leads	<b>83820</b>
<b>100 Cabriolet (XP) 114</b>	<b>1997-98</b>
14 K4F	75 102
Ignition Leads	<b>83820</b>
Ignition Leads	<b>85760</b>
<b>100 Cabriolet (XP) 114</b>	<b>1994-97</b>
14 K2D/14 K2A	55 75
Ignition Leads	<b>83820</b>
<b>200 (RF) 214 Si</b>	<b>1995-00</b>
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads 14 K4F	<b>85760</b>
Ignition Leads	<b>85765</b>
Ignition Leads Ch.YD 471565->	<b>85766</b>
<b>200 (RF) 216 Si</b>	<b>1995-00</b>
16 K4F	82 112
Ignition Leads	<b>85765</b>
Ignition Leads Ch.YD 471565->	<b>85766</b>



ROVER Cont.	
<b>200 (RF) 218 K Vi</b>	1995-00
18 K4K	107 146
Ignition Leads ->Ch.YD 471564	<b>85764</b>
Ignition Leads Ch.YD 471565->	<b>85766</b>
<b>200 (RF) 218 Si</b>	1999-00
18 K4F	88 120
Ignition Leads	<b>85765</b>
<b>200 (XH) 213 S</b>	1985-89
EV 2	54 73
Ignition Leads	<b>83450</b>
<b>200 (XH) 216</b>	1985-89
16 H	61 83
Ignition Leads 01.1989->	<b>85811</b>
<b>200 (XH) 216 Vitesse</b>	1985-89
16 H	75 102
Ignition Leads 01.1989->	<b>85811</b>
<b>200 Coupe (XW) 216</b>	1996-97
16 K4F	82 112
Ignition Leads 03.1996->	<b>85765</b>
<b>200 Coupe (XW) 216</b>	1992-99
D 16 A8	90 122
Ignition Leads	<b>85811</b>
Ignition Leads ->02.1996	<b>85821</b>
<b>200 Hatchback (XW) 214</b>	1993-95
14 K2D/14 K2A	55 75
Ignition Leads	<b>85790</b>
<b>200 Hatchback (XW) 214 GSI/Si</b>	1992-95
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85760</b>
<b>200 Hatchback (XW) 214 GSI/Si</b>	1990-95
14 K4C	70 95
Ignition Leads	<b>85760</b>
<b>200 Hatchback (XW) 214 Si/Gsi</b>	1989-95
14 K4C/14 K4D	66 90
Ignition Leads ->09.1993	<b>85760</b>
Ignition Leads	<b>85765</b>
Ignition Leads	<b>85790</b>
<b>200 Hatchback (XW) 216 GSI</b>	1989-95
D 16 Z2	82 112
Ignition Leads	<b>85811</b>
Ignition Leads	<b>85821</b>
<b>200 Hatchback (XW) 216 GSI</b>	1989-95
D 16 A7	85 116
Ignition Leads	<b>85811</b>
Ignition Leads	<b>85821</b>
<b>200 Hatchback (XW) 216 GTI</b>	1990-95
D 16 A8	90 122
Ignition Leads	<b>85811</b>
<b>200 Hatchback (XW) 216 GTI</b>	1990-95
D 16 A9	96 130
Ignition Leads	<b>85811</b>
<b>25 (RF) 1.1 16V</b>	2004-05
11 K4F	55 75
Ignition Coil	<b>80254</b>
<b>25 (RF) 1.4 16V</b>	1999-05
14 K4M	62 84
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85765</b>
Ignition Leads Ch.YD 471565->; 02.2000->	<b>85766</b>
<b>25 (RF) 1.4 16V</b>	1999-05
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85765</b>
Ignition Leads Ch.YD 471565->; 02.2000->	<b>85766</b>
<b>25 (RF) 1.6 16V</b>	1999-05
16 K4F	80 109
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85765</b>
Ignition Leads Ch.YD 471565->; 02.2000->	<b>85766</b>
<b>25 (RF) 1.8 16V</b>	1999-05
18 K4F	85 116
Ignition Coil	<b>80254</b>
Ignition Leads ->Ch.YD 471564	<b>85765</b>
Ignition Leads	<b>85766</b>
<b>25 (RF) 1.8 16V</b>	2000-05
18 K4K	107 146
Ignition Leads ->Ch.YD 471564; ->10.2004	<b>85764</b>
Ignition Leads Ch.YD 471565->; ->10.2004	<b>85766</b>

ROVER Cont.	
<b>400 (RT) 414 Si</b>	1995-00
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85765</b>
<b>400 (RT) 416 Si</b>	1995-00
16 K4F	82 112
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85765</b>
<b>400 (RT) 416 Si</b>	1995-00
D 16 Y2	83 113
Ignition Coil Ch.AD074465-AD250028	<b>80250</b>
Ignition Coil ->Ch.AD074464	<b>80299</b>
Ignition Leads	<b>85765</b>
<b>400 (RT) 416 Si</b>	1995-00
D16B2	85 116
Ignition Leads	<b>85765</b>
<b>400 (RT) 420 Si Lux</b>	1995-00
20 T4H	100 136
Ignition Coil	<b>80272</b>
<b>400 (XW) 414</b>	1993-95
14 K4C	70 95
Ignition Leads	<b>85760</b>
<b>400 (XW) 414 GSI/SI</b>	1990-95
14 K4C/14 K4D	66 90
Ignition Leads ->01.1992	<b>83820</b>
Ignition Leads ->10.1992	<b>85760</b>
Ignition Leads	<b>85790</b>
<b>400 (XW) 414 GSI/SI KAT</b>	1992-95
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads 14 K4F	<b>85760</b>
Ignition Leads	<b>85765</b>
Ignition Leads With ignition lead	<b>85790</b>
<b>400 (XW) 416 GSI</b>	1990-95
D 16 Z2	82 112
Ignition Leads	<b>85765</b>
Ignition Leads D 16 Z2	<b>85811</b>
Ignition Leads	<b>85821</b>
<b>400 (XW) 416 GSI/GSE</b>	1990-95
D 16 A7	85 116
Ignition Leads	<b>85811</b>
Ignition Leads	<b>85821</b>
<b>400 Fastback (RT) 416 Si</b>	1995-00
D16B2	85 116
Ignition Leads ->10.1999	<b>85765</b>
<b>400 Hatchback (RT) 414</b>	1996-97
14 K2F	55 75
Ignition Leads	<b>85765</b>
<b>400 Hatchback (RT) 414 Si</b>	1995-00
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85765</b>
<b>400 Hatchback (RT) 416 Si</b>	1995-00
16 K4F	82 112
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85765</b>
<b>400 Hatchback (RT) 416 Si</b>	1995-00
D 16 Y2	83 113
Ignition Coil Ch.AD074465-Ch.AD250028	<b>80250</b>
Ignition Coil ->Ch.AD074464	<b>80299</b>
Ignition Leads	<b>85765</b>
Ignition Leads D 16 Y2	<b>85811</b>
<b>400 Hatchback (RT) 420 Si Lux</b>	1995-00
20 T4H	100 136
Ignition Coil	<b>80272</b>
<b>400 Tourer (XW) 1.6 i</b>	1994-98
D 16 Z2	82 112
Ignition Coil	<b>80250</b>
Ignition Leads 02.1996->	<b>85765</b>
Ignition Leads 14 K4F	<b>85811</b>
Ignition Leads ->02.1996	<b>85821</b>
<b>400 Tourer (XW) 1.6 i</b>	1994-98
D 16 A8	90 122
Ignition Coil	<b>80250</b>
Ignition Leads With ignition lead	<b>85765</b>
<b>400 Tourer (XW) 1.8 i</b>	1996-98
18 K4K	107 146
Ignition Leads	<b>85764</b>

**ROVER Cont.**

<b>400 Tourer (XW) 2.0 i</b>	<b>1994-98</b>
20 T4H	100 136
Ignition Coil	<b>80272</b>
<b>45 (RT) 1.4</b>	<b>2000-05</b>
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>45 (RT) 1.6</b>	<b>2000-05</b>
16 K4F	80 109
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>45 (RT) 1.8</b>	<b>2000-05</b>
18 K4F	86 117
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>45 (RT) 2.0 V6</b>	<b>2000-05</b>
20 K4F	110 150
Ignition Coil 20 K4F	<b>80216</b>
Ignition Leads	<b>85768</b>
<b>45 Sedan (RT) 1.4</b>	<b>2000-05</b>
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>45 Sedan (RT) 1.6</b>	<b>2000-05</b>
16 K4F	80 109
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>45 Sedan (RT) 1.8</b>	<b>2000-05</b>
18 K4F	86 117
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>45 Sedan (RT) 2.0 V6</b>	<b>2000-05</b>
20 K4F	110 150
Ignition Coil 20 K4F	<b>80216</b>
Ignition Leads	<b>85768</b>
<b>600 (RH) 618 i/Si</b>	<b>1996-99</b>
F 18 A3	85 115
Ignition Coil Ch.BM246797->	<b>80250</b>
Ignition Coil ->Ch.AM246796	<b>80299</b>
Ignition Leads	<b>85811</b>
<b>600 (RH) 620 i</b>	<b>1993-96</b>
F 20 Z2	85 115
Ignition Coil Ch.246797->	<b>80250</b>
Ignition Coil ->Ch.246796	<b>80299</b>
Ignition Leads	<b>85811</b>
<b>600 (RH) 620 Si</b>	<b>1993-99</b>
F 20 Z1	96 131
Ignition Coil Ch.246797->	<b>80250</b>
Ignition Coil ->Ch.246796	<b>80299</b>
Ignition Leads	<b>85811</b>
<b>600 (RH) 620 Ti Vitesse</b>	<b>1994-99</b>
20 T4G	147 200
Ignition Coil	<b>80272</b>
Ignition Coil	<b>80299</b>
<b>600 (RH) 623 Si</b>	<b>1993-99</b>
H 23 A3	116 158
Ignition Coil	<b>80299</b>
Ignition Leads	<b>85811</b>
<b>75 (R.J) 1.8</b>	<b>1999-05</b>
K 1.8	88 120
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>75 (R.J) 1.8 Turbo</b>	<b>2003-05</b>
18 K4G	110 150
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>75 (R.J) 2.0 V6</b>	<b>1999-05</b>
20 K4F	110 150
Ignition Coil 20 K4F	<b>80216</b>
Ignition Leads	<b>85768</b>
<b>75 (R.J) 2.5 V6</b>	<b>1999-01</b>
KV 6	129 175
Ignition Coil KV 6	<b>80216</b>
Ignition Leads	<b>85768</b>
<b>75 (R.J) 2.5 V6</b>	<b>2001-05</b>
25 K4F	130 177
Ignition Coil 25 K4F	<b>80216</b>
Ignition Leads	<b>85768</b>

**ROVER Cont.**

<b>75 Tourer (R.J) 1.8</b>	<b>2001-05</b>
K 1.8	88 120
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>75 Tourer (R.J) 1.8 Turbo</b>	<b>2003-05</b>
18 K4G	110 150
Ignition Coil	<b>80254</b>
Ignition Leads	<b>85766</b>
<b>75 Tourer (R.J) 2.0 V6</b>	<b>2001-05</b>
20 K4F	110 150
Ignition Coil 20 K4F	<b>80216</b>
Ignition Leads	<b>85768</b>
<b>75 Tourer (R.J) 2.5 V6</b>	<b>2001-05</b>
KV 6	130 177
Ignition Coil	<b>80216</b>
Ignition Leads	<b>85768</b>
<b>800 (XS) 820 16 V I/SI</b>	<b>1986-88</b>
20 HD	103 140
Ignition Leads	<b>85410</b>
<b>800 (XS) 820 16V Turbo</b>	<b>1992-99</b>
T 16	132 180
Ignition Coil	<b>80272</b>
<b>800 (XS) 820 I/SI</b>	<b>1992-99</b>
20 T4H	100 136
Ignition Coil	<b>80272</b>
<b>800 (XS) 820 SE/SI</b>	<b>1986-91</b>
20 HS	88 120
Ignition Leads	<b>85410</b>
<b>800 (XS) 820 SI</b>	<b>1988-91</b>
20 HD M 16	98 133
Ignition Leads	<b>85410</b>
<b>800 (XS) 820 Sport</b>	<b>1994-96</b>
20 T4G	145 197
Ignition Coil	<b>80272</b>
<b>800 (XS) 820e</b>	<b>1986-91</b>
20 HS	88 120
Ignition Leads DIN	<b>85410</b>
<b>800 Hatchback (XS) 820 16V Turbo</b>	<b>1992-99</b>
T 16	132 180
Ignition Coil	<b>80272</b>
<b>800 Hatchback (XS) 820 i/Si</b>	<b>1988-91</b>
20 HD	103 140
Ignition Leads	<b>85410</b>
<b>800 Hatchback (XS) 820 I/SI</b>	<b>1993-99</b>
20 T4H	100 136
Ignition Coil	<b>80272</b>
<b>800 Hatchback (XS) 820 SE/SI</b>	<b>1986-91</b>
20 HS	88 120
Ignition Leads	<b>85410</b>
<b>800 Hatchback (XS) 820 SI</b>	<b>1988-91</b>
20 HD M 16	98 133
Ignition Leads	<b>85410</b>
<b>800 Hatchback (XS) 820 Sport</b>	<b>1994-96</b>
20 T4G	145 197
Ignition Coil	<b>80272</b>
<b>Cabriolet (XW) 214 1.4</b>	<b>1990-92</b>
14 K4C	70 95
Ignition Leads	<b>85760</b>
<b>Cabriolet (XW) 214 1.4</b>	<b>1992-99</b>
14 K4C/14 K4D	66 90
Ignition Leads	<b>85760</b>
Ignition Leads	<b>85790</b>
<b>Cabriolet (XW) 214 1.4i 16V</b>	<b>1993-99</b>
14 K4F	76 103
Ignition Coil	<b>80254</b>
Ignition Leads 14 K4F	<b>85760</b>
<b>Cabriolet (XW) 216 1.6i 16V</b>	<b>1996-99</b>
16 K4F	82 111
Ignition Leads	<b>85765</b>
<b>Cityrover 1.4 Elegance</b>	<b>2003-05</b>
14K2/475 Si	62 84
Ignition Coil	<b>80207</b>
<b>Coupe 1.6 16 V</b>	<b>1996-99</b>
16 K4F	82 111
Ignition Leads	<b>85765</b>
<b>Coupe 1.8 16 V</b>	<b>1996-99</b>
18 K4K	107 145
Ignition Leads	<b>85764</b>





ROVER Cont.	
<b>Mini 1000</b>	<b>1992-93</b>
99 HD 81	30 41
Ignition Leads	<b>83850</b>
<b>Mini 1300</b>	<b>1991-91</b>
12 A2A	45 61
Ignition Coil	<b>80272</b>
Ignition Leads	<b>83850</b>
<b>Mini 1300</b>	<b>1992-95</b>
12 A2D	39 53
Ignition Coil	<b>80272</b>
Ignition Leads	<b>83850</b>
<b>Mini 1300</b>	<b>1992-00</b>
12 A2E/12 A2L	46 63
Ignition Coil	<b>80272</b>
Ignition Leads	<b>83850</b>
<b>Mini 1300</b>	<b>1992-00</b>
12 A2B	37 50
Ignition Coil	<b>80272</b>
Ignition Leads	<b>83850</b>
<b>Mini Cabriolet (XN) 1300</b>	<b>1992-95</b>
12 A2E	46 63
Ignition Coil	<b>80272</b>
Ignition Leads	<b>83850</b>
<b>Streetwise 1.4</b>	<b>2003-05</b>
14 K4F	76 103
Ignition Coil	<b>80254</b>
<b>Streetwise 1.4</b>	<b>2003-05</b>
14 K4M	62 84
Ignition Coil	<b>80254</b>

SAAB	
<b>900 I (AC4, AM4) 2.0 EMS</b>	<b>1979-80</b>
BI 20	87 118
Ignition Leads	<b>85350</b>
<b>900 I Combi Coupe 2.0 c</b>	<b>1978-84</b>
B20T/BT 20	79 108
Ignition Leads	<b>85350</b>
<b>9-3 (YS3F) 1.8 i</b>	<b>2004-15</b>
Z 18 XE	90 122
Ignition Coil Z18XE	<b>80224</b>
<b>9-3 (YS3F) 2.0 t</b>	<b>2011-15</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-3 (YS3F) 2.0 t Bio Power</b>	<b>2011-15</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-3 (YS3F) 2.0 t BioPower XWD</b>	<b>2008-15</b>
A 20 NFT	162 220
Ignition Coil 01.2011->	<b>80329</b>
<b>9-3 (YS3F) 2.0 t XWD</b>	<b>2008-15</b>
A 20 NFT	162 220
Ignition Coil 01.2011->	<b>80329</b>
<b>9-3 (YS3F) 2.8 Turbo V6</b>	<b>2005-15</b>
LP9	184 250
Ignition Coil	<b>80355</b>
<b>9-3 (YS3F) 2.8 Turbo V6</b>	<b>2007-15</b>
B284L	188 256
Ignition Coil	<b>80355</b>
<b>9-3 (YS3F) 2.8 Turbo V6</b>	<b>2008-15</b>
B284L	203 276
Ignition Coil	<b>80355</b>
<b>9-3 (YS3F) 2.8 Turbo V6</b>	<b>2005-15</b>
LP9	169 230
Ignition Coil	<b>80355</b>
<b>9-3 (YS3F) 2.8 Turbo V6 XWD</b>	<b>2008-15</b>
B284R	206 280
Ignition Coil	<b>80355</b>
<b>9-3 Cabriolet (YS3F) 2.0 t</b>	<b>2011-15</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-3 Cabriolet (YS3F) 2.0 t BioPower</b>	<b>2011-15</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-3 Cabriolet (YS3F) 2.8 Turbo V6</b>	<b>2006-15</b>
LP9	184 250
Ignition Coil	<b>80355</b>

SAAB Cont.	
<b>9-3 Cabriolet (YS3F) 2.8 Turbo V6</b>	<b>2007-15</b>
B284L	188 256
Ignition Coil	<b>80355</b>
<b>9-3 Cabriolet (YS3F) 2.8 Turbo V6</b>	<b>2009-15</b>
B284R	203 276
Ignition Coil	<b>80355</b>
<b>9-3 Cabriolet (YS3F) 2.8 Turbo V6</b>	<b>2009-15</b>
B284R	206 280
Ignition Coil	<b>80355</b>
<b>9-3 Cabriolet (YS3F) 2.8 Turbo V6</b>	<b>2006-15</b>
LP9	169 230
Ignition Coil	<b>80355</b>
<b>9-3 Combi 1.8 i</b>	<b>2005-15</b>
Z 18 XE	90 122
Ignition Coil Z18XE	<b>80224</b>
<b>9-3 Combi 2.0 t</b>	<b>2011-15</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-3 Combi 2.0 t BioPower</b>	<b>2011-15</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-3 Combi 2.0 t XWD</b>	<b>2011-15</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-3 Combi 2.8 Turbo V6</b>	<b>2005-15</b>
LP9	184 250
Ignition Coil	<b>80355</b>
<b>9-3 Combi 2.8 Turbo V6</b>	<b>2007-15</b>
B284L	188 256
Ignition Coil	<b>80355</b>
<b>9-3 Combi 2.8 Turbo V6</b>	<b>2008-15</b>
B284R	203 276
Ignition Coil	<b>80355</b>
<b>9-3 Combi 2.8 Turbo V6</b>	<b>2005-15</b>
LP9	169 230
Ignition Coil	<b>80355</b>
<b>9-3 Combi 2.8 Turbo V6 XWD</b>	<b>2008-15</b>
B284R	206 280
Ignition Coil	<b>80355</b>
<b>9-3 Kombi (YS3F) 2.0 t BioPower XWD</b>	<b>2011-15</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-3X 2.0 t BioPower XWD</b>	<b>2011-12</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-5 (YS3G) 2.0 t BioPower</b>	<b>2010-12</b>
A 20 NFT	162 220
Ignition Coil	<b>80329</b>
<b>9-5 (YS3G) 2.0 t BioPower XWD</b>	<b>2010-12</b>
A 20 NHT	162 220
Ignition Coil	<b>80329</b>
<b>9-5 (YS3G) 2.0 Turbo</b>	<b>2010-12</b>
A 20 NHT	162 220
Ignition Coil	<b>80329</b>
<b>9-5 (YS3G) 2.0 Turbo XWD</b>	<b>2010-12</b>
A 20 NHT	162 220
Ignition Coil	<b>80329</b>
<b>99 2.0 EMS</b>	<b>1974-78</b>
B 20 I	87 118
Ignition Leads	<b>85350</b>
<b>99 2.0 GL</b>	<b>1974-84</b>
B 20 I/B 20 C	74 100
Ignition Leads	<b>85350</b>
<b>99 Combi Coupe 2.0</b>	<b>1976-78</b>
B20T	79 107
Ignition Leads	<b>85350</b>
<b>99 Combi Coupe 2.0 Turbo</b>	<b>1977-80</b>
BSI 20	107 146
Ignition Leads	<b>85350</b>



SEAT	
124 D1200	1968-76
124 A.000	44 60
Ignition Leads	83030
124 Familiar LS1200	1970-76
124 A.000	48 65
Ignition Leads	83030
124 LS1200	1968-80
FA12	48 65
Ignition Leads	83030
127 (127A) 0.9	1972-82
A112 A5.000	33 45
Ignition Leads	83060
127 (127A) 1.0	1972-82
110F00	38 52
Ignition Leads	83060
128 1.2	1976-80
124 A.000	49 67
Ignition Leads	83060
128 1.4	1976-80
124 B2.000	57 77
Ignition Leads	83060
131 1.5	1982-85
138A00	55 75
Ignition Leads	83030
131 1.6	1982-85
132 BB 0A 0	71 97
Ignition Leads	83060
131 2.0	1978-85
131 C4.000	85 116
Ignition Leads	83060
132 1.8	1973-80
	77 105
Ignition Leads	83060
133 0.8	1974-79
DG	25 34
Ignition Leads	83010
600 D 0.8	1963-70
126G106	17 23
Ignition Leads	83010
850 0.9	1966-74
120G100	27 37
Ignition Leads	83010
850 0.9	1966-74
126G100	35 47
Ignition Leads	83010
850 0.9	1972-75
100 GL 6000	25 34
Ignition Leads	83010
Alhambra (710) 1.4 TSI	2010->
CNWB/CTHA/CAVA	110 150
Ignition Coil	80201
Alhambra (710) 2.0 TSI	2010->
CCZA	147 200
Ignition Coil	80240
Alhambra (710, 711) 1.4 TSI	2015->
CZDA	110 150
Ignition Coil	80249
Alhambra (7V8, 7V9) 1.8 T 20V	1997-10
AWC/AJH	110 150
Ignition Coil	80239
Ignition Coil 11.1997->	80252
Alhambra (7V8, 7V9) 2.0 i	1996-10
ATM/ADY	85 115
Ignition Coil ADY	80200
Ignition Coil ATM	80218
Ignition Leads ADY	85865
Ignition Leads ATM	85875
Altea (5P1) 1.2 TSI	2010->
CBZB	77 105
Ignition Coil	80218
Ignition Leads	85871
Altea (5P1) 1.4 16V	2006->
CGGB/BXW	63 86
Ignition Coil	80201
Altea (5P1) 1.4 TSI	2007->
CAXC	92 125
Ignition Coil	80201

SEAT Cont.	
Altea (5P1) 1.6	2004->
BGU/CCSA/BSF/CMXA/BSE	75 102
Ignition Coil BGU/BSF/BSE	80218
Ignition Leads	85875
Altea (5P1) 1.6 LPG	2009->
CHGA	75 102
Ignition Coil	80218
Ignition Leads ->07.2015	85879
Altea (5P1) 1.8 TFSI	2007->
BZB/CDA/AYT	118 160
Ignition Coil	80240
Altea (5P1) 2.0 FSI	2004-09
BLR/BLY/BVZ/BVY	110 150
Ignition Coil BLR,BLY,BVZ,BVY	80240
Altea (5P1) 2.0 TFSI	2006-09
BWA	147 200
Ignition Coil BWA	80240
Altea XL (5P5, 5P8) 1.2 TSI	2010->
CBZB	77 105
Ignition Coil	80218
Ignition Leads	85871
Altea XL (5P5, 5P8) 1.4 16V	2006->
CGGB/BXW	63 86
Ignition Coil	80201
Altea XL (5P5, 5P8) 1.4 TSI	2007->
CAXC	92 125
Ignition Coil	80201
Altea XL (5P5, 5P8) 1.6	2006->
CCSA/BSF/CMXA/BSE	75 102
Ignition Coil	80218
Ignition Leads	85875
Altea XL (5P5, 5P8) 1.6 LPG	2009->
CHGA	75 102
Ignition Coil	80218
Ignition Leads ->07.2015	85879
Altea XL (5P5, 5P8) 1.8 TFSI	2007->
BZB/CDA/AYT	118 160
Ignition Coil	80240
Altea XL (5P5, 5P8) 2.0 FSI	2006-09
BVZ/BVY	110 150
Ignition Coil	80240
Altea XL (5P5, 5P8) 2.0 TFSI 4x4	2007-09
BWA	147 200
Ignition Coil	80240
Altea XL (5P5, 5P8) 2.0 TFSI 4x4	2009->
CCZB	155 211
Ignition Coil	80240
Arosa (6H) 1.0	1997-04
AER/ANV/ALD/ALL/AUC	37 50
Ignition Coil AER/ALL	80200
Ignition Coil ALD/ANV/AUC	80218
Ignition Leads AUC	85681
Ignition Leads AER	85691
Arosa (6H) 1.4	1997-04
AEX/AKV/ANW/AKK/APQ/AUD	44 60
Ignition Coil AEX/AKV/APQ	80200
Ignition Coil ANW/AKK/AUD	80218
Ignition Leads AUD	85681
Ignition Leads AEX	85691
Arosa (6H) 1.4 16V	2000-04
AFK/AUB/AQQ	74 100
Ignition Coil	80218
Ignition Leads	85696
Ateca (KH7) 1.0 TSI	2016->
CHZJ	85 115
Ignition Coil	80249
Ateca (KH7) 1.4 TSI	2016->
CZEA	110 150
Ignition Coil	80249
Ateca (KH7) 1.4 TSI 4Drive	2016->
CZEA	110 150
Ignition Coil	80249
Cordoba (6K1, 6K2) 1.0 i	1996-99
AER	37 50
Ignition Coil	80200
Ignition Leads	85693



SEAT Cont.		
<b>Cordoba (6K1, 6K2) 1.4 i</b>		1994-99
AEX/AKV/ABD/APQ		44 60
Ignition Coil ABD,ANX,APQ,AEX,AKV		80200
Ignition Leads		85693
Ignition Leads ABD		85694
<b>Cordoba (6K1, 6K2) 1.4 i 16V</b>		1996-99
AFH		74 101
Ignition Coil		80200
Ignition Leads AFH		85695
<b>Cordoba (6K1, 6K2) 1.6 i</b>		1994-99
1F		55 75
Ignition Coil		80200
Ignition Leads 1F		85685
Ignition Leads		85690
Ignition Leads ->Ch.6KZR510001, ZR010001		85692
<b>Cordoba (6K1, 6K2) 1.6 i</b>		1993-99
ABU/ALM/AEE		55 75
Ignition Coil ABU,AEE,ALM		80200
Ignition Leads		85685
Ignition Leads ALM		85693
Ignition Leads ABU		85694
<b>Cordoba (6K1, 6K2) 1.6 i</b>		1996-99
AKL/AFT		74 101
Ignition Coil AFT		80200
Ignition Leads ->Ch.6KZR510001, ZR010001		85692
Ignition Leads		85865
<b>Cordoba (6K1, 6K2) 1.8 i</b>		1993-99
ACC/ADZ/ABS		66 90
Ignition Coil ADZ,ABS		80200
Ignition Leads ->Ch.6KZR510001, ZR010001		85685
Ignition Leads		85690
<b>Cordoba (6K1, 6K2) 1.8 i 16V</b>		1993-96
ADL		95 129
Ignition Coil 3 term.; Ch.6K-ZR132109,6K-ZR672->		80200
Ignition Coil 6 term.; ->Ch.6K-ZR132108,6K-ZR671		80219
Ignition Leads		85059
<b>Cordoba (6K1, 6K2) 2.0 i</b>		1993-99
2E/AGG		85 115
Ignition Coil Ch.6K-ZR132109->		80200
Ignition Leads ->Ch.6KZR510001, ZR010001		85685
Ignition Leads		85690
<b>Cordoba (6K1, 6K2) 2.0 i 16V</b>		1996-99
ABF		110 150
Ignition Coil		80200
Ignition Leads		85059
<b>Cordoba (6K2) 1.0</b>		1999-02
ANV/ALD/AUC		37 50
Ignition Coil		80218
Ignition Leads		85681
<b>Cordoba (6K2) 1.4</b>		1999-02
ANW/AKK/AUD		44 60
Ignition Coil		80218
Ignition Leads		85681
<b>Cordoba (6K2) 1.4 16V</b>		2000-02
APE/AUA		55 75
Ignition Coil		80218
Ignition Leads		85696
<b>Cordoba (6K2) 1.4 16V</b>		2000-02
AUB/AQQ		74 100
Ignition Coil		80218
Ignition Leads		85696
<b>Cordoba (6K2) 1.6</b>		1999-02
ALM		55 75
Ignition Coil		80200
Ignition Leads		85693
<b>Cordoba (6K2) 1.6</b>		1999-02
AKL/APF/AEH/AUR		74 101
Ignition Coil		80218
Ignition Leads AKL/AEH		85875
<b>Cordoba (6K2) 1.8 T 20V Cupra</b>		2000-02
AYP/AQX		115 156
Ignition Coil AYP		80202
Ignition Coil AQX		80239
<b>Cordoba (6L2) 1.2</b>		2002-06
AZQ/BME		47 64
Ignition Coil ->04.2004		80201
<b>Cordoba (6L2) 1.2 12V</b>		2006-09
BXV		51 70
Ignition Coil Intake manifold injection		80201

SEAT Cont.		
<b>Cordoba (6L2) 1.4 16V</b>		2002-07
BBY/BKY		55 75
Ignition Coil BBY; ->04.2004		80201
Ignition Leads		85696
<b>Cordoba (6L2) 1.4 16V</b>		2002-09
BBZ/AUB		74 100
Ignition Coil BBZ		80201
Ignition Leads		85696
<b>Cordoba (6L2) 1.4 16V</b>		2006-09
BXW		63 86
Ignition Coil ->11.2006; Intake manifold injection		80201
<b>Cordoba (6L2) 1.6</b>		2003-09
BAH		74 101
Ignition Coil		80218
Ignition Leads		85697
<b>Cordoba (6L2) 1.6 16V</b>		2006-09
BTS		77 105
Ignition Coil Intake manifold injection		80201
<b>Cordoba (6L2) 2.0</b>		2002-09
AZL/BBX		85 115
Ignition Coil		80218
Ignition Leads		85875
<b>Cordoba Vario (6K5) 1.4</b>		1999-02
ANW/AKK/AUD		44 60
Ignition Coil		80218
Ignition Leads		85681
<b>Cordoba Vario (6K5) 1.4 16V</b>		1999-02
APE/AUA		55 75
Ignition Coil APE		80218
Ignition Leads		85696
<b>Cordoba Vario (6K5) 1.4 i</b>		1996-99
AEX/AKV/APQ		44 60
Ignition Coil AEX,AKV,ANX,APQ		80200
Ignition Leads APQ		85692
Ignition Leads AEX		85693
<b>Cordoba Vario (6K5) 1.6</b>		1999-02
ABU/ALM		55 75
Ignition Coil		80200
Ignition Coil 10.1999->		80218
Ignition Leads		85693
<b>Cordoba Vario (6K5) 1.6</b>		1999-02
AKL/APF/AEH/AUR		74 101
Ignition Coil		80218
Ignition Leads AKL/AEH		85875
<b>Cordoba Vario (6K5) 1.6 i</b>		1997-99
1F		55 75
Ignition Coil		80200
Ignition Leads		85685
Ignition Leads		85690
Ignition Leads ->Ch.6KZR510001, ZR010001		85692
<b>Cordoba Vario (6K5) 1.6 i</b>		1996-99
AFT		74 101
Ignition Coil		80200
Ignition Leads ->Ch.6KZR510001, ZR010001		85692
Ignition Leads		85865
<b>Cordoba Vario (6K5) 1.6 i</b>		1996-99
ALM/AEE		55 75
Ignition Coil ALM,AEE		80200
Ignition Leads ->Ch.6KZR510001, ZR010001		85692
<b>Exeo (3R2) 1.6</b>		2009-10
ALZ		75 102
Ignition Coil		80218
<b>Exeo (3R2) 1.8 T</b>		2008-10
CFMA		110 150
Ignition Coil		80202
Ignition Coil		80218
<b>Exeo (3R2) 1.8 TSI</b>		2010->
CDHA		88 120
Ignition Coil ->07.2011		80240
<b>Exeo (3R2) 1.8 TSI</b>		2010->
CDHB		118 160
Ignition Coil		80240
<b>Exeo (3R2) 2.0 TFSI</b>		2009->
BWE		147 200
Ignition Coil		80240
<b>Exeo (3R2) 2.0 TFSI</b>		2010->
CDND		155 211
Ignition Coil		80240



SEAT Cont.		
<b>Exeo ST (3R5) 1.6</b>		<b>2009-10</b>
ALZ		75 102
Ignition Coil		<b>80218</b>
<b>Exeo ST (3R5) 1.8 T</b>		<b>2009-10</b>
CFMA		110 150
Ignition Coil		<b>80202</b>
Ignition Coil		<b>80218</b>
<b>Exeo ST (3R5) 1.8 TSI</b>		<b>2010-&gt;</b>
CDHA		88 120
Ignition Coil ->07.2011		<b>80240</b>
<b>Exeo ST (3R5) 1.8 TSI</b>		<b>2010-&gt;</b>
CDHB		118 160
Ignition Coil		<b>80240</b>
<b>Exeo ST (3R5) 2.0 TFSI</b>		<b>2009-&gt;</b>
BWE		147 200
Ignition Coil		<b>80240</b>
<b>Exeo ST (3R5) 2.0 TFSI</b>		<b>2010-&gt;</b>
CDND		155 211
Ignition Coil		<b>80240</b>
<b>Fura (025A) 0.9</b>		<b>1984-86</b>
100 GL 7000/09 NCA		29 40
Ignition Leads		<b>83660</b>
<b>Fura (025A) 0.9</b>		<b>1982-86</b>
HB 90		31 43
Ignition Leads		<b>83660</b>
<b>Fura (025A) 0.9</b>		<b>1982-86</b>
100 GL 3000		33 45
Ignition Leads		<b>83660</b>
<b>Fura (025A) 1.4</b>		<b>1982-86</b>
127 B.7000		55 75
Ignition Leads		<b>83660</b>
<b>Ibiza I (021A) 0.9</b>		<b>1986-93</b>
146 A 000		32 44
Ignition Leads 146 A 000		<b>83030</b>
<b>Ibiza I (021A) 0.9</b>		<b>1990-93</b>
146 A 000/09 NCA		29 40
Ignition Leads		<b>83030</b>
<b>Ibiza I (021A) 1.2</b>		<b>1984-93</b>
021 A 1000		44 60
Ignition Leads		<b>83110</b>
<b>Ibiza I (021A) 1.2</b>		<b>1984-93</b>
021 A 1000		47 64
Ignition Leads		<b>83110</b>
<b>Ibiza I (021A) 1.2 i</b>		<b>1989-93</b>
021 C.1000		52 71
Ignition Leads		<b>83110</b>
<b>Ibiza I (021A) 1.5</b>		<b>1984-93</b>
021 A 2000		63 85
Ignition Leads		<b>83110</b>
<b>Ibiza I (021A) 1.5 i</b>		<b>1986-93</b>
021 B.2000		74 100
Ignition Leads		<b>83110</b>
Ignition Leads 04.1991->		<b>85693</b>
<b>Ibiza I (021A) 1.5 i</b>		<b>1986-93</b>
021 D.2000		65 89
Ignition Leads		<b>83110</b>
<b>Ibiza I (021A) 1.5 i KAT</b>		<b>1986-93</b>
021 C.2000		66 90
Ignition Leads		<b>83110</b>
<b>Ibiza I (021A) 1.7</b>		<b>1991-93</b>
021 A.3000		72 98
Ignition Leads 1700i; ->01.1992		<b>85861</b>
<b>Ibiza II (6K1) 1.0</b>		<b>1993-96</b>
AAU		33 45
Ignition Coil		<b>80200</b>
Ignition Leads		<b>85685</b>
<b>Ibiza II (6K1) 1.0 i</b>		<b>1996-99</b>
AER		37 50
Ignition Coil		<b>80200</b>
Ignition Leads		<b>85693</b>
<b>Ibiza II (6K1) 1.3 i</b>		<b>1993-99</b>
2G/AAV		40 54
Ignition Coil AAV; 3 term.; ->07.1994		<b>80200</b>
Ignition Coil 2G; 6 term.; ->07.1994		<b>80219</b>
Ignition Leads AVV		<b>83979</b>

SEAT Cont.		
<b>Ibiza II (6K1) 1.4 i</b>		<b>1993-99</b>
AEX/AKV/ABD/APQ		44 60
Ignition Coil ABD,AEX,AKV,APQ		<b>80200</b>
Ignition Leads AKV/APQ/AEX/ANX		<b>85693</b>
Ignition Leads ABD		<b>85694</b>
<b>Ibiza II (6K1) 1.4 i 16V</b>		<b>1997-99</b>
AFH		74 101
Ignition Coil		<b>80200</b>
Ignition Leads AFH		<b>85695</b>
<b>Ibiza II (6K1) 1.6 i</b>		<b>1994-99</b>
1F		55 75
Ignition Coil		<b>80200</b>
Ignition Leads		<b>85690</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
<b>Ibiza II (6K1) 1.6 i</b>		<b>1993-99</b>
ABU/ALM/AEE		55 75
Ignition Coil ABU,ALM,AEE		<b>80200</b>
Ignition Leads ->07.1994		<b>85685</b>
Ignition Leads ALM / AEE		<b>85691</b>
Ignition Leads ABU		<b>85693</b>
<b>Ibiza II (6K1) 1.6 i</b>		<b>1996-99</b>
AKL/AFT		74 101
Ignition Coil		<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
Ignition Leads		<b>85685</b>
<b>Ibiza II (6K1) 1.8 i</b>		<b>1993-99</b>
ACC/ADZ/ABS		66 90
Ignition Coil 3 term.; ABS,ADZ		<b>80200</b>
Ignition Coil 6 term.		<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85685</b>
Ignition Leads		<b>85690</b>
<b>Ibiza II (6K1) 1.8 i 16V</b>		<b>1993-96</b>
ADL		95 129
Ignition Coil		<b>80200</b>
Ignition Leads		<b>85059</b>
<b>Ibiza II (6K1) 2.0 i</b>		<b>1993-99</b>
2E/AGG		85 115
Ignition Coil 3 term.		<b>80200</b>
Ignition Coil 6 term.		<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85685</b>
Ignition Leads		<b>85690</b>
<b>Ibiza II (6K1) 2.0 i 16V</b>		<b>1996-99</b>
ABF		110 150
Ignition Coil		<b>80200</b>
Ignition Leads		<b>85059</b>
<b>Ibiza III (6K1) 1.0</b>		<b>1999-02</b>
ANV/ALD/AUC		37 50
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85681</b>
<b>Ibiza III (6K1) 1.4</b>		<b>1999-02</b>
ANW/AKK/AUD		44 60
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85681</b>
<b>Ibiza III (6K1) 1.4 16V</b>		<b>2000-02</b>
APE/AUA		55 75
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Ibiza III (6K1) 1.4 16V</b>		<b>1999-02</b>
AUB/AQQ		74 100
Ignition Coil		<b>80200</b>
Ignition Coil AUB		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Ibiza III (6K1) 1.6</b>		<b>1999-02</b>
AKL/APF/AEH/AUR		74 101
Ignition Coil		<b>80218</b>
Ignition Leads AKL/AEH		<b>85875</b>
<b>Ibiza III (6K1) 1.6</b>		<b>1999-02</b>
ALM		55 75
Ignition Coil		<b>80200</b>
Ignition Leads		<b>85693</b>
<b>Ibiza III (6K1) 1.8 T 20V Cupra</b>		<b>2000-02</b>
AYP/AQX		115 156
Ignition Coil With regul.cat.(3way)		<b>80202</b>
Ignition Coil OE N° 06B905115E		<b>80239</b>
<b>Ibiza IV (6L1) 1.2</b>		<b>2002-06</b>
AZQ/BME		47 64
Ignition Coil AZQ; ->04.2004		<b>80201</b>



SEAT Cont.	
<b>Ibiza IV (6L1) 1.2</b>	<b>2007-08</b>
BBM	44 60
Ignition Coil	<b>80326</b>
<b>Ibiza IV (6L1) 1.2 12V</b>	<b>2006-09</b>
BXV	51 70
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Ibiza IV (6L1) 1.4 16V</b>	<b>2002-09</b>
BBZ/AUB	74 100
Ignition Coil BBZ	<b>80201</b>
Ignition Coil AUB	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Ibiza IV (6L1) 1.4 16V</b>	<b>2002-07</b>
BBY/BKY	55 75
Ignition Coil BBY; ->04.2004	<b>80201</b>
Ignition Leads	<b>85696</b>
<b>Ibiza IV (6L1) 1.4 16V</b>	<b>2006-09</b>
BXW	63 86
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Ibiza IV (6L1) 1.6</b>	<b>2003-09</b>
BAH	74 101
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85697</b>
<b>Ibiza IV (6L1) 1.6 16V</b>	<b>2006-09</b>
BTS	77 105
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Ibiza IV (6L1) 1.8 T Cupra R</b>	<b>2004-08</b>
BBU/BLZ	132 180
Ignition Coil	<b>80202</b>
<b>Ibiza IV (6L1) 1.8 T FR</b>	<b>2003-08</b>
BKV/BJX	110 150
Ignition Coil	<b>80202</b>
<b>Ibiza IV (6L1) 2.0</b>	<b>2002-09</b>
AZL/BBX	85 116
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Ibiza V (6J5) 1.2</b>	<b>2008-&gt;</b>
CJLB/BZG/CGPA	51 70
Ignition Coil	<b>80201</b>
<b>Ibiza V (6J5) 1.2</b>	<b>2009-&gt;</b>
CGPB	44 60
Ignition Coil	<b>80201</b>
<b>Ibiza V (6J5) 1.2 TSI</b>	<b>2010-&gt;</b>
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Ibiza V (6J5) 1.2 TSI</b>	<b>2012-&gt;</b>
CBZA	63 86
Ignition Coil ->05.2015	<b>80218</b>
<b>Ibiza V (6J5) 1.4</b>	<b>2008-&gt;</b>
CGGB/BXW	63 85
Ignition Coil	<b>80201</b>
<b>Ibiza V (6J5) 1.4 TSI</b>	<b>2013-&gt;</b>
CPTA	103 140
Ignition Coil	<b>80249</b>
<b>Ibiza V (6J5) 1.4 TSI</b>	<b>2009-&gt;</b>
CAVF/CTHF/CNUB/CTJB	110 150
Ignition Coil	<b>80201</b>
<b>Ibiza V (6J5) 1.6</b>	<b>2008-&gt;</b>
BTS	77 105
Ignition Coil	<b>80201</b>
<b>Ibiza V (6J5) 1.6 LPG</b>	<b>2011-&gt;</b>
CNKA	60 81
Ignition Coil ->05.2015	<b>80201</b>
<b>Ibiza V (6J5, 6P1) 1.0</b>	<b>2015-&gt;</b>
CHYB	55 75
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V (6J5, 6P1) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZC	81 110
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V (6J5, 6P1) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZB	70 95
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V (6J5, 6P1) 1.2 TSI</b>	<b>2015-&gt;</b>
CJZC	66 90
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V Sportcoupe (6J1) 1.2</b>	<b>2008-&gt;</b>
CJLB/BZG/CGPA	51 70
Ignition Coil	<b>80201</b>

SEAT Cont.	
<b>Ibiza V Sportcoupe (6J1) 1.2</b>	<b>2009-&gt;</b>
CGPB	44 60
Ignition Coil	<b>80201</b>
<b>Ibiza V Sportcoupe (6J1) 1.2 TSI</b>	<b>2012-&gt;</b>
CBZA	63 86
Ignition Coil ->05.2015	<b>80218</b>
<b>Ibiza V Sportcoupe (6J1) 1.2 TSI</b>	<b>2010-&gt;</b>
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Ibiza V Sportcoupe (6J1) 1.4</b>	<b>2008-&gt;</b>
CGGB/BXW	63 85
Ignition Coil	<b>80201</b>
<b>Ibiza V Sportcoupe (6J1) 1.4 TSI</b>	<b>2013-&gt;</b>
CPTA	103 140
Ignition Coil	<b>80249</b>
<b>Ibiza V Sportcoupe (6J1) 1.4 TSI</b>	<b>2009-&gt;</b>
CAVF/CTHF/CNUB/CTJB	110 150
Ignition Coil	<b>80201</b>
<b>Ibiza V Sportcoupe (6J1) 1.4 TSI Cupra</b>	<b>2009-&gt;</b>
CTJC/CAVE/CTHE	132 180
Ignition Coil	<b>80201</b>
<b>Ibiza V Sportcoupe (6J1) 1.6</b>	<b>2008-&gt;</b>
BTS	77 105
Ignition Coil	<b>80201</b>
<b>Ibiza V Sportcoupe (6J1) 1.6 LPG</b>	<b>2011-&gt;</b>
CNKA	60 81
Ignition Coil ->05.2015	<b>80201</b>
<b>Ibiza V Sportcoupe (6J1, 6P5) 1.0</b>	<b>2015-&gt;</b>
CHYB	55 75
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V Sportcoupe (6J1, 6P5) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZB	70 95
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V Sportcoupe (6J1, 6P5) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZC	81 110
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V Sportcoupe (6J1, 6P5) 1.2 TSI</b>	<b>2015-&gt;</b>
CJZC	66 90
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V ST (6J8) 1.2</b>	<b>2010-&gt;</b>
CGPB	44 60
Ignition Coil	<b>80201</b>
<b>Ibiza V ST (6J8) 1.2</b>	<b>2010-&gt;</b>
CJLB/BZG/CGPA	51 70
Ignition Coil	<b>80201</b>
<b>Ibiza V ST (6J8) 1.2 TSI</b>	<b>2010-&gt;</b>
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Ibiza V ST (6J8) 1.2 TSI</b>	<b>2012-&gt;</b>
CBZA	63 86
Ignition Coil ->05.2015	<b>80218</b>
<b>Ibiza V ST (6J8) 1.4</b>	<b>2010-&gt;</b>
CGGB	63 85
Ignition Coil	<b>80201</b>
<b>Ibiza V ST (6J8) 1.4 TSI</b>	<b>2013-&gt;</b>
CPTA	103 140
Ignition Coil	<b>80249</b>
<b>Ibiza V ST (6J8) 1.4 TSI</b>	<b>2012-&gt;</b>
CAVF/CTHF/CNUB/CTJB	110 150
Ignition Coil 04.2012-05.2015	<b>80201</b>
<b>Ibiza V ST (6J8, 6P8) 1.0</b>	<b>2015-&gt;</b>
CHYB	55 75
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V ST (6J8, 6P8) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZB	70 95
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V ST (6J8, 6P8) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZC	81 110
Ignition Coil ->06.2015	<b>80249</b>
<b>Ibiza V ST (6J8, 6P8) 1.2 TSI</b>	<b>2015-&gt;</b>
CJZC	66 90
Ignition Coil ->06.2015	<b>80249</b>
<b>Inca (6K9) 1.4 16V</b>	<b>2000-03</b>
AUA	55 75
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>





SEAT Cont.		
<b>Inca (6K9) 1.4 i</b>		<b>1995-03</b>
AEX/AKV/APQ/AUD	44	60
Ignition Coil With regul.cat.(3way)		<b>80200</b>
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85681</b>
Ignition Leads AEX/AKV		<b>85693</b>
<b>Inca (6K9) 1.6 i</b>		<b>1997-00</b>
ALM/AEE	55	75
Ignition Coil AEE		<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
Ignition Leads		<b>85693</b>
<b>Inca (6K9) 1.6 i</b>		<b>1995-98</b>
1F	55	75
Ignition Coil		<b>80200</b>
Ignition Leads ->05.1997		<b>85685</b>
Ignition Leads		<b>85691</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
<b>Leon (1M1) 1.4 16V</b>		<b>1999-06</b>
AHW/AXP/BCA/APE/AUA	55	75
Ignition Coil BCA		<b>80201</b>
Ignition Coil APE/AXP/BCA/AHW		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Leon (1M1) 1.6</b>		<b>1999-06</b>
AKL/APF/AEH	74	100
Ignition Coil AKL/AEH		<b>80218</b>
Ignition Leads AKL/AEH		<b>85875</b>
<b>Leon (1M1) 1.6</b>		<b>2005-06</b>
BGU/BFQ	75	102
Ignition Coil		<b>80218</b>
<b>Leon (1M1) 1.6 16 V</b>		<b>2000-06</b>
AUS/ATN/BCB/AZD	77	105
Ignition Coil AZD/BCB		<b>80201</b>
Ignition Coil AUS; ->04.2001		<b>80218</b>
Ignition Leads AUS		<b>85696</b>
<b>Leon (1M1) 1.8 20V</b>		<b>1999-06</b>
AGN/APG	92	125
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85065</b>
<b>Leon (1M1) 1.8 20V T</b>		<b>1999-06</b>
APP/AUQ	132	180
Ignition Coil With regul.cat.(3way)		<b>80202</b>
Ignition Coil AUQ,APP		<b>80239</b>
<b>Leon (1M1) 1.8 20V T 4</b>		<b>1999-06</b>
AJQ/ARY	132	180
Ignition Coil ARY; 09.2000-04.2004		<b>80202</b>
Ignition Coil AJQ		<b>80239</b>
Ignition Coil		<b>80252</b>
<b>Leon (1M1) 1.8 T Cupra R</b>		<b>2002-06</b>
AMK	154	209
Ignition Coil With regul.cat.(3way)		<b>80202</b>
<b>Leon (1M1) 1.8 T Cupra R</b>		<b>2003-06</b>
BAM	165	225
Ignition Coil Intake manifold injection		<b>80202</b>
<b>Leon (1M1) 2.8 Cupra 4</b>		<b>2001-06</b>
AUE	150	204
Ignition Coil		<b>80327</b>
<b>Leon (1P1) 1.2 TSI</b>		<b>2010-12</b>
CBZB	77	105
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85871</b>
<b>Leon (1P1) 1.4 16V</b>		<b>2006-12</b>
CGGB/BXW	63	86
Ignition Coil		<b>80201</b>
<b>Leon (1P1) 1.4 TSI</b>		<b>2007-12</b>
CAXC	92	125
Ignition Coil		<b>80201</b>
<b>Leon (1P1) 1.6</b>		<b>2005-12</b>
CCSA/BSF/CMXA/BSE	75	102
Ignition Coil BSE/BSF		<b>80218</b>
Ignition Leads		<b>85875</b>
<b>Leon (1P1) 1.6 LPG</b>		<b>2009-12</b>
CHGA	75	102
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85879</b>
<b>Leon (1P1) 1.8 TSI</b>		<b>2007-12</b>
BZB/CDA	118	160
Ignition Coil		<b>80240</b>

SEAT Cont.		
<b>Leon (1P1) 2.0 FSI</b>		<b>2005-10</b>
BLR/BLY/BVZ/BVY	110	150
Ignition Coil BLY,BVY,BVZ,BLR		<b>80240</b>
<b>Leon (1P1) 2.0 TFSI</b>		<b>2005-06</b>
BWA1	136	185
Ignition Coil		<b>80240</b>
<b>Leon (1P1) 2.0 TFSI</b>		<b>2005-09</b>
BWA	147	200
Ignition Coil BWA		<b>80240</b>
<b>Leon (1P1) 2.0 TFSI</b>		<b>2006-11</b>
BWJ/CDLD	177	240
Ignition Coil		<b>80240</b>
<b>Leon (1P1) 2.0 TFSI</b>		<b>2009-12</b>
CCZB	155	211
Ignition Coil		<b>80240</b>
<b>Leon (5F1) 1.0 TSI</b>		<b>2015-&gt;</b>
CHZD	85	115
Ignition Coil		<b>80249</b>
<b>Leon (5F1) 1.2 TSI</b>		<b>2014-&gt;</b>
CYVB	81	110
Ignition Coil		<b>80249</b>
<b>Leon (5F1) 1.2 TSI</b>		<b>2012-&gt;</b>
CJZB/CYVA	63	86
Ignition Coil		<b>80249</b>
<b>Leon (5F1) 1.2 TSI</b>		<b>2013-&gt;</b>
CJZA	77	105
Ignition Coil		<b>80249</b>
<b>Leon (5F1) 1.4 TGI</b>		<b>2013-&gt;</b>
CPWA	81	110
Ignition Coil		<b>80249</b>
<b>Leon (5F1) 1.4 TSI</b>		<b>2014-&gt;</b>
CZCA	92	125
Ignition Coil		<b>80249</b>
<b>Leon (5F1) 1.4 TSI</b>		<b>2014-&gt;</b>
CZEA	110	150
Ignition Coil		<b>80249</b>
<b>Leon (5F1) 1.4 TSI</b>		<b>2012-&gt;</b>
CMBA/CXSA	90	122
Ignition Coil CMBA; ->06.2013		<b>80249</b>
<b>Leon (5F1) 1.4 TSI</b>		<b>2012-&gt;</b>
CHPA/CPTA	103	140
Ignition Coil		<b>80249</b>
<b>Leon (5F1) 1.8 TSI</b>		<b>2013-&gt;</b>
CJSA	132	180
Ignition Coil		<b>80238</b>
<b>Leon SC (5F5) 1.0 TSI</b>		<b>2015-&gt;</b>
CHZD	85	115
Ignition Coil		<b>80249</b>
<b>Leon SC (5F5) 1.2 TSI</b>		<b>2014-&gt;</b>
CYVB	81	110
Ignition Coil		<b>80249</b>
<b>Leon SC (5F5) 1.2 TSI</b>		<b>2013-&gt;</b>
CJZB/CYVA	63	86
Ignition Coil		<b>80249</b>
<b>Leon SC (5F5) 1.2 TSI</b>		<b>2013-&gt;</b>
CJZA	77	105
Ignition Coil		<b>80249</b>
<b>Leon SC (5F5) 1.4 TSI</b>		<b>2014-&gt;</b>
CZCA	92	125
Ignition Coil		<b>80249</b>
<b>Leon SC (5F5) 1.4 TSI</b>		<b>2014-&gt;</b>
CZEA	110	150
Ignition Coil		<b>80249</b>
<b>Leon SC (5F5) 1.4 TSI</b>		<b>2013-&gt;</b>
CMBA/CXSA	90	122
Ignition Coil		<b>80249</b>
<b>Leon SC (5F5) 1.4 TSI</b>		<b>2013-&gt;</b>
CHPA/CPTA	103	140
Ignition Coil		<b>80249</b>
<b>Leon SC (5F5) 1.8 TSI</b>		<b>2013-&gt;</b>
CJSA	132	180
Ignition Coil		<b>80238</b>
<b>Leon ST (5F8) 1.0 TSI</b>		<b>2015-&gt;</b>
CHZD	85	115
Ignition Coil		<b>80249</b>
<b>Leon ST (5F8) 1.2 TSI</b>		<b>2014-&gt;</b>
CYVB	81	110
Ignition Coil		<b>80249</b>



SEAT Cont.	
<b>Leon ST (5F8) 1.2 TSI</b>	2013->
CJZA	77 105
Ignition Coil	<b>80249</b>
<b>Leon ST (5F8) 1.2 TSI</b>	2013->
CJZB/CYVA	63 86
Ignition Coil	<b>80249</b>
<b>Leon ST (5F8) 1.4 TGI</b>	2013->
CPWA	81 110
Ignition Coil	<b>80249</b>
<b>Leon ST (5F8) 1.4 TSI</b>	2014->
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Leon ST (5F8) 1.4 TSI</b>	2014->
CZEA	110 150
Ignition Coil	<b>80249</b>
<b>Leon ST (5F8) 1.4 TSI</b>	2013->
CHPA/CPTA	103 140
Ignition Coil	<b>80249</b>
<b>Leon ST (5F8) 1.4 TSI</b>	2013->
CMBA/CXSA	90 122
Ignition Coil	<b>80249</b>
<b>Leon ST (5F8) 1.8 TSI</b>	2013->
CJSA	132 180
Ignition Coil	<b>80238</b>
<b>Malaga (023A) 1.2</b>	1985-93
021 A 1000	44 60
Ignition Leads	<b>83110</b>
<b>Malaga (023A) 1.2</b>	1984-93
021 A 1000	47 64
Ignition Leads	<b>83110</b>
<b>Malaga (023A) 1.2 i</b>	1989-93
021 C.1000	52 71
Ignition Leads	<b>83110</b>
<b>Malaga (023A) 1.5</b>	1985-93
021 A 2000	63 85
Ignition Leads	<b>83110</b>
<b>Malaga (023A) 1.5 i</b>	1987-93
021 B.2000	74 100
Ignition Leads	<b>83110</b>
<b>Malaga (023A) 1.5 i KAT</b>	1986-93
021 A 2000/021 C.2000/021 D.2000	66 90
Ignition Leads	<b>83110</b>
<b>Marbella (28) 0.8</b>	1986-93
08 NCA	25 34
Ignition Leads ->05.1989	<b>83030</b>
<b>Marbella (28) 0.9</b>	1997-98
08 NCB	32 44
Ignition Coil	<b>80232</b>
Ignition Leads	<b>83330</b>
<b>Marbella (28) 0.9</b>	1987-93
100 GL 7000/09 NCA	29 40
Ignition Coil	<b>80232</b>
Ignition Leads	<b>83030</b>
Ignition Leads 01.1992->	<b>83330</b>
<b>Marbella (28) 0.9 KAT</b>	1990-96
100 GL 7000/09 NCB	29 40
Ignition Coil	<b>80232</b>
Ignition Leads 01.1992->	<b>83330</b>
<b>Marbella (28) 0.9 KAT</b>	1996-98
08 NCB	30 41
Ignition Coil	<b>80232</b>
Ignition Leads	<b>83330</b>
Ignition Leads	<b>85130</b>
<b>Marbella Van (028A) 0.9</b>	1987-93
09 NCA	29 40
Ignition Coil	<b>80232</b>
Ignition Leads 01.1992->	<b>83330</b>
<b>Marbella Van (028A) 0.9 KAT</b>	1987-93
09 NCB	29 40
Ignition Coil	<b>80232</b>
Ignition Leads 01.1992->	<b>83330</b>
<b>Mii (KF1) 1.0</b>	2011->
CHYA	44 60
Ignition Coil	<b>80249</b>
<b>Mii (KF1) 1.0</b>	2011->
CHYB	55 75
Ignition Coil	<b>80249</b>

SEAT Cont.	
<b>Mii (KF1) 1.0 EcoFuel</b>	2012->
CPGA	50 68
Ignition Coil	<b>80249</b>
<b>Panda (141A) 0.9</b>	1980-86
100 GL 3000	31 42
Ignition Leads	<b>83030</b>
<b>Ronda (022A) 1.2</b>	1983-85
021 A 1000/124 B6.000	47 64
Ignition Leads 021 A 1000	<b>83030</b>
<b>Ronda (022A) 1.4</b>	1982-88
124 B7.000	54 73
Ignition Leads 124 B 7000	<b>83030</b>
<b>Ronda (022A) 1.6</b>	1983-85
138 AR6.000/022 A 000	68 92
Ignition Leads	<b>83030</b>
<b>Terra (24) 0.9</b>	1987-96
09 NCA	29 40
Ignition Coil	<b>80232</b>
Ignition Leads	<b>83030</b>
Ignition Leads 01.1992->	<b>83330</b>
<b>Terra (24) 0.9 KAT</b>	1992-94
09 NCB	29 40
Ignition Coil 09 NCB	<b>80232</b>
Ignition Leads	<b>83030</b>
Ignition Leads	<b>83330</b>
<b>Terra Van (024A) 0.9</b>	1987-95
09 NCA	29 40
Ignition Coil	<b>80232</b>
Ignition Leads	<b>83030</b>
Ignition Leads 01.1992->	<b>83330</b>
<b>Terra Van (024A) 0.9 KAT</b>	1990-95
09 NCB	29 40
Ignition Coil	<b>80232</b>
Ignition Leads	<b>83030</b>
Ignition Leads 01.1992->	<b>83330</b>
<b>Toledo I (1L) 1.6 i</b>	1991-99
EZ/ABN/1F	54 73
Ignition Coil 3 term.; Ch.1L-ZR001001->	<b>80200</b>
Ignition Coil 6 term.	<b>80219</b>
Ignition Leads	<b>85685</b>
Ignition Leads Ch.1L-ZD304851->	<b>85690</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
Ignition Leads ABN;->Ch.1L-ZD304850	<b>85865</b>
<b>Toledo I (1L) 1.6 i</b>	1991-93
1F	52 71
Ignition Coil 3 term.; Ch.1L-ZR001001->	<b>80200</b>
Ignition Coil 6 term.	<b>80219</b>
Ignition Leads	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo I (1L) 1.6 i</b>	1993-99
1F	55 75
Ignition Coil 3 term.; Ch.1L-ZR001001->	<b>80200</b>
Ignition Coil 6 term.	<b>80219</b>
Ignition Leads	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo I (1L) 1.6 i</b>	1996-99
AFT	74 101
Ignition Coil 3 term.	<b>80200</b>
Ignition Coil 6 term.	<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo I (1L) 1.8 16V</b>	1991-99
KR	98 133
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo I (1L) 1.8 16V</b>	1991-99
PL	92 125
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
Ignition Leads ->Ch.1L-ZD304850	<b>85865</b>
<b>Toledo I (1L) 1.8 i</b>	1991-96
RP	65 88
Ignition Leads ->11.1993	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.1L-ZD304850	<b>85865</b>



SEAT Cont.		
<b>Toledo I (1L) 1.8 i</b>		<b>1993-96</b>
ACC/ADZ/ABS		66 90
Ignition Coil	3 term.; ADZ,ABS	<b>80200</b>
Ignition Coil	ADZ, ABS; 6 term.; With regul.cat.(3way)	<b>80219</b>
Ignition Leads	ADZ; ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads		<b>85690</b>
Ignition Leads	ABS; ->Ch.6KZR510001, ZR010001	<b>85692</b>
Ignition Leads	->Ch.1L-ZD304850	<b>85865</b>
<b>Toledo I (1L) 1.9 D</b>		<b>1991-99</b>
1Y		50 68
Ignition Leads	->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo I (1L) 1.9 D</b>		<b>1995-99</b>
1Y		47 64
Ignition Leads	->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo I (1L) 1.9 TD</b>		<b>1991-99</b>
AAZ		55 75
Ignition Leads	->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo I (1L) 1.9 TDI</b>		<b>1995-99</b>
1Z/AHU		66 90
Ignition Leads	->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo I (1L) 1.9 TDI</b>		<b>1996-99</b>
AFN		81 110
Ignition Leads	->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo I (1L) 2.0 i</b>		<b>1991-99</b>
2E/AGG		85 115
Ignition Coil	3 term.; Ch.1L-ZR001001->; 01.1993->	<b>80200</b>
Ignition Coil	6 term.; ->Ch.1L-ZR001000; With regul.cat.(3way)	<b>80219</b>
Ignition Leads	AGG; ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads		<b>85690</b>
Ignition Leads	2E; ->Ch.6KZR510001, ZR010001	<b>85692</b>
Ignition Leads	2E	<b>85865</b>
<b>Toledo I (1L) 2.0 i 16V</b>		<b>1993-99</b>
ABF		110 150
Ignition Coil	3 term.; Ch.1L-ZR-001001->; 03.1994->	<b>80200</b>
Ignition Coil	6 term.; ->Ch.1L-ZR001000; 03.1994->	<b>80219</b>
Ignition Leads		<b>85059</b>
Ignition Leads	->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Toledo II (1M2) 1.4 16V</b>		<b>2000-02</b>
AHW/AXP/BCA/APE/AUA		55 75
Ignition Coil	AHW/AXP	<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Toledo II (1M2) 1.6</b>		<b>1998-04</b>
AKL/APF/AEH		74 100
Ignition Coil	AEH/AKL	<b>80218</b>
Ignition Leads	AKL/AEH	<b>85875</b>
<b>Toledo II (1M2) 1.6 16V</b>		<b>2000-06</b>
AUS/BCB/AZD		77 105
Ignition Coil	AUS/AZD; ->04.2001	<b>80201</b>
Ignition Coil	AUS/AZD	<b>80218</b>
Ignition Leads	AUS	<b>85696</b>
<b>Toledo II (1M2) 1.8 20V</b>		<b>1998-04</b>
AGN/APG		92 125
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85065</b>
<b>Toledo II (1M2) 1.8 20VT</b>		<b>2000-04</b>
APP/AUQ		132 180
Ignition Coil	AUQ; With regul.cat.(3way)	<b>80202</b>
Ignition Coil	AUQ	<b>80239</b>
<b>Toledo III (5P2) 1.4 16V</b>		<b>2006-09</b>
BXW		63 86
Ignition Coil		<b>80201</b>
<b>Toledo III (5P2) 1.6</b>		<b>2004-09</b>
BGU/CCSA/BSF/BSE		75 102
Ignition Coil	BSE/BSF/BGU	<b>80218</b>
Ignition Leads		<b>85875</b>
<b>Toledo III (5P2) 2.0 FSI</b>		<b>2004-09</b>
BLR/BLY/BVZ/BVY		110 150
Ignition Coil	BLY,BLR	<b>80240</b>
<b>Toledo III (5P2) 2.0 TFSI</b>		<b>2005-09</b>
BWA		147 200
Ignition Coil		<b>80240</b>
<b>Toledo IV (KG3) 1.2</b>		<b>2012-&gt;</b>
CGPC		55 75
Ignition Coil	->06.2015	<b>80201</b>
<b>Toledo IV (KG3) 1.2 TSI</b>		<b>2015-&gt;</b>
CJZC		66 90
Ignition Coil		<b>80249</b>

SEAT Cont.		
<b>Toledo IV (KG3) 1.2 TSI</b>		<b>2015-&gt;</b>
CJZD		81 110
Ignition Coil		<b>80249</b>
<b>Toledo IV (KG3) 1.2 TSI</b>		<b>2012-&gt;</b>
CBZA		63 86
Ignition Coil	->06.2015	<b>80218</b>
<b>Toledo IV (KG3) 1.2 TSI</b>		<b>2012-&gt;</b>
CBZB		77 105
Ignition Coil	->06.2015	<b>80218</b>
<b>Toledo IV (KG3) 1.4 TSI</b>		<b>2015-&gt;</b>
CZCA		92 125
Ignition Coil		<b>80249</b>
<b>Toledo IV (KG3) 1.4 TSI</b>		<b>2012-&gt;</b>
CAXA		90 122
Ignition Coil	->06.2015	<b>80201</b>
<b>Toledo IV (KG3) 1.6</b>		<b>2013-&gt;</b>
CFNA		77 105
Ignition Coil	->06.2015	<b>80201</b>
<b>SKODA</b>		
<b>Citigo 1.0</b>		<b>2011-&gt;</b>
CHYA		44 60
Ignition Coil	->01.2015	<b>80249</b>
<b>Citigo 1.0</b>		<b>2011-&gt;</b>
CHYB		55 75
Ignition Coil		<b>80249</b>
<b>Citigo 1.0 CNG</b>		<b>2012-&gt;</b>
CPGA		50 68
Ignition Coil	->01.2015	<b>80249</b>
<b>Fabia (6Y2) 1.0</b>		<b>1999-02</b>
AQV/ARV		37 50
Ignition Leads		<b>85681</b>
<b>Fabia (6Y2) 1.2</b>		<b>2002-08</b>
AWY/BMD		40 54
Ignition Coil		<b>80326</b>
<b>Fabia (6Y2) 1.2</b>		<b>2003-08</b>
AZQ/BME		47 64
Ignition Coil	->04.2007; Intake manifold injection	<b>80201</b>
<b>Fabia (6Y2) 1.4</b>		<b>2000-02</b>
AZF/AZE		44 60
Ignition Leads		<b>85681</b>
<b>Fabia (6Y2) 1.4 16V</b>		<b>1999-08</b>
BBZ/AUB		74 100
Ignition Coil	Ch.6Y-2-535 495->; 05.2002-04.2007	<b>80201</b>
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Fabia (6Y2) 1.4 16V</b>		<b>1999-08</b>
BBY/BKY/AUA		55 75
Ignition Coil	Ch.6Y-2-535 495->; 05.2002-04.2007	<b>80201</b>
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Fabia (6Y2) 2.0</b>		<b>1999-08</b>
AZL		85 116
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85875</b>
<b>Fabia (NJ3) 1.0</b>		<b>2014-&gt;</b>
CHYA		44 60
Ignition Coil		<b>80249</b>
<b>Fabia (NJ3) 1.0</b>		<b>2014-&gt;</b>
CHYB		55 75
Ignition Coil		<b>80249</b>
<b>Fabia (NJ3) 1.2 TSI</b>		<b>2014-&gt;</b>
CJZC		66 90
Ignition Coil		<b>80249</b>
<b>Fabia (NJ3) 1.2 TSI</b>		<b>2014-&gt;</b>
CJZD		81 110
Ignition Coil		<b>80249</b>
<b>Fabia (NJ3) 1.6</b>		<b>2015-&gt;</b>
CWVA		81 110
Ignition Coil		<b>80249</b>
<b>Fabia 1.2</b>		<b>2006-14</b>
BBM/CHFA		44 60
Ignition Coil	->11.2011	<b>80326</b>
<b>Fabia 1.2</b>		<b>2007-14</b>
CEVA/BZG/CGPA/CHTA		51 70
Ignition Coil	BZG; Intake manifold injection	<b>80201</b>



SKODA Cont.	
<b>Fabia 1.2 12V</b>	2011-14
CGPB	44 60
Ignition Coil	<b>80201</b>
Ignition Coil	<b>80326</b>
<b>Fabia 1.2 TSI</b>	2010-14
CBZB	77 105
Ignition Coil	<b>80218</b>
<b>Fabia 1.2 TSI</b>	2010-14
CBZA	63 86
Ignition Coil	<b>80218</b>
<b>Fabia 1.4</b>	2007-14
CGGB/BXW	63 86
Ignition Coil BXW; Intake manifold injection	<b>80201</b>
<b>Fabia 1.4 TSI RS</b>	2010-14
CAVE/CTHE	132 180
Ignition Coil	<b>80201</b>
<b>Fabia 1.6</b>	2007-14
BTS/CFNA/CLSA	77 105
Ignition Coil BTS; Intake manifold injection	<b>80201</b>
<b>Fabia Combi (6Y5) 1.2</b>	2003-07
AZQ/BME	47 64
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Fabia Combi (6Y5) 1.2</b>	2001-07
AWY/BMD	40 54
Ignition Coil 08.2002->	<b>80326</b>
<b>Fabia Combi (6Y5) 1.4</b>	2000-03
AME/ATZ/AQW	50 68
Ignition Leads	<b>85681</b>
<b>Fabia Combi (6Y5) 1.4</b>	2000-03
AZF/AZE	44 60
Ignition Leads	<b>85681</b>
<b>Fabia Combi (6Y5) 1.4 16V</b>	2000-07
BBY/BKY/AUA	55 75
Ignition Coil Ch.6Y-2-535 495->; 05.2002->	<b>80201</b>
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Fabia Combi (6Y5) 1.4 16V</b>	2000-07
BBZ/AUB	74 100
Ignition Coil Ch.6Y-2-535 495->; 05.2002->	<b>80201</b>
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Fabia Combi (6Y5) 1.4 16V</b>	2006-07
BUD	59 80
Ignition Coil	<b>80201</b>
<b>Fabia Combi (6Y5) 2.0</b>	2000-07
AZL	85 116
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Fabia Combi (NJ5) 1.0</b>	2014->
CHYB	55 75
Ignition Coil	<b>80249</b>
<b>Fabia Combi (NJ5) 1.0</b>	2014->
CHYA	44 60
Ignition Coil	<b>80249</b>
<b>Fabia Combi (NJ5) 1.2 TSI</b>	2014->
CJZC	66 90
Ignition Coil	<b>80249</b>
<b>Fabia Combi (NJ5) 1.2 TSI</b>	2014->
CJZD	81 110
Ignition Coil	<b>80249</b>
<b>Fabia Combi 1.2</b>	2007-14
CEVA/BZG/CGPA/CHTA	51 70
Ignition Coil BZG; Intake manifold injection	<b>80201</b>
<b>Fabia Combi 1.2</b>	2007-14
BBM/CHFA	44 60
Ignition Coil ->11.2011	<b>80326</b>
<b>Fabia Combi 1.2 12V</b>	2011-14
CGPB	44 60
Ignition Coil	<b>80201</b>
Ignition Coil	<b>80326</b>
<b>Fabia Combi 1.2 TSI</b>	2010-14
CBZB	77 105
Ignition Coil	<b>80218</b>
<b>Fabia Combi 1.2 TSI</b>	2010-14
CBZA	63 86
Ignition Coil	<b>80218</b>
<b>Fabia Combi 1.4</b>	2007-14
CGGB/BXW	63 86
Ignition Coil BXW; Intake manifold injection	<b>80201</b>

SKODA Cont.	
<b>Fabia Combi 1.4 TSI RS</b>	2010-14
CAVE/CTHE	132 180
Ignition Coil	<b>80201</b>
<b>Fabia Combi 1.6</b>	2007-14
BTS/CFNA	77 105
Ignition Coil BTS; Intake manifold injection	<b>80201</b>
<b>Fabia Praktik 1.2</b>	2003-07
AZQ/BME	47 64
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Fabia Praktik 1.2</b>	2001-07
AWY/BMD	40 54
Ignition Coil 08.2002->	<b>80326</b>
<b>Fabia Sedan (6Y3) 1.2</b>	2003-07
AZQ/BME	47 64
Ignition Coil ->11.2004; Intake manifold injection	<b>80201</b>
<b>Fabia Sedan (6Y3) 1.2</b>	2001-07
AWY/BMD	40 54
Ignition Coil	<b>80326</b>
<b>Fabia Sedan (6Y3) 1.4</b>	2000-02
AZF/AZE	44 60
Ignition Leads	<b>85681</b>
<b>Fabia Sedan (6Y3) 1.4 16V</b>	1999-07
BBY/BKY/AUA	55 75
Ignition Coil Ch.6Y-2-535 495->; 05.2002->	<b>80201</b>
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Fabia Sedan (6Y3) 1.4 16V</b>	1999-07
BBZ/AUB	74 100
Ignition Coil Ch.6Y-2-535 495->; 05.2002->	<b>80201</b>
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Fabia Sedan (6Y3) 1.4 16V</b>	2006-07
BUD	59 80
Ignition Coil	<b>80201</b>
<b>Fabia Sedan (6Y3) 2.0</b>	1999-07
AZL	85 116
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Favorit (781) 1,3</b>	1994-94
136B	50 68
Ignition Coil	<b>80200</b>
<b>Favorit (781) 1.3 135</b>	1990-94
781.135	44 60
Ignition Coil	<b>80200</b>
<b>Favorit (781) 1.3 135</b>	1991-94
781.135	42 57
Ignition Coil	<b>80200</b>
<b>Favorit (781) 1.3 135</b>	1991-94
781.135	43 58
Ignition Coil	<b>80200</b>
<b>Favorit (781) 1.3 135 X,LX,GLX</b>	1990-94
781.135E	40 54
Ignition Coil	<b>80200</b>
<b>Favorit (781) 1.3 135L</b>	1989-94
781.135	43 58
Ignition Coil	<b>80200</b>
<b>Favorit (781) 1.3 136</b>	1990-94
136 L	45 61
Ignition Coil	<b>80200</b>
<b>Favorit Forman (785) 1,3</b>	1991-95
781135	44 60
Ignition Coil 09.1994->	<b>80200</b>
<b>Favorit Forman (785) 1,3</b>	1991-95
OHC	45 61
Ignition Coil 09.1994->	<b>80200</b>
<b>Favorit Forman (785) 1,3</b>	1991-95
781.135E	40 54
Ignition Coil	<b>80200</b>
<b>Favorit Forman (785) 1.3</b>	1994-95
136B	50 68
Ignition Coil	<b>80200</b>
<b>Favorit Pick-Up (787) 1.3</b>	1992-97
136B	50 68
Ignition Coil	<b>80200</b>
<b>Favorit Pick-Up (787) 1.3</b>	1992-97
135B	40 54
Ignition Coil	<b>80200</b>



SKODA Cont.		
<b>Favorit Pick-Up (787) 1.3</b>	1992-97	
781.135	42 57	
Ignition Coil	<b>80200</b>	
<b>Felicia I (6U1) 1.3</b>	1994-98	
AMJ/135 L	43 58	
Ignition Coil	<b>80200</b>	
<b>Felicia I (6U1) 1.3</b>	1994-98	
135B/AMG	40 54	
Ignition Coil	<b>80200</b>	
<b>Felicia I (6U1) 1.3</b>	1994-98	
136B/AMH	50 68	
Ignition Coil	<b>80200</b>	
<b>Felicia I (6U1) 1.6 LX</b>	1995-98	
EA111/AEE	55 75	
Ignition Coil AEE	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>	
<b>Felicia I Fun (797) 1.3</b>	1997-02	
136B/136M/AMH	50 68	
Ignition Coil	<b>80200</b>	
<b>Felicia I Fun (797) 1.3</b>	1997-02	
135B/135M/AMG	40 54	
Ignition Coil	<b>80200</b>	
<b>Felicia I Fun (797) 1.6</b>	1997-02	
AEE	55 75	
Ignition Coil	<b>80200</b>	
<b>Felicia I Kombi (6U5) 1.3</b>	1995-98	
AMJ/135 L	43 58	
Ignition Coil	<b>80200</b>	
<b>Felicia I Kombi (6U5) 1.3 LX</b>	1995-98	
135B/AMG	40 54	
Ignition Coil	<b>80200</b>	
<b>Felicia I Kombi (6U5) 1.3 LXI</b>	1995-98	
136B/AMH	50 68	
Ignition Coil	<b>80200</b>	
<b>Felicia I Kombi (6U5) 1.6 GLX</b>	1995-98	
AEE	55 75	
Ignition Coil	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>	
<b>Felicia II (6U1) 1.3</b>	1998-01	
AMG	40 54	
Ignition Coil	<b>80200</b>	
<b>Felicia II (6U1) 1.3</b>	1998-01	
AMH	50 68	
Ignition Coil	<b>80200</b>	
<b>Felicia II (6U1) 1.3</b>	1998-01	
AMJ	43 58	
Ignition Coil	<b>80200</b>	
<b>Felicia II (6U1) 1.6</b>	1998-01	
AEE	55 75	
Ignition Coil	<b>80200</b>	
<b>Felicia II Kombi (6U5) 1.3</b>	1998-01	
AMH	50 68	
Ignition Coil	<b>80200</b>	
<b>Felicia II Kombi (6U5) 1.6</b>	1998-01	
AEE	55 75	
Ignition Coil	<b>80200</b>	
<b>Octavia (1U2) 1.4</b>	1999-01	
AMD	44 60	
Ignition Leads	<b>85681</b>	
<b>Octavia (1U2) 1.4 16V</b>	2000-10	
AXP/BCA	55 75	
Ignition Coil Ch.1U-2-624 899->; 03.2002->	<b>80201</b>	
Ignition Coil	<b>80218</b>	
Ignition Leads	<b>85696</b>	
<b>Octavia (1U2) 1.6</b>	2000-10	
AVU/BFQ	75 102	
Ignition Coil	<b>80218</b>	
Ignition Leads	<b>85875</b>	
<b>Octavia (1U2) 1.6</b>	1996-04	
AEE	55 75	
Ignition Coil	<b>80200</b>	
Ignition Leads	<b>85693</b>	
<b>Octavia (1U2) 1.6</b>	1997-07	
AKL/AEH	74 101	
Ignition Coil	<b>80218</b>	
Ignition Leads Ch.1V-W-060001->	<b>85875</b>	

SKODA Cont.		
<b>Octavia (1U2) 1.8</b>	1996-00	
AGN	92 125	
Ignition Coil	<b>80218</b>	
Ignition Leads	<b>85065</b>	
<b>Octavia (1U2) 1.8 T</b>	1997-10	
ARX/ARZ/AGU/AUM	110 150	
Ignition Coil With regul.cat.(3way)	<b>80202</b>	
Ignition Coil Hydraulic Brake	<b>80239</b>	
Ignition Coil ARZ,ARX,AGU,AUM	<b>80252</b>	
<b>Octavia (1U2) 1.8 T 4x4</b>	2001-06	
ARX	110 150	
Ignition Coil With regul.cat.(3way)	<b>80202</b>	
Ignition Coil Hydraulic Brake	<b>80239</b>	
Ignition Coil	<b>80252</b>	
<b>Octavia (1U2) 2.0</b>	1999-07	
APK/AZH/AZJ/AQY/AEG	85 116	
Ignition Coil AZH/AEG/APK/AQY	<b>80218</b>	
Ignition Coil	<b>80270</b>	
Ignition Leads	<b>85875</b>	
Ignition Leads	<b>85879</b>	
<b>Octavia (1U2) RS 1.8 T</b>	2001-06	
AUQ	132 180	
Ignition Coil With regul.cat.(3way)	<b>80202</b>	
Ignition Coil AUQ	<b>80239</b>	
<b>Octavia (1Z3) 1.2 TSI</b>	2010-13	
CBZB	77 105	
Ignition Coil	<b>80218</b>	
Ignition Leads	<b>85871</b>	
<b>Octavia (1Z3) 1.4</b>	2004-06	
BCA	55 75	
Ignition Coil Intake manifold injection	<b>80201</b>	
<b>Octavia (1Z3) 1.4</b>	2004-13	
BUD/CGGA	59 80	
Ignition Coil BUD; 05.2006->; Intake manifold injection	<b>80201</b>	
<b>Octavia (1Z3) 1.4 TSI</b>	2008-13	
CAXA	90 122	
Ignition Coil	<b>80201</b>	
<b>Octavia (1Z3) 1.6</b>	2004-13	
BGU/CCSA/BSF/CMXA/BSE	75 102	
Ignition Coil BGU	<b>80218</b>	
Ignition Leads	<b>85879</b>	
<b>Octavia (1Z3) 1.6 FSI</b>	2004-08	
BLF	85 115	
Ignition Coil Direct Injection	<b>80201</b>	
<b>Octavia (1Z3) 1.6 LPG</b>	2009-12	
CHGA	75 102	
Ignition Coil	<b>80218</b>	
<b>Octavia (1Z3) 1.6 MultiFuel</b>	2008-13	
CCSA/CMXA	75 102	
Ignition Coil	<b>80218</b>	
<b>Octavia (1Z3) 1.8 TSI</b>	2007-13	
BZB/CDAA	118 160	
Ignition Coil	<b>80240</b>	
<b>Octavia (1Z3) 2.0 FSI</b>	2004-08	
BLY/BLR/BVZ/BVY	110 150	
Ignition Coil	<b>80240</b>	
<b>Octavia (1Z3) 2.0 RS</b>	2005-13	
BWA/CCZA	147 200	
Ignition Coil BWA	<b>80240</b>	
<b>Octavia (5E3) 1.2 TSI</b>	2015->	
CYVB	81 110	
Ignition Coil	<b>80249</b>	
<b>Octavia (5E3) 1.2 TSI</b>	2012->	
CJZB	63 86	
Ignition Coil	<b>80249</b>	
<b>Octavia (5E3) 1.2 TSI</b>	2012->	
CJZA	77 105	
Ignition Coil	<b>80249</b>	
<b>Octavia (5E3) 1.4 TSI</b>	2014->	
CHPB/CZDA	110 150	
Ignition Coil CZDA	<b>80249</b>	
<b>Octavia (5E3) 1.4 TSI</b>	2012->	
CHPA	103 140	
Ignition Coil	<b>80249</b>	
<b>Octavia (5E3) 1.4 TSI G-TEC</b>	2013->	
CPWA	81 110	
Ignition Coil	<b>80249</b>	





SKODA Cont.	
<b>Octavia (5E3) 1.6</b>	2014->
CWVA	81 110
Ignition Coil	<b>80249</b>
<b>Octavia (5E3) 1.8 TSI</b>	2012->
CJSA	132 180
Ignition Coil	<b>80238</b>
<b>Octavia (5E3) 2.0 TSI RS</b>	2013->
CHHB	162 220
Ignition Coil	<b>80238</b>
<b>Octavia Combi (1U5) 1.4 16V</b>	2000-10
AXP/BCA	55 75
Ignition Coil Ch.1U-2-624 899->; 03.2002->	<b>80201</b>
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Octavia Combi (1U5) 1.6</b>	1998-04
AEE	55 75
Ignition Coil	<b>80200</b>
Ignition Leads	<b>85693</b>
<b>Octavia Combi (1U5) 1.6</b>	2000-10
AVU/BFQ	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Octavia Combi (1U5) 1.6</b>	1998-07
AKL/AEH	74 101
Ignition Coil	<b>80218</b>
Ignition Leads Ch.1U-W-060001->	<b>85875</b>
<b>Octavia Combi (1U5) 1.8 20V</b>	1998-00
AGN	92 125
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85065</b>
<b>Octavia Combi (1U5) 1.8 T</b>	1998-10
ARX/ARZ/AGU/AUM	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil ARZ,ARX,AGU,AUM	<b>80239</b>
Ignition Coil 05.2001->	<b>80252</b>
<b>Octavia Combi (1U5) 1.8 T 4x4</b>	2001-06
ARX	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil Hydraulic Brake	<b>80239</b>
Ignition Coil	<b>80252</b>
<b>Octavia Combi (1U5) 2.0</b>	1999-07
APK/AZH/AZJ/AQY/AEG	85 116
Ignition Coil	<b>80218</b>
Ignition Coil	<b>80270</b>
Ignition Leads	<b>85875</b>
Ignition Leads	<b>85879</b>
<b>Octavia Combi (1U5) 2.0 4x4</b>	2000-10
ATF	88 120
Ignition Coil	<b>80218</b>
<b>Octavia Combi (1U5) 2.0 4x4</b>	2000-04
AZH/AZJ	85 116
Ignition Coil	<b>80218</b>
Ignition Coil AZJ	<b>80270</b>
Ignition Leads	<b>85874</b>
Ignition Leads	<b>85875</b>
<b>Octavia Combi (1U5) RS 1.8 T</b>	2002-06
AUQ	132 180
Ignition Coil With regul.cat.(3way)	<b>80202</b>
Ignition Coil AUQ	<b>80239</b>
<b>Octavia Combi (1Z5) 1.2 TSI</b>	2010-13
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Octavia Combi (1Z5) 1.4</b>	2006-13
BUD/CGGA	59 80
Ignition Coil BUD; Intake manifold injection	<b>80201</b>
<b>Octavia Combi (1Z5) 1.4</b>	2004-06
BCA	55 75
Ignition Coil	<b>80201</b>
<b>Octavia Combi (1Z5) 1.4 TSI</b>	2008-13
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Octavia Combi (1Z5) 1.6</b>	2004-13
BGU/CCSA/BSF/CMXA/BSE	75 102
Ignition Coil BGU	<b>80218</b>
Ignition Leads	<b>85879</b>
<b>Octavia Combi (1Z5) 1.6 FSI</b>	2004-08
BLF	85 115
Ignition Coil Direct Injection	<b>80201</b>

SKODA Cont.	
<b>Octavia Combi (1Z5) 1.6 LPG</b>	2009-12
CHGA	75 102
Ignition Coil	<b>80218</b>
<b>Octavia Combi (1Z5) 1.6 MultiFuel</b>	2008-13
CCSA/CMXA	75 102
Ignition Coil	<b>80218</b>
<b>Octavia Combi (1Z5) 1.8 TSI</b>	2007-13
BZB/CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Octavia Combi (1Z5) 1.8 TSI 4x4</b>	2008-13
CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Octavia Combi (1Z5) 1.8 TSI 4x4</b>	2009-13
CDAB	112 152
Ignition Coil	<b>80240</b>
<b>Octavia Combi (1Z5) 2.0 FSI</b>	2004-08
BLY/BLR/BVZ/BVY	110 150
Ignition Coil	<b>80240</b>
<b>Octavia Combi (1Z5) 2.0 FSI 4x4</b>	2004-08
BVX/BLX	110 150
Ignition Coil	<b>80240</b>
<b>Octavia Combi (1Z5) 2.0 RS</b>	2005-13
BWA/CCZA	147 200
Ignition Coil	<b>80240</b>
<b>Octavia Combi (5E5) 1.2 TSI</b>	2015->
CYVB	81 110
Ignition Coil	<b>80249</b>
<b>Octavia Combi (5E5) 1.2 TSI</b>	2012->
CJZB	63 86
Ignition Coil	<b>80249</b>
<b>Octavia Combi (5E5) 1.2 TSI</b>	2012->
CJZA	77 105
Ignition Coil	<b>80249</b>
<b>Octavia Combi (5E5) 1.4 TSI</b>	2014->
CHPB/CZDA	110 150
Ignition Coil CZDA	<b>80249</b>
<b>Octavia Combi (5E5) 1.4 TSI</b>	2012->
CHPA	103 140
Ignition Coil	<b>80249</b>
<b>Octavia Combi (5E5) 1.4 TSI G-TEC</b>	2013->
CPWA	81 110
Ignition Coil	<b>80249</b>
<b>Octavia Combi (5E5) 1.6</b>	2014->
CWVA	81 110
Ignition Coil	<b>80249</b>
<b>Octavia Combi (5E5) 1.8 TSI</b>	2012->
CJSA	132 180
Ignition Coil	<b>80238</b>
<b>Octavia Combi (5E5) 1.8 TSI 4x4</b>	2012->
CJSB	132 180
Ignition Coil	<b>80238</b>
<b>Octavia Combi (5E5) 2.0 TSI RS</b>	2012->
CHHB	162 220
Ignition Coil	<b>80238</b>
<b>Rapid (NH3) 1.2</b>	2012->
CGPC	55 75
Ignition Coil ->06.2015	<b>80201</b>
<b>Rapid (NH3) 1.2 TSI</b>	2015->
CJZC	66 90
Ignition Coil	<b>80249</b>
<b>Rapid (NH3) 1.2 TSI</b>	2015->
CJZD	81 110
Ignition Coil	<b>80249</b>
<b>Rapid (NH3) 1.2 TSI</b>	2012->
CBZA	63 86
Ignition Coil ->05.2015	<b>80218</b>
<b>Rapid (NH3) 1.2 TSI</b>	2012->
CBZB	77 105
Ignition Coil ->05.2015	<b>80218</b>
<b>Rapid (NH3) 1.4 TSI</b>	2015->
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Rapid (NH3) 1.4 TSI</b>	2012->
CAXA	90 122
Ignition Coil ->06.2015	<b>80201</b>
<b>Rapid (NH3) 1.6</b>	2015->
CWVA	81 110
Ignition Coil	<b>80249</b>



SKODA Cont.	
<b>Rapid (NH3) 1.6</b>	2012->
CFNA	77 105
Ignition Coil ->06.2015	<b>80201</b>
<b>Rapid Spaceback (NH1) 1.2 TSI</b>	2015->
CJZC	66 90
Ignition Coil	<b>80249</b>
<b>Rapid Spaceback (NH1) 1.2 TSI</b>	2015->
CJZD	81 110
Ignition Coil	<b>80249</b>
<b>Rapid Spaceback (NH1) 1.2 TSI</b>	2012->
CBZA	63 86
Ignition Coil ->05.2015	<b>80218</b>
<b>Rapid Spaceback (NH1) 1.2 TSI</b>	2012->
CBZB	77 105
Ignition Coil ->05.2015	<b>80218</b>
<b>Rapid Spaceback (NH1) 1.4 TSI</b>	2015->
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Rapid Spaceback (NH1) 1.4 TSI</b>	2012->
CAXA	90 122
Ignition Coil ->06.2015	<b>80201</b>
<b>Rapid Spaceback (NH1) 1.6</b>	2012->
CFNA	77 105
Ignition Coil ->06.2015	<b>80201</b>
<b>Roomster (5J) 1.2</b>	2006-07
BME	47 64
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Roomster (5J) 1.2</b>	2007-15
BZG/CGPA	51 70
Ignition Coil	<b>80201</b>
<b>Roomster (5J) 1.2 TSI</b>	2010-15
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Roomster (5J) 1.2 TSI</b>	2010-15
CBZA	63 86
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Roomster (5J) 1.4</b>	2006-15
CGGB/BXW	63 86
Ignition Coil BXW; Intake manifold injection	<b>80201</b>
<b>Roomster (5J) 1.6</b>	2006-15
BTS/CFNA	77 105
Ignition Coil BTS; Intake manifold injection	<b>80201</b>
<b>Roomster Praktik (5J) 1.2</b>	2007-15
BZG/CGPA	51 70
Ignition Coil	<b>80201</b>
<b>Roomster Praktik (5J) 1.2 TSI</b>	2010-15
CBZA	63 86
Ignition Coil	<b>80218</b>
<b>Roomster Praktik (5J) 1.4</b>	2007-15
CGGB/BXW	63 86
Ignition Coil	<b>80201</b>
<b>Superb (3T4) 1.4 TSI</b>	2008-15
CAXC	92 125
Ignition Coil	<b>80201</b>
<b>Superb (3T4) 1.8 TSI</b>	2008-15
BZB/CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Superb (3T4) 1.8 TSI 4x4</b>	2008-15
CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Superb (3T4) 2.0 TSI</b>	2010-15
CCZA	147 200
Ignition Coil	<b>80240</b>
<b>Superb (3T4) 3.6 V6 4x4</b>	2008-15
CDVA	191 260
Ignition Coil	<b>80327</b>
<b>Superb (3U4) 1.8 T</b>	2001-08
AWT	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>Superb (3U4) 2.0</b>	2001-08
AZM	85 115
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Superb (3U4) 2.8 V6</b>	2001-08
AMX	142 193
Ignition Leads	<b>85062</b>

SKODA Cont.	
<b>Superb (3V3) 1.4 TSI</b>	2015->
CZEA/CZDA	110 150
Ignition Coil 05.2015->	<b>80249</b>
<b>Superb (3V3) 1.4 TSI</b>	2015->
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Superb (3V3) 1.4 TSI 4x4</b>	2015->
CZEA	110 150
Ignition Coil	<b>80249</b>
<b>Superb Kombi (3T5) 1.4 TSI</b>	2009-15
CAXC	92 125
Ignition Coil	<b>80201</b>
<b>Superb Kombi (3T5) 1.8 TSI</b>	2009-15
CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Superb Kombi (3T5) 1.8 TSI 4x4</b>	2009-15
CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Superb Kombi (3T5) 2.0 TSI</b>	2010-15
CCZA	147 200
Ignition Coil	<b>80240</b>
<b>Superb Kombi (3T5) 3.6 V6 4x4</b>	2009-15
CDVA	191 260
Ignition Coil	<b>80327</b>
<b>Superb Kombi (3V5) 1.4 TSI</b>	2015->
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Superb Kombi (3V5) 1.4 TSI</b>	2015->
CZEA/CZDA	110 150
Ignition Coil 05.2015->	<b>80249</b>
<b>Superb Kombi (3V5) 1.4 TSI 4x4</b>	2015->
CZEA	110 150
Ignition Coil	<b>80249</b>
<b>Yeti (5L) 1.2 TSI</b>	2015->
CYVB	81 110
Ignition Coil	<b>80249</b>
<b>Yeti (5L) 1.2 TSI</b>	2009->
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Yeti (5L) 1.4 TSI</b>	2015->
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Yeti (5L) 1.4 TSI</b>	2010->
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Yeti (5L) 1.4 TSI 4x4</b>	2015->
CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Yeti (5L) 1.6</b>	2014->
CWVA	81 110
Ignition Coil ->02.2015	<b>80249</b>
<b>Yeti (5L) 1.8 TSI 4x4</b>	2009->
CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Yeti (5L) 1.8 TSI 4x4</b>	2009->
CDAB	112 152
Ignition Coil	<b>80240</b>
SMART	
<b>Cabrio (450) 0,6</b>	2000-04
M 160.910/M 160 E6AL B03	40 55
Ignition Coil	<b>80293</b>
Ignition Leads	<b>83995</b>
<b>Cabrio (450) 0,6</b>	2001-04
M 160.910/M 160 E6AL B05	45 61
Ignition Coil	<b>80293</b>
Ignition Leads	<b>83995</b>
<b>Cabrio (450) 0,6</b>	2002-04
M 160.910	52 71
Ignition Coil	<b>80293</b>
<b>Cabrio (450) 0,7</b>	2003-04
M 160.920	45 61
Ignition Coil	<b>80293</b>
Ignition Leads	<b>83995</b>



SMART Cont.	
<b>Cabrio (450) 0,7</b>	2003-04
M 160.920	55 75
Ignition Coil	<b>80293</b>
Ignition Leads M 160.910	<b>83995</b>
<b>City-Coupe (450) 0,6</b>	2001-04
M 160.910/M 160 E6AL B05	45 61
Ignition Coil	<b>80293</b>
Ignition Leads ->12.2002	<b>83995</b>
<b>City-Coupe (450) 0,6</b>	2002-04
M 160.910	52 71
Ignition Coil	<b>80293</b>
<b>City-Coupe (450) 0,6</b>	1998-04
M 160.910/M 160 E6AL B04	33 45
Ignition Coil	<b>80293</b>
Ignition Leads SAE	<b>83995</b>
<b>City-Coupe (450) 0,6</b>	1998-04
M 160.910/M 160 E6AL B03	40 55
Ignition Coil	<b>80293</b>
Ignition Leads SAE	<b>83995</b>
<b>City-Coupe (450) 0,7</b>	2003-04
M 160.920	37 50
Ignition Coil	<b>80293</b>
Ignition Leads SAE	<b>83995</b>
<b>City-Coupe (450) 0,7</b>	2003-04
M 160.920	45 61
Ignition Coil	<b>80293</b>
Ignition Leads SAE	<b>83995</b>
<b>City-Coupe (450) 0,7</b>	2003-04
M 160.920	55 75
Ignition Coil	<b>80293</b>
<b>Crossblade (450) 0,6</b>	2002-03
M 160.910	52 71
Ignition Coil	<b>80293</b>
Ignition Leads SAE	<b>83995</b>
<b>Forfour (454) 1,1</b>	2004-06
M 134.910	55 75
Ignition Coil	<b>80339</b>
<b>Forfour (454) 1,1</b>	2005-06
M 134.911	47 64
Ignition Coil	<b>80339</b>
<b>Forfour (454) 1,3</b>	2004-06
M 135.930	70 95
Ignition Coil	<b>80339</b>
<b>Forfour (454) 1,5</b>	2004-06
M 135.950	80 109
Ignition Coil	<b>80339</b>
<b>Forfour (454) 1,5</b>	2004-06
M 135.950	90 122
Ignition Coil	<b>80339</b>
<b>Fortwo Cabrio (450) 0,7</b>	2004-07
M 160.920	45 61
Ignition Coil	<b>80293</b>
<b>Fortwo Cabrio (450) 0,7</b>	2004-07
M 160.920	55 75
Ignition Coil	<b>80293</b>
<b>Fortwo Coupe (450) 0,7</b>	2004-07
M 160.920	37 50
Ignition Coil	<b>80293</b>
<b>Fortwo Coupe (450) 0,7</b>	2004-07
M 160.920	45 61
Ignition Coil	<b>80293</b>
<b>Fortwo Coupe (450) 0,7 (450.335)</b>	2004-07
M 160.920	40 54
Ignition Coil 02.2004->	<b>80293</b>
<b>Roadster (452) 0,7</b>	2003-05
M 160.922	60 82
Ignition Coil	<b>80293</b>
<b>Roadster (452) 0,7</b>	2003-05
M 160.921	45 61
Ignition Coil	<b>80293</b>
Ignition Leads SAE	<b>83995</b>
<b>Roadster (452) 0.7 Brabus</b>	2003-05
M 160.923	74 101
Ignition Coil	<b>80293</b>

SMART Cont.	
<b>Roadster Coupe (452) 0,7</b>	2003-05
M 160.921	60 82
Ignition Coil	<b>80293</b>
<b>Roadster Coupe (452) 0,7</b>	2003-05
M 160.922	45 61
Ignition Coil	<b>80293</b>
Ignition Leads SAE	<b>83995</b>
<b>Roadster Coupe (452) 0.7 Brabus</b>	2003-05
M 160.923	74 101
Ignition Coil	<b>80293</b>
SSANGYONG	
<b>Actyon I 2.3</b>	2006->
G23D	110 150
Ignition Coil	<b>80211</b>
<b>Korando (KJ) 2.0</b>	1997-02
E20	94 128
Ignition Coil	<b>80211</b>
<b>Korando (KJ) 2.3</b>	1999-06
	105 143
Ignition Coil	<b>80211</b>
<b>Korando (KJ) 2.3</b>	1997-00
M 111.970	103 140
Ignition Coil	<b>80211</b>
<b>Korando (KJ) 3,2</b>	1996-02
M 104.995	154 209
Ignition Coil M 104.995; With regul.cat.(3way)	<b>80211</b>
<b>Korando (KJ) 3.2</b>	1997->
M 104.992	162 220
Ignition Coil ->12.2005	<b>80211</b>
<b>Korando (KJ) 3.2</b>	1999-00
M 104.995	156 212
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Korando Cabrio (KJ) 2.3</b>	1999-06
	105 143
Ignition Coil	<b>80211</b>
<b>Korando Cabrio (KJ) 2.3</b>	1997-00
	103 140
Ignition Coil	<b>80211</b>
<b>Korando Cabrio (KJ) 3.2</b>	1997->
M 104.992	162 220
Ignition Coil ->12.2005	<b>80211</b>
<b>Korando Cabrio (KJ) 3.2</b>	1999-02
M 104.995	156 212
Ignition Coil With regul.cat.(3way)	<b>80211</b>
<b>Musso (FJ) 2.0</b>	1996-05
E20	93 126
Ignition Coil	<b>80211</b>
<b>Musso (FJ) 2.3</b>	2003-06
	110 150
Ignition Coil	<b>80211</b>
<b>Musso (FJ) 2.3</b>	1996-02
M 111.970	103 140
Ignition Coil	<b>80211</b>
Ignition Leads	<b>85052</b>
<b>Musso (FJ) 3.2</b>	1996-04
M 104.992	162 220
Ignition Coil	<b>80211</b>
<b>Rexton (GAB) 3.2</b>	2002->
G32D	162 220
Ignition Coil	<b>80211</b>
<b>Rodius 3.2</b>	2005->
G32D	162 220
Ignition Coil ->12.2010	<b>80211</b>
<b>Rodius 3.2 4WD</b>	2007->
G32D	162 220
Ignition Coil ->12.2010	<b>80211</b>



SUBARU		
<b>Forester (SF) 2.0</b>	<b>1998-02</b>	
EJ202	92	125
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83236</b>	
<b>Forester (SF) 2.0</b>	<b>1997-02</b>	
EJ202	90	122
Ignition Coil 06.1998->	<b>80364</b>	
Ignition Leads	<b>83237</b>	
<b>Forester (SG) 2.0</b>	<b>2002-05</b>	
EJ201	92	125
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83238</b>	
<b>Forester (SG) 2.0 S Turbo</b>	<b>2002-05</b>	
EJ205	130	177
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83238</b>	
<b>Forester (SG) 2.0 X</b>	<b>2005-08</b>	
EJ204	116	158
Ignition Coil	<b>80364</b>	
<b>Forester (SG) 2.5</b>	<b>2003-05</b>	
EJ25	155	211
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83236</b>	
<b>Forester (SG) 2.5 RX Nato AWD</b>	<b>2002-05</b>	
EJ25	115	156
Ignition Coil	<b>80364</b>	
<b>Impreza Coupe (GFC) 1.6</b>	<b>1996-00</b>	
EJ16E/EJ161	66	90
Ignition Leads	<b>83235</b>	
<b>Impreza Coupe (GFC) 1.6 AWD</b>	<b>1996-00</b>	
EJ161	66	90
Ignition Leads	<b>83235</b>	
<b>Impreza Sedan (GC) 1.6 i</b>	<b>1998-00</b>	
EJ161	70	95
Ignition Leads	<b>83235</b>	
<b>Impreza Sedan (GC) 1.6 i</b>	<b>1992-00</b>	
EJ16	66	90
Ignition Leads	<b>83235</b>	
<b>Impreza Sedan (GC) 1.6 i AWD</b>	<b>1998-00</b>	
EJ161	70	95
Ignition Leads	<b>83235</b>	
<b>Impreza Sedan (GC) 1.6 i AWD</b>	<b>1992-00</b>	
EJ16	66	90
Ignition Leads	<b>83235</b>	
<b>Impreza Sedan (GC) 2.0 i</b>	<b>1998-00</b>	
EJ201	92	125
Ignition Coil	<b>80364</b>	
<b>Impreza Sedan (GC) 2.0 i AWD</b>	<b>1998-00</b>	
EJ201	92	125
Ignition Coil	<b>80364</b>	
<b>Impreza Sedan (GC) 2.2 GX AWD</b>	<b>1998-00</b>	
EJ22E	96	131
Ignition Coil	<b>80364</b>	
<b>Impreza Sedan (GD) 2.5 AWD</b>	<b>2001-05</b>	
EJ251	130	177
Ignition Coil	<b>80364</b>	
<b>Impreza Sedan (GD) 2.5 i AWD</b>	<b>2002-05</b>	
EJ251	112	152
Ignition Coil	<b>80364</b>	
<b>Impreza Sedan (GD, GG) 1.6 AWD</b>	<b>2000-&gt;</b>	
EJ161	70	95
Ignition Leads	<b>83235</b>	
<b>Impreza Sedan (GD, GG) 2.0 i AWD</b>	<b>2000-&gt;</b>	
EJ201	92	125
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83238</b>	
<b>Impreza Station Wagon (GD, GG) 1.6 AWD</b>	<b>2000-&gt;</b>	
EJ161	70	95
Ignition Leads	<b>83235</b>	
<b>Impreza Station Wagon (GD, GG) 2.0 AWD</b>	<b>2000-&gt;</b>	
EJ201	92	125
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83238</b>	
<b>Impreza Station Wagon (GD, GG) 2.0 i R AWD</b>	<b>2005-07</b>	
EJ204	118	160
Ignition Coil	<b>80364</b>	
<b>Impreza Station Wagon (GF) 1.6 i</b>	<b>1998-00</b>	
EJ161	70	95
Ignition Leads	<b>83235</b>	

SUBARU Cont.		
<b>Impreza Station Wagon (GF) 1.6 i AWD</b>	<b>1998-00</b>	
EJ161	70	95
Ignition Leads	<b>83235</b>	
<b>Impreza Station Wagon (GF) 1.6 i AWD</b>	<b>1992-00</b>	
EJ16	66	90
Ignition Leads	<b>83235</b>	
<b>Impreza Station Wagon (GF) 2.0 i 16V AWD</b>	<b>1998-00</b>	
EJ201/EJ20E	92	125
Ignition Coil EJ201	<b>80364</b>	
<b>Impreza Station Wagon (GF) 2.0 i AWD</b>	<b>1995-00</b>	
EJ20	85	116
Ignition Leads	<b>83237</b>	
<b>Impreza Station Wagon (GF) 2.2 GX AWD</b>	<b>1998-00</b>	
EJ22E	96	131
Ignition Coil	<b>80364</b>	
<b>Impreza Station Wagon (GF) 2.2 GX AWD</b>	<b>1995-98</b>	
EJ22	97	132
Ignition Coil	<b>80364</b>	
<b>Impreza Station Wagon (GG) 2.0 AWD</b>	<b>2005-&gt;</b>	
EJ205	184	250
Ignition Coil	<b>80364</b>	
<b>Justy II (JMA, MS) 1.3 4x4</b>	<b>2001-03</b>	
G13BB	63	86
Ignition Leads	<b>85806</b>	
<b>Justy III (G3X) 1.3</b>	<b>2003-&gt;</b>	
M13A	69	94
Ignition Coil	<b>80343</b>	
<b>Justy III (G3X) 1.5</b>	<b>2003-&gt;</b>	
M15A	73	99
Ignition Coil	<b>80343</b>	
<b>Justy IV 1.0</b>	<b>2007-&gt;</b>	
1KR-FE	51	69
Ignition Coil	<b>80282</b>	
<b>Legacy III (BE, BH) 2.0</b>	<b>1999-03</b>	
EJ201	92	125
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83238</b>	
<b>Legacy III (BE, BH) 2.5</b>	<b>1998-03</b>	
EJ25	115	156
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83238</b>	
<b>Legacy III Station Wagon (BE, BH) 2.0 AWD</b>	<b>1998-03</b>	
EJ201	92	125
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83238</b>	
<b>Legacy III Station Wagon (BE, BH) 2.5 AWD</b>	<b>1998-03</b>	
EJ25	115	156
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83238</b>	
<b>Legacy IV (BL) 2.0 AWD</b>	<b>2005-09</b>	
EJ204	121	165
Ignition Coil	<b>80364</b>	
<b>Legacy IV (BL, BP) 2.0</b>	<b>2003-05</b>	
EJ202	101	138
Ignition Leads	<b>83236</b>	
<b>Legacy IV (BL, BP) 2.5</b>	<b>2003-09</b>	
EJ25	121	165
Ignition Coil	<b>80364</b>	
<b>Legacy IV Station Wagon (BL, BP, B13) 2.0 AWD</b>	<b>2003-05</b>	
EJ202	101	138
Ignition Leads	<b>83236</b>	
<b>Legacy IV Station Wagon (BL, BP, B13) 2.5 AWD</b>	<b>2003-09</b>	
EJ25	121	165
Ignition Coil	<b>80364</b>	
<b>Outback (BE, BH) 2.5</b>	<b>2000-03</b>	
EJ25	115	156
Ignition Coil	<b>80364</b>	
Ignition Leads	<b>83238</b>	
<b>Outback (BL, BP) 2.5 AWD</b>	<b>2008-09</b>	
EJ251	127	173
Ignition Coil	<b>80364</b>	
<b>Trezia 1.3</b>	<b>2011-&gt;</b>	
1NR-FKE/1NR-FE	73	99
Ignition Coil 1NR-FE	<b>80367</b>	



SUZUKI		
<b>Alto III (EF) 1.0</b>		1994-98
G10BB		39 53
Ignition Leads		<b>85350</b>
<b>Alto IV (FF) 1.1</b>		2004-08
F10DN/F10D		46 63
Ignition Coil F10D		<b>80343</b>
Ignition Leads		<b>85806</b>
<b>Baleno (EG) 1.3</b>		1996-02
G13BA		52 71
Ignition Coil 03.1999->		<b>80343</b>
Ignition Leads		<b>85805</b>
Ignition Leads 03.1999->		<b>85806</b>
<b>Baleno (EG) 1.3 i 16V</b>		1995-02
G13BB		63 85
Ignition Coil		<b>80343</b>
Ignition Leads ->01.1999		<b>85805</b>
Ignition Leads 02.1999->		<b>85806</b>
<b>Baleno (EG) 1.6 i 16V</b>		1995-02
G16B		72 98
Ignition Coil Ch.00160001->		<b>80343</b>
Ignition Leads ->01.1999		<b>85805</b>
Ignition Leads 02.1999->		<b>85806</b>
<b>Baleno (EG) 1.6 i 16V 4x4</b>		1995-02
G16B		72 98
Ignition Coil Ch.00160001->		<b>80343</b>
Ignition Leads ->01.1999		<b>85805</b>
Ignition Leads 02.1999->		<b>85806</b>
<b>Baleno Fastback (EG) 1.3</b>		1996-02
G13BA		52 71
Ignition Coil 03.1999->		<b>80343</b>
Ignition Leads		<b>85805</b>
Ignition Leads 03.1999->		<b>85806</b>
<b>Baleno Fastback (EG) 1.3 i 16V</b>		1995-02
G13BB		63 85
Ignition Coil		<b>80343</b>
Ignition Leads ->02.1999		<b>85805</b>
Ignition Leads 03.1999->		<b>85806</b>
<b>Baleno Fastback (EG) 1.6 i 16V</b>		1995-02
G16B		72 98
Ignition Coil Ch.00160001->		<b>80343</b>
Ignition Leads ->01.1999		<b>85805</b>
Ignition Leads 02.1999->		<b>85806</b>
<b>Baleno Fastback (EG) 1.6 i 16V 4x4</b>		1995-02
G16B		72 98
Ignition Coil Ch.00160001->		<b>80343</b>
Ignition Leads ->01.1999		<b>85805</b>
Ignition Leads 02.1999->		<b>85806</b>
<b>Baleno Station Wagon (EG) 1.3 16V</b>		1997-02
G13BB		63 86
Ignition Coil		<b>80343</b>
Ignition Leads ->01.1999		<b>85805</b>
Ignition Leads Ch.00160001->		<b>85806</b>
<b>Baleno Station Wagon (EG) 1.6 i 16V</b>		1996-02
G16B		73 99
Ignition Coil		<b>80343</b>
Ignition Leads		<b>85805</b>
Ignition Leads Ch.00160001->		<b>85806</b>
<b>Baleno Station Wagon (EG) 1.6 i 16V</b>		1996-02
G16B		72 98
Ignition Coil Ch.00160001->		<b>80343</b>
Ignition Leads ->01.1999		<b>85805</b>
Ignition Leads 02.1999->		<b>85806</b>
<b>Baleno Station Wagon (EG) 1.6 i 16V 4x4</b>		1996-02
G16B		73 99
Ignition Coil		<b>80343</b>
Ignition Leads		<b>85805</b>
Ignition Leads Ch.00160001->		<b>85806</b>
<b>Baleno Station Wagon (EG) 1.6 i 16V 4x4</b>		1996-02
G16B		72 98
Ignition Coil Ch.00160001->		<b>80343</b>
Ignition Leads ->01.1999		<b>85805</b>
Ignition Leads 02.1999->		<b>85806</b>
<b>Carry Van (FD) 1.3</b>		1999->
G13BB		58 79
Ignition Coil		<b>80343</b>
Ignition Leads		<b>85806</b>

SUZUKI Cont.		
<b>Carry Van (FD) 1.3 16 V</b>		2000->
G13BB		58 79
Ignition Coil		<b>80343</b>
Ignition Leads		<b>85806</b>
<b>Grand Vitara I (FT, GT) 1.6</b>		1998-03
G16B		69 94
Ignition Leads		<b>85805</b>
Ignition Leads		<b>85806</b>
<b>Grand Vitara II (JT) 1.6 4WD</b>		2005->
M16A		78 106
Ignition Coil		<b>80343</b>
<b>Grand Vitara II (JT) 1.6 4WD</b>		2005-15
M16A		73 99
Ignition Coil		<b>80343</b>
<b>Ignis (FH) 1.3</b>		2000-03
M13A		61 83
Ignition Coil		<b>80343</b>
Ignition Leads		<b>85806</b>
<b>Ignis (FH) 1.3 4WD</b>		2000-03
M13A		61 83
Ignition Coil		<b>80343</b>
Ignition Leads		<b>85806</b>
<b>Ignis II 1.3</b>		2003->
M13A		69 94
Ignition Coil		<b>80343</b>
<b>Ignis II 1.3 4x4</b>		2003->
M13A		69 94
Ignition Coil		<b>80343</b>
<b>Ignis II 1.5</b>		2003->
M15A		73 99
Ignition Coil		<b>80343</b>
<b>Ignis II 1.5 4x4</b>		2003->
M15A		73 99
Ignition Coil		<b>80343</b>
<b>Ignis II 1.5 Sport</b>		2003->
M15A		80 109
Ignition Coil		<b>80343</b>
<b>Jimny (FJ) 1.3 16V</b>		1998->
G13BB		59 80
Ignition Leads		<b>85806</b>
<b>Jimny (FJ) 1.3 16V 4WD</b>		1998->
G13BB		59 80
Ignition Leads		<b>85806</b>
<b>Liana (ER) 1.3</b>		2002->
M13A		66 90
Ignition Coil		<b>80343</b>
<b>Liana (ER) 1.6</b>		2002->
M16A		76 103
Ignition Coil		<b>80343</b>
<b>Liana (ER) 1.6 4WD</b>		2002->
M16A		76 103
Ignition Coil		<b>80343</b>
<b>Liana (ER) 1.6 4WD</b>		2002->
M16A		78 106
Ignition Coil		<b>80343</b>
<b>Liana (ER) 1.6 i</b>		2002->
M16A		78 106
Ignition Coil		<b>80343</b>
<b>Liana (ER, RH) 1.5 (RH415)</b>		2004-07
M15A		81 110
Ignition Coil		<b>80332</b>
<b>Liana Station Wagon (ER) 1.3</b>		2001-07
M13A		66 90
Ignition Coil		<b>80343</b>
<b>Liana Station Wagon (ER) 1.6</b>		2001-07
M16A		76 103
Ignition Coil		<b>80343</b>
Ignition Leads		<b>85806</b>
<b>Liana Station Wagon (ER) 1.6</b>		2005-07
M16A		79 107
Ignition Coil		<b>80343</b>
<b>Liana Station Wagon (ER) 1.6 4WD</b>		2001-07
M16A		76 103
Ignition Coil		<b>80343</b>
Ignition Leads		<b>85806</b>
<b>Liana Station Wagon (ER) 1.6 4WD</b>		2002-07
M16A		78 106
Ignition Coil		<b>80343</b>
Ignition Leads		<b>85806</b>





SUZUKI Cont.	
<b>Liana Station Wagon (ER) 1.6 i</b>	<b>2002-07</b>
M16A	78 106
Ignition Coil	<b>80343</b>
Ignition Leads	<b>85806</b>
<b>Samurai (SJ) 1,3</b>	<b>1988-04</b>
G13A	47 64
Ignition Leads	<b>83590</b>
<b>Samurai (SJ) 1.0 4WD</b>	<b>1988-04</b>
F10A	33 45
Ignition Leads	<b>83590</b>
<b>Samurai (SJ) 1.3 4WD</b>	<b>1988-04</b>
G13BA	51 70
Ignition Leads	<b>83590</b>
<b>Samurai (SJ) 1.3 4WD</b>	<b>1988-04</b>
G13A	44 60
Ignition Leads	<b>83590</b>
<b>SJ 410 1.0</b>	<b>1981-88</b>
F10A	33 45
Ignition Leads	<b>83590</b>
<b>SJ 410 Cabrio 1.0</b>	<b>1981-88</b>
F10A	33 45
Ignition Leads	<b>83590</b>
<b>SJ 413 1.3</b>	<b>1986-90</b>
G13A	44 60
Ignition Leads	<b>83590</b>
<b>SJ 413 1.3</b>	<b>1984-90</b>
G13A	47 64
Ignition Leads	<b>83590</b>
<b>Swift Cabrio (SF413) 1.3 i</b>	<b>1991-96</b>
G13BA	50 68
Ignition Coil	<b>80343</b>
Ignition Leads	<b>85350</b>
<b>Swift I (AA) 1,3</b>	<b>1986-89</b>
G13A	47 64
Ignition Leads	<b>83590</b>
Ignition Leads With ignition distributor	<b>85350</b>
<b>Swift I (AA) 1,3</b>	<b>1984-89</b>
G13A	50 68
Ignition Leads	<b>83590</b>
Ignition Leads With ignition distributor	<b>85350</b>
<b>Swift I (AA) 1,3</b>	<b>1984-89</b>
G13A	54 73
Ignition Leads	<b>85350</b>
<b>Swift II Fastback (EA, MA) 1,3</b>	<b>1989-01</b>
G13A	50 68
Ignition Coil	<b>80343</b>
Ignition Leads	<b>85350</b>
Ignition Leads 01.1999->	<b>85806</b>
<b>Swift II Fastback (EA, MA) 1,3</b>	<b>1989-91</b>
G13A	52 71
Ignition Leads	<b>85350</b>
<b>Swift II Fastback (EA, MA) 1.3 4WD</b>	<b>1989-01</b>
G13A	50 68
Ignition Coil	<b>80343</b>
Ignition Leads	<b>85350</b>
Ignition Leads 01.1999->	<b>85806</b>
<b>Swift II Fastback (EA, MA) 1.3 4WD</b>	<b>1989-91</b>
G13A	52 71
Ignition Coil	<b>80343</b>
Ignition Leads	<b>85350</b>
<b>Swift II Sedan (AH, AJ) 1,3</b>	<b>1991-95</b>
G13B	50 68
Ignition Coil	<b>80343</b>
Ignition Leads	<b>85350</b>
Ignition Leads	<b>85806</b>
<b>Swift II Sedan (AH, AJ) 1,3</b>	<b>1989-91</b>
G13B	52 71
Ignition Coil	<b>80343</b>
Ignition Leads	<b>85350</b>
<b>Swift II Sedan (AH, AJ) 1,6</b>	<b>1989-91</b>
G16B	70 95
Ignition Leads	<b>85350</b>
<b>Swift II Sedan (AH, AJ) 1.6 4WD</b>	<b>1989-91</b>
G16B	70 95
Ignition Leads	<b>85350</b>
<b>Swift II Sedan (AH, AJ) 1.6 i</b>	<b>1990-01</b>
G16B	68 92
Ignition Coil	<b>80343</b>
Ignition Leads 03.1999->	<b>85806</b>

SUZUKI Cont.	
<b>Swift II Sedan (AH, AJ) 1.6 i 4WD</b>	<b>1990-01</b>
G16B	68 92
Ignition Leads 03.1999->	<b>85806</b>
<b>Swift III (MZ, EZ) 1.3</b>	<b>2005-&gt;</b>
M13A	68 92
Ignition Coil	<b>80343</b>
<b>Swift III (MZ, EZ) 1.3 4x4</b>	<b>2006-&gt;</b>
M13A	66 90
Ignition Coil	<b>80343</b>
Ignition Leads	<b>85806</b>
<b>Swift III (MZ, EZ) 1.3 4x4</b>	<b>2005-&gt;</b>
M13A	68 92
Ignition Coil	<b>80343</b>
<b>Swift III (MZ, EZ) 1.5</b>	<b>2005-&gt;</b>
M15A	75 102
Ignition Coil	<b>80343</b>
<b>Swift III (MZ, EZ) 1.5 4x4</b>	<b>2005-&gt;</b>
M15A	74 101
Ignition Coil	<b>80343</b>
<b>Swift III (MZ, EZ) 1.6</b>	<b>2006-&gt;</b>
M16A	92 125
Ignition Coil	<b>80343</b>
<b>SX4 (EY, GY) 1.5</b>	<b>2006-10</b>
M15A	73 99
Ignition Coil	<b>80343</b>
<b>SX4 (EY, GY) 1.5 VVT</b>	<b>2010-&gt;</b>
M15A	82 112
Ignition Coil	<b>80343</b>
<b>SX4 (EY, GY) 1.6</b>	<b>2006-&gt;</b>
M16A	74 101
Ignition Coil	<b>80343</b>
<b>SX4 (EY, GY) 1.6 VVT</b>	<b>2006-&gt;</b>
M16A	79 107
Ignition Coil	<b>80343</b>
<b>SX4 (EY, GY) 1.6 VVT</b>	<b>2009-&gt;</b>
M16A	88 120
Ignition Coil	<b>80343</b>
<b>SX4 (EY, GY) 1.6 VVT 4x4</b>	<b>2006-&gt;</b>
M16A	79 107
Ignition Coil	<b>80343</b>
<b>SX4 (EY, GY) 1.6 VVT 4x4</b>	<b>2009-&gt;</b>
M16A	88 120
Ignition Coil	<b>80343</b>
<b>SX4 (EY, GY) 1.6 VVT 4x4</b>	<b>2009-&gt;</b>
M16A	82 112
Ignition Coil	<b>80343</b>
<b>SX4 Sedan (GY) 1.6</b>	<b>2007-&gt;</b>
M16A	79 107
Ignition Coil	<b>80343</b>
<b>SX4 Sedan (GY) 1.6</b>	<b>2007-&gt;</b>
M16A	74 101
Ignition Coil	<b>80343</b>
<b>SX4 Sedan (GY) 1.6</b>	<b>2007-&gt;</b>
M16A	75 102
Ignition Coil	<b>80343</b>
<b>SX4 Sedan (GY) 1.6</b>	<b>2007-&gt;</b>
M16A	88 120
Ignition Coil	<b>80343</b>
<b>Vitara (ET, TA) 1.6 4WD</b>	<b>1988-98</b>
G16A (8V)	59 80
Ignition Leads	<b>83270</b>
<b>Vitara (ET, TA) 1.6 4WD</b>	<b>1988-91</b>
G16A (8V)	60 82
Ignition Leads	<b>83270</b>
<b>Vitara (ET, TA) 1.6 i 16V 4WD</b>	<b>1990-98</b>
G16B	71 97
Ignition Leads	<b>85805</b>
<b>Vitara Cabrio (ET, TA) 1.6</b>	<b>1988-95</b>
G16A (8V)	59 80
Ignition Leads DIN	<b>83270</b>
Ignition Leads	<b>85805</b>
<b>Vitara Cabrio (ET, TA) 1.6 i 16V</b>	<b>1990-99</b>
G16B	71 97
Ignition Leads	<b>85805</b>
<b>Wagon R+ (MM) 1.3</b>	<b>2000-04</b>
G13BB	56 76
Ignition Coil	<b>80343</b>
Ignition Leads	<b>85806</b>



SUZUKI Cont.		
<b>Wagon R+ (MM) 1.3</b>	<b>2003-&gt;</b>	
M13A	69	94
Ignition Coil	<b>80343</b>	
Ignition Leads	<b>85806</b>	
<b>Wagon R+ (MM) 1.3 4WD</b>	<b>2001-&gt;</b>	
G13BB	56	76
Ignition Coil	<b>80343</b>	
Ignition Leads	<b>85806</b>	
<b>Wagon R+ (MM) 1.3 4WD</b>	<b>2003-&gt;</b>	
M13A	69	94
Ignition Coil	<b>80343</b>	
<b>X-90 (EL) 1.6 i 16V</b>	<b>1995-97</b>	
G16B	71	97
Ignition Leads	<b>85805</b>	
<b>X-90 (EL) 1.6 i 16V 4x4</b>	<b>1995-97</b>	
G16B	71	97
Ignition Leads	<b>85805</b>	

TALBOT		
<b>Horizon 1.3</b>	<b>1978-84</b>	
2G1-BTC	43	58
Ignition Leads	<b>83370</b>	
<b>Samba Cabriolet (51E) 1.4</b>	<b>1981-86</b>	
XY8	58	79
Ignition Leads XY8	<b>83040</b>	
<b>Simca 1000 0.9</b>	<b>1961-75</b>	
1D1	29	39
Ignition Leads	<b>85988</b>	
<b>Simca 1301 1.3 Special</b>	<b>1974-76</b>	
	40	54
Ignition Leads	<b>83370</b>	
<b>Solara 1.3</b>	<b>1980-86</b>	
6G1D/VP	40	54
Ignition Leads	<b>83370</b>	
<b>Solara 1.6</b>	<b>1982-84</b>	
J1B	51	69
Ignition Leads	<b>83370</b>	
<b>Solara 1.6</b>	<b>1981-84</b>	
6J1	54	73
Ignition Leads	<b>83370</b>	
<b>Solara 1.6</b>	<b>1980-81</b>	
6J2/J2/J1	65	88
Ignition Leads	<b>83370</b>	
<b>Solara 1.6</b>	<b>1981-86</b>	
J1B	66	90
Ignition Leads	<b>83370</b>	

TOYOTA		
<b>Allion (T26) 1.8</b>	<b>2007-&gt;</b>	
2ZR-FAE	106	144
Ignition Coil	<b>80337</b>	
<b>Allion (T26) 1.8 4WD</b>	<b>2007-&gt;</b>	
2ZR-FAE	98	133
Ignition Coil	<b>80337</b>	
<b>Allion (T26) 2.0</b>	<b>2007-&gt;</b>	
3ZR-FAE	116	158
Ignition Coil	<b>80337</b>	
<b>Auris (E15) 1.8 (ZRE152)</b>	<b>2006-12</b>	
2ZR-FAE/2ZR-FE	100	136
Ignition Coil	<b>80337</b>	
<b>Auris (E18) 1.8 Hybrid (ZWE186)</b>	<b>2012-&gt;</b>	
2ZR-FXE	73	99
Ignition Coil	<b>80337</b>	
<b>Auris (NRE15, ZZE15, ADE15, ZRE15, NDE15) 1.4 VVT-i</b>	<b>2007-12</b>	
4ZZ-FE	71	97
Ignition Coil	<b>80282</b>	
<b>Auris (NRE15, ZZE15, ADE15, ZRE15, NDE15) 1.6</b>	<b>2009-12</b>	
1ZR-FE/1ZR-FAE	97	132
Ignition Coil	<b>80337</b>	
<b>Auris (NRE15, ZZE15, ADE15, ZRE15, NDE15) 1.6 VVT-i</b>	<b>2007-12</b>	
1ZR-FE	91	124
Ignition Coil	<b>80337</b>	
<b>Auris (NRE15, ZZE15, ADE15, ZRE15, NDE15) 1.8</b>	<b>2009-12</b>	
2ZR-FAE	108	147
Ignition Coil	<b>80337</b>	

TOYOTA Cont.		
<b>Auris (NRE15, ZZE15, ADE15, ZRE15, NDE15) 1.8</b>	<b>2009-12</b>	
2ZR-FAE	106	144
Ignition Coil	<b>80337</b>	
<b>Auris (NRE15, ZZE15, ADE15, ZRE15, NDE15) 1.8 4WD</b>	<b>2009-12</b>	
2ZR-FAE	100	136
Ignition Coil	<b>80337</b>	
<b>Auris (NRE15, ZZE15, ADE15, ZRE15, NDE15) 1.8 Hybrid</b>	<b>2010-12</b>	
2ZR-FXE	73	99
Ignition Coil	<b>80337</b>	
<b>Auris (NZE18, ZRE18) 1.3</b>	<b>2012-&gt;</b>	
1NR-FE	73	99
Ignition Coil	<b>80367</b>	
<b>Auris (NZE18, ZRE18) 1.6</b>	<b>2012-&gt;</b>	
1ZR-FAE	97	132
Ignition Coil	<b>80337</b>	
<b>Auris Touring Sports (ADE18, ZWE18, ZRE18) 1.6 (ZRE185)</b>	<b>2013-&gt;</b>	
1ZR-FAE	97	132
Ignition Coil	<b>80337</b>	
<b>Auris Touring Sports (E18) 1.8 Hybrid (ZWE186)</b>	<b>2013-&gt;</b>	
2ZR-FXE	73	99
Ignition Coil	<b>80337</b>	
<b>Avensis (T22) 1,6</b>	<b>1997-00</b>	
4A-FE	74	101
Ignition Coil Terra	<b>80241</b>	
Ignition Leads 4A-FE	<b>83581</b>	
Ignition Leads	<b>83585</b>	
Ignition Leads ->07.2000	<b>83586</b>	
<b>Avensis (T22) 1,6</b>	<b>1997-00</b>	
4A-FE	81	110
Ignition Coil Terra	<b>80241</b>	
Ignition Leads 4A-FE	<b>83581</b>	
Ignition Leads	<b>83585</b>	
Ignition Leads ->07.2000	<b>83586</b>	
<b>Avensis (T22) 1,6</b>	<b>1997-00</b>	
7A-FE	81	110
Ignition Coil ->07.2000	<b>80241</b>	
Ignition Leads	<b>83586</b>	
<b>Avensis (T22) 1.6 VVT-i</b>	<b>2000-03</b>	
3ZZ-FE	81	110
Ignition Coil	<b>80282</b>	
<b>Avensis (T22) 1.8 VVT-i</b>	<b>2000-03</b>	
1ZZ-FE	95	129
Ignition Coil	<b>80282</b>	
Ignition Leads	<b>83589</b>	
<b>Avensis (T22) 2.0</b>	<b>1997-00</b>	
3S-FE	94	128
Ignition Leads	<b>83587</b>	
<b>Avensis (T25) 1.6 VVT-i</b>	<b>2003-08</b>	
3ZZ-FE	81	110
Ignition Coil	<b>80282</b>	
<b>Avensis (T25) 1.8</b>	<b>2003-08</b>	
1ZZ-FE	95	129
Ignition Coil	<b>80282</b>	
<b>Avensis (T25) 2.4</b>	<b>2003-08</b>	
2AZ-FSE	125	170
Ignition Coil	<b>80301</b>	
<b>Avensis (T25) 2.4</b>	<b>2003-08</b>	
2AZ-FSE	120	163
Ignition Coil	<b>80301</b>	
<b>Avensis Combi (T25) 1.6 VVT-i</b>	<b>2003-08</b>	
3ZZ-FE	81	110
Ignition Coil	<b>80282</b>	
<b>Avensis Combi (T25) 1.8</b>	<b>2003-08</b>	
1ZZ-FE	95	129
Ignition Coil	<b>80282</b>	
<b>Avensis Combi (T25) 2.4</b>	<b>2003-08</b>	
2AZ-FSE	125	170
Ignition Coil	<b>80301</b>	
<b>Avensis Combi (T25) 2.4</b>	<b>2003-08</b>	
2AZ-FSE	120	163
Ignition Coil	<b>80301</b>	
<b>Avensis Liftback (T22) 1,6</b>	<b>1997-00</b>	
4A-FE	74	101
Ignition Coil Terra	<b>80241</b>	
Ignition Leads 4A-FE	<b>83581</b>	
Ignition Leads	<b>83585</b>	
Ignition Leads	<b>83586</b>	



TOYOTA Cont.		
<b>Avensis Liftback (T22) 1,6</b>	1997-00	
4A-FE	81 110	
Ignition Coil Terra	<b>80241</b>	
Ignition Leads 4A-FE	<b>83581</b>	
Ignition Leads	<b>83585</b>	
Ignition Leads ->07.2000	<b>83586</b>	
<b>Avensis Liftback (T22) 1,8</b>	1997-00	
7A-FE	81 110	
Ignition Leads	<b>83586</b>	
<b>Avensis Liftback (T22) 1.6 VVT-i</b>	2000-03	
3ZZ-FE	81 110	
Ignition Coil	<b>80282</b>	
<b>Avensis Liftback (T22) 1.8 VVT-i</b>	2000-03	
1ZZ-FE	95 129	
Ignition Coil	<b>80282</b>	
Ignition Leads	<b>83589</b>	
<b>Avensis Liftback (T22) 2.0</b>	1997-00	
3S-FE	94 128	
Ignition Leads	<b>83587</b>	
<b>Avensis Sedan (T25) 1.6 VVT-i</b>	2003-08	
3ZZ-FE	81 110	
Ignition Coil	<b>80282</b>	
<b>Avensis Sedan (T25) 1.8</b>	2003-08	
1ZZ-FE	95 129	
Ignition Coil	<b>80282</b>	
<b>Avensis Sedan (T25) 2.4</b>	2003-08	
2AZ-FSE	125 170	
Ignition Coil	<b>80301</b>	
<b>Avensis Sedan (T25) 2.4</b>	2003-08	
2AZ-FSE	120 163	
Ignition Coil	<b>80301</b>	
<b>Avensis Sedan (ZRT27, ADT27) 1.6</b>	2008->	
1ZR-FAE	97 132	
Ignition Coil	<b>80337</b>	
<b>Avensis Sedan (ZRT27, ADT27) 1.8</b>	2008->	
2ZR-FAE	108 147	
Ignition Coil	<b>80337</b>	
<b>Avensis Sedan (ZRT27, ADT27) 2.0</b>	2008->	
3ZR-FAE/3ZR-FE	112 152	
Ignition Coil	<b>80337</b>	
<b>Avensis Station Wagon (T22) 1,6</b>	1997-00	
4A-FE	74 101	
Ignition Coil Terra	<b>80241</b>	
Ignition Leads 4A-FE	<b>83581</b>	
Ignition Leads	<b>83585</b>	
Ignition Leads ->07.2000	<b>83586</b>	
<b>Avensis Station Wagon (T22) 1,6</b>	1997-00	
4A-FE	81 110	
Ignition Coil Terra	<b>80241</b>	
Ignition Leads 4A-FE	<b>83581</b>	
Ignition Leads	<b>83585</b>	
Ignition Leads ->07.2000	<b>83586</b>	
<b>Avensis Station Wagon (T22) 1,8</b>	1997-00	
7A-FE	81 110	
Ignition Leads	<b>83586</b>	
<b>Avensis Station Wagon (T22) 1.6 VVT-i</b>	2000-03	
3ZZ-FE	81 110	
Ignition Coil	<b>80282</b>	
<b>Avensis Station Wagon (T22) 1.8 VVT-i</b>	2000-03	
1ZZ-FE	95 129	
Ignition Coil	<b>80282</b>	
Ignition Leads	<b>83589</b>	
<b>Avensis Station Wagon (T22) 2.0</b>	1997-00	
3S-FE	94 128	
Ignition Leads	<b>83587</b>	
<b>Avensis Station Wagon (ZRT27, ADT27) 1.6</b>	2009->	
1ZR-FAE	97 132	
Ignition Coil	<b>80337</b>	
<b>Avensis Station Wagon (ZRT27, ADT27) 1.8</b>	2009->	
2ZR-FAE	108 147	
Ignition Coil	<b>80337</b>	
<b>Avensis Station Wagon (ZRT27, ADT27) 2.0</b>	2009->	
3ZR-FAE/3ZR-FE	112 152	
Ignition Coil	<b>80337</b>	
<b>Avensis Verso (CLM2, ACM2) 2.0 VVT-i</b>	2001-09	
1AZ-FE	110 150	
Ignition Coil	<b>80344</b>	

TOYOTA Cont.		
<b>Avensis Verso (CLM2, ACM2) 2.4 VVTi GLS</b>	2003-09	
2AZ-FE	115 156	
Ignition Coil	<b>80301</b>	
<b>Aygo (B1) 1.0 GPL (KGB10_)</b>	2005->	
1KR-FE	50 68	
Ignition Coil	<b>80282</b>	
<b>Aygo (PAB4, KGB4) 1.0 (KGB40)</b>	2014->	
1KR-FE	51 69	
Ignition Coil	<b>80282</b>	
<b>Aygo (WNB1, KGB1) 1.0</b>	2005->	
1KR-FE	50 68	
Ignition Coil	<b>80282</b>	
<b>Camry (CV2, XV2) 2,2</b>	1996-01	
5S-FE	96 131	
Ignition Leads	<b>83587</b>	
<b>Camry (CV2, XV2) 2.2</b>	2000-01	
5S-FE	93 126	
Ignition Leads	<b>83587</b>	
<b>Camry (MCV3, ACV3, XV3) 2.4 VVT-i</b>	2001-06	
2AZ-FE	112 152	
Ignition Coil	<b>80344</b>	
<b>Camry (V2) 1.8 i</b>	1986-88	
1S-L	66 90	
Ignition Coil	<b>80241</b>	
<b>Camry (V2) 2.0</b>	1986-91	
3S-FE	94 128	
Ignition Coil	<b>80241</b>	
<b>Camry (V2) 2.0 Gli 16V</b>	1986-91	
3S-FE	89 121	
Ignition Coil	<b>80241</b>	
<b>Camry Liftback (V1) 2.0</b>	1986-88	
2S-ELC	73 99	
Ignition Coil	<b>80241</b>	
<b>Camry Sedan (V1) 2.0</b>	1986-88	
2S-E/2S-ELC	73 99	
Ignition Coil	<b>80241</b>	
<b>Camry Sedan (V1) 2.0 GLI</b>	1983-86	
2S-EL	79 107	
Ignition Coil	<b>80241</b>	
<b>Camry Sedan (V3) 2.0</b>	2001-06	
1AZ-FE	110 150	
Ignition Coil	<b>80344</b>	
<b>Camry Sedan (V4) 2.5</b>	2010-11	
2AR-FE	129 175	
Ignition Coil	<b>80367</b>	
<b>Camry Sedan (V4) 3.5 (GSV40_)</b>	2008-11	
2GR-FE	204 277	
Ignition Coil	<b>80368</b>	
<b>Camry Sedan (V5) 2.5 (ASV50_)</b>	2011->	
2AR-FE	133 181	
Ignition Coil	<b>80367</b>	
<b>Camry Station Wagon (V2) 1,8</b>	1986-88	
1S	66 90	
Ignition Coil	<b>80241</b>	
<b>Camry Station Wagon (V2) 2.0</b>	1986-91	
3S-FE	94 128	
Ignition Coil	<b>80241</b>	
<b>Camry Station Wagon (V2) 2.0 GLI 16V</b>	1986-91	
3S-FE	89 121	
Ignition Coil	<b>80241</b>	
<b>Carina E (T19) 1,6</b>	1993-97	
4A-FE	73 99	
Ignition Coil 4A-FE	<b>80241</b>	
Ignition Leads	<b>83581</b>	
Ignition Leads With ignition distributor	<b>83585</b>	
<b>Carina E (T19) 1,6</b>	1993-97	
4A-FE	85 116	
Ignition Coil	<b>80241</b>	
Ignition Leads	<b>83581</b>	
Ignition Leads With ignition distributor	<b>83585</b>	
<b>Carina E (T19) 1,8</b>	1995-97	
7A-FE	79 107	
Ignition Coil	<b>80241</b>	
Ignition Leads	<b>83581</b>	
Ignition Leads	<b>83585</b>	



TOYOTA Cont.		
<b>Carina E (T19) 1.6 16V</b>		1995-97
4A-FE		78 106
Ignition Coil	4A-FE	<b>80241</b>
Ignition Leads	SAE	<b>83581</b>
Ignition Leads	With ignition distributor	<b>83585</b>
<b>Carina E (T19) 1.6 GLI</b>		1992-97
4A-FE		79 107
Ignition Coil	4A-FE	<b>80241</b>
Ignition Leads	SAE	<b>83581</b>
Ignition Leads	With ignition distributor	<b>83585</b>
<b>Carina E Sedan (T19) 1,6</b>		1993-97
4A-FE		79 107
Ignition Coil	4A-FE	<b>80241</b>
Ignition Leads	SAE	<b>83581</b>
Ignition Leads	With ignition distributor	<b>83585</b>
<b>Carina E Sedan (T19) 1,6</b>		1995-97
4A-FE		73 99
Ignition Coil	4A-FE	<b>80241</b>
Ignition Leads		<b>83581</b>
Ignition Leads	With ignition distributor	<b>83585</b>
<b>Carina E Sedan (T19) 1,6</b>		1995-97
4A-FE		78 106
Ignition Coil	4A-FE	<b>80241</b>
Ignition Leads	SAE	<b>83581</b>
Ignition Leads	With ignition distributor	<b>83585</b>
<b>Carina E Sedan (T19) 1.6 16V</b>		1994-97
4A-FE		85 116
Ignition Coil	4A-FE	<b>80241</b>
Ignition Leads		<b>83581</b>
Ignition Leads	With ignition distributor	<b>83585</b>
<b>Carina E Sedan (T19) 1.8 i 16V</b>		1995-97
7A-FE		79 107
Ignition Leads		<b>83581</b>
Ignition Leads		<b>83585</b>
<b>Carina E Sportswagon (T19) 1.6</b>		1992-97
4A-FE		85 115
Ignition Leads		<b>83581</b>
<b>Carina E Sportswagon (T19) 1.6 GLI</b>		1993-97
4A-FE		79 107
Ignition Coil	4A-FE	<b>80241</b>
Ignition Leads	SAE	<b>83581</b>
Ignition Leads	With ignition distributor	<b>83585</b>
<b>Carina E Sportswagon (T19) 1.6 i</b>		1995-97
4A-FE		73 99
Ignition Coil	4A-FE	<b>80241</b>
Ignition Leads	SAE	<b>83581</b>
Ignition Leads	With ignition distributor	<b>83585</b>
<b>Carina E Sportswagon (T19) 1.8 i</b>		1995-97
7A-FE		79 107
Ignition Leads		<b>83581</b>
Ignition Leads		<b>83585</b>
<b>Carina II (T17) 1,6</b>		1987-89
4A-F		66 90
Ignition Coil	4A-FE	<b>80241</b>
<b>Carina II (T17) 1,6</b>		1987-92
4A-FE		75 102
Ignition Coil		<b>80241</b>
<b>Carina II (T17) 1,6</b>		1987-92
4A-FE		72 98
Ignition Coil		<b>80241</b>
<b>Carina II (T17) 2.0 GLI</b>		1987-92
3S-FE		89 121
Ignition Coil		<b>80241</b>
<b>Carina II Sedan (T15) 1.8 GLI</b>		1983-87
1S-EL		74 101
Ignition Coil		<b>80241</b>
<b>Carina II Sedan (T17) 1,6</b>		1987-90
4A-F		66 90
Ignition Coil		<b>80241</b>
<b>Carina II Sedan (T17) 1,6</b>		1987-92
4A-FE		75 102
Ignition Coil		<b>80241</b>
<b>Carina II Sedan (T17) 1,6</b>		1987-92
4A-FE		72 98
Ignition Coil		<b>80241</b>
<b>Carina II Sedan (T17) 2.0 GLI</b>		1987-92
3S-FE		89 121
Ignition Coil		<b>80241</b>

TOYOTA Cont.		
<b>Carina II Station Wagon (T17) 1,6</b>		1987-89
4A-F		66 90
Ignition Coil	4A-FE	<b>80241</b>
<b>Carina II Station Wagon (T17) 2.0</b>		1987-92
3S-FE		89 121
Ignition Coil		<b>80241</b>
<b>Celica (AT16, ST16) 1.6</b>		1986-89
4A-L		63 86
Ignition Coil	4A-L	<b>80241</b>
<b>Celica (ST20, AT20) 1.8 i 16V</b>		1993-99
7A-FE		85 116
Ignition Coil	7A-FE	<b>80241</b>
Ignition Leads	->12.1994	<b>83581</b>
<b>Celica (ZZT23) 1.8 16V TS</b>		1999-05
2ZZ-GE		141 192
Ignition Leads		<b>83589</b>
<b>Celica (ZZT23) 1.8 16V VT-i</b>		1999-05
1ZZ-FE		105 143
Ignition Coil		<b>80282</b>
Ignition Leads		<b>83589</b>
<b>Celica Coupe (AT18, ST18) 1.6 STI</b>		1989-93
4A-FE		77 105
Ignition Coil		<b>80241</b>
<b>Celica Liftback (ST16, AT16) 1.6</b>		1986-89
4A-L		63 86
Ignition Coil	4A-L	<b>80241</b>
<b>Corolla (E10) 1.3 12V</b>		1992-97
2E		53 72
Ignition Coil	2E	<b>80241</b>
<b>Corolla (E10) 1.3 XLI</b>		1995-97
4E-FE		55 75
Ignition Coil	4E-FE	<b>80241</b>
<b>Corolla (E10) 1.3 XLI 16V</b>		1992-95
4E-FE		65 88
Ignition Coil	4E-FE	<b>80241</b>
<b>Corolla (E10) 1.6</b>		1992-95
4A-FE		85 115
Ignition Coil		<b>80241</b>
Ignition Leads		<b>83581</b>
<b>Corolla (E10) 1.6 Si</b>		1995-97
4A-FE		84 114
Ignition Coil	4A-FE	<b>80241</b>
Ignition Leads		<b>83581</b>
<b>Corolla (E11) 1,4</b>		1997-00
4E-FE		63 86
Ignition Leads		<b>83588</b>
<b>Corolla (E11) 1.4 16V</b>		2000-01
4ZZ-FE		71 97
Ignition Coil		<b>80282</b>
Ignition Coil		<b>80369</b>
<b>Corolla (E11) 1.6 16V</b>		2000-01
3ZZ-FE		81 110
Ignition Coil		<b>80282</b>
Ignition Leads		<b>83581</b>
<b>Corolla (E11) 1.6 Aut.</b>		1997-00
4A-FE		79 107
Ignition Coil	AE111	<b>80241</b>
Ignition Leads		<b>83581</b>
<b>Corolla (E8) 1,3</b>		1984-87
2E-LC/2E-L		55 75
Ignition Coil		<b>80241</b>
<b>Corolla (E8) 1,6</b>		1985-87
4A-LC		53 72
Ignition Coil		<b>80241</b>
<b>Corolla (E8) 1,6</b>		1983-87
4A-L		62 84
Ignition Coil		<b>80241</b>
<b>Corolla (E8) 1,6</b>		1985-88
4A-LC		54 73
Ignition Coil		<b>80241</b>
<b>Corolla (E9) 1,6</b>		1987-89
4A-F		66 90
Ignition Coil	4A-F	<b>80241</b>
<b>Corolla (E9) 1.3 i</b>		1987-92
2E-E/2E		55 75
Ignition Coil	2E, 2E-E	<b>80241</b>
<b>Corolla (E9) 1.6 i</b>		1989-93
4A-FE		77 105
Ignition Coil		<b>80241</b>



TOYOTA Cont.	
<b>Corolla (E9) 1.6 i 4WD</b>	1987-90
4A-FE	77 105
Ignition Leads	<b>83581</b>
<b>Corolla (ZZE12, NDE12, ZDE12) 1.4 VVT-i</b>	2002-06
4ZZ-FE	71 97
Ignition Coil	<b>80282</b>
<b>Corolla (ZZE12, NDE12, ZDE12) 1.6 VVT-i</b>	2002-06
3ZZ-FE	81 110
Ignition Coil	<b>80282</b>
<b>Corolla Combi (E12J, E12T) 1.4 VVT-i</b>	2002-07
4ZZ-FE	71 97
Ignition Coil	<b>80282</b>
<b>Corolla Combi (E12J, E12T) 1.6 VVT-i</b>	2002-07
3ZZ-FE	81 110
Ignition Coil	<b>80282</b>
<b>Corolla Compact (E10) 1.3 12V</b>	1992-95
2E	53 72
Ignition Coil 2E	<b>80241</b>
<b>Corolla Compact (E10) 1.3 XLI</b>	1995-97
4E-FE	55 75
Ignition Coil 4E-FE	<b>80241</b>
<b>Corolla Compact (E10) 1.3 XLI 16V</b>	1992-95
4E-FE	65 88
Ignition Coil 4E-FE	<b>80241</b>
<b>Corolla Compact (E10) 1.6 i (AE101)</b>	1994-99
4A-FE	78 106
Ignition Coil ->08.1998	<b>80241</b>
Ignition Leads ->08.1998	<b>83581</b>
<b>Corolla Compact (E10) 1.6 Si</b>	1992-97
4A-FE	84 114
Ignition Coil 4A-FE	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Compact (E10) 1.8 GT</b>	1992-95
7A-FE	86 117
Ignition Coil 7A-FE	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Compact (E11) 1,4</b>	2000-02
4ZZ-FE	71 97
Ignition Coil	<b>80282</b>
Ignition Coil	<b>80369</b>
<b>Corolla Compact (E11) 1,4</b>	1997-00
4E-FE	63 86
Ignition Coil	<b>80241</b>
Ignition Leads	<b>83588</b>
<b>Corolla Compact (E11) 1,6</b>	2000-02
3ZZ-FE	81 110
Ignition Coil	<b>80282</b>
Ignition Leads	<b>83581</b>
<b>Corolla Compact (E11) 1,6</b>	1997-00
4A-FE	81 110
Ignition Coil AE111	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Compact (E11) 1.6 Aut.</b>	1997-00
4A-FE	79 107
Ignition Coil AE111	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Compact (E9) 1,3</b>	1987-89
2E	55 75
Ignition Coil 2E	<b>80241</b>
<b>Corolla Compact (E9) 1,6</b>	1987-92
4A-F	66 90
Ignition Coil 4A-F	<b>80241</b>
<b>Corolla Compact (E9) 1.6 i</b>	1989-92
4A-FE	77 105
Ignition Coil	<b>80241</b>
<b>Corolla Liftback (E10) 1.3 12V</b>	1992-95
2E	53 72
Ignition Coil 2E	<b>80241</b>
<b>Corolla Liftback (E10) 1.3 XLI</b>	1992-97
4E-FE	65 88
Ignition Coil 4E-FE	<b>80241</b>
<b>Corolla Liftback (E10) 1.6 GLI</b>	1992-97
4A-FE	84 114
Ignition Coil 4A-FE	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Liftback (E10) 1.8 GT</b>	1992-95
7A-FE	86 117
Ignition Coil 7A-FE	<b>80241</b>
Ignition Leads	<b>83581</b>

TOYOTA Cont.	
<b>Corolla Liftback (E11) 1,4</b>	2000-02
4ZZ-FE	71 97
Ignition Coil	<b>80282</b>
Ignition Coil	<b>80369</b>
<b>Corolla Liftback (E11) 1,4</b>	1997-00
4E-FE	63 86
Ignition Coil	<b>80241</b>
Ignition Leads	<b>83588</b>
<b>Corolla Liftback (E11) 1,6</b>	2000-02
3ZZ-FE	81 110
Ignition Coil	<b>80282</b>
Ignition Leads	<b>83581</b>
<b>Corolla Liftback (E11) 1,6</b>	1997-00
4A-FE	81 110
Ignition Coil AE111	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Liftback (E11) 1.6 Aut.</b>	1997-00
4A-FE	79 107
Ignition Coil AE111	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Liftback (E8) 1,6</b>	1985-87
4A-LC	54 73
Ignition Coil	<b>80241</b>
<b>Corolla Liftback (E8) 1,6</b>	1983-87
4A-L	62 84
Ignition Coil	<b>80241</b>
<b>Corolla Liftback (E8) 1.6</b>	1985-88
4A-L	63 86
Ignition Coil	<b>80241</b>
<b>Corolla Liftback (E9) 1,6</b>	1987-92
4A-F	66 90
Ignition Coil 4A-F	<b>80241</b>
<b>Corolla Liftback (E9) 1,6</b>	1989-92
4A-FE	77 105
Ignition Coil	<b>80241</b>
<b>Corolla Liftback (E9) 1.3 i</b>	1987-92
2E-E/2E	55 75
Ignition Coil 2E-E, 2E	<b>80241</b>
<b>Corolla Liftback (E9) 1.6</b>	1987-92
4A-F	70 95
Ignition Coil	<b>80241</b>
<b>Corolla Rumion (E15) 1.8</b>	2007->
2ZR-FAE	106 144
Ignition Coil OE 90919-02252; OE 90919-02258; 12.2009->	<b>80337</b>
<b>Corolla Rumion (E15) 1.8 4WD</b>	2007->
2ZR-FAE	100 136
Ignition Coil	<b>80337</b>
<b>Corolla Sedan (E12J, E12T) 1.4 VVT-i</b>	2002-07
4ZZ-FE	71 97
Ignition Coil	<b>80282</b>
<b>Corolla Sedan (E12J, E12T) 1.6 VVT-i</b>	2002-07
3ZZ-FE	81 110
Ignition Coil	<b>80282</b>
<b>Corolla Sedan (E15) 1.33</b>	2007->
1NR-FE	74 101
Ignition Coil	<b>80367</b>
<b>Corolla Sedan (E15) 1.4 VVT-i</b>	2007->
4ZZ-FE	71 97
Ignition Coil	<b>80282</b>
<b>Corolla Sedan (E15) 1.6</b>	2009->
1ZR-FE/1ZR-FAE	97 132
Ignition Coil	<b>80337</b>
<b>Corolla Sedan (E15) 1.6 Dual VVTi (ZRE141)</b>	2007->
1ZR-FE	91 124
Ignition Coil	<b>80337</b>
<b>Corolla Sedan (E15) 1.8 VVTi</b>	2010->
2ZR-FBE/2ZR-FE	103 140
Ignition Coil	<b>80337</b>
<b>Corolla Sedan (E15) 1.8 VVTLi (ZZE152)</b>	2007->
2ZR-FAE/2ZR-FE	100 136
Ignition Coil	<b>80337</b>
<b>Corolla Sedan (E18, ZRE17) 1.6 BiFuel</b>	2013->
1ZR-FE	90 122
Ignition Coil	<b>80337</b>
<b>Corolla Sedan (E18, ZRE17) 1.8 VVTi</b>	2013->
2ZR-FE	98 133
Ignition Coil	<b>80337</b>





TOYOTA Cont.	
<b>Corolla Sedan (NRE18, ZRE17, ZRE18, NDE18) 1.3 (NRE180)</b>	2013->
1NR-FE	73 99
Ignition Coil	<b>80367</b>
<b>Corolla Sedan (NRE18, ZRE17, ZRE18, NDE18) 1.6 (ZRE181)</b>	2013->
1ZR-FAE	97 132
Ignition Coil	<b>80337</b>
<b>Corolla Sedan (NRE18, ZRE17, ZRE18, NDE18) 1.8 VVTi</b>	2013->
2ZR-FBE/2ZR-FE	103 140
Ignition Coil	<b>80337</b>
<b>Corolla Station Wagon (E14) 1.8</b>	2006->
2ZR-FAE	106 144
Ignition Coil	<b>80337</b>
<b>Corolla Station Wagon (E14) 1.8 4WD</b>	2006->
2ZR-FAE	98 133
Ignition Coil	<b>80337</b>
<b>Corolla Station Wagon (E9) 1.3</b>	1987-92
2E	55 75
Ignition Coil 2E	<b>80241</b>
<b>Corolla Station Wagon (E9) 1.6</b>	1988-92
4A-F	66 90
Ignition Coil 4A-F	<b>80241</b>
<b>Corolla Station Wagon (E9) 1.6</b>	1987-92
4A-F	70 95
Ignition Coil	<b>80241</b>
<b>Corolla Station Wagon (E9) 1.6 XLI</b>	1989-92
4A-FE	77 105
Ignition Coil	<b>80241</b>
<b>Corolla Station Wagon (E9) 1.6 XLI 4WD</b>	1988-92
4A-FE	77 105
Ignition Coil	<b>80241</b>
<b>Corolla Verso (ZDE12, CDE12) 1.6 VVT-i</b>	2002-04
3ZZ-FE	81 110
Ignition Coil	<b>80282</b>
<b>Corolla Verso (ZDE12, CDE12) 1.8 VVT-i</b>	2002-04
1ZZ-FE	99 135
Ignition Coil	<b>80282</b>
<b>Corolla Verso (ZER, ZZE12, R1) 1.6</b>	2004-09
3ZZ-FE	81 110
Ignition Coil	<b>80282</b>
<b>Corolla Verso (ZER, ZZE12, R1) 1.8</b>	2004-09
1ZZ-FE	95 129
Ignition Coil	<b>80282</b>
<b>Corolla Wagon (E10) 1.3 12V</b>	1992-95
2E	53 72
Ignition Coil 2E	<b>80241</b>
<b>Corolla Wagon (E10) 1.3 XLI</b>	1995-97
4E-FE	55 75
Ignition Coil 4E-FE	<b>80241</b>
<b>Corolla Wagon (E10) 1.3 XLI 16V</b>	1992-95
4E-FE	65 88
Ignition Coil AE-FE	<b>80241</b>
<b>Corolla Wagon (E10) 1.6 Si</b>	1992-97
4A-FE	84 114
Ignition Coil 4A-FE	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Wagon (E10) 1.8 16V 4WD</b>	1995-97
7A-FE	81 110
Ignition Coil 7A-FE	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Wagon (E11) 1,4</b>	1997-00
4E-FE	63 86
Ignition Leads	<b>83588</b>
<b>Corolla Wagon (E11) 1,6</b>	1997-00
4A-FE	81 110
Ignition Coil AE111	<b>80241</b>
Ignition Leads	<b>83581</b>
<b>Corolla Wagon (E11) 1.4 16V</b>	2000-01
4ZZ-FE	71 97
Ignition Coil	<b>80282</b>
Ignition Coil	<b>80369</b>
<b>Corolla Wagon (E11) 1.6 16V</b>	2000-01
3ZZ-FE	81 110
Ignition Coil	<b>80282</b>
Ignition Leads	<b>83581</b>
<b>Corolla Wagon (E11) 1.6 Aut.</b>	1997-00
4A-FE	79 107
Ignition Coil AE111	<b>80241</b>
Ignition Leads	<b>83581</b>

TOYOTA Cont.	
<b>Corolla Wagon (E11) 1.8 4WD</b>	1997-01
7A-FE	81 110
Ignition Coil	<b>80241</b>
Ignition Leads ->07.2001	<b>83581</b>
<b>Cressida Sedan (Rx3) 2.0</b>	1977-81
18R	66 90
Ignition Leads 18R	<b>83220</b>
<b>Cressida Station Wagon (RX3) 2.0</b>	1977-81
18R	66 90
Ignition Leads 18R	<b>83220</b>
<b>FJ Cruiser (GSJ1) 4.0 4WD (GSJ15_)</b>	2011->
1GR-FE	203 276
Ignition Coil	<b>80367</b>
<b>Hiace I Van (RH1, LH3, RH3, RH2, LH2, LH1) 1,6</b>	1977-83
12R	49 67
Ignition Leads 12R	<b>83210</b>
<b>Hiace I Wagon (LH1, RH1, LH3, RH3, LH2, RH2) 1.6</b>	1977-82
12R	49 67
Ignition Leads 12R	<b>83210</b>
<b>Hiace III Van (YH7, LH6, LH7, LH5, YH5, YH6) 2.0</b>	1990-95
1RZ	74 101
Ignition Coil 1RZ	<b>80241</b>
<b>Hiace III Van (YH7, LH6, LH7, LH5, YH5, YH6) 2.4</b>	1989-95
2RZ-E	88 120
Ignition Coil	<b>80241</b>
<b>Hiace III Van (YH7, LH6, LH7, LH5, YH5, YH6) 2.4 4WD</b>	1989-95
2RZ-E	88 120
Ignition Coil	<b>80241</b>
<b>Hiace III Wagon (LH1, RZH1) 2,4</b>	1989-95
2RZ-E	88 120
Ignition Coil	<b>80241</b>
<b>Hiace III Wagon (LH1, RZH1) 2.0</b>	1989-98
1RZ	74 101
Ignition Coil 1RZ	<b>80241</b>
<b>Hiace III Wagon (LH1, RZH1) 2.4 4WD</b>	1989-95
2RZ-E	88 120
Ignition Coil	<b>80241</b>
<b>Hiace IV Bus (LH1) 2,4</b>	1995-98
2RZ-E	85 115
Ignition Coil 2RZ-E	<b>80241</b>
<b>Hiace IV Bus (LH1) 2.4 4WD</b>	1995-98
2RZ-E	85 116
Ignition Coil 2RZ-E	<b>80241</b>
<b>Hiace IV Van (LXH1, RZH1, LH1) 2,4</b>	1995-05
2RZ-E	85 116
Ignition Coil 2RZ-E	<b>80241</b>
<b>Hiace IV Van (LXH1, RZH1, LH1) 2.4 4WD</b>	1995-98
2RZ-E	85 116
Ignition Coil 2RZ-E	<b>80241</b>
<b>Hilux II Pick-up (RN6, RN5, LN6, YN6, YN5, LN5) 1,8</b>	1988-98
2Y	61 83
Ignition Coil	<b>80241</b>
<b>IQ (KPJ1, NGJ1, KGJ1, NUJ1) 1.0</b>	2009->
1KR-FE	50 68
Ignition Coil	<b>80242</b>
<b>IQ (KPJ1, NGJ1, KGJ1, NUJ1) 1.33</b>	2009->
1NR-FE	72 98
Ignition Coil	<b>80367</b>
<b>Isis (M1) 1.8 VVTi</b>	2007->
2ZR-FAE	106 144
Ignition Coil	<b>80337</b>
<b>Isis (M1) 1.8 VVTi 4WD</b>	2007->
2ZR-FAE	98 133
Ignition Coil	<b>80337</b>
<b>Isis (M1) 2.0 VVTi</b>	2007->
3ZR-FAE	116 158
Ignition Coil	<b>80337</b>
<b>Kluger (U4) 3.5 4WD (GSU45_)</b>	2007->
2GR-FE	201 273
Ignition Coil	<b>80368</b>
<b>Land Cruiser (J15) 2.7</b>	2010->
2TR-FE	120 163
Ignition Coil	<b>80344</b>
<b>Land Cruiser (J15) 4.0 V6 Dual VVTi (GRJ150_)</b>	2009->
1GR-FE	205 279
Ignition Coil	<b>80367</b>
<b>Land Cruiser (KDJ12, GRJ12) 4</b>	2003-09
1GR-FE	183 249
Ignition Coil	<b>80301</b>



TOYOTA Cont.	
<b>Land Cruiser (VDJ20, UZJ20) 4.6 V8</b>	2012->
1UR-FE	234 318
Ignition Coil	<b>80367</b>
<b>Land Cruiser 150 (KDJ15, GRJ15) 4.0 V6 VVT-i</b>	2009->
1GR-FE	207 282
Ignition Coil	<b>80367</b>
<b>Land Cruiser 200 (J2) 4.6 V8</b>	2010->
1UR-FE	227 309
Ignition Coil	<b>80367</b>
<b>Mark X I (GRX12) 2.5 VVTi</b>	2004-09
4GR-FSE	158 215
Ignition Coil	<b>80367</b>
<b>Mark X I (GRX12) 2.5 VVTi 4WD</b>	2004-09
4GR-FSE	158 215
Ignition Coil	<b>80367</b>
<b>Mark X I (GRX12) 3.0 VVTi</b>	2004-09
3GR-FSE	183 249
Ignition Coil	<b>80367</b>
<b>Model F Bus (R2, 31) 1.8 De Luxe</b>	1982-84
2Y-C/2Y	58 79
Ignition Coil	<b>80241</b>
<b>Model F Bus (R2, 31) 2,2</b>	1985-90
4Y-EC	72 98
Ignition Coil	<b>80241</b>
<b>Model F Bus (R2, 31) 2.0</b>	1988-90
3Y	66 90
Ignition Coil	<b>80241</b>
<b>Model F Bus (R2, 31) 2.0 Super</b>	1984-88
3Y/3Y-C	65 88
Ignition Coil	<b>80241</b>
<b>MR 2 III (ZZW3) 1.8 16V VT-i</b>	1999-07
1ZZ-FE	103 140
Ignition Coil	<b>80282</b>
<b>Noah/Voxy (R7) 2.0</b>	2007->
3ZR-FAE	116 158
Ignition Coil	<b>80337</b>
<b>Noah/Voxy (R7) 2.0 4WD</b>	2007-13
3ZR-FAE	114 155
Ignition Coil	<b>80337</b>
<b>Noah/Voxy (R8) 2.0</b>	2013->
3ZR-FAE	111 151
Ignition Coil	<b>80337</b>
<b>Noah/Voxy (R8) 2.0 4WD</b>	2013->
3ZR-FAE	111 151
Ignition Coil	<b>80337</b>
<b>Paseo Cabrio (E154) 1.5</b>	1996-98
5E-FE	66 90
Ignition Coil 5E-FE	<b>80241</b>
<b>Paseo Coupe (E154) 1.5 16V</b>	1995-99
5E-FE	66 90
Ignition Coil 5E-FE	<b>80241</b>
<b>Picnic (XM10) 2.0</b>	2001-01
3S-FE	90 122
Ignition Leads	<b>83587</b>
<b>Picnic (XM10) 2.0 16V</b>	1996-01
3S-FE	94 128
Ignition Leads	<b>83587</b>
<b>Premio (T26) 1.8</b>	2007-12
2ZR-FAE	106 144
Ignition Coil	<b>80337</b>
<b>Premio (T26) 1.8 4WD</b>	2007->
2ZR-FAE	98 133
Ignition Coil	<b>80337</b>
<b>Premio (T26) 2.0</b>	2007->
3ZR-FAE	116 158
Ignition Coil	<b>80337</b>
<b>Premio (T26) 2.0 4WD</b>	2007->
3ZR-FAE	116 158
Ignition Coil	<b>80337</b>
<b>Previa (MCR3, ACR3, CLR3) 2.4</b>	2000-06
2AZ-FE	115 156
Ignition Coil	<b>80301</b>
Ignition Coil	<b>80344</b>
<b>Prius (ZVW3) 1.8 Hybrid</b>	2009->
2ZR-FXE	73 99
Ignition Coil	<b>80337</b>
<b>Prius Liftback (NHW20) 1.5</b>	2003-09
1NZ-FXE	57 78
Ignition Coil 1NZ-FXE	<b>80242</b>

TOYOTA Cont.	
<b>Prius Plus (ZVW4) 1.8 Hybrid</b>	2011->
2ZR-FXE	73 99
Ignition Coil	<b>80337</b>
<b>Prius Sedan (NHW11) 1.5 Hybrid</b>	2000-04
1NZ-FXE	53 72
Ignition Coil 03.2003->	<b>80242</b>
<b>Rav 4 I (SXA1) 2.0 4WD</b>	1994-00
3S-FE	95 129
Ignition Coil	<b>80241</b>
Ignition Leads	<b>83587</b>
<b>Rav 4 I Cabrio (SXA1) 2.0 16V 4WD</b>	1997-00
3S-FE	94 129
Ignition Leads	<b>83587</b>
<b>Rav 4 II (CLA2, XA2, ZCA2, ACA2) 1.8 VVTi</b>	2000-05
1ZZ-FE	92 125
Ignition Coil	<b>80282</b>
<b>Rav 4 II (CLA2, XA2, ZCA2, ACA2) 2.0 VVTi 4WD</b>	2000-05
1AZ-FE	110 150
Ignition Coil	<b>80344</b>
<b>Rav 4 III (A3) 2.0 VVT-i</b>	2009->
3ZR-FAE	109 148
Ignition Coil	<b>80337</b>
<b>Rav 4 III (A3) 2.0 VVT-i 4WD</b>	2009->
3ZR-FAE	109 148
Ignition Coil	<b>80337</b>
<b>Rav 4 III (A3) 2.0 VVT-i 4WD</b>	2005->
2AZ-FE	125 170
Ignition Coil	<b>80344</b>
<b>Rav 4 III (A3) 3.5 4WD</b>	2007->
2GR-FE	206 280
Ignition Coil	<b>80368</b>
<b>Rav 4 III (A3) 3.5 VVTi 4WD (GSA33)</b>	2005->
2GR-FE	201 273
Ignition Coil	<b>80368</b>
<b>Rav 4 III (ACA3, ACE, ALA3, GSA3, ZSA3) 2.0</b>	2008->
3ZR-FAE	116 158
Ignition Coil	<b>80337</b>
<b>Rav 4 III (ACA3, ACE, ALA3, GSA3, ZSA3) 2.0 4WD</b>	2008->
3ZR-FAE	116 158
Ignition Coil	<b>80337</b>
<b>Rav 4 III (ACA3, ACE, ALA3, GSA3, ZSA3) 2.0 VVT-i 4WD</b>	2006->
1AZ-FE	112 152
Ignition Coil	<b>80344</b>
<b>Rav 4 III (ACA3, ACE, ALA3, GSA3, ZSA3) 2.4 VVTi</b>	2005->
2AZ-FE	125 170
Ignition Coil	<b>80344</b>
<b>Rav 4 IV (A4) 2.0 VVT-i</b>	2012->
3ZR-FAE	107 146
Ignition Coil	<b>80337</b>
<b>Rav 4 IV (A4) 2.5 VVT-i 4WD</b>	2012->
2AR-FE	132 180
Ignition Coil	<b>80367</b>
<b>Rav 4 IV (ZSA4, ALA4) 2.0 VVT-i 4WD</b>	2012->
3ZR-FAE	111 151
Ignition Coil	<b>80337</b>
<b>Starlet (Ep91) 1.3</b>	1996-99
4E-FE	55 75
Ignition Coil 4E-FE	<b>80241</b>
<b>Starlet (P7) 1,3</b>	1984-89
2E-LC	55 75
Ignition Coil	<b>80241</b>
<b>Starlet (P7) 1.0</b>	1984-89
1E-L	40 54
Ignition Leads 01.1986->	<b>85350</b>
<b>Starlet (P8) 1.0</b>	1989-92
1E	40 54
Ignition Coil 01.1992->	<b>80241</b>
<b>Starlet (P8) 1.3 12V</b>	1989-92
2E-E/2E	55 75
Ignition Coil 2E, 2E-E	<b>80241</b>
Ignition Leads	<b>85350</b>
<b>Starlet (P8) 1.3 12V KAT</b>	1989-96
2E-E	55 75
Ignition Coil 2E-E	<b>80241</b>
Ignition Leads	<b>85350</b>
<b>Urban Cruiser (NSP1, NLP1, ZSP1, NCP11) 1.33</b>	2009->
1NR-FE	74 101
Ignition Coil	<b>80367</b>



TOYOTA Cont.	
<b>Urban Cruiser (NSP1, NLP1, ZSP1, NCP11) 1.33</b>	<b>2009-&gt;</b>
1NR-FE	73 99
Ignition Coil	<b>80367</b>
<b>Venza (V1) 2.7 (AGV10_)</b>	<b>2008-&gt;</b>
1AR-FE	136 185
Ignition Coil	<b>80367</b>
<b>Venza (V1) 2.7 4WD (AGV15_)</b>	<b>2008-&gt;</b>
1AR-FE	136 185
Ignition Coil	<b>80367</b>
<b>Verso (AUR2, ZGR2) 1.6</b>	<b>2009-&gt;</b>
1ZR-FAE	97 132
Ignition Coil	<b>80337</b>
<b>Verso (AUR2, ZGR2) 1.8</b>	<b>2009-&gt;</b>
2ZR-FAE	108 147
Ignition Coil	<b>80337</b>
<b>Verso S (NLP12, NCP12, NSP12) 1.33</b>	<b>2010-16</b>
1NR-FE	73 99
Ignition Coil	<b>80367</b>
<b>Verso S (P12) 1.33 (NSP120_)</b>	<b>2010-16</b>
1NR-FE	70 95
Ignition Coil	<b>80367</b>
<b>Vios/Yaris Sedan (P9) 1.0 (KSP90_)</b>	<b>2007-&gt;</b>
1KR-FE	52 71
Ignition Coil	<b>80282</b>
<b>Wish MPV (E2) 2.0 (ZGE21, ZGE22)</b>	<b>2009-&gt;</b>
3ZR-FAE	116 158
Ignition Coil	<b>80337</b>
<b>Wish MPV (E2) 2.0 4WD (ZGE21, ZGE22)</b>	<b>2009-&gt;</b>
3ZR-FAE	116 158
Ignition Coil	<b>80337</b>
<b>Yaris (NHP13, NSP13, NCP13, KSP13, NLP13) 1.0</b>	<b>2010-&gt;</b>
1KR-FE	51 69
Ignition Coil	<b>80282</b>
<b>Yaris (NHP13, NSP13, NCP13, KSP13, NLP13) 1.3</b>	<b>2011-&gt;</b>
1NR-FKE/1NR-FE	73 99
Ignition Coil	<b>80367</b>
<b>Yaris (NHP13, NSP13, NCP13, KSP13, NLP13) 1.3</b>	<b>2011-&gt;</b>
1NR-FE	70 95
Ignition Coil	<b>80367</b>
<b>Yaris (P9) 1.0 GPL (KSP90_)</b>	<b>2006-&gt;</b>
1KR-FE	51 69
Ignition Coil	<b>80282</b>
<b>Yaris (SCP1, NLP1, NCP1) 1.0 16V</b>	<b>1999-05</b>
1SZ-FE	50 68
Ignition Coil	<b>80242</b>
<b>Yaris (SCP1, NLP1, NCP1) 1.0 16V</b>	<b>2003-05</b>
1SZ-FE	48 65
Ignition Coil	<b>80242</b>
<b>Yaris (SCP1, NLP1, NCP1) 1.3</b>	<b>1999-05</b>
2SZ-FE	64 87
Ignition Coil	<b>80242</b>
<b>Yaris (SCP1, NLP1, NCP1) 1.3 16V</b>	<b>1999-05</b>
2NZ-FE/2SZ-FE	63 86
Ignition Coil	<b>80242</b>
<b>Yaris (SCP1, NLP1, NCP1) 1.5 TS</b>	<b>2003-05</b>
1NZ-FE	77 105
Ignition Coil	<b>80242</b>
<b>Yaris (SCP1, NLP1, NCP1) 1.5 VVT-i TS</b>	<b>2001-05</b>
1NZ-FE	78 106
Ignition Coil	<b>80242</b>
<b>Yaris (SCP1, NLP1, NCP1) 1.5 VVT-i TS</b>	<b>2000-05</b>
1NZ-FE	110 150
Ignition Coil	<b>80242</b>
<b>Yaris (SCP9, NSP9, KSP9, NCP9, ZSP9) 1.0 VVT-i</b>	<b>2005-11</b>
1KR-FE	51 69
Ignition Coil	<b>80282</b>
<b>Yaris (SCP9, NSP9, KSP9, NCP9, ZSP9) 1.3 VVT-i</b>	<b>2005-&gt;</b>
2SZ-FE	64 87
Ignition Coil	<b>80242</b>
<b>Yaris (SCP9, NSP9, KSP9, NCP9, ZSP9) 1.33 VVT-i</b>	<b>2008-&gt;</b>
1NR-FE	74 100
Ignition Coil	<b>80367</b>
<b>Yaris (SCP9, NSP9, KSP9, NCP9, ZSP9) 1.33 VVT-i</b>	<b>2010-&gt;</b>
1NR-FE	73 99
Ignition Coil	<b>80367</b>
<b>Yaris (SCP9, NSP9, KSP9, NCP9, ZSP9) 1.8 VVTi</b>	<b>2007-&gt;</b>
2ZR-FE	98 133
Ignition Coil	<b>80337</b>
Ignition Coil	OE 90919-02252

TOYOTA Cont.	
<b>Yaris Verso (NLP2, NCP2) 1,3</b>	<b>1999-02</b>
2NZ-FE	63 86
Ignition Coil	<b>80242</b>
<b>Yaris Verso (NLP2, NCP2) 1,3</b>	<b>2002-05</b>
2NZ-FE	62 84
Ignition Coil	<b>80242</b>
<b>Yaris Verso (NLP2, NCP2) 1,5</b>	<b>2000-05</b>
1NZ-FE	78 106
Ignition Coil	<b>80242</b>
03.2003->	
<b>Yaris Verso (NLP2, NCP2) 1,5</b>	<b>2003-05</b>
1NZ-FE	77 105
Ignition Coil	<b>80242</b>
1NZ-FE	
TRIUMPH	
<b>1300 1.3 TC</b>	<b>1967-70</b>
GE1EH	56 76
Ignition Leads	<b>83850</b>
<b>Acclaim 1,3</b>	<b>1982-85</b>
EJ	51 69
Ignition Leads	<b>83450</b>
<b>Herald 1200</b>	<b>1968-69</b>
AJM	35 48
Ignition Leads	<b>85115</b>
VAUXHALL	
<b>Adam 1.2</b>	<b>2012-&gt;</b>
A 12 XEL/B 12 XEL	51 69
Ignition Coil	<b>80322</b>
<b>Adam 1.4</b>	<b>2012-&gt;</b>
A 14 XEL	64 87
Ignition Coil	<b>80322</b>
<b>Adam 1.4</b>	<b>2012-&gt;</b>
A 14 XER	74 101
Ignition Coil	<b>80322</b>
<b>Agila Mk I (A) 1.0 12V</b>	<b>2000-05</b>
Z 10 XE	43 58
Ignition Coil	<b>80259</b>
<b>Agila Mk I (A) 1.0 12V</b>	<b>2000-06</b>
Z 10 XEP	44 60
Ignition Coil	<b>80259</b>
<b>Agila Mk I (A) 1.2 16V</b>	<b>2000-08</b>
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Agila Mk I (A) 1.2 16V Twinport</b>	<b>2004-06</b>
Z 12 XEP	59 80
Ignition Coil	<b>80350</b>
<b>Agila Mk II (B) 1.0 12V</b>	<b>2008-14</b>
K10B	48 65
Ignition Coil	<b>80268</b>
<b>Agila Mk II (B) 1.0 i</b>	<b>2011-14</b>
K10B	50 68
Ignition Coil	<b>80268</b>
<b>Agila Mk II (B) 1.2 i 16V</b>	<b>2008-14</b>
K12B	63 86
Ignition Coil	<b>80268</b>
<b>Agila Mk II (B) 1.2 i 16V</b>	<b>2008-14</b>
K12B	69 94
Ignition Coil	<b>80268</b>
<b>Ampera EV 150 (D1J0I)</b>	<b>2012-&gt;</b>
4ET50/A 14 XFL	111 151
Ignition Coil	<b>80322</b>
<b>Antara (J26, H26) 2.4</b>	<b>2010-15</b>
A 24 XE	123 167
Ignition Coil	<b>80329</b>
<b>Antara (J26, H26) 2.4</b>	<b>2010-15</b>
A 24 XE	123 167
Ignition Coil	<b>80329</b>
<b>Antara (J26, H26) 2.4</b>	<b>2010-15</b>
A 24 XE	126 171
Ignition Coil	<b>80329</b>
12.2010->	
<b>Antara (J26, H26) 2.4</b>	<b>2010-15</b>
A 24 XE	126 171
Ignition Coil	<b>80329</b>
12.2010->	
<b>Astra Mk II Belmont 1.3</b>	<b>1985-91</b>
13 S	55 75
Ignition Coil	<b>80261</b>



VAUXHALL Cont.	
<b>Astra Mk II Belmont 1.4 i</b>	1990-91
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
<b>Astra Mk II Belmont 1.6</b>	1985-91
16 SH	66 90
Ignition Coil 16SV	<b>80261</b>
Ignition Coil	<b>80262</b>
<b>Astra Mk II Belmont 1.6 S</b>	1989-91
16 SV	60 82
Ignition Coil 16SV	<b>80261</b>
Ignition Coil	<b>80262</b>
<b>Astra Mk II Belmont 1.8</b>	1986-90
18 SE	82 111
Ignition Coil	<b>80262</b>
<b>Astra Mk II Belmont 1.8 i</b>	1985-91
18 SE/18 E	85 115
Ignition Coil	<b>80262</b>
<b>Astra Mk II CC 1.2</b>	1984-91
12 S	44 60
Ignition Coil	<b>80261</b>
<b>Astra Mk II CC 1.3</b>	1984-91
13 S	55 75
Ignition Coil	<b>80261</b>
<b>Astra Mk II CC 1.4 i</b>	1990-91
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
<b>Astra Mk II CC 1.4 S</b>	1990-91
14 NV	55 75
Ignition Coil	<b>80210</b>
<b>Astra Mk II CC 1.6</b>	1984-91
16 SV	60 82
Ignition Coil 16SV	<b>80261</b>
Ignition Coil	<b>80262</b>
<b>Astra Mk II CC 1.6 S</b>	1984-86
16 SH	66 90
Ignition Coil	<b>80262</b>
<b>Astra Mk II CC 1.8 GTE</b>	1984-91
18 SE/18 E	82 112
Ignition Coil	<b>80262</b>
<b>Astra Mk II Convertible 1.6 i</b>	1987-91
16 SV	60 82
Ignition Coil 16SV	<b>80261</b>
Ignition Coil	<b>80262</b>
<b>Astra Mk II Estate 1.3</b>	1984-91
13 S	55 75
Ignition Coil	<b>80261</b>
<b>Astra Mk II Estate 1.6</b>	1984-91
16 SV	60 82
Ignition Coil 16SV	<b>80261</b>
Ignition Coil	<b>80262</b>
<b>Astra Mk III (F) 1.4 i</b>	1992-98
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astra Mk III (F) 1.4 i</b>	1992-98
C 14 SE	60 82
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astra Mk III (F) 1.4 i 16V</b>	1996-98
X 14 XE	66 90
Ignition Coil	<b>80209</b>
<b>Astra Mk III (F) 1.6 i</b>	1994-96
X 16 SZ	52 71
Ignition Coil	<b>80210</b>
<b>Astra Mk III (F) 1.6 i</b>	1992-98
C 16 NZ/X 16 SZR	55 75
Ignition Coil	<b>80210</b>
<b>Astra Mk III (F) 1.6 i</b>	1992-94
C 16 SE	74 100
Ignition Coil	<b>80210</b>
<b>Astra Mk III (F) 1.6 i 16V</b>	1994-98
X 16 XEL	74 100
Ignition Coil	<b>80209</b>
<b>Astra Mk III (F) 1.8 i</b>	1992-98
C 18 NZ	66 90
Ignition Coil	<b>80262</b>
<b>Astra Mk III (F) 1.8 i 16V</b>	1993-94
C 18 XE	92 125
Ignition Coil	<b>80223</b>

VAUXHALL Cont.	
<b>Astra Mk III (F) 1.8 i 16V</b>	1994-96
C 18 XEL	85 115
Ignition Coil	<b>80223</b>
<b>Astra Mk III (F) 2.0 i 16V</b>	1995-98
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Astra Mk III (F) CC 1.4 i</b>	1991-98
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astra Mk III (F) CC 1.4 i</b>	1992-98
C 14 SE	60 82
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astra Mk III (F) CC 1.4 i 16V</b>	1996-98
X 14 XE	66 90
Ignition Coil	<b>80209</b>
<b>Astra Mk III (F) CC 1.4 S</b>	1991-98
14 NV	55 75
Ignition Leads	<b>85105</b>
<b>Astra Mk III (F) CC 1.6 i</b>	1991-98
C 16 NZ/E 16 NZ	55 75
Ignition Coil	<b>80261</b>
<b>Astra Mk III (F) CC 1.6 i</b>	1992-98
C 16 SE	74 100
Ignition Coil	<b>80209</b>
<b>Astra Mk III (F) CC 1.6 i</b>	1993-96
X 16 SZ	52 71
Ignition Coil	<b>80210</b>
<b>Astra Mk III (F) CC 1.6 i 16V</b>	1994-98
X 16 XEL	74 101
Ignition Coil	<b>80209</b>
<b>Astra Mk III (F) CC 1.8 i</b>	1991-98
C 18 NZ	66 90
Ignition Coil	<b>80262</b>
<b>Astra Mk III (F) CC 1.8 i 16V</b>	1994-98
C 18 XE	92 125
Ignition Coil	<b>80223</b>
<b>Astra Mk III (F) CC 1.8 i 16V</b>	1994-98
C 18 XEL	85 115
Ignition Coil	<b>80223</b>
<b>Astra Mk III (F) CC 2.0 i 16V</b>	1994-98
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Astra Mk III (F) CC 2.0 i 16V</b>	1991-98
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Astra Mk III (F) Convertible 1.4 i</b>	1993-01
C 14 SE	60 82
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astra Mk III (F) Convertible 1.6 i</b>	1993-96
X 16 SZ	52 71
Ignition Coil	<b>80210</b>
<b>Astra Mk III (F) Convertible 1.6 i</b>	1996-01
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
<b>Astra Mk III (F) Convertible 1.8 16V</b>	1994-01
X 18 XE/C 18 XEL	85 116
Ignition Coil	<b>80223</b>
<b>Astra Mk III (F) Estate 1.4 i</b>	1991-98
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astra Mk III (F) Estate 1.4 i</b>	1991-98
C 14 SE	60 82
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astra Mk III (F) Estate 1.4 i 16V</b>	1996-98
X 14 XE	66 90
Ignition Coil	<b>80209</b>
<b>Astra Mk III (F) Estate 1.4 S</b>	1991-98
14 NV	55 75
Ignition Leads	<b>85105</b>
<b>Astra Mk III (F) Estate 1.6 i</b>	1991-98
C 16 NZ/E 16 NZ	55 75
Ignition Coil	<b>80261</b>



VAUXHALL Cont.	
<b>Astra Mk III (F) Estate 1.6 i</b>	1994-98
X 16 SZ	52 71
Ignition Coil	<b>80210</b>
<b>Astra Mk III (F) Estate 1.6 i 16V</b>	1994-98
X 16 XEL	74 100
Ignition Coil	<b>80209</b>
<b>Astra Mk III (F) Estate 1.6 Si</b>	1991-94
C 16 SE	74 100
Ignition Coil	<b>80210</b>
<b>Astra Mk III (F) Estate 1.8 i</b>	1991-98
C 18 NZ	66 90
Ignition Coil	<b>80262</b>
<b>Astra Mk III (F) Estate 1.8 i 16V</b>	1994-98
C 18 XE	92 125
Ignition Coil	<b>80223</b>
<b>Astra Mk III (F) Estate 1.8 i 16V</b>	1994-98
X 18 XE/C 18 XEL	85 115
Ignition Coil	<b>80223</b>
<b>Astra Mk III (F) Estate 2.0 i 16V</b>	1994-98
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Astra Mk IV (G) CC 1.2 16V</b>	1998-00
X 12 XE	48 65
Ignition Coil	<b>80257</b>
<b>Astra Mk IV (G) CC 1.2 16V</b>	2000-05
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Astra Mk IV (G) CC 1.4 16V</b>	1998-05
X 14 XE/Z 14 XE	66 90
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Astra Mk IV (G) CC 1.6</b>	1998-00
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
<b>Astra Mk IV (G) CC 1.6 16V</b>	1998-05
Z 16 XE/X 16 XEL	74 101
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Astra Mk IV (G) CC 1.6 Dualfuel</b>	2002-05
Z 16 XE	63 85
Ignition Coil	<b>80209</b>
<b>Astra Mk IV (G) CC 1.8 16V</b>	1998-00
X 18 XE1	85 116
Ignition Coil	<b>80224</b>
<b>Astra Mk IV (G) CC 1.8 16V</b>	2000-05
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra Mk IV (G) CC 1.8 16V Dualfuel</b>	2002-05
Z 18 XE	87 118
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra Mk IV (G) CC 2.0 16V</b>	1998-05
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Astra Mk IV (G) CC 2.0 SRI Turbo</b>	2001-05
Z 20 LET	141 192
Ignition Coil	<b>80354</b>
<b>Astra Mk IV (G) Convertible 1.6 16V</b>	2001-05
Z 16 XE	74 101
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Astra Mk IV (G) Convertible 1.8 16V</b>	2001-05
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra Mk IV (G) Convertible 2.0</b>	2002-05
Z 20 LET	147 199
Ignition Coil ->08.2005	<b>80354</b>
<b>Astra Mk IV (G) Convertible 2.0 Turbo</b>	2002-05
Z 20 LET	141 192
Ignition Coil ->08.2005	<b>80354</b>
<b>Astra Mk IV (G) Coupe (F67) 1.8 16V</b>	2000-05
Z 18 XEL/X 18 XE1	85 115
Ignition Coil	<b>80224</b>
<b>Astra Mk IV (G) Coupe (F67) 1.8 16V</b>	2000-05
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra Mk IV (G) Coupe (F67) 1.8 16V Dualfuel</b>	2002-05
Z 18 XE	87 118
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra Mk IV (G) Coupe (F67) 2.0 16V Turbo</b>	2000-05
Z 20 LET	140 190
Ignition Coil	<b>80354</b>

VAUXHALL Cont.	
<b>Astra Mk IV (G) Estate 1.2 16V</b>	1998-00
X 12 XE	48 65
Ignition Coil	<b>80257</b>
<b>Astra Mk IV (G) Estate 1.2 16V</b>	2000-05
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Astra Mk IV (G) Estate 1.4 16V</b>	1998-05
X 14 XE/Z 14 XE	66 90
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Astra Mk IV (G) Estate 1.6</b>	1998-04
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
<b>Astra Mk IV (G) Estate 1.6 16V</b>	1998-04
Z 16 XE/X 16 XEL	74 101
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Astra Mk IV (G) Estate 1.6 Dualfuel</b>	1998-04
Z 16 XE	63 85
Ignition Coil	<b>80209</b>
<b>Astra Mk IV (G) Estate 1.8 16V</b>	1998-00
X 18 XE1	85 116
Ignition Coil	<b>80224</b>
<b>Astra Mk IV (G) Estate 1.8 16V</b>	2000-05
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra Mk IV (G) Estate 1.8 16V Dualfuel</b>	2002-05
Z 18 XE	87 118
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra Mk IV (G) Estate 2.0 16V</b>	1998-05
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Astra Mk IV (G) Saloon 1.2 16V</b>	1998-00
X 12 XE	48 65
Ignition Coil	<b>80257</b>
<b>Astra Mk IV (G) Saloon 1.2 16V</b>	2000-05
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Astra Mk IV (G) Saloon 1.4 16V</b>	1998-05
X 14 XE/Z 14 XE	66 90
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Astra Mk IV (G) Saloon 1.6</b>	1998-00
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
<b>Astra Mk IV (G) Saloon 1.6 16V</b>	1998-05
Z 16 XE/X 16 XEL/Z 16 XEP/C 16 SEL	74 101
Ignition Coil Z 16 XE, X 16 XEL; With regul.cat.(3way)	<b>80209</b>
<b>Astra Mk IV (G) Saloon 1.6 Dualfuel</b>	2002-05
Z 16 XE	63 85
Ignition Coil	<b>80209</b>
<b>Astra Mk IV (G) Saloon 1.8 16V</b>	1998-04
X 18 XE1	85 116
Ignition Coil	<b>80224</b>
<b>Astra Mk IV (G) Saloon 1.8 16V Dualfuel</b>	1998-04
Z 18 XE	87 118
Ignition Coil Z 18 XE	<b>80224</b>
<b>Astra Mk IV (G) Saloon 2.0 16V</b>	1998-05
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Astra Mk V (H) CC 1.4</b>	2004-05
Z 14 XEL	55 75
Ignition Coil	<b>80350</b>
<b>Astra Mk V (H) CC 1.4</b>	2004-09
Z 14 XEP	66 90
Ignition Coil	<b>80350</b>
<b>Astra Mk V (H) CC 1.6</b>	2004-09
Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Astra Mk V (H) CC 2.0 Turbo</b>	2004-09
Z 20 LER	125 170
Ignition Coil ->02.2009	<b>80354</b>
<b>Astra Mk V (H) CC 2.0 Turbo</b>	2004-09
Z 20 LER	147 200
Ignition Coil	<b>80354</b>
<b>Astra Mk V (H) CC 2.0 Turbo</b>	2004-09
Z 20 LEH	177 240
Ignition Coil	<b>80354</b>



**VAUXHALL Cont.**

<b>Astra Mk V (H) Estate 1.4</b>	<b>2004-10</b>
Z 14 XEL	55 75
Ignition Coil ->12.2005	<b>80350</b>
<b>Astra Mk V (H) Estate 1.4</b>	<b>2004-09</b>
Z 14 XEP	66 90
Ignition Coil	<b>80350</b>
<b>Astra Mk V (H) Estate 1.6</b>	<b>2004-09</b>
Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Astra Mk V (H) Estate 2.0 Turbo</b>	<b>2004-10</b>
Z 20 LEL	125 170
Ignition Coil ->02.2009	<b>80354</b>
<b>Astra Mk V (H) Estate 2.0 Turbo</b>	<b>2004-10</b>
Z 20 LER	147 200
Ignition Coil ->03.2010	<b>80354</b>
<b>Astra Mk V (H) Sport Hatch 1.4</b>	<b>2005-10</b>
Z 14 XEL	55 75
Ignition Coil ->02.2009	<b>80350</b>
<b>Astra Mk V (H) Sport Hatch 1.4 i 16V</b>	<b>2005-10</b>
Z 14 XEP	66 90
Ignition Coil ->03.2009	<b>80350</b>
<b>Astra Mk V (H) Sport Hatch 1.6</b>	<b>2005-10</b>
Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Astra Mk V (H) Sport Hatch 2.0 Turbo</b>	<b>2005-10</b>
Z 20 LEL	125 170
Ignition Coil ->02.2009	<b>80354</b>
<b>Astra Mk V (H) Sport Hatch 2.0 VXR</b>	<b>2009-10</b>
Z 20 LEH	176 240
Ignition Coil ->03.2009	<b>80354</b>
<b>Astra Mk VI (J) 1.4</b>	<b>2009-&gt;</b>
A 14 XER	74 100
Ignition Coil	<b>80322</b>
<b>Astra Mk VI (J) 1.4</b>	<b>2009-&gt;</b>
A 14 XEL	64 87
Ignition Coil	<b>80322</b>
<b>Astra Mk VI (J) 1.4 Turbo</b>	<b>2011-&gt;</b>
A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Astra Mk VI (J) 1.4 Turbo</b>	<b>2009-&gt;</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Astra Mk VI (J) 1.6</b>	<b>2009-&gt;</b>
A 16 XER/B 16 XER	85 115
Ignition Coil A 16 XER	<b>80321</b>
<b>Astra Mk VI (J) 1.6 Turbo</b>	<b>2009-&gt;</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Astra Mk VI (J) Estate 1.4</b>	<b>2010-&gt;</b>
A 14 XER	74 101
Ignition Coil	<b>80322</b>
<b>Astra Mk VI (J) Estate 1.4 Turbo</b>	<b>2010-&gt;</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Astra Mk VI (J) Estate 1.6</b>	<b>2010-&gt;</b>
A 16 XER/B 16 XER	85 116
Ignition Coil A 16 XER	<b>80321</b>
<b>Astra Mk VI (J) Estate 1.6 Turbo</b>	<b>2010-&gt;</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Astra Mk VI (J) GTC 1.4</b>	<b>2011-&gt;</b>
B 14 NEL/A 14 NEL	88 120
Ignition Coil A 14 NEL	<b>80322</b>
<b>Astra Mk VI (J) GTC 1.4</b>	<b>2011-&gt;</b>
A 14 XER	74 101
Ignition Coil	<b>80322</b>
<b>Astra Mk VI (J) GTC 1.4</b>	<b>2011-&gt;</b>
A 14 NET/B 14 NET	103 140
Ignition Coil A 14 NET	<b>80322</b>
<b>Astra Mk VI (J) GTC 1.6</b>	<b>2011-&gt;</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Astra Mk VI (J) GTC 2.0 VXR</b>	<b>2012-&gt;</b>
A 20 NFT/B 20 NFT	206 280
Ignition Coil A 20 NFT	<b>80329</b>
<b>Astra Mk VI (J) Sedan 1.4</b>	<b>2012-&gt;</b>
A 14 XER	74 101
Ignition Coil	<b>80322</b>

**VAUXHALL Cont.**

<b>Astra Mk VI (J) Sedan 1.4 Turbo</b>	<b>2012-&gt;</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Astra Mk VI (J) Sedan 1.6</b>	<b>2012-&gt;</b>
A 16 XER	85 116
Ignition Coil	<b>80352</b>
<b>Astra Mk VI (J) Sedan 1.6 Turbo</b>	<b>2012-&gt;</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Astra Twintop Mk V (H) 1.6</b>	<b>2005-10</b>
Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Astra Twintop Mk V (H) 2.0</b>	<b>2006-10</b>
Z 20 LEL	125 170
Ignition Coil ->02.2009	<b>80354</b>
<b>Astra Twintop Mk V (H) 2.0 Turbo</b>	<b>2006-10</b>
Z 20 LER	147 200
Ignition Coil ->12.2009	<b>80354</b>
<b>Astravan Mk III (F) 1.4 i</b>	<b>1991-94</b>
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Astravan Mk III (F) 1.6 i</b>	<b>1991-98</b>
C 16 NZ	55 75
Ignition Coil	<b>80261</b>
<b>Astravan Mk III (F) 1.6 i</b>	<b>1994-96</b>
X 16 SZ	52 71
Ignition Coil	<b>80210</b>
<b>Astravan Mk IV (G) 1.6 i</b>	<b>1998-00</b>
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
<b>Astravan Mk V (H) 1.4 i</b>	<b>2005-&gt;</b>
Z 14 XEP	66 90
Ignition Coil ->03.2010	<b>80350</b>
<b>Brava Pick-Up 2,3</b>	<b>1991-94</b>
4 ZD1	69 94
Ignition Leads	<b>86030</b>
<b>Brava Pick-Up 2,3</b>	<b>1994-96</b>
23 P	72 98
Ignition Leads	<b>86030</b>
<b>Brava Pick-Up 2.3 4x4</b>	<b>1994-96</b>
23 P	72 98
Ignition Leads	<b>86030</b>
<b>Brava Pick-Up 2.3 4x4</b>	<b>1990-94</b>
4 ZD1	69 94
Ignition Leads	<b>86030</b>
<b>Calibra 2.0 i 16V</b>	<b>1990-97</b>
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Calibra 2.0 i 16V</b>	<b>1990-94</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Calibra 2.0 i 16V 4x4</b>	<b>1994-97</b>
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Calibra 2.0 i 16V 4x4</b>	<b>1990-94</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Carlton Mk III 1.8</b>	<b>1987-94</b>
E 18 NVR	65 88
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85980</b>
<b>Carlton Mk III 1.8 i</b>	<b>1986-94</b>
18 SEH	85 115
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85980</b>
<b>Carlton Mk III 1.8 N</b>	<b>1986-87</b>
18 NV	60 82
Ignition Leads	<b>85980</b>
<b>Carlton Mk III 1.8 S</b>	<b>1986-94</b>
18 SV	66 90
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85980</b>
<b>Carlton Mk III 2.0</b>	<b>1990-94</b>
C 20 NEJ	73 99
Ignition Leads	<b>85980</b>
<b>Carlton Mk III 2.0</b>	<b>1990-94</b>
C 20 NEF	74 100
Ignition Leads	<b>85980</b>



VAUXHALL Cont.	
<b>Carlton Mk III 2.0</b>	<b>1986-94</b>
C 20 NE	85 115
Ignition Leads	<b>85980</b>
<b>Carlton Mk III 2.0 i</b>	<b>1986-94</b>
20 SE	90 122
Ignition Leads	<b>85980</b>
<b>Carlton Mk III Estate 1.8</b>	<b>1987-94</b>
E 18 NVR	65 88
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85980</b>
<b>Carlton Mk III Estate 1.8 i</b>	<b>1986-94</b>
18 SEH	85 115
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85980</b>
<b>Carlton Mk III Estate 1.8 N</b>	<b>1986-87</b>
18 NV	60 82
Ignition Leads	<b>85980</b>
<b>Carlton Mk III Estate 1.8 S</b>	<b>1986-94</b>
18 SV	66 90
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85980</b>
<b>Carlton Mk III Estate 2.0</b>	<b>1990-94</b>
C 20 NEF	74 100
Ignition Leads	<b>85980</b>
<b>Carlton Mk III Estate 2.0</b>	<b>1986-94</b>
C 20 NE	85 115
Ignition Leads	<b>85980</b>
<b>Carlton Mk III Estate 2.0 i</b>	<b>1986-94</b>
20 SE	90 122
Ignition Leads	<b>85980</b>
<b>Carlton Mk III Estate 2.0 i</b>	<b>1990-94</b>
C 20 NEJ	73 99
Ignition Leads	<b>85980</b>
<b>Cascada Convertible 1.4</b>	<b>2013-&gt;</b>
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Cascada Convertible 1.4</b>	<b>2013-&gt;</b>
A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Cavalier Mk II 1.3 N</b>	<b>1981-88</b>
13 N	44 60
Ignition Coil	<b>80261</b>
<b>Cavalier Mk II 1.3 S</b>	<b>1981-88</b>
13 S	55 75
Ignition Coil	<b>80261</b>
<b>Cavalier Mk II CC 1.3 S</b>	<b>1981-88</b>
13 S	55 75
Ignition Coil	<b>80261</b>
<b>Cavalier Mk II Estate 1.3 S</b>	<b>1981-88</b>
13 S	55 75
Ignition Coil	<b>80261</b>
<b>Cavalier Mk III (87) 1.6</b>	<b>1988-93</b>
16 SV	60 82
Ignition Coil 16SV	<b>80261</b>
Ignition Coil	<b>80262</b>
<b>Cavalier Mk III (87) 1.6 i</b>	<b>1988-95</b>
E 16 NZ	55 75
Ignition Coil E16NZ	<b>80261</b>
Ignition Coil	<b>80262</b>
<b>Cavalier Mk III (87) 1.8</b>	<b>1988-95</b>
C 18 NZ/18 SV	66 90
Ignition Coil	<b>80262</b>
<b>Cavalier Mk III (87) 1.8 i KAT</b>	<b>1990-95</b>
C 18 NZ	66 90
Ignition Coil	<b>80262</b>
<b>Cavalier Mk III (87) 2.0 i 16V</b>	<b>1988-95</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Cavalier Mk III (87) 2.0 i 16V 4x4</b>	<b>1988-95</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Cavalier Mk III (87) 2.0 SRi 16V</b>	<b>1993-95</b>
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Cavalier Mk III CC 1.6</b>	<b>1988-93</b>
16 SV	60 82
Ignition Coil 16SV	<b>80261</b>
Ignition Coil	<b>80262</b>

VAUXHALL Cont.	
<b>Cavalier Mk III CC 1.6 i</b>	<b>1993-95</b>
X 16 SZ	52 71
Ignition Coil	<b>80261</b>
<b>Cavalier Mk III CC 1.6 i</b>	<b>1988-95</b>
E 16 NZ	55 75
Ignition Coil	<b>80261</b>
<b>Cavalier Mk III CC 1.8</b>	<b>1988-90</b>
C 18 NZ/18 SV	66 90
Ignition Coil	<b>80262</b>
<b>Cavalier Mk III CC 1.8 i KAT</b>	<b>1990-95</b>
C 18 NZ	66 90
Ignition Coil	<b>80262</b>
<b>Cavalier Mk III CC 2.0 i 16V</b>	<b>1993-95</b>
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Cavalier Mk III CC 2.0 i 16V</b>	<b>1988-95</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Cavalier Mk III CC 2.0 i 16V 4x4</b>	<b>1992-93</b>
C 20 XE	110 150
Ignition Coil	<b>80289</b>
<b>Combo Mk I (B) 1.2</b>	<b>1994-01</b>
C 12 NZ/X 12 SZ	33 45
Ignition Coil	<b>80262</b>
Ignition Leads X 12 SZ; Engine 19330001->	<b>85085</b>
Ignition Leads C 12 NZ	<b>85105</b>
<b>Combo Mk I (B) 1.4</b>	<b>1994-01</b>
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Combo Mk I (B) 1.4</b>	<b>1994-01</b>
C 14 SE	60 82
Ignition Coil	<b>80210</b>
<b>Combo Mk II (C) Box/Estate (F25) 1.4 16V</b>	<b>2001-07</b>
Z 14 XE	66 90
Ignition Coil Z 14 XEO <Twinport>; 01.2004->	<b>80350</b>
<b>Combo Mk II (C) Box/Estate (F25) 1.4 i 16V</b>	<b>2004-11</b>
Z 14 XEP	66 90
Ignition Coil	<b>80350</b>
<b>Combo Mk III (D) Box/Estate 1.4 CNG</b>	<b>2011-&gt;</b>
A 14 FC	88 120
Ignition Coil	<b>80267</b>
<b>Combo Tour Mk II (C) (F25) 1.4</b>	<b>2004-10</b>
Z 14 XEP	66 90
Ignition Coil	<b>80350</b>
<b>Corsa Mk I (B) 1.0 i 12V</b>	<b>1996-00</b>
X 10 XE	40 54
Ignition Coil	<b>80259</b>
<b>Corsa Mk I (B) 1.2 i</b>	<b>1993-00</b>
C 12 NZ/X 12 SZ	33 45
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Corsa Mk I (B) 1.2 i 16V</b>	<b>1998-00</b>
X 12 XE	48 65
Ignition Coil	<b>80257</b>
<b>Corsa Mk I (B) 1.4 i</b>	<b>1993-00</b>
C 14 NZ/X 14 SZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads X 14 SZ; 09.1996-08.1998	<b>85085</b>
Ignition Leads C 14 NZ	<b>85105</b>
<b>Corsa Mk I (B) 1.4 i 16V</b>	<b>1994-00</b>
X 14 XE	66 90
Ignition Coil	<b>80210</b>
<b>Corsa Mk I (B) 1.4 i S</b>	<b>1993-00</b>
C 14 SE	60 82
Ignition Coil	<b>80210</b>
Ignition Leads Ch.02BD1413-02HY3579	<b>85085</b>
<b>Corsa Mk I (B) 1.6 GSI 16V</b>	<b>1993-00</b>
C 16 XE	80 109
Ignition Coil	<b>80210</b>
<b>Corsa Mk I (B) 1.6 i 16V</b>	<b>1994-00</b>
X 16 XE/C 16 XE	78 106
Ignition Coil	<b>80210</b>
<b>Corsa Mk II (C) (W5L, F08) 1.0 12V</b>	<b>2000-03</b>
Z 10 XE	43 58
Ignition Coil	<b>80259</b>
<b>Corsa Mk II (C) (W5L, F08) 1.0 12V</b>	<b>2003-06</b>
Z 10 XEP	44 60
Ignition Coil	<b>80259</b>

**VAUXHALL Cont.**

<b>Corsa Mk II (C) (W5L, F08) 1.2 16V</b>	<b>2000-06</b>
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Corsa Mk II (C) (W5L, F08) 1.2 16V Dualfuel</b>	<b>2001-06</b>
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Corsa Mk II (C) (W5L, F08) 1.2 Twinport</b>	<b>2004-06</b>
Z 12 XEP	59 80
Ignition Coil ->09.2006	<b>80350</b>
<b>Corsa Mk II (C) (W5L, F08) 1.4 16V</b>	<b>2000-06</b>
Z 14 XE	66 90
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Corsa Mk II (C) (W5L, F08) 1.8 16V</b>	<b>2000-06</b>
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Corsa Mk III (D) (L8) 1.0</b>	<b>2006-14</b>
Z 10 XEP/A 10 XEP	44 60
Ignition Coil	<b>80258</b>
Ignition Coil	<b>80259</b>
<b>Corsa Mk III (D) (L8) 1.0 i 12V</b>	<b>2010-14</b>
A 10 XEP	48 65
Ignition Coil	<b>80258</b>
<b>Corsa Mk III (D) (L8) 1.2</b>	<b>2006-14</b>
Z 12 XEP	59 80
Ignition Coil ->12.2011	<b>80350</b>
<b>Corsa Mk III (D) (L8) 1.2</b>	<b>2010-14</b>
A 12 XEL	51 69
Ignition Coil	<b>80322</b>
<b>Corsa Mk III (D) (L8) 1.2 i 16V</b>	<b>2006-14</b>
A 12 XER	63 86
Ignition Coil	<b>80322</b>
<b>Corsa Mk III (D) (L8) 1.2 LPG</b>	<b>2011-14</b>
A 12 XER	63 86
Ignition Coil	<b>80322</b>
<b>Corsa Mk III (D) (L8) 1.2 LPG</b>	<b>2009-14</b>
Z 12 XEP	59 80
Ignition Coil ->12.2011	<b>80350</b>
<b>Corsa Mk III (D) (L8) 1.4</b>	<b>2009-14</b>
A 14 XEL	64 87
Ignition Coil	<b>80322</b>
<b>Corsa Mk III (D) (L8) 1.4</b>	<b>2006-14</b>
Z 14 XEP	66 90
Ignition Coil ->11.2010	<b>80350</b>
<b>Corsa Mk III (D) (L8) 1.4</b>	<b>2010-14</b>
A 14 XER	74 101
Ignition Coil	<b>80322</b>
<b>Corsa Mk III (D) (L8) 1.4</b>	<b>2012-14</b>
A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Corsa Mk III (D) (L8) 1.4 LPG</b>	<b>2009-14</b>
A 14 XEL	64 87
Ignition Coil	<b>80322</b>
<b>Corsa Mk III (D) (L8) 1.4 LPG</b>	<b>2006-14</b>
Z 14 XEP	66 90
Ignition Coil ->11.2010	<b>80350</b>
<b>Corsa Mk III (D) (L8) 1.6 VXR</b>	<b>2007-14</b>
A 16 LER/Z 16 LER	141 192
Ignition Coil	<b>80291</b>
<b>Corsavan Mk I (B) 1.4 i</b>	<b>1994-00</b>
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
Ignition Leads	<b>85105</b>
<b>Corsavan Mk II (C) 1.2 16V</b>	<b>2000-06</b>
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Corsavan Mk II (C) 1.2 16V Dualfuel</b>	<b>2001-06</b>
Z 12 XE	55 75
Ignition Coil	<b>80257</b>
<b>Corsavan Mk III (D) 1.2</b>	<b>2009-&gt;</b>
Z 12 XEP	59 80
Ignition Coil ->12.2011	<b>80350</b>
<b>Corsavan Mk III (D) 1.2</b>	<b>2010-&gt;</b>
A 12 XEL	51 69
Ignition Coil	<b>80322</b>
<b>Frontera Mk I (A) 2.0</b>	<b>1995-98</b>
C 20 NE/X 20 SE	85 115
Ignition Leads	<b>85083</b>

**VAUXHALL Cont.**

<b>Frontera Mk I (A) 2.2 i</b>	<b>1995-98</b>
X 22 XE	100 136
Ignition Coil	<b>80289</b>
<b>Frontera Mk I (A) Sport 2.0 i</b>	<b>1992-98</b>
C 20 NE/X 20 SE	85 115
Ignition Coil	<b>80289</b>
Ignition Leads C 20 NE; Engine 14672354->; 08.1995->	<b>83800</b>
Ignition Leads X 20 SE	<b>85083</b>
Ignition Leads C 20 NE; ->Engine 14672353; ->08.1995	<b>85980</b>
<b>Insignia Mk I (A) 1.4</b>	<b>2011-17</b>
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia Mk I (A) 1.4 LPG</b>	<b>2012-17</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia Mk I (A) 1.6</b>	<b>2008-17</b>
A 16 XER	85 116
Ignition Coil	<b>80352</b>
<b>Insignia Mk I (A) 1.6 Turbo</b>	<b>2009-17</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Insignia Mk I (A) 1.8</b>	<b>2008-17</b>
B 18 XER/A 18 XER	103 140
Ignition Coil A 18 XER	<b>80321</b>
<b>Insignia Mk I (A) 2.0 Turbo</b>	<b>2014-17</b>
A 20 NHT/A 20 NFT/B 20 NHT	184 250
Ignition Coil A 20 NFT	<b>80329</b>
<b>Insignia Mk I (A) 2.0 Turbo</b>	<b>2008-17</b>
A 20 NHT/A 20 NFT	162 220
Ignition Coil A 20 NHT	<b>80329</b>
<b>Insignia Mk I (A) 2.0 Turbo 4x4</b>	<b>2008-17</b>
A 20 NHT/A 20 NFT	162 220
Ignition Coil A 20 NHT	<b>80329</b>
<b>Insignia Mk I (A) 2.0 Turbo 4x4</b>	<b>2011-17</b>
A 20 NHT/A 20 NFT/B 20 NHT	184 250
Ignition Coil A 20 NFT	<b>80329</b>
<b>Insignia Mk I (A) Estate 1.4</b>	<b>2011-17</b>
A 14 NET/B 14 NET	103 140
Ignition Coil A 14 NET	<b>80322</b>
<b>Insignia Mk I (A) Estate 1.4 LPG</b>	<b>2012-17</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia Mk I (A) Estate 1.6</b>	<b>2008-17</b>
A 16 XER	85 116
Ignition Coil	<b>80352</b>
<b>Insignia Mk I (A) Estate 1.6 Turbo</b>	<b>2009-17</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Insignia Mk I (A) Estate 1.8</b>	<b>2008-17</b>
B 18 XER/A 18 XER	103 140
Ignition Coil A 18 XER	<b>80321</b>
<b>Insignia Mk I (A) Estate 2.0 Turbo</b>	<b>2014-17</b>
A 20 NHT/A 20 NFT/B 20 NHT	184 250
Ignition Coil A 20 NFT	<b>80329</b>
<b>Insignia Mk I (A) Estate 2.0 Turbo</b>	<b>2008-17</b>
A 20 NHT/A 20 NFT	162 220
Ignition Coil A 20 NHT	<b>80329</b>
<b>Insignia Mk I (A) Estate 2.0 Turbo 4x4</b>	<b>2008-17</b>
A 20 NHT/A 20 NFT	162 220
Ignition Coil A 20 NHT	<b>80329</b>
<b>Insignia Mk I (A) Estate 2.0 Turbo 4x4</b>	<b>2011-17</b>
A 20 NHT/A 20 NFT/B 20 NHT	184 250
Ignition Coil A 20 NFT	<b>80329</b>
<b>Insignia Mk I (A) Sedan 1.4</b>	<b>2011-17</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia Mk I (A) Sedan 1.4 LPG</b>	<b>2012-17</b>
A 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Insignia Mk I (A) Sedan 1.6</b>	<b>2008-17</b>
A 16 XER	85 116
Ignition Coil	<b>80352</b>
<b>Insignia Mk I (A) Sedan 1.6 Turbo</b>	<b>2009-17</b>
A 16 LET	132 180
Ignition Coil	<b>80321</b>
<b>Insignia Mk I (A) Sedan 1.8</b>	<b>2008-17</b>
B 18 XER/A 18 XER	103 140
Ignition Coil A 18 XER	<b>80321</b>



VAUXHALL Cont.	
<b>Insignia Mk I (A) Sedan 2.0 Turbo</b>	2008-17
A 20 NHT/A 20 NFT	162 220
Ignition Coil A 20 NHT	<b>80329</b>
<b>Insignia Mk I (A) Sedan 2.0 Turbo 4x4</b>	2008-17
A 20 NHT/A 20 NFT	162 220
Ignition Coil A 20 NHT	<b>80329</b>
<b>Insignia Mk I (A) Sedan 2.0 Turbo 4x4</b>	2011-17
A 20 NHT/A 20 NFT/B 20 NHT	184 250
Ignition Coil A 20 NFT	<b>80329</b>
<b>Meriva Mk I (A) 1.4 16V Twinport</b>	2003-10
Z 14 XEP	66 90
Ignition Coil	<b>80350</b>
<b>Meriva Mk I (A) 1.6 i 16V</b>	2003-05
Z 16 XE	74 100
Ignition Coil	<b>80209</b>
<b>Meriva Mk I (A) 1.6 i 16V Twinport</b>	2003-10
Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Meriva Mk I (A) 1.6 Turbo</b>	2006-10
Z 16 LET	132 180
Ignition Coil	<b>80291</b>
<b>Meriva Mk I (A) 1.8 i 16V</b>	2003-10
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Meriva Mk II (B) 1.4</b>	2010->
A 14 XER/B 14 XER	74 101
Ignition Coil A 14 XER	<b>80322</b>
<b>Meriva Mk II (B) 1.4</b>	2010->
B 14 NEL/A 14 NEL	88 120
Ignition Coil A 14 NEL	<b>80322</b>
<b>Meriva Mk II (B) 1.4</b>	2010->
A 14 NET/B 14 NET	103 140
Ignition Coil A 14 NET	<b>80322</b>
<b>Meriva Mk II (B) 1.4 LPG</b>	2011->
B 14 NEL/A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Mokka 1.4</b>	2013->
A 14 NET/B 14 NET	103 140
Ignition Coil A 14 NET	<b>80322</b>
<b>Mokka 1.4 4x4</b>	2012->
A 14 NET/B 14 NET	103 140
Ignition Coil A 14 NET	<b>80322</b>
<b>Mokka 1.6</b>	2012->
A 16 XER/B 16 XER	85 116
Ignition Coil A 16 XER	<b>80352</b>
<b>Nova 1.2 N</b>	1985-87
E 12 GV/12 NC	33 45
Ignition Coil	<b>80261</b>
<b>Nova 1.2 S</b>	1982-87
12 ST	40 55
Ignition Coil	<b>80261</b>
<b>Nova 1.3 i</b>	1985-87
13 NB	44 60
Ignition Coil	<b>80261</b>
<b>Nova 1.3 S</b>	1982-87
13 SB	51 70
Ignition Coil	<b>80261</b>
<b>Nova CC 1.2 i KAT</b>	1989-93
C 12 NZ	33 45
Ignition Coil	<b>80262</b>
<b>Nova CC 1.2 N</b>	1990-93
12 NV	38 52
Ignition Coil	<b>80261</b>
<b>Nova CC 1.2 S</b>	1983-90
12 ST	40 55
Ignition Coil	<b>80261</b>
<b>Nova CC 1.2 S</b>	1988-90
12 ST/12 S	43 58
Ignition Coil	<b>80261</b>
<b>Nova CC 1.3 i</b>	1985-89
13 NB	44 60
Ignition Coil	<b>80261</b>
<b>Nova CC 1.3 i KAT</b>	1989-93
C 13 N	44 60
Ignition Coil	<b>80261</b>
<b>Nova CC 1.3 S</b>	1983-89
13 SB	51 70
Ignition Coil	<b>80261</b>

VAUXHALL Cont.	
<b>Nova CC 1.4 i</b>	1990-93
C 14 NZ	44 60
Ignition Coil	<b>80262</b>
<b>Nova CC 1.4 i S</b>	1991-93
C 14 SE	60 82
Ignition Coil	<b>80262</b>
<b>Nova CC 1.6 GSI</b>	1988-92
E 16 SE	74 100
Ignition Coil	<b>80262</b>
<b>Nova CC 1.6 GSI KAT</b>	1992-93
C 16 SE	74 101
Ignition Coil	<b>80210</b>
<b>Novavan 1.2</b>	1990-94
12 NV	38 52
Ignition Coil	<b>80261</b>
<b>Omega (B) 2.0</b>	1995-96
20 SE	85 115
Ignition Coil	<b>80289</b>
Ignition Leads	<b>85980</b>
<b>Omega (B) 2.0</b>	1994-99
X 20 SE	85 116
Ignition Coil	<b>80289</b>
<b>Omega (B) 2.0 16V</b>	1994-01
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Omega (B) 2.6 V6</b>	2000-03
Y 26 SE	132 180
Ignition Coil	<b>80210</b>
<b>Omega (B) Estate 2.0</b>	1994-99
X 20 SE	85 116
Ignition Coil	<b>80289</b>
<b>Omega (B) Estate 2.0 16V</b>	1994-01
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Omega (B) Estate 2.6 V6</b>	2000-03
Y 26 SE	132 180
Ignition Coil	<b>80210</b>
<b>Signum 2.2 i</b>	2003-08
Z 22 YH	114 155
Ignition Coil	<b>80269</b>
<b>Signum 2.8 V6 Turbo</b>	2005-08
Z 28 NEL	169 230
Ignition Coil	<b>80355</b>
<b>Sintra 2.2 i 16 V</b>	1996-99
X 22 XE	104 141
Ignition Coil	<b>80289</b>
<b>Tigra Mk I (F07) 1.4 16V</b>	1994-00
X 14 XE	66 90
Ignition Coil	<b>80209</b>
<b>Tigra Mk I (F07) 1.6 16V</b>	1994-00
X 16 XE	78 106
Ignition Coil	<b>80210</b>
<b>Tigra Twintop 1.4</b>	2004-09
Z 14 XEP	66 90
Ignition Coil	<b>80350</b>
<b>Vectra (B) 1.6 i</b>	1995-01
X 16 SZR	55 75
Ignition Coil	<b>80210</b>
<b>Vectra (B) 1.6 i 16V</b>	1995-01
Z 16 XE/X 16 XEL/Y 16 XE	74 100
Ignition Coil With regul.cat.(3way)	<b>80209</b>
<b>Vectra (B) 1.8 i 16V</b>	2000-02
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra (B) 1.8 i 16V</b>	1995-00
X 18 XE	85 116
Ignition Coil X 18 XE	<b>80223</b>
Ignition Coil	<b>80224</b>
<b>Vectra (B) 2.0 i 16V</b>	1995-01
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Vectra (B) CC 1.6 i</b>	1995-01
X 16 SZR	55 75
Ignition Coil	<b>80262</b>
<b>Vectra (B) CC 1.6 i 16V</b>	1995-01
Z 16 XE/X 16 XEL/Y 16 XE	74 101
Ignition Coil With regul.cat.(3way)	<b>80209</b>

**VAUXHALL Cont.**

<b>Vectra (B) CC 1.8 i 16V</b>	<b>2000-03</b>
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra (B) CC 1.8 i 16V</b>	<b>1995-00</b>
X 18 XE/X 18 XE1	85 116
Ignition Coil	<b>80223</b>
<b>Vectra (B) CC 2.0 i 16V</b>	<b>1995-01</b>
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Vectra (B) Estate 1.8 i 16V</b>	<b>2000-02</b>
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra (B) Estate 1.8 i 16V</b>	<b>1996-00</b>
X 18 XE/X 18 XE1	85 115
Ignition Coil X 18 XE	<b>80223</b>
Ignition Coil	<b>80224</b>
<b>Vectra (B) Estate 2.0 i 16V</b>	<b>1995-01</b>
X 20 XEV	100 136
Ignition Coil	<b>80223</b>
<b>Vectra Mk II (C) 1.8</b>	<b>2006-08</b>
Z 18 XER	103 140
Ignition Coil	<b>80291</b>
<b>Vectra Mk II (C) 1.8 16V</b>	<b>2002-08</b>
Z 18 XE	90 122
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra Mk II (C) 1.8 16V Dualfuel</b>	<b>2002-08</b>
Z 18 XE	90 122
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra Mk II (C) 2.2 direct</b>	<b>2002-08</b>
Z 22 YH	114 155
Ignition Coil	<b>80269</b>
<b>Vectra Mk II (C) Estate 1.8</b>	<b>2006-08</b>
Z 18 XER	103 140
Ignition Coil	<b>80291</b>
<b>Vectra Mk II (C) Estate 1.8 16V</b>	<b>2003-05</b>
Z 18 XE	90 122
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra Mk II (C) Estate 2.2 direct</b>	<b>2003-08</b>
Z 22 YH	114 155
Ignition Coil	<b>80269</b>
<b>Vectra Mk II (C) Estate 2.8 V6 Turbo</b>	<b>2006-08</b>
Z 28 NET	206 280
Ignition Coil	<b>80355</b>
<b>Vectra Mk II (C) Estate 2.8 V6 Turbo</b>	<b>2005-08</b>
Z 28 NEL	169 230
Ignition Coil	<b>80355</b>
<b>Vectra Mk II (C) Estate 2.8 V6 Turbo</b>	<b>2006-08</b>
Z 28 NET	188 255
Ignition Coil	<b>80355</b>
<b>Vectra Mk II (C) GTS 1.8</b>	<b>2006-08</b>
Z 18 XER	103 140
Ignition Coil	<b>80291</b>
<b>Vectra Mk II (C) GTS 1.8 16V</b>	<b>2002-08</b>
Z 18 XE	90 122
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra Mk II (C) GTS 1.8 16V Dualfuel</b>	<b>2002-08</b>
Z 18 XE	90 122
Ignition Coil Z 18 XE	<b>80224</b>
<b>Vectra Mk II (C) GTS 2.2 direct</b>	<b>2003-05</b>
Z 22 YH	114 155
Ignition Coil	<b>80269</b>
<b>Vectra Mk II (C) GTS 2.8 V6 Turbo</b>	<b>2005-08</b>
Z 28 NEL	169 230
Ignition Coil	<b>80355</b>
<b>Vectra Mk II (C) GTS 2.8 V6 Turbo</b>	<b>2006-08</b>
Z 28 NET	184 250
Ignition Coil	<b>80355</b>
<b>Vectra Mk II (C) GTS 2.8 V6 Turbo</b>	<b>2005-08</b>
Z 28 NET	188 255
Ignition Coil	<b>80355</b>
<b>Vivaro Box (F7) 2.0 16V</b>	<b>2001-06</b>
F4R 720	88 120
Ignition Coil ->Engine C002324	<b>80203</b>
<b>Vivaro Combi (J7) 2.0 16V</b>	<b>2001-06</b>
F4R 720	88 120
Ignition Coil ->Engine C002324	<b>80203</b>
<b>VX220 2.0 i Turbo</b>	<b>2001-05</b>
Z 20 LET	147 200
Ignition Coil	<b>80354</b>

**VAUXHALL Cont.**

<b>Zafira Mk I (A) (F75) 1.6 16V</b>	<b>1999-05</b>
Z 16 XE/X 16 XEL	74 101
Ignition Coil X 16 XEL; With regul.cat.(3way)	<b>80209</b>
<b>Zafira Mk I (A) (F75) 1.8 16V</b>	<b>1999-00</b>
X 18 XE1	85 116
Ignition Coil	<b>80224</b>
<b>Zafira Mk I (A) (F75) 1.8 16V</b>	<b>2000-05</b>
Z 18 XE	92 125
Ignition Coil Z 18 XE	<b>80224</b>
<b>Zafira Mk I (A) (F75) 2.0</b>	<b>2002-05</b>
Z 20 LET	147 199
Ignition Coil	<b>80354</b>
<b>Zafira Mk I (A) (F75) 2.0 GSI Turbo</b>	<b>2001-05</b>
Z 20 LET	141 192
Ignition Coil	<b>80354</b>
<b>Zafira Mk II (B) (M75) 1.6</b>	<b>2005-14</b>
Z 16 XE1/Z 16 XEP	77 105
Ignition Coil	<b>80291</b>
<b>Zafira Mk II (B) (M75) 1.8</b>	<b>2005-14</b>
Z 18 XER/A 18 XER	103 140
Ignition Coil	<b>80291</b>
<b>Zafira Mk II (B) (M75) 2.0</b>	<b>2005-14</b>
Z 20 LER	147 200
Ignition Coil ->12.2010	<b>80354</b>
<b>Zafira Mk II (B) (M75) 2.0</b>	<b>2006-14</b>
Z 20 LEH	176 240
Ignition Coil ->12.2010	<b>80354</b>
<b>Zafira Mk II (B) (M75) 2.2</b>	<b>2005-14</b>
Z 22 YH	110 150
Ignition Coil	<b>80269</b>
<b>Zafira Mk III (P12) 1.4</b>	<b>2011-&gt;</b>
A 14 NEL	88 120
Ignition Coil	<b>80322</b>
<b>Zafira Mk III (P12) 1.4</b>	<b>2011-&gt;</b>
A 14 NET/B 14 NET	103 140
Ignition Coil	<b>80322</b>
<b>Zafira Mk III (P12) 1.8</b>	<b>2011-&gt;</b>
A 18 XEL	85 115
Ignition Coil	<b>80321</b>
<b>Zafira Mk III (P12) 1.8</b>	<b>2011-&gt;</b>
A 18 XER	103 140
Ignition Coil	<b>80321</b>

**VOLKSWAGEN**

<b>Beetle (5C1) 1.2 TSI</b>	<b>2011-&gt;</b>
CBZB	77 105
Ignition Coil	<b>80218</b>
<b>Beetle (5C1) 1.2 TSI 16V</b>	<b>2014-&gt;</b>
CYVD	77 105
Ignition Coil	<b>80249</b>
<b>Beetle (5C1) 1.4 TSI</b>	<b>2014-&gt;</b>
CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Beetle (5C1) 1.4 TSI</b>	<b>2011-&gt;</b>
CTKA/CAVD/CTHD/CNWA	118 160
Ignition Coil ->06.2016	<b>80201</b>
<b>Beetle (5C1) 2.0 TSI</b>	<b>2012-&gt;</b>
CPPA/CPLA	155 211
Ignition Coil	<b>80238</b>
<b>Beetle Cabriolet (5C7) 1.2 TSI</b>	<b>2012-&gt;</b>
CBZB	77 105
Ignition Coil 01.2013->	<b>80218</b>
<b>Beetle Cabriolet (5C7) 1.2 TSI 16V</b>	<b>2014-&gt;</b>
CYVD	77 105
Ignition Coil	<b>80249</b>
<b>Beetle Cabriolet (5C7) 1.4 TSI</b>	<b>2014-&gt;</b>
CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Beetle Cabriolet (5C7) 1.4 TSI</b>	<b>2012-&gt;</b>
CTKA/CAVD/CTHD/CNWA	118 160
Ignition Coil ->07.2016	<b>80201</b>
<b>Beetle Cabriolet (5C7) 2.0 TSI</b>	<b>2012-&gt;</b>
CPPA/CPLA	155 210
Ignition Coil	<b>80238</b>





VOLKSWAGEN Cont.		
<b>Bora (1J2) 1.4 16V</b>		<b>2000-05</b>
AHW/AXP/BCA/APE/AKQ		55 75
Ignition Coil 10.2001->		<b>80201</b>
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Bora (1J2) 1.6</b>		<b>1998-05</b>
AKL/APF/AEH		74 101
Ignition Coil		<b>80218</b>
Ignition Leads APF/AKL/AEH		<b>85875</b>
<b>Bora (1J2) 1.6</b>		<b>2000-05</b>
AVU/BFQ/BJH		75 102
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85879</b>
<b>Bora (1J2) 1.6 16V</b>		<b>2000-05</b>
AUS/ATN/BCB/AZD		77 105
Ignition Coil 09.2000->		<b>80201</b>
Ignition Coil		<b>80218</b>
Ignition Leads AHW, AXP		<b>85696</b>
<b>Bora (1J2) 1.6 FSI</b>		<b>2002-05</b>
BAD		81 110
Ignition Coil		<b>80201</b>
<b>Bora (1J2) 1.8</b>		<b>1998-05</b>
AGN/BAF		92 125
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85065</b>
<b>Bora (1J2) 1.8 4motion</b>		<b>1999-05</b>
AGN		92 125
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85065</b>
<b>Bora (1J2) 1.8 T</b>		<b>2000-05</b>
ARX/BAE/AGU/AUM		110 150
Ignition Coil AUM; 09.2000->		<b>80202</b>
Ignition Coil BAE; 08.2001->		<b>80218</b>
Ignition Coil		<b>80239</b>
Ignition Coil AGU; 09.2000->		<b>80252</b>
Ignition Leads 08.2001->		<b>85879</b>
<b>Bora (1J2) 1.8 T</b>		<b>2002-05</b>
AWP/AUQ		132 180
Ignition Coil AUQ; With regul.cat.(3way)		<b>80202</b>
Ignition Coil AUQ		<b>80239</b>
<b>Bora (1J2) 2.0</b>		<b>1998-05</b>
APK/AZH/AZJ/AQY/AZG/BBW		85 115
Ignition Coil AQY/APK/AZH		<b>80218</b>
Ignition Coil AZG/AZJ		<b>80270</b>
Ignition Leads		<b>85874</b>
Ignition Leads APK; AQY; AZH		<b>85875</b>
<b>Bora (1J2) 2.0 4motion</b>		<b>2000-05</b>
AZH/AZJ		85 115
Ignition Coil AZH		<b>80218</b>
Ignition Coil AZJ		<b>80270</b>
Ignition Leads		<b>85874</b>
Ignition Leads AZH		<b>85875</b>
<b>Bora Kombi (1J6) 1.4 16V</b>		<b>2001-05</b>
AHW/AXP/BCA		55 75
Ignition Coil With regul.cat.(3way)		<b>80201</b>
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Bora Variant (1J6) 1.6</b>		<b>1999-05</b>
AKL/APF/AEH		74 100
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85875</b>
<b>Bora Variant (1J6) 1.6</b>		<b>2000-05</b>
AVU/BFQ		75 102
Ignition Coil AVU,BFQ		<b>80218</b>
Ignition Leads		<b>85879</b>
<b>Bora Variant (1J6) 1.6 16V</b>		<b>2000-05</b>
AUS/ATN/BCB/AZD		77 105
Ignition Coil 09.2000->		<b>80201</b>
Ignition Coil		<b>80218</b>
Ignition Leads ATN, AUS		<b>85696</b>
<b>Bora Variant (1J6) 1.6 FSI</b>		<b>2002-05</b>
BAD		81 110
Ignition Coil		<b>80201</b>
<b>Bora Variant (1J6) 1.8 4motion</b>		<b>1999-05</b>
AGN		92 125
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85065</b>

VOLKSWAGEN Cont.		
<b>Bora Variant (1J6) 1.8 T</b>		<b>2000-05</b>
ARX/AGU/AUM		110 150
Ignition Coil With regul.cat.(3way)		<b>80202</b>
Ignition Coil ARX,AGU,AUM		<b>80239</b>
Ignition Coil 09.2000->		<b>80252</b>
Ignition Leads		<b>85065</b>
<b>Bora Variant (1J6) 1.8 T</b>		<b>2002-05</b>
AUQ		132 180
Ignition Coil With regul.cat.(3way)		<b>80202</b>
Ignition Coil AUQ		<b>80239</b>
<b>Bora Variant (1J6) 2.0</b>		<b>1999-05</b>
APK/AZH/AZJ/AQY/AZG		85 115
Ignition Coil		<b>80218</b>
Ignition Coil AZG/AZJ		<b>80270</b>
Ignition Leads		<b>85874</b>
Ignition Leads AZH; APK; AQY		<b>85875</b>
<b>Bora Variant (1J6) 2.0 4motion</b>		<b>2000-05</b>
AZH/AZJ		85 115
Ignition Coil AZH		<b>80218</b>
Ignition Coil AZJ		<b>80270</b>
Ignition Leads		<b>85874</b>
Ignition Leads AZH		<b>85875</b>
<b>Caddy Alltrack Kombi (SAB) 1.0 TSI</b>		<b>2015-&gt;</b>
CHZG		75 102
Ignition Coil		<b>80249</b>
<b>Caddy Alltrack Kombi (SAB) 1.2 TSI</b>		<b>2015-&gt;</b>
CYVC		62 84
Ignition Coil		<b>80249</b>
<b>Caddy Alltrack Kombi (SAB) 1.4 TGI CNG</b>		<b>2015-&gt;</b>
CPWA		81 110
Ignition Coil		<b>80249</b>
<b>Caddy Alltrack Kombi (SAB) 1.4 TSI</b>		<b>2015-&gt;</b>
CZCB		92 125
Ignition Coil		<b>80249</b>
<b>Caddy Alltrack Van (SAA) 1.0 TSI</b>		<b>2015-&gt;</b>
CHZG		75 102
Ignition Coil		<b>80249</b>
<b>Caddy Alltrack Van (SAA) 1.2 TSI</b>		<b>2015-&gt;</b>
CYVC		62 84
Ignition Coil		<b>80249</b>
<b>Caddy Alltrack Van (SAA) 1.4 TGI CNG</b>		<b>2015-&gt;</b>
CPWA		81 110
Ignition Coil		<b>80249</b>
<b>Caddy Alltrack Van (SAA) 1.4 TSI</b>		<b>2015-&gt;</b>
CZCB		92 125
Ignition Coil		<b>80249</b>
<b>Caddy I (14) 1.5</b>		<b>1982-83</b>
JB		51 70
Ignition Leads		<b>85690</b>
Ignition Leads ->Ch.14-F-00370		<b>85865</b>
<b>Caddy I (14) 1.6</b>		<b>1983-92</b>
EW		55 75
Ignition Leads 08.1984->		<b>85685</b>
Ignition Leads		<b>85690</b>
Ignition Leads ->Ch.14-F-00370		<b>85865</b>
<b>Caddy I (14) 1.8</b>		<b>1985-92</b>
JH		70 95
Ignition Leads		<b>85685</b>
Ignition Leads		<b>85690</b>
Ignition Leads ->Ch.14-F-00370		<b>85865</b>
<b>Caddy II Pick-Up (9U7) 1.6</b>		<b>1996-00</b>
AEE		55 75
Ignition Coil		<b>80200</b>
Ignition Leads		<b>85693</b>
<b>Caddy II Van (9K9A) 1.4</b>		<b>2000-04</b>
AUA		55 75
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Caddy II Van (9K9A) 60 1.4</b>		<b>1995-04</b>
AEX/APQ/AUD		44 60
Ignition Coil With regul.cat.(3way)		<b>80200</b>
Ignition Coil		<b>80218</b>
Ignition Leads AUD		<b>85681</b>
Ignition Leads		<b>85692</b>
Ignition Leads APQ/AEX		<b>85693</b>



VOLKSWAGEN Cont.	
<b>Caddy II Van (9K9A) 75 1.6</b>	<b>1995-97</b>
1F	55 75
Ignition Coil	<b>80200</b>
Ignition Leads	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Caddy II Van (9K9A) 75 1.6</b>	<b>1995-00</b>
AEE	55 75
Ignition Coil	<b>80200</b>
Ignition Leads	<b>85693</b>
<b>Caddy II Variant (9K9B) 1.4</b>	<b>1995-04</b>
AEX/AKV/APQ/AUD	44 60
Ignition Coil AEX/AKV/APQ	<b>80200</b>
Ignition Coil AUD	<b>80218</b>
Ignition Leads AUD	<b>85692</b>
Ignition Leads AKV	<b>85693</b>
<b>Caddy II Variant (9K9B) 1.4 16V</b>	<b>2000-04</b>
AUA	55 75
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Caddy II Variant (9K9B) 1.6</b>	<b>1995-97</b>
1F	55 75
Ignition Coil	<b>80200</b>
Ignition Leads	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
<b>Caddy II Variant (9K9B) 1.6</b>	<b>1997-00</b>
AEE	55 75
Ignition Coil	<b>80200</b>
Ignition Leads	<b>85693</b>
<b>Caddy III Van (2KA, 2KH, 2CA, 2CH) 1.2 TSI</b>	<b>2010-15</b>
CBZA	63 86
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Caddy III Van (2KA, 2KH, 2CA, 2CH) 1.2 TSI</b>	<b>2010-15</b>
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Caddy III Van (2KA, 2KH, 2CA, 2CH) 1.4</b>	<b>2004-06</b>
BCA	55 75
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Caddy III Van (2KA, 2KH, 2CA, 2CH) 1.4 16V</b>	<b>2006-10</b>
BUD	59 80
Ignition Coil	<b>80201</b>
<b>Caddy III Van (2KA, 2KH, 2CA, 2CH) 1.6</b>	<b>2004-15</b>
BGU/BSF/BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Caddy III Van (2KA, 2KH, 2CA, 2CH) 1.6 BiFuel</b>	<b>2011-&gt;</b>
CHGA	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85879</b>
<b>Caddy III Van (2KA, 2KH, 2CA, 2CH) 2.0 EcoFuel</b>	<b>2006-15</b>
BSX	80 109
Ignition Coil	<b>80270</b>
Ignition Leads <2C>; 10.2010->	<b>85874</b>
Ignition Leads <2K>; ->08.2010	<b>85874</b>
<b>Caddy III Variant (2KB, 2KJ, 2CB, 2CJ) 1.2 TSI</b>	<b>2010-15</b>
CBZA	63 86
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Caddy III Variant (2KB, 2KJ, 2CB, 2CJ) 1.2 TSI</b>	<b>2010-15</b>
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Caddy III Variant (2KB, 2KJ, 2CB, 2CJ) 1.4</b>	<b>2004-06</b>
BCA	55 75
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Caddy III Variant (2KB, 2KJ, 2CB, 2CJ) 1.4 16V</b>	<b>2006-10</b>
BUD	59 80
Ignition Coil	<b>80201</b>
<b>Caddy III Variant (2KB, 2KJ, 2CB, 2CJ) 1.6</b>	<b>2004-15</b>
BGU/BSF/BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Caddy III Variant (2KB, 2KJ, 2CB, 2CJ) 1.6 BiFuel</b>	<b>2011-&gt;</b>
CHGA	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85879</b>

VOLKSWAGEN Cont.	
<b>Caddy III Variant (2KB, 2KJ, 2CB, 2CJ) 2.0 EcoFuel</b>	<b>2006-15</b>
BSX	80 109
Ignition Coil	<b>80270</b>
Ignition Leads <2C>; 10.2010->	<b>85874</b>
Ignition Leads <2K>; ->08.2010	<b>85874</b>
<b>Caddy IV Kasten (SAA, SAH) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZG	75 102
Ignition Coil	<b>80249</b>
<b>Caddy IV Kasten (SAA, SAH) 1.2 TSI</b>	<b>2015-&gt;</b>
CYVC	62 84
Ignition Coil	<b>80249</b>
<b>Caddy IV Kasten (SAA, SAH) 1.4 TGI CNG</b>	<b>2015-&gt;</b>
CPWA	81 110
Ignition Coil	<b>80249</b>
<b>Caddy IV Kasten (SAA, SAH) 1.4 TSI</b>	<b>2015-&gt;</b>
CZCB	92 125
Ignition Coil	<b>80249</b>
<b>Caddy IV Kombi (SAB, SAJ) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZG	75 102
Ignition Coil	<b>80249</b>
<b>Caddy IV Kombi (SAB, SAJ) 1.2 TSI</b>	<b>2015-&gt;</b>
CYVC	62 84
Ignition Coil	<b>80249</b>
<b>Caddy IV Kombi (SAB, SAJ) 1.4 TGI CNG</b>	<b>2015-&gt;</b>
CPWA	81 110
Ignition Coil	<b>80249</b>
<b>Caddy IV Kombi (SAB, SAJ) 1.4 TSI</b>	<b>2015-&gt;</b>
CZCB	92 125
Ignition Coil	<b>80249</b>
<b>CC (358) 1.4 TSI</b>	<b>2015-&gt;</b>
CZDA	110 150
Ignition Coil	<b>80249</b>
<b>CC (358) 1.4 TSI</b>	<b>2011-&gt;</b>
CTHD	118 160
Ignition Coil ->12.2016	<b>80201</b>
<b>CC (358) 1.4 TSI MultiFuel</b>	<b>2011-&gt;</b>
CKMA	118 160
Ignition Coil ->12.2016	<b>80201</b>
<b>Corrado (53I) 1.8 16V</b>	<b>1989-92</b>
KR	100 136
Ignition Leads	<b>85059</b>
<b>Corrado (53I) 1.8 G60</b>	<b>1988-93</b>
PG	118 160
Ignition Leads	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads PG	<b>85865</b>
<b>Corrado (53I) 2.0 i</b>	<b>1993-95</b>
ADY/2E	85 115
Ignition Coil ADY,2E	<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ADY	<b>85865</b>
<b>Corrado (53I) 2.0 i 16V</b>	<b>1991-95</b>
9A	100 136
Ignition Coil	<b>80200</b>
Ignition Leads	<b>85059</b>
<b>Corrado (53I) 2.9 VR6</b>	<b>1991-95</b>
ABV	140 190
Ignition Leads Ch.50-P-010001->	<b>85070</b>
<b>Derby (86) 0.9</b>	<b>1977-81</b>
HA	29 40
Ignition Leads	<b>83720</b>
<b>Derby (86) 1.1</b>	<b>1977-81</b>
HB	37 50
Ignition Leads	<b>83720</b>
<b>Derby (86) 1.3</b>	<b>1977-81</b>
HH	44 60
Ignition Leads	<b>83720</b>
<b>Derby (86) 1.3</b>	<b>1977-81</b>
HJ	43 58
Ignition Leads	<b>83720</b>
<b>Derby (86C, 80) 1.0</b>	<b>1981-84</b>
GL	29 40
Ignition Leads	<b>83720</b>
<b>Derby (86C, 80) 1.1</b>	<b>1981-83</b>
HB	37 50
Ignition Leads	<b>83720</b>



VOLKSWAGEN Cont.	
<b>Derby (86C, 80) 1.3</b>	<b>1983-84</b>
HK	40 55
Ignition Leads	<b>83720</b>
<b>Derby (86C, 80) 1.3</b>	<b>1981-83</b>
HH	44 60
Ignition Leads	<b>83720</b>
<b>Derby (86C, 80) 1.3</b>	<b>1983-84</b>
HW	37 50
Ignition Leads	<b>83720</b>
<b>Derby (86C, 80) 1.3</b>	<b>1982-84</b>
GK	55 75
Ignition Leads	<b>83720</b>
<b>Eos (1F7, 1F8) 1.4 TSI</b>	<b>2007-15</b>
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Eos (1F7, 1F8) 1.4 TSI</b>	<b>2008-15</b>
CAVD/CTHD	118 160
Ignition Coil	<b>80201</b>
<b>Eos (1F7, 1F8) 1.6 FSI</b>	<b>2006-08</b>
BLF	85 115
Ignition Coil Direct Injection	<b>80201</b>
<b>Eos (1F7, 1F8) 2.0 FSI</b>	<b>2006-08</b>
BVZ/BVY	110 150
Ignition Coil BVY	<b>80240</b>
<b>Eos (1F7, 1F8) 2.0 TFSI</b>	<b>2006-15</b>
BWA/BPY/CBFA/CCZA/CAWB/CCTA	147 200
Ignition Coil BWA	<b>80240</b>
<b>Eos (1F7, 1F8) 2.0 TSI</b>	<b>2009-15</b>
CCZB	155 210
Ignition Coil	<b>80240</b>
<b>Eos (1F7, 1F8) 3.2 V6</b>	<b>2006-09</b>
CBRA/BUB	184 250
Ignition Coil	<b>80327</b>
<b>Eos (1F7, 1F8) 3.6 V6</b>	<b>2009-10</b>
CDVA	191 260
Ignition Coil	<b>80327</b>
<b>Escarabajo 1600 i</b>	<b>1992-03</b>
ACD	34 46
Ignition Coil	<b>80200</b>
<b>Fox (5Z1, 5Z3) 1.2</b>	<b>2005-&gt;</b>
BMD/CHFB	40 55
Ignition Coil	<b>80326</b>
<b>Fox (5Z1, 5Z3) 1.2</b>	<b>2010-&gt;</b>
CHFA	44 60
Ignition Coil ->12.2012	<b>80326</b>
<b>Fox (5Z1, 5Z3) 1.4</b>	<b>2005-&gt;</b>
BKR	55 75
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85697</b>
<b>Fox 1.6 Highline Flex 16 V</b>	<b>2014-&gt;</b>
CNXA	88 120
Ignition Coil 09.2014->	<b>80249</b>
<b>Golf I (17) 1.1</b>	<b>1974-83</b>
GG/FA	37 50
Ignition Leads	<b>83720</b>
<b>Golf I (17) 1.1</b>	<b>1976-80</b>
FJ	38 52
Ignition Leads	<b>83720</b>
<b>Golf I (17) 1.3</b>	<b>1979-83</b>
GF	44 60
Ignition Leads	<b>83720</b>
<b>Golf I (17) 1.3</b>	<b>1982-83</b>
GS	43 58
Ignition Leads	<b>83720</b>
<b>Golf I (17) 1.6 GTI</b>	<b>1976-82</b>
EG	81 110
Ignition Leads	<b>83500</b>
<b>Golf I Cabriolet (155) 1.6</b>	<b>1986-90</b>
RE	53 72
Ignition Leads	<b>85685</b>
<b>Golf I Cabriolet (155) 1.6</b>	<b>1983-92</b>
EW/HN	55 75
Ignition Leads 03.1984->	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads EW	<b>85865</b>

VOLKSWAGEN Cont.	
<b>Golf I Cabriolet (155) 1.8</b>	<b>1983-92</b>
EX	66 90
Ignition Leads 08.1984->	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.15-E-02700	<b>85865</b>
<b>Golf I Cabriolet (155) 1.8</b>	<b>1983-93</b>
JH	70 95
Ignition Leads 08.1984->	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.15-E-02700	<b>85865</b>
<b>Golf I Cabriolet (155) 1.8</b>	<b>1982-89</b>
EV/PB/DX	82 112
Ignition Leads 08.1984->	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads DX/EV/PB; ->Ch.15-E-02700	<b>85865</b>
<b>Golf I Cabriolet (155) 1.8</b>	<b>1989-93</b>
2H	72 98
Ignition Leads	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.15-E-02700	<b>85865</b>
<b>Golf II (19E, 1G1) 1.0</b>	<b>1983-85</b>
GN	33 45
Ignition Leads 08.1984-07.1985	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads GN	<b>85865</b>
<b>Golf II (19E, 1G1) 1.3</b>	<b>1983-87</b>
MH/HK	40 55
Ignition Leads	<b>85693</b>
<b>Golf II (19E, 1G1) 1.3 KAT</b>	<b>1986-92</b>
NZ/2G/MH	40 55
Ignition Coil NZ, 2G; 3 term.; 10.1990->	<b>80200</b>
Ignition Coil NZ, 2G; 6 term.; 10.1990->	<b>80219</b>
<b>Golf II (19E, 1G1) 1.6</b>	<b>1986-92</b>
PN	51 70
Ignition Leads ->07.1992	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads PN	<b>85865</b>
<b>Golf II (19E, 1G1) 1.6</b>	<b>1986-91</b>
RF	53 72
Ignition Leads	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads RF	<b>85865</b>
<b>Golf II (19E, 1G1) 1.6</b>	<b>1983-92</b>
HM/ABN/EZ	55 75
Ignition Leads 08.1984-07.1991	<b>85685</b>
Ignition Leads Ch.19-E-855001->	<b>85690</b>
Ignition Leads ->Ch.19-E-855001	<b>85865</b>
<b>Golf II (19E, 1G1) 1.8</b>	<b>1986-90</b>
RH	62 84
Ignition Leads	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->Ch.19-E-855001	<b>85865</b>
<b>Golf II (19E, 1G1) 1.8</b>	<b>1984-91</b>
GX/GU/HV	66 90
Ignition Leads	<b>85685</b>
Ignition Leads Ch.19-E-855001->	<b>85690</b>
Ignition Leads GX/GU	<b>85693</b>
Ignition Leads	<b>85865</b>
<b>Golf II (19E, 1G1) 1.8 GTI</b>	<b>1983-91</b>
EV/GZ/PB/DX	82 112
Ignition Leads	<b>85690</b>
Ignition Leads	<b>85865</b>
<b>Golf II (19E, 1G1) 1.8 GTI</b>	<b>1985-87</b>
RD	79 107
Ignition Leads	<b>85685</b>
<b>Golf II (19E, 1G1) 1.8 GTI G60 Syncro</b>	<b>1988-91</b>
PG/1H	118 160
Ignition Leads 1H	<b>85690</b>
Ignition Leads PG	<b>85865</b>
<b>Golf II (19E, 1G1) 1.8 GTI KAT</b>	<b>1987-91</b>
PF	79 107
Ignition Leads	<b>85685</b>
<b>Golf II (19E, 1G1) 1.8 i KAT</b>	<b>1987-91</b>
GX/RP	66 90
Ignition Leads 10.1987-08.1988	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads GX	<b>85693</b>
Ignition Leads ->Ch.19-E-855001	<b>85865</b>



VOLKSWAGEN Cont.		
<b>Golf II (19E, 1G1) 1.8 i Syncro KAT</b>	<b>1987-91</b>	
RP	66	90
Ignition Leads 10.1987->	<b>85685</b>	
Ignition Leads	<b>85690</b>	
Ignition Leads RP	<b>85693</b>	
Ignition Leads RP	<b>85865</b>	
<b>Golf II (19E, 1G1) 1.8 Syncro</b>	<b>1986-91</b>	
GX/GU	66	90
Ignition Leads	<b>85690</b>	
Ignition Leads	<b>85693</b>	
<b>Golf II (19E, 1G1) 1.8 Syncro</b>	<b>1987-88</b>	
RH	62	84
Ignition Leads	<b>85685</b>	
<b>Golf III (1H1) 1.4</b>	<b>1991-97</b>	
AEX/ABD	40	55
Ignition Coil AEX,ABD	<b>80200</b>	
Ignition Leads	<b>85693</b>	
Ignition Leads	<b>85694</b>	
<b>Golf III (1H1) 1.4</b>	<b>1991-97</b>	
AEX/ABD	44	60
Ignition Coil ABD,AEX	<b>80200</b>	
Ignition Leads AEX	<b>85693</b>	
Ignition Leads ABD	<b>85694</b>	
<b>Golf III (1H1) 1.6</b>	<b>1992-97</b>	
ABU/AEA/AEE	55	75
Ignition Coil ABU,AEA,AEE	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>	
Ignition Leads 07.1995->	<b>85693</b>	
<b>Golf III (1H1) 1.6</b>	<b>1995-97</b>	
AEK/AFT/AKS	74	101
Ignition Coil AEK,AFT,AKS	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>	
Ignition Leads	<b>85865</b>	
Ignition Leads AEK	<b>85870</b>	
<b>Golf III (1H1) 1.8</b>	<b>1991-97</b>	
AAM	55	75
Ignition Coil	<b>80200</b>	
Ignition Leads ->07.1994	<b>85865</b>	
<b>Golf III (1H1) 1.8</b>	<b>1991-97</b>	
ACC/ADZ/ABS	66	90
Ignition Coil ACC,ABS,ADZ	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>	
Ignition Leads ADZ	<b>85690</b>	
Ignition Leads ACC	<b>85865</b>	
<b>Golf III (1H1) 1.8 Syncro</b>	<b>1993-97</b>	
ADZ/ABS	66	90
Ignition Coil ADZ,ABS	<b>80200</b>	
Ignition Leads ABS	<b>85865</b>	
<b>Golf III (1H1) 2.0</b>	<b>1991-97</b>	
ABA/ADY/AKR/2E/AGG	85	115
Ignition Coil AGG,AKR,ADY,2E	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>	
Ignition Leads	<b>85690</b>	
<b>Golf III (1H1) 2.0 GTI 16V</b>	<b>1992-97</b>	
ABF	110	150
Ignition Coil	<b>80200</b>	
Ignition Leads	<b>85059</b>	
<b>Golf III (1H1) 2.0 Syncro</b>	<b>1995-97</b>	
AGG	85	115
Ignition Coil	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>	
<b>Golf III (1H1) 2.8 VR6</b>	<b>1992-97</b>	
AAA	128	174
Ignition Coil	<b>80200</b>	
Ignition Leads AAA; Ch.1H-PB060001-IH-VW-600000	<b>85070</b>	
<b>Golf III (1H1) 2.9 VR6 Syncro</b>	<b>1994-97</b>	
ABV	140	190
Ignition Leads ->Ch.1H-V-600000	<b>85070</b>	
<b>Golf III Cabriolet (1E7) 1.6</b>	<b>1994-98</b>	
AEK/AFT/AKS	74	101
Ignition Coil AKS,AEK,AFT	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>	
Ignition Leads	<b>85865</b>	
Ignition Leads AEK	<b>85870</b>	
<b>Golf III Cabriolet (1E7) 1.8</b>	<b>1993-98</b>	
AAM	55	75
Ignition Coil	<b>80200</b>	

VOLKSWAGEN Cont.		
<b>Golf III Cabriolet (1E7) 1.8</b>	<b>1993-98</b>	
ADZ/ABS	66	90
Ignition Coil ADZ,ABS	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>	
Ignition Leads	<b>85865</b>	
<b>Golf III Cabriolet (1E7) 2.0</b>	<b>1993-98</b>	
ADY/AKR/2E/AGG	85	115
Ignition Coil AGG,ADY,AKR,2E	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>	
Ignition Leads	<b>85690</b>	
<b>Golf III Variant (1H5) 1.4</b>	<b>1993-99</b>	
ABD	40	55
Ignition Coil	<b>80200</b>	
Ignition Leads	<b>85692</b>	
Ignition Leads	<b>85693</b>	
Ignition Leads ->07.1995	<b>85694</b>	
<b>Golf III Variant (1H5) 1.4</b>	<b>1993-99</b>	
AEX/ABD/APQ	44	60
Ignition Coil APQ,ABD,AEX	<b>80200</b>	
Ignition Leads	<b>85692</b>	
Ignition Leads AEX/ APQ	<b>85693</b>	
Ignition Leads ABD	<b>85694</b>	
<b>Golf III Variant (1H5) 1.6</b>	<b>1994-99</b>	
AEK/AFT/AKS	74	101
Ignition Coil AFT,AEK,AKS	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>	
Ignition Leads	<b>85865</b>	
Ignition Leads AEK	<b>85870</b>	
<b>Golf III Variant (1H5) 1.8</b>	<b>1993-99</b>	
ANN/AAM	55	75
Ignition Coil AAM,ANN	<b>80200</b>	
Ignition Leads AAH	<b>85865</b>	
<b>Golf III Variant (1H5) 1.8</b>	<b>1993-99</b>	
ADZ/ABS/ANP	66	90
Ignition Coil ABS,ADZ,ANP	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>	
Ignition Leads	<b>85690</b>	
Ignition Leads ABS	<b>85865</b>	
<b>Golf III Variant (1H5) 1.8 Syncro</b>	<b>1994-99</b>	
ADZ	66	90
Ignition Coil	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>	
<b>Golf III Variant (1H5) 2.0</b>	<b>1993-99</b>	
ADY/AKR/2E/AGG	85	115
Ignition Coil 2E,AGG,ADY,AKR	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>	
Ignition Leads	<b>85690</b>	
<b>Golf III Variant (1H5) 2.0 Syncro</b>	<b>1995-99</b>	
AGG	85	115
Ignition Coil	<b>80200</b>	
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>	
<b>Golf III Variant (1H5) 2.9 VR6 Syncro</b>	<b>1994-99</b>	
ABV	140	190
Ignition Leads ->Ch.1H-V-600000	<b>85070</b>	
<b>Golf IV (1J1) 1.4 16V</b>	<b>1997-05</b>	
AHW/AXP/BCA/APE/AKQ	55	75
Ignition Coil ->05.2004	<b>80201</b>	
Ignition Coil	<b>80218</b>	
Ignition Leads	<b>85696</b>	
<b>Golf IV (1J1) 1.6</b>	<b>2000-05</b>	
AVU/BFQ/BJH	75	102
Ignition Coil	<b>80218</b>	
Ignition Leads	<b>85879</b>	
<b>Golf IV (1J1) 1.6</b>	<b>1997-04</b>	
AKL/APF/AEH	74	100
Ignition Coil	<b>80218</b>	
Ignition Leads AEH/AKL; ->Ch.1J-W-050000	<b>85875</b>	
<b>Golf IV (1J1) 1.6 16V</b>	<b>2000-05</b>	
AUS/ATN/BCB/AZD	77	105
Ignition Coil 09.2000-05.2004	<b>80201</b>	
Ignition Coil	<b>80218</b>	
Ignition Leads ATN, AUS	<b>85696</b>	
<b>Golf IV (1J1) 1.6 FSI</b>	<b>2002-05</b>	
BAD	81	110
Ignition Coil ->05.2004	<b>80201</b>	
<b>Golf IV (1J1) 1.8</b>	<b>1997-05</b>	
AGN/BAF	92	125
Ignition Coil	<b>80218</b>	
Ignition Leads	<b>85065</b>	



VOLKSWAGEN Cont.		
<b>Golf IV (1J1) 1.8 4motion</b>		<b>1998-05</b>
AGN		92 125
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85065</b>
<b>Golf IV (1J1) 1.8 T</b>		<b>1997-05</b>
ARZ/AQA/AGU/AUM/AWD		110 150
Ignition Coil AWD; Ch.1J-1-000 001->		<b>80202</b>
Ignition Coil AUM; 05.2001->		<b>80202</b>
Ignition Coil AWD; ->Ch.1J-Y-900 000		<b>80239</b>
Ignition Coil ARZ		<b>80239</b>
Ignition Coil AGU; 05.2002->		<b>80252</b>
<b>Golf IV (1J1) 1.8 T GTI</b>		<b>2001-05</b>
AUQ		132 180
Ignition Coil With regul.cat.(3way)		<b>80202</b>
Ignition Coil AUQ		<b>80239</b>
<b>Golf IV (1J1) 2.0</b>		<b>1998-04</b>
APK/AZJ/AQY/BER/AZG		85 115
Ignition Coil		<b>80218</b>
Ignition Coil AZG/AZJ		<b>80270</b>
Ignition Leads		<b>85874</b>
Ignition Leads AQY; APK		<b>85875</b>
<b>Golf IV (1J1) 2.0 4motion</b>		<b>2000-05</b>
AZH/AZJ		85 115
Ignition Coil AZH; ->06.2001		<b>80218</b>
Ignition Coil AZJ		<b>80270</b>
Ignition Leads		<b>85874</b>
Ignition Leads AZH; 05.2001->		<b>85875</b>
<b>Golf IV (1J1) 3.2 R32 4motion</b>		<b>2002-05</b>
BFH/BML		177 241
Ignition Coil		<b>80327</b>
<b>Golf IV Cabriolet (1E7) 1.6</b>		<b>1998-02</b>
AFT/AKS		74 100
Ignition Coil AKS,AFT		<b>80200</b>
Ignition Leads		<b>85865</b>
<b>Golf IV Cabriolet (1E7) 1.8</b>		<b>1998-02</b>
ANN/AAM		55 75
Ignition Coil AAM,ANN		<b>80200</b>
<b>Golf IV Cabriolet (1E7) 1.8</b>		<b>1998-02</b>
ADZ/ANP		66 90
Ignition Coil ADZ,ANP		<b>80200</b>
Ignition Leads ADZ		<b>85690</b>
<b>Golf IV Cabriolet (1E7) 2.0</b>		<b>1998-02</b>
ATU/AKR/AWF/AGG/AWG		85 115
Ignition Coil AKR,AWG,ATU,AWF,AGG		<b>80200</b>
Ignition Leads AGG/AKR		<b>85690</b>
Ignition Leads ATU		<b>85696</b>
<b>Golf IV Variant (1J5) 1.4 16V</b>		<b>1999-06</b>
AHW/AXP/BCA/APE/AKQ		55 75
Ignition Coil 10.2001->		<b>80201</b>
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Golf IV Variant (1J5) 1.6</b>		<b>1999-02</b>
AKL/APF/AEH		74 101
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85875</b>
<b>Golf IV Variant (1J5) 1.6</b>		<b>2000-06</b>
AVU/BFQ		75 102
Ignition Coil AVU		<b>80218</b>
Ignition Leads		<b>85879</b>
<b>Golf IV Variant (1J5) 1.6 16V</b>		<b>2000-06</b>
AUS/ATN/BCB/AZD		77 105
Ignition Coil 09.2000->		<b>80201</b>
Ignition Coil		<b>80218</b>
Ignition Leads ATN, AUS		<b>85696</b>
<b>Golf IV Variant (1J5) 1.6 FSI</b>		<b>2002-06</b>
BAD		81 110
Ignition Coil		<b>80201</b>
<b>Golf IV Variant (1J5) 1.8 4motion</b>		<b>1999-06</b>
AGN		92 125
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85065</b>
<b>Golf IV Variant (1J5) 1.8 T</b>		<b>2000-06</b>
ARZ/AQA/AGU/AUM/AWD		110 150
Ignition Coil AWD; Ch.1J-1-000 001->		<b>80202</b>
Ignition Coil AUM; 05.2001->		<b>80202</b>
Ignition Coil ARZ		<b>80239</b>
Ignition Coil AWD; ->Ch.1J-Y-900 000		<b>80239</b>
Ignition Coil AUM,AGU; 05.2002->		<b>80252</b>

VOLKSWAGEN Cont.		
<b>Golf IV Variant (1J5) 2.0</b>		<b>1999-06</b>
APK/AZJ/AQY		85 115
Ignition Coil APK/AQY		<b>80218</b>
Ignition Coil AZJ		<b>80270</b>
Ignition Leads		<b>85874</b>
Ignition Leads APK; AQY		<b>85875</b>
<b>Golf IV Variant (1J5) 2.0 4motion</b>		<b>2000-06</b>
AZH/AZJ		85 115
Ignition Coil AZH; ->06.2001		<b>80218</b>
Ignition Coil AZJ		<b>80270</b>
Ignition Leads		<b>85874</b>
Ignition Leads AZH		<b>85875</b>
<b>Golf IV Variant (1J5) 2.0 Bi-Fuel</b>		<b>2002-06</b>
BEH		85 116
Ignition Coil Without ignition distributor		<b>80218</b>
Ignition Coil		<b>80270</b>
Ignition Leads		<b>85874</b>
<b>Golf Plus (5M1, 521) 1.2 TSI</b>		<b>2009-13</b>
CBZB		77 105
Ignition Coil		<b>80218</b>
<b>Golf Plus (5M1, 521) 1.4 16V</b>		<b>2005-06</b>
BCA		55 75
Ignition Coil ->05.2006; Intake manifold injection		<b>80201</b>
<b>Golf Plus (5M1, 521) 1.4 16V</b>		<b>2006-13</b>
BUD/CGGA		59 80
Ignition Coil BUD; ->07.2007; Intake manifold injection		<b>80201</b>
<b>Golf Plus (5M1, 521) 1.4 FSI</b>		<b>2005-06</b>
BLN		66 90
Ignition Coil Intake manifold injection		<b>80201</b>
<b>Golf Plus (5M1, 521) 1.4 TSI</b>		<b>2006-08</b>
BMY		103 140
Ignition Coil Direct Injection		<b>80201</b>
<b>Golf Plus (5M1, 521) 1.4 TSI</b>		<b>2006-08</b>
BLG		125 170
Ignition Coil Direct Injection		<b>80201</b>
<b>Golf Plus (5M1, 521) 1.4 TSI</b>		<b>2007-13</b>
CAXA		90 122
Ignition Coil		<b>80201</b>
<b>Golf Plus (5M1, 521) 1.4 TSI</b>		<b>2008-13</b>
CAVD/CNWA		118 160
Ignition Coil		<b>80201</b>
<b>Golf Plus (5M1, 521) 1.6</b>		<b>2005-13</b>
CCSA/BSF/CMXA/BSE		75 102
Ignition Coil BSE/BSF		<b>80218</b>
Ignition Leads		<b>85875</b>
<b>Golf Plus (5M1, 521) 1.6 BiFuel</b>		<b>2009-13</b>
CHGA		75 102
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85879</b>
<b>Golf Plus (5M1, 521) 1.6 FSI</b>		<b>2005-08</b>
BLF		85 115
Ignition Coil Direct Injection		<b>80201</b>
<b>Golf Plus (5M1, 521) 1.6 MultiFuel</b>		<b>2007-13</b>
CCSA/CMXA		75 102
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85879</b>
<b>Golf Plus (5M1, 521) 2.0 FSI</b>		<b>2005-08</b>
BLY/BLR/BVZ/BVY		110 150
Ignition Coil BVZ,BLY,BLR,BVY		<b>80240</b>
<b>Golf Sportsvan (AM1) 1.0 TSI</b>		<b>2015-&gt;</b>
CHZD		85 115
Ignition Coil		<b>80249</b>
<b>Golf Sportsvan (AM1) 1.2 TSI</b>		<b>2014-&gt;</b>
CYVB		81 110
Ignition Coil		<b>80249</b>
<b>Golf Sportsvan (AM1) 1.2 TSI</b>		<b>2014-&gt;</b>
CYVA		63 86
Ignition Coil		<b>80249</b>
<b>Golf Sportsvan (AM1) 1.4 TSI</b>		<b>2014-&gt;</b>
CZDA		110 150
Ignition Coil		<b>80249</b>
<b>Golf Sportsvan (AM1) 1.4 TSI</b>		<b>2014-&gt;</b>
CPVB/CZCA		92 125
Ignition Coil CZCA		<b>80249</b>
<b>Golf Sportsvan (AM1) 1.4 TSI MultiFuel</b>		<b>2014-&gt;</b>
CPVB		92 125
Ignition Coil		<b>80249</b>





VOLKSWAGEN Cont.	
<b>Golf Sportsvan (AM1) 1.6</b>	2014->
CWVA	81 110
Ignition Coil	<b>80249</b>
<b>Golf V (1K1) 1.4 16V</b>	2003-06
BCA	55 75
Ignition Coil Intake manifold injection	<b>80201</b>
Ignition Leads	<b>85696</b>
<b>Golf V (1K1) 1.4 16V</b>	2006-08
BUD	59 80
Ignition Coil ->11.2006; Intake manifold injection	<b>80201</b>
<b>Golf V (1K1) 1.4 FSI</b>	2003-06
BKG/BLN	66 90
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Golf V (1K1) 1.4 TSI</b>	2005-08
BLG	125 170
Ignition Coil Direct Injection	<b>80201</b>
<b>Golf V (1K1) 1.4 TSI</b>	2006-08
BMV	103 140
Ignition Coil Direct Injection	<b>80201</b>
<b>Golf V (1K1) 1.4 TSI</b>	2007-08
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Golf V (1K1) 1.6</b>	2004-08
BGU/BSF/BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Golf V (1K1) 1.6 FSI</b>	2003-08
BLF/BLP/BAG	85 115
Ignition Coil Direct Injection	<b>80201</b>
<b>Golf V (1K1) 2.0</b>	2006-08
BHY/CBPA	85 116
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Golf V (1K1) 2.0 FSI</b>	2004-08
BVX/BLX/BLY/BLR/AXW/BVZ/BVY	110 150
Ignition Coil	<b>80240</b>
<b>Golf V (1K1) 2.0 FSI 4motion</b>	2004-08
BVX/BLX	110 150
Ignition Coil	<b>80240</b>
<b>Golf V (1K1) 2.0 GTI</b>	2004-09
BWA/BPY/AXX/CBFA/CAWB/CCTA	147 200
Ignition Coil BWA,BPY,AXX	<b>80240</b>
<b>Golf V (1K1) 2.0 GTI</b>	2006-08
BYD	169 230
Ignition Coil	<b>80240</b>
<b>Golf V (1K1) 3.2</b>	2005-08
BUB	184 250
Ignition Coil	<b>80327</b>
<b>Golf V (1K1) 3.2 R32 4motion</b>	2005-08
CBRA/BUB	184 250
Ignition Coil	<b>80327</b>
<b>Golf V Variant (1K5) 1.4</b>	2007-09
BUD	59 80
Ignition Coil Intake manifold injection	<b>80201</b>
<b>Golf V Variant (1K5) 1.4 TSI</b>	2007-09
BMV	103 140
Ignition Coil Direct Injection	<b>80201</b>
<b>Golf V Variant (1K5) 1.4 TSI</b>	2007-09
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Golf V Variant (1K5) 1.4 TSI</b>	2007-09
BLG	125 170
Ignition Coil Direct Injection	<b>80201</b>
<b>Golf V Variant (1K5) 1.4 TSI</b>	2008-09
CAVD	118 160
Ignition Coil	<b>80201</b>
<b>Golf V Variant (1K5) 1.6</b>	2007-09
BGU/CCSA/BSF/BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Golf V Variant (1K5) 2.0</b>	2007-09
BWA/CAWB/CCTA	147 200
Ignition Coil	<b>80240</b>
<b>Golf VI (5K1) 1.2 TSI</b>	2008-12
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>

VOLKSWAGEN Cont.	
<b>Golf VI (5K1) 1.2 TSI</b>	2010-12
CBZA	63 86
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Golf VI (5K1) 1.4</b>	2008-12
CGGA	59 80
Ignition Coil	<b>80201</b>
<b>Golf VI (5K1) 1.4 TSI</b>	2008-12
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Golf VI (5K1) 1.4 TSI</b>	2008-12
CTKA/CAVD/CTHD/CNWA	118 160
Ignition Coil	<b>80201</b>
<b>Golf VI (5K1) 1.6</b>	2008-12
CCSA/BSF/CMXA/BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
Ignition Leads	<b>85879</b>
<b>Golf VI (5K1) 1.6 BiFuel</b>	2009-12
CHGA	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85879</b>
<b>Golf VI (5K1) 1.6 MultiFuel</b>	2008-12
CCSA/CMXA	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85879</b>
<b>Golf VI (5K1) 1.8 TSI</b>	2009-11
CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Golf VI (5K1) 2.0 GTi</b>	2009-12
CCZB	155 210
Ignition Coil	<b>80240</b>
<b>Golf VI (5K1) 2.0 R 4motion</b>	2009-12
CDLF	199 270
Ignition Coil	<b>80240</b>
<b>Golf VI (5K1) 2.0 R 4motion</b>	2009-13
CRZA/CDLC	188 256
Ignition Coil	<b>80240</b>
<b>Golf VI Cabriolet (517) 1.2 TSI</b>	2011-13
CBZB	77 105
Ignition Coil ->05.2016	<b>80218</b>
<b>Golf VI Cabriolet (517) 1.2 TSI 16V</b>	2013->
CYVD	77 105
Ignition Coil	<b>80249</b>
<b>Golf VI Cabriolet (517) 1.4 TSI</b>	2013->
CXSB/CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Golf VI Cabriolet (517) 1.4 TSI</b>	2013->
CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Golf VI Cabriolet (517) 1.4 TSI</b>	2011->
CAXA	90 122
Ignition Coil ->05.2016	<b>80201</b>
<b>Golf VI Cabriolet (517) 1.4 TSI</b>	2011->
CTKA/CAVD/CTHD/CNWA	118 160
Ignition Coil ->05.2016	<b>80201</b>
<b>Golf VI Variant (AJ5) 1.2 TSI</b>	2009-13
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Golf VI Variant (AJ5) 1.2 TSI</b>	2010-13
CBZA	63 86
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Golf VI Variant (AJ5) 1.4</b>	2009-13
BUD/CGGA	59 80
Ignition Coil	<b>80201</b>
<b>Golf VI Variant (AJ5) 1.4 TSI</b>	2009-13
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Golf VI Variant (AJ5) 1.4 TSI</b>	2009-13
CTKA/CAVD/CTHD/CNWA	118 160
Ignition Coil	<b>80201</b>
<b>Golf VI Variant (AJ5) 1.6</b>	2009-13
CCSA/BSF/CMXA/BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85879</b>

**VOLKSWAGEN Cont.**

<b>Golf VII (5G1, BE1) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZD	85 115
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.2 TSI</b>	<b>2014-&gt;</b>
CYVB	81 110
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.2 TSI</b>	<b>2012-&gt;</b>
CJZB/CYVA	63 86
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.2 TSI</b>	<b>2012-&gt;</b>
CJZA	77 105
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.4 GTE Hybrid</b>	<b>2014-&gt;</b>
CUKB	110 150
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.4 TGI CNG</b>	<b>2013-&gt;</b>
CPWA	81 110
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.4 TSI</b>	<b>2014-&gt;</b>
CPVB/CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.4 TSI</b>	<b>2014-&gt;</b>
CZEA/CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.4 TSI</b>	<b>2012-&gt;</b>
CHPA/CPTA	103 140
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.4 TSI</b>	<b>2012-&gt;</b>
CPVA/CMBA/CXSA	90 122
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.4 TSI MultiFuel</b>	<b>2013-&gt;</b>
CPVB	92 125
Ignition Coil ->05.2014	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.4 TSI MultiFuel</b>	<b>2013-&gt;</b>
CPVA	90 122
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 1.6</b>	<b>2014-&gt;</b>
CWVA	81 110
Ignition Coil	<b>80249</b>
<b>Golf VII (5G1, BE1) 2.0 GTI</b>	<b>2013-&gt;</b>
CXCB/CXDA/CHHB	162 220
Ignition Coil	<b>80238</b>
<b>Golf VII (5G1, BE1) 2.0 GTI</b>	<b>2013-&gt;</b>
CHHA	169 230
Ignition Coil	<b>80238</b>
<b>Golf VII Kombi (BA5) 1.0 TSI</b>	<b>2015-&gt;</b>
CHZD	85 115
Ignition Coil	<b>80249</b>
<b>Golf VII Kombi (BA5) 1.2 TSI</b>	<b>2014-&gt;</b>
CYVB	81 110
Ignition Coil	<b>80249</b>
<b>Golf VII Kombi (BA5) 1.4 TSI</b>	<b>2014-&gt;</b>
CPVB/CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Golf VII Kombi (BA5) 1.4 TSI</b>	<b>2014-&gt;</b>
CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Golf VII Kombi (BA5) 1.4 TSI MultiFuel</b>	<b>2014-&gt;</b>
CPVB	92 125
Ignition Coil	<b>80249</b>
<b>Golf VII Kombi (BA5) 1.6</b>	<b>2014-&gt;</b>
CWVA	81 110
Ignition Coil	<b>80249</b>
<b>Golf VII Variant (BA5) 1.2 TSI</b>	<b>2013-&gt;</b>
CJZB/CYVA	63 86
Ignition Coil	<b>80249</b>
<b>Golf VII Variant (BA5) 1.2 TSI</b>	<b>2013-&gt;</b>
CJZA	77 105
Ignition Coil	<b>80249</b>
<b>Golf VII Variant (BA5) 1.4 TGI CNG</b>	<b>2013-&gt;</b>
CPWA	81 110
Ignition Coil	<b>80249</b>
<b>Golf VII Variant (BA5) 1.4 TSI</b>	<b>2013-&gt;</b>
CHPA	103 140
Ignition Coil	<b>80249</b>
<b>Golf VII Variant (BA5) 1.4 TSI</b>	<b>2013-&gt;</b>
CPVA/CXSA	90 122
Ignition Coil	<b>80249</b>

**VOLKSWAGEN Cont.**

<b>Golf VII Variant (BA5) 1.4 TSI MultiFuel</b>	<b>2013-&gt;</b>
CPVA	90 122
Ignition Coil	<b>80249</b>
<b>Jetta I (16) 1.1</b>	<b>1978-84</b>
GG/FA	37 50
Ignition Leads	<b>83720</b>
<b>Jetta I (16) 1.3</b>	<b>1979-84</b>
GF	44 60
Ignition Leads	<b>83720</b>
<b>Jetta I (16) 1.3</b>	<b>1982-84</b>
GS	43 58
Ignition Leads	<b>83720</b>
<b>Jetta I (16) 1.6 GLI</b>	<b>1978-82</b>
EG	81 110
Ignition Leads	<b>83500</b>
<b>Jetta II (19E, 1G2, 165) 1.6</b>	<b>1986-91</b>
PN	51 70
Ignition Leads	<b>85685</b>
<b>Jetta II (19E, 1G2, 165) 1.6</b>	<b>1986-91</b>
RF	53 72
Ignition Leads	<b>85685</b>
Ignition Leads	<b>85865</b>
<b>Jetta II (19E, 1G2, 165) 1.6</b>	<b>1984-92</b>
HM/ABN/EZ	55 75
Ignition Leads	<b>85685</b>
<b>Jetta II (19E, 1G2, 165) 1.8</b>	<b>1986-90</b>
RH	62 84
Ignition Leads	<b>85685</b>
<b>Jetta II (19E, 1G2, 165) 1.8</b>	<b>1984-91</b>
EV/GZ/PB	82 112
Ignition Leads 08.1984->	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads Ch.19-E-855001->	<b>85865</b>
<b>Jetta II (19E, 1G2, 165) 1.8</b>	<b>1985-87</b>
RD	79 107
Ignition Leads	<b>85685</b>
<b>Jetta II (19E, 1G2, 165) 1.8</b>	<b>1984-91</b>
GX/GU/HV	66 90
Ignition Leads <Jetta 1.8>; <Jetta 1.8 Syncro>; ->10.1987	<b>85685</b>
Ignition Leads Ch.19-E-855001->	<b>85865</b>
<b>Jetta II (19E, 1G2, 165) 1.8 16V</b>	<b>1986-91</b>
PL	95 129
Ignition Leads	<b>85059</b>
<b>Jetta II (19E, 1G2, 165) 1.8 16V</b>	<b>1987-89</b>
KR	102 140
Ignition Leads	<b>85059</b>
<b>Jetta II (19E, 1G2, 165) 1.8 KAT</b>	<b>1987-91</b>
GX/RP	66 90
Ignition Leads	<b>85690</b>
Ignition Leads	<b>85865</b>
<b>Jetta II (19E, 1G2, 165) 1.8 KAT</b>	<b>1987-91</b>
PF	79 107
Ignition Leads	<b>85685</b>
<b>Jetta II (19E, 1G2, 165) 1.8 Syncro</b>	<b>1988-91</b>
1P	72 98
Ignition Leads	<b>85685</b>
<b>Jetta II (19E, 1G2, 165) 1.8 Syncro</b>	<b>1987-88</b>
RP/GU	66 90
Ignition Leads	<b>85685</b>
<b>Jetta III (1K2) 1.4 TSI</b>	<b>2006-10</b>
BMY	103 140
Ignition Coil Direct Injection	<b>80201</b>
<b>Jetta III (1K2) 1.4 TSI</b>	<b>2006-10</b>
BLG	125 170
Ignition Coil Direct Injection	<b>80201</b>
<b>Jetta III (1K2) 1.4 TSI</b>	<b>2007-10</b>
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Jetta III (1K2) 1.4 TSI</b>	<b>2008-10</b>
CAVD	118 160
Ignition Coil	<b>80201</b>
<b>Jetta III (1K2) 1.6</b>	<b>2005-10</b>
BGU/CCSA/BSF/BSE	75 102
Ignition Coil BSF/BSE	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Jetta III (1K2) 1.6 FSI</b>	<b>2005-10</b>
BLF	85 115
Ignition Coil Direct Injection	<b>80201</b>



VOLKSWAGEN Cont.	
<b>Jetta III (1K2) 2.0 FSI</b>	2005-10
BLX/BLY/BLR/BVZ/BVY	110 150
Ignition Coil BLY,BLR,BVY,BVZ	<b>80240</b>
<b>Jetta III (1K2) 2.0 TFSI</b>	2005-10
BWA/BPY/AXX/CBFA/CCZA/CAWB/CCCTA	147 200
Ignition Coil BWA,BPY	<b>80240</b>
<b>Jetta III (1K2) 2.5 FSI</b>	2006-10
BTK/BGP	110 150
Ignition Coil	<b>80240</b>
<b>Jetta IV (162, 163) 1.2 TSI</b>	2010->
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Coil	<b>80249</b>
<b>Jetta IV (162, 163) 1.4 TSI</b>	2014->
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Jetta IV (162, 163) 1.4 TSI</b>	2014->
CZTA/CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Jetta IV (162, 163) 1.4 TSI</b>	2011->
CMSB/CAXA	90 122
Ignition Coil 07.2011->	<b>80201</b>
<b>Jetta IV (162, 163) 1.4 TSI</b>	2011-14
CTHA/CAVA	110 150
Ignition Coil	<b>80201</b>
<b>Jetta IV (162, 163) 1.4 TSI</b>	2011->
CAVD/CTHD	118 160
Ignition Coil	<b>80201</b>
<b>Jetta IV (162, 163) 1.4 TSI Hybrid</b>	2011->
CRJA/CNLA	110 150
Ignition Coil	<b>80249</b>
<b>Jetta IV (162, 163) 1.6</b>	2011->
CFNA/CLRA	77 105
Ignition Coil ->07.2014	<b>80201</b>
<b>Jetta IV (162, 163) 2.0</b>	2010->
CKJA/CBPA	85 115
Ignition Coil ->07.2014	<b>80218</b>
Ignition Coil	<b>80270</b>
Ignition Leads 10.2010-02.2016	<b>85874</b>
<b>Jetta IV (162, 163) 2.0 TSI</b>	2012->
CPPA/CPLA	155 211
Ignition Coil	<b>80238</b>
<b>Load Up 1.0</b>	2014->
CHYA	44 60
Ignition Coil ->06.2016	<b>80249</b>
<b>Load Up 1.0 EcoFuel</b>	2014->
CPGA	50 68
Ignition Coil ->07.2016	<b>80249</b>
<b>LT 28-35 II Bus (2DB, 2DE, 2DK) 2.3</b>	1996-06
AGL	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>LT 28-46 II Chassis (2DC, 2DF, 2DG, 2DL, 2DM) 2.3</b>	1996-06
AGL	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>LT 28-46 II Van (2DA, 2DD, 2DH) 2.3</b>	1996-06
AGL	105 143
Ignition Coil With regul.cat.(3way)	<b>80211</b>
Ignition Leads SAE	<b>85051</b>
<b>Lupo (6X1, 6E1) 1.0</b>	1998-05
AER/ALD/ANV/ALL/AUC	37 50
Ignition Coil AER/ALL	<b>80200</b>
Ignition Coil ALD/AUC/ANV	<b>80218</b>
Ignition Leads AUC; 05.2000->	<b>85681</b>
Ignition Leads AER/ ALL; ->05.2000	<b>85693</b>
<b>Lupo (6X1, 6E1) 1.4</b>	2000-05
AUD	44 60
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85681</b>
<b>Lupo (6X1, 6E1) 1.4 16V</b>	1999-05
AFK/AUB/AQQ	74 100
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Lupo (6X1, 6E1) 1.4 16V</b>	1998-05
AHW/APE/BBY/AKQ/AUA	55 75
Ignition Coil 11.2001->	<b>80201</b>
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>

VOLKSWAGEN Cont.	
<b>Lupo (6X1, 6E1) 1.4 FSI</b>	2001-05
ARR	77 105
Ignition Leads	<b>85681</b>
<b>Lupo (6X1, 6E1) 1.6 GTI</b>	2000-05
AVY	92 125
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85681</b>
<b>Multivan V (7HM, 7HN, 7HF, 7EF, 7EM, 7EN) 2.0</b>	2003->
AXA	85 115
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Multivan V (7HM, 7HN, 7HF, 7EF, 7EM, 7EN) 3.2 V6</b>	2004-04
BDL	170 231
Ignition Coil	<b>80327</b>
<b>Multivan V (7HM, 7HN, 7HF, 7EF, 7EM, 7EN) 3.2 V6</b>	2004-09
BKK/CFLA	173 235
Ignition Coil	<b>80327</b>
<b>Multivan V (7HM, 7HN, 7HF, 7EF, 7EM, 7EN) 3.2 V6 4motion</b>	2004-09
BKK/CFLA	173 235
Ignition Coil	<b>80327</b>
<b>New Beetle (9C1, 1C1) 1.4</b>	2001-10
BCA	55 75
Ignition Coil	<b>80201</b>
<b>New Beetle (9C1, 1C1) 1.6</b>	1999-00
AWH	74 100
Ignition Coil	<b>80218</b>
Ignition Leads AWH	<b>85875</b>
<b>New Beetle (9C1, 1C1) 1.6</b>	2000-10
AYD/BFS	75 102
Ignition Coil AYD	<b>80218</b>
Ignition Leads	<b>85879</b>
<b>New Beetle (9C1, 1C1) 1.8 T</b>	1999-10
AWW/APH/AVC/AGU/AWU/BKF	110 150
Ignition Coil AVC,AWU,AWW	<b>80202</b>
Ignition Coil APH	<b>80239</b>
<b>New Beetle (9C1, 1C1) 1.8 T</b>	2001-05
AWP/BNU	132 180
Ignition Coil	<b>80202</b>
<b>New Beetle (9C1, 1C1) 2.0</b>	1998-10
APK/AZJ/AVH/AQY/AEG/BEV/BHP/BER/AZG/CBPA/BEJ	85 115
Ignition Coil	<b>80218</b>
Ignition Coil AZG/AVH	<b>80270</b>
Ignition Leads	<b>85874</b>
Ignition Leads AEG/APK/AQY; ->Ch.1C-Y466575	<b>85875</b>
<b>New Beetle (9C1, 1C1) 2.5</b>	2005-10
BPS/BPR	110 150
Ignition Coil	<b>80240</b>
<b>New Beetle Cabriolet (1Y7) 1.4</b>	2003-10
BCA	55 75
Ignition Coil	<b>80201</b>
<b>New Beetle Cabriolet (1Y7) 1.6</b>	2003-10
BFS	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85879</b>
<b>New Beetle Cabriolet (1Y7) 1.8 T</b>	2003-10
AWW/AWU/BKF	110 150
Ignition Coil Ch.9C-1-600001->	<b>80202</b>
Ignition Coil AWU, AWV; ->Ch.9C-Y-699000	<b>80239</b>
<b>New Beetle Cabriolet (1Y7) 2.0</b>	2002-10
AZJ/AQY/BEV/BDC/BGD	85 115
Ignition Coil	<b>80218</b>
Ignition Coil AZJ	<b>80270</b>
Ignition Leads	<b>85874</b>
<b>New Beetle Cabriolet (1Y7) 2.5</b>	2005-10
BPS/BPR	110 150
Ignition Coil	<b>80240</b>
<b>Passat (32) 1.3</b>	1973-80
FY	40 55
Ignition Leads	<b>83960</b>
<b>Passat (32) 1.3</b>	1973-78
ZA	40 55
Ignition Leads	<b>83960</b>
<b>Passat (32) 1.3</b>	1973-78
ZF	44 60
Ignition Leads	<b>83960</b>
<b>Passat (32) 1.5</b>	1973-75
ZB/YJ	55 75
Ignition Leads	<b>83960</b>



VOLKSWAGEN Cont.	
<b>Passat (32) 1.5</b>	<b>1973-75</b>
ZC	63 86
Ignition Leads	<b>83960</b>
<b>Passat (32) 1.6</b>	<b>1975-80</b>
YP	63 85
Ignition Leads	<b>83960</b>
<b>Passat (32B) 1.3</b>	<b>1980-83</b>
FY	40 55
Ignition Leads	<b>83720</b>
<b>Passat (32B) 1.3</b>	<b>1980-86</b>
FZ	44 60
Ignition Leads ->12.1983	<b>83960</b>
<b>Passat (32B) 1.6</b>	<b>1987-88</b>
PP	51 70
Ignition Leads	<b>83960</b>
<b>Passat (32B) 1.6</b>	<b>1986-88</b>
RL	53 72
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat (32B) 1.6</b>	<b>1980-88</b>
WV/YN	55 75
Ignition Leads ->12.1983	<b>83960</b>
<b>Passat (32B) 1.6</b>	<b>1981-83</b>
YP	63 85
Ignition Leads	<b>83960</b>
<b>Passat (32B) 1.6</b>	<b>1980-88</b>
DT	55 75
Ignition Leads ->12.1983	<b>83960</b>
Ignition Leads 08.1984->	<b>85685</b>
<b>Passat (32B) 1.8</b>	<b>1986-88</b>
RM	64 87
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat (32B) 1.8</b>	<b>1983-88</b>
DS/JN/JV	66 90
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat (32B) 1.8</b>	<b>1983-88</b>
DZ	82 112
Ignition Leads	<b>83960</b>
<b>Passat (32B) 2.0</b>	<b>1983-88</b>
JS/HP	85 115
Ignition Leads M4	<b>83950</b>
Ignition Leads	<b>83960</b>
<b>Passat (32B) 2.2</b>	<b>1985-88</b>
KX	85 115
Ignition Leads	<b>83950</b>
<b>Passat (32B) 2.2</b>	<b>1985-88</b>
KV	100 136
Ignition Leads	<b>83950</b>
<b>Passat (362) 1.4 TSI</b>	<b>2010-&gt;</b>
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Passat (362) 1.4 TSI</b>	<b>2012-&gt;</b>
CTHD	118 160
Ignition Coil	<b>80201</b>
<b>Passat (362) 1.4 TSI EcoFuel</b>	<b>2010-&gt;</b>
CDGA	110 150
Ignition Coil	<b>80201</b>
<b>Passat (362) 1.4 TSI MultiFuel</b>	<b>2010-&gt;</b>
CKMA	118 160
Ignition Coil	<b>80201</b>
<b>Passat (362) 3.6 FSI 4motion</b>	<b>2011-14</b>
BWS	220 300
Ignition Coil	<b>80327</b>
<b>Passat (3A2, 35I) 1.6</b>	<b>1988-91</b>
EZ /1F	53 72
Ignition Coil EZ,1F	<b>80200</b>
Ignition Coil With regul.cat.(3way)	<b>80219</b>
Ignition Leads	<b>85685</b>
<b>Passat (3A2, 35I) 1.6</b>	<b>1988-88</b>
ABN/EZ	55 75
Ignition Coil EZ	<b>80200</b>
Ignition Coil EZ; Intake manifold injection	<b>80219</b>
Ignition Leads	<b>85685</b>

VOLKSWAGEN Cont.	
<b>Passat (3A2, 35I) 1.6</b>	<b>1994-96</b>
AEK/AFT	74 101
Ignition Coil AFT,AEK	<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
Ignition Leads	<b>85865</b>
Ignition Leads AEK	<b>85870</b>
<b>Passat (3A2, 35I) 1.8</b>	<b>1988-93</b>
PF	79 107
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat (3A2, 35I) 1.8</b>	<b>1988-92</b>
PB	82 112
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat (3A2, 35I) 1.8</b>	<b>1990-96</b>
AAM	55 75
Ignition Coil	<b>80200</b>
Ignition Coil With regul.cat.(3way)	<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ->09.1993	<b>85865</b>
<b>Passat (3A2, 35I) 1.8</b>	<b>1988-96</b>
RP/ADZ/ABS	66 90
Ignition Coil RP,ADZ,ABS	<b>80200</b>
Ignition Coil With regul.cat.(3way)	<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads ADZ	<b>85690</b>
Ignition Leads RP	<b>85865</b>
<b>Passat (3A2, 35I) 1.8 16V</b>	<b>1988-89</b>
KR	100 136
Ignition Leads	<b>85059</b>
<b>Passat (3A2, 35I) 1.8 G60 Syncro</b>	<b>1988-96</b>
PG	118 160
Ignition Leads	<b>85685</b>
<b>Passat (3A2, 35I) 2.0</b>	<b>1995-96</b>
AEP	79 107
Ignition Coil	<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads	<b>85690</b>
<b>Passat (3A2, 35I) 2.0</b>	<b>1990-96</b>
ABA/ADY/2E/AGG	85 115
Ignition Coil 3 term.	<b>80200</b>
Ignition Coil 6 term.	<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads 2E; ->09.1993	<b>85865</b>
<b>Passat (3A2, 35I) 2.0 16V</b>	<b>1994-96</b>
ABF	110 150
Ignition Coil 3 term.	<b>80200</b>
Ignition Coil 6 term.	<b>80219</b>
Ignition Leads	<b>85059</b>
<b>Passat (3A2, 35I) 2.0 Syncro</b>	<b>1990-96</b>
ADY/2E/AGG	85 115
Ignition Coil 2E; 3 term.	<b>80200</b>
Ignition Coil 2E; 6 term.	<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads 2E; ->07.1993	<b>85865</b>
<b>Passat (3A2, 35I) 2.8 VR6</b>	<b>1991-96</b>
AAA	128 174
Ignition Coil ->Ch.31-P-136 398	<b>80200</b>
Ignition Leads Ch.31-P-240001->	<b>85070</b>
<b>Passat (3B2) 1.6</b>	<b>1996-00</b>
AHL/ADP/ARM/ANA	74 101
Ignition Coil	<b>80218</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
Ignition Leads ADP	<b>85870</b>
Ignition Leads AHL/ANA/ARM	<b>85875</b>
<b>Passat (3B2) 1.8</b>	<b>1997-00</b>
AFY	85 115
Ignition Leads	<b>85682</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat (3B2) 1.8</b>	<b>1996-00</b>
ADR/APT/ARG	92 125
Ignition Coil	<b>80200</b>
Ignition Leads	<b>85682</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat (3B2) 1.8 Syncro/4motion</b>	<b>1996-00</b>
ADR/APT/ARG	92 125
Ignition Leads	<b>85682</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>



VOLKSWAGEN Cont.	
<b>Passat (3B2) 1.8 T</b>	1996-00
AEB/ANB/APU	110 150
Ignition Coil APU,ANB,AEB	<b>80252</b>
<b>Passat (3B2) 2.0</b>	2000-00
ASU/AUZ	88 120
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat (3B2) 2.0 4motion</b>	2000-00
ASU	88 120
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat (3B2) 2.8 V6</b>	1996-00
APR/ACK/AHA/AQD	142 193
Ignition Leads 01.1997->	<b>85062</b>
<b>Passat (3B2) 2.8 V6 Syncro/4motion</b>	1996-00
APR/ACK/ALG/AHA/AQD	142 193
Ignition Leads 06.1997->	<b>85062</b>
<b>Passat (3B3) 1.6</b>	2000-05
ALZ	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Passat (3B3) 1.8 T 20V</b>	2000-05
AWT/AWL	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>Passat (3B3) 2.0</b>	2000-05
AZM/BFF	85 115
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Passat (3B3) 2.0</b>	2001-05
ALT	96 130
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>Passat (3B3) 2.0 4motion</b>	2000-05
AZM	85 115
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Passat (3B3) 2.8 4motion</b>	2000-05
ATQ/AMX	142 193
Ignition Leads	<b>85062</b>
<b>Passat (3C2) 1.4 TSI</b>	2007-10
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Passat (3C2) 1.4 TSI EcoFuel</b>	2009-10
CDGA	110 150
Ignition Coil	<b>80201</b>
<b>Passat (3C2) 1.6</b>	2005-10
BSF/BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Passat (3C2) 1.6 FSI</b>	2005-08
BLF	85 115
Ignition Coil Direct Injection	<b>80201</b>
<b>Passat (3C2) 1.8 TSI</b>	2007-10
BZB/CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Passat (3C2) 2.0 FSI</b>	2005-10
BLY/BLR/BVZ/BVY	110 150
Ignition Coil BLY,BLR	<b>80240</b>
<b>Passat (3C2) 2.0 FSI</b>	2005-10
BWA/BPY/AXX/CBFA/CCZA/CAWB/CCTA	147 200
Ignition Coil BPY,AXX,BWA	<b>80240</b>
<b>Passat (3C2) 2.0 FSI 4motion</b>	2005-10
BVX/BLX/BLY	110 150
Ignition Coil BLX,BVX,BLY	<b>80240</b>
<b>Passat (3C2) 3.2 FSI 4motion</b>	2005-10
AXZ	184 250
Ignition Coil	<b>80327</b>
<b>Passat (3C2) 3.6 R36 4motion</b>	2007-10
BWS	220 300
Ignition Coil	<b>80327</b>
<b>Passat (3G2) 1.4 GTE Hybrid</b>	2015->
CUKC	115 156
Ignition Coil	<b>80249</b>
<b>Passat (3G2) 1.4 TSI</b>	2014->
CZEA/CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Passat (3G2) 1.4 TSI</b>	2014->
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Passat (3G2) 1.4 TSI 4motion</b>	2015->
CZEA	110 150
Ignition Coil	<b>80249</b>

VOLKSWAGEN Cont.	
<b>Passat Alltrack (3G5) 1.4 TSI 4motion</b>	2015->
CZEA	110 150
Ignition Coil	<b>80249</b>
<b>Passat CC (357) 1.4 TSI MultiFuel</b>	2011-12
CKMA	118 160
Ignition Coil	<b>80201</b>
<b>Passat CC (357) 1.8 TSI</b>	2008-12
BZB/CDAA	118 160
Ignition Coil	<b>80240</b>
<b>Passat CC (357) 2.0 TSI</b>	2008-12
CBFA/CCZA/CAWB/CCTA	147 200
Ignition Coil	<b>80240</b>
<b>Passat CC (357) 3.6 FSI 4motion</b>	2008-10
BWS	220 300
Ignition Coil	<b>80327</b>
<b>Passat Sedan (32B) 1.6</b>	1985-88
DT	55 75
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat Sedan (32B) 1.6</b>	1985-88
RL	53 72
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat Sedan (32B) 1.6</b>	1987-88
PP	51 69
Ignition Leads	<b>83960</b>
<b>Passat Sedan (32B) 1.8</b>	1985-88
DS/JN	66 90
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat Sedan (32B) 1.8</b>	1986-88
RM	64 87
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat Sedan (32B) 2.2</b>	1985-88
KX	85 115
Ignition Leads	<b>83950</b>
<b>Passat Variant (32B) 1.6</b>	1980-88
DT	55 75
Ignition Leads	<b>85685</b>
<b>Passat Variant (32B) 1.6</b>	1987-88
PP	51 70
Ignition Leads	<b>83960</b>
<b>Passat Variant (32B) 1.6</b>	1986-88
RL	53 72
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat Variant (32B) 1.6</b>	1980-88
WV/YN	55 75
Ignition Leads	<b>85685</b>
<b>Passat Variant (32B) 1.8</b>	1986-88
RM	64 87
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat Variant (32B) 1.8</b>	1983-88
DS/JN/JV	66 90
Ignition Leads	<b>85685</b>
<b>Passat Variant (32B) 1.8 Syncro</b>	1986-88
DS/JN	66 90
Ignition Leads	<b>83960</b>
Ignition Leads	<b>85685</b>
<b>Passat Variant (32B) 2.0</b>	1983-88
JS/HP	85 115
Ignition Leads	<b>83950</b>
<b>Passat Variant (32B) 2.0 Syncro</b>	1984-88
JS	85 116
Ignition Leads M4	<b>83950</b>
Ignition Leads	<b>83960</b>
<b>Passat Variant (32B) 2.2</b>	1985-88
KX	85 115
Ignition Leads	<b>83950</b>
<b>Passat Variant (32B) 2.2</b>	1985-88
KV	100 136
Ignition Leads	<b>83950</b>
<b>Passat Variant (32B) 2.2 Syncro</b>	1985-88
JT	88 120
Ignition Leads	<b>83950</b>





VOLKSWAGEN Cont.	
<b>Passat Variant (365) 1.4 TSI</b>	2010->
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Passat Variant (365) 1.4 TSI</b>	2012->
CTHD	118 160
Ignition Coil	<b>80201</b>
<b>Passat Variant (365) 1.4 TSI EcoFuel</b>	2010->
CDGA	110 150
Ignition Coil	<b>80201</b>
<b>Passat Variant (365) 1.4 TSI MultiFuel</b>	2010->
CKMA	118 160
Ignition Coil	<b>80201</b>
<b>Passat Variant (365) 3.6 FSI 4motion</b>	2011-14
BWS	220 300
Ignition Coil	<b>80327</b>
<b>Passat Variant (3A5, 35I) 1.6</b>	1988-91
EZ /1F	53 72
Ignition Coil EZ,1F	<b>80200</b>
Ignition Coil With regul.cat.(3way)	<b>80219</b>
Ignition Leads ->07.1990	<b>85685</b>
Ignition Leads EZ	<b>85690</b>
Ignition Leads 1F	<b>85865</b>
<b>Passat Variant (3A5, 35I) 1.6</b>	1988-88
EZ	55 75
Ignition Coil	<b>80200</b>
Ignition Coil Intake manifold injection	<b>80219</b>
Ignition Leads	<b>85685</b>
<b>Passat Variant (3A5, 35I) 1.6</b>	1994-95
AEK/AFT	74 101
Ignition Coil AEK,AFT	<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
Ignition Leads	<b>85865</b>
Ignition Leads AEK	<b>85870</b>
<b>Passat Variant (3A5, 35I) 1.8</b>	1988-90
PF	79 107
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat Variant (3A5, 35I) 1.8</b>	1988-92
PB	82 112
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat Variant (3A5, 35I) 1.8</b>	1990-97
AAM	55 75
Ignition Coil	<b>80200</b>
Ignition Coil With regul.cat.(3way)	<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads 10.1993->	<b>85690</b>
Ignition Leads ->09.1993	<b>85865</b>
<b>Passat Variant (3A5, 35I) 1.8</b>	1988-97
RP/ADZ/ABS	66 90
Ignition Coil ABS,RP,ADZ	<b>80200</b>
Ignition Coil With regul.cat.(3way)	<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads ABS/RP; ->09.1993	<b>85865</b>
<b>Passat Variant (3A5, 35I) 1.8 16V</b>	1988-89
KR	100 136
Ignition Leads	<b>85059</b>
<b>Passat Variant (3A5, 35I) 1.8 G60 Syncro</b>	1988-97
PG	118 160
Ignition Leads	<b>85685</b>
<b>Passat Variant (3A5, 35I) 2.0</b>	1995-96
AEP	79 107
Ignition Coil	<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads	<b>85690</b>
<b>Passat Variant (3A5, 35I) 2.0</b>	1990-97
ADY/2E/AGG	85 115
Ignition Coil 3 term.	<b>80200</b>
Ignition Coil 6 term.; 2E	<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads	<b>85690</b>
Ignition Leads 2E; ->09.1993	<b>85865</b>
<b>Passat Variant (3A5, 35I) 2.0 16V</b>	1994-97
ABF	110 150
Ignition Coil 3 term.	<b>80200</b>
Ignition Coil 6 term.; ->03.1997	<b>80219</b>
Ignition Leads	<b>85059</b>

VOLKSWAGEN Cont.	
<b>Passat Variant (3A5, 35I) 2.0 Syncro</b>	1990-97
ADY/2E/AGG	85 115
Ignition Coil 2E; 3 term.	<b>80200</b>
Ignition Coil 2E; 6 term.	<b>80219</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads	<b>85690</b>
<b>Passat Variant (3A5, 35I) 2.8 VR6</b>	1991-97
AAA	128 174
Ignition Coil ->Ch.31-P-136 398	<b>80200</b>
Ignition Leads Ch.AAA->	<b>85070</b>
<b>Passat Variant (3A5, 35I) 2.9 VR6 Syncro</b>	1994-97
ABV	135 184
Ignition Leads ABV	<b>85070</b>
<b>Passat Variant (3B5) 1.6</b>	1997-00
AHL/ADP/ARM/ANA	74 101
Ignition Coil	<b>80218</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
Ignition Leads ADP	<b>85870</b>
Ignition Leads AHL/ANA/ARM	<b>85875</b>
<b>Passat Variant (3B5) 1.8</b>	1997-00
AFY	85 115
Ignition Leads	<b>85682</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat Variant (3B5) 1.8</b>	1997-00
ADR/APT/ARG	92 125
Ignition Leads	<b>85682</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat Variant (3B5) 1.8 Syncro/4motion</b>	1997-00
ADR/APT/ARG	92 125
Ignition Leads	<b>85682</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat Variant (3B5) 1.8 T</b>	1997-00
AEB/ANB/APU	110 150
Ignition Coil ->12.1998	<b>80252</b>
<b>Passat Variant (3B5) 2.0</b>	2000-00
ASU/AUZ	88 120
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat Variant (3B5) 2.0 4motion</b>	2000-00
ASU/AUZ	88 120
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
<b>Passat Variant (3B5) 2.8 V6</b>	1997-00
APR/ACK/AHA/AQD	142 193
Ignition Leads	<b>85062</b>
<b>Passat Variant (3B5) 2.8 V6 Syncro/4motion</b>	1997-00
APR/ACK/ALG/AHA/AQD	142 193
Ignition Leads ->08.2000	<b>85062</b>
<b>Passat Variant (3B6) 1.6</b>	2000-05
ALZ	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Passat Variant (3B6) 1.8 T 20V</b>	2000-05
AWT	110 150
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>Passat Variant (3B6) 2.0</b>	2000-05
AZM	85 115
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Passat Variant (3B6) 2.0</b>	2001-05
ALT	96 130
Ignition Coil With regul.cat.(3way)	<b>80202</b>
<b>Passat Variant (3B6) 2.0 4motion</b>	2000-05
AZM	85 115
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Passat Variant (3B6) 2.8 4motion</b>	2000-05
ATQ/AMX	142 193
Ignition Leads	<b>85062</b>
<b>Passat Variant (3C5) 1.4 TSI</b>	2007-10
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Passat Variant (3C5) 1.4 TSI EcoFuel</b>	2009-10
CDGA	110 150
Ignition Coil	<b>80201</b>
<b>Passat Variant (3C5) 1.6</b>	2005-10
BSF/BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>



VOLKSWAGEN Cont.	
<b>Passat Variant (3C5) 1.6 FSI</b>	<b>2005-08</b>
BLF	85 115
Ignition Coil Direct Injection	<b>80201</b>
<b>Passat Variant (3C5) 1.8 TSI</b>	<b>2007-11</b>
BZB/CDA	118 160
Ignition Coil	<b>80240</b>
<b>Passat Variant (3C5) 2.0 FSI</b>	<b>2005-10</b>
BLY/BLR/BVZ/BVY	110 150
Ignition Coil BLY,BLR	<b>80240</b>
<b>Passat Variant (3C5) 2.0 FSI</b>	<b>2005-10</b>
BWA/BPY/AXX/CBFA/CCZA/CAWB/CCTA	147 200
Ignition Coil	<b>80240</b>
<b>Passat Variant (3C5) 2.0 FSI 4motion</b>	<b>2005-10</b>
BVX/BLX/BLY	110 150
Ignition Coil BVX,BLX,BLY	<b>80240</b>
<b>Passat Variant (3C5) 3.2 FSI 4motion</b>	<b>2005-10</b>
AXZ	184 250
Ignition Coil	<b>80327</b>
<b>Passat Variant (3C5) 3.6 R36 4motion</b>	<b>2007-10</b>
BWS	220 300
Ignition Coil	<b>80327</b>
<b>Passat Variant (3G5) 1.4 GTE Hybrid</b>	<b>2015-&gt;</b>
CUKC	115 156
Ignition Coil	<b>80249</b>
<b>Passat Variant (3G5) 1.4 TSI</b>	<b>2014-&gt;</b>
CZEA/CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Passat Variant (3G5) 1.4 TSI</b>	<b>2014-&gt;</b>
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Passat Variant (3G5) 1.4 TSI 4motion</b>	<b>2015-&gt;</b>
CZEA	110 150
Ignition Coil	<b>80249</b>
<b>Phaeton (3D) 3.2 V6</b>	<b>2002-05</b>
AYT/BKL	177 241
Ignition Coil	<b>80327</b>
<b>Phaeton (3D) 3.2 V6 4motion</b>	<b>2004-08</b>
BRK/BKL	177 241
Ignition Coil	<b>80327</b>
<b>Polo (6N1) 100 1.4 16V</b>	<b>1996-99</b>
AFH	74 100
Ignition Coil	<b>80200</b>
Ignition Leads AFH	<b>85695</b>
<b>Polo (6N1) 120 1.6 16V GTI</b>	<b>1998-99</b>
AJV	88 120
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Polo (6N1) 45 1.0</b>	<b>1994-96</b>
AEV	33 45
Ignition Coil	<b>80200</b>
Ignition Leads	<b>85693</b>
<b>Polo (6N1) 50 1.0</b>	<b>1996-99</b>
AER/ALL	37 50
Ignition Coil AER,ALL	<b>80200</b>
Ignition Leads ->Ch.6N-W-000001	<b>85691</b>
<b>Polo (6N1) 55 1.3</b>	<b>1994-95</b>
ADX	40 55
Ignition Coil	<b>80200</b>
Ignition Leads	<b>85693</b>
<b>Polo (6N1) 55 1.4</b>	<b>1995-99</b>
AEX	40 55
Ignition Coil	<b>80200</b>
Ignition Leads Ch.6N-W-000001->	<b>85691</b>
<b>Polo (6N1) 60 1.4</b>	<b>1995-99</b>
AEX/AKV/APQ	44 60
Ignition Coil AEX,APQ,AKV	<b>80200</b>
Ignition Leads AEX/AKV	<b>85691</b>
Ignition Leads AEX	<b>85692</b>
Ignition Leads APQ	<b>85693</b>
<b>Polo (6N1) 75 1.6</b>	<b>1994-99</b>
AEA/AEE/AHS	55 75
Ignition Coil AEA,AEE,AHS	<b>80200</b>
Ignition Leads AHS/AEE; ->Ch.6N-W-000001	<b>85691</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85692</b>
Ignition Leads	<b>85693</b>
<b>Polo (6N2) 1.0</b>	<b>1999-01</b>
ALD/AUC	37 50
Ignition Coil	<b>80218</b>
Ignition Leads Ch.6N-Y-050 001->	<b>85681</b>

VOLKSWAGEN Cont.	
<b>Polo (6N2) 1.4</b>	<b>1999-01</b>
AKK/AUD	44 60
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85681</b>
<b>Polo (6N2) 1.4</b>	<b>1999-01</b>
ANX/AKP	40 54
Ignition Coil AKP	<b>80218</b>
Ignition Leads AKP; Ch.6N-Y-050 001->	<b>85681</b>
<b>Polo (6N2) 1.4 16V</b>	<b>1999-01</b>
AHW/APE/AUA	55 75
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Polo (6N2) 1.4 16V</b>	<b>1999-01</b>
AFK/AUB/AQQ	74 101
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Polo (6N2) 1.6 16V GTI</b>	<b>1999-01</b>
AVY/ARC	92 125
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85696</b>
<b>Polo (6R, 6C) 1.0</b>	<b>2014-&gt;</b>
CHYA	44 60
Ignition Coil	<b>80249</b>
<b>Polo (6R, 6C) 1.0</b>	<b>2014-&gt;</b>
CHYB	55 75
Ignition Coil	<b>80249</b>
<b>Polo (6R, 6C) 1.0 TSI</b>	<b>2014-&gt;</b>
CHZB	70 95
Ignition Coil	<b>80249</b>
<b>Polo (6R, 6C) 1.0 TSI</b>	<b>2014-&gt;</b>
CHZC	81 110
Ignition Coil	<b>80249</b>
<b>Polo (6R, 6C) 1.2</b>	<b>2009-&gt;</b>
CGPB	44 60
Ignition Coil	<b>80201</b>
<b>Polo (6R, 6C) 1.2</b>	<b>2009-&gt;</b>
CGPA	51 70
Ignition Coil	<b>80201</b>
<b>Polo (6R, 6C) 1.2 TSI</b>	<b>2014-&gt;</b>
CJZD	81 110
Ignition Coil	<b>80249</b>
<b>Polo (6R, 6C) 1.2 TSI</b>	<b>2011-14</b>
CBZC	66 90
Ignition Coil ->02.2014	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Polo (6R, 6C) 1.2 TSI</b>	<b>2009-&gt;</b>
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Polo (6R, 6C) 1.2 TSI 16V</b>	<b>2014-&gt;</b>
CJZC	66 90
Ignition Coil	<b>80249</b>
<b>Polo (6R, 6C) 1.4</b>	<b>2009-&gt;</b>
CGGB/CLPA/CDDA	63 85
Ignition Coil	<b>80201</b>
<b>Polo (6R, 6C) 1.4 BiFuel</b>	<b>2010-11</b>
CMAA	60 82
Ignition Coil	<b>80201</b>
<b>Polo (6R, 6C) 1.4 GTI</b>	<b>2010-&gt;</b>
CAVE/CTHE	132 180
Ignition Coil	<b>80201</b>
<b>Polo (6R, 6C) 1.4 TSI</b>	<b>2014-&gt;</b>
CZEA	110 150
Ignition Coil	<b>80249</b>
<b>Polo (6R, 6C) 1.4 TSI</b>	<b>2012-&gt;</b>
CPTA	103 140
Ignition Coil ->02.2014	<b>80249</b>
<b>Polo (6R, 6C) 1.6 BiFuel</b>	<b>2011-&gt;</b>
CNKA	60 82
Ignition Coil ->02.2014	<b>80201</b>
<b>Polo (86) 0.8</b>	<b>1975-81</b>
HE	25 34
Ignition Leads	<b>83720</b>
<b>Polo (86) 0.9</b>	<b>1975-81</b>
HA	29 40
Ignition Leads	<b>83720</b>
<b>Polo (86) 1.1</b>	<b>1975-81</b>
HB	37 50
Ignition Leads	<b>83720</b>



VOLKSWAGEN Cont.		
<b>Polo (86) 1.1</b>		<b>1975-81</b>
HC	44	60
Ignition Leads		<b>83720</b>
<b>Polo (86C, 80) 1.0</b>		<b>1981-86</b>
GL	29	40
Ignition Leads		<b>85685</b>
<b>Polo (86C, 80) 1.0</b>		<b>1985-92</b>
HZ	33	45
Ignition Coil 3 term.; 10.1990->		<b>80200</b>
Ignition Coil 6 term.; 10.1990->; With unregulated cat.		<b>80219</b>
Ignition Leads		<b>83979</b>
Ignition Leads		<b>85685</b>
<b>Polo (86C, 80) 1.0 KAT</b>		<b>1989-94</b>
AAU/AAK/ACM	33	45
Ignition Coil 3 term.; AAU; 10.1990->		<b>80200</b>
Ignition Coil 6 term.; ACM; 02.1992-12.1992; With regul.cat.(3way)		<b>80219</b>
Ignition Leads		<b>85685</b>
<b>Polo (86C, 80) 1.3</b>		<b>1983-88</b>
MH/HK	40	55
Ignition Leads		<b>83979</b>
Ignition Leads		<b>85685</b>
<b>Polo (86C, 80) 1.3 KAT</b>		<b>1987-94</b>
NZ/2G/MH/AAV	40	55
Ignition Coil 3 term.; AAV,2G,NZ; 10.1990->		<b>80200</b>
Ignition Coil 6 term.; 2G,NZ; 10.1990->; With regul.cat.(3way)		<b>80219</b>
Ignition Leads		<b>83979</b>
Ignition Leads 2G/MH (KAT)/NZ		<b>85685</b>
<b>Polo (86C, 80) 1.3 KAT</b>		<b>1989-91</b>
3F	55	75
Ignition Coil		<b>80200</b>
Ignition Leads		<b>83979</b>
<b>Polo (9N) 1.2</b>		<b>2002-07</b>
AWY/BMD	40	54
Ignition Coil		<b>80326</b>
<b>Polo (9N) 1.2</b>		<b>2007-09</b>
BBM	44	60
Ignition Coil		<b>80326</b>
<b>Polo (9N) 1.2 12V</b>		<b>2001-07</b>
AZQ/BME	47	64
Ignition Coil ->04.2005		<b>80201</b>
<b>Polo (9N) 1.2 12V</b>		<b>2007-09</b>
BZG	51	69
Ignition Coil Intake manifold injection		<b>80201</b>
<b>Polo (9N) 1.4 16V</b>		<b>2001-08</b>
BBY/BKY/AUA	55	75
Ignition Coil ->07.2007		<b>80201</b>
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Polo (9N) 1.4 16V</b>		<b>2001-08</b>
BBZ/AUB	74	101
Ignition Coil ->05.2007		<b>80201</b>
Ignition Leads		<b>85696</b>
<b>Polo (9N) 1.4 16V</b>		<b>2006-09</b>
BUD	59	80
Ignition Coil Intake manifold injection		<b>80201</b>
<b>Polo (9N) 1.4 FSI</b>		<b>2002-06</b>
AXU	63	86
Ignition Coil		<b>80201</b>
<b>Polo (9N) 1.6</b>		<b>2002-05</b>
BAH	74	101
Ignition Leads		<b>85697</b>
<b>Polo (9N) 1.6 16V</b>		<b>2006-09</b>
BTS	77	105
Ignition Coil Intake manifold injection		<b>80201</b>
<b>Polo (9N) 1.8 GTI</b>		<b>2005-09</b>
BJX	110	150
Ignition Coil		<b>80202</b>
<b>Polo (9N) 1.8 GTI Cup Edition</b>		<b>2006-09</b>
BBU	132	180
Ignition Coil		<b>80202</b>
<b>Polo Classic (6KV2) 100 1.6</b>		<b>1995-01</b>
AKL/APF/AEH/AUR/AFT	74	100
Ignition Coil AFT; ->08.1999		<b>80200</b>
Ignition Coil AEH/AKL/APF/AUR; 10.1999->		<b>80218</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
Ignition Leads AFT		<b>85865</b>
Ignition Leads AEH/AKL		<b>85875</b>

VOLKSWAGEN Cont.		
<b>Polo Classic (6KV2) 60 1.4</b>		<b>1995-01</b>
AEX/AKV/ANW/AKK/APQ/AUD	44	60
Ignition Coil With regul.cat.(3way)		<b>80200</b>
Ignition Coil		<b>80218</b>
Ignition Leads AUD		<b>85681</b>
Ignition Leads		<b>85692</b>
Ignition Leads AEX		<b>85693</b>
<b>Polo Classic (6KV2) 75 1.4 16V</b>		<b>1999-01</b>
APE/AUA	55	75
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Polo Classic (6KV2) 75 1.6</b>		<b>1995-97</b>
1F	55	75
Ignition Coil		<b>80200</b>
Ignition Leads 1F		<b>85685</b>
Ignition Leads		<b>85690</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
<b>Polo Classic (6KV2) 75 1.6</b>		<b>1995-01</b>
ALM/AEE	55	75
Ignition Coil AEE,ALM		<b>80200</b>
Ignition Leads		<b>85685</b>
Ignition Leads ALM		<b>85690</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
Ignition Leads AEE		<b>85693</b>
<b>Polo Classic (6KV2) 90 1.8</b>		<b>1997-01</b>
ADZ/ADD/ABS	66	90
Ignition Coil ADZ,ADD		<b>80200</b>
<b>Polo Classic (86C, 80) 1.0</b>		<b>1985-86</b>
GL	29	40
Ignition Leads		<b>83979</b>
Ignition Leads		<b>85685</b>
<b>Polo Classic (86C, 80) 1.0</b>		<b>1985-94</b>
AAU/HZ/AAK	33	45
Ignition Coil AAU, HZ; 3 term.; 10.1990->		<b>80200</b>
Ignition Coil HZ; 6 term.; 10.1990-01.1992; With unregulated cat.		<b>80219</b>
Ignition Leads		<b>83979</b>
Ignition Leads HZ		<b>85685</b>
<b>Polo Classic (86C, 80) 1.3</b>		<b>1985-87</b>
MH/HK	40	55
Ignition Leads		<b>83979</b>
Ignition Leads		<b>85685</b>
<b>Polo Classic (86C, 80) 1.3 KAT</b>		<b>1987-94</b>
NZ/MH	40	55
Ignition Coil NZ; 3 term.; 10.1990-12.1992		<b>80200</b>
Ignition Coil NZ; 6 term.; 10.1990-12.1992; With regul.cat.(3way)		<b>80219</b>
Ignition Leads		<b>83979</b>
Ignition Leads		<b>85685</b>
<b>Polo Coupe (86C, 80) 1.0</b>		<b>1982-86</b>
GL	29	40
Ignition Leads		<b>83979</b>
<b>Polo Coupe (86C, 80) 1.0</b>		<b>1985-92</b>
HZ	33	45
Ignition Coil 3 term.; 10.1990->		<b>80200</b>
Ignition Coil 6 term.; 10.1990->; With unregulated cat.		<b>80219</b>
Ignition Leads		<b>83979</b>
Ignition Leads		<b>85685</b>
<b>Polo Coupe (86C, 80) 1.0 KAT</b>		<b>1989-94</b>
AAU/AAK/ACM	33	45
Ignition Coil 3 term.; AAU,ACM; 10.1990->		<b>80200</b>
Ignition Coil ACM; 6 term.; With regul.cat.(3way); 02.1992-12.1992		<b>80219</b>
Ignition Leads		<b>83979</b>
Ignition Leads AAK/AAU		<b>85685</b>
<b>Polo Coupe (86C, 80) 1.3</b>		<b>1991-94</b>
3F	57	78
Ignition Coil		<b>80200</b>
<b>Polo Coupe (86C, 80) 1.3</b>		<b>1983-87</b>
MH/HK	40	55
Ignition Leads		<b>83979</b>
Ignition Leads		<b>85685</b>
<b>Polo Coupe (86C, 80) 1.3</b>		<b>1982-89</b>
GK	55	75
Ignition Leads		<b>83979</b>
<b>Polo Coupe (86C, 80) 1.3 G40</b>		<b>1987-90</b>
PY	85	115
Ignition Leads PY		<b>85685</b>
<b>Polo Coupe (86C, 80) 1.3 G40</b>		<b>1990-94</b>
PY	83	113
Ignition Coil		<b>80200</b>
Ignition Leads PY		<b>85685</b>



VOLKSWAGEN Cont.		
<b>Polo Coupe (86C, 80) 1.3 KAT</b>		<b>1987-94</b>
NZ/2G/MH/AAV		40 55
Ignition Coil 3 term.; NZ,2G,AAV; 10.1990->		<b>80200</b>
Ignition Coil NZ,2G; 6 term.; With regul.cat.(3way); 10.1990->		<b>80219</b>
Ignition Leads 2G/MH (KAT)/NZ		<b>85685</b>
<b>Polo Coupe (86C, 80) 1.3 KAT</b>		<b>1989-94</b>
3F		55 75
Ignition Coil		<b>80200</b>
Ignition Leads		<b>83979</b>
<b>Polo Sedan (9A4) 1.4</b>		<b>2003-&gt;</b>
BBY/BKY		55 75
Ignition Coil BBY; Intake manifold injection		<b>80201</b>
<b>Polo Sedan (9A4) 1.4</b>		<b>2003-&gt;</b>
BBZ		74 101
Ignition Coil ->Ch.9N5P017000; ->11.2004; Intake manifold		<b>80201</b>
<b>Polo Sedan (9A4) 1.6</b>		<b>2002-&gt;</b>
BPA/CFZA/BAH		74 101
Ignition Leads		<b>85697</b>
<b>Polo Van (6NF) 1.0</b>		<b>1994-99</b>
AEV		33 45
Ignition Coil		<b>80200</b>
Ignition Leads AAU		<b>85685</b>
<b>Polo Van (6NF) 1.4</b>		<b>1998-99</b>
AEX/APQ		44 60
Ignition Coil APQ,AEX		<b>80200</b>
Ignition Leads APQ		<b>85692</b>
Ignition Leads AEX		<b>85693</b>
<b>Polo Van (6R) 1.0</b>		<b>2014-&gt;</b>
CHYA		44 60
Ignition Coil 02.2014->		<b>80249</b>
<b>Polo Van (6R) 1.0</b>		<b>2014-&gt;</b>
CHYB		55 75
Ignition Coil 02.2014->		<b>80249</b>
<b>Polo Van (6R) 1.0 TSI</b>		<b>2014-&gt;</b>
CHZB		70 95
Ignition Coil		<b>80249</b>
<b>Polo Van (6R) 1.2 TSI</b>		<b>2014-&gt;</b>
CJZC		66 90
Ignition Coil		<b>80249</b>
<b>Polo Van (6R) 1.2 TSI</b>		<b>2014-&gt;</b>
CJZD		81 110
Ignition Coil 02.2014->		<b>80249</b>
<b>Polo Van (6R) 1.4 TSI</b>		<b>2014-&gt;</b>
CZEA		110 150
Ignition Coil		<b>80249</b>
<b>Polo Van (86CF) 1.0</b>		<b>1992-94</b>
AAU		33 45
Ignition Coil		<b>80200</b>
Ignition Leads AAU		<b>85685</b>
<b>Polo Van (86CF) 1.3</b>		<b>1992-94</b>
AAV		40 54
Ignition Coil 3 term.		<b>80200</b>
Ignition Coil 6 term.		<b>80219</b>
<b>Polo Variant (6KV5) 1.4</b>		<b>1998-01</b>
AKP		40 54
Ignition Coil		<b>80218</b>
Ignition Leads Ch.6N-Y-050 001->		<b>85681</b>
<b>Polo Variant (6KV5) 1.4</b>		<b>1997-01</b>
AEX/AKV/ANW/AKK/APQ/AUD		44 60
Ignition Coil		<b>80200</b>
Ignition Coil		<b>80218</b>
Ignition Leads AUD		<b>85681</b>
Ignition Leads		<b>85692</b>
Ignition Leads AEX		<b>85693</b>
<b>Polo Variant (6KV5) 1.4 16V</b>		<b>1999-01</b>
APE/AUA		55 75
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85696</b>
<b>Polo Variant (6KV5) 1.6</b>		<b>1997-01</b>
ALM/AEE		55 75
Ignition Coil ALM,AEE		<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
Ignition Leads		<b>85693</b>

VOLKSWAGEN Cont.		
<b>Polo Variant (6KV5) 1.6</b>		<b>1997-01</b>
AKL/APF/AEH/AUR/AFT		74 101
Ignition Coil AFT		<b>80200</b>
Ignition Coil AEH/AKL/APF/AUR		<b>80218</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
Ignition Leads AFT		<b>85685</b>
Ignition Leads		<b>85875</b>
<b>Polo Variant (6KV5) 1.8</b>		<b>1997-01</b>
ADZ		66 90
Ignition Coil		<b>80200</b>
<b>Santana (32B) 1.3</b>		<b>1981-83</b>
FZ		44 60
Ignition Leads		<b>83960</b>
<b>Santana (32B) 1.6</b>		<b>1981-84</b>
WV		55 75
Ignition Leads		<b>83960</b>
<b>Santana (32B) 1.6</b>		<b>1981-82</b>
YP		63 85
Ignition Leads		<b>83960</b>
<b>Santana (32B) 1.6</b>		<b>1981-84</b>
DT		55 75
Ignition Leads		<b>83960</b>
Ignition Leads 08.1984->		<b>85685</b>
<b>Santana (32B) 1.8</b>		<b>1983-84</b>
DS		66 90
Ignition Leads		<b>85685</b>
<b>Santana (32B) 2.0</b>		<b>1983-84</b>
JS/HP		85 115
Ignition Leads		<b>83950</b>
<b>Scirocco (137, 138) 1.4 TSI</b>		<b>2015-&gt;</b>
CZDA		110 150
Ignition Coil		<b>80249</b>
<b>Scirocco (137, 138) 1.4 TSI</b>		<b>2008-&gt;</b>
CTKA/CAVD/CTHD/CNWA		118 160
Ignition Coil		<b>80201</b>
<b>Scirocco (137, 138) 1.4 TSI</b>		<b>2008-&gt;</b>
CMSB/CAXA		90 122
Ignition Coil		<b>80201</b>
<b>Scirocco (137, 138) 2.0 R</b>		<b>2009-&gt;</b>
CDLA		195 265
Ignition Coil		<b>80240</b>
<b>Scirocco (137, 138) 2.0 TSI</b>		<b>2008-09</b>
CAWB		147 200
Ignition Coil		<b>80240</b>
<b>Scirocco (137, 138) 2.0 TSI</b>		<b>2009-&gt;</b>
CCZB		155 210
Ignition Coil		<b>80240</b>
<b>Scirocco (53) 1.3</b>		<b>1979-80</b>
GF		44 60
Ignition Leads		<b>83960</b>
<b>Scirocco (53) 1.5</b>		<b>1977-80</b>
JB		51 70
Ignition Leads		<b>83960</b>
<b>Scirocco (53) 1.5</b>		<b>1974-75</b>
FH		51 70
Ignition Leads		<b>83960</b>
<b>Scirocco (53) 1.5</b>		<b>1974-77</b>
FD		63 86
Ignition Leads		<b>83960</b>
<b>Scirocco (53) 1.5</b>		<b>1974-75</b>
ZB/YJ		55 75
Ignition Leads		<b>83960</b>
<b>Scirocco (53) 1.6</b>		<b>1975-79</b>
FN/FP		55 75
Ignition Leads		<b>83960</b>
<b>Scirocco (53) 1.6</b>		<b>1975-80</b>
FR		63 85
Ignition Leads		<b>83960</b>
<b>Scirocco (53) 1.6</b>		<b>1976-80</b>
EG		81 110
Ignition Leads		<b>83960</b>
<b>Scirocco (53B) 1.6</b>		<b>1983-89</b>
EW		55 75
Ignition Leads 08.1984->		<b>85685</b>
Ignition Leads Ch.53-E-056001->		<b>85690</b>
Ignition Leads Ch.53-E-046001->		<b>85685</b>
<b>Scirocco (53B) 1.6</b>		<b>1980-82</b>
EG		81 110
Ignition Leads		<b>83960</b>





VOLKSWAGEN Cont.	
<b>Scirocco (53B) 1.6</b>	1986-90
RE	53 72
Ignition Leads	<b>85685</b>
<b>Scirocco (53B) 1.6</b>	1983-84
EWA	51 70
Ignition Leads Ch.53-E-056001->	<b>85690</b>
Ignition Leads Ch.53-E-046001->	<b>85865</b>
<b>Scirocco (53B) 1.8</b>	1983-92
EX	66 90
Ignition Leads 08.1984->	<b>85685</b>
Ignition Leads Ch.53-E-056001->	<b>85690</b>
Ignition Leads Ch.53-E-046001->	<b>85865</b>
<b>Scirocco (53B) 1.8</b>	1985-92
JH	70 95
Ignition Leads	<b>85685</b>
Ignition Leads Ch.53-E-056001->	<b>85690</b>
Ignition Leads Ch.53-E-046001->	<b>85865</b>
<b>Scirocco (53B) 1.8</b>	1982-89
EV/JJ/PB/DX	82 112
Ignition Leads 08.1984->	<b>85685</b>
Ignition Leads Ch.53-E-056001->	<b>85690</b>
Ignition Leads Ch.53-E-046001->	<b>85865</b>
<b>Scirocco (53B) 1.8 16V</b>	1985-89
KR	102 139
Ignition Leads	<b>85059</b>
<b>Sharan (7M8, 7M9, 7M6) 1.8 T 20V</b>	1997-10
AWC/AJH	110 150
Ignition Coil AWC; 04.2000->	<b>80239</b>
Ignition Coil AJH; ->03.2000	<b>80252</b>
<b>Sharan (7M8, 7M9, 7M6) 2.0</b>	1995-10
ATM/ADY	85 115
Ignition Coil With regul.cat.(3way)	<b>80200</b>
Ignition Coil	<b>80218</b>
Ignition Leads ->Ch.6KZR510001, ZR010001	<b>85685</b>
Ignition Leads ADY	<b>85865</b>
<b>Sharan (7M8, 7M9, 7M6) 2.0 LPG</b>	2006-10
ATM	85 115
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
<b>Sharan (7M8, 7M9, 7M6) 2.8 VR6</b>	1995-00
AAA/AMY	128 174
Ignition Leads AAA; ->Ch.7M-V-060000	<b>85070</b>
<b>Sharan (7M8, 7M9, 7M6) 2.8 VR6 Syncro</b>	1996-00
AAA/AMY	128 174
Ignition Leads AAA; ->Ch.7M-V-060000	<b>85070</b>
<b>Sharan (7N) 1.4 TSI</b>	2010->
CTHA/CNWB/CAVA	110 150
Ignition Coil	<b>80201</b>
<b>Sharan (7N) 2.0 TSI</b>	2010->
CCZA	147 200
Ignition Coil	<b>80240</b>
<b>Sharan (7N1, 7N2) 1.4 TSI</b>	2015->
CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Tiguan (5N) 1.4 TSI</b>	2011->
CAVD/CTHD	118 160
Ignition Coil ->12.2016	<b>80201</b>
<b>Tiguan (5N) 1.4 TSI</b>	2015->
CZDB	92 125
Ignition Coil	<b>80249</b>
<b>Tiguan (5N) 1.4 TSI</b>	2015->
CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Tiguan (5N) 1.4 TSI</b>	2008->
BWK/CTHA/CAVA	110 150
Ignition Coil	<b>80201</b>
<b>Tiguan (5N) 1.4 TSI</b>	2010->
CAXA	90 122
Ignition Coil	<b>80201</b>
<b>Tiguan (5N) 1.4 TSI 4motion</b>	2011->
CAVD/CTHD	118 160
Ignition Coil ->12.2016	<b>80201</b>
<b>Tiguan (5N) 1.4 TSI 4motion</b>	2007->
BWK/CTHA/CAVA	110 150
Ignition Coil Direct Injection	<b>80201</b>
<b>Tiguan (5N) 2.0 TFSI 4motion</b>	2007->
CCZA/CAWB/CCTA	147 200
Ignition Coil	<b>80240</b>

VOLKSWAGEN Cont.	
<b>Tiguan (5N) 2.0 TFSI 4motion</b>	2007->
CAWA/CCZC	125 170
Ignition Coil	<b>80240</b>
<b>Tiguan (AD1) 1.4 TSI</b>	2016->
CZCA	92 125
Ignition Coil	<b>80249</b>
<b>Tiguan (AD1) 1.4 TSI</b>	2016->
CZEA/CZDA	110 150
Ignition Coil	<b>80249</b>
<b>Tiguan (AD1) 1.4 TSI 4motion</b>	2016->
CZEA/CZDA	110 150
Ignition Coil CZEA; ->05.2016	<b>80249</b>
<b>Touareg (7LA, 7L6, 7L7) 3.2 V6</b>	2002-06
AZZ/BMV/BKJ/BAA/BMX/BRJ	162 220
Ignition Coil ->06.2005	<b>80327</b>
<b>Touareg (7LA, 7L6, 7L7) 3.2 V6</b>	2004-06
BMV	177 241
Ignition Coil	<b>80327</b>
<b>Touareg (7LA, 7L6, 7L7) 3.6 V6 FSI</b>	2005-10
BHL/BHK	206 280
Ignition Coil	<b>80327</b>
<b>Touareg (7LA, 7L6, 7L7) 4.2 V8 FSI</b>	2006-10
BAR	257 350
Ignition Coil	<b>80240</b>
Ignition Coil OE N° 06E 905 115 E	<b>80248</b>
<b>Touareg (7P5) 3.0 V6 TSI Hybrid</b>	2010->
CGFA/CGEA	245 333
Ignition Coil	<b>80248</b>
<b>Touareg (7P5) 3.6 V6 FSI</b>	2010->
CGRA	206 280
Ignition Coil	<b>80248</b>
Ignition Coil	<b>80327</b>
<b>Touareg (7P5) 4.2 V8 FSI</b>	2011->
CGNA	265 360
Ignition Coil	<b>80248</b>
<b>Touran (1T1, 1T2) 1.4 FSI</b>	2006-10
BLG/CAVB	125 170
Ignition Coil	<b>80201</b>
<b>Touran (1T1, 1T2) 1.4 TSI</b>	2006-10
BMV/CAVC	103 140
Ignition Coil BMV; Direct Injection	<b>80201</b>
<b>Touran (1T1, 1T2) 1.4 TSI EcoFuel</b>	2009-10
CDGA	110 150
Ignition Coil	<b>80201</b>
<b>Touran (1T1, 1T2) 1.6</b>	2003-10
BGU/BSF/BSE	75 102
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85875</b>
Ignition Leads	<b>85879</b>
<b>Touran (1T1, 1T2) 1.6 FSI</b>	2003-07
BLF/BLP/BAG	85 115
Ignition Coil Direct Injection	<b>80201</b>
<b>Touran (1T1, 1T2) 2.0 EcoFuel</b>	2006-09
BSX	80 109
Ignition Coil	<b>80270</b>
Ignition Leads	<b>85874</b>
<b>Touran (1T1, 1T2) 2.0 FSI</b>	2003-07
BLX/BLY/BLR/AXW/BVZ/BVY	110 150
Ignition Coil BLR,AXW,BLY,BLX	<b>80240</b>
<b>Touran (1T3) 1.2 TSI</b>	2010->
CBZB	77 105
Ignition Coil	<b>80218</b>
Ignition Leads	<b>85871</b>
<b>Touran (1T3) 1.4 TSI</b>	2010->
CTHC/CAVC	103 140
Ignition Coil	<b>80201</b>
<b>Touran (1T3) 1.4 TSI</b>	2010->
CTHB/CAVB	125 170
Ignition Coil	<b>80201</b>
<b>Touran (1T3) 1.4 TSI EcoFuel</b>	2010->
CDGA	110 150
Ignition Coil	<b>80201</b>
<b>Touran (5T1) 1.2 TSI</b>	2015->
CYVB	81 110
Ignition Coil	<b>80249</b>
<b>Touran (5T1) 1.4 TSI</b>	2015->
CZDA	110 150
Ignition Coil	<b>80249</b>





VOLKSWAGEN Cont.		
<b>Transporter IV Bus (70XB, 70XC, 7DB, 7DW) 1.8</b>		<b>1990-92</b>
PD		49 67
Ignition Coil 3 term.		<b>80200</b>
Ignition Coil 6 term.; Intake manifold injection		<b>80219</b>
Ignition Leads <Caravelle T4 1.8>		<b>85685</b>
Ignition Leads		<b>85690</b>
<b>Transporter IV Bus (70XB, 70XC, 7DB, 7DW) 2.0</b>		<b>1990-03</b>
AAC		62 84
Ignition Coil Ch.70-S-045001->; ->12.1993		<b>80200</b>
Ignition Coil ->Ch.70-S-045000; ->12.1993		<b>80219</b>
Ignition Leads		<b>85690</b>
<b>Transporter IV Bus (70XB, 70XC, 7DB, 7DW) 2.5</b>		<b>1990-03</b>
AEN/AAF/ACU/AEU		81 110
Ignition Coil ACU,AEN,AAF,AEU		<b>80200</b>
<b>Transporter IV Bus (70XB, 70XC, 7DB, 7DW) 2.5</b>		<b>1996-03</b>
AVT/AET/APL		85 115
Ignition Coil AVT,APL,AET		<b>80200</b>
<b>Transporter IV Bus (70XB, 70XC, 7DB, 7DW) 2.5 Syncro</b>		<b>1992-03</b>
AEN/AAF/ACU/AEU		81 110
Ignition Coil AAF,AEN,AEU,ACU		<b>80200</b>
<b>Transporter IV Bus (70XB, 70XC, 7DB, 7DW) 2.5 Syncro</b>		<b>1996-03</b>
AVT/AET/APL		85 115
Ignition Coil AET,APL,AVT		<b>80200</b>
<b>Transporter IV Chassis (70XD) 2.0</b>		<b>1990-03</b>
AAC		62 84
Ignition Coil Ch.70-S-045001->; ->12.1993		<b>80200</b>
Ignition Coil ->Ch.70-S-045000; ->12.1993		<b>80219</b>
Ignition Leads		<b>85690</b>
<b>Transporter IV Chassis (70XD) 2.5</b>		<b>1990-03</b>
AEN/AAF/ACU/AEU		81 110
Ignition Coil ACU,AEN,AAF,AEU		<b>80200</b>
<b>Transporter IV Chassis (70XD) 2.5</b>		<b>1996-03</b>
AVT/AET/APL		85 115
Ignition Coil AET,AVT,APL		<b>80200</b>
<b>Transporter IV Chassis (70XD) 2.5 Syncro</b>		<b>1992-03</b>
AEN/AAF/ACU/AEU		81 110
Ignition Coil AEU,AAF,ACU,AEN		<b>80200</b>
<b>Transporter IV Chassis (70XD) 2.5 Syncro</b>		<b>1996-03</b>
AVT/AET/APL		85 115
Ignition Coil APL,AVT,AET		<b>80200</b>
<b>Transporter IV Van (70XA) 2.0</b>		<b>1990-03</b>
AAC		62 84
Ignition Coil Ch.70-S-045001->; ->12.1993		<b>80200</b>
Ignition Coil ->Ch.70-S-045000; ->12.1993		<b>80219</b>
Ignition Leads		<b>85690</b>
<b>Transporter IV Van (70XA) 2.5</b>		<b>1990-03</b>
AEN/AAF/ACU/AEU		81 110
Ignition Coil ACU,AAF,AEN,AEU		<b>80200</b>
<b>Transporter IV Van (70XA) 2.5</b>		<b>1996-03</b>
AVT/AET/APL		85 115
Ignition Coil AET,APL,AVT		<b>80200</b>
<b>Transporter IV Van (70XA) 2.5 Syncro</b>		<b>1992-03</b>
AEN/AAF/ACU/AEU		81 110
Ignition Coil AEN,AAF,AEU,ACU		<b>80200</b>
<b>Transporter IV Van (70XA) 2.5 Syncro</b>		<b>1996-03</b>
AVT/AET/APL		85 115
Ignition Coil AET,AVT,APL		<b>80200</b>
<b>Transporter V Bus (7HB, 7HJ, 7EB, 7EJ, 7EF) 2.0</b>		<b>2003-&gt;</b>
AXA		85 115
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85875</b>
<b>Transporter V Bus (7HB, 7HJ, 7EB, 7EJ, 7EF) 3.2 V6</b>		<b>2004-04</b>
BDL		170 231
Ignition Coil		<b>80327</b>
<b>Transporter V Bus (7HB, 7HJ, 7EB, 7EJ, 7EF) 3.2 V6</b>		<b>2004-09</b>
BKK/CFLA		173 235
Ignition Coil		<b>80327</b>
<b>Transporter V Bus (7HB, 7HJ, 7EB, 7EJ, 7EF) 3.2 V6 4motion</b>		<b>2003-09</b>
BKK/CFLA		173 235
Ignition Coil		<b>80327</b>
<b>Transporter V Chassis (7JD, 7JE, 7JL, 7JY, 7JZ, 2.0)</b>		<b>2003-&gt;</b>
AXA		85 115
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85875</b>
<b>Transporter V Chassis (7JD, 7JE, 7JL, 7JY, 7JZ, 3.2 V6</b>		<b>2004-09</b>
BDL		170 231
Ignition Coil		<b>80327</b>

VOLKSWAGEN Cont.		
<b>Transporter V Chassis (7JD, 7JE, 7JL, 7JY, 7JZ, 3.2 V6</b>		<b>2003-06</b>
BKK		173 235
Ignition Coil		<b>80327</b>
<b>Transporter V Van (7HA, 7HH, 7EA, 7EH) 2.0</b>		<b>2003-&gt;</b>
AXA		85 115
Ignition Coil		<b>80218</b>
Ignition Leads		<b>85875</b>
<b>Transporter V Van (7HA, 7HH, 7EA, 7EH) 3.2 4motion</b>		<b>2003-09</b>
BKK/CFLA		173 235
Ignition Coil		<b>80327</b>
<b>Transporter V Van (7HA, 7HH, 7EA, 7EH) 3.2 V6</b>		<b>2003-04</b>
BDL		170 231
Ignition Coil		<b>80327</b>
<b>Transporter V Van (7HA, 7HH, 7EA, 7EH) 3.2 V6</b>		<b>2004-09</b>
BKK/CFLA		173 235
Ignition Coil		<b>80327</b>
<b>Up 1.0</b>		<b>2011-&gt;</b>
CHYA		44 60
Ignition Coil		<b>80249</b>
<b>Up 1.0</b>		<b>2011-&gt;</b>
CHYB		55 75
Ignition Coil		<b>80249</b>
<b>Up 1.0 EcoFuel</b>		<b>2012-&gt;</b>
CPGA		50 68
Ignition Coil		<b>80249</b>
<b>Up 1.0 TSI</b>		<b>2016-&gt;</b>
CHZA		66 90
Ignition Coil		<b>80249</b>
<b>Vento (1H2) 1.4</b>		<b>1991-98</b>
AEX/ABD		40 55
Ignition Coil ABD,AEX		<b>80200</b>
Ignition Leads		<b>85692</b>
Ignition Leads		<b>85693</b>
<b>Vento (1H2) 1.4</b>		<b>1991-98</b>
AEX/ABD		44 60
Ignition Coil AEX,ABD		<b>80200</b>
Ignition Leads ->Ch.1H-R-990000		<b>85690</b>
Ignition Leads		<b>85692</b>
Ignition Leads AEX		<b>85693</b>
<b>Vento (1H2) 1.6</b>		<b>1992-98</b>
ABU/AEA/AEE		55 75
Ignition Coil 3 term.		<b>80200</b>
Ignition Coil 6 term.		<b>80219</b>
Ignition Leads		<b>85693</b>
<b>Vento (1H2) 1.6</b>		<b>1994-98</b>
AEK/AFT		74 101
Ignition Coil AFT,AEK		<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85692</b>
Ignition Leads		<b>85865</b>
Ignition Leads AEK		<b>85870</b>
<b>Vento (1H2) 1.8</b>		<b>1991-98</b>
AAM		55 75
Ignition Coil		<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85685</b>
Ignition Leads Ch.1H-R-990000->		<b>85865</b>
<b>Vento (1H2) 1.8</b>		<b>1991-98</b>
ACC/ADZ/ADD/ABS		66 90
Ignition Coil ADZ,ABS		<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85685</b>
<b>Vento (1H2) 2.0</b>		<b>1991-98</b>
ADY/AKR/2E/AGG		85 115
Ignition Coil AGG,AKR,2E,ADY		<b>80200</b>
Ignition Leads ->Ch.6KZR510001, ZR010001		<b>85685</b>
Ignition Leads 2E		<b>85690</b>
Ignition Leads AKR		<b>85865</b>
<b>Vento (1H2) 2.8 VR6</b>		<b>1992-98</b>
AAA		128 174
Ignition Coil ->Ch.1H-PM480 000		<b>80200</b>
Ignition Leads ->Ch.1H-VW600000		<b>85070</b>
<b>Voyage 1.0 Flex</b>		<b>2008-&gt;</b>
CCNA		56 76
Ignition Coil		<b>80270</b>
<b>Voyage 1.6 Flex</b>		<b>2008-&gt;</b>
CFZA		74 101
Ignition Coil		<b>80270</b>



VOLVO	
140 (142, 144) 1.8	1966-68
B 18 A	55 75
Ignition Leads B 18 A	<b>83210</b>
140 (142, 144) 1.8 S	1967-72
B 18 B	74 101
Ignition Leads B 18 B	<b>83210</b>
140 (142, 144) 2.0	1968-74
B 20 A	60 82
Ignition Leads B 20 A	<b>83210</b>
140 (142, 144) 2.0	1970-75
B 20 E	91 124
Ignition Leads B 20 E	<b>83210</b>
140 (142, 144) 2.0	1971-72
B 20 D	70 95
Ignition Leads B 20 D	<b>83210</b>
140 (142, 144) 2.0 S	1968-72
B 20 B	74 101
Ignition Leads	<b>83210</b>
140 (142, 144) 2.0 S	1972-75
B 20 F	85 116
Ignition Leads B 20 F	<b>83210</b>
140 Wagon (145) 2.0 S	1972-74
B 20 B	74 101
Ignition Leads	<b>83210</b>
140 Wagon (145) 2.0 S	1968-74
B 20 A	60 82
Ignition Leads	<b>83210</b>
140 Wagon (145) 2.0 S	1973-75
B 20 F	85 116
Ignition Leads B 20 F	<b>83210</b>
140 Wagon (145) 2.0 S	1972-73
B 20 B	73 100
Ignition Leads	<b>83210</b>
140 Wagon (145) 2.0 S	1972-73
B 20 E	91 124
Ignition Leads	<b>83210</b>
340-360 (343, 345) 1.4	1979-83
B 14.3 E	47 64
Ignition Leads B 14.3 E	<b>83220</b>
340-360 (343, 345) 1.4	1975-83
B 14.4 S	51 70
Ignition Coil	<b>80264</b>
340-360 (343, 345) 1.4	1983-86
B 14.4 S	52 71
Ignition Coil	<b>80264</b>
340-360 (343, 345) 1.4	1982-85
B 14.3 E	46 63
Ignition Coil	<b>80264</b>
Ignition Leads ->12.1983	<b>83220</b>
340-360 (343, 345) 1.4	1986-88
B 14.4 S	50 68
Ignition Coil	<b>80264</b>
340-360 (343, 345) 1.4	1987-88
B 14.4 S	51 70
Ignition Coil	<b>80264</b>
340-360 (343, 345) 1.7	1985-91
B 17 2 K	59 80
Ignition Coil	<b>80264</b>
340-360 (343, 345) 2.0	1980-83
B 19 A/B 200 K	70 95
Ignition Coil	<b>80264</b>
340-360 (343, 345) 2.0	1980-84
B 19 A	65 88
Ignition Coil	<b>80264</b>
340-360 (343, 345) 2.0	1988-89
B 200 F	80 109
Ignition Coil	<b>80264</b>
340-360 (343, 345) 2.0	1986-88
B 200 E/B 200 F	82 112
Ignition Coil	<b>80264</b>
340-360 (343, 345) 2.0	1984-87
B 200 K	77 105
Ignition Coil	<b>80264</b>
340-360 (343, 345) 2.0	1984-86
B 200 E	87 118
Ignition Coil	<b>80264</b>
340-360 (343, 345) 2.0	1987-88
B 200 F	81 110
Ignition Coil	<b>80264</b>

VOLVO Cont.	
340-360 Sedan (344) 1.4	1986-88
B 14.4 S	50 68
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 1.4	1987-88
B 14.4 S	51 69
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 1.4	1983-86
B 14.4 S	53 72
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 1.7	1985-91
B 17 2 K	59 80
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 2.0	1984-90
B 200 K	75 102
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 2.0	1984-86
B 200 E	85 115
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 2.0	1984-87
B 200 K	77 105
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 2.0	1984-86
B 200 E	87 118
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 2.0	1986-88
B 200 EA	82 112
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 2.0	1988-89
B 200 F	80 109
Ignition Coil	<b>80264</b>
340-360 Sedan (344) 2.0	1987-88
B 200 EA	81 110
Ignition Coil	<b>80264</b>
440 K (445) 1.6	1991-93
B 16 FI	69 93
Ignition Coil	<b>80264</b>
440 K (445) 1.6	1988-96
B 16 F	61 83
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83190</b>
440 K (445) 1.7	1988-89
B 18 F	70 95
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83190</b>
440 K (445) 1.7	1988-96
B 18 EP	78 106
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83190</b>
440 K (445) 1.7	1988-96
B 18 KP	64 87
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83190</b>
440 K (445) 1.7	1989-96
B 18 FP	75 102
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83190</b>
440 K (445) 1.7	1988-92
B 18 KD	58 78
Ignition Coil	<b>80264</b>
440 K (445) 1.7	1988-89
B 18 KP/B 18 K	60 81
Ignition Coil	<b>80264</b>
440 K (445) 1.7 Turbo	1988-96
B 18 FT	88 120
Ignition Coil	<b>80264</b>
Ignition Leads	<b>85470</b>
440 K (445) 1.7 Turbo	1991-96
B 18 FT	90 122
Ignition Leads	<b>83190</b>
440 K (445) 1.8	1991-96
B 18 U	66 90
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83190</b>
440 K (445) 1.8	1995-96
B 18 U	66 90
Ignition Coil	<b>80264</b>
Ignition Leads	<b>83190</b>



VOLVO Cont.	
440 K (445) 2.0	1992-95
B 20 F	81 110
Ignition Coil	80264
Ignition Leads	83190
440 K (445) 2.0	1993-96
B 20 F	80 109
Ignition Coil	80264
Ignition Leads	83190
460 L (464) 1.6	1992-96
B 16 F	61 83
Ignition Coil	80264
Ignition Leads	83190
460 L (464) 1.7	1989-92
B 18 EP	75 102
Ignition Coil	80264
Ignition Leads	83190
460 L (464) 1.7	1990-96
B 18 KP	66 90
Ignition Leads	83190
460 L (464) 1.7	1988-96
B 18 KP	64 87
Ignition Coil	80264
Ignition Leads	83190
460 L (464) 1.7	1989-92
B 18 E	80 109
Ignition Coil	80264
Ignition Leads	83190
460 L (464) 1.7 Turbo	1989-96
B 18 FT	88 120
Ignition Coil	80264
Ignition Leads	85470
460 L (464) 1.7 Turbo	1991-96
B 18 FT	90 122
Ignition Leads	85470
460 L (464) 1.8	1991-96
B 18 U	66 90
Ignition Coil	80264
Ignition Leads	83190
460 L (464) 2.0	1992-95
B 20 F	81 110
Ignition Coil	80264
Ignition Leads	83190
460 L (464) 2.0	1993-96
B 20 F	80 109
Ignition Coil	80264
Ignition Leads	83190
480 E 1.7	1987-89
B 18 F	70 95
Ignition Coil	80264
Ignition Leads	83190
480 E 1.7	1986-88
B 18 E	80 109
Ignition Coil	80264
Ignition Leads	83190
480 E 1.7	1989-96
B 18 EP	75 102
Ignition Coil	80264
Ignition Leads	83190
480 E 1.7	1986-89
B 18 E	78 106
Ignition Coil	80264
Ignition Leads	83190
480 E 1.7 Turbo	1987-96
B 18 FT	88 120
Ignition Leads	85470
480 E 1.7 Turbo	1991-96
B 18 FT	90 122
Ignition Leads	85470
480 E 2.0	1992-95
B 20 F	81 110
Ignition Coil	80264
Ignition Leads	83190
01.1993->	83190
Ignition Leads	85470
66 GL 1.3	1975-78
B 130	42 57
Ignition Leads	83210
66 Wagon DL 1.1	1975-79
B 11	33 45
Ignition Leads	83210

VOLVO Cont.	
66 Wagon GL 1.3	1975-79
B 130	42 57
Ignition Leads	83210
740 (744) 2.0	1988-90
B 200 K	76 103
Ignition Leads	83080
740 (744) 2.0	1983-84
B 19 ET	110 150
Ignition Leads	83080
740 (744) 2.3	1984-90
B 23 A/B 230 F	84 114
Ignition Leads	83080
08.1987->	83080
740 (744) 2.3	1988-91
B 234 F	114 156
Ignition Leads	83080
740 (744) 2.3	1987-92
B 234 F	85 115
Ignition Leads	85440
740 (744) 2.3	1990-92
B 230 FB	100 136
Ignition Leads	83080
740 (744) 2.3	1987-89
B 234 F	117 159
Ignition Leads	83080
740 (744) 2.3	1988-92
B 234 F	111 151
Ignition Leads	83080
740 (744) 2.3 Turbo	1985-88
B 230 ET	134 182
Ignition Leads	83080
740 (744) 2.3 Turbo	1989-90
B 230 FT	140 190
Ignition Leads	83080
740 Kombi (745) 2.0	1988-90
B 200 K	76 103
Ignition Leads	83080
740 Kombi (745) 2.3	1985-90
B 230 K	84 114
Ignition Leads	85440
740 Kombi (745) 2.3	1988-90
B 234 F	114 156
Ignition Leads	83080
740 Kombi (745) 2.3	1987-89
B 234 F	117 159
Ignition Leads	83080
740 Kombi (745) 2.3	1989-92
B 234 F	111 151
Ignition Leads	83080
740 Kombi (745) 2.3	1988-92
B 230 FT	121 165
Ignition Leads	83080
740 Kombi (745) 2.3 Turbo	1984-88
B 230 ET	134 182
Ignition Leads	83080
740 Kombi (745) 2.3 Turbo	1982-84
B 23 ET	127 173
Ignition Leads	83080
740 Kombi (745) 2.3 Turbo	1984-90
B 230 ET	134 182
Ignition Leads	83080
850 (LS) 2.0	1991-96
B 5204 F	105 143
Ignition Coil	80264
Ignition Coil	80303
08.1995->	80303
850 (LS) 2.0	1994-96
B 5202 S	93 126
Ignition Coil	80303
850 (LS) 2.0 Turbo	1993-96
B 5204 T/B 5204 FT	155 210
Ignition Coil	80303
Ignition Leads	85480
850 (LS) 2.3 T5	1993-96
B 5234 FT	166 226
Ignition Coil	80303
Ignition Leads	85480
850 (LS) 2.3 T5-R	1995-96
B 5234 T4	184 250
Ignition Coil	80303
Ignition Leads	85480



VOLVO Cont.	
<b>850 (LS) 2.5</b>	1991-94
B 5252	103 140
Ignition Coil	<b>80303</b>
<b>850 (LS) 2.5</b>	1991-96
B 5254 S	125 170
Ignition Coil	<b>80303</b>
<b>850 (LS) 2.5</b>	1994-96
B 5252 FS	106 144
Ignition Coil	<b>80303</b>
<b>850 Wagon (LW) 2.0</b>	1994-96
B 5202 S	93 126
Ignition Coil	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>850 Wagon (LW) 2.0</b>	1993-96
B 5204 F	105 143
Ignition Coil	<b>80264</b>
Ignition Coil 08.1995->	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>850 Wagon (LW) 2.0 Turbo</b>	1993-96
B 5204 T/B 5204 FT	155 210
Ignition Coil	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>850 Wagon (LW) 2.3 T5</b>	1993-96
B 5234 FT	166 226
Ignition Coil	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>850 Wagon (LW) 2.3 T5-R</b>	1995-96
B 5234 T4	184 250
Ignition Coil	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>850 Wagon (LW) 2.5</b>	1992-96
B 5254 S	125 170
Ignition Coil	<b>80303</b>
<b>850 Wagon (LW) 2.5</b>	1992-94
B 5252	103 140
Ignition Coil	<b>80303</b>
<b>850 Wagon (LW) 2.5</b>	1994-96
B 5252 FS	106 144
Ignition Coil	<b>80303</b>
<b>850 Wagon (LW) 2.5 AWD</b>	1996-96
B 5254 T	142 193
Ignition Coil	<b>80303</b>
<b>940 (944) 2.3</b>	1990-91
B 234 F /B 234 G	114 156
Ignition Leads	<b>83080</b>
<b>940 Break (945) 2.3</b>	1990-91
B 234 F	114 155
Ignition Leads	<b>83080</b>
<b>C30 1.6</b>	2006-12
B 4164 S3	74 100
Ignition Coil	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>C30 1.8</b>	2006-12
B 4184 S11	92 125
Ignition Coil	<b>80231</b>
<b>C30 1.8 FlexFuel</b>	2007-12
B 4184 S8	92 125
Ignition Coil	<b>80231</b>
<b>C30 2.0</b>	2006-12
B 4204 S3	107 145
Ignition Coil	<b>80231</b>
<b>C30 2.4 i</b>	2006-12
B 5244 S4	125 170
Ignition Coil	<b>80304</b>
<b>C30 T5</b>	2006-12
B 5254 T3	162 220
Ignition Coil	<b>80304</b>
<b>C30 T5</b>	2007-12
B 5254 T7	169 230
Ignition Coil	<b>80304</b>
<b>C70 I Cabriolet 2.0</b>	1998-05
B 5204 T2	132 180
Ignition Coil	<b>80303</b>
<b>C70 I Cabriolet 2.0 T</b>	2000-05
B 5204 T4	120 163
Ignition Coil	<b>80302</b>

VOLVO Cont.	
<b>C70 I Cabriolet 2.0 T</b>	1998-05
B 5204 T3	166 226
Ignition Coil	<b>80302</b>
Ignition Coil ->08.1998	<b>80303</b>
<b>C70 I Cabriolet 2.3 T5</b>	2002-05
B 5234 T9	180 245
Ignition Coil	<b>80302</b>
<b>C70 I Cabriolet 2.3 T5</b>	1998-05
B 5234 T3	176 239
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>C70 I Cabriolet 2.4 T</b>	2002-05
B 5244 T7	147 200
Ignition Coil	<b>80302</b>
<b>C70 I Cabriolet 2.5</b>	1998-05
B 5254 S	125 170
Ignition Coil	<b>80302</b>
Ignition Coil ->03.1999	<b>80303</b>
<b>C70 I Cabriolet 2.5 T</b>	1998-05
B 5254 T/B 5244 T	142 193
Ignition Coil	<b>80302</b>
Ignition Coil ->08.1998	<b>80303</b>
<b>C70 I Coupe 2.0</b>	1997-02
B 5204 T2	132 180
Ignition Coil	<b>80303</b>
<b>C70 I Coupe 2.0 T</b>	2000-02
B 5204 T4	120 163
Ignition Coil	<b>80302</b>
<b>C70 I Coupe 2.0 T</b>	1997-02
B 5204 T3	166 226
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>C70 I Coupe 2.3 T-5</b>	1997-02
B 5234 T3	176 240
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>C70 I Coupe 2.5</b>	1999-02
B 5254 S	121 165
Ignition Coil	<b>80302</b>
<b>C70 I Coupe 2.5</b>	1999-02
B 5244 S/B 5254 S	125 170
Ignition Coil	<b>80302</b>
<b>C70 I Coupe 2.5 T</b>	1997-02
B 5254 T/B 5244 T	142 193
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>C70 II Cabriolet 2.4</b>	2006-09
B 5244 S5	103 140
Ignition Coil	<b>80304</b>
<b>C70 II Cabriolet 2.4 i</b>	2006-09
B 5244 S4	125 170
Ignition Coil	<b>80304</b>
<b>C70 II Cabriolet T5</b>	2006-07
B 5254 T3	162 220
Ignition Coil	<b>80304</b>
<b>C70 II Cabriolet T5</b>	2007-09
B 5254 T7	169 230
Ignition Coil	<b>80304</b>
<b>P 122 S Amazon 1.8</b>	1959-67
B 18	59 80
Ignition Leads B 18	<b>83210</b>
<b>P 122 S Amazon 1.8</b>	1966-71
B 18	63 86
Ignition Leads B 18	<b>83210</b>
<b>P 122 S Amazon 1.8</b>	1966-71
B 18	76 103
Ignition Leads B 18	<b>83210</b>
<b>P 122 S Amazon 2.0</b>	1968-71
B 20 B	74 101
Ignition Leads B 20 B	<b>83210</b>
<b>P 122 S Amazon Kombi 1.8</b>	1961-67
B 18	59 80
Ignition Leads B 18	<b>83210</b>
<b>S40 I (VS) 1.6</b>	1995-99
B 4164 S	77 105
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil Cyl. 2-3; With regul.cat.(3way)	<b>80221</b>
Ignition Leads	<b>85485</b>



VOLVO Cont.	
<b>S40 I (VS) 1.8</b>	<b>1999-03</b>
B 4184 S2/B 4184 S9	90 122
Ignition Leads B 4184 S2	<b>85481</b>
Ignition Leads B 4184 S9	<b>85485</b>
<b>S40 I (VS) 1.8</b>	<b>1995-99</b>
B 4184 S3/B 4184 S	85 115
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil With regul.cat.(3way); Cyl. 2-3	<b>80221</b>
Ignition Leads	<b>85485</b>
<b>S40 I (VS) 1.8 i</b>	<b>1998-03</b>
B 4184 SM	92 125
Ignition Leads	<b>85485</b>
<b>S40 I (VS) 1.8 i</b>	<b>2001-03</b>
B 4184 SJ	90 122
Ignition Coil OE N° 70863020	<b>80220</b>
Ignition Coil OE N° 70863021	<b>80221</b>
<b>S40 I (VS) 1.9 T4</b>	<b>1997-00</b>
B 4194 T/B 4194 T2	147 200
Ignition Leads	<b>85481</b>
<b>S40 I (VS) 2.0</b>	<b>1995-03</b>
B 4204 S2/B 4204 S	100 136
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil With regul.cat.(3way); Cyl. 2-3	<b>80221</b>
Ignition Leads	<b>85480</b>
<b>S40 I (VS) 2.0</b>	<b>1995-99</b>
B 4204 S	103 140
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil With regul.cat.(3way); Cyl. 2-3	<b>80221</b>
Ignition Leads	<b>85480</b>
<b>S40 I (VS) 2.0 T</b>	<b>2000-01</b>
B 4204 T2/B 4204 T3	121 165
Ignition Leads	<b>85481</b>
<b>S40 I (VS) 2.0 T</b>	<b>2001-03</b>
B 4204 T3	120 163
Ignition Leads	<b>85481</b>
<b>S40 II (MS) 1.6</b>	<b>2005-12</b>
B 4164 S3	74 101
Ignition Coil	<b>80214</b>
Ignition Coil Ch.106167->	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>S40 II (MS) 1.8</b>	<b>2004-10</b>
B 4184 S11	92 125
Ignition Coil	<b>80231</b>
<b>S40 II (MS) 1.8 FlexFuel</b>	<b>2006-10</b>
B 4184 S8	92 125
Ignition Coil	<b>80231</b>
<b>S40 II (MS) 2.0</b>	<b>2006-12</b>
B 4204 S3	107 146
Ignition Coil	<b>80231</b>
<b>S40 II (MS) 2.4</b>	<b>2004-10</b>
B 5244 S5	103 140
Ignition Coil	<b>80304</b>
<b>S40 II (MS) 2.4</b>	<b>2004-10</b>
B 5244 S4	125 170
Ignition Coil	<b>80304</b>
<b>S40 II (MS) T5</b>	<b>2004-07</b>
B 5254 T3	162 220
Ignition Coil	<b>80304</b>
<b>S40 II (MS) T5</b>	<b>2007-12</b>
B 5254 T7	169 230
Ignition Coil	<b>80304</b>
<b>S40 II (MS) T5 AWD</b>	<b>2004-07</b>
B 5254 T3	162 220
Ignition Coil	<b>80304</b>
<b>S40 II (MS) T5 AWD</b>	<b>2007-10</b>
B 5254 T7	169 230
Ignition Coil	<b>80304</b>
<b>S60 I 2.0 T</b>	<b>2000-10</b>
B 5204 T5	132 180
Ignition Coil ->07.2004	<b>80302</b>
Ignition Coil 08.2004->	<b>80304</b>
<b>S60 I 2.4</b>	<b>2000-10</b>
B 5244 S2	103 140
Ignition Coil	<b>80302</b>
<b>S60 I 2.4</b>	<b>2000-10</b>
B 5244 S	125 170
Ignition Coil	<b>80302</b>

VOLVO Cont.	
<b>S60 I 2.4 Bifuel</b>	<b>2002-10</b>
B 5244 SG2	103 140
Ignition Coil	<b>80302</b>
<b>S60 I 2.4 Bifuel</b>	<b>2001-10</b>
B 5244 SG	103 140
Ignition Coil	<b>80302</b>
<b>S60 I 2.4 T</b>	<b>2000-10</b>
B 5244 T3	147 200
Ignition Coil ->07.2003	<b>80302</b>
Ignition Coil 08.2003->	<b>80304</b>
<b>S60 I 2.4 T AWD</b>	<b>2001-10</b>
B 5244 T3	147 200
Ignition Coil ->07.2003	<b>80302</b>
Ignition Coil 08.2003->	<b>80304</b>
<b>S60 I 2.4 T5</b>	<b>2004-10</b>
B 5244 T5	191 260
Ignition Coil	<b>80304</b>
<b>S60 I 2.5 T</b>	<b>2003-10</b>
B 5254 T2	154 210
Ignition Coil	<b>80302</b>
<b>S60 I 2.5 T AWD</b>	<b>2004-10</b>
B 5254 T2	154 210
Ignition Coil	<b>80302</b>
<b>S60 I R 2,5 T AWD</b>	<b>2003-10</b>
B 5254 T4	221 300
Ignition Coil	<b>80304</b>
<b>S60 I T5</b>	<b>2000-10</b>
B 5234 T3	184 250
Ignition Coil	<b>80302</b>
<b>S60 II 2.0 T</b>	<b>2012-15</b>
B 5204 T8	132 180
Ignition Coil	<b>80304</b>
<b>S60 II T5</b>	<b>2010-14</b>
B 4204 T7	177 240
Ignition Coil 08.2011-07.2014	<b>80255</b>
<b>S70 (LS) 2.0</b>	<b>1997-00</b>
B 5204 T4	120 163
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>S70 (LS) 2.0</b>	<b>1997-00</b>
B 5202 S/B 5202 FS	93 126
Ignition Coil	<b>80303</b>
<b>S70 (LS) 2.0</b>	<b>1997-00</b>
B 5204 F	105 143
Ignition Coil	<b>80303</b>
<b>S70 (LS) 2.0</b>	<b>1997-00</b>
B 5204 T2	132 180
Ignition Coil	<b>80303</b>
<b>S70 (LS) 2.0 Turbo</b>	<b>1997-00</b>
B 5204 T	155 210
Ignition Coil	<b>80303</b>
<b>S70 (LS) 2.0 Turbo</b>	<b>1997-00</b>
B 5204 T3	166 226
Ignition Coil	<b>80302</b>
Ignition Coil	<b>80303</b>
<b>S70 (LS) 2.3 T-5</b>	<b>1997-00</b>
B 5234 T3	176 239
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>S70 (LS) 2.3 Turbo</b>	<b>1997-00</b>
B 5234 FT+	184 250
Ignition Coil	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>S70 (LS) 2.4</b>	<b>1999-00</b>
B 5244 SG/B 5244 S2	103 140
Ignition Coil	<b>80302</b>
<b>S70 (LS) 2.4</b>	<b>1997-00</b>
B 5244 S/B 5254 S	125 170
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>S70 (LS) 2.4 AWD</b>	<b>1999-00</b>
B 5244 S2	103 140
Ignition Coil	<b>80302</b>
<b>S70 (LS) 2.4 AWD</b>	<b>1996-99</b>
B 5252 FS	106 144
Ignition Coil 01.1997->; Bosch	<b>80303</b>





VOLVO Cont.	
<b>S70 (LS) 2.4 AWD</b>	1999-00
B 5244 S	125 170
Ignition Coil	<b>80302</b>
<b>S70 (LS) 2.4 T5 AWD</b>	1996-99
B 5254 T	142 193
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>S70 (LS) 2.4 Turbo</b>	1997-00
B 5254 T/B 5244 T	142 193
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>S70 (LS) 2.5</b>	1998-00
B 5254 S	121 165
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>S70 (LS) 2.5</b>	1997-00
B 5252 FS	106 144
Ignition Coil	<b>80303</b>
<b>S70 (LS) 2.5 Bifuel</b>	1998-00
GB 5252 S	106 144
Ignition Coil	<b>80303</b>
<b>S70 (LS) 2.5 Bifuel</b>	1999-00
B 5244 SG	103 140
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.0</b>	1998-06
B 5204 T4	120 163
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.0 T</b>	1999-06
B 5204 T5	132 180
Ignition Coil ->07.2004	<b>80302</b>
Ignition Coil 08.2004->	<b>80304</b>
<b>S80 I (TS, XY) 2.0 T</b>	1998-06
B 5204 T3	166 226
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.4</b>	1999-06
B 5244 S	125 170
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.4</b>	1999-06
B 5244 S2	103 140
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.4 Bifuel</b>	2001-06
B 5244 SG2	103 140
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.4 Bifuel (LPG)</b>	2001-06
B 5244 SG	103 140
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.4 T</b>	2000-06
B 5244 T3	147 200
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.4 T5 AWD</b>	2000-03
B 5244 T3	147 200
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.5 T</b>	2003-06
B 5254 T2	154 210
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.5 T AWD</b>	2003-06
B 5254 T2	154 210
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.8 T6</b>	1998-06
B 6284 T	200 272
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.9</b>	1999-06
B 6294 S	147 200
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 2.9</b>	1998-06
B 6304 S3	150 204
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 3.0</b>	2001-06
B 6294 S2	144 196
Ignition Coil	<b>80302</b>
<b>S80 I (TS, XY) 3.0 T6</b>	2001-06
B 6294 T	200 272
Ignition Coil	<b>80302</b>
<b>S80 II (AS) 2.0</b>	2008->
B 4204 S3	107 146
Ignition Coil	<b>80231</b>
<b>S80 II (AS) 2.0 FlexFuel</b>	2008->
B 4204 S4	107 146
Ignition Coil	<b>80231</b>

VOLVO Cont.	
<b>S80 II (AS) 2.0 T</b>	2010->
B 4204 T6	149 203
Ignition Coil	<b>80255</b>
<b>S80 II (AS) 2.5 T</b>	2006->
B 5254 T6	147 200
Ignition Coil	<b>80304</b>
<b>S80 II (AS) 2.5 T</b>	2010->
B 5254 T10	170 231
Ignition Coil	<b>80304</b>
<b>S80 II (AS) 2.5 T FlexFuel</b>	2008->
B 5254 T8	147 200
Ignition Coil	<b>80304</b>
<b>S80 II (AS) 2.5 T FlexFuel</b>	2010->
B 5254 T11	170 231
Ignition Coil	<b>80304</b>
<b>S80 II (AS) T5</b>	2010->
B 4204 T7	177 241
Ignition Coil ->07.2013	<b>80255</b>
<b>V40 Fastback T4</b>	2013->
B 5204 T8	132 180
Ignition Coil	<b>80304</b>
<b>V40 Fastback T4 AWD</b>	2013->
B 5204 T8	132 180
Ignition Coil	<b>80304</b>
<b>V40 Fastback T5</b>	2012->
B 5254 T12	187 254
Ignition Coil	<b>80304</b>
<b>V40 Fastback T5</b>	2013->
B 5204 T9	157 214
Ignition Coil	<b>80304</b>
<b>V40 Fastback T5 AWD</b>	2013->
B 5204 T9	157 214
Ignition Coil	<b>80304</b>
<b>V40 Fastback T5 AWD</b>	2013->
B 5254 T12	187 254
Ignition Coil	<b>80304</b>
<b>V40 Wagon (VW) 1.6</b>	1995-99
B 4164 S	77 105
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil Cyl. 2-3; With regul.cat.(3way)	<b>80221</b>
Ignition Leads	<b>85485</b>
<b>V40 Wagon (VW) 1.8</b>	1999-04
B 4184 S2/B 4184 S9	90 122
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil Cyl. 2-3	<b>80221</b>
Ignition Leads	<b>85485</b>
<b>V40 Wagon (VW) 1.8</b>	1995-99
B 4184 S3/B 4184 S	85 115
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil With regul.cat.(3way); Cyl. 2-3	<b>80221</b>
Ignition Leads	<b>85485</b>
<b>V40 Wagon (VW) 1.8 i</b>	1998-04
B 4184 SM	92 125
Ignition Coil	<b>80220</b>
Ignition Coil	<b>80221</b>
<b>V40 Wagon (VW) 1.8 i</b>	2001-04
B 4184 SJ	90 122
Ignition Leads	<b>85481</b>
<b>V40 Wagon (VW) 1.9 T4</b>	1997-00
B 4194 T/B 4194 T2	147 200
Ignition Leads	<b>85481</b>
<b>V40 Wagon (VW) 2.0</b>	1995-04
B 4204 S2/B 4204 S	100 136
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil Cyl. 2-3	<b>80221</b>
Ignition Leads	<b>85485</b>
<b>V40 Wagon (VW) 2.0</b>	1995-99
B 4204 S	103 140
Ignition Coil Cyl. 1-4	<b>80220</b>
Ignition Coil With regul.cat.(3way); Cyl. 2-3	<b>80221</b>
Ignition Leads	<b>85485</b>
<b>V40 Wagon (VW) 2.0 T4</b>	2000-04
B 4204 T5	147 200
Ignition Leads	<b>85481</b>



VOLVO Cont.	
<b>V50 (MW) 1.6</b>	2005-12
B 4164 S3	74 101
Ignition Coil ->Ch.105439	<b>80214</b>
Ignition Coil Ch.105440->	<b>80284</b>
Ignition Leads	<b>85115</b>
Ignition Leads	<b>85125</b>
<b>V50 (MW) 1.8</b>	2004-10
B 4184 S11	92 125
Ignition Coil	<b>80231</b>
<b>V50 (MW) 1.8 FlexFuel</b>	2005-10
B 4184 S8	92 125
Ignition Coil	<b>80231</b>
<b>V50 (MW) 2.0</b>	2006-12
B 4204 S3	107 146
Ignition Coil	<b>80231</b>
<b>V50 (MW) 2.4</b>	2004-10
B 5244 S5	103 140
Ignition Coil	<b>80304</b>
<b>V50 (MW) 2.4</b>	2004-10
B 5244 S4	125 170
Ignition Coil	<b>80304</b>
<b>V50 (MW) T5</b>	2004-07
B 5254 T3	162 220
Ignition Coil	<b>80304</b>
<b>V50 (MW) T5</b>	2007-12
B 5254 T7	169 230
Ignition Coil	<b>80304</b>
<b>V50 (MW) T5 AWD</b>	2004-07
B 5254 T3	162 220
Ignition Coil	<b>80304</b>
<b>V50 (MW) T5 AWD</b>	2007-10
B 5254 T7	169 230
Ignition Coil	<b>80304</b>
<b>V60 2.0 T</b>	2010-12
B 4204 T6	149 203
Ignition Coil ->08.2011	<b>80255</b>
<b>V60 T5</b>	2013->
B 5204 T9	157 214
Ignition Coil	<b>80304</b>
<b>V60 T5</b>	2010-14
B 4204 T7	177 241
Ignition Coil ->08.2013	<b>80255</b>
<b>V70 I (LV) 2.0</b>	1997-00
B 5204 T4	120 163
Ignition Coil	<b>80302</b>
Ignition Leads	<b>85480</b>
<b>V70 I (LV) 2.0</b>	1995-00
B 5202 S	93 126
Ignition Coil	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>V70 I (LV) 2.0</b>	1995-00
B 5204 F	105 143
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>V70 I (LV) 2.0</b>	1996-00
B 5204 T2	132 180
Ignition Coil	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>V70 I (LV) 2.0 Turbo</b>	1995-00
B 5204 T	155 211
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>V70 I (LV) 2.0 Turbo</b>	1996-00
B 5204 T3	166 226
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>V70 I (LV) 2.0 Turbo AWD</b>	1996-00
B 5204 T3	166 226
Ignition Coil 08.1998->	<b>80302</b>
Ignition Coil	<b>80303</b>
<b>V70 I (LV) 2.3 AWD</b>	1997-98
B 5234 T3	177 241
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
<b>V70 I (LV) 2.3 T AWD</b>	1997-00
B 5234 T4/B 5234 FT+	184 250
Ignition Coil	<b>80303</b>

VOLVO Cont.	
<b>V70 I (LV) 2.3 T-5</b>	1996-00
B 5234 T3	176 239
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>V70 I (LV) 2.3 T-5 AWD</b>	1997-00
B 5234 T3	176 239
Ignition Coil	<b>80302</b>
Ignition Coil ->07.1998	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>V70 I (LV) 2.3 Turbo</b>	1995-00
B 5234 FT+	184 250
Ignition Coil	<b>80303</b>
<b>V70 I (LV) 2.4</b>	1999-00
B 5244 SG2/B 5244 S2	103 140
Ignition Coil	<b>80302</b>
Ignition Leads	<b>85480</b>
<b>V70 I (LV) 2.4</b>	1995-00
B 5244 S/B 5254 S	125 170
Ignition Coil	<b>80302</b>
Ignition Coil 01.1997-07.1998	<b>80303</b>
<b>V70 I (LV) 2.4 AWD</b>	1998-99
B 5254 S	121 165
Ignition Coil	<b>80302</b>
<b>V70 I (LV) 2.4 Bifuel</b>	1999-00
B 5244 SG	103 140
Ignition Coil	<b>80302</b>
<b>V70 I (LV) 2.4 Turbo</b>	1996-00
B 5254 T/B 5244 T	142 193
Ignition Coil 08.1998->	<b>80302</b>
Ignition Coil	<b>80303</b>
Ignition Leads	<b>85480</b>
<b>V70 I (LV) 2.5</b>	1998-99
B 5254 S	121 165
Ignition Coil 08.1998->	<b>80302</b>
Ignition Coil	<b>80303</b>
<b>V70 I (LV) 2.5</b>	1995-00
B 5252 FS	106 144
Ignition Coil	<b>80303</b>
<b>V70 I (LV) 2.5 AWD</b>	1999-00
B 5244 T2	195 265
Ignition Coil	<b>80302</b>
<b>V70 I (LV) 2.5 Bifuel</b>	1998-99
GB 5252 S	106 144
Ignition Coil	<b>80303</b>
<b>V70 I (LV) 2.5 Turbo AWD</b>	1996-00
B 5254 T/B 5244 T	142 193
Ignition Coil	<b>80302</b>
Ignition Coil 01.1997-07.1998	<b>80303</b>
<b>V70 II (SW) 2.0 T</b>	1999-07
B 5204 T5	132 180
Ignition Coil	<b>80302</b>
Ignition Coil ->07.2007	<b>80304</b>
<b>V70 II (SW) 2.3 T5</b>	1999-04
B 5234 T3	184 250
Ignition Coil	<b>80302</b>
<b>V70 II (SW) 2.4</b>	2000-07
B 5244 S2	103 140
Ignition Coil	<b>80302</b>
<b>V70 II (SW) 2.4</b>	2000-07
B 5244 S	125 170
Ignition Coil	<b>80302</b>
<b>V70 II (SW) 2.4 Bifuel</b>	2001-07
B 5244 SG	103 140
Ignition Coil	<b>80302</b>
<b>V70 II (SW) 2.4 Bifuel</b>	2001-07
B 5244 SG	103 140
Ignition Coil	<b>80302</b>
<b>V70 II (SW) 2.4 T</b>	1999-03
B 5244 T3	147 200
Ignition Coil	<b>80302</b>
<b>V70 II (SW) 2.4 T AWD</b>	2001-02
B 5244 T3	147 200
Ignition Coil	<b>80302</b>
<b>V70 II (SW) 2.4 T5</b>	2004-07
B 5244 T5	191 260
Ignition Coil	<b>80304</b>



<b>VOLVO Cont.</b>	
<b>V70 II (SW) 2.5 T</b>	<b>2001-07</b>
B 5254 T2	154 209
Ignition Coil	<b>80302</b>
<b>V70 II (SW) 2.5 T AWD</b>	<b>2002-07</b>
B 5254 T2	154 209
Ignition Coil	<b>80302</b>
<b>V70 II (SW) R 2,5 T AWD</b>	<b>2003-07</b>
B 5254 T4	221 300
Ignition Coil	<b>80304</b>
<b>V70 III (BW) 2.0</b>	<b>2007-11</b>
B 4204 S3	107 145
Ignition Coil	<b>80231</b>
<b>V70 III (BW) 2.0 FlexiFuel</b>	<b>2008-11</b>
B 4204 S4	107 146
Ignition Coil	<b>80231</b>
<b>V70 III (BW) 2.5 T</b>	<b>2007-09</b>
B 5254 T6	147 200
Ignition Coil	<b>80304</b>
<b>V70 III (BW) 2.5 T</b>	<b>2009-12</b>
B 5254 T10	170 231
Ignition Coil	<b>80304</b>
<b>V70 III (BW) 2.5 T FlexiFuel</b>	<b>2008-09</b>
B 5254 T8	147 200
Ignition Coil	<b>80304</b>
<b>V70 III (BW) 2.5 T FlexiFuel</b>	<b>2009-11</b>
B 5254 T11	170 231
Ignition Coil	<b>80304</b>
<b>V70 III (BW) T5</b>	<b>2010-14</b>
B 4204 T7	177 241
Ignition Coil ->07.2014	<b>80255</b>
<b>XC60 T5</b>	<b>2010-14</b>
B 4204 T7	177 241
Ignition Coil 08.2011-07.2014	<b>80255</b>
<b>XC60 T6 AWD</b>	<b>2014-15</b>
B 6304 T3/B 6304 T4	242 329
Ignition Coil	<b>80304</b>
<b>XC70 Cross Country 2.4 T XC AWD</b>	<b>2000-02</b>
B 5244 T3	147 200
Ignition Coil	<b>80302</b>
<b>XC70 Cross Country 2.4 T XC AWD</b>	<b>1997-02</b>
B 5254 T	142 193
Ignition Coil	<b>80303</b>
<b>XC70 Cross Country 2.5 T XC AWD</b>	<b>2002-07</b>
B 5254 T2	154 209
Ignition Coil	<b>80302</b>
<b>XC90 I 2.5 T</b>	<b>2002-06</b>
B 5254 T2	154 209
Ignition Coil	<b>80302</b>
<b>XC90 I 2.5 T AWD</b>	<b>2012-&gt;</b>
B 5254 T9	154 209
Ignition Coil	<b>80302</b>
<b>XC90 I T6</b>	<b>2002-06</b>
B 6294 T	200 272
Ignition Coil	<b>80302</b>



